

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Morton Academy
Address 431 North Troy Street

Oracle Unit 26091 **Building ID** 6800
Region 2 **General Services Route** 34

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01	9"x9" Brown VFT	2400	SF	Auditorium	Chrysotile	MISC	No	None	0	SF	
<i>3YR Inspector Comments: Tile abated in 8/22/08 in all areas (1st and 3rd Floor Corridors) except Auditorium.</i>											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
<i>Comments:</i>											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
<i>Comments:</i>											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 26091

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	12"x12" Taupe VFT (ABATED 2008)			1st Flr Corr., Rm 103, 109, Main Off, Tchrs Lunchrm, 201-203, 205-207, 211, 212, 303, 306, 307, 402	Chrysotile						
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Chrysotile						
Comments:											
Condition Not Changed in Spring 2011					Chrysotile						
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	9"x9" Brown VFT Mastic	2400	SF	Auditorium	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Tile and mastic abated in 8/22/08 in all areas (1st and 3rd Floor Corridors) except Auditorium.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12"x12" Taupe VFT Mastic (ABATED 2008)	6950	SF	1st Flr Corr., Rm 103, 109, Main Off, Tchrs Lunchrm, 201-203, 211, 212, 303, 306, 307, 402	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	9"x9" Gray VFT (ABATED)	3200	SF	Lunchroom, Attendance Office, Room 106	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	9"x9" Gray VFT Mastic (ABATED)	3200	SF	Lunchroom, Attendance Office, Room 106	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" Cream VFT Mastic (ABATED 2008)	6950	SF	1st Flr Corr., Rm 103, 109, Main Off, Tchrs Lunchrm, 201-203, 205-207, 211, 212, 303, 306, 307, 402	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Brown w/ Rust Streaks VFT (ABATED 2008)	850	SF	Corridor Outside Auditorium, Room 304	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" Brown w/ Rust Streaks VFT Mastic (ABATED 2008)			Corridor Outside Auditorium, Room 304	Assumed						
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010					Assumed						
Comments:											
Condition Not Changed in Spring 2011					Assumed						
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Sand VFT (ABATED 8/22/08)	1875	SF	Room 110, 2nd Floor Corridor, Room 305	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Sand VFT Mastic (ABATED 2008)	1875	SF	Room 110, 2nd Floor Corridor, Room 305	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Beige VFT (ABATED 2008)	750	SF	Main Entrance, 1st Floor Corridor	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Beige VFT Mastic (ABATED 2008)	750	SF	Main Entrance, 1st Floor Corridor	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9"x9" Dark Gray VFT (ABATED 2008)	2500	SF	2nd Floor Corridor, 4th Floor Corridor, Room 204	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Dark Gray VFT Mastic (ABATED 2008)	2500	SF	2nd & 4th Floor Corridors, Room 204	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	9"x9" Light Green VFT (ABATED 2008)	100	SF	2nd Floor Corridor	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9"x9" Light Green VFT Mastic (ABATED 2008)	100	SF	2nd Floor Corridor	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	9" x 9" Beige VFT (ABATED 2008)	12635	SF	Throughout (See Hatching Maps)	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9"x9" Beige VFT Mastic (ABATED 2008)	12635	SF	Throughout (See Hatching Maps)	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	9"x9" Dark Green VFT (ABATED 2008)	1000	SF	Kitchen, Elevator	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	9"x9" Dark Green VFT Mastic (ABATED 2008)	1000	SF	Kitchen, Elevator	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	9"x 9" Moss Green VFT (ABATED 2008)	1250	SF	Rooms 101, 108	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	9"x9" Moss Green VFT Mastic (ABATED 2008)	1250	SF	Rooms 101, 108	Chrysotile	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Interior Window Caulk	250	EA	Interior Windows	Chrysotile	MISC	No	None	0	EA	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			EA		Chrysotile	MISC				EA	
Comments:											
Condition Not Changed in Spring 2011			EA		Chrysotile	MISC				EA	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12 x 12 inch Gray w/ White & Brown Streaks VFT (ABATED 2008)	25	SF	Elevator	Assumed	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32 A	12 x 12 inch Gray w/ White & Brown VFT Mastic (ABATED 2008)	25	SF	Elevator	Assumed	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Carpet Mastic (ABATED 2008)	1125	SF	Rooms 102, 103, Main Office	Assumed	MISC	No				
3YR Inspector Comments: Abated 8/22/08											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12 x 12 inch Brown w/Yellow Streaks VFT	80	SF	Gymnasium Office	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34 A	12 x 12 inch Brown w/ Yellow Streaks VFT Mastic	80	SF	Gymnasium Office	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12 x 12 Burgundy/Beige Floor Tile	12500	SF	Throughout 2nd and 4th Floors	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35A	12 x 12 Burgundy/Beige Floor Tile Mastic	12500	SF	Throughout 2nd and 4th Floors	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12 x 12 Light Blue/Beige Floor Tile	6250	SF	Throughout 3rd Floor	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36A	12 x 12 Light Blue/Beige Floor Tile Mastic	6250	SF	Throughout 3rd Floor	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12 x 12 Blue/Beige Floor Tile	10000	SF	Throughout 1st Floor	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37A	12 x 12 Blue/Beige Floor Tile Mastic	10000	SF	Throughout 1st Floor	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12 x 12 Blue Floor Tile	3000	SF	Lunchroom and Kitchen	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38A	12 x 12 Blue Floor Tile Mastic	3000	SF	Lunchroom and Kitchen	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Mag Block Tank Insulation	300	SF	Boiler Room	Chrysotile	TSI	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI					SF
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI					SF
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C	MJP E/F/V on Fiberglass Pipe Insulation	60	LF	Boiler Room	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: Material has been abated from all Janitor's Closets, only 60 LF remains in the Boiler Room											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					LF
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					LF
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	MJP/E/F/V on Fiberglass	600	LF	Above Ceiling Tile Throughout 1st Floor	Assumed	MISC	Yes	None	0	LF	
3YR Inspector Comments: New HA - Not previously identified											
Condition Not Changed in Fall 2010			LF		Assumed	MISC					LF
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC					LF
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

All LEA Responsibilities, for this school, will be met.

Lynn A. Crivello

Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 26091

Page 15

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125