

Chicago Public Schools

6 Month Asbestos Surveillance

2015 - Fall

School: Frank W Gunsaulus Scholastic Academy School
Address: 4420 S. Sacramento

Oracle Unit: 29121
Region: 04

Building ID: 3690
Mail Room: 40

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: Deane, Mr. Kevin Barry
Survey Date: 11/13/2015
Email Address: kbdeane@cps.edu

A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via:
 Each child's backpack Notice printed in school's newsletter Notice printed in school's calendar Other

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Hard Plaster	31000	SF	Throughout		Surface	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
 Comments:

2014- Spring: Damaged
 Comments: Minor water damage from roof leaks

2014 - Fall: No Change
 Comments:

2015 - Fall: No Change
 Comments:

2015- Spring: Damaged
 Comments: Water damage in most classrooms and corridors

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2	2' x 4' Ceiling Tile	50000	SF	Throughout		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: Damaged
Comments:Minor water damage from roof leaks

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments:Water damage in 307 and third floor corridor

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	1' x 1' Ceiling Tile	6020	SF	Not Observed		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged
Comments:Gymnasium Ceiling water damage

2014- Spring: Damaged
Comments:Minor water damage from roof leaks in gymnasium

2014 - Fall: Damaged
Comments:Gym ceiling water damage

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:They are in the gymnasium

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	12" x 12" Brown w/White Speck Floor Tile	4000	SF	2nd, 3rd Floor Halls, 2nd, 3rd Floor Teacher's Lounges, Rooms 312A, 108, Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: Repaired
Comments: Replaced >10 tiles from underlayment deterioration

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments: Replaced two tiles outside 211 others are cracked in area

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	9" x 9" Brown Floor Tile	1500	SF	Assembly Hall, Rm 312A, and engineers office		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged
Comments:Slight cracking and chipping in auditorium

2014- Spring: Repaired
Comments:Replaced tiles damaged and cracked

2014 - Fall: Deteriorated
Comments:cracks and breaks auditorium

2015 - Fall: Deteriorated
Comments:Engineers office tile damaged in flood. Underlayment has buckelrd lifting tiles.

2015- Spring: Damaged
Comments:approximatly 150 missing cracked or loose tiles. Engineer office many loose or missing tiles

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	Linoleum			Was in Gym and Gym has New Floor		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	12" x 12" Brown w/White Speck Floor Tile Mastic	4000	SF	2nd, 3rd Floor Halls and Teacher's Lounge See HA 4		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Deteriorated
Comments:cracking anc chipping outside 309

2014- Spring: Repaired
Comments:Replaced >10 damaged tiles

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments:Replaced two tiles outside 211 many others cracked in area

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	9" x 9" Brown Floor Tile Mastic	1800	SF	Assembly Hall		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: Repaired
Comments:Replaced damaged tiles

2014 - Fall: Deteriorated
Comments:Cracks and breaks

2015 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments:exposed due to missing and loose tiles

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	Linoleum Mastic			See HA 6		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	1' x 1' Ceiling Tile Adhesive	6020	SF	Gym		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged
Comments:Water damage to ceiling

2014- Spring: Damaged
Comments:Minor water damage from roof leaks

2014 - Fall: Deteriorated
Comments:Water damage

2015 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments:replaced approximatly 10 missing tiles from water damage

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12" x 12" Tan Floor Tile	725	SF	Room 312A and 2nd Floor Teachers' Lounge		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: Deteriorated
Comments:Asbestos insp positive in 312A. Asbestos under damaged 12x12

2015 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:312A abated

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12" x 12" Tan Floor Tile Mastic	300	SF	3rd Floor Teacher's Lounge		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12" x 12" Speckled Gray Floor Tile	900	SF	1st and 3rd Floor Teacher's Lounges		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12" x 12" Speckled Gray Floor Tile Mastic - HA13	700	SF	Room 312A		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: Deteriorated
Comments:Asbestos under damaged 12X12

2015 - Fall: Abated
Comments:Removed Removed 12/14

2015- Spring: Abated
Comments:312A abated

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12" x 12" Cream Floor Tile w/Black Specs	600	SF	Front Office and Principle's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Cream Floor Tile w/Black Specs Mastic-HA15	600	SF	Front Office and Principle's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9" x 9" Green Floor Tile	400	SF	1st Floor Principal Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9" x 9" Green Floor Tile Mastic - HA17	400	SF	1st Floor Principal Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12" x 12" Cream w/Brown Specks Floor Tile	1500	SF	Room 115, 206		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Deteriorated
Comments:Had to replace 10+ tiles underlayment lifting in 206

2014- Spring: Repaired
Comments:Replaced damage floor tiles from underlayment deterioration

2014 - Fall: No Change
Comments:

2015 - Fall: Repaired
Comments:4/15 underlayment reapires and replaced 4-6 tiles

2015- Spring: Damaged
Comments:Room 206 underlayment deteriorating replaced approximatly 8 tiles

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12" x 12" Cream w/Brown Specks Floor Tile Mastic	1500	SF	Room 115		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: Repaired
Comments:Replaced damaged floor tiles from underlayment deterioration

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Unknown Size Floor Tile	3000	SF	2nd and 3rd Floor Halls, 3rd Floor Teacher's Lounge		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: Repaired
Comments: Replaced damage floor tiles

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: Deteriorated
Comments: craked tiles second floor south

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Unknown Size Floor Tile Mastic	3000	SF	2nd and 3rd Floor Halls, 3rd Floor Teacher's Lounge		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: Repaired
Comments: Replaced damage floor tiles

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	9" x 9" Beige Floor Tile	300	SF	Assembly Hall		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9" x 9" Beige Floor Tile Mastic	100	SF	Assembly Hall		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	4" Red Baseboard	350	LF	Gym		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	4" Red Baseboard Mastic	300	LF	Gym		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Carpet Mastic	1000	SF	Rooms 212 and 310, Office, Kindergarten Room, and Library		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: Other
Comments:No change. Kindergarten was in room 115/116 but that is now art room please change location description from kindergaten to 115/116

2014 - Fall: Other
Comments:Room 310 not asbestos rug removed

2015 - Fall: Other
Comments:12/14 carpet in 310 removed. No asbestos

2015- Spring: Abated
Comments:310 carpet removed floor sanded and varnished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Blue Carpet Mastic	500	SF	Room 110, Office, Principal's Office, 112		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Green Carpet Mastic	750	SF	Rooms 212A Computer, Library and 310		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: Other
Comments:Room 310 not asbestos rug removed

2015 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:310 carpet removed floor sanded and varnished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Brick/Brown Multi Color Ceramic Floor Tile Grout	6200	SF	All Boys' and Girls' Washrooms on 1st, 2nd, and 3rd Floors		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Abated
Comments:1st fl Boys and girls rehabbed summer 2012

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Yellow Ceramic Wall Tile Grout	6200	SF	All Boys' and Girls' Washrooms on 1st,2nd and 3rd Floors		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Abated
Comments:1st floor boys and girls rehabbed summer 2012

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Yellow Ceramic Wall Tile Grout Adhesive	420	SF	All Boys' and Girls' Washrooms on 1st,2nd and 3rd Floors		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Abated
Comments:1st floor boys and girls rehabbed summer 2012

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Brown Carpet Mastic	120	SF	Room 312		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: Other
Comments:Change location to 312A. Room 312A positive test for asbestos

2015 - Fall: Abated
Comments:Actually room 312A. Abated 12/14

2015- Spring: Abated
Comments:312 sanded and varnished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Drywall-Wall	830	SF	Rooms 207,217 and 208		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Other
Comments:Room rehabbed summer 2012 no asbestos found

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Drywall-Compound	142	LF	Rooms 207,217 and 208		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Other
Comments:Room rehabbed summer 2012 o asbestos found

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Drywall-Wall Tape	142	LF	Rooms 207,217 and 208		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Other
Comments:Room rehabbed summer 2012 no asbestos found

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Drywall-Ceiling	102	SF	Rooms 207,217 and 208		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Other
Comments:Room Rehabbed summer 2012 no asbestos found

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Drywall-Ceiling-Compound	37	LF	Rooms 207,218 and 208		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Other
Comments:Room rehabbed sunner 2012 no asbestos found

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Drywall-Ceiling-Tape	37	LF	Rooms 207,218 and 208		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Other
Comments:Room rehabbed summer 2012 no asbestos found

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Orange Carpet Mastic	918	SF	Room 115		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	9"x 9" Brick Floor Tile	300	SF	1st Floor Principal Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	9"x9" Brick Floor Tile Mastic	300	SF	1st Floor Principal Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" Brown Floor Tile w/Brown and White Streaks	200	SF	Assembly Hall Patch, 1st Floor Principal Office and Washroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12"x12" Brwn Floor Tile w/ Brwn&Wht Streaks Mastic	200	SF	Assembly Hall Patch and 1st Floor Principal Office and Washroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12"x12" Brown Speckled Floor Tile Patch	1800	SF	Lunchroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12"x12" Brwn Speckled Floor Tile Mastic	1800	SF	Lunchroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Pre-formed Pipe Lagging	300	LF	Boiler Room		TSI	Yes	None	40		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Fittings Off Pre-formed Pipe Lagging	50	LF	Boiler Room		TSI	No	None	4		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Abated
Comments:less than 3 feet bagged and removed from around check valve domestic water booster pump pipe

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Cardboard Pipe Insulation	120	LF	Boiler Room		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Fittings Off Cardboard Pipe Insulation	50	LF	Boiler Room		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
H	Air Cell Duct Insulation	50	LF	Basement		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Pipe Fittings Off Fiberglass Pipe	50	LF	Basement		TSI	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Air Cell Pipe Insulation (Covering)	240	LF	Basement - Crawl Space		TSI	Yes	Dist	150		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Fittings Off Air Cell Pipe Runs	90	LF	Basement - Crawl Space		TSI	No	None	50		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M	Gaskets Off Boiler	20	LF	Boiler Room		TSI	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Refractory Brick - Non AHERA		SF	Boiler Room		Miscellaneous	No	Unknown	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

Lynn A. Crivello

Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Frank W Gunsaulus Scholastic Academy School

Date: 11/13/2015

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.