

Chicago Public Schools

6 Month Asbestos Surveillance

2015 - Fall

School: Stone Scholastic Academy
Address: 6239 N Leavitt Street

Oracle Unit: 29291
Region: 01

Building ID: 6070
Mail Room: 32

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: _____
Survey Date: 10/15/2015
Email Address: _____

A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via:
 Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01	Hard Coat Plaster	10000	SF	Throughout - 1951		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	Brown Linoleum	70	SF	Help Room and Store Room next to Help Room - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02A	Brown Linoleum Mastic	70	SF	Help Room and Store Room next to the Help Room - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	9"x9" Green w/ White Streaks VFT - NOT OBSERVED			Teacher's Lunchroom - 1928 - NOT OBSERVED		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03A	9"x9" Green w/ White Streaks VFT Mastic - NOT OBSERVED			Teacher's Lunchroom - 1928 - NOT OBSERVED		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12"x12" White w/ Tan Specks VFT	4500	SF	Main Office, Store Room and the 1st, 2nd and 3rd Floor Corridors - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04A	12"x12" White w/Tan Specks VFT Mastic	4500	SF	Main Office, Assistant Principal's Office, Store Room, 1st, 2nd and 3rd Floor Corridors - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	9"x9" White w/Green Streaks VFT - NOT OBSERVED			Teacher's Lunchroom - 1928 - NOT OBSERVED		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05A	9"x9" White w/Green Streaks Mastic - NOT OBSERVED			Teacher's Lunchroom - 1928 - NOT OBSERVED		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" Tan VFT	2000	SF	Rooms 111, 112, 113, 211, 212 and 213 and the Work Room - 1951		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06A	12"x12" Tan VFT Mastic	2000	SF	Rooms 111, 112, 113, 211, 212 and 213 and the Work Room - 1951		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12"x12" Blue & Gray VFT	2000	SF	Rooms 111, 112, 211, 212, Teacher's Lunchroom and the Work Room - 1951		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07A	12"x12" Blue & Gray Mastic	2000	SF	Rooms 111, 112, 211, 212, Teacher's Lunchroom and the Work Room - 1951		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	9"x9" Black VFT (Under HA20 and 20A)	850	SF	Room 211 and 212 - 1951		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08A	9"x9" Black Mastic (Under HA20 & HA20A)	850	SF	Rooms 211 and 212 - 1951		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	9"x9" Red VFT	850	SF	Rooms 211 and 212 - 1951		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09A	9"x9" Red VFT Mastic	850	SF	Rooms 211 and 212 - 1951		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" Tan w/Tan Spots VFT	2600	SF	Rooms 101 and 109 and the Auditorium - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10A	12"x12" Tan w/ Tan Spots VFT Mastic	2600	SF	Rooms 101 and 109 and the Auditorium - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" White VFT	180	SF	Rooms 111 and 112 and their entrances - 1951		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11A	12"x12" White VFT Mastic	180	SF	Rooms and the entryways to Rooms 111 and 112 - 1951		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: Damaged
Comments:on the second floor by 201 about 1/8 of the floor has to come up. but install new tile in it place

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	9"x9" Tan w/ Brown Streaks VFT	20	SF	Vestibules to Rooms 106 and 107 (Engineer's Office, Assistant Principal's Office and the Adjustment Office - NOT OBSERVED) - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12A	9"x9" Tan w/Brown Streaks VFT Mastic	20	SF	Vestibules to Rooms 106 and 107 (Engineer's Office, Assistant Principal's Office and the Adjustment Office - NOT OBSERVED) - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9"x9" Green w/ Black & White Streaks VFT	300	SF	Room 107 - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13A	9"x9" Green w/ Black & White Streaks VFT Mastic	300	SF	Room 107 - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" Black VFT	1700	SF	Auditorium - 1928		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14A	12"x12" Black VFT Mastic	1700	SF	Auditorium - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Red VFT	1700	SF	Auditorium - 1928		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15A	12"x12" Red VFT Mastic	1700	SF	Auditorium - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x24" Black VFT	1700	SF	Auditorium - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:good

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16A	12"x24" Black VFT Mastic	1700	SF	Auditorium - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Beige w/Tan Streaks VFT (over HA12)	170	SF	Engineer's Office - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17A	12"x12' Beige w/Tan Streaks VFT Mastic (over HA12)	170	SF	Engineer's Office - 1928		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Tan Mottled VFT	2000	SF	Rooms 101 and 106		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: Other
Comments:we put a rubber floor over the tile in room 101. now it a gym room

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18A	12"x12" Tan Mottled VFT Mastic	2000	SF	Rooms 101 and 106		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:good

2014- Spring: No Change
Comments:

2015 - Fall: Other
Comments:in room 101 we put a rubber floor over the tile. made it a gym room

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Blue and Tan VFT	1300	SF	Room 212		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19A	12"x12" Blue & Tan VFT Mastic	1300	SF	Room 212		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:good

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Not Used										<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20A	Not Used										<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Not Used										<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Pink Insulation	9000	SF	Attic - 1928		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:fair

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Firedoors	5	EA	Auditorium		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Asbestos Repair	20		Unfinished/Unexcavated Area - North		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" White w/tan streaks VFT	1600	SF	Library (Rooms 209 and 211)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32A	12"x12" White w/tan streaks Mastic	1600	SF	Library (Rooms 209 and 211)		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12"x12" White w/tan speckles VFT	1000	SF	Room 106, Help Room, Store Room, Office Waiting Area		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33A	12"x12" White/tan streaks Mastic	1000	SF	Room 106, Help Room, Store Room, Office Waiting Area		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:good

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Carpet Mastic	300	SF	Office and Principal's Office		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:fair

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Cardboard Pipe Insulation	1163	LF	Boiler, North and South Fan Rooms, North and South Air Tunnels and Unexcavated Areas Under Auditorium - 1928		TSI	Yes	Dist	100		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:fair

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	MJP E/F/V on Card Pipe Insulation	110	LF	Boiler, North and South Fan Rooms, North and South Air Tunnels and Unexcavated Areas Under Auditorium - 1928		TSI	Yes	Dist	2		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:fair

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	MJP E/F/V on Fiberglass Pipe Insulation	34	LF	1st, 2nd and 3rd Floor Girl's Washroom - 1928		TSI	Yes	Dist	5		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:fair

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
H	Foam Insulation - NOT OBSERVED			Throughout - 1928 - NOT OBSERVED							<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:fair

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Aircell Pipe Insulation	3395	LF	Boiler, Pump, North and South Fan Rooms, 2nd and 3rd Floor Girl's Washroom and Unexcavated Areas Under the Auditorium - 1928		TSI	Yes	Dist	7		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:fair

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	MJP E/F/V on Aircell Pipe Insulation	316	LF	Boiler, Pump, North and South Fan Rooms, 2nd and 3rd Floor Girl's Washroom and the Unexcavated Areas Under the Auditorium - 1928		TSI	Yes	Dist	10		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:fair

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Preformed Pipe Insulation	200	LF	Boiler Room and South Fan Room - 1928		TSI	Yes	Dist	5		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:fair

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	MJP E/F/V on Mag Block Pipe Insulation	36	LF	South Fan Room and Boiler Room - 1928		TSI	Yes	Dist	2		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:fair

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Aircell Duct Insulation	1745	SF	North and South Air Tunnels, North Fan Room and the Space Under the Assembly Hall - 1928		TSI	Yes	Dist	135		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:good

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
O	Hardcoat Plaster	40000	SF	Throughout - 1928		Surface	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:fair

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
P	Tank Insulation	115	SF	Boiler Room - 1928		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:fair

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	Carpet Mastic	1000	SF	Main Office and the Principal's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:fair

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	Terrazo	3000	SF	Entry Ways and Halls		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:very good

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.



Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Stone Scholastic Academy

Date: 10/15/2015

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.