

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Amundsen High School
Address 5110 N. Damen

Oracle Unit 46031 **Building ID** 1210
Region 1 **General Services Route** 31

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	9x9 White VFT	960	SF	Room 222	Chrysotile	MISC	No	None	0		
<i>3YR Inspector Comments: No change from last inspection</i>											
<i>Condition Not Changed in Fall 2010</i>											
<i>Comments:</i>											
<i>Condition Not Changed in Spring 2011</i>											
<i>Comments:</i>											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 46031

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12x12 Tan VFT	325	SF	Room 128	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: No change from last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12x12 Tan VFT Mastic	650	SF	Room 128, 221	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: No change from last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	9x9 White VFT Mastic	960	SF	Room 222	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: No change from last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19 A	12x12 White w/Beige VFT Mastic	4600	SF	Rooms 113, 205, 113, 111,117, library	Chrysotile	TSI		None	0		
3YR Inspector Comments: Add classroom 117, and the Library, beside that, no change from last inspection.											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23A	12x12 Grey VFT Mastic	2900	SF	Clubroom A & B, College Faculty, 209, Main Office & 117	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: No change from last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9x9 Green VFT	0		Engineers Office	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: No change from last inspection											
Condition Not Changed in Fall 2010					Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24A	9x9 Green VFT Mastic	260	SF	Engineers Office	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: No change from last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	9"x9" Dark Brown VFT	36	SF	Room 201	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: No change from last inspection. Summer 2009 - material removed from the 1st fl corridor.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25A	9x9 Dark Brown VFT Mastic	36	SF	Room 201	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: No change from last inspection. Summer 2009 - material removed from the 1st fl corridor.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	9x9 Light Brown VFT	1490	SF	Engineers Lounge and 306 & 201	Chrysotile	MISC	Yes	None	0		
3YR Inspector Comments: No change from last inspection. 2008 - This material is found in the space known as Assistan Engineer Office											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26A	9x9 Light Brown VFT Mastic	1490	SF	Engineers Lounge and 306 & 201	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: No change from last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27A	9x9 Red VFT Mastic	10240	SF	2nd, and 3rd floor corridors	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: The Red VFT mastic is assocatied with 33A mastic in all hallway. Summer 2009 - material removed from the 1st fl corridor on July 23, 2009											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Changed in Spring 2011			SF		Chrysotile	MISC					
Comments: Tile popping off											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32A	12"x12" Red with red streaks VFT MASTIC		SF	Room 230	Assumed	MISC	No	None	0		
3YR Inspector Comments: HA 32 Removed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33A	9x9 Black VFT Mastic	13490	SF	2nd, & 3rd Floor Corridors	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: No change from last inspection. Summer 2009 - material removed on July 23, 2009 from the 1st fl corridor.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Changed in Spring 2011			SF		Chrysotile	MISC					
Comments: Tile popping off											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36A	12x12 Brown w/Grey VFT Mastic	900	SF	Rooms 129, 229	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	9"x9" Red w/ White VFT	300	SF	Engineers Office	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38A	9"x9" Red w/ White VFT Mastic	300	SF	Engineers Office	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: Analytical results located in the 1998 3yr Reinspection Report											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	2 x 2 ft Blue VFT	2000	SF	Weight Rooms	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39 A	2' x2' blue VFT Mastic	2000	SF	Weight Rooms	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	2 x 2 ft Dot/Wave Ceiling Tile	2500	SF	Rooms: 113, 115, 230	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Salmon Linoleum	5000	SF	Rooms: 215, 217, 221, 317, 318, 321, 322, 327	Assumed	MISC	No	None	0		
3YR Inspector Comments: New lab areas											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41A	Salmon Linoleum Mastic	5000	SF	Rooms 215, 217, 221, 317, 318, 322, 321 and 327	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Carpet Mastic	1500	SF	Main Office, Room 325 & 109	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Terrazo	5000	SF	Entryways, Stairs, Lunch Room, Serving Area, Kitchen, 1st & 2nd & 3rd floor corridors, Auditorium vestibule and stairs	Assumed	MISC	No	None	0		
3YR Inspector Comments: Not a AHERA material											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12"x12" light tan with specks VFT	5000		1st floor corridors	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44 A	12"x12" light tan with specks MASTIC	5000	SF	1st floor corridors	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12"x12" Dark red VFT	300	SF	1st floor corridors	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45 A	12"x12" Dark red VFT MASTIC	308	SF	1st floor corridor	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12"x12" black with white streaks VFT	200	SF	Room 230 and corridor outside room 230	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46 A	12"x12" Black with white streaks VFT MASTIC	200		Room 230 and corridor outside romm 230	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12"x12" Red with red streaks VFT	230	SF	Room 230	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12"x12" Sand VFT	150	SF	Room 303	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48 A	12"x12" Sand VFT MASTIC	150	SF	Room 303	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Aircell Pipe Insulation	350	LF	Basement Air Tunnel, south	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments: 24 lfl of pipe insulation were removed from Air tunnel #3 at south end of basement in Summer 2009.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					
Comments:											
Fall 2011										YES	NO
Comment:											


HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	MJP E/F/V on Aircell Pipe Insulation	15	LF	Basement Air Tunnel, South	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	MJP E/F/V on Fiberglass Pipe Insulation	50	LF	Rooms: 121, 221, 218	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments: 2008 - Material was not observed during the February 6, 2008 audit visit. IDPH format Abatement Report has removal info regarding TSI in Rm. 218.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

All LEA Responsibilities, for this school, will be met.



Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 46031

Page 14

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.