

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Foreman High School
Address 3235 N. LeClaire Ave.

Oracle Unit 46131 **Building ID** 1330
Region 1 **General Services Route** 29

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
01	Boiler Gasket #1	4	SF	Boiler Room	Chrysotile	TSI	Yes	None	0				
<i>3YR Inspector Comments:</i>													
Condition Not Changed in Fall 2010													
<i>Comments:</i>													
Condition Not Changed in Spring 2011													
<i>Comments:</i>													
Fall 2011												YES	NO
<i>Comment:</i>													

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 46131

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	Boiler Gasket #2	4	SF	Boiler Room	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010											
Comments:											
Condition Not Changed in Spring 2011											
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	Boiler Gasket #3	4	SF	Boiler Room	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010											
Comments:											
Condition Not Changed in Spring 2011											
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	Boiler Gasket #4	4	SF	Boiler Room	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010											
Comments:											
Condition Not Changed in Spring 2011											
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	12" x 12" Peach w/ Gray Specks VFT	1600	SF	Room 322, 318	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	12" x 12" Peach w/ Gray Specks VFT Mastic	1600	SF	Room 322, 318	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	2' x 2' Ceiling Tile	800	SF	Room 225	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	2' x 4' White Dot Ceiling Tile	1200	SF	Boys Lockerroom, Room 125	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	1' x 1' White Dot Ceiling Tile	650	SF	Lunchroom, Serving Area	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	Drywall	5200	SF	Room 115, 124, 126, 228, 306	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	Drywall Joint Compound	1500	SF	Room 115, 124, 126, 228, 306	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	Beige Linoleum	800	SF	Room 225	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	Beige Linoleum Mastic	800	SF	Room 225	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
109	12 x 12 inch Beige w/Dark Streaks VFT	1500	SF	Rooms 100, 102, 104	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	Terrazo	5000	SF	All Stairwells and Corridors	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	Carpet Mastic	7000	SF	Rooms:110, 112, 123, 129, 222,	Assumed	MISC	No	None	0		
3YR Inspector Comments: The following, originally under this HA, have been included in new HAs during the 2010 Re-inspection: Main Office (new HA 114); Rm 115 (new HAs 115 and 115A); Rms 127, and 224 (both in new HAs 117 and 117A).											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	Textured Ceiling Plaster	1500	SF	Library	Assumed	SURFACE	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	SURFACE					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	SURFACE					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	12"x12" Beige w/Dark Streaks VFT Mastic	1500	SF	Rooms 100, 102, 104	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114	2'X4' White Grooved Ceiling Tiles	800	SF	Main Office Area, Principal's Office	Assumed	MISC	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
115	12"X12" Gray-Streaked Floor Tiles	3000	SF	Rms 111, 113, 115, and 117	Assumed	MISC	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
115A	12"X12" Gray-Streaked Floor Tiles Mastic	3000	SF	Rms 111, 113, 115, and 117	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116	12"X12" White w/Gray Streaks VFT	4000	SF	Auditorium	Assumed	MISC	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116A	12"X12" White w/Gray Streaks VFT Mastic	4000	SF	Auditorium	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
117	12"X12" Off-White w/Gray Streaks VFT	2250	SF	Rms 125, 127, 224	Assumed	MISC	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
117A	12"X12" Off-White w/Gray Streaks VFT Mastic	2250	SF	Rms 125, 127, 224	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
118	Trowled on Plaster	5000	SF	Auditorium	Assumed	SURFACE	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	SURFACE					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	SURFACE					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
119	12'X12" White w/Gray Streaks VFT	6000	SF	Throughout All Classrooms and Hallways in Both 2003 and Mobile Units	Assumed	MISC	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
119A	12'X12" White w/Gray Streaks VFT Mastic	6000	SF	Throughout All Classrooms and Hallways in Both 2003 and Mobile Units	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
120	2'X2' White Ceiling Tiles	6000	SF	Throughout All Classrooms and Hallways in Both 2003 and Mobile Units	Assumed	MISC	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
121	Vinyl Baseboard Mastic	1200	SF	Throughout Both 2003 and Mobile Units	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
122	Fire Doors (2 Each)	4		Mechanical Rooms in Both 2003 and Mobile Units	Assumed	MISC	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
123	Blue Linoleum	200	SF	Boys Restrooms in Both 2003 and Mobile Units	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
123A	Blue Linoleum Mastic	200	SF	Boys Restrooms in Both 2003 and Mobile Units	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
124	Pink Linoleum	200	SF	Girls Toilets in Both 2003 and Mobile Units	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
124A	Pink Linoleum Mastic	200	SF	Girls Toilets in Both 2003 and Mobile Units	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	MJP E/F/V on Fiberglass Pipe Insulation	500	LF	All Toilet Pipe Chases & Room 217	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Vibration Joint Material	20	SF	Basement & NW Fan Room	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	9"x9" Green w/ White Streaks VFT	9095	SF	1st and 2nd Floor Corridor, Library, & Engineer's Office and Closet	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	9"x9" Green w/ White Streaks VFT Mastic	9095	SF	1st and 2nd Floor Corridor, Library, & Engineer's Office and Closet	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	9"x9" Green w/ Gray Streaks VFT	1440	SF	Rooms 312 & 314	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	9"x9" Green w/ Gray Streaks VFT Mastic	1440	SF	Rooms 312 & 314	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12"x12" Off White w/ Gray Streaks VFT	3700	SF	Rooms 328 (Hard Wood), 122, 124, 126, 123 A, 123 B	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: Rm 328 was found having a hard-wood floor during 2010 Re-inspection.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	12"x12" Off White w/ Gray Streaks VFT Mastic	3700	SF	Rooms 328 (Hard Wood), 122, 124, 126, 123 A (Under Carpet), 123 B (Under Carpet)	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: Rm 328 was found having a hard-wood floor during 2010 Re-inspection.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	9"x9" Gray w/ White & Black Streaks VFT	9999	SF	1st and 2nd Floor Hall, Rm 128 and Engineer's Office and Closet, Vault	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: Rm 113, originally under this HA, has been included in a new HA (#115) during the 2010 Re-inspection.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	9"x9" Gray w/ White & Black Streaks VFT Mastic	9999	SF	1st and 2nd Floor Hall, Rm 128 and Engineer's Office and Closet, Vault	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: Rm 113, originally under this HA, has been included in a new HA (#115A) during the 2010 Re-inspection.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	9"x9" Gray w/ Pink, White, & Black Streaks VFT	1550	SF	Room 213 & 215	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	9"x9" Gray w/ Pink, White, & Blk Strks VFT Mastic	1550	SF	Room 213 & 215	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	12"x12" Brown w/ White & Black Streaks VFT	1200	SF	Rooms 218 , 220	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: Auditorium, originally under this HA, has been included in a new HA (#116) during the 2010 Re-inspection.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	12"x12" Brown w/ White & Black Streaks VFT Mastic	1200	SF	Rooms 218 & 220	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: Auditorium, originally under this HA, has been included in a new HA (#116A) during the 2010 Re-inspection.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	1'x2' Black VFT	120	SF	Room 128, 129 (Under Carpet)	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	1'x2' Black VFT Mastic	120	SF	Room 128, 129 (Under Carpet)	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12'x12" Sand w/ White Streaks VFT	880	SF	Main Office & Principal's Office	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	Table Tops	200	SF	Room 317, 318, 321, 322	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	Exterior Window Caulk	1000	LF	Exterior Windows	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CM-001	Brown Capet Adhesive	350	SF	Room 129	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-001	9x9 Green Floor Tile	350	SF	Room 128	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.


HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM-001	9x9 Green Floor Tile Mastic	350	SF	Room 128	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
TSI-001	MJP E/F/V	100	LF	Boiler Room	Assumed	TSI	Yes	Dist	30	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Assumed	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

All LEA Responsibilities, for this school, will be met.



Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.