

# Chicago Public Schools

## 6 Month Asbestos Surveillance

Fall 2011

**School** Kelvyn Park High School  
**Address** 4343 W. Wrightwood Ave.

**Oracle Unit** 46191 **Building ID** 1410  
**Region** 2 **General Services Route** 29

**Asbestos Surveyor:** \_\_\_\_\_

**Survey Date:** \_\_\_\_\_

**E-mail Address:** \_\_\_\_\_

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:**

*Each child's backpack*    
  *Notice printed in school's newsletter/calendar*    
  *Other* \_\_\_\_\_

**Principal Signature** \_\_\_\_\_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	<b>Change in Assessment Category</b>	
001A	1'x1' Black w/ White Streaks Floor Tile	13500	SF	1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206 - 1918 Bldg.	Chrysotile	MISC	No	None	0	SF		
<i>3YR Inspector Comments:</i>												
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF		
<i>Comments: 1st tiles replaced</i>												
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF		
<i>Comments:</i>												
<b>Fall 2011</b>											<b>YES</b>	<b>NO</b>
<b>Comment:</b>												

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 46191

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
004A	1'x1' Black w/ White Streaks Floor Tile Mastic	13500	SF	1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206 - 1918 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: yes 1st floor tiles replaced											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
006A	1'x1' Black w/ Brown Streaks Floor Tile	900	SF	3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Inspector did not observe these tiles in Rooms 319, 323 & 327. No abatement records on site											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
007A	9"x9" Dark Red Floor Tile	4000	SF	1st 2nd & 3rd Floor Corridors - 1928 Bldg	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: 1st fl tiles replaced											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
008A	1'x1' Black w/ Brown Streaks Floor Tile Mastic	2400	SF	3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
009A	9"x9" Dark Red Floor Tile Mastic	4000	SF	1st 2nd & 3rd Floor Corridors - 1928 Bldg	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: 1st floor replaced											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
017	Boiler Gasket (Removed)			Boiler Room - 1918 Bldg	Chrysotile	TSI	Yes				
3YR Inspector Comments: The boiler has been replaced. No abatement records on site.											
Condition Not Changed in Fall 2010					Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	TSI					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
018	Boiler Insulation (Removed)			Boiler Room - 1918 Bldg	Chrysotile	TSI	Yes				
3YR Inspector Comments: The boiler has been replaced. No abatement records on site.											
Condition Not Changed in Fall 2010					Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	TSI					
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
019	Boiler Lagging (Removed)			Boiler Room - 1918 Bldg	Chrysotile	TSI	Yes				
3YR Inspector Comments: The boiler has been replaced. No abatement records on site.											
Condition Not Changed in Fall 2010					Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	TSI					
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
020	Boiler Brick - REMOVED			Boiler Room - 1918 Bldg	Chrysotile	TSI					
3YR Inspector Comments: The boiler has been replaced. No abatement records on site.											
Condition Not Changed in Fall 2010					Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	TSI					
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
040	Vent Debris (Removed)			Inside Ducts - Throughout 1918 Bldg	Chrysotile	MISC	Yes				
3YR Inspector Comments: This material was not observed. No abatement records on site.											
Condition Not Changed in Fall 2010					Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
057	Cardboard Pipe Insulation (Removed)			1st Floor Janitor Closet (West) - 1918 Bldg.	Chrysotile	TSI	Yes				
3YR Inspector Comments: This insulation was not observed. No abatement records on site.											
Condition Not Changed in Fall 2010					Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	TSI					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
058	Aircell Pipe Insulation (Removed)			1st Floor Janitor Close tWest) - 1918 Bldg.	Chrysotile	TSI					
3YR Inspector Comments: This insulation has been removed. No abatement records on site.											
Condition Not Changed in Fall 2010					Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	TSI					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
080	MJP E/F/V on Fiberglass Pipe Insulation	150	SF	1st Floor: Men's Toilet Pipe Chases, Rooms 119 & 123 - 1928 Bldg.	Assumed	TSI	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	TSI				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
087	1'x1' Brown w/ White Streaks Floor Tile	4200	SF	Room 398, 300, 302, 304, 311 - 1918 Bldg	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
087A	1'x1' Brown w/ White Streaks Floor Tile Mastic	4200	SF	Room 398, 300, 302, 304, 311 - 1918 Bldg	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
088	1'x1' Off White w/ Speckles Floor Tile	6400	SF	Room 398, 300, 302, 304, 311 - 1918 Bldg	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
088A	1'x1' Off White w/ Speckles Floor Tile Mastic	6400	SF	Room 398, 300, 302, 304, 311 - 1918 Bldg	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
090	1'x1' Green W/White Speckles Floor Tile	2500	SF	2nd Floor Kitchen - 1928	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
090A	1'x1' Green w/White Speckles Floor Tile Mastic	2500	SF	2nd Floor Kitchen - 1928 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
092	9"x9" Gray w/ Speckles Floor Tile	5000	SF	Main Offices (211), Auditorium, 201 - 1918 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
092A	9"x9" Gray w/Speckles VFT Mastic	5000	SF	Main Offices (211), Auditorium, 201 - 1918 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
093	9"x9" Light Brown Floor Tile	2700	SF	Room 205, 107 Closet, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Room 205 is carpeted. No abatement records are on site. It is assumed the floor tile are beneath the carpet.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
093A	9"x9" Light Brown Floor Tile Mastic	3000	SF	Room 205, 107 Vloset, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Room 205 is carpeted. No abatement records are on site. It is assumed the floor tile are beneath the carpet.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
094	9"x9" Beige w/ Green Streaks Floor Tile	750	SF	Room 211 - 1918 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
094A	9"x9" Beige w/ Green Streaks VFT Mastic	1200	SF	Room 211 - 1918 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
097	9"x9" Black Floor Tile	6000	SF	1st, 2nd & 3rd Floor Corridors - 1928 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: 1st floor tiles replaced											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
097A	9"x9" Black Floor Tile Mastic	6000	SF	1st, 2nd & 3rd Floor Corridors - 1928 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: 1st floor tiles replaced											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
098	1'x1' Light Brown w/ White & Dark Streaks Floor Tile	4800	SF	Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129 - 1928 - 1928 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: 1st floor retiled.											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
098A	1'x1' Light Brown w/ White & Dark Strks Floor Tile Mastic	4800	SF	Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129 - 1928 - 1928 Bldg.	Anthophyllite	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Anthophyllite	MISC				SF	
Comments: 1st floor retiled											
Condition Not Changed in Spring 2011			SF		Anthophyllite	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
099	1'x1' Gray Floor Tile	5500	SF	3rd Fl: Computer Rm & Off; Rms: 113, 117, 123, 216, 220, 221 & 227 - 1928 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
099A	1'x1' Gray Floor Tile Mastic	5500	SF	3rd Fl: Computer Rm & Off; Rms: 113, 117, 123, 216, 220, 221 & 227 - 1928 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	1'x1' Light Brown VFT	1800	SF	3rd Floor Corridor to Room 314; Rooms: 121, 220 Entry, 223 & 227 - 1928 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100A	1'x1' Light Brown Floor Tile Mastic	3300	SF	3rd Floor Corridor to Room 314; Rooms: 121, 223 & 227 - 1928 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	1'x1' Light Pink Floor Tile	1600	SF	Rooms: 113, 125, 221 & 223 - 1928 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101A	1'x1' Light Pink Floor Tile Mastic	1600	SF	Rooms: 113, 125, 221 & 223 - 1928 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	1'x1' Light Brown w/ Speckles Floor Tile	1600	SF	Rooms: 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102A	1'x1' Light Brown w/ Speckles Floor Tile Mastic	1600	SF	Rooms: 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	1'x1' Light Beige w/ White Streaks Floor Tile	1600	SF	Rooms 121, 123 & 125 - 1928 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103A	1'x1' Beige w/ White Streaks VFT Mastic	1600	SF	Rooms 121, 123 & 125 - 1928 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	12"x12" Blue Floor Tile	2150	SF	Room 312, Gym, ROTC, Library (100) - 1918	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Carpet in the Library and wood floor in the gym.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	12"x12" Blue Floor Tile Mastic	2150	SF	Room 312, Gym, ROTC, Library (100) - 1918	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Carpet in the Library and wood floor in the gym.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	12"x12" Tan w/ Brown & White Spots VFT	4000	SF	099, 101, 103, 107, 109, 111, 309, 2nd Floor Hall Lockers - 1918	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	12"x12" Tan w/ Brown & White Spots VFT Mastic	4000	SF	099, 101, 103, 107, 109, 111, 309, 2nd Floor Hall Lockers - 1918	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	12"x12" Grey W/ Specks VFT	6000	SF	1st Floor Corridor, Engineers Office - 1928	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
109	12"x12" Grey W/ Specks VFT Mastic	6000	SF	1st Floor Corridor, Engineers Office - 1928	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	Blue Linoleum	4800	SF	Rooms: 113, 125, 221, 223, 225, 227	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110 A	Blue Linoleum Mastic	4800	SF	Rooms: 113, 125, 221, 223, 225, 227	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	12"x12" Black w/White Specks Floor Tile	800	SF	1928 Bldg: Music Room, 313, 319, 323, 327	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: These tiles were not identified in previous inspections											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111A	12"x12" Black w/White Specks Floor Tile Mastic	800	SF	1928 Bldg: Music Room, Rooms 313, 319, 323, and 327	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: This mastic was not identified in previous inspections											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	12"x12" Blue w/White Specks Floor Tile	700	SF	Music Room (313)	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: These tiles were not identified in previous inspections											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112A	12"x12" Blue w/White Specks Floor Tile Mastic	700	SF	Music Room (313)	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: This mastic was not identified in previous inspections											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 46191

Page 18

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	12"x12" White w/Specks Floor Tile	1400	SF	Room 316 and 1st Floor Corridor	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: These tiles were recently installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113A	12"x12" White w/Specks Floor Tile Mastic	1400	SF	Room 316 and 1st Floor Corridor	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: This mastic was recently installed											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: 1st floor retiled											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114	12"x12" Light Blue w/Specks Floor Tile	1400	SF	2nd Floor Lunchroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: These tiles were recently installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114A	12"x12" Light Blue w/Specks Floor Tile Mastic	1400	SF	2nd Floor Lunchroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: This mastic was recently installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
115	Blue Carpet Adhesive	3800	SF	Library, Main Office, Principal's Office and Rooms 104 and 211	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: This carpet was recently installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116	12"x12" Ceramic Tile Grout	100	SF	Main Office	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: These tiles were recently installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
117	12"x12" Ceramic Tile Adhesive	100	SF	Main Office	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: These tiles were recently installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	Aircell Pipe Insulation (Removed)			SW Unexcavated Area - 1928	Chrysotile	TSI	Yes				
3YR Inspector Comments: No aircell was found in this location. No abatement records on site. The unexcavated area contains fiberglass pipe insulation											
Condition Not Changed in Fall 2010					Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	TSI					
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	2'x4' White Wormy Ceiling Tile	1500	SF	Rooms: 206 Closet, 208 & 398 - 1918 Bldg.	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C	2'x4' Multiple Color 1/4" Wormy Ceiling Tile			Rooms 200 & 300 - 1918 Bldg.	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	2'x4' Dk Wht w/Multi Color 1/2" Wormy Ceiling Tile	900	SF	Rooms 104 & 300 - 1918 Bldg.	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	2'x4' Off White Large Wormy Ceiling Tile	300	SF	Room 208 - 1918 Bldg.	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	1'x1' Off White Wormy Ceiling Tile	2400	SF	ROTC, ROTC Office, Rooms 110 & 212, Engineer's Office - 1918 Bldg.	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	1'x1' Off White Large Wormy Ceiling Tile	1500	SF	ROTC, Room 212, Cafeteria by Lunchroom & Auditorium - 1918 Bldg.	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
H	Spray - On Walls & Beams	800	SF	3rd Floor Computer Room - 1928 Bldg.	Assumed	SURFACE	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	SURFACE				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	SURFACE				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	18"x18" Dirty White Ceiling Tile	1000	SF	3rd Floor Music Room - 1928 Bldg.	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	1'x1' Dirty White Ceiling Tile	200	SF	Room 314 East & West Vestibule - 1928 Bldg.	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	2'x4' Multiple Color 1/2" Wormy Ceiling Tile	2400	SF	3rd Fl: Computer Rm & Office, S Computer Rm by Stairwell, Rms: 127 & 220 - 1928 Bldg.	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	1'x1' White Wormy Ceiling Tile	1400	SF	Rooms 123 and 213 - 1928 Bldg.	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											


HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M	Transite Table Tops	160	SF	Rooms: 123, 125 - 1928 Bldg. (129 Abated in 2003)	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Sheeted Walls	800	SF	1st Floor Supply Storage near Exit - 1928 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

*All LEA Responsibilities, for this school, will be met.*



*Lynn A. Crivello*

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

**NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: \_\_\_\_\_

Date: \_\_\_\_\_

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

*VFT = Vinyl Floor Tile*

*Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.*

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125