

# Chicago Public Schools

## 6 Month Asbestos Surveillance

Fall 2011

**School** Lane Tech High School  
**Address** 2501 W. Addison

**Oracle Unit** 46221 **Building ID** 1440  
**Region** 1 **General Services Route** 35

*Asbestos Surveyor:* \_\_\_\_\_

*Survey Date:* \_\_\_\_\_

*E-mail Address:* \_\_\_\_\_

**CHECK HERE IF NO CHANGE TO ASBESTOS**

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

*Each child's backpack*

*Notice printed in school's newsletter/calendar*

*Other* \_\_\_\_\_

**Principal Signature** \_\_\_\_\_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	<b>Change in Assessment Category</b>	
110	12" x 12" White Floor Tile	700	SF	Tobacco Store and Barbershop	Assumed	MISC	No	None	0	SF		
<i>3YR Inspector Comments:</i>												
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF		
<i>Comments:</i>												
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF		
<i>Comments:</i>												
<b>Fall 2011</b>											<b>YES</b>	<b>NO</b>
<b>Comment:</b>												

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 46221

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	12" x 12" White Floor Tile Mastic	700	SF	Tobacco Store and Barber Shop	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Engineer insisted this area dose not exist.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											<b>YES      NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Aircell Pipe Insulation	1300	LF	Unexcavated Areas, Pipe Chases - 1931; Rms 251, 253, and 153D.	Chrysotile	TSI	Yes	Dist	10	LF	
3YR Inspector Comments: 2007 - No change since last inspection. Spring 2009 - abatement project within flrs. 12,3,4 SE boy's restrooms. Summer 2009 - abatement project within flrs. 1,2,3,4 SW girls' restrooms. During the 2010 Re-inspection conducted on 3-25-10, child-occupied classrooms 251, 253, and 153D had significantly damaged friable TST ACBM. Emergency abatement of Rms 251 and 253 was performed by Galaxy Environmental on 3-31-10; Rm 153D was patched up by School Engineer.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											<b>YES      NO</b>
<b>Comment:</b>											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	MJP E/F/V on Aircell Pipe Insulation	98	LF	Unexcavated Areas, Pipe Chases - 1931; Rms 251, 253, and 153D	Chrysotile	TSI	Yes	Dist	1	LF	
3YR Inspector Comments: 2007 - No change since last inspection. Spring 2009 - abatement project within flrs. 12,3,4 SE boy's restrooms. Summer 2009 - abatement project within flrs. 1,2,3,4 SW girls' restrooms During the 2010 Re-inspection conducted on 3-25-10, child-occupied classrooms 251, 253, and 153D had significantly damaged friable TST ACBM. Emergency abatement of Rms 251 and 253 was performed by Galaxy Environmental on 3-31-10; Rm 153D was patched up by School Engineer.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Light Blue w/ Dark Spots Linoleum	1200	SF	Room 115 - 1931	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Light Blue w/ Dark Spots Linoleum Mastic	1200	SF	Room 115 - 1931	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	2x4' White w/ Holes & Grooves Ceiling Tile	1200	SF	Room 115 - 1931	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Drywall	500	SF	Room 115 - 1931	Assumed	MISC	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Drywall Joint Compound	100	LF	Room 115 - 1931	Assumed	MISC	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Vinyl Baseboard	150	LF	Room 115 - 1931	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Vinyl Baseboard Mastic	150	LF	Room 115 - 1931	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AA	Stage Door	1000	SF	Auditorium Stage - 1931	Chrysotile	MISC	Yes	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AAA	2x 2' ceiling tile; fissured, White	800	SF	Room 445, Art Area corridor	Assumed	MISC	Yes	Loc	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BBB	Acoustical Wall tile, fissured	450	SF	Room 252	Assumed	MISC	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CCC	Textured Plaster, Walls and Ceiling		SF	1st floor corridor by main office, Auditorium, Room 202	Assumed	SURFACE	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	SURFACE					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	SURFACE					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CT1	2 x 4 ft Ceiling Tiles with Grooves	800	SF	Engineer's Office	Assumed	MISC	Yes	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
DDD	Teroazzo Floor		SF	Corridor and stairwells	Assumed	SURFACE	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	SURFACE					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	SURFACE					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FF	Aircell Duct Insulation	2000	SF	SW Unexcavated Area - 1931	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT11	12"x12" Dark Brown w/ Black Streaks VFT	16270	SF	Room 443, 129 - 1931	Assumed	MISC	No	None	0		
3YR Inspector Comments: Summer 2009 - abatement in SW corner of 1st fl Auditorium rm 109.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT12	12"x12" Peach VFT	2520	SF	Rooms 132, 203, 338, 342, 432 - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: Removed from Room 432. Otherwise, No Change. 2007-Not present in rooms 134, 217, 302A During 2010 re-inspection, removed from Rm 432.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT14	9"x9" Off White w/ Gray Streaks VFT	4000	SF	Lunchroom - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT15	9"x9" Green VFT	4000	SF	Lunchroom - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT16	9"x9" Beige w/ Brown Streaks VFT	3300	SF	Serving Area - 1931 , 217	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - Add room 217											
Condition Changed in Fall 2010			SF		Chrysotile	MISC					
Comments: Removal of tile and mastic on serving line completed 7/8/10. New VCT flooring installed by Accurate General. Nationwide env. PO #10-1-49027											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT17	12"x12" White w/ Brown Specks VFT	950	SF	Kitchen, Rooms 123 & 100W - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT18	12"x12" Beige w/ Wavy Brown VFT	1800	SF	Kitchen - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT19	9"x9" Black w/ White Streaks VFT	210	SF	Lunchroom, Storage, & Engineer's Office - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT20	9"x9" Maroon w/ White Streaks VFT	710	SF	Lunchroom, Storage, Room 118A, & Engineer's Office - 1931	Chrysotile	MISC	No	Loc	100	SF	
3YR Inspector Comments: 2007- Damaged floor tile in room 118A											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT22	12"x12" Gray w/ White & Brown Specks VFT	2737	SF	Girl's Locker Room Office, Shower Office, Storage, Laundry, 439, 431, 438, 342 - 1975	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT29	12 x 12 inch White w/Tan Streaks VFT	800	SF	Engineer's Office	Assumed	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT30	12 x 12 inch Pink VFT	800	SF	Room 146	Assumed	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT4	12"x12" Beige w/ Brown & White Specks VFT	49000	SF	Throughout (See Hatching Maps) - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection Summer 2009 abatement project in entryway to 2nd fl Library											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT5	9"x9" Peach VFT	5218	SF	Throughout (See Hatching Maps) - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT7	12"x12" Green VFT	1884	SF	Driver's Education Building - 1975	Chrysotile	MISC	No	Dist	206	SF	
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT8	12"x12" Gray w/ White Streaks VFT	2400	SF	Rooms 144, 322, 336, 449 - 1931	Chrysotile	MISC	No				
3YR Inspector Comments: 2007 - Exposed wood floor in room 346 During the 2010 Re-inspection, most probably removed from Rm 449; may still be under HA# FT9.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
KK	Tan Rubber Flooring	600	SF	Old Dishwasher Room	Assumed	MISC	No	Loc	5	SF	
3YR Inspector Comments: 2007 - Small area 5SF is peeling.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
LM10	Brown Linoleum Mastic	900	SF	Rooms 128, - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - Not present in room 133											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M10	9"x9" Peach VFT Mastic	5218	SF	Throughout (See Hatching Maps) - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M12	12"x12" Green VFT Mastic	5000	SF	Driver's Education Building - 1975	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M13	12"x12" Gray w/ White Streaks VFT Mastic	5400	SF	Rooms 144, 322, 336, 346, 449,133 - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M14	12"x12" Sand VFT Mastic	5150	SF	Rooms 447, 147, 145, & 143, 116 - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection. Analytical results located in the 1998 3yr Reinspection Report											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M16	12"x12" Dark Brown w/ Black Streaks VFT Mastic	16270	SF	Corridors & Auditorium - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection Summer 2009 abatement project in SW corner of 1st fl Auditorium rm 109											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M17	12"x12" Peach VFT Mastic	2420	SF	Rooms 132, 134, 203, 217, 302A, 338, - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M19	9"x9" Off White w/ Gray Streaks VFT Mastic	4000	SF	Lunchroom - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M20	9"x9" Green VFT Mastic	4000	SF	Lunchroom - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M21	9"x9" Beige w/ Brown Streaks VFT Mastic	4300	SF	Serving Area - 1931, 134	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M22	12"x12" White w/ Brown Specks VFT Mastic	650	SF	Kitchen, Rooms 123 - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M23	12"x12" Beige w/ Wavy Brown VFT Mastic	3500	SF	Kitchen, 232 - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - Present in room 232											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M24	9"x9" Black w/ White Streaks VFT Mastic	210	SF	Lunchroom, Storage, & Engineer's Office - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M25	9"x9" Maroon w/ White Streaks VFT Mastic	910	SF	Lunchroom, Storage, Room 118A, & 2 Engineer's Office's - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>										YES	NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M27	12"x12" Gray w/ White & Brown Specks VFT Mastic	2737	SF	Girl's Locker Room Office, Shower Office, Storage, & Laundry - 1975	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M29	12 x 12 inch White w/Tan Streaks VFT Mastic	800	SF	Engineer's Office	Assumed	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M30	12 x 12 inch Pink VFT Mastic	800	SF	Room 146	Assumed	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**


HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M31	Carpet Mastic	2400		Rooms: 130, 210, 235, 330, 205, 212, 213	Assumed	MISC	No	None	0		
3YR Inspector Comments: 2007 - Not found in 256 and 232. No room # 266											
Condition Not Changed in Fall 2010					Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M9	12"x12" Beige w/ Brown & White Specks VFT Mastic	49000	SF	Throughout - 1931	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection Summer 2009 - abatement project in Entryway to 2nd fl Library											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*All LEA Responsibilities, for this school, will be met.*



*Lynn A. Crivello*

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 46221

Page 21

**Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125**

**NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: \_\_\_\_\_

Date: \_\_\_\_\_

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

*VFT = Vinyl Floor Tile*

*Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.*

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125