

Chicago Public Schools

School Lane Tech High School
Address 2501 W. Addison

Chicago, IL 60618-

Unit 1440 Building ID 1440
Region 1 General Services Route 31

Fall 2009

6 Month Asbestos Surveillance

Asbestos Surveyor: _____

Survey Date: _____

Contact Phone #: _____

Check here if no change.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	12" x 12" White Floor Tile	700	SF	Tobacco Store and Barbershop	Assumed	MISC	No	None		SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC				SF	
Comments: No tobacco store or barbershop located in school											
Condition Changed in Fall 2008			SF		Assumed	MISC				SF	
Comments: No tobacco store or barbershop located in school.											
Condition Not Changed in Spring 2009			SF		Assumed	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	12" x 12" White Floor Tile Mastic	700	SF	Tobacco Store and Barber Shop	Assumed	MISC	No	None		SF	
3YR Inspector Comments: Engineer insisted this area dose not exist.											
Condition Not Changed in Fall 2007			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC				SF	
Comments: No tobacco store or barber shop located in school.											
Condition Changed in Fall 2008			SF		Assumed	MISC				SF	
Comments: No tobacco store or barbershop located in school.											
Condition Not Changed in Spring 2009			SF		Assumed	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Aircell Pipe Insulation	1300	LF	Unexcavated Areas, Pipe Chases - 1931	Chrysotile	TSI	Yes	Dist	50	LF	
3YR Inspector Comments: 2007 - No change since last inspection. Spring 2009 - abatement project within flrs. 12,3,4 SE boy's restrooms. Summer 2009 - abatement project within flrs. 1,2,3,4 SW girls' restrooms											
Condition Not Changed in Fall 2007			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2008			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Fall 2008			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2009			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	MJP E/F/V on Aircell Pipe Insulation	98	LF	Unexcavated Areas, Pipe Chases - 1931	Chrysotile	TSI	Yes	None			
3YR Inspector Comments: 2007 - No change since last inspection. Spring 2009 - abatement project within flrs. 12,3,4 SE boy's restrooms. Summer 2009 - abatement project within flrs. 1,2,3,4 SW girls' restrooms											
Condition Not Changed in Fall 2007			LF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2008			LF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Fall 2008			LF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2009			LF		Chrysotile	TSI					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AA	Stage Door	1000	SF	Auditorium Stage - 1931	Chrysotile	MISC	Yes	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AAA	2'x 2' ceiling tile; fissured, White	800	SF	Room 445, Art Area corridor	Assumed	MISC	Yes				
3YR Inspector Comments:											
Condition Not Changed in Spring 2009											
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BBB	Acoustical Wall tile, fissured	450	SF	Room 252	Assumed	MISC	Yes				
3YR Inspector Comments:											
Condition Not Changed in Spring 2009											
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CCC	Textured Plaster, Walls and Ceiling		SF	1st floor corridor by main office, Auditorium, Room 202	Assumed	SURFACE	Yes				
3YR Inspector Comments:											
Condition Not Changed in Spring 2009											
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
CT1	2 x 4 ft Ceiling Tiles with Grooves	800	SF	Engineer's Office	Assumed	MISC	Yes	None				
3YR Inspector Comments: 2007 - No change since last inspection												
Condition Not Changed in Fall 2007			SF		Assumed	MISC						
Comments:												
Condition Not Changed in Spring 2008			SF		Assumed	MISC						
Comments:												
Condition Not Changed in Fall 2008			SF		Assumed	MISC						
Comments:												
Condition Not Changed in Spring 2009			SF		Assumed	MISC						
Comments:												
Fall 2009												YES NO
Comment:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
DDD	Teroazzo Floor		SF	Corridor and stairwells	Assumed	SURFACE	No					
3YR Inspector Comments:												
Condition Not Changed in Spring 2009			SF		Assumed	SURFACE						
Comments:												
Fall 2009												YES NO
Comment:												

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FF	Aircell Duct Insulation	2000	SF	SW Unexcavated Area - 1931	Chrysotile	TSI	Yes	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	TSI					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT12	12"x12" Peach VFT	2520	SF	Rooms 132, 203, 338, 342, 432 - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: Removed from Room 432. Otherwise, No Change. 2007-Not present in rooms 134, 217, 302A											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT14	9"x9" Off White w/ Gray Streaks VFT	4000	SF	Lunchroom - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT15	9"x9" Green VFT	4000	SF	Lunchroom - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT16	9"x9" Beige w/ Brown Streaks VFT	3300	SF	Serving Area - 1931 , 217	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - Add room 217											
Condition Not Changed in Fall 2007											
Comments:											
Condition Not Changed in Spring 2008											
Comments:											
Condition Not Changed in Fall 2008											
Comments:											
Condition Not Changed in Spring 2009											
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT17	12"x12" White w/ Brown Specks VFT	950	SF	Kitchen, Rooms 123 & 100W - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007											
Comments:											
Condition Not Changed in Spring 2008											
Comments:											
Condition Not Changed in Fall 2008											
Comments:											
Condition Not Changed in Spring 2009											
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT18	12"x12" Beige w/ Wavy Brown VFT	1800	SF	Kitchen - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT19	9"x9" Black w/ White Streaks VFT	210	SF	Lunchroom, Storage, & Engineer's Office - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT20	9"x9" Maroon w/ White Streaks VFT	710	SF	Lunchroom, Storage, Room 118A, & Engineer's Office - 1931	Chrysotile	MISC	No	Loc	100	SF	
3YR Inspector Comments: 2007- Damaged floor tile in room 118A											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT22	12"x12" Gray w/ White & Brown Specks VFT	2737	SF	Girl's Locker Room Office, Shower Office, Storage, Laundry, 439, 431, 438, 342 - 1975	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT29	12 x 12 inch White w/Tan Streaks VFT	800	SF	Engineer's Office	Assumed	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT30	12 x 12 inch Pink VFT	800	SF	Room 146	Assumed	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT4	12"x12" Beige w/ Brown & White Specks VFT	49000	SF	Throughout (See Hatching Maps) - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection Summer 2009 abatement project in entryway to 2nd fl Library											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT5	9"x9" Peach VFT	5218	SF	Throughout (See Hatching Maps) - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT7	12"x12" Green VFT	1884	SF	Driver's Education Building - 1975	Chrysotile	MISC	No	Dist	206	SF	
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT8	12"x12" Gray w/ White Streaks VFT	2400	SF	Rooms 144, 322, 336, 449 - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - Exposed wood floor in room 346											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
KK	Tan Rubber Flooring	600	SF	Old Dishwasher Room	Assumed	MISC	No	Loc	5	SF	
3YR Inspector Comments: 2007 - Small area 5SF is peeling.											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					SF
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
LM10	Brown Linoleum Mastic	900	SF	Rooms 128, - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - Not present in room 133											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M10	9"x9" Peach VFT Mastic	5218	SF	Throughout (See Hatching Maps) - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M12	12"x12" Green VFT Mastic	5000	SF	Driver's Education Building - 1975	Chrysotile	MISC	No	None			
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M13	12"x12" Gray w/ White Streaks VFT Mastic	5400	SF	Rooms 144, 322, 336, 346, 449,133 - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments:											
Condition Not Changed in Fall 2007											
Comments:											
Condition Not Changed in Spring 2008											
Comments:											
Condition Not Changed in Fall 2008											
Comments:											
Condition Not Changed in Spring 2009											
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M14	12"x12" Sand VFT Mastic	5150	SF	Rooms 447, 147, 145, & 143, 116 - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007											
Comments:											
Condition Not Changed in Spring 2008											
Comments:											
Condition Not Changed in Fall 2008											
Comments:											
Condition Not Changed in Spring 2009											
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M16	12"x12" Dark Brown w/ Black Streaks VFT Mastic	16270	SF	Corridors & Auditorium - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection Summer 2009 abatement project in SW corner of 1st fl Auditorium rm 109											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M17	12"x12" Peach VFT Mastic	2420	SF	Rooms 132, 134, 203, 217, 302A, 338, - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M19	9"x9" Off White w/ Gray Streaks VFT Mastic	4000	SF	Lunchroom - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M20	9"x9" Green VFT Mastic	4000	SF	Lunchroom - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M21	9"x9" Beige w/ Brown Streaks VFT Mastic	4300	SF	Serving Area - 1931, 134	Chrysotile	MISC	No	None			
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M22	12"x12" White w/ Brown Specks VFT Mastic	650	SF	Kitchen, Rooms 123 - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M23	12"x12" Beige w/ Wavy Brown VFT Mastic	3500	SF	Kitchen, 232 - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - Present in room 232											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M24	9"x9" Black w/ White Streaks VFT Mastic	210	SF	Lunchroom, Storage, & Engineer's Office - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M25	9"x9" Maroon w/ White Streaks VFT Mastic	910	SF	Lunchroom, Storage, Room 118A, & 2 Engineer's Office's - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments:											
Condition Not Changed in Fall 2007											
Comments:											
Condition Not Changed in Spring 2008											
Comments:											
Condition Not Changed in Fall 2008											
Comments:											
Condition Not Changed in Spring 2009											
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M27	12"x12" Gray w/ White & Brown Specks VFT Mastic	2737	SF	Girl's Locker Room Office, Shower Office, Storage, & Laundry - 1975	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007											
Comments:											
Condition Not Changed in Spring 2008											
Comments:											
Condition Not Changed in Fall 2008											
Comments:											
Condition Not Changed in Spring 2009											
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M29	12 x 12 inch White w/Tan Streaks VFT Mastic	800	SF	Engineer's Office	Assumed	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M30	12 x 12 inch Pink VFT Mastic	800	SF	Room 146	Assumed	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					
Comments:											
Fall 2009											YES NO
Comment:											


VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M31	Carpet Mastic	2400		Rooms: 130, 210, 235, 330, 205, 212, 213	Assumed	MISC	No	None			
3YR Inspector Comments: 2007 - Not found in 256 and 232. No room # 266											
Condition Not Changed in Fall 2007					Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2008					Assumed	MISC					
Comments:											
Condition Not Changed in Fall 2008					Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2009					Assumed	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M9	12"x12" Beige w/ Brown & White Specks VFT Mastic	49000	SF	Throughout - 1931	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection Summer 2009 - abatement project in Entryway to 2nd fl Library											
Condition Not Changed in Fall 2007					Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2008					Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008					Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009					Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

All LEA Responsibilities, for this school, will be met.



 Lynn A. Crivello

VFT = Vinyl Floor Tile
 Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.