

# Chicago Public Schools

## 6 Month Asbestos Surveillance

Fall 2011

**School**     Roosevelt High School  
**Address**    3436 W. Wilson

**Oracle Unit** 46271     **Building ID** 1520  
**Region** 1             **General Services Route** 31

*Asbestos Surveyor:* \_\_\_\_\_

*Survey Date:* \_\_\_\_\_

*E-mail Address:* \_\_\_\_\_

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:**

*Each child's backpack*

*Notice printed in school's newsletter/calendar*

*Other* \_\_\_\_\_

**Principal Signature** \_\_\_\_\_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	<b>Change in Assessment Category</b>	
22	12"x12" Beige w/ Brown & White Marble VFT Mastic	28700	SF	Throughout Corridors, E Janitor's Closet #1, Rooms 249 & 206, Balcony, 1st, 2nd, & 3rd Fl Corridors	Chrysotile	MISC	No	None	0			
<i>3YR Inspector Comments:</i>												
Condition Not Changed in Fall 2010												
			SF		Chrysotile	MISC						
<i>Comments:</i>												
Condition Not Changed in Spring 2011												
			SF		Chrysotile	MISC						
<i>Comments:</i>												
<b>Fall 2011</b>											<b>YES</b>	<b>NO</b>
<i>Comment:</i>												

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 46271

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" White w/ Tan Striations VFT Mastic	5100	SF	Rooms 315, 320, 244 (under carpet), 220, & 130	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Gray w/ Black & White Specks VFT Mastic	1520	SF	Room 204, 204 Storage Room	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Tan w/ Brown & White Striation VFT Mastic	3105	SF	1st Floor Kitchen, Serving Area	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
31	9"x9" White, Brown, Tan, & Turquoise VFT Mastic	2400	SF	Room 115, 117, Main Office	Chrysotile	MISC	No	None	0			
3YR Inspector Comments: Room 115(Material is under orange linoleum. Room 117 & Main Office (material is under carpet) Main Office its underneath HA# 52 and HA# 53.										2010- In		
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC						
Comments:												
Condition Changed in Spring 2011			SF		Chrysotile	MISC						
Comments: Main Office: Carpet removed, 12"x12" (non-asbestos) tile installed over existing in summer of 2008												
<b>Fall 2011</b>											YES	NO
<b>Comment:</b>												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
33	9"x9" Dk Tan w/ Brn & White Striations VFT Mastic	300	SF	1st Floor Carpenter Shop, Room 167	Chrysotile	MISC	No	None	0			
3YR Inspector Comments:												
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC						
Comments:												
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC						
Comments:												
<b>Fall 2011</b>											YES	NO
<b>Comment:</b>												

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	9"x9" Tan w/ Brown & White Specks VFT Mastic	350	SF	Room 135, 150, Under HA# R15 in Rm 235	Assumed	MISC	No	None	0		
3YR Inspector Comments: 2010: Under HA# R15 in Rm 235											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Changed in Spring 2011			SF		Assumed	MISC					
Comments: Tile in 150 has been covered by 3/4" plywood & 12"x12" non-asbestos tile											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	9"x9" Dk Brn w/ Light Brown Striations VFT Mastic	350	SF	Engineer's Office	Chrysotile	MISC	No	Loc	100	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	9"x9" Light Brown w/ Marble Design VFT Mastic	350	SF	Engineers Office	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12"Lt Brn-Gray w/White,Tn,&Bn Str's VFT Mastic	1800	SF	Rooms 248, 114, 116, & 1st Floor Book Room	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2010- In Rm 114, its now under HA# 42 and HA# 43.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" Brown VFT Mastic	4500	SF	Rooms 114, 116, 132, 167, & 168	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	9"x9" Rust w/ Black Specks VFT	750	SF	Room 129 (under carpet) & 2nd Floor Teacher's Lounge	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2010- No carpet in Rm 129 under HA# R9.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	9"x9" Rust w/ Black Specks VFT Mastic	750	SF	Room 129 (Under Carpet) & 2nd Floor Teacher's Lounge	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2010- No carpet in Rm 129 under HA# R9.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	9"x9" Tan w/ White Streaks VFT	1875	SF	Rooms 135 (under carpet), 150 & Faculty Dining Room	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2010- No carpet in Rm 135 under HA# R9.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Changed in Spring 2011			SF		Chrysotile	MISC					
Comments: Tile in 150 has been covered by 3/4" plywood & 12"x12" non-asbestos tile. March 2011											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	9"x9" Tan w/ White Streaks VFT Mastic	1875	SF	Rooms 135 (Under Carpet), 150 & Faculty Dining Room	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2010- No carpet in Rm 135 under HA# R9.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Changed in Spring 2011			SF		Chrysotile	MISC					
Comments: Tile in 150 has been covered by 3/4" plywood & 12"x12" non-asbestos tile											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	9"x9" Tan w/ Brown & White Specks VFT	2400	SF	Rooms 115 (Under New VFT) , 117, & Main Office (Both Under Carpet)	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Changed in Spring 2011			SF		Chrysotile	MISC					
Comments: 117 covered in linoleum. Main Office carpet removed, has new non-asbestos vct installed over existing.											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	9"x9" Tan w/ Brown & White Specks VFT Mastic	2400	SF	Rooms 115 (Under New VFT), 117, & Main Office (Both Under Carpet)	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition NOT Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Changed in Spring 2011			SF		Chrysotile	MISC					
Comments: 117 covered in linoleum. Main Office carpet removed, has new non-asbestos vct installed over existing.											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	9"x9" Tan w/ Rust & Brown Specks VFT(under carpet)	750	SF	Rooms 131 & 129	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Changed in Spring 2011			SF		Chrysotile	MISC					
Comments: 131 &129: carpet removed, plywood and non-asbestos 12"x12" VFT installed in 2009											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	9"x9" Tan w/ Rust & Brown Specks VFT Mastic	750	SF	Rooms 131 & 129 (Under Carpet)	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments: 131 & 129: carpet removed, plywood and non-asbestos 12"x12" VFT installed in 2009											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	12"x18" Black VFT	150	SF	Engineer's Office	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	12"x18" Black VFT Mastic	150	SF	Engineer's Office	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	White w/ Gold Swirls Linoleum	100	SF	Music Booth	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76 A	12: x 12" Beige w/ Specks VFT Mastic	500	SF	Weightroom/Room 168	Chrysotile			None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile						
Comments:											
Condition Changed in Spring 2011			SF		Chrysotile						
Comments: Covered with rubber matting for past eight years											
<b>Fall 2011</b>										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77 A	12" x 12" Brown w/ Specks VFT Mastic	500	SF	Weightroom	Chrysotile			None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile						
Comments:											
Condition Changed in Spring 2011			SF		Chrysotile						
Comments: Covered with rubber matting for past eight years											
<b>Fall 2011</b>										YES	NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	Pink Linoleum	4000	SF	Rooms 306, 308 & 310; Rm 106	Assumed	MISC	No	None	0		
3YR Inspector Comments: 2010-Rm 106 and its area added to this HA.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	Pink Linoleum Mastic	4000	SF	Rooms 306, 308 & 310, Rm 106	Assumed	MISC	No	None	0		
3YR Inspector Comments: 2010-Rm 106 and its area added to this HA.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	Orange Linoleum	1500	SF	Room 115	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	Orange Linoleum Mastic	1500	SF	Room 115	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	MJP E/F/V on Cardboard Pipe Insulation	16	LF	1st Floor Girl's Washroom and Locker Room	Chrysotile	TSI	Yes	Loc	2	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C	Boiler Gaskets	100	LF	Boiler Room	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					
Comments:											
Condition Changed in Spring 2011			LF		Chrysotile	TSI					
Comments: Only rubber gaskets used											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Incinerator Gaskets	20	LF	Boiler Room	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010											
Comments:											
Condition Not Changed in Spring 2011											
Comments:											
<b>Fall 2011</b>										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Oven Gaskets	70	LF	Room 244	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010											
Comments:											
Condition Changed in Spring 2011											
Comments: No ovens for eight years											
<b>Fall 2011</b>										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-001	12x12 Blue Floor Tile	1100		Room 167	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010											
Comments:											
Condition Not Changed in Spring 2011											
Comments:											
<b>Fall 2011</b>										YES	NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM-001	Room 167	1100		12x12 Blue Floor Tile Mastic	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R1	12"x12" Beige w/ Brown & White Marble VFT	28700	SF	Throughout Corridors, E Janitor's Closet #1, Rooms 249 & 206, Balcony, 1st, 2nd, & 3rd FI Corridors	Chrysotile	MISC	No	Dist	300	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R11	9"x9" White, Brown, Tan, & Turquoise VFT	2400	SF	Rooms 115 (Under New VFT) , 117, & Main Office (Both Under Carpet)	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2010- Rm 117 and Main Office are now both under HA# 52, HA# 53, and HA# R9 (carpet has been removed).											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Changed in Spring 2011			SF		Chrysotile	MISC					
Comments: 115 is carpet and linoleum (6 years).											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 46271

Page 13

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R14	9"x9" Dark Tan w/ Brown & White Striations VFT	300	SF	1st Floor Carpenter Shop, Room 167	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments: Blue 12"x12" VCT?											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R15	9"x9" Tan w/ Brown & White Specks VFT	2250	SF	Rooms 235 (Under New VFT) , 135 (Under New VFT, No Carpet), & 150	Chrysotile	MISC	No	Dist	200	SF	
3YR Inspector Comments: During the 2010 Re-inspection no change was observed in Rms 235 and 150; in Rm 135 no carpet observed, under new VFT also.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R16	9"x9" Dark Brown w/ Light Brown Striations VFT	350	SF	Engineer's Office	Chrysotile	MISC	No	Dist	350	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>										<b>YES</b>	<b>NO</b>
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R17	9"x9" Light Brown w/ Marble Design VFT	350	SF	Engineer's Office	Chrysotile	MISC	No	Dist	350	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R22	Cardboard Pipe Insulation	60	LF	1st Floor Girl's Washroom and Locker Room	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R5	12"x12" White w/ Tan Striations VFT	5100	SF	Rooms 315, 320, 244 (carpeted), 220, & 130	Chrysotile	MISC	No	Dist	700	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R6	12"x12" Gray w/ Black & White Specks VFT	1520	SF	Room 204 & Storage	Chrysotile	MISC	No	Dist	70	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R9	12"x12" Tan w/ Brown & White Striations VFT	3105	SF	1st Floor Kitchen, Serving Area	Chrysotile	MISC	No	Dist	15	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*All LEA Responsibilities, for this school, will be met.*

  
\_\_\_\_\_

*Lynn A. Crivello*

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 46271

Page 17

**Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125**

**NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: \_\_\_\_\_

Date: \_\_\_\_\_

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

*VFT = Vinyl Floor Tile*

*Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.*