

# Chicago Public Schools

## 6 Month Asbestos Surveillance

Fall 2011

**School** Hope College Prep High School  
**Address** 5515 S. Lowe

**Oracle Unit** 49091 **Building ID** 1940  
**Region** 5 **General Services Route** 45

**Asbestos Surveyor:** \_\_\_\_\_

**Survey Date:** \_\_\_\_\_

**E-mail Address:** \_\_\_\_\_

**CHECK HERE IF NO CHANGE TO ASBESTOS**

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

*Each child's backpack*    
  *Notice printed in school's newsletter/calendar*    
  *Other* \_\_\_\_\_

**Principal Signature** \_\_\_\_\_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	<b>Change in Assessment Category</b>
01A	12x12 F.T. tan/brown specks	6640	SF	SO. Corridor, Maint. RM, Eng. Off., Rec. Off., So. Women locker Rm., Rms: 132,134,135,pool tols	Chrysotile	MISC	No	Loc	10	SF	
<i>3YR Inspector Comments: damaged areas adjacent to kitchen</i>											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
<i>Comments:</i>											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
<i>Comments:</i>											
<b>Fall 2011</b>											<b>YES</b> <b>NO</b>
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 49091

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01D	12x12 white F.T.	630	SF	1st floor stage	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No Change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08A	12x12 F.T. mastic tan/brown specks	6640	SF	SO. Corridor, Maint. RM, Eng. Off., Rec. Off., So. Women locker Rm., Rms: 132,134,135,pool tols	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08B	12x12 F.T. mastic brown/brown & white specks	7040	SF	Lobby at elev., stage rms., office vault, library rooms (220,224)	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No Change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08C	12x12 F.T. mastic offwhite/brown & gray specks	23930	SF	All house corridors, lunch area, front lobby at main entrance	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No Change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08D	12x12 white F.T. mastic	630	SF	1st floor stage	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No Change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12x12 off-white w/ gray specs floor tile	49400	SF	1st, 2nd, 3rd floors, classrooms, main corridors	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12A	12x12 off-white w/ gray specs mastic	49400	SF	1st, 2nd, 3rd floors, classrooms, main corridors, pool corridor	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	off-white linoleum	6000	SF	Rooms 106, 206, 230, 306, 330	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13A	off-white linoleum mastic	6000	SF	Rooms 106, 206, 230, 306, 330	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	2x4 ceiling tile	50000	SF	throughout building	Assumed	MISC	Yes	Dist	4	SF	
3YR Inspector Comments: 3 or 4 cracked ceiling tiles distributed throughout building											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12x12 VFT Black w/ white specs	80	SF	Pool corridor, 2nd & 3rd floor main corridors	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Assumed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15A	12x12 VFT Black w/ white specs mastic	80	SF	Pool corridor, 2nd & 3rd floor, main corridors	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Assumed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12x12 lt gray w/white floor tile	1000	SF	Teacher's lunchroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12x12 lt gray ft w/ white mastic	1000	SF	Teacher's lunchroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Maroon carpet mastic	2000	SF	Media center, rooms 108, and 109	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12x12 red floor tile	600	SF	Stairs to media center	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12x12 red floor tile mastic	600	SF	Stairs to media center	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Pipe insulation associated with swimming pool tank insulation	50	LF	Swimming pool basement	Assumed	TSI	Yes	Dist	15	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Assumed	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	TSI				LF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**


HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
C	Tank insulation magblock	210	SF	swimming pool basement	Chrysotile	TSI	Yes	None	0	SF		
3YR Inspector Comments:												
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				SF		
Comments:												
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				SF		
Comments:												
<b>Fall 2011</b>											<b>YES</b>	<b>NO</b>
Comment:												

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

*All LEA Responsibilities, for this school, will be met.*



*Lynn A. Crivello*

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

**NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: \_\_\_\_\_

Date: \_\_\_\_\_

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

*VFT = Vinyl Floor Tile*

*Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.*