

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Harlan Academy High School
Address 9652 S. Michigan

Oracle Unit 51021 **Building ID** 1350
Region 6 **General Services Route** 48

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01	Acoustical Ceiling Plaster	9000	SF	Auditorium	Chrysotile	SURFAC E	No	None	0	SF	
<small>3YR Inspector Comments: No O&M or repair records on-site</small>											
Condition Not Changed in Fall 2010			SF		Chrysotile	SURFAC E				SF	
<small>Comments:</small>											
Condition Not Changed in Spring 2011			SF		Chrysotile	SURFAC E				SF	
<small>Comments:</small>											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04E	12x12 cream w/brown specks floor tile	6400	SF	Rooms 115A, 116, 117, 117B, 119, 124, 126, 132, 134, 210, 211, 213, 217, 218A,	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: This material was sampled during the 1998 Three Year Reinspection. Laboratory Analysis Results found in 1998 Three Year Reinspection Report. observed in Rooms 160, 121-123, 125, 136, 204, 209, 224A, 228, 232, 236, 238, and 240. No abatement records on-site.											Not
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04F	12x12 grey (dark tan) w/white strikes floor tile (REMOVED)			2nd floor corridor	Chrysotile	MISC					
3YR Inspector Comments: This material was sampled during the 1998 Three Year Reinspection. Laboratory Analysis Results found in 1998 Three Year Reinspection Report. observed - No abatement records on-site											Not
Condition Not Changed in Fall 2010					Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04G	12x12 beige w/brown & white streaks floor tile (NOT OBSERVED)	16000	SF	Mens Faculty, 1st fl: corridor, SE stair well, main office sitting area, ladies restroom	Chrysotile	MISC					
3YR Inspector Comments: This material was sampled during the 1998 Three Year Reinspection. Laboratory Analysis Results found in 1998 Three Year Reinspection Report.										Not observed - No abatement records on-site	
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04H	12x12 crème w/ tan & white streaks floor tile	7050	SF	faculty dining room & cafeteria, ladies restroom	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: This material was sampled during the 1998 Three Year Reinspection. Laboratory Analysis Results found in 1998 Three Year Reinspection Report.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05A	9x9 grey w/white streaks floor tile	3500	SF	Rooms 229, 239, 242, 216, 121, 123	Chrysotile	MISC	Yes	None	0	SF	
3YR Inspector Comments: This material was sampled during the 1998 Three Year Reinspection. Laboratory Analysis Results found in 1998 Three Year Reinspection Report. Not observed in 201, 206-208, 241A, 230, 224, 224A, 218, 218A, 206, and 214. No abatement records on-site.											Not
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05B	9x9 beige w/brown streaks floor tile	1500	SF	Rooms 135 and 136	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: This material was sampled during the 1998 Three Year Reinspection. Laboratory Analysis Results found in 1998 Three Year Reinspection Report. Not observed in Rooms 115, 117 and 230. No abatement records on-site.											Not
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
06A	9x9 Grey w/White Streaks Floor Tile Mastic	3500	SF	Rooms 230, 229, 239, 242, 216, 121, 123	Chrysotile	MISC	No	None	0	SF		
3YR Inspector Comments: This material was sampled during the 1998 Three Year Reinspection. Laboratory Analysis Results found in 1998 Three Year Reinspection Report in 201, 206-208, 241A, 224, 224A, 218, 218A, 206, and 214. No abatement records on-site.										Not observed		
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF		
Comments:												
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF		
Comments:												
Fall 2011											YES	NO
Comment:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
06B	9x9 beige w/brown streaks floor tile mastic	1000	SF	Rooms 135 and 136	Chrysotile	MISC	Yes	None	0	SF		
3YR Inspector Comments: This material was sampled during the 1998 Three Year Reinspection. Laboratory Analysis Results found in 1998 Three Year Reinspection Report. observed in Rooms 115, 117 and 230. No abatement records on-site.										Not		
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF		
Comments:												
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF		
Comments:												
Fall 2011											YES	NO
Comment:												

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
07A	12x12 Various Shades of Beige Floor Tile Mastic (NOT OBSERVED_	2081	SF	1st fl west exit & corridor, sw exits, ne corridor & mens washroom (1st fl), swimming pool corridor	Chrysotile	MISC						
3YR Inspector Comments: This material was sampled during the 1998 Three Year Reinspection. Laboratory Analysis Results found in 1998 Three Year Reinspection Report.										Not observed - No abatement records on-site		
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC						
Comments:												
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC						
Comments:												
Fall 2011											YES	NO
Comment:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
07B	12x12 Various Shades of Tan Floor Tile Mastic (NOT OBSERVED)			corridor outside room 134, water fountain, outside room 124 & 126 patchwork	Chrysotile	MISC						
3YR Inspector Comments: This material was sampled during the 1998 Three Year Reinspection. Laboratory Analysis Results found in 1998 Three Year Reinspection Report.										Not observed - No abatement records on-site		
Condition Not Changed in Fall 2010					Chrysotile	MISC						
Comments:												
Condition Not Changed in Spring 2011					Chrysotile	MISC						
Comments:												
Fall 2011											YES	NO
Comment:												

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07C	12x12 Multicolor Dark Beige Floor Tile Mastic	1920	SF	Rooms 220 and 222	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: This material was sampled during the 1998 Three Year Reinspection. Laboratory Analysis Results found in 1998 Three Year Reinspection Report.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
071	12x12 beige w/white specks floor tile mastic (REMOVED)			1st floor SE exit	Chrysotile	MISC					
3YR Inspector Comments: This material was sampled during the 1998 Three Year Reinspection. Laboratory Analysis Results found in 1998 Three Year Reinspection Report.											Not observed - No abatement records on-site
Condition Not Changed in Fall 2010					Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07J	12x12 taupe w/brn & white specks floor tile mastic	216	SF	Room 212	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: This material was sampled during the 1998 Three Year Reinspection. Laboratory Analysis Results found in 1998 Three Year Reinspection Report. observed in SE mens facility,N. side lounge and 214. No abatement records on-site											Not
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07K	12x12 multicolor cream mastic floor tile	2108	SF	Rooms 220 and 222	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: This material was sampled during the 1998 Three Year Reinspection. Laboratory Analysis Results found in 1998 Three Year Reinspection Report. observed in Rooms 106, 109 or 210. No abatement records on-site.											Not
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	1x2 ceiling tile (REMOVED)			Boys' gym	Assumed	MISC					
3YR Inspector Comments: Not observed - No abatement records on-site											
Condition Not Changed in Fall 2010					Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11C	Cream baseboard	142	LF	Rooms 106 and 108	Assumed	MISC	No	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Assumed	MISC				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC				LF	
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12C	Cream Baseboard Mastic	142	LF	Rooms 106 and 108	Assumed	MISC	No	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Assumed	MISC				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC				LF	
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13C	Black with Gray Linoleum	840	SF	Rooms 106, 107 and 108	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14C	Black with Gray Linoleum Mastic	840	SF	Rooms 106, 107 and 108	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15P	12 x 12 Black with Maroon Checkerboard VFT.	1390		Room 217 Corridor	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Not observed in 232 Corridor or in Auditorium Pit											
Condition Not Changed in Fall 2010					Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17A	Interior Window Glazing (REMOVED/REPLACED)			Throughout 1st&2nd floor	Assumed	MISC					
3YR Inspector Comments: Not observed - No abatement records on-site											
Condition Not Changed in Fall 2010					Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	2x4 ceiling tile	840	SF	room 108	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Drywall	400	SF	Room 108	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Transite Countertops (REMOVED)	200	SF	Room 108	Assumed	MISC					
3YR Inspector Comments: Removed - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12" x 12" dark blue floor tile (NOT OBSERVED)	3800	SF	Rooms 136, 208, 226, 214, 218	Assumed	MISC					
3YR Inspector Comments: Not observed - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25M	12 x 12 dark blue floor tile mastic (NOT OBSERVED)	3800	SF	Rooms 136, 208, 214, 218, 226	Assumed	MISC					
3YR Inspector Comments: Not observed - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12 x 12 White w/ Beige Streaks Floor Tile	10000	SF	Rooms 112, 115, 122, 124, 125, 126, 130, 133, 134A, 207, 219, 219A, 221, 228, 227A, 231, 232, 234, 236, 238, 240, and Library	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Not observed in Rooms 117, 119, 231 or in Auditorium side entry. No abatement records on-site.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26M	12 x 12 White w/ Beige Streaks Floor Tile Mastic	10000	SF	Rooms 112, 115, 122, 124, 125, 126, 130, 133, 134A, 207, 219, 219A, 221, 228, 227A, 231, 232, 234, 236, 238, 240, and Library	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Not observed in Rooms 117, 119, 231 or in Auditorium side entry. No abatement records on-site.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12" x 12" Brown and White Floor Tile	1500	SF	Hallway in Modular Building	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27M	12" x 12" Brown and White Floor Tile Mastic	1500	SF	Hallway in Modular Building	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA in 2007											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	2' x 4' White Fissured Ceiling Tiles	5000	SF	Hallway and Classrooms Throughout Modular Building	Assumed	MISC	Yes	Dist	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12 x 12 Red Floor Tile	1000	SF	Rooms 112 and 114	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12 x 12 Red Floor Tile Mastic	1000	SF	Rooms 112 and 114	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12 x 12 Light Blue Floor Tile	1000	SF	Rooms 112 and 114	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12 x 12 Light blue Floor Tile Mastic	1000	SF	Rooms 112 and 114	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12 x 12 White Floor Tile	1000	SF	Rooms 112 and 114	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12 x 12 White Floor Tile Mastic	1000	SF	Rooms 112 and 114	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12 x 12 Dark Blue Floor Tile	12000	SF	Corridors Border, Stairwells, Rooms 218, 214, 208, 241 and 226	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12 x 12 Dark Blue Floor Tile Mastic	12000	SF	Corridors Border, Stairwells, Rooms 218, 214, 208, 241 and 226	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12 x 12 Sky Blue Floor Tile	10500	SF	Corridors and Room 138A	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12 x 12 Sky Blue Floor Tile Mastic	10500	SF	Corridors and Room 138A	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	22 x 22 White Floor Tile	5000	SF	Main Hall	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	22 x 22 White Floor Tile Mastic	5000	SF	Main Hall	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	22 x 22 Light Blue Floor tile	5000	SF	Main Hall	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	22 x 22 Light Blue Floor Tile Mastic	5000	SF	Main Hall	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	22 x 22 Dark Blue Floor Tile	5000	SF	Main Hall	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	22 x 22 Dark Blue Floor Tile Mastic	5000	SF	Main Hall	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	22 x 22 Orange Floor Tile	5000	SF	Main Hall	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	22 x 22 Orange Floor Tile Mastic	5000	SF	Main Hall	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	2 x 2 Ceiling Tile	5000	SF	Main Hall	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments: New HA											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Insulation in Fire Rated Doors	240	SF	At Fire Stops Throughout Facility	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Analytical results located in Management Plan											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	MJV on Fiberglass Pipe Insulation	700	LF	Throughout Basement Crawl Space	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: Sample analysis results located in Management Plan											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
H	Vibration collars	5	SF	Basement Boiler room.	Assumed	TSI	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-100	2'x4' plain white Ceiling Tile	150	SF	1st floor Boy's restroom	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-101	2'x4' white ceiling tile with grooves and pinholes	7000	SF	Classrooms	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-102	Acoustical "Pop Corn" Plaster	9000	SF	Auditorium	Chrysotile	SURFACE	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	SURFACE				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	SURFACE				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-103	2'x4' white ceiling tile with random fissures and	1800	SF	classroom, corridor, men's room	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-104	2'x4' White Ceiling Tile with Regular Holes	200	SF	Ladies Room	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-105	12"x12" beige VFT with brown and white specks	400	SF	restrooms	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-105m	Adhesive for 12"x12" beige VFT with brown and white specks	400	SF	restrooms	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-106	12"x12" off white with beige specks floor tile (NOT OBSERVED)	500	SF	corridor	Assumed	MISC					
3YR Inspector Comments: Not observed - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-106/107m	12"x12" off white and brown floor tile adhesive (NOT OBSERVED)	1000	SF	corridor	Assumed	MISC					
3YR Inspector Comments: Not observed - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-107	12"X12" Brown with Specks Floor Tile	500	SF	Corridor	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-108	Red Carpet Adhesive (NOT OBSERVED)	3000	SF	classrooms	Assumed	MISC					
3YR Inspector Comments: Not observed - No sampling or abatement records on-site											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-109	Gray Carpet Adhesive	3000	SF	Rooms 102A, 120, 224A, Attendance Office, 131A, 130, Auditorium, Main Office, Assitant Principals Office	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					SF
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-110	4" black baseboard	5000	LF	throughout	Assumed	MISC	No	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Assumed	MISC					LF
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC					LF
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-110m	Adhesive for 4" blackbaseboard	5000	LF	throughout	Assumed	MISC	No	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Assumed	MISC					LF
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC					LF
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-111	Hard Joint Mudded Fittings on Fiberglass Insulated Pipe	4	LF	Utility Sink Room by the Water Heater	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: Sample analysis results located in Management Plan											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	12x12 light blue floor tile (NOT OBSERVED)	12000	SF	1st and 2nd floor corridors	Assumed	MISC					
3YR Inspector Comments: Not observed - No sampling or abatement records on-site											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	12x12 Dark blue floor tile (NOT OBSERVED)	6000	SF	1st and 2nd floor corridors.	Assumed	MISC					
3YR Inspector Comments: Not observed - No sampling or abatement records on-site											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Brown Linoleum	1000	SF	Rooms 104 and 104A	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Not observed in Rooms 103, 105 or 107. No sampling or abatement records on-site.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Brown Linoleum Mastic	1000	SF	Rooms 104 and 104A	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Not observed in Rooms 103, 105 or 107. No sampling or abatement records on-site.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M	12x12 light blue floor tile mastic (NOT OBSERVED)	12000	SF	1st and 2nd floor corridor	Assumed	MISC					
3YR Inspector Comments: Not observed - No sampling or abatement records on-site											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	12x12 dark blue floor tile mastic (NOT OBSERVED)	6000	SF	1st and 2nd floor corridors.	Assumed	MISC					
3YR Inspector Comments: Not observed - No sampling or abatement records on-site											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											


HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
O	1x1 Slotted Acoustical Ceiling Tile	800		Boy's & Girl's Gym	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
P	1x1 Slotted Acoustical Ceiling Tile Adhesive	800		Boy's & Girl's Gym	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

All LEA Responsibilities, for this school, will be met.



Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 51021

Page 30

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125