

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Clemente Academy
 Address 1147 N. Western Ave

Oracle Unit 51091 Building ID 1840
 Region 2 General Services Route 35

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01	12"X12" Dark Brown w/Speckles Floor Tile	27500	SF	Basement, Corridors, 2nd , 4th , 5th , 6th , 7th Floor Lunchrooms, ROTC Room, and Rooms 201-208, 215, 216, 218, TV Studio, Audio, Dark Room, Control Room, Supply Room, Stairways, 5th, 6th & 7th Floor Washrooms, 799, 812, 813, 816, 817, 818, 821, 822, 826	Chrysotile	MISC	No	Loc	200	SF	
3YR Inspector Comments: There is 200 sq. ft. of broken floor tile in the basement											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 51091

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	12"x12" Dark Brown w/Speckles Floor Tile Mastic	17500	SF	Basement, Corridors, 2nd , 4th , 5th , 6th , 7th Floor Lunchrooms, ROTC Room, and Rooms 201-208, 215, 216, 218, TV Studio, Audio, Dark Room, Control Room, Supply Room, Stairways, 5th, 6th & 7th Floor Washrooms, 799, 812, 813, 816, 817, 818, 821, 822, 826	Chrysotile	MISC	No	Loc	200	SF	

3YR Inspector Comments: The basement has 200 sq. ft. of broken floor tile by the kitchen

Condition Not Changed in Fall 2010		SF		Chrysotile	MISC					SF	
------------------------------------	--	----	--	------------	------	--	--	--	--	----	--

Comments:

Condition Not Changed in Spring 2011		SF		Chrysotile	MISC					SF	
--------------------------------------	--	----	--	------------	------	--	--	--	--	----	--

Comments:

Fall 2011											YES NO
------------------	--	--	--	--	--	--	--	--	--	--	--------

Comment:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	Vibration Dampening Cloth	341	LF	Valve and Mechanical Rooms and Mechanical Rooms in Main and Athletic Bldgs.	Chrysotile	MISC	Yes	None	0	LF	

3YR Inspector Comments: No changes from last inspection

Condition Not Changed in Fall 2010		LF		Chrysotile	MISC					LF	
------------------------------------	--	----	--	------------	------	--	--	--	--	----	--

Comments:

Condition Not Changed in Spring 2011		LF		Chrysotile	MISC					LF	
--------------------------------------	--	----	--	------------	------	--	--	--	--	----	--

Comments:

Fall 2011											YES NO
------------------	--	--	--	--	--	--	--	--	--	--	--------

Comment:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	Ventilation Duct Caulk	1000	LF	Mechanical Rooms	Chrysotile	MISC	No	None	0	LF	
3YR Inspector Comments: No changes from last inspection											
Condition Not Changed in Fall 2010			LF		Chrysotile	MISC				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	MISC				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Water Tank Insulation	260	SF	Athletic Building, Gym - Mechanical Room Tank #2	Chrysotile	TSI	Yes	None	0	SF	
3YR Inspector Comments: No changes from last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	Insulation in Fire Doors	48	SF	Storage Room outside assembly hall	Chrysotile	TSI	No	None	0	SF	
3YR Inspector Comments: This insulation was sampled in 1989 under HA # 5 of the Management Plan. Sample analysis results are located in the Management Plan											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Black Floor Tile Mastic	1000	SF	Basement South Corridor	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No changes from last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Brown Speckled VFT Mastic	800	SF	Room 802	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	2 x 4 Tectum Ceiling Tile	700	SF	Room 810	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments: No changes from last inspection											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Beige Speckled Linoleum	700	SF	Room 810	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No changes from last inspection											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31A	Beige Speckled Linoleum Mastic	700	SF	Room 810	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No changes from last inspection											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Terrazo	7000	SF	Main Lobby, Auditorium Upper Level, Athletic Building, Stairwells, Gym Lobby	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No changes from last inspection											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Lab Countertops	500	SF	Room 810	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No changes from last inspection											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Ductwrap	950	SF	Main Building Penthouse	Chrysotile	TSI	Yes	None	0	SF	
3YR Inspector Comments: No changes from last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	Duct Insulation	25	SF	Main Building Penthouse	Chrysotile	TSI	Yes	None	0	SF	
3YR Inspector Comments: No changes from last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C	Hard Coat Plaster	25000	SF	Throughout	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Drywall Tape	500	LF	Throughout	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Drywall Joint Compound	500	SF	Throughout	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

All LEA Responsibilities, for this school, will be met.



Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 51091

Page 8

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125