

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Dunbar High School
Address 3000 S. King Dr.

Oracle Unit 53021 **Building ID** 1030
Region 4 **General Services Route** 40

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1 B	Beige Carpet Mastic	200	SF	Engineer's Office	Assumed	MISC	No	None	0	SF	
<small>3YR Inspector Comments: No change</small>											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
<small>Comments:</small>											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
<small>Comments:</small>											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 53021

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1 C	Gold Carpet Mastic	600	SF	Room 9-C	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: No gold mastic carpet in room 9-c/tile floor blue											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1030	12" x 12" White Floor Tile w/ Blue Streaks Mastic	600	SF	208	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Peg Board	2000	SF	Auditorium Walls	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 A	9"x9" Dk Green Floor Tile w/ White Streaks Mastic	6100	SF	1st, 2nd & 3rd Floor Corridors	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change. 2008 during the 1/30/2008 audit visit material was observed to be damaged throughout the building: 1st fl. Corridor Boy's GYM, by the auditorium.											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: 3rd floor west end to center replaced tiles											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 B	9" x 9" White Floor Tile w/Dark Grn Streaks Mastic	6100	SF	1st, 2nd & 3rd Floor Corridors	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change 008 during the 1/30/2008 audit visit material was observed to be damaged throughout the building: 1st fl. Corridor Boy's GYM, by the auditorium.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 D	9" x 9" White Floor Tile w/ Lt Grn Streaks Mastic	400	SF	As Patches in the 1st & 3rd Floor Corridors	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 E	9" x 9" Brown Floor Tile w/ Brown Streaks Mastic	500	SF	1st Floor Corridor, Rooms 100	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 F	9"x9" Gray FloorTile w/Lt. Gray & Blk Strks Mastic	10692	SF	13A&B, Dressing Rms,100,103-105,119,120,128,140,200,208,211,212,214,217,221A&B,225,300, 301,etc.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change. 2008 - during the 1/30/2008 audit visit material was observed to be damaged throughout classrooms on 2nd floor (Rms. 225 - 8 s.f., 221 - 5 s.f., 211 -20s.f. and Library (230 s.f.)											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: new floor tile - 212											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 G	9" x 9" Lt Gray VFT w/ Gray & Blk Strks Mastic	10692	SF	3 A&B, Dressing Rooms, and Various Classrooms Throughout Building	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change 2008 - during the 1/30/2008 audit visit material was observed to be damaged throughout classrooms on 2nd floor (Rms. 225 - 8 s.f., 221 - 5 s.f.,211 -20s.f.)and Library (230 s.f.)											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: Library - new tile floor											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 H	9"x9" Lt Brn Floor Tile w/Wh & Blk Streaks Mastic	200	SF	Rooms 212 & 311	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: new tile floor - room 212											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13C	9" x 9" Bright Grn Floor Tile w/ Wh Streaks Mastic	400	SF	As Patches in the 1st & 3rd Floor Corridors	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 A	12" x 12" White FT w/Blue & Grey Streaks Mastic	5600	SF	Rooms 222, 224, 310, and 312	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 AA	12" x 12" Gray Floor Tile Mastic	1200	SF	Band Room Hall, Chorus Room, Foyer & Practice Room	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2010 - Sample Results not found. Material Changed to assumed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 AB	12" x 12" Multi-Blue Floor Tile Mastic	1600	SF	Room 208	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 AE	12" x 12" White Floor Tile w/ Blue Streaks Mastic	600	SF	Room 208	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 AF	12" x 12" Gray Floor Tile w/ Black Streaks Mastic	20	SF	Room 208	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 B	12" x 12" Gray VFT w/ Wh & Blk Streaks Mastic	200	SF	Men's Lounge	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 C	12" x 12" Dk Gray Floor Tile w/Blk Streaks Mastic	5400	SF	Rooms 140, 211, 214, 217, 305, 308, and 313	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: 201-new tile floor											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 D	12" x12" Brown VFT w/ Dk Brn & White Strks Mastic	25000	SF	Boys Gym, Lunchroom, 1st and 2nd Floor Corridors, 114, 201, 213, 215, 216, 218-220, 223, 227, 303	Chrysotile	MISC	No	Loc	20	SF	
3YR Inspector Comments: 2010- 20SF of damage in the lunchroom											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 E	12" x 12" White Floor Tile w/Brown Streaks Mastic	25000	SF	Boys Gym, Lunchroom, 1st and 2nd Floor Corridors, 114, 201, 213, 215, 216, 218-220, 223, 227, 303	Chrysotile	MISC	No	Loc	20	SF	
3YR Inspector Comments: 2010- 20 SF damaged in lunchroom											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: room 201 - new tile floor											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 F	12"x12" Lt Brown Floor Tile w/White Streaks Mastic	750	SF	1st Floor Corridor by Ramps and as a Patch in the 2nd Floor Corridor	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 G	12"x12"Gray Floor Tile w/Dk Gray/Wh Streaks Mastic	6400	SF	Rooms 100, 119, 121, 140, 305, 306, 308, and 313	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comment: Damages located in room 100. 2007 comments - no damage observed in room 100, 12" x 12" blue replacement tiles were observed in this area along with the existing tile. 2010 comment - not observed in 100											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 H	12" x 12" Beige Floor Tile w/White Streaks Mastic	250	SF	1st Floor Corridor by Ramps and as a Patch in the 2nd Floor Corridor	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 I	12" x 12" Brown Floor Tile Mastic	250	SF	Room 138	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 J	12" x 12" Beige Floor Tile Mastic	432	SF	Room 138	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change in 2007.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 K	12" x 12" Green Floor Tile Mastic	150	SF	1st, 2nd & 3rd Floor Corridors as Patches	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 L	12" x 12" Light Green Floor Tile Mastic	150	SF	1st, 2nd & 3rd Floor Corridors as Patches	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 M	12" x 12" Gray Floor Tile Mastic	550	SF	1st Floor Corridor Ramps	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 Q	12" x 12" Black Floor Tile Mastic	1100	SF	Room 105	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 R	12" x 12" White Floor Tile Mastic	1500	SF	Room 105	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 S	12" x 12" Light Blue Floor Tile Mastic	175	SF	Room 104	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 T	12" x 12" Light Brown Floor Tile Mastic	700	SF	Rooms 114, 117, 119, 130, 206, & 207	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2010 - Sample Results not found. Material Changed to assumed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 U	12" x 12" Beige Floor Tile Mastic	700	SF	Rooms 114, 117, 119, 130, 206, & 207	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2010 - Sample Results not found. Material Changed to assumed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 V	12"x12" Dk Brn Floor Tile w/Dk Brn & Lt Brn Mastic	300	SF	On Cabinets in Various Classrooms	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 W	12"x12" Gray Floor Tile w/Lt. Gray Streaks Mastic	300	SF	On Cabinets in Various Classrooms	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 X	12" x 12" Multi-Brown Floor Tile Mastic	1150	SF	Room 201 and 203	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: New tile floor in room 201 and 203											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 Y	12" x 12" Beige Floor Tile Mastic	1150	SF	Rooms 201 and 203	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: New tile floor in room 201 and 203											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 Z	12" x 12" Light Green Floor Tile Mastic	2400	SF	Band Room, Chorus Room, Hall and Foyer	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2010 - Previous sampling shows this material is ACBM.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16 C	4" Beige Baseboard	300	LF	Band Room, Hall, Foyer and Chorus Room	Assumed	MISC	No	None	0	LF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			LF		Assumed	MISC				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16 D	4" Dark Gray Baseboard	150	LF	Room 208	Assumed	MISC	No	None	0	LF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			LF		Assumed	MISC				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17 C	4" Beige Baseboard Mastic	300	LF	Band Room, Chorus Room, Hall and Foyer	Assumed	MISC	No	None	0	LF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			LF		Assumed	MISC				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17 D	4" Dark Gray Baseboard Mastic	150	LF	Room 208	Assumed	MISC	No	None	0	LF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			LF		Assumed	MISC				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2 A	9" x 9" Dark Green Floor Tiles w/White Streaks	6100	SF	1st, 2nd and 3rd Floor Corridors and Gym Balcony	Chrysotile	MISC	No	Loc	30	SF	
3YR Inspector Comments: 2004 and 2007 Comments - 50 SF is located in the Gym Balcony and 150 SF is distributed throughout the Hallways. 008 during the 1/30/2008 audit visit material was observed to be damaged throughout the building: 1st fl. Corridor Boy's GYM, by the auditorium. 2010- 30 SF Damaged. Third Floor Hall.											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: West end to center 3rd floor tiles replaced											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2 B	9" x 9" White Floor Tile w/Dark Green Streaks	6100	SF	Various 1st, 2nd, and 3rd Floor Corridors and Gym Balcony	Chrysotile	MISC	No	Loc	30	SF	
3YR Inspector Comments: This floor tile is used in conjunction with HA #2A, and shares the some associated mastic. 008 during the 1/30/2008 audit visit material was observed to be damaged throughout the building: 1st fl. Corridor Boy's GYM, by the auditorium. 2010-30 SF damaged in 3rd Floor Hall.											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: West end toe center 3rd floor tiles replaced											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2 C	9" x 9" Bright Green Floor Tile w/ White Streaks	400	SF	As Patches in the 1st and 3rd Floor Corridors	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2 D	9" x 9" White Floor Tile w/Bright Green Streaks	400	SF	1st, 2nd, and 3rd Floor Corridors	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: This floor tile is used in conjunction with HA #2C, and shares the some associated mastic.											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: West end to center 3rd floor tiles replaced											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2 E	9" x 9" Brown w/Brown Floor Tile	50	SF	Rooms 100 & 140 and the 1st Floor Corridor	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2004 Comments: Material not observed in room 100. Material assumed to be under existing tile (12 x 12 blue and gray pattern FT) since no abatement records were provided for removal of this ACM.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2 F	9"x9" Gray w/Lt. Gray & Black Streaks Floor Tile	10692	SF	13 A & B, Dressing Rooms, and Various Classrooms Throughout Building	Chrysotile	MISC	No	Dist	50	SF	
3YR Inspector Comments: 2004 and 2007 Comments: Damage located in Room 13A & B. 2010- Rm 221A has 20 SF damaged. Library has 30 SF damaged.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2 G	9" x 9" Lt. Gray Floor Tile w/Gray & Black Streaks	10692	SF	13 A & B, Dressing Rooms, and Various Classrooms Throughout Building	Chrysotile	MISC	No	Dist	50	SF	
3YR Inspector Comments: 2004 and 2007 Comments: Damage located in Room 13A & B. 2010- Rm 221A has 20 SF damaged. Library has 30 SF damaged.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2 H	9" x 9" Light Brn Floor Tile w/White & Blk Streaks	200	SF	Rooms 311 and 212	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments: Damage located in room 311. Room 311 also have 30 missing tiles exposing the mastic. 2007 comments: damaged areas have been repaired.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2 I	9" x 9" White Floor Tile w/Lt Brn & Blk Streaks	200	SF	Rooms 212 and 311	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments: Damage located in room 311. Room 311 also have 30 missing tiles exposing the mastic. 2007 Comments: missing tiles have been replaced.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
251	Gray Carpet Adhesive	0	SF	1st Floor Corridor, CPS ID	Assumed	MISC	No				
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Aircell Pipe Insulation	10	LF	Boiler House Washroom Behind Wall-In Chase	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 AA	12" x 12" Gray Floor Tile	1200	SF	Band Room, Chorus Room, Hall, Foyer & Practice Room	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2010 - Sample Results not found. Material Changed to assumed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 AB	12" x 12" Multi-Blue Floor Tile	1600	SF	Room 208	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 AE	12" x 12" White Floor Tile w/ Blue Streaks	600	SF	Room 208, 100, 128	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 AF	12" x 12" Gray Floor Tile w/ Black Streaks	20	SF	Room 208, 100, 128	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 Q	12" x 12" Black Floor Tile	1100	SF	Room 105	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: Replaced tile floor											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 R	12" x 12" White Floor Tile	1100	SF	Room 105	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: Replaced tile floor											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 S	12" x 12" Light Blue Floor Tile	175	SF	Room 104, 134, Social Room, 300B	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 T	12" x 12" Light Brown Floor Tile	2400	SF	Rooms 114, 116, 117, 119, 130, and 206	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2010 - Sample Results not found. Material Changed to assumed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 U	12" x 12" Beige Floor Tile	2400	SF	Rooms 114, 116, 117, 119, 130, and 206	Anthophyllite	MISC	No	None	0	SF	
3YR Inspector Comments: 2010 - Sample Results not found. Material Changed to assumed											
Condition Not Changed in Fall 2010			SF		Anthophyllite	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Anthophyllite	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	2' x 4' Lay-In Ceiling Panels	1500	SF	Rooms 311 and 110	Amosite	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Amosite	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Amosite	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Lab Tops and Sinks	500	SF	Rooms 117, 310, 312, 222, and 224	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Vibration Collars	50	LF	Dressing Room, Janitor's Closet in Girl's Locker Room, Room 310 & Electrical Room in Room 206	Assumed	MISC	No	None	0	LF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			LF		Assumed	MISC				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	Insulation Inside Firedoors	160	SF	Exits and Boiler Room	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	Roof - Not AHERA			Boiler House	Assumed						
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed						
Comments:											
Condition Not Changed in Spring 2011					Assumed						
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	Roof Flashing - Not AHERA			Boiler House	Assumed						
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed						
Comments:											
Condition Not Changed in Spring 2011					Assumed						
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	Roof - Not AHERA			Main Building	Assumed	MISC	No				
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	Roof Flashing - Not AHERA			Main Building	Assumed	MISC	No				
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	Mastic on Wall	0	SF	Room 128 - Material not observed	Chrysotile	MISC	No				
3YR Inspector Comments: 2004 and 2007 Comments - Material not observed.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	1' x 1' Fissured Ceiling Tile Mastic	10000	SF	Throughout Building, Cafeteria	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2010 - Sample Results not found. Material Changed to assumed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	2' x 4' Ceiling Panels	2400	SF	Room 208, 117	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	Drywall	1600	SF	Room 208	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	Drywall Compound	200	LF	Room 208	Assumed	MISC	Yes	None	0	LF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			LF		Assumed	MISC				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	MISC				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	Boiler Gaskets	10	SF	Bryan Boiler in Basement	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	12" x 12" Multi-Gray Floor Tile	2000	SF	Rooms 203 & 205	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: New tile floor in rooms 203 and 205											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	12" x 12" Multi-Gray Floor Tile Mastic	2000	SF	Rooms 203 & 205	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: New tile floor in rooms 203 and 205											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	1' x 1' White Small Fissured Ceiling Tile	4700	SF	Lunchroom	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	12 x 12 gold and beige pattern FT	2000	SF	114, 207, 206, 204	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA in 2007											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: New tile floor rooms 207											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80M	12 x 12 gold and beige pattern VFT mastic	2000	SF	114, 207, 206, 204	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA in 2007											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: New tile floor room 207											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	12x12 Blueish Grey w/ Dark Grey & White Floor Tile	800	SF	Rm 128, 100	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: New tile floor room 128											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	12x12 Blueish Grey w/Dark Grey & White Floor Tile Mastic	800	SF	Rm 128, 100	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: New tile floor room 128											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	12x12 Lt Grey w/Dark Grey & White Floor Tile	3200	SF	Rm 100, 128, 203, 301, 300, 308	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: New tile floor room 128											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	12x12 Lt Grey w/Dark Grey & White Floor Tile Mastic	3200	SF	Rm 100, 128, 203, 301, 300, 308	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: New tile floor room 203											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Aircell Pipe Insulation	500	LF	Pipe Chases, Boiler Room and Throughout Building	Chrysotile	TSI	Yes	Dist	15	LF	
3YR Inspector Comments: 2004 and 2007 Comments - Room 119 Janitor's Closet by Room 117 has 1 LF damage, Pipe Chase in Carpenter Shop in Basement and Library Storage has 3 LF of damage, 3rd Floor Boy's Washroom has 3 LF of damage, remaining damaged distributed throughout Room 202 Closet, B33, B32, Throughout Office Complex and the Library. 2010- 5 LF Damaged in main foyer (pipe chase across from rm 101). 5 LF damaged and debris on ground. 5 LF damaged in boys locker room (pipe chase).											
Condition Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments: Library has new tile floor											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	(Cardboard) Paperwrap Pipe Insulation	600	LF	Boiler Room and Throughout Building, rm 115, 125	Chrysotile	TSI	Yes	Loc	1	LF	
3YR Inspector Comments: 2004 and 2007Comments - The 3rd Floor Boy's Washroom has 3 LF of damage. 2010- 1 LF damaged RM 115											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C	Aircell Duct Insulation			Abated in 1992 - See 2004 Comments	Chrysotile						
3YR Inspector Comments: No change 2008 - material abated											
Condition Not Changed in Fall 2010					Chrysotile						
Comments:											
Condition Not Changed in Spring 2011					Chrysotile						
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Fittings on Fiberglass Pipe Insulation	60	LF	Main Building	Assumed	TSI	Yes	None	0	LF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			LF		Assumed	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1000	White woven electrical wire insulation	50	LF	Auditorium stage light fixtures	Chrysotile	MISC	Yes	None	0	n	
3YR Inspector Comments: 2008 - Material was listed in old inspection report as ACM. Old light fixtures are still present on site as of 1/30/08 audit visit. Quantities estimated											
Condition Not Changed in Fall 2010			LF		Chrysotile	MISC				n	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	MISC				n	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I3 I	9"x 9" White Floor Tile w/Brn & Blk Streaks Mastic	1500	SF	Rooms 212 and 311	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Cementitious Pipe Joint Insulation on Aircell Pipe	50	LF	Pipe Chases, Boiler Room and Throughout Building	Assumed	TSI	No	None	0	LF	
3YR Inspector Comments: 2004 Comments: All accessible fittings have been abated, but it is possible that some fittings remain inside walls, pipe chases, etc. No change in 2007											
Condition Not Changed in Fall 2010			LF		Assumed	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile


Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
K	Cementitious Pipe Joint Insulation on Paperwrap	20	LF	Boiler Room, Pipe Chases and Throughout Building	Chrysotile	TSI	Yes	None			LF		
3YR Inspector Comments: 2004 and 2007 Comments: No damages was found. No cementious Joints in boiler room. All fiberglass.													
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					LF		
Comments:													
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					LF		
Comments:													
Fall 2011												YES	NO
Comment:													

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

All LEA Responsibilities, for this school, will be met.



Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125