

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Farragut Academy
Address 2345 S. Christiana

Oracle Unit 53091 **Building ID** 1300
Region 4 **General Services Route** 37

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
04M	12" x 12" Light Tan Replacement Floor Tile Mastic	20	SF	3rd Floor Hallway	Chrysotile	MISC	No	None	0	SF		
<i>3YR Inspector Comments: No change</i>												
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF		
<i>Comments:</i>												
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF		
<i>Comments:</i>												
Fall 2011											YES	NO
Comment:												

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 53091

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12" x 12" Tan Floor Tile	20	SF	First Floor North Corridor of South Building	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06M	12" x 12" Tan Floor Tile Mastic	20	SF	First Floor North Corridor of South Building	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08M	12" x 12" Olive Green Floor Tile Mastic	2000	SF	First Floor Corridor as Replacement Tiles	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2004 and 2007 comments - 12" x 12" Olive Green replacement tiles not found. However, the floor tile and mastic throughout the 1st floor corridor contain asbestos (SEE HA 06 and 06M).											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12M	12" x 12" White/Blue Streaks Floor Tile Mastic	288	SF	175	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12" x 12" Tan Floor Tile w/Streaks	20925	SF	2nd&3rd Flr Corridors,Band,Drama Of.,112,113,114,308,317,400,401,437,439,440,446,450,451,	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Also noted in MDF Room (3rd Flr) and the periodicals office. 2004 - There is 1 SF of cracked floor tile in Room 439, 4 SF cracked in Room 451 and 12 SF cracked in Room 113. No chnged noted in 2007											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28M	12" x 12" Tan Floor Tile w/Streaks Mastic	20925	SF	2nd&3rd Flr Corridors,Band,Drama Of.,112,113,114,308,317,400,401,437,439,440,446,450,451	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2004 - There is 1 SF of exposed mastic in Room 439, 1 SF of exposed mastic in Room 451 and 9 SF of exposed mastic in Room 113. Also noted in the MDF Room (3rd flr) and the periodicals room. No changed noted in 2007.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Fire Doors	500	SF	Basement Mechanical Rooms	Assumed	TSI	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Exterior Brick (Not AHERA)				Assumed						
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed						
Comments:											
Condition Not Changed in Spring 2011					Assumed						
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Exterior Brick Mortar (Not AHERA)				Assumed						
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed						
Comments:											
Condition Not Changed in Spring 2011					Assumed						
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Roof Flashing (Not AHERA)				Assumed						
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed						
Comments:											
Condition Not Changed in Spring 2011					Assumed						
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Insulation Inside Vault Doors	200	SF	Second, Third, & Fourth Floor Corridor	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" White Floor Tile w/Brown Streaks Mastic	3000	SF	South Building Corridors, Rooms 462, 463, and 465	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2004 - There is 1 SF of exposed mastic in Room 463 (localized). No change noted in 2007.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12" x 12" Beige Floor Tile w/Brown Streaks Mastic	700	SF	ROTC Basement Classroom (In Building Suspension room)	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2004 - There are 2 SF of exposed and damaged mastic in the ROTC Basement Classroom. No change noted in 2007.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Floor Sheeting	1000	SF	464	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2004 Comments - Room has been renovated, material not observed. No change noted in 2007. 2010 Comment Floor sheeting observed in classroom.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Blue Carpet Mastic	700	SF	374	Assumed	MISC	No	Dist	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Adhesive Beneath Tectum Panels	10000	SF	Auditorium, 113, 114, 101, 102	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No changed noted											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	12" x 12" Brown Floor Tile Mastic	1000	SF	Basement Corridor, Break Room, 3 basement locker rooms, Auditorium dressing rooms, auditorium entran	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Also noted in P.E. offices. No change noted in 2007.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	Roof Flashing - (Not AHERA)			2nd Floor Roof off ROTC Office	Chrysotile						
3YR Inspector Comments: Material contains asbestos.											
Condition Not Changed in Fall 2010					Chrysotile						
Comments:											
Condition Not Changed in Spring 2011					Chrysotile						
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	Beige Caulk on Metal - (Not AHERA)			2nd Floor Roof off ROTC Office	Chrysotile						
3YR Inspector Comments: Material contains asbestos											
Condition Not Changed in Fall 2010					Chrysotile						
Comments:											
Condition Not Changed in Spring 2011					Chrysotile						
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	Black Metal Sealant - (Not AHERA)			2nd Floor Roof off ROTC Office	Chrysotile						
3YR Inspector Comments: Material contains asbestos.											
Condition Not Changed in Fall 2010					Chrysotile						
Comments:											
Condition Not Changed in Spring 2011					Chrysotile						
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	Exterior Door Caulk - (Not AHERA)			South Building	Chrysotile						
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Chrysotile						
Comments:											
Condition Not Changed in Spring 2011					Chrysotile						
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	12" x 12" White w/Multi-Colored Specks FT	11	SF	Room 463	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: This floor tile is used for patching/replacement tile. No change noted in 2007.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	12" x 12" White w/Multi-Colored Specks FT Mastic	11	SF	Room 463	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	12 x 12 White VFT with blue streaks w/mastic	20000	SF	Classrooms throughout on 3rd and 4th floor north building. Teachers lounge, Copy Room 175,200, 202, Faculty Center faculty dining room.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA in 2007.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	12" x 12" blue and light blue checked VFT and glue	1000	SF	272, 161	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA in 2007.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	12" x 12" off white and brown checked VFT& and Mastic	500	SF	167	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA in 2007											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	12" x 12" blue and gray checked VFT& Mastic	2000	SF	163 -165, 160	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA in 2007											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	12 x 12 White with tan streaks VFT & glue	1000	SF	P.E. Office 130A, 130B,474C	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA in 2007											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	18" x 18" Blue Gray Floor tile	2850	SF	2nd floor lunchroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85m	Mastic for HA 85	2850	SF	2nd floor lunchroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	18" x 18"	2850	SF	3rd Floor Lunchroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86m	Mastic for HA 86	2850	SF	Third floor lunchroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	Light blue mottle lineloum	650	SF	Room 464	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87M	Mastic for HA 87	650	SF	Room 464	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	12" x 12" Tan floor tile with Brown Streaks	650	SF	Room 374	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88M	Mastic for HA 88	650	SF	Rom 374	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-100	Aircell pipe insulation debris	0	SF	Unexcavated spaces beneath the basement	Assumed	TSI	Yes				
3YR Inspector Comments: 2010 Comment: Material not observed. 2008 - Material was identified during the January 28, 2008 audit visit.											
Condition Not Changed in Fall 2010			SF		Assumed	TSI					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	TSI					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
HA-101	White woven copper Wire Insulation	30	LF	Old stage light fixtures in Auditorium	Assumed	MISC	Yes	None	0	LF		
3YR Inspector Comments: 2008 - material was identified during the January 28, 2008 audit visit.												
Condition Not Changed in Fall 2010			LF		Assumed	MISC				LF		
Comments:												
Condition Not Changed in Spring 2011			LF		Assumed	MISC				LF		
Comments:												
Fall 2011											YES	NO
Comment:												

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

All LEA Responsibilities, for this school, will be met.



Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.