

Chicago Public Schools

6 Month Asbestos Surveillance

2015 - Fall

School: Edward Tilden Career Community Academy
Address: 4747 S. Union

Oracle Unit: 53121
Region: 04

Building ID: 1590
Mail Room: 42

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: Kilroy, Mr. John
Survey Date: 10/9/2015
Email Address: jkilroy@cps.edu

A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via:
 Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	2x4 Ceiling Tile			003, 228, 438, 439, 227		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2	1x1 Ceiling Tile			Room 223		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments:missing

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	Plaster			Throughout		Miscellaneous					<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged
Comments:10 sq. ft. water damage.

2014- Spring: No Change
Comments:

2014 - Fall: Damaged
Comments:Water damage

2015- Spring: Damaged
Comments:water damage

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	12x12 VFT, Dark Brown	375	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4A	12x12 VFT, Dark Brown Mastic	375	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	9x9 VFT, Tan (Checkered)	11000	SF	1st, 2nd and 3rd Floor Hallways		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged
Comments:6 sq. ft.

2014- Spring: Damaged
Comments:6 sq. ft. damaged

2014 - Fall: Damaged
Comments:Approx. 2 sq, ft

2015- Spring: Damaged
Comments:missing tiles

2015 - Fall: Damaged
Comments:2nd floor front cross corridor has more damage , 3rd floor middle cross corridor has more damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5A	9x9 VFT, Tan Mastic (Checkered)	11000	SF	1st, 2nd and 3rd Floor Hallways		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Other
Comments:Same as 6A.

2014- Spring: No Change
Comments:

2014 - Fall: Damaged
Comments:Approx. 2 sq, ft

2015- Spring: Damaged
Comments:missing tiles

2015 - Fall: Damaged
Comments:2nd floor front cross corridor has more damage , 3rd floor middle cross corridor has more damage

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	9x9 VFT, Brown (Checkered)	11000	SF	1st, 2nd and 3rd Floor Hallways		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Other
Comments: Same as 6A.

2014- Spring: Damaged
Comments: 6 sq. ft. damaged

2014 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments: missing tiles

2015 - Fall: Damaged
Comments: 2nd floor front cross corridor has more damage , 3rd floor middle cross corridor has more damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6A	9x9 VFT, Brown Mastic (Checkered)	11000	SF	1st, 2nd and 3rd Floor Hallways		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged
Comments: 6sq. ft. damage tile

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments: missing tiles

2015 - Fall: Damaged
Comments: 2nd floor front cross corridor has more damage , 3rd floor middle cross corridor has more damage

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	Brown Linoleum			425 Hallway		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7A	Brown Linoleum Mastic			425 Hallway		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	12x12 VFT, Off-White Mottled	375	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9A	12x12 VFT, Off-White Mottled Mastic	375	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12x12 VFT, Yellowish Green	400	SF	1st Floor North Corridor		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10A	12x12 VFT, Yellowish Green Mastic	400	SF	1st Floor Corridor		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12x12 VFT, Off-White w/Tan Specks	2700	SF	Rooms 227, 317, 439		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11A	12x12 VFT, Off-White w/Tan Specks Mastic	2700	SF	Rooms 227, 317, 439		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12x12 VFT, Off-White w/Gray Specks	39000	SF	1st, 2nd, 3rd and 4th Floor Classrooms		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12A	12x12 VFT, Off-White w/Gray Specks Mastic	39000	SF	1st, 2nd, 3rd and 4th Floor Classrooms		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9x9 VFT, Beige w/Dark Specks	2800	SF	2nd and 3rd Floor N/E Hallways		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged
Comments:8 sq. ft. damage.

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments:missing tiles

2015 - Fall: Damaged
Comments:2nd floor front cross corridor has more damage , 3rd floor middle cross corridor has more damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13A	9x9 VFT, Beige w/Dark Specks Mastic	2800	SF	2nd and 3rd Floor N/E Hallways		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged
Comments:8 sq. ft. damage.

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments:missing tiles

2015 - Fall: Damaged
Comments:2nd floor front cross corridor has more damage , 3rd floor middle cross corridor has more damage

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12x12 VFT, Black	4000	SF	Kitchen and Lunchroom, Gym Locker Rm, Gym Teacher Washrm		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14A	12x12 VFT, Black Mastic	3400	SF	Kitchen and Lunchroom, Gym Locker Rm, Gym Teacher's Washrm		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12x12 VFT, Blue	900	SF	Room 437		Miscellaneous	No	Dist	90		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15A	12x12 VFT, Blue Mastic	2800	SF	Room 437		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12x12 VFT, Mottled Brown	900	SF	Room 213		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16A	12x12 VFT, Mottled Brown Mastic	900	SF	Room 213		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12x12 VFT, Mottled Tan	900	SF	Room 213		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17A	12x12 VFT, Mottled Tan Mastic	900	SF	Room 213		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12x12 VFT, Beige Mottled	2700	SF	Room 334, 331 (beneath new tile)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18A	12x12 VFT, Beige Mottled Mastic	2700	SF	Room 334, 331 (beneath new tile)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12x12 VFT, Mottled Gray			Room 440		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19A	12x12 VFT, Mottled Gray Mastic			Room 440		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12x12 VFT, Beige w/Red Specks	900	SF	Rooms 418		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20A	12x12 VFT, Beige w/Red Specks Mastic	900	SF	Rooms 418		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	9x9 VFT, Tan w/Dark Streaks			Room 332		Miscellaneous		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21A	9x9 VFT, Tan w/Dark Streaks Mastic			Room 332		Miscellaneous		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9x9 VFT, Brown	15	SF	4th Floor ROTC Rooms on Table		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22A	9x9 VFT, Brown Mastic	15	SF	ROTC Building, on Table		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Bluish Gray Linoleum			3rd Floor Gym		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: Damaged
Comments:Approx. 1 sq. ft.

2015- Spring: Damaged
Comments:small sections missing

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23A	Bluish Gray Linoleum Mastic			3rd Floor Gym		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Brick Mortar - Non AHERA			Exterior		Miscellaneous					<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged
Comments:water damage from gaps in the motar.

2014- Spring: No Change
Comments:

2014 - Fall: Damaged
Comments:Approx. 125 sq. ft.

2015- Spring: Damaged
Comments:water damage

2015 - Fall: Repaired
Comments:Construction done to parapit walls around building

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Limestone Mortar - Non AHERA			Exterior		Miscellaneous					<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged
Comments:water damage from gaps in the motar.

2014- Spring: No Change
Comments:

2014 - Fall: Deteriorated
Comments:approx. 100 sq. ft.

2015- Spring: No Change
Comments:

2015 - Fall: Repaired
Comments:Construction done to parapit walls around building

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Brick Mortar, ROTC Building - Non AHERA	1000	SF	ROTC Building Exterior		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	9x9 Sand Floor Tile	3200	SF	Rooms 301, 303, 102, 407, 409 , 102, 305 (beneath new tile)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015- Spring: Damaged
Comments:missing tiles

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27A	9x9 Sand Floor Tile Mastic	3700	SF	Rooms 301, 303, 102, 407, 409 , 102, 305 (beneath new tile)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments:missing tiles

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Wall Board			Rooms 226 and 228, Electrical Foreman's Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Stage Curtains			Auditorium		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Wire Insulation	1000	LF	Throughout		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12" x 12" Brown w/White Specks VFT	100	SF	4th flr corridor North E/W Corridor by Stairwell 7, 3rd flr North E/W Corridor by Stairwell 7		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" x 12" Brown w/White Specks VFT Mastic	100	SF	4th flr corridor North E/W Corridor by Stairwell 7, 3rd flr North E/W Corridor by Stairwell 7		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12" x 12" Yellow w/ White Specks VFT	1100	SF	Room 439		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12" x 12" Yellow w/ White Specks VFT Mastic	1100	SF	Room 439		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12" x 12" Dark Blue VFT	3000	SF	Room 331 and 333		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12" x 12" Dark Blue VFT Mastic	3000	SF	Room 331 and 333		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12" x 12" Light Blue VFT	2000	SF	Room 205,317		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12" x 12" Light Blue VFT Mastic	2000	SF	Room 103, 117, 121, 205, 231,305, 333, 335		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12" x 12" Yellow w/White Streaks VFT	3500	SF	Rooms 405, 401, 115, 113		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12" x 12" Yellow w/White Streaks VFT Mastic	3500	SF	Rooms 405, 401, 115, 113		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12" x 12" Tan w/Dk. Beige Specks Floor Tile	2000	SF	Rooms 329, 331		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" Tan w/Dk. Beige Specks Floor Tile Mastic	2000	SF	Rooms 329, 331		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12" x 12" Dark Grey w/White Specks VFT			Room 223 Closet, wood closet		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments:missing tiles

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12" x 12" Dark Grey w/White Specks VFT Mastic		SF	Room 223 Closet		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments:missing tiles

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12" x 12" Battleship Gray w/White Specks FT	1800	SF	Room 214,215		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12" x 12" Battleship Gray w/White Specks FT Mastic	1800	SF	Room 214,215		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12" x 12" Beige w/Dark Beige & White Specks FT	1000	SF	Room 211 and 209		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12" x 12" Beige w/Dk Beige & Wht Specks FT Mastic	1000	SF	Room 209 & 207		Miscellaneous	No	Loc	30		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments:missing tiles in room 209

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12" x 12" Beige w/Dk Beige & Wht Specks FT Mastic	1000	SF	Room 209, 207		Miscellaneous	No	Loc	30		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments:missing tiles in room 209

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12" x 12" Baby Blue w/Dk Blue Specks FT Mastic	500	SF	Room 205		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Damaged
Comments:missing tiles

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12" x 12" Olive Green w/Dk Green & Wht Specks FT	1000	SF	1st Floor North E/W Corridor		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12"x12" Olive Grn w/Dk Grn & Wht Specks FT Mastic	1000	SF	1st Floor North E/W Corridor		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Boiler Breeching	900	SF	Boiler Room		TSI	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged
Comments:2 sq. ft.

2014- Spring: Repaired
Comments:Patched breaching some acm leaching out still.

2014 - Fall: Deteriorated
Comments:friable ACM comes out of joints upon start up of boilers.

2015- Spring: Repaired
Comments:3/2014

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Two Tanks	900	SF	Boiler Room		TSI	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	Blue Linoleum and associated adhesive			403		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Lab table tops			Rooms 301,303,401,403,405,407		Miscellaneous		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Grey Rubber Flax Adhesive	2500	SF	Southwest Gym		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Green Carpet Adhesive	2000	SF	Library, 2nd Floor Lobby		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged
Comments:512 sq. ft. of carpeting removed.

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	Multicolored Carpet Adhesive	1500	SF	Room 320		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	Black Carpet Mastic	500	SF	Rm. 323		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Water Tank			Pump Room		TSI		None			<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Other
Comments:ACM removed 12/2010

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:removed 12/2010

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Boiler Gaskets	80	LF	Boiler Room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Aircell Pipe Insulation	100	LF	North Boy's Toilet in Basement, Boiler Room		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Fittings off Aircell Pipe Insulation	45	LF	North Boys' Toilet in Basement, Boiler Room		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-100	1'x1' white plain Ceiling tile	1000	SF	Kitchen		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-101	Glue for 1'x1' white plain Ceiling tile	1000	SF	Kitchen		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-102	Boiler Breeching Insulation	20	LF	Boiler rm		TSI	Yes	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged
Comments:2 sq. ft. damage.

2014- Spring: Repaired
Comments:See # 53

2014 - Fall: Other
Comments:See # 53

2015 - Fall: No Change
Comments:

2015- Spring: Repaired
Comments:3/2014

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Fittings Off Fiberglass Pipe Runs	25	LF	Pump Room		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M	Blue Carpet	200	SF	Auditorium		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Blue Carpet Mastic	200	SF	Auditorium		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

Lynn A. Crivello

Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Edward Tilden Career Community Academy

Date: 10/15/2015

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.