

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2015 - Fall

**School:** Chicago International Charter School (CICS)- Longwood Campus  
**Address:** 1309 W.95th St (9500S) 43

**Oracle Unit:** 66061  
**Region:** 02

**Building ID:** 2420  
**Mail Room:** 49

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** \_\_\_\_\_  
**Survey Date:** 11/10/2015  
**Email Address:** \_\_\_\_\_

A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 Each child's backpack   
 Notice printed in school's newsletter   
 Notice printed in school's calendar   
 Other

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01	Aircell Pipe Insulation	701	LF	Incinerator Room , Closet by Main Shop, Kitchen, Men's Washrrom Closet, 101-201-301 Janitor Closets, Aquinus Ground Floor Corridor, Tunnel leading to Convent, Weight Room & Attic Bldg 1890		TSI	No	Loc	4		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Preform Pipe Cover (Mag Block Pipe Insulation)	367	LF	Incinerator Room, Tunnel, Main Shop Room, Electric Room		TSI	Yes	None	1		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	Cardboard Pipe Cover	49	LF	Kitchen and Maintenance Closet		TSI	Yes	Loc	2		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	Aircell Pipe Joint Packing	67	LF	Tunnels and Corridors, Incinerator Room, Closet by Main Shop, Kitchen, Men's Washroom Closet, 101-201-301 Janitor Closets, Weight Room & Attic Bldg 1890		TSI	Yes	None	5		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Preformed Pipe Joint Insulation	44	LF	Incinerator Room, Main Shop Room, Tunnel, Electrical Room, Ground Floor Corridor		TSI	Yes	None	1		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Joint packing on Fiberglass Insulated Piping			Incinerator Rm, Tunnel, Basement Sink Room, Pantry and East Lunchroom		TSI	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Stack Insulation	0	SF	Incinerator Rm		TSI	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	KEWANEE BOILER COVER-ABATED	0	SF	MAIN BOILER RM		TSI	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	MAG BLOCK COVERING-ABATED	0	SF	Boiler Room		TSI	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	HAND PACKING-ABATED	0	LF	BOILER RM		TSI	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	HOT WATER HOLDING TANK	0	SF	BOILER RM		TSI	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	HOT WATER HOLDING TANK- ABATED	0	SF	BOILER ROOM		TSI	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19A	WRAP OVER FIBER GLASS		LF	HOT WATER HOLDING TANK-BOILER ROOM TUNNEL		TSI	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	TANK HARD PACKING-REMOVED	0	LF	CONVENT BOILER RM		TSI	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	COVERED VENT SUPPLYNG COMBUSTION AIR-ABATED	0	SF	MAIN BOILER RM		TSI	Yes				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	CONVAS COVERED BLOCK TYPE DUCT-ABATED	0		BOILER RM		TSI	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	PIPE JOINT-ABATED	0	LF	BOILER ROOM		TSI	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	LIGHT CORDS	150	LF	AUDITORIUM		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	ACOUSTIC PLASTER		SF	CONVENT CHAPEL		Surface	Yes				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	1'x1' Ceiling Tile	77046	SF	CLASSROOMS, HALLS, OFFICES, LUNCHROOMS, CAFETERIA, KITCHEN, MUSIC ROOM, AUDITORIUM		Miscellaneous	Yes	Loc	500		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	2'x4' Lay In Ceiling Tile	5000	SF	Corridors and Aquinas Buildings, 250, 254, 255, 257, 352, 358		Miscellaneous	Yes	Loc	72		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
 Comments:

2014- Spring: No Change  
 Comments:

2014 - Fall: No Change  
 Comments:

2015- Spring: No Change  
 Comments:

2015 - Fall: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12" x 12" Floor Tile Tan Mixed Speckled	10580	SF	Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, m, Washrooms, Classrooms, Corridors, Stairs,		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	9"x9" Floor Tile	37796	SF	Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	PLASTER	1495000	SF	Throughout All Buildings		Surface	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Blue Carpet Adhesive	1225	SF	Main Entrance, Office and Ground Floor Entrance by Parking Lot		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Brown Carpet Adhesive	120	SF	101 Closet		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Purple Carpet Adhesive	416	SF	Music Room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Brown Striped Carpet Adhesive	144	SF	Room 277		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Purple Carpet Adhesive	988	SF	Room 132		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Terrazzo	21646	SF	Throughout Facility Including: Stairways & Landings, Corridors, Washrooms, Classrooms, Teachers Lounge, Nurse, Locker Rooms, Cafeteria, Kitchen, Entrances, Bookroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Ceramic Tile Grout	2746	SF	Washrooms Throughout Facility		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Ceramic Tile Adhesive	2746	SF	Washrooms Throughout Facility		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Drywall	1350	SF	Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Drywall Compound	1350	SF	Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Tectum Ceiling Panels	5457	SF	Gym		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Chalkboard/Whiteboard Adhesive	7200	SF	Classrooms Throughout Facility		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Vinyl Stair Treads	582	SF	Throughout Facility Stairways		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Vinyl Stair Thread Adhesive	582	SF	Throughout Facility Stairways		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	4" Black Baseboard	701	LF	West Lunchroom, 051, 054, 281		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	4" Black Baseboard Adhesive	701	LF	West Lunchroom, 051, 054, 281		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	6" Brown Baseboard (Abated)	46	LF	Women's Ground Floor Washroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	6" Brown Basebord Adhesive	46	LF	Women's Ground Floor Washroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	4" Brown Baseboard	316	LF	Ground Floor Security Office and East Cafeteria		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	4" Brown Baseboard Adhesive	316	LF	Ground Floor Security Office and East Cafeteria		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	4" Grey Baseboard	70	LF	Room 351		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	4" Gray Baseboard Adhesive	70	LF	Room 351		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	4" x 4" Floor Tile	25	SF	Elevator in Aquinus Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	4" x 4" Floor Tile Mastic	25	SF	Elevator in Aquinus Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	Grey and Black Carpet Adhesive	2156	SF	Auditorium		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Acoustical Ceiling Plaster	1725	SF	Auditorium		Surface	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Pegboard on Walls	1960	SF	Teacher's Lounge		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	1 x 1 CT White	200	SF	Rm 126, Bldg 1950- Notre Dame		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	1 x 1 White w/ groves	4000	SF	Throughout Bld. 1950 - Notre Dame		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	12 x 12 VFT Tan Mixed Speckled	600	SF	Rm 126 Bldg 1950 Notre Dame		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	12 x 12 VFT Tan Mixed Speckled Mastic	600	SF	Rm 126 Bldg 1950 Notre Dame		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	9 x 9 VFT Gray w/ streaks VFT	2000	SF	Rm 128, 130, 144, 148, 146 Bldg 1950 Notre Dome		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	9 x 9 VFT Gray w/ Streaks Mastic	2000	SF	Rm 128, 130, 144, 148, 146 Bldg 1950 Notre Dame		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	9 x 9 VFT Green	1000	SF	Rm 128, 130, 144, 146 Bldg 1950 Notre Dame		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	9 x 9 VFT Green Mastic	1000	SF	Rm 128, 130, 144, 146 Bldg 1950 Notre Dame		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	Plaster	10000	SF	Throughout Bldg 1950 Notre Dame		Surface	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	12 x 12 VFT Gray w/ Balck & White Specks	500	SF	Stairway Bldg 1955 Eddison		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12 x 12 VFT Gray w/ Black & White Specs Mastic	500	SF	Stairway Bldg 1955 Eddison		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	9 x 9 VFT Tan	100	SF	Rm 230 Closet and Rm 231 Closet Bldg 1955 Eddison		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	9 x 9 VFT Tan Mastic	100	SF	Rm 230 Closet and Rm 231 Closet Bldg 1955 Edison		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	9 x9 VFT Dark Brown VFT	1200	SF	Rm 230, 231 Bldg 1955 Edison		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	9 x 9 VFT Dark Brown Mastic	1200	SF	Rm 230, 231 Bldg 1955 Edison		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	12 x 12 VFT Tan w/ Brown Specs	1200	SF	Rms 331, 330 Bldg 1955		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	12 x 12 VFT Tan w/ Brown Specs Mastic	1200	SF	Rms 331, 330 Bldg 1955		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	Gray Linoleum	60	SF	Rm 330 Closet Bldg 1955 (Edison)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	Gray Linoleum Mastic	60	SF	Rm 330 Closet Bldg 1955 (Edison)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	12 x 12 VFT Tan Mixed Speckled	2000	SF	Rm 54, 56, 22 HH, 03 HH, Bldg 1930 Hackman		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	12 x 12 VFT Tan Mixed Speckled Mastic	2000	SF	Rm 54, 56, 22HH, 03 HH, Bldg 1930 Hackman		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	Plaster	14000	SF	Throughout Bldg 1930		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	12 x 12 VFT Beige w/ white Specs	17000	SF	1st and 2nd Floor Corridor and 23H Bldg 1930 (Hackman Hall) Auditorium		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	12 x 12 VFT Beige w/ white Specs Mastic	17000	SF	1st and 2nd Floor Corridor and 23H Bld. 1930 (Hackman Hall) Auditorium		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	2 x 4 CT White w/ Swirls	1300	SF	43HH and 44HH Bldg 1930		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	12 x 12 Black VFT	7800	SF	1st and 2nd Flr Corridor and Auditorium Bldg 1930		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	12 x 12 Black VFT & Mastic	7800	SF	1st and 2nd Floor Corridor and Auditorium Bldg 1930		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	9 x 9 VFT Lt. Brown w/ Specs	100	SF	Rm 24HH, 25HH and 81HH Bldg 1930		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	9 x 9 VFT Lt Brown w/ Specs Mastic	100	SF	Rm 24HH, 25HH and 81 HH Bldg 1930		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	12 x 12 VFT Lt Brown w/ Mixed Specs	600	SF	Rm HH-1 Bldg 1930		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	12 x 12 VFT Lt Brown w/ mixed specs Mastic	600	SF	Rm HH-1 Bldg 1930		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
94	12 x 12 VFT Gray w/ white & Black Specs	500	SF	HH - 13 Bldg 1930		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	12 x 12 VFT Gray w/ white & Black Specs Mastic	500	SF	HH - 13 Bldg 1930		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
96	12 x 12 VFT Mixed Red Speckled	500	SF	Rm 362 Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	12 x 12 VFT Mixed Red Speckled Mastic	500	SF	Rm 362 Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
98	K1 CT White w/ Pinhole	12000	SF	Throughout 1920 Bldg		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	Terrazzo	12000	SF	Throughout Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	9 x 9 VFT Black w/ Camouflouge	400	SF	Rm 358 Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	9 x 9 VFT Black w/ Camouflouge Mastic	400	SF	Rm 358 Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	9 x 9 VFT Brown	400	SF	Rm 358 Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	9 x 9 VFT Brown Mastic	400	SF	Rm 358 Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	9 x 9 Brown VFT	1400	SF	Rm 356 and 354 Bldg. 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	9 x 9 Brown VFT & Mastic	1400	SF	Rm 356 and 354 Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	12 x 12 Gray VFT Speckled	3700	SF	Rm 350, 351, 352, 257, 254 Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	12 x 12 Gray VFT Speckled Mastic	3700	SF	Rm 350, 351, 352, 257, 254, Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	12 x 12 Gray w/ Red, White & Blue Specs VFT	800	SF	Stairwell Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
109	12 x 12 Gray w/ Red, White and Blue Specs Mastic	800	SF	Stairwell Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	Plaster	28000	SF	Throughout Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	12 x 12 VFT Beige w/ Black Streaks	600	SF	Rm 255 Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	12 x 12 VFT Beige w/ Black Streaks Mastic	600	SF	Rm 255 Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	1 x 1 Ceiling Tile white w/ Swirls	2100	SF	Weight Room and Rm 51 Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114	Green Terrazo	600	SF	Rm 51 Bldg 1920		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
115	Spray On	2300	SF	Attic Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116	Terrazzo	8000	SF	Throughout Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
117	12 x 12 VFT Gray Speckled	1200	SF	Rm 114 and 314 Bldg 1890		Miscellaneous	No	None	1200		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
118	12 x 12 VFT Gray Speckled Mastic	1200	SF	Rm 114 and 314 Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
119	1 x 1 CT White w/ Pinhole	29000	SF	Throughout		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
120	9 x9 VFT White w/ gray strks	1400	SF	Rm 201, 304, 316, 312, 310 Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
121	9 x 9 VFT White w/ gray Mastic	1400	SF	Rm 201, 304, 316, 312,310 Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
122	9 x 9 VFT (Black)	1900	SF	Rm 205, 307, 211, 216 and 312 Bldg. 1890 and Rm 305		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
123	9 x 9 VFT Black Mastic	1900	SF	Rm 205, 307, 211, 216, and 312 Bldg 1890 and Rm 305		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
124	9 x 9 VFT Pink w/ Black Strks	900	SF	Rm 211, 308 and 307 Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
125	9 x 9 VFT Pink w/ Black Strks Mastic	900	SF	Rm 211, 308 and 307 Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
126	9 x 9 VFT Dark Gray w/ white strks	600	SF	Rm 308 & 305 Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
127	9 x 9 VFT Dark Gray w/ white strks Mastic	600	SF	Rm 308, 305 Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
128	9 x 9 VFT Dark Pink w/ strks	600	SF	Rm 205 & 307 Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
129	9 x 9 VFT Dark Pink w/ strks Mastic	600	SF	Rm 205 & 307 Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
130	12 x 12 VFT Beige Mixed Speckled	2600	SF	Rm 106, 105, 200, 207, 116 Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
131	12 x 12 VFT Beige mixed speckled Mastic	2600	SF	Rm 106, 105, 200, 207, 116 Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
132	9 x 9 VFT H Brown	500	SF	Rm 208 Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
133	9 x 9 VFT H. Brown Mastic	500	SF	Rm 208 Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
134	Plaster	25000	SF	Throughout Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
135	12 x 12 VFT Purple Speckled	1800	SF	Lunchroom Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
136	12 x 12 VFT Purple Speckled Mastic	1800	SF	Lunchroom Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
137	12 x 12 VFT Tan w/ Lt Brown Specs	1800	SF	Lunchroom Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
138	12 x 12 VFT Tan w/ Light Brown Specs Mastic	1800	SF	Lunchroom Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
139	12 x 12 VFT Black	4000	SF	Basement & Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
140	12 x 12 VFT Black Mastic	4000	SF	Basement Bldg 1890		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CM	Mastic Associated with 1' x 1' Ceiling Tile	77046	SF	CLASSROOMS, HALLS, OFFICES, LUNCHROOMS, CAFETERIA, KITCHEN, MUSIC ROOM, AUDITORIUM		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
MM1	9" x 9" Floor Tile Mastic	37796	SF	Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
MM2	12" x 12" Floor Tile Mastic			Classrooms, Teachers Lounge, W Cafeteria, Ground Floor Corridor & Entries, Auditorium Entrance & Foyer, Reading Room, Staff Washrooms, Corridors, and Classrooms		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

*Lynn A. Crivello*

---

Lynn A. Crivello

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

Oracle Unit: 66061

Page 72

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Chicago International Charter School (CICS)- Longwood Campus

Date: 11/10/2015

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**