### ILLINOIS DEPARTMENT OF PUBLIC HEALTH AHERA THREE YEAR REINSPECTION ASBESTOS ABATEMENT PROGRAM SCHOOL INFORMATION FORM

**UNKNOWN** 

CHICAGO SCHOOL DIST 299

William B Ogden Elementary School

### **SECTION I**

NAME OF SCHOOL DISTRICT:

SCHOOL ID NUMBER:

**SCHOOL NAME:** 

ADDRESS OF SCHOOL: 24 W Walton St CITY: Chicago, IL, 60610 DATE LAST THREE YEAR REINSPECTION WAS COMPLETED If the address on this form is different than the address of the building, submit a written explanation. **SECTION II** (Please type or print) PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION: ENROLLMENT 1729 DATE REINSPECTION COMPLETED: 10/1/2019 IDPH INSPECTOR LICENSE NUMBER: 100-11089 IDPH LICENSED INSPECTOR NAME(Please Print): Panfilo Carrazco IDPH MP LICENSE NUMBER: 100-07342 IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197 Adul 10/1/2019 Signature of Designated Person Date **SECTION III** PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT. School building has been sold. Date of Sale: School has been closed. Date closed: School building has been demolished. Date: School building is asbestos free since last reinspection: Please explain in writing why the school building is now asbestos free and include the supporting documentation. If a new school building has been added to the district, submit either and exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building. Explain in writing if the address of the building is different than the address on this form:

IL-482-1026 Revised 10.03

### THREE-YEAR REINSPECTION

### **CHICAGO SCHOOL DIST 299**

### William B Ogden Elementary School

24 W Walton St Chicago, IL, 60610

Unit: 24731 Building ID: 5150

IDPH ID Number: UNKNOWN

### **REPORT DATE:**

Tuesday, October 01, 2019

Prepared for: Chicago Public Schools 42 West Madison Street Chicago, IL 60602

Prepared by: GSG-Probe Consulting, Inc.

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

DO NOT REMOVE FROM SCHOOL REQUIRED BY FEDERAL LAW

June 12, 2019

Mr. Glen E. Garner Asbestos Program Illinois Department of Public Health 525 West Jefferson Street Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 24731 Region: 02 IDPH ID:UNKNOWN

School: William B Ogden Elementary School Building ID: 5150

Address: 24 W Walton St

Chicago, IL, 60610

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 11/12/2019

Inspector: Panfilo Carrazco Inspector IDPH License: 100-11089

Management Planner: Jigar Shah Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at 3123197575

Sincerely, GSG-Probe Consulting, Inc.

Jigar Shah 100-07342

### **Environmental Notification to Occupants**

To: Faculty, Staff and Parents From: Chicago Public Schools

Date: June 12, 2019

RE: William B Ogden Elementary School, Unit 24731

24 W Walton St Chicago, IL, 60610

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at William B Ogden Elementary School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at William B Ogden Elementary School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197.

### **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

Appendix A: Assessment Sheets, Drawings and Photos

Appendix B: Inspector and Management Planner Licenses

Appendix C: Laboratory Accreditations

Appendix D: Laboratory Results

Appendix E: Chain of Custody Forms

### SCHOOL AND INSPECTION INFORMATION

### 1. School Information

William B Ogden School:

Unit: 24731

Region: 02

Elementary School

Address: 24 W Walton St IDPH ID: UNKNOWN

Chicago, IL, 60610 Building ID: 5150

Contact:

Phone:

### **Description of Facility**

Original Construction:

Additional Construction:

No of Floors:

Total Square Footage: 74400 Current Occupancy: 1729

### LEA Designated Person

Contact: Robert Christlieb

Phone: (773) 553-3197

Address: 42 West Madison Street Chicago, IL 60602

### **Managing Environmental Consultant**

MEC: GSG-Probe Consulting, Inc.

Contact: Jigar Shah

Address 2942 W. Van Buren

Chicago, IL, 60612

Phone: 3123197575 Fax:

### Inspector

Inspector Name: Panfilo Carrazco

Signature:

Inspector IDPH license # 100-11089 Date: 6/12/2019

### **Management Planner**

Management Planner Name: Jigar Shah

Signature:

Management Planner IDPH license # 100-07342 Date: 11/12/2019

### 7. Review Date:11/12/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:

Unit: 24731

Date: 10/1/2019

Name: Robert Christlieb

### II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the William B Ogden Elementary School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5150:

B. The following new homogenous areas have been identified for Building 5150:	

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:
The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Panfilo Carrazco, IDPH License # 100-11089. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### III. METHODOLOGY

Tasks performed on-site included the following:

- 1. Review current management plan, identify HA(s) and extract appropriate information.
- 2. Examine and verify abatement records.
- 3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
- 4. Touchand visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
- 5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
- 6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
- 7. Tabulate reinspection findingsand submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
- 8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

### **Abatement Dates:**

### V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### VI. CONCLUSIONS

The William B Ogden Elementary School Building 5150 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Attimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

### **Table I Inspector's Reinspection Findings**

School William B Ogden Elementary School Unit 24731 Building ID 5150

Address 24 W Walton St Region 02

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

Ī	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment	Damage Category	Damage Reason	Disturbance Potential
												Category			

School William B Ogden Elementary School Unit 24731 Building ID 5150

Address 24 W Walton St Region 02

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 6/12/2019

Inspector Name Panfilo Carrazco

<u>100-11089</u> <u>5/15/2020</u>

Inspector's IDPH License Number / Expiration Date

**Inspector's Comments** 

**HA Number:** Inspector Comments:

### Table II

### **Management Planner's Review**

William B Ogden

School Elementary School

**Unit** 24731

Building ID 5150

Address 24 W Walton St

Chicago, IL, 60610

Region 02

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

						mana	genien	. i idiiiici	3 001111	ments Gammanzea at the	End of the Report	
HA	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Category	Response	
Num	ber	Quantity	Units		Type	Category		Quantity	Units			

Review Date	11/12/2019
Manager Planner Name	Jigar Shah

HA Number Management Comments

William B Ogden

School Elementary School

Unit 24731

Building ID 5150

Address 24 W Walton St

Chicago, IL, 60610

Region 02

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

**Management Planner's Review Table II** 

Managing Environmental Consultant (MEC)

GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone:

3123197575

Fax:


Management Planner's Comments Summarized at the End of the Report

100-07342 5/15/2020 Manager IDPH License No/Expiration

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### APPENDIX B

### **Inspector and Management Planner Licenses**



FORM # A-010B

Doctor of Public Health

Nicholas J. Peneff

Certificate Number:



325-535 West Jefferson Street . Springfield, litinals 62761-0001 . www.dph.lllinals.gov

PANFILO CARRAZCO 855 W ADAMS STREET, SUITE 200 CHICAGO, IL 60607 4/28/2017

ASBESTOS PROFESSIONAL LICENSE ID NUMBER:

11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

### COPY OF THE ASBESTOS PROFESSIONAL LICENSE

]	Front of Licen	se	Back of License				
Hara to Dissentative of Person Hara	ASBE:	STOS SIONAL	ENDORSEMENTS	TC EXPIRES 2/11/2018			
Charles of Martin Secretary in	LICE	NSE	INSPECTOR				
ID NUMBER 100 - 11089	ISSUED 4/28/2017	EXPIRES 05/15/2018	PROJECT MANAGER	2/4/2018			
PANFILO CARRA	ZCO		AIR SAMPLING PROFESSIONAL				
855 W ADAMS ST CHICAGO, IL 6060 Environmental	7	ulf Denny	Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos  $EMAIL\ Address$ : dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Mationally Accredited by PHAB





525-535 West Jefferson Street . Springfield, Illinois 62761-0001 . www.dph.illinois.gov

PANFILO CARRAZCO 2942 W VAN BUREN ST CHICAGO, IL 60612

4/19/2019

### ASBESTOS PROFESSIONAL LICENSE ID NUMBER:

11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

### COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

ASBESTOS **PROFESSIONAL** 

**ID NUMBER** 100 - 11089 ISSUED 4/19/2019

**EXPIRES** 05/15/2020

PANFILO CARRAZCO 2942 W VAN BUREN ST CHICAGO, IL 60612

Environmental Health



**ENDORSEMENTS** TC EXPIRES

Back of License

INSPECTOR 2/9/2020

PROJECT MANAGER

AIR SAMPLING PROFESSIONAL

2/2/2020

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



525-535 Wast Jefferson Street . Springfield, Illinois 62761-8201 . www.dph.flfinsis.gov.

### 4/18/2016

PANFILO CARRAZCO 855 W ADAMS STREET, SUITE 200 CHICAGO, IL 60607

### ASBESTOS PROFESSIONAL LICENSE ID NUMBER:

11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

### COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License Back of License **ASBESTOS ENDORSEMENTS** TC EXPIRES **PROFESSIONAL** LICENSE INSPECTOR 2/13/2017 ID NUMBER ISSUED **EXPIRES** 4/18/2016 05/15/2017 100 - 11089 PROJECT MANAGER 2/6/2017 AIR SAMPLING PROFESSIONAL PANFILO CARRAZCO Alteration of this license shall result in legal action 855 W ADAMS STREET, SUITE This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid CHICAGO, IL 60607 Environmental Health training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-hcalth-protection/asbestos EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAS



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street • Willowbrook, IL 60527 • (630) 655-3900 • www.ofssafety.com

## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

### Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280695

Kathy DeSalvo, Director

Moth DeSalva



525-535 West Jefferson Street . Springfield, Illinois 62761-0001 . www.dph.illinois.gov

JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612

4/19/2019

### ASBESTOS PROFESSIONAL LICENSE ID NUMBER:

07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

### COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

TC EXPIRES



### **ASBESTOS PROFESSIONAL** LICENSE

**ID NUMBER** 100 - 07342

JIGAR M SHAH

CHICAGO, IL 60612

ISSUED . 4/19/2019

**EXPIRES** 05/15/2020



### **ENDORSEMENTS**

INSPECTOR 2/28/2020 PROJECT DESIGNER 3/15/2020 MANAGEMENT PLANNER 2/28/2020 PROJECT MANAGER 2/22/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action This license issued under authority of the State of Illinois 2942 W VAN BUREN ST Department of Public Health
This license is valid only when accompanied by a valid Environmental Health training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

### APPENDIX C

### **Laboratory Accreditations**

### APPENDIX D

### **Laboratory Results**

### APPENDIX E

### Chain of Custody Forms

### **Three-Year Reinspection Key to Terms**

	CODE	KEY
MATERIAL CATEGORY	ACBM	Asbestos Containing Building Materials
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed