

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1901	3	51,568	\$2,945,968
Branch	0	3	31,274	\$1,843,428
SITE				\$727,407
Campus Total		•	82,842	\$5,516,803

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Intranc	e						
	Entrance Control - Audio and Video	1	1	EA	7	\$0	
	Entrance Control - Audio and Video	2	1	EA	7	\$0	
	Exterior Doors - Exterior FRP Door	1	1	EA	7	\$0	
	Exterior Doors - Exterior FRP Door	9	1	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	2	2	EA	5	\$2,683	
	Exterior Doors - Exterior Steel Door	2nd Floor Fire Escape	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	3	2	EA	5	\$2,683	
	Exterior Doors - Exterior Steel Door	3rd Floor Fire Escape	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	4	2	EA	5	\$2,683	
	Exterior Doors - Exterior Steel Door	5	2	EA	5	\$2,683	
	Exterior Doors - Exterior Steel Door	6	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	7	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	8	2	EA	5	\$2,683	
	Exterior Doors - Exterior Wood Door	East Courtyard	1	EA	5	\$1,341	
	Exterior Doors - Exterior Wood Door	West Courtyard	1	EA	5	\$1,341	
	Exterior Doors - Side lite	1	1	EA	7	\$0	
	Exterior Doors - Side lite	2	1	EA	5	\$476	
	Exterior Doors - Side lite	2nd Floor Fire Escape	1	EA	6	\$313	
	Exterior Doors - Side lite	3rd Floor Fire Escape	1	EA	6	\$313	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Intran	ce						
	Exterior Doors - Side lite	9	1	EA	7	\$0	
	Exterior Doors - Transom Lite	1	1	EA	7	\$0	
	Exterior Doors - Transom Lite	2	2	EA	5	\$1,643	
	Exterior Doors - Transom Lite	2nd Floor Fire Escape	1	EA	6	\$313	
	Exterior Doors - Transom Lite	3	2	EA	5	\$1,643	
	Exterior Doors - Transom Lite	3rd Floor Fire Escape	1	EA	6	\$313	
	Exterior Doors - Transom Lite	4	2	EA	5	\$1,643	
	Exterior Doors - Transom Lite	6	1	EA	6	\$313	
	Exterior Doors - Transom Lite	9	1	EA	7	\$0	
	Exterior Stairs - Concrete	2	27	LF	6	\$2,208	
	Exterior Stairs - Concrete	3	6	LF	6	\$491	
	Exterior Stairs - Concrete	4	6	LF	6	\$491	
	Exterior Stairs - Concrete	West Courtyard	3	LF	7	\$0	
	Power Door Operator and Controls	1	1	EA	7	\$0	
ire Es	scape						
	Fire Escape	North Façade	110	LF	6	\$69,494	
ounda	ation						
	Foundation - Masonry	Entire Building	507	LF	7	\$0	
	Foundation - Masonry	Entire Building	50	LF	7	\$0	water infiltration at boiler room near courtyards
	Superstructure - Heavy Timber	Entire Building	51,568	SF	7	\$0	
.ightin	lg						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	2	EA	4	\$10,190	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	27	EA	6	\$14,486	
	Exterior Lighting - Wall Mounted	Entire Building	9	EA	6	\$2,599	
loof S	ystem						
	Cell Tower	A	1	EA	7	\$0	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	A / Boiler Room	82	LF	6	\$78,284	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	A / Boiler Room	2	LF	5	\$5,703	tuckpoint
	Coping - Metal	E / North	350	LF	5	\$14,795	
	Coping - Stone	A	665	LF	6	\$21,358	
	Coping - Stone	В	44	LF	6	\$1,413	
	Coping - Stone	С	44	LF	6	\$1,413	
	Coping - Stone	D	32	LF	6	\$1,028	
	Coping - Stone	E	68	LF	6	\$2,184	
	Coping - Stone	F	66	LF	5	\$7 228	open joints



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof S	ystem						
	Downspouts - Exterior Downspouts	A	288	LF	6	\$9,571	
	Downspouts - Exterior Downspouts	В	42	LF	6	\$1,396	
	Downspouts - Exterior Downspouts	С	42	LF	6	\$1,396	
	Downspouts - Exterior Downspouts	D	40	LF	6	\$1,329	
	Downspouts - Exterior Downspouts	E	24	LF	6	\$798	
	Downspouts - Exterior Downspouts	F / East	14	LF	4	\$1,896	dented downspout and cover
	Downspouts - Exterior Downspouts	F / West	14	LF	6	\$465	
	Parapet - 16" - 30" Height	A	434	LF	6	\$17,340	
	Parapet - 16" - 30" Height	В	44	LF	6	\$1,758	
	Parapet - 16" - 30" Height	С	44	LF	6	\$1,758	
	Parapet - 16" - 30" Height	E / North	98	LF	6	\$3,916	
	Parapet - 16" - 30" Height	F	66	LF	5	\$11,419	
	Parapet - Parapet < 16" Height	D	7	LF	6	\$149	
	Parapet - Parapet < 16" Height	E / North	320	LF	6	\$6,818	
	Parapet - Parapet > 30"	A	111	LF	6	\$8,498	
	Parapet - Parapet > 30"	A / North	120	LF	4	\$107,231	deteriorated/open mortar joints & spalled brick
	Parapet - Parapet > 30"	В	44	LF	6	\$2,813	
	Parapet - Parapet > 30"	С	44	LF	6	\$2,813	
	Parapet - Parapet > 30"	D	25	LF	6	\$1,598	
	Roof Structure - Heavy Timber	A	10,802	SF	7	\$0	
	Roof Structure - Heavy Timber	В	480	SF	6	\$5,217	
	Roof Structure - Heavy Timber	С	480	SF	6	\$5,217	
	Roof Structure - Heavy Timber	D	705	SF	7	\$0	
	Roof Structure - Heavy Timber	E	3,964	SF	7	\$0	
	Roof Structure - Heavy Timber	F	266	SF	7	\$0	
	Roof - Metal	D / South	80	SF	6	\$1,072	
	Roof - Modified Bitumen	A	10,802	SF	6	\$101,640	
	Roof - Modified Bitumen	В	480	SF	6	\$4,517	
	Roof - Modified Bitumen	С	480	SF	6	\$4,517	
	Roof - Modified Bitumen	D	625	SF	5	\$13,147	ponding, moss growth at drain
	Roof - Modified Bitumen	E	3,964	SF	6	\$37,299	
	Roof - Modified Bitumen	F	266	SF	6	\$2,503	
Walls							
	Cheek-Wall - Stone	Entire Building	48	SF	6	\$492	
	Cornice - Cast Stone	Entire Building	330	LF	6	\$11,444	
	Exterior Walls - Brick	Entire Building	25,213	SF	6	\$169,457	
	Exterior Walls - Brick	Entire Building	1,450	SF	4	\$238,743	step cracks, displacement
		D 0					



Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Walls							
	Exterior Walls - Brick	Entire Building / Site West	180	SF	6	\$1,634	
	Exterior Walls - Stone-Cut	Entire Building	792	SF	5	\$12,639	chipped with open joints
	Exterior Walls - Stone-Cut	Entire Building	488	SF	6	\$3,817	open joints
	Exterior Walls - Stone-Cut	Entire Building	280	SF	5	\$4,933	clean/replace broken pieces
	Exterior Walls - Stone-Cut	Entire Building	336	SF	6	\$3,051	cleaning horizontal bands
	Exterior Walls - Stone-Cut	Entire Building / 1st Floor	2,128	SF	6	\$14,302	
Window	vs						
	Guard - Guards perforated	Entire Building	2,134	SF	6	\$27,251	
	Lintels - Brick	Entire Building	368	LF	6	\$0	
	Lintels - Stone	Entire Building	370	LF	5	\$60,894	repair chips/cracks and repoint
	Windows - Louver	Entire Building	50	SF	6	\$373	
	Windows - Sash Aluminum Double-pane	Entire Building	6,036	SF	6	\$45,056	
Build	ing Exterior Subtotal:				\$1	,211,012	

5

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Automatic Transfer Switch	Basement	1	EA	4	\$8,200	Note: This is an existing ATS and is co-located in the switchgear room with the main switchboard.
	Emergency A/C Power - Corridors and Stairs	Entire Building	9,293	SF	6	\$2,791	
	Emergency A/C Power - Students Toilets	Entire Building	1,145	SF	6	\$426	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	22	EA	7	\$0	
	Emergency Battery Packs - Gym	Entire Building / 1st Floor	2	EA	6	\$405	
	Emergency Battery Packs - Lunchrooms	Entire Building / Basement	1	EA	7	\$0	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	7	\$0	
	Exit Signs - Corridors and Stairs	Entire Building	28	EA	7	\$0	
	Exit Signs - Gym	Entire Building	2	EA	6	\$315	
	Exit Signs - Lunchroom	Entire Building	2	EA	7	\$0	
	Security System - CCTV	1st Floor	51,568	SF	5	\$40,558	
	Security System - Intrusion Detection	Entire Building	51,568	SF	6	\$13,274	
Main S	ervice						
	Independent Electrical Service for emergency power	Basement	1	EA	6	\$2,921	EM Lighting Panel is screw type fuses. EM Service is common tap from same transformer as main power supply to switchgear.
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	5	\$0	-



Building: Main

Category: Electrical System

o Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Service						
PA System	Entire Building	51,568	SF	5	\$35,396	Per the Building Engineer, the entire PA system is fully functional. However, the components are over 20 years old not all areas are covered.
r Distribution						
r Distribution Lighting and Power Panels - Above 100 A	Entire Building	7	EA	7	\$0	
	Entire Building Entire Building	7 8		7 6	\$0 \$3,976	

Electrical System Subtotal:

\$109,316

Building: Main

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alar	m						
	Fire Alarm Panel	Basement / Electrical Room	1	EA	7	\$0	
	Fire Alarm Strobe Lights	Basement / Entire Building	51,568	SF	7	\$0	
	Fire Alarm_System	Basement / Entire Building	51,568	SF	7	\$0	
	Fire Pump Controller	Basement	1	EA	4	\$23,389	
Pump R	oom Assembly						
	Fire Pump - Less than 25hp	Basement	1	EA	5	\$5,674	
Sprinkle	er System						
	Dry Sprinkler System	Entire Building	51,568	SF	5	\$18,436	
	Sprinkler Heads	Entire Building	51,568	SF	4	\$26,547	
	Sprinkler Piping	Entire Building	51,568	SF	5	\$36,134	
Safty S	System Subtotal:					\$110,179	

Safty System Subtotal:

Building: Main

Category: Mechanical System

-							
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Cor	ditioning						
	Condensing Unit- Ground Mounted - Less than 5 tons	East Entrances	1	EA	7	\$0	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	7	\$0	



Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Han	dling Systems						
	Air Handling Unit- Built Up-Multi Zone-Double Delivery- Steam Coils - 30001 - 45000 cfm	Basement	1	EA	5	\$184,422	System has 2 return dampers for hallway air located in the OA intake chamber
	Air Intake	Basement	2	EA	5	\$14,941	
	Auxiliaries - 30001 - 45000 cfm	Basement	1	EA	5	\$18,883	
	Fan Coil Unit- Celing Mounted - Electric	3rd Floor	1	EA	6	\$820	
	Fan Coil Unit- Celing Mounted - Electric	Basement	1	EA	6	\$820	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	400	LF	4	\$0	
	Zone Dampers	Basement / Mechanical Room	25	EA	6	\$20,826	Engineeer states that all actuators worked well before the main pneumatic line was cut. West hot deck/cold deck has 13 zones. East hot deck/cold deck has 12 zones.
Boiler S	Systems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	\$24,345	
	Chemical Feeder	Boiler Room	2	EA	6	\$2,156	
	Combustion Dampers	Boiler Room	2	EA	6	\$818	
	Condensate Pump	Boiler Room	2	EA	6	\$4,042	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	\$2,545	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	\$24,345	
	Piping - Condensate Pipe- Steel	Boiler Room / Entire Building	200	LF	6	\$378	
	Piping - Steam Pipe- Steel	Boiler Room / Entire Building	200	LF	6	\$378	
	Steam Traps	Boiler Room / Entire Building	20	EA	6	\$5,283	
Heating	Devices						
	Cabinet Heaters - With Steam Coil	Entire Building	2	EA	6	\$713	
	Cabinet Heaters - With Steam Coil	Entire Building	10	EA	7	\$0	
	Fin Tube - Steam	Electrical Room	8	LF	5	\$651	
	Unit Heater - Electric	Entire Building	12	EA	7	\$0	
	Unit Heater - Electric	Entire Building	1	EA	4	\$2,001	
	Unit Heater - Gas	Boiler Room	1	EA	5	\$1,527	
Temper	ature Control						
	Electric Thermostat	Entire Building	2	EA	7	\$0	
	Pneumatic System	Entire Building / Basement	51,568	SF	5	\$177,719	Compressor looks semi new but cut line has not been fixed.
	Thermostats - Pneumatic	Entire Building	20	EA	6	\$0	



Building: Main

Category: Mechanical System

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
entilation						
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	6	\$592	Brand: Greenheck Model #: US6F-160HP-7-6 S/N: 12456607 1105
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	3	EA	4	\$12,734	
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	1	EA	6	\$592	
Type II Exhaust Hood- Warming Kitchen	Entire Building / Basement	1	EA	7	\$0	
lashan isal Quatam Qubtatal					¢504 500	

Mechanical System Subtotal:

\$501,532

Building: Main

Category: Plumbing System

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ot Wat	er						
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	2	EA	7	\$0	
ping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	51,568	SF	7	\$0	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	51,568	SF	7	\$0	
	Domestic Piping-Cold Water Risers	Entire Building	51,568	SF	4	\$41,296	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	51,568	SF	7	\$0	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	51,568	SF	7	\$0	
	Domestic Piping-Hot Water Return Lines	Entire Building	51,568	SF	6	\$7,374	
	Domestic Piping-Hot Water Return Risers	Entire Building	51,568	SF	4	\$25,072	
	Sanitary Piping	Entire Building	51,568	SF	6	\$47,195	
	Storm Piping	Entire Building	51,568	SF	6	\$44,983	
	Vent Piping	Entire Building	51,568	SF	6	\$34,659	
mps							
	Pumps - Sump-Duplex	Basement	1	EA	7	\$0	
	Pumps - Sump-Simplex	Basement	1	EA	7	\$0	
	ing System Subtotal:					\$200,579	

Calegory. Classrooms			
Group Item - Type	Location	Quantity Unit Rank	Cost Comments
Classroom #102 (Regular Classroom)			
Casework		7 LF 6	\$177

Building: Main

Category: Classrooms

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	oom #102 (Regular Classroom)						
	Ceiling - Plaster/Drywall		949	SF	6	\$3,284	
	Doors - Transom Window		8	SF	6	\$135	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		949	SF	6	\$6,690	
	Lighting - Pendent/Surface		14	EA	6	\$1,735	
	Marker Board		24	LF	7	\$0	
	Storage/ Closet		150	SF	6	\$1,088	
	Walls - Plaster/Drywall		1,393	SF	6	\$3,845	
Classro	oom #103 (Regular Classroom)						
	Casework		7	LF	6	\$177	
	Ceiling - Plaster/Drywall		949	SF	6	\$3,284	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		949	SF	5	\$13,883	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		48	LF	7	\$0	
	Storage/ Closet		150	SF	6	\$1,088	
	Walls - Plaster/Drywall		1,393	SF	6	\$3,845	
Classro	oom #104 (Regular Classroom)						
	Casework		11	LF	5	\$2,300	
	Ceiling - Plaster/Drywall		871	SF	6	\$3,014	
	Doors - Transom Window		8	SF	6	\$135	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Wood		871	SF	6	\$6,140	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		48	LF	7	\$0	
	Storage/ Closet		122	SF	6	\$885	
	Walls - Plaster/Drywall		1,349	SF	6	\$3,723	
Classro	oom #105 (Regular Classroom)						
	Casework		10	LF	6	\$253	
	Ceiling - Plaster/Drywall		858	SF	6	\$2,969	
	Chalk Board		24	LF	4	\$2,203	partially covered
	Doors - Transom Window		16	SF	6	\$271	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Wood		858	SF	5	\$12,552	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		10	LF	6	\$214	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #105 (Regular Classroom)						
	Storage/ Closet		150	SF	6	\$1,088	
	Walls - Plaster/Drywall		1,335	SF	6	\$3,684	
	Work Sink		1	EA	5	\$1,508	
Classro	oom #106 (Gymnasium)						
	Ceiling - Plaster/Drywall		956	SF	6	\$3,308	
	Doors - Transom Window		8	SF	6	\$135	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		956	SF	6	\$6,740	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Storage/ Closet		122	SF	6	\$885	
	Walls - Plaster/Drywall		1,913	SF	6	\$5,280	
Classro	oom #202 (Regular Classroom)						
	Casework		4	LF	6	\$101	
	Ceiling - Plaster/Drywall		885	SF	5	\$8,112	cracks
	Doors - Transom Window		8	SF	5	\$339	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		885	SF	6	\$6,239	
	Lighting - Pendent/Surface		14	EA	6	\$1,735	
	Marker Board		24	LF	6	\$514	
	Storage/ Closet		143	SF	6	\$1,037	
	Walls - Plaster/Drywall		1,348	SF	5	\$10,216	
Classro	oom #203 (Regular Classroom)						
	Casework		4	LF	6	\$101	
	Ceiling - Plaster/Drywall		949	SF	6	\$3,284	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		949	SF	6	\$6,690	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		48	LF	6	\$1,028	
	Storage/ Closet		150	SF	6	\$1,088	
	Walls - Plaster/Drywall		1,367	SF	5	\$10,360	
Classro	oom #204 (Regular Classroom)						
	Ceiling - Plaster/Drywall		883	SF	6	\$3,056	
	Chalk Board		24	LF	4	\$2,203	partially covered
	Doors - Transom Window		8	SF	6	\$135	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #204 (Regular Classroom)						
	Floor - Wood		883	SF	5	\$12,917	
	Lighting - Pendent/Surface		14	EA	6	\$1,735	
	Marker Board		34	LF	6	\$728	
	Storage/ Closet		135	SF	6	\$979	
	Walls - Plaster/Drywall		1,372	SF	6	\$3,787	
Classro	oom #205 (Regular Classroom)						
	Casework		4	LF	6	\$101	
	Ceiling - Plaster/Drywall		950	SF	6	\$3,288	
	Chalk Board		24	LF	4	\$2,203	
	Doors - Transom Window		16	SF	6	\$271	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Wood		950	SF	5	\$13,897	
	Lighting - Pendent/Surface		14	EA	6	\$1,735	
	Marker Board		48	LF	6	\$1,028	
	Walls - Plaster/Drywall		1,380	SF	5	\$10,459	
Classro	oom #206 (Regular Classroom)						
	Casework		7	LF	6	\$177	
	Ceiling - Plaster/Drywall		948	SF	6	\$3,281	
	Chalk Board		24	LF	4	\$2,203	partially covered
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		948	SF	6	\$6,683	
	Lighting - Pendent/Surface		14	EA	6	\$1,735	
	Marker Board		48	LF	6	\$1,028	
	Storage/ Closet		145	SF	6	\$1,051	
	Walls - Plaster/Drywall		1,443	SF	5	\$10,936	
Classro	oom #302 (Regular Classroom)						
	AC Units		2	EA	6	\$991	
	Casework		4	LF	6	\$101	
	Ceiling - Plaster/Drywall		885	SF	6	\$3,063	
	Doors - Transom Window		8	SF	6	\$135	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		885	SF	5	\$12,947	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		30	LF	6	\$643	
	Storage/ Closet		143	SF	6	\$1,037	
	Walls - Plaster/Drywall		1,378	SF	6	\$3,803	

Cateo	ory: Classrooms						
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	om #302 (Regular Classroom)	Location	quantity	0		0001	
Classro	om #303 (Regular Classroom)						
	Casework		7	LF	5	\$1,464	
	Ceiling - Plaster/Drywall		947	SF	6	\$3,277	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		947	SF	6	\$6,676	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		24	LF	6	\$514	
	Storage/ Closet		159	SF	6	\$1,153	
	Walls - Plaster/Drywall		1,329	SF	4	\$13,379	cracks in plaster and peeling paint
lassro	om #304 (Regular Classroom)						
	Casework		7	LF	6	\$177	
	Ceiling - Plaster/Drywall		898	SF	6	\$3,108	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		898	SF	5	\$13,137	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		32	LF	6	\$685	
	Storage/ Closet		143	SF	6	\$1,037	
	Walls - Plaster/Drywall		1,341	SF	5	\$10,163	
Classro	om #305 (Library)						
	AC Units		2	EA	7	\$0	
	Casework		93	LF	7	\$0	
	Ceiling - Plaster/Drywall		2,044	SF	6	\$7,073	
	Doors - Side-lite		24	SF	6	\$401	
	Doors - Wood Doors inclu hw		3	EA	6	\$903	
	Floor - Carpet		2,044	SF	6	\$4,355	
	Lighting - Pendent/Surface		28	EA	7	\$0	
	Storage/ Closet		446	SF	6	\$3,234	
	Walls - Plaster/Drywall		1,433	SF	5	\$10,861	
lassro	om #306 (Computer Lab)						
	AC Units		2	EA	6	\$991	
	Ceiling - Plaster/Drywall		885	SF	6	\$3,063	
	Chalk Board		7	LF	4	\$643	
	Doors - Steel Doors incl hw		1	EA	7	\$0 \$0	
	Doors - Transom Window		24	SF	6	φ0 \$406	
	Doors - Transom Window		12	SF	7	\$400 \$0	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #306 (Computer Lab)						
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Carpet		885	SF	7	\$0	
	Lighting - Pendent/Surface		28	EA	7	\$0	
	Storage/ Closet		150	SF	6	\$1,088	
	Walls - Plaster/Drywall		1,284	SF	5	\$9,731	
	Wireless System		1	EA	7	\$0	
Class	rooms Subtotal:					\$358,332	

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comme			
Adminis	dministrative Suites/Offices									
	Ceiling - Plaster/Drywall	003 Office	291	SF	7	\$0				
	Doors - Wood Doors inclu hw	003 Office	1	EA	7	\$0				
	Floor - Tile/Sheet	003 Office	291	SF	6	\$291				
	Lighting - Pendent/Surface	003 Office	5	EA	7	\$0				
	Storage/ Closet	003 Office	87	SF	6	\$631				
	Walls - Masonry	003 Office	300	SF	6	\$944				
	Walls - Plaster/Drywall	003 Office	300	SF	6	\$828				
	Ceiling - Plaster/Drywall	006A Engineer Office in 016 Engine Room	98	SF	6	\$339				
	Doors - Wood Doors inclu hw	006A Engineer Office in 016 Engine Room	1	EA	5	\$1,174				
	Floor - Tile/Sheet	006A Engineer Office in 016 Engine Room	98	SF	6	\$98				
	Lighting - Pendent/Surface	006A Engineer Office in 016 Engine Room	2	EA	7	\$0				
	Walls - Masonry	006A Engineer Office in 016 Engine Room	198	SF	5	\$8,183				
	Walls - Plaster/Drywall	006A Engineer Office in 016 Engine Room	198	SF	5	\$1,501				
	Ceiling - Plaster/Drywall	008 Staff Lounge	467	SF	7	\$0				
	Doors - Wood Doors inclu hw	008 Staff Lounge	1	EA	7	\$0				
	Floor - Tile/Sheet	008 Staff Lounge	467	SF	6	\$467				
	Lighting - Pendent/Surface	008 Staff Lounge	12	EA	6	\$1,487				
	Power Distribution	008 Staff Lounge	6	EA	6	\$12,749				
	Walls - Plaster/Drywall	008 Staff Lounge	676	SF	6	\$1,866				
	Ceiling - Exposed	010 Kitchen Office	322	SF	6	\$479				



ıp Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
inistrative Suites/Offices						
Doors - Wood Doors inclu hw	010 Kitchen Office	4	EA	6	\$1,204	
Floor - Tile/Sheet	010 Kitchen Office	322	SF	6	\$322	
Lighting - Pendent/Surface	010 Kitchen Office	2	EA	6	\$248	
Walls - Masonry	010 Kitchen Office	562	SF	6	\$1,768	
Ceiling - Plaster/Drywall	101A Office	204	SF	7	\$0	
Doors - Wood Doors inclu hw	101A Office	1	EA	6	\$301	
Floor - Tile/Sheet	101A Office	204	SF	6	\$204	
Lighting - Pendent/Surface	101A Office	4	EA	6	\$496	
Walls - Plaster/Drywall	101A Office	653	SF	7	\$0	
Ceiling - Plaster/Drywall	101B Office	351	SF	7	\$0	
Doors - Wood Doors inclu hw	101B Office	1	EA	7	\$0	
Floor - Tile/Sheet	101B Office	281	SF	6	\$281	
Lighting - Pendent/Surface	101B Office	8	EA	7	\$0	
Storage/ Closet	101B Office	70	SF	6	\$508	
Walls - Plaster/Drywall	101B Office	740	SF	6	\$2,042	
Ceiling - Plaster/Drywall	107 Office	310	SF	6	\$1,073	
Doors - Transom Window	107 Office	8	SF	6	\$135	
Doors - Wood Doors inclu hw	107 Office	1	EA	6	\$301	
Floor - Tile/Sheet	107 Office	310	SF	5	\$1,392	
Lighting - Pendent/Surface	107 Office	6	EA	6	\$743	
Storage/ Closet	107 Office	6	SF	6	\$44	
Walls - Plaster/Drywall	107 Office	733	SF	6	\$2,023	
AC Unit	108 Main Office	1	EA	6	\$496	
Ceiling - Plaster/Drywall	108 Main Office	380	SF	6	\$1,315	
Doors - Transom Window	108 Main Office	8	SF	6	\$135	
Doors - Wood Doors inclu hw	108 Main Office	1	EA	6	\$301	
Floor - Tile/Sheet	108 Main Office	380	SF	6	\$380	
Lighting - Pendent/Surface	108 Main Office	6	EA	6	\$743	
Power Distribution	108 Main Office	12	EA	6	\$25,499	
Walls - Plaster/Drywall	108 Main Office	863	SF	6	\$2,382	
Ceiling - Plaster/Drywall	201A Office	209	SF	6	\$723	
Doors - Wood Doors inclu hw	201A Office	1	EA	6	\$301	
Floor - Wood	201A Office	209	SF	6	\$1,473	
Lighting - Pendent/Surface	201A Office	4	EA	6	\$496	
Storage/ Closet	201A Office	162	SF	6	\$1,175	
Walls - Plaster/Drywall	201A Office	722	SF	7	\$0	
Ceiling - Plaster/Drywall	201B Office	265	SF	6	\$917	



Building: Main

Administrative Subsect/Item V V Dors - Wood Dorrs Inclu Inv 2018 Office 1 EA 6 \$265 Lipting - Paridett/Surface 2018 Office 26 S 6 \$226 Lipting - Paridett/Surface 2018 Office 36 S 6 \$226 Walls - Plaster/Dynall 2018 Office 7 S0 Adu Ontin 301A Office 1 EA 4 \$6.66 AC unit does not work Celling - Plaster/Dynall 301A Office 1 EA 7 S0 Doros - Wood Doors inclu Inv 301A Office 35 SF 6 \$457 301E Upting - Pendent/Surface 301A Office 35 SF 6 \$457 301E Upting - Pendent/Surface 301A Office 35 SF 6 \$457 301E Upting - Pendent/Surface 301A Office 35 SF 6 \$452 301E Upting - Pendent/Surface 011 Food Saracice 122 SF 6<	Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Dors - Word Dors indu hw 2018 Office 1 EA 6 \$301 Floor - TheOhenel 2018 Office 4 EA 7 \$301 Strange/ Closet 2018 Office 4 EA 7 \$30 Wales - Flaster/Drywall 2018 Office 1 EA 4 \$50,066 AC unit does not work Celling - Flaster/Drywall 301A Office 1 EA 4 \$50,066 AC unit does not work Celling - Flaster/Drywall 301A Office 15 S 6 \$\$477 Doors - Wood Doors inclu hw 301A Office 15 S 6 \$\$167 Vood Core sinclu hw 301A Office 15 S 6 \$\$177 \$\$0 Straage/ Closet 301A Office 15 S 6 \$\$1475 \$\$15 Vood Core sinclu hw 301A Office 516 SF 6 \$\$1,371 Doors - Wood Oors inclu hw 011 Food Service 92 SF 6 \$\$1,424 Walls - Ving Coated Gysoum Panel											
FloorFloorFloor6StrateLighting - Pendent/Surface2018 Office65SF6SV-14Walle - Plaster/Dywall2018 Office65SF6SV-14AC Unit2018 Office15SF6SV-14AC Unit301A Office15SF6SV-14DoorsNood Doors inclu hw301A Office15SF6SV-14DoorsNood Doors inclu hw301A Office15SF6SV-14Lighting - Pendent/Surface301A Office15SF6SV-14Nood Doors inclu hw301A Office63SF6SV-14DoorsNood Doors inclu hw301A Office577S0Doors101 Food Service922SF8\$1,371Doors11 Food Service922SF7S0Poor- Wood11 Food Service922SF7S0Poor- Wood Doors inclu hw011 Food Service922SF7S0Poor- Hile011 Food Service928SF7S0Poor- Hile011 Food Service928SF7S0Poor- Hile011 Food Service928SF7S0 </td <td></td> <td></td> <td>201B Office</td> <td>1</td> <td>EA</td> <td>6</td> <td>\$301</td> <td></td>			201B Office	1	EA	6	\$301				
Induiting - Pendent/Surface2018 Office4FA7%0Storage Closet2018 Office75056\$471Wale - Plaster/Dywall2018 Office750576\$471Calling - Plaster/Dywall3014 Office15576\$407Calling - Plaster/Dywall3014 Office15576\$547Dores - Wood Doors inclu tw3014 Office15576\$552Iptor Wood3014 Office15576\$542Universe Closet3014 Office356\$142Universe Closet3014 Office356\$142Verse Closet3014 Office25576\$142Verse Closet3014 Office25576\$142Verse Closet3014 Office25576\$142Verse Closet3014 Office25576\$142Verse Closet3014 Office25576\$213Ipting - Pendent/Surface011 Food Service182576\$238Unither Devse Closet111 Food Service182576\$547Unither Devsel3014 Office182577\$00Unither Devsel3014 Office182577\$01Unither Devsel3014 Office182577\$02Unither Devsel3014 Office182577\$02Unither Devsel3014 Office182 <td< td=""><td></td><td></td><td>201B Office</td><td>265</td><td></td><td></td><td></td><td></td></td<>			201B Office	265							
Sincage Closet 2018 Office 75 5 6 7471 Walls - Plaster/Drywall 2018 Office 750 SF 7 800 A C Unit 301A Office 18 K 8 808 AC Unit does not work Colling - Plaster/Drywall 301A Office 18 K 7 80 Doors - Wood Doors inclu hw 301A Office 38 F 6 9457 301E Lighting - Pendent/Surface 301A Office 38 F 6 9457 301E Kitce Stronge Closet 301A Office 35 F 6 \$15.24 Colling - Exposed 011 Food Service 92 SF 6 \$1.371 Doors - Wood Doors inclu hw 011 Food Service 22 SF 6 \$2.017 Boors - Wood Doors inclu hw 011 Food Service 28 5 6 \$2.017 Lighting - Pendent/Surface 011 Food Service 28 5 6 \$2.017 Boors - Vinod Doors inclu hw 11 Food Service <td></td> <td>Lighting - Pendent/Surface</td> <td>201B Office</td> <td>4</td> <td>EA</td> <td>7</td> <td></td> <td></td>		Lighting - Pendent/Surface	201B Office	4	EA	7					
A C Unit301A Office1EA4\$6,08A C unit does not workCeiling - Plaster/Dywall301A Office13576\$467Boors - Wood Doors inclu hw301A Office13576\$952Lighting - Pender/Surface301A Office13576\$952Storage/ Closet301A Office63576\$472Walls - Plaster/Dywall301A Office63576\$1424Ceiling - Epoted011 Food Service922576\$1,371Doors - Wood Doors inclu hw011 Food Service2EA7\$00Doors - Wood Doors inclu hw011 Food Service2EA7\$00Doors - Wood Doors inclu hw011 Food Service2EA7\$00Uighting - Pender/Surface011 Food Service18EA7\$00Walls - Viny Coated Oppour Panel011 Food Service18EA7\$00Uighting - Pender/Surface011 Food Service18EA7\$00Walls - Viny Coated Oppour Panel011 Food Service18EA7\$00Uighting - Pender/SurfaceBasement1,892SF6\$3,315Uighting - Pender/SurfaceBasement1,892SF6\$3,315Uighting - Pender/SurfaceBasement1,892SF6\$3,315Uighting - Pender/SurfaceBasement1,892SF6\$3,315Uighting - Pender/Surface<			201B Office	65	SF	6	\$471				
Ceiling - Plaster/Dynall301A Office1115F6\$467Doors - Wood Doors inclu hw301A Office116K7\$0Floor - Wood301A Office3KE7\$0Lighting - Pendent/Surface301A Office3KE7\$00Storage/ Clocet301A Office3KE7\$00Wals - Plaster/Drynall301A Office3KE7\$00Ceiling - Exposed011 Food Service22SF6\$11.24Poor - Wood Doors inclu hw011 Food Service22SF6\$22.07Floor - Tile011 Food Service22SF6\$22.01Poor - Tile011 Food Service22SF6\$22.01Hoor - Tile011 Food Service18.02SF6\$22.01Uighting - Pendent/Surface011 Food Service18.02SF6\$22.01Wals - Viny Coated Gysum Panel011 Food Service18.02SF6\$22.01Uighting - Pendent/Surface011 Food Service28.02S6\$23.01Wals - NaconyBasement19.92SF6\$33.04Wals - MaconyBasement19.92SF6\$33.04Wals - MaconyBasement28.02S6\$33.04Wals - MaconyBasement28.02S6\$33.04Joors - Wood Doors inclu hw301B1EA7\$30.02Joors - Wood D		Walls - Plaster/Drywall	201B Office	750	SF	7	\$0				
DearsWood Doors inclu hw301A Office1EAF55000000000000000000000000000000000000		AC Unit	301A Office	1	EA	4	\$6,086	AC unit does not work			
Floor - Wood301A Office135SF6\$952Lighting - Pendent/Surface301A Office3EA750Storage/Closet301A Office516SF6\$14,24Walls - Plaster/Drywall301A Office516SF6\$1,371Celling - Exposed011 Food Service22SF6\$1,371Doors - Wood Doors inclu hw011 Food Service22SF6\$2,017Floor - Tile011 Food Service922SF6\$2,2017Ughting - Pendent/Surface011 Food Service922SF6\$2,2083Ughting - Pendent/Surface011 Food Service922SF6\$2,2083Ughting - Pendent/Surface011 Food Service928SF6\$2,983Ughting - Pendent/Surface011 Food Service928SF6\$2,983Ughting - Pendent/SurfaceBasement1,982SF6\$2,983Ughting - Pendent/SurfaceBasement1,982SF6\$3,134Hoor - Tile/SheetBasement2,982SF6\$3,134Hoor - Tile/SheetBasement2,983SF6\$3,134Hoor - Tile/Sheet90181EA7\$00Hoor - Tile/Sheet90181EA6\$3,134Hoor - Slow - Wood Doors inclu hw30181EA7\$01Hoor - Tile/Sheet30181EA7\$02Hoors		Ceiling - Plaster/Drywall	301A Office	135	SF	6	\$467				
Lighting - Pendent/Surface301A Office3EA7\$0Storage' Closet301A Office635F6\$457301EWalls - Plaster/Dynwall301A Office565F6\$472301EKitcherCeiling - Exposed011 Food Service922SF6\$2,171Doors - Wood Doors inclu hw011 Food Service922SF6\$2,017Floor - Tile011 Food Service2EA7\$0Doors - Wood Doors inclu hw011 Food Service18EA7\$0Horner VSurface011 Food Service18EA7\$0Uphting - Pendent/Surface011 Food Service18EA7\$0Walls - Vinyl Coated Gypsum PanelBasement1,892SF6\$6,547Floor - Tile/SheetBasement1,892SF6\$6,547Floor - Tile/SheetBasement1,892SF6\$3,469Walls - Vinyl Coated Gypsum PanelBasement1,892SF6\$3,346Walls - Vinyl Coated Gypsum PanelBasement2,288SF6\$3,345Walls - Vinyl Coated Gypsum Panel301B1EA7\$0Doors - Vood Doors inclu hw301B1EA6\$3,01Morts- Closet301B1EA6\$3,021Finishes301B1EA6\$3,021Doors - Vood Doors inclu hw301B1 <td></td> <td>Doors - Wood Doors inclu hw</td> <td>301A Office</td> <td>1</td> <td>EA</td> <td>7</td> <td>\$0</td> <td></td>		Doors - Wood Doors inclu hw	301A Office	1	EA	7	\$0				
StorageClosetStorageClosetStorageClosetStorageS		Floor - Wood	301A Office	135	SF	6	\$952				
Walls - Plaster/Dryvall301 A Office5156\$1,42KitchemCelling - Exposed011 Food Service9256\$1,371Dors - Wood Doors inclu hw0111 Food Service9256\$2,017Floor - Tile011 Food Service9256\$2,017Walls - Vinyl Coated Gypsum Panel011 Food Service9256\$2,017Malls - Vinyl Coated Gypsum Panel011 Food Service1056\$2,983Celling - Plaster/DryvallBasement1,89257\$0Floor - Tile SheetBasement1,89257\$0Lighting - Pendent/SurfaceBasement1,89257\$0Walls - MasonyBasement1,89256\$6,317Walls - MasonyBasement1,89256\$6,317Walls - MasonyBasement1,89256\$6,317Walls - MosonyBasement1,89256\$6,317Walls - MosonyBasement1,89256\$6,317Walls - MosonyBasement2,28356\$6,317Walls - MosonyBasement1,28256\$6,317Walls - MosonyBasement2,28356\$6,317Walls - MosonyBasement2,28356\$6,317Walls - Mosony011 B1EA6\$301Doors - Wood Doors inclu h		Lighting - Pendent/Surface	301A Office	3	EA	7	\$0				
Kitchen Kitchen 922 SF 6 \$1,371 Doors - Wood Doors inclu hw 011 Food Service 2 EA 7 \$00 Floor - Tile 011 Food Service 2 EA 7 \$0 Lighting - Pendent/Surface 011 Food Service 922 SF 6 \$2,017 Walls - Vinyl Coated Gypsum Panel 011 Food Service 18 A 7 \$0 Eding - Plaster/Dryvall Basement 1,082 SF 6 \$52,983 Floor - Tile/Shed Basement 1,982 SF 6 \$54,943 Lighting - Pendent/Surface Basement 1,982 SF 6 \$54,943 Walls - Wasony Basement 1,982 SF 6 \$53,469 Walls - Wasony Basement 2,288 SF 6 \$53,459 Walls - Wasony Basement 2,288 SF 6 \$53,451 Walls - Wasony Basement 2,288 SF 6 \$53,451 <		Storage/ Closet	301A Office	63	SF	6	\$457	301E			
Ceiling - Exposed 011 Food Service 922 SF 6 \$1,371 Doors - Wood Doors inclu hw 011 Food Service 2 EA 7 \$0 Floor - Tile 011 Food Service 922 SF 6 \$2,017 Lighting - Pendent/Surface 011 Food Service 18 EA 7 \$0 Walls - Viryl Coated Gypsum Panel 011 Food Service 1,081 SF 6 \$2,983 Lunch & Multipurpose Room E Ceiling - Plaster/Drywall Basement 1,892 SF 6 \$6,547 Floor - Tile/Sheet Basement 1,892 SF 6 \$53,469 Walls - Masonry Basement 1,892 SF 6 \$53,469 Walls - Masonry Basement 2,88 SF 6 \$53,469 Walls - Masonry Basement 2,288 SF 6 \$53,469 Walls - Masonry Basement 2,288 SF 6 \$53,469 Joors - Wood Doors inclu hw 301B 1		Walls - Plaster/Drywall	301A Office	516	SF	6	\$1,424				
DoorsWood Doors inclu hw011 Food Service2EA7\$0Floor - Tile011 Food Service922SF6\$2,017Lighting - Pendent/Surface011 Food Service18EA7\$0Walls - Vinyl Coated Gypsum Panel011 Food Service1,081SF6\$2,93Lucht A Witipurpose RoomCeiling - Plaster/DrywallBasement1,892SF6\$6,547Floor - Tile/SheetBasement1,892SF6\$3,469Walls - MasonryBasement440SF6\$1,318Walls - MasonryBasement2,288SF6\$1,318Malls - MasonryBasement2,288SF6\$1,318Doors - Wood Doors inclu hw301B1EA7\$00Doors - Wood Doors inclu hw301B1EA6\$1,355Mochanical/Service Rooms301B1EA6\$1,355Mechanical/Service Rooms301B1EA6\$1,355Mechanical/Service Rooms151 Floor12SF5\$1,419Janitor's Closet151 Floor24SF5\$1,419Matoris Closet151 Floor24SF5\$1,419Janitor's Closet151 Floor24SF5\$1,419Janitor's Closet151 Floor24SF5\$1,419Janitor's Closet151 Floor24SF5\$1,419	Kitcher	n									
Floor - Tile 011 Food Service 92 SF 6 \$2,017 Lighting - Pendent/Surface 011 Food Service 18 EA 7 \$0 Walls - Vinyl Coated Gypsum Panel 011 Food Service 1.081 SF 6 \$2,983 Lighting - Pendent/Surface Ceiling - Plaster/Drywall Basement 1,892 SF 6 \$6,547 Floor - Tile/She4t Basement 1,892 SF 6 \$3,469 Lighting - Pendent/Surface Basement 1,492 SF 6 \$3,469 Walls - Masonry Basement 2,498 SF 6 \$3,469 Walls - Vinyl Coated Gypsum Panel Basement 2,498 SF 6 \$3,469 Walls - Vinyl Coated Gypsum Panel Basement 2,498 SF 6 \$3,469 Wors - Wood Doors inclu hw 301B 1 EA 7 \$0 Dors - Wood Doors inclu hw 301B 1 EA 7 \$0 Ventilation and Cooling 301B<		Ceiling - Exposed	011 Food Service	922	SF	6	\$1,371				
Lighting - Pendent/Surface 011 Food Service 18 EA 7 \$0 Walls - Vinyl Coated Gypsum Panel 011 Food Service 1,081 SF 6 \$2,983 Lunch & Multipurpose Room E E 6 \$6,547 Ceiling - Plaster/Drywall Basement 1,892 SF 6 \$6,547 Lighting - Pendent/Surface Basement 1,892 SF 6 \$5,647 Lighting - Pendent/Surface Basement 1,892 SF 6 \$5,647 Walls - Masonry Basement 2,88 K 6 \$5,149 Walls - Vinyl Coated Gypsum Panel Basement 2,288 SF 6 \$6,315 MDF_IDF Malls - Vinyl Coated Gypsum Panel Basement 2,288 SF 6 \$6,315 More parametric Malls - Vinyl Coated Gypsum Panel Basement 2,288 SF 6 \$6,315 Doors - Viood Doors inclu hw 301B 1 EA 7 \$00 Janitor's Closet 301B 1<		Doors - Wood Doors inclu hw	011 Food Service	2	EA	7	\$0				
Walls - Vinyl Coated Gypsum Panel011 Food Service1,081SF6\$2,983Luch & Multipurpose RoomCeiling - Plaster/DrywallBasement1,892SF6\$6,547Floor - Tile/SheetBasement1,892SF7\$00Lighting - Pendent/SurfaceBasement2.88EA6\$3,469Walls - MasonryBasement24.80SF6\$1,384Walls - Vinyl Coated Gypsum PanelBasement24.80SF6\$1,384Walls - Vinyl Coated Gypsum PanelBasement24.80SF6\$6,315More Hermitica Gypsum PanelBasement4.00SF6\$1,384More Joors - Wood Doors inclu hw301B1EA7\$00Finishes301B1EA6\$3,015Youtilation and Cooling301B1EA6\$1,855Mechanical/ Service RoomsJanitor's Closet1st Floor12SF5\$1,419Mechanical/ Service Rooms1st Floor12SF5\$1,419Janitor's Closet1st Floor28SF5\$1,419Janitor's Closet1st Floor28SF5\$1,419Janitor's Closet1st Floor12SF5\$1,419		Floor - Tile	011 Food Service	922	SF	6	\$2,017				
Lunch & Lutch burburbose RoomCeiling - Plaster/DrywallBasement1,892SF6\$6,547Floor - Tile/SheetBasement1,892SF7\$0Lighting - Pendent/SurfaceBasement28EA6\$3,469Walls - MasonryBasement440SF6\$6,313Walls - Vinyl Coated Gypsum PanelBasement2,288SF6\$6,314Doors - Wood Doors inclu hw301B1EA7\$0Finishes301B15SF6\$963Ventilation and Cooling301B15SF6\$963Moter-americation of the Second Secon		Lighting - Pendent/Surface	011 Food Service	18	EA	7	\$0				
Ceiling - Plaster/DrywallBasement1,892SF6\$6,547Floor - Tile/SheetBasement1,892SF7\$0Lighting - Pendent/SurfaceBasement28EA6\$3,469Walls - MasonryBasement440SF6\$1,334Walls - Vinyl Coated Gypsum PanelBasement2,288SF6\$6,315reinforced plastic MDF_IDF AC Unit301B1EA7\$0Doors - Wood Doors inclu hw301B1EA6\$301Finishes301B1EA6\$301Ventilation and Cooling301B1EA6\$963Mechanical/ Service RoomsJanitor's Closet1st Floor8SF5\$194Jontor's Closet1st Floor8SF5\$194Janitor's Closet2nd Floor12SF5\$194		Walls - Vinyl Coated Gypsum Panel	011 Food Service	1,081	SF	6	\$2,983				
Floor - Tile/SheetBasement1,892SF7\$0Lighting - Pendent/SurfaceBasement28EA6\$3,469Walls - MasonryBasement440SF6\$1,384Walls - Vinyl Coated Gypsum PanelBasement2,288SF6\$6,315reinforced plastic MDF_IDF AC Unit301B1EA7\$0Doors - Wood Doors inclu hw301B1EA6\$301Finishes301B15SF6\$963Ventilation and Cooling301B15SF6\$963Mechanical/ Service Rooms1st Floor2F5\$194JC Rm 100AMechanical/ Service Rooms1st Floor8F5\$1,419Storage Room1st Floor8F5\$1,419Janitor's Closet1st Floor2SF6\$673Storage Room1st Floor15SF6\$673Janitor's Closet2nd Floor12SF5\$194	Lunch	& Multipurpose Room									
Lighting - Pendent/SurfaceBasementBasement28EA6\$3,469Walls - MasonryBasement400SF6\$1,384Walls - Vinyl Coated Gypsum PanelBasement2,288SF6\$6,315reinforced plastic MDF_IDF MDF_IDF301B1EA7\$0Doors - Wood Doors inclu hw301B1EA6\$301Finishes301B135SF6\$963Ventilation and Cooling301B1EA6\$1,855 Mechanical/ Service Rooms 1st Floor2SF5\$194JC Rm 100AMechanical/ Service Rooms1st Floor88SF5\$1,419Storage Room1st Floor94SF6\$673storage/closet Rm 101EJanitor's Closet1st Floor94SF5\$194JC Rm 100A		Ceiling - Plaster/Drywall	Basement	1,892	SF	6	\$6,547				
Walls - Masonry Walls - Vinyl Coated Gypsum PanelBasement440SF6\$1,384Basement2,288SF6\$6,315reinforced plasticMDF_IDFAC Unit301B1EA7\$0Doors - Wood Doors inclu hw301B1EA6\$301Finishes301B15SF6\$963Ventilation and Cooling301B15SF6\$963Mechanical/ Service Rooms301B12SF5\$194JC Rm 100AMechanical/ Service Rooms1st Floor88SF5\$1,419Storage Room1st Floor88SF5\$1,419Janitor's Closet1st Floor94SF6\$673Storage Room1st Floor94SF6\$673Janitor's Closet1st Floor12SF5\$194		Floor - Tile/Sheet	Basement	1,892	SF	7	\$0				
Walls - Vinyl Coated Gypsum PanelBasement2,288SF6\$6,315reinforced plasticMDF_IDFAC Unit301B1EA7\$0Doors - Wood Doors inclu hw301B1EA6\$301Finishes301B135SF6\$963Ventilation and Cooling301B135SF6\$963Mechanical/ Service Rooms1st Floor12SF5\$194JC Rm 100AMechanical/ Service Rooms1st Floor88SF5\$1,419Storage Room1st Floor94SF6\$673storage/coset Rm 101EJanitor's Closet1st Floor12SF5\$194CRm 100A		Lighting - Pendent/Surface	Basement	28	EA	6	\$3,469				
MDF_IDFAC Unit301B1EA7\$0Doors - Wood Doors inclu hw301B1EA6\$301Finishes301B135SF6\$963Ventilation and Cooling301B1EA6\$11,855Mechanical/ Service RoomsJanitor's Closet1st Floor12SF5\$194Mechanical/ Service Rooms1st Floor88SF5\$1,419Storage Room1st Floor94SF6\$673storage/closet Rm 101EJanitor's Closet1st Floor12SF5\$194		Walls - Masonry	Basement	440	SF	6	\$1,384				
AC Unit301B1EA7\$0Doors - Wood Doors inclu hw301B1EA6\$301Finishes301B135SF6\$963Ventilation and Cooling301B1EA6\$1,855Mechanical/ Service Rooms1st Floor12SF5\$194JC Rm 100AMechanical/ Service Rooms1st Floor88SF5\$1,419Storage Room1st Floor94SF6\$673storage/closet Rm 101EJanitor's Closet1st Floor12SF5\$194		Walls - Vinyl Coated Gypsum Panel	Basement	2,288	SF	6	\$6,315	reinforced plastic			
Doors - Wood Doors inclu hw301B1EA6\$301Finishes301B135SF6\$963Ventilation and Cooling301B1EA6\$1,855Mechanical/ Service RoomsJanitor's Closet1st Floor12SF5\$194JC Rm 100AMechanical/ Service Rooms1st Floor88SF5\$1,419Storage Room1st Floor94SF6\$673storage/closet Rm 101EJanitor's Closet2nd Floor12SF5\$194	MDF_I	DF									
Finishes301B135SF6\$963Ventilation and Cooling301B1EA6\$1,855Mechanical/ Service RoomsIst Floor12SF5\$194JC Rm 100AMechanical/ Service Rooms1st Floor88SF5\$1,419Storage Room1st Floor94SF6\$673storage/closet Rm 101EJanitor's Closet2nd Floor12SF5\$194		AC Unit	301B	1	EA	7	\$0				
Ventilation and Cooling301B1EA6\$1,855Mechanical/ Service Rooms1EA6\$1,855Janitor's Closet1st Floor12SF5\$194JC Rm 100AMechanical/ Service Rooms1st Floor88SF5\$1,419Storage Room1st Floor94SF6\$673storage/closet Rm 101EJanitor's Closet2nd Floor12SF5\$194		Doors - Wood Doors inclu hw	301B	1	EA	6	\$301				
Mechanical/ Service RoomsJanitor's Closet1st Floor12SF5\$194JC Rm 100AMechanical/ Service Rooms1st Floor88SF5\$1,419Storage Room1st Floor94SF6\$673storage/closet Rm 101EJanitor's Closet2nd Floor12SF5\$194		Finishes	301B	135	SF	6	\$963				
Janitor's Closet1st Floor12SF5\$194JC Rm 100AMechanical/ Service Rooms1st Floor88SF5\$1,419Storage Room1st Floor94SF6\$673storage/closet Rm 101EJanitor's Closet2nd Floor12SF5\$194		Ventilation and Cooling	301B	1	EA	6	\$1,855				
Mechanical/ Service Rooms1st Floor88SF5\$1,419Storage Room1st Floor94SF6\$673storage/closet Rm 101EJanitor's Closet2nd Floor12SF5\$194	Mecha	nical/ Service Rooms									
Storage Room 1st Floor 94 SF 6 \$673 storage/closet Rm 101E Janitor's Closet 2nd Floor 12 SF 5 \$194		Janitor's Closet		12		5	\$194	JC Rm 100A			
Janitor's Closet2nd Floor12SF5\$194		Mechanical/ Service Rooms	1st Floor	88	SF	5	\$1,419				
		Storage Room	1st Floor	94	SF	6	\$673	storage/closet Rm 101E			
Storage Room2nd Floor74SF6\$530Storage Rm 201E		Janitor's Closet	2nd Floor	12	SF	5	\$194				
		Storage Room	2nd Floor	74	SF	6	\$530	Storage Rm 201E			



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Mechan	lechanical/ Service Rooms									
	Janitor's Closet	3rd Floor	12	SF	5	\$194	JC Rm 300A			
	Storage Room	3rd Floor	74	SF	6	\$530	Stirage Rm 301E			
	Janitor's Closet	Basement	202	SF	5	\$3,258				
	Mechanical/ Service Rooms	Basement	1,379	SF	5	\$22,244				
	Mechanical/ Service Rooms	Basement	163	SF	6	\$1,168	Supply Room 015			
	Mechanical/ Service Rooms	Basement	2,011	SF	6	\$14,407	Supply Room 020			
	Mechanical/ Service Rooms	Basement	305	SF	5	\$4,920	Electrical Room			
	Mechanical/ Service Rooms	Basement	88	SF	5	\$1,419	012 Fire Pump Room			
	Mechanical/ Service Rooms	Basement	199	SF	6	\$1,426	Supply Room 007			
	Mechanical/ Service Rooms	Basement	584	SF	5	\$9,420	Fan Room			
	Mechanical/ Service Rooms	Basement	272	SF	6	\$1,949	Fresh Air Chamber Rm 005			
	Mechanical/ Service Rooms	Basement	213	SF	6	\$1,526	Supply Room 006			
	Mechanical/ Service Rooms	Basement	50	SF	6	\$358	Elevator Room 004			
	Mechanical/ Service Rooms	Basement	530	SF	5	\$8,549				
	Storage Room	Basement	281	SF	6	\$2,013				
Restroo	m									
	Ceiling - Lay-in	006C in Engine Room	26	SF	6	\$78				
	Doors - Wood Doors inclu hw	006C in Engine Room	1	EA	6	\$301				
	Floor - Tile	006C in Engine Room	26	SF	4	\$223	Sunken floor			
	Lavatory	006C in Engine Room	1	EA	5	\$1,590				
	Lighting - Lay-in	006C in Engine Room	1	EA	6	\$119				
	Walls - Plaster/Drywall	006C in Engine Room	129	SF	5	\$978				
	Water Closet	006C in Engine Room	1	EA	5	\$1,344				
	Ceiling - Plaster/Drywall	101A-1 Unisex	61	SF	6	\$211				
	Doors - Wood Doors inclu hw	101A-1 Unisex	1	EA	6	\$301				
	Floor Drain	101A-1 Unisex	1	EA	6	\$1,059				
	Floor - Tile Ceramic/ Porcelain	101A-1 Unisex	61	SF	6	\$129				
	Lavatory	101A-1 Unisex	1	EA	6	\$320				
	Lighting - Pendent/Surface	101A-1 Unisex	1	EA	6	\$124				
	Partitions	101A-1 Unisex	1	EA	6	\$297				
	Walls - Plaster/Drywall	101A-1 Unisex	291	SF	6	\$803				
	Water Closet	101A-1 Unisex	1	EA	6	\$336				
	Accessories	107A Unisex	1	SF	6	\$9				
	Ceiling - Plaster/Drywall	107A Unisex	45	SF	6	\$156				
	Doors - Wood Doors inclu hw	107A Unisex	1	EA	6	\$301				
	Floor - Tile Ceramic/ Porcelain	107A Unisex	45	SF	6	\$95				
	Lavatory	107A Unisex	1	EA	6	\$320				



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Lighting - Pendent/Surface	107A Unisex	1	EA	6	\$124	
	Partitions	107A Unisex	1	EA	6	\$297	
	Walls - Plaster/Drywall	107A Unisex	343	SF	6	\$947	
	Water Closet	107A Unisex	1	EA	6	\$336	
	Ceiling - Plaster/Drywall	2nd Floor East Unisex	60	SF	6	\$208	
	Doors - Wood Doors inclu hw	2nd Floor East Unisex	1	EA	6	\$301	
	Floor Drain	2nd Floor East Unisex	1	EA	6	\$1,059	
	Floor - Tile/Sheet	2nd Floor East Unisex	60	SF	5	\$269	
	Hand Dryer	2nd Floor East Unisex	1	EA	7	\$0	
	Lavatory	2nd Floor East Unisex	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd Floor East Unisex	1	EA	6	\$124	
	Walls - Concrete Block	2nd Floor East Unisex	134	SF	6	\$393	
	Walls - Plaster/Drywall	2nd Floor East Unisex	134	SF	6	\$370	
	Water Closet	2nd Floor East Unisex	1	EA	6	\$336	
	Ceiling - Plaster/Drywall	2nd Floor West Unisex Accessible	142	SF	6	\$491	
	Doors - Wood Doors inclu hw	2nd Floor West Unisex Accessible	2	EA	6	\$602	
	Floor Drain	2nd Floor West Unisex Accessible	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	2nd Floor West Unisex Accessible	48	SF	6	\$102	
	Floor - Tile/Sheet	2nd Floor West Unisex Accessible	77	SF	6	\$77	
	Hand Dryer	2nd Floor West Unisex Accessible	1	EA	7	\$0	
	Lavatory	2nd Floor West Unisex Accessible	1	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor West Unisex Accessible	2	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor West Unisex Accessible	142	SF	7	\$0	
	Walls - Tile Ceramic/ Porcelain	2nd Floor West Unisex Accessible	426	SF	7	\$0	
	Water Closet	2nd Floor West Unisex Accessible	1	EA	7	\$0	
	Accessories	2nd Floor	1	SF	7	\$0	
	Ceiling - Plaster/Drywall	2nd Floor	188	SF	6	\$651	
	Ceiling - Plaster/Drywall	2nd Floor	184	SF	6	\$637	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor - Concrete	2nd Floor	184	SF	6	\$97	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	188	SF	6	\$398	
	Hand Dryer	2nd Floor	1	EA	7	\$0	
	Hand Dryer	2nd Floor	2	EA	7	\$0	
	Lavatory	2nd Floor	2	EA	7	\$0	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Lavatory	2nd Floor	8	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	\$0	
	Partitions	2nd Floor	2	EA	7	\$0	
	Partitions	2nd Floor	3	EA	7	\$0	
	Urinals	2nd Floor	3	EA	6	\$1,008	
	Walls - Plaster/Drywall	2nd Floor	651	SF	6	\$1,797	
	Walls - Plaster/Drywall	2nd Floor	664	SF	6	\$1,833	
	Water Closet	2nd Floor	3	EA	7	\$0	
	Water Closet	2nd Floor	4	EA	6	\$1,344	
	Ceiling - Plaster/Drywall	Basement Unisex Accessible	60	SF	6	\$208	
	Doors - Wood Doors inclu hw	Basement Unisex Accessible	1	EA	6	\$301	
	Floor Drain	Basement Unisex Accessible	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Basement Unisex Accessible	60	SF	6	\$127	
	Hand Dryer	Basement Unisex Accessible	1	EA	7	\$0	
	Lavatory	Basement Unisex Accessible	1	EA	6	\$320	
	Lighting - Pendent/Surface	Basement Unisex Accessible	1	EA	6	\$124	
	Walls - Concrete Block	Basement Unisex Accessible	129	SF	6	\$378	
	Walls - Plaster/Drywall	Basement Unisex Accessible	129	SF	6	\$356	
	Water Closet	Basement Unisex Accessible	1	EA	6	\$336	
	Ceiling - Plaster/Drywall	Basement	300	SF	6	\$1,038	
	Ceiling - Plaster/Drywall	Basement	473	SF	6	\$1,637	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	\$0	
	Floor Drain	Basement	1	EA	6	\$1,059	
	Floor Drain	Basement	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Basement	300	SF	7	\$0	
	Floor - Tile Ceramic/ Porcelain	Basement	473	SF	6	\$1,001	
	Hand Dryer	Basement	2	EA	7	\$0	
	Hand Dryer	Basement	2	EA	7	\$0	
	Lavatory	Basement	3	EA	7	\$0	
	Lavatory	Basement	2	EA	7	\$0	
	Lighting - Pendent/Surface	Basement	6	EA	7	\$0	
	Lighting - Pendent/Surface	Basement	7	EA	7	\$0	
	Partitions	Basement	2	EA	6	\$594	
	Partitions	Basement	6	EA	7	\$0	
	Urinals	Basement	3	EA	7	\$0	
	UIIIIdiS	Dasement	3	EA	1	Ф О	



Building: Main

Category: Rooms (Other Than Classrooms)

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom						
Walls - Concrete Block	Basement	424	SF	6	\$1,243	
Walls - Concrete Block	Basement	519	SF	6	\$1,521	
Walls - Plaster/Drywall	Basement	424	SF	6	\$1,170	reinforced plastic
Walls - Structural Glazed Tile	Basement	173	SF	6	\$544	
Water Closet	Basement	2	EA	6	\$672	
Water Closet	Basement	6	EA	6	\$2,016	
Rooms (Other Than Classrooms) Subtotal:					\$236,874	

Building: Main

Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
r						
Ceiling - Plaster/Drywall	1st Floor Corridor	2,187	SF	6	\$13,542	
Doors - Steel Doors incl hw	1st Floor Corridor	4	EA	6	\$1,204	
Doors - Wood Doors include hw	1st Floor Corridor	6	EA	6	\$1,806	
Drinking Fountains - Single Fountain	1st Floor Corridor	4	EA	7	\$0	
Floor - Tile/Sheet	1st Floor Corridor	2,187	SF	6	\$1,188	
Lighting - Pendent/Surface	1st Floor Corridor	14	EA	7	\$0	
Walls - Plaster/Drywall	1st Floor Corridor	2,510	SF	6	\$11,127	
Ceiling - Plaster/Drywall	2nd Floor Corridor	2,187	SF	6	\$13,542	
Drinking Fountains - Single Fountain	2nd Floor Corridor	4	EA	7	\$0	
Floor - Epoxy/ Painted	2nd Floor Corridor	2,187	SF	6	\$1,157	
Lighting - Pendent/Surface	2nd Floor Corridor	18	EA	7	\$0	
Walls - Plaster/Drywall	2nd Floor Corridor	2,410	SF	6	\$10,684	
Ceiling - Plaster/Drywall	3rd Floor Corridor	2,187	SF	6	\$13,542	
Drinking Fountains - Single Fountain	3rd Floor Corridor	4	EA	7	\$0	
Floor - Epoxy/ Painted	3rd Floor Corridor	2,187	SF	6	\$1,157	
Lighting - Pendent/Surface	3rd Floor Corridor	18	EA	7	\$0	
Walls - Plaster/Drywall	3rd Floor Corridor	2,302	SF	6	\$10,205	
Ceiling - Plaster/Drywall	Basement NW	218	SF	6	\$1,350	
Doors - Steel Doors incl hw	Basement NW	1	EA	6	\$301	
Floor - Tile Quarry	Basement NW	170	SF	6	\$474	
Lighting - Pendent/Surface	Basement NW	4	EA	6	\$496	
Stairs - Concrete Stairs	Basement NW	48	LF	6	\$398	
Walls - Concrete Block	Basement NW	284	SF	5	\$2,916	
Walls - Structural Glazed Tile	Basement NW	284	SF	5	\$14,429	



_	Item - Type	Location	Quantity	Unit	Pank	Cost	Comments
Corrido		Location	Quantity	Unit	Nalik	CUSI	Commenta
Corrido		Decoment	4 005	05	6	¢0.000	
			,				
	0 0						
	Walls - Masonry						
	Ceiling - Plaster/Drywall	Main entrance	467		6		
	Doors - Steel Doors incl hw	Main entrance	4		6	\$1,204	
	Doors - Wood Doors include hw	Main entrance	4		6	\$1,204	
	Floor - Tile/Sheet	Main entrance	46	SF	6	\$25	
	Lighting - Pendent/Surface	Main entrance	2	EA	6	\$248	
	Stairs - Concrete Stairs	Main entrance	171	LF	6	\$1,418	
	Walls - Masonry	Main entrance	630	SF	6	\$1,982	
	Walls - Plaster/Drywall	Main entrance	625	SF	6	\$2,771	
Safety							
	Camera Viewing Station		1	EA	6	\$683	Main Office
	Security Cameras		12	EA	6	\$2,328	
	Security Cameras		3	EA	4	\$3,977	Three cameras are not functional
Stairs	lis - Structural Glazed Tile Basement 420 SF 6 \$1,321 ling - Plaster/Dywall Main entrance 447 SF 6 \$2,892 vis - Wood Doors include hw Main entrance 4 EA 6 \$1,204 vis - Wood Doors include hw Main entrance 4 EA 6 \$1,204 vir - Tile/Sheet Main entrance 1 EA 6 \$2,248 ting - Pendent/Surface Main entrance 11 EA 6 \$2,484 is - Masony Main entrance 630 SF 6 \$2,448 is - Masony Main entrance 630 SF 6 \$2,428 is - Masony Main entrance 12 EA 6 \$2,328 uitly Cameras 12 EA 6 \$2,327 Three cameras are not functional uitly Cameras 1 EA 6 \$2,327 Three cameras are not functional uitly Cameras 12 EA 6 \$2,327 Three cameras are not functional uitly Cameras 12 EA 6						
	Ceiling - Plaster/Drywall	East	383	SF	6	\$2,804	
	Floor - Epoxy/ Painted	East	631	SF	6	\$334	
	Floor - Tile/Sheet	East	191	SF	6	\$104	
	Handrails	East	190	LF	6	\$1,647	
	Lighting - Pendent/Surface	East	12	EA	7	\$0	
	Stairs - Concrete	East	498	LF	6	\$4,130	
	Walls - Masonry	East	150	SF	6	\$472	
	Walls - Plaster/Drywall	East	2,347	SF	6	\$6,477	
	Ceiling - Plaster/Drywall	West	383	SF	6	\$2,804	
	Floor - Epoxy/ Painted	West	631	SF	6	\$334	
	Floor - Tile/Sheet	West	191	SF	6		
	Handrails	West	190	LF	6		
	Lighting - Pendent/Surface		12	EA	7		
	Stairs - Concrete						
	Walls - Masonry						



\$2,945,968

950 W 33rd PI Chicago, IL 60608

Building: Main

Category: Building Interior							
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments	
Stairs							
Walls - Plaster/Drywall	West	2,497	SF	6	\$6,891		
Vertical Conveyance							
Elevator - Hydraulic Elevator		1	EA	6	\$19,238		
Building Interior Subtotal:					\$218,143		

Total Building Cost

Building: Branch

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entranc	e						
	Entrance Control - Audio and Video	1	1	EA	7	\$0	
	Exterior Doors - Exterior FRP Door	1	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	4	2	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	1st Floor Fire Escape	1	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	2	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	3	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	5	1	EA	5	\$1,341	
	Exterior Doors - Exterior Steel Door	6	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	7	1	EA	4	\$3,823	deteriorated/corroded door, frame, and hardware
	Exterior Doors - Side lite	1	2	EA	7	\$0	
	Exterior Doors - Side lite	4	2	EA	7	\$0	
	Exterior Doors - Transom Lite	1	2	EA	7	\$0	
	Exterior Doors - Transom Lite	1st Floor Fire Escape	1	EA	7	\$0	
	Exterior Doors - Transom Lite	2	1	EA	7	\$0	
	Exterior Doors - Transom Lite	3	1	EA	6	\$313	
	Exterior Doors - Transom Lite	4	2	EA	7	\$0	
	Exterior Doors - Transom Lite	7	1	EA	4	\$2,007	deteriorated/corroded
	Exterior Stairs - Concrete	2	56	LF	7	\$0	
	Exterior Stairs - Concrete	3	56	LF	7	\$0	
	Exterior Stairs - Concrete	5	40	LF	6	\$3,271	
	Exterior Stairs - Stone	6	6	LF	6	\$678	cracked, displaced
	Exterior Stairs - Wood	6	42	LF	7	\$0	
	Power Door Operator and Controls	1	1	EA	7	\$0	
	Stair Handrail - Steel_Stair Handrail	2	20	LF	7	\$0	



Building: Branch

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand	ce						
	Stair Handrail - Steel_Stair Handrail	3	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	5	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	6	8	LF	6	\$69	
Fire Es	cape						
	Fire Escape	South Façade	28	LF	5	\$29,401	missing guardrail/handrail at landing
ounda	tion						
	Foundation - Concrete	Entire Building	532	LF	7	\$0	
	Superstructure - Concrete	Entire Building	31,274	SF	7	\$0	
_ightin	a						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	9	EA	6	\$4,829	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	6	\$866	
Roof S		Ű					
001 3	Chimney - Metal Flue	A / South East	48	LF	6	\$7,591	
	Coping - Metal	А	184	LF	6	\$5,910	
	Coping - Metal	A / North East	40	LF	4	\$3,542	seal joints
	Coping - Metal	В	114	LF	6	\$3,661	
	Coping - Stone	А	58	LF	6	\$1,863	
	Downspouts - Exterior Downspouts	A / South Façade	184	LF	6	\$6,115	
	Downspouts - Exterior Downspouts	B / East Façade	12	LF	4	\$1,626	missing
	Parapet - 16" - 30" Height	A	118	LF	6	\$4,715	
	Parapet - 16" - 30" Height	В	25	LF	6	\$999	
	Parapet - Parapet < 16" Height	А	60	LF	6	\$1,278	
	Parapet - Parapet < 16" Height	В	64	LF	6	\$1,364	roof membrane up to coping
	Parapet - Parapet > 30"	А	104	LF	6	\$6,648	
	Parapet - Parapet > 30"	В	25	LF	6	\$1,598	
	Roof Structure - Concrete	А	9,936	SF	7	\$0	
	Roof Structure - Concrete	В	1,466	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	А	9,936	SF	6	\$101,022	loose/open flashing at north parapet
	Roof - Modified Bitumen	В	1,466	SF	6	\$13,794	
Nalls							
	Cornice - Cast Stone	Entire Building	210	LF	5	\$31,285	clean and seal joint
	Cornice - Metal Projecting	Entire Building	580	LF	4	\$501,704	corroded, deteriorated, leaking
	Exterior Walls - Brick	Entire Building	14,334	SF	6		210 sf of graffitti at south facade of 1-story



Building: Branch

Category: Building Exterior

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Windows						
Guard - Guards perforated	Entire Building	1,452	SF	7	\$0	
Lintels - Steel	Entire Building	12	LF	4	\$5,433	rusted and deflecting
Lintels - Steel	Entire Building	546	LF	6	\$15,850	scrape and paint
Windows - Sash Aluminum Double-pane	Entire Building	4,434	SF	6	\$33,098	
Windows - Sash Aluminum Double-pane	Entire Building / West Façade	20	SF	4	\$0	window is missing and boarded up
Building Exterior Subtotal:					\$894,910	

Building Exterior Subtotal:

Building: Branch

Category: Electrical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
mergency System						
Automatic Transfer Switch	Electrical Room	1	EA	7	\$0	
Emergency A/C Power - Corridors and Stairs	Entire Building	3,560	SF	7	\$0	
Emergency A/C Power - Gym	Basement	5,092	SF	7	\$0	
Emergency Battery Packs - Corridors and Stairs	Entire Building	15	EA	7	\$0	
Emergency Battery Packs - Multipurpose Room	Basement	2	EA	7	\$0	
Emergency Battery Packs - Students Toilets	Entire Building	6	EA	7	\$0	
Exit Signs - Corridors and Stairs	Entire Building	17	EA	7	\$0	
Exit Signs - Gym	3rd Floor	1	EA	7	\$0	
Exit Signs - Multipurpose Room	Basement	5	EA	7	\$0	
Security System - CCTV	1st Floor	31,274	SF	6	\$9,392	
Security System - Intrusion Detection	1st Floor	31,274	SF	6	\$8,050	
Iain Service						
Independent Electrical Service for emergency power	Electrical Room	1	EA	7	\$0	
Main Electrical Service - 1200 A 120/240/3PH	Electrical Room	1	EA	7	\$0	
PA System	1st Floor	31,274	SF	6	\$10,286	
Power Distribution						
Lighting and Power Panels - 100 A	Entire Building	3	EA	6	\$897	
Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	\$1,988	
Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	\$0	
Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	\$0	
Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	4	\$8,819	
Transformers - 120/240 - 120/208	Entire Building	1	EA	7	\$0	



Building: Branch

Category: Electrical System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Electrical System Subtotal:					\$39,432	
Defit from Description						
Building: Branch						
Category: Safty System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm						
Fire Alarm Panel	Basement	1	EA	7	\$0	
Fire Alarm Strobe Lights	Basement / Entire Building	31,274	SF	7	\$0	
Fire Alarm_System	Basement / Entire Building	31,274	SF	7	\$0	
Fire Pump Controller	Basement	1	EA	4	\$23,389	
Pump Room Assembly						
Fire Pump - Less than 25hp	Basement	1	EA	4	\$26,665	Serves Branch building only.
Sprinkler System						
Dry Sprinkler System	Basement / Entire Building	31,274	SF	4	\$42,486	
Sprinkler Heads	Basement / Entire Building	31,274	SF	4	\$16,100	
Sprinkler Piping	Basement / Entire Building	31,274	SF	4	\$45,169	
Safty System Subtotal:					\$153,809	
Building: Branch						
Category: Mechanical System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Conditioning						
Condensing Unit- Ground Mounted - Less than 5 tons	1st Floor	2	EA	7	\$0	
Air Handling Systems						
Fan Coil Unit- Celing Mounted - Electric	Basement	2	EA	6	\$1,641	
Boiler Systems						
Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	\$9,533	
Chemical Feeder	Boiler Room	1	EA	6	\$1,078	
Combustion Dampers	Boiler Room	1	EA	6	\$409	
Condensate Pump	Boiler Room	1	EA	6	\$2,021	
- · · ·				_		

Condensate Pump

Feed Water Pumps and Tank

Boiler Room / 1st Floor

Boiler Room

5

6

\$18,196

\$2,545

ΕA

1 EA

1



Building: Branch

Category: Mechanical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Boiler Systems						
Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	\$9,533	
Piping - Condensate Pipe- Steel	Boiler Room	500	LF	5	\$6,099	
Piping - Steam Pipe- Steel	Boiler Room	500	LF	5	\$7,043	
Steam Traps	Boiler Room / Entire Building	1	EA	6	\$264	
Heating Devices						
Cabinet Heaters - With Steam Coil	Entire Building	3	EA	7	\$0	
Radiators - Steam	Entire Building	57	EA	5	\$95,493	
Radiators - Steam	Entire Building	4	EA	7	\$0	
Unit Heater - Steam	Basement	5	EA	4	\$8,777	4 UH serve the multipurpose room in the basement and 1 serves the boys bathroom in the basement
Wall Heater - Electric	Entire Building	1	EA	6	\$139	
Wall Heater - Electric	Entire Building	1	EA	7	\$0	
Temperature Control						
Electric Thermostat	Basement	2	EA	7	\$0	
Ventilation						
Exhaust Fans- Indoor - 500 - 1500 CFM	Basement	3	EA	6	\$1,777	
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Basement	1	EA	6	\$592	
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Basement / Roof	3	EA	6	\$1,777	
Type II Exhaust Hood- Warming Kitchen	Basement	1	EA	7	\$0	
Machanical System Subtatal:					¢166 010	

Mechanical System Subtotal:

\$166,919

Building: Branch

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wat	er						
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	2	EA	7	\$0	
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	31,274	SF	7	\$0	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	31,274	SF	6	\$7,603	
	Domestic Piping-Cold Water Risers	Entire Building	31,274	SF	4	\$25,044	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	31,274	SF	7	\$0	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	31,274	SF	6	\$5,814	



Building: Branch

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	31,274	SF	4	\$26,833	
	Domestic Piping-Hot Water Return Risers	Entire Building	31,274	SF	4	\$15,205	
	Sanitary Piping	Entire Building	31,274	SF	5	\$0	
	Storm Piping	Entire Building	31,274	SF	5	\$0	
	Vent Piping	Entire Building	31,274	SF	5	\$0	
Pumps							
	Pumps - Ejector-Simplex	Boiler Room	1	EA	6	\$745	
	Pumps - Sump-Duplex	Boiler Room	1	EA	6	\$1,387	
	Pumps - Sump-Simplex		1	EA	6	\$745	

Plumbing System Subtotal:

\$83,376

Building: Branch

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #113 (Regular Classroom)						
	Ceiling - Plaster/Drywall		720	SF	4	\$10,842	cracks and water damage
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	5	\$2,348	
	Floor - Wood		720	SF	6	\$5,076	
	Lighting - Pendent/Surface		10	EA	6	\$1,239	
	Marker Board		46	LF	6	\$985	
	Walls - Plaster/Drywall		1,140	SF	5	\$8,640	
Classro	oom #114 (Regular Classroom)						
	Ceiling - Plaster/Drywall		806	SF	6	\$2,789	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		806	SF	5	\$3,619	
	Lighting - Pendent/Surface		5	EA	6	\$619	
	Marker Board		47	LF	6	\$1,007	
	Storage/ Closet		78	SF	6	\$566	
	Walls - Plaster/Drywall		1,137	SF	6	\$3,138	
Classro	oom #115 (Regular Classroom)						
	Ceiling - Plaster/Drywall		716	SF	6	\$2,478	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	

Building: Branch

-						-	-
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #115 (Regular Classroom)						
	Floor - Wood		716	SF	5	\$10,474	
	Lighting - Pendent/Surface		12	EA	6	\$1,487	
	Marker Board		34	LF	7	\$0	
	Storage/ Closet		103	SF	6	\$747	
	Walls - Plaster/Drywall		1,140	SF	6	\$3,146	
Classro	oom #116 (Lunch Room)						
	Casework		32	LF	6	\$808	
	Ceiling - Plaster/Drywall		648	SF	5	\$5,940	
	Chalk Board		16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		648	SF	6	\$649	
	Lighting - Pendent/Surface		10	EA	6	\$1,239	
	Walls - Plaster/Drywall		1,048	SF	6	\$2,892	
Classro	oom #210 (Regular Classroom)						
	Ceiling - Plaster/Drywall		837	SF	6	\$2,897	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		837	SF	5	\$12,244	
	Lighting - Pendent/Surface		10	EA	6	\$1,239	
	Marker Board		22	LF	7	\$0	
	Storage/ Closet		127	SF	6	\$921	
	Walls - Plaster/Drywall		1,146	SF	5	\$8,686	
Classro	oom #211 (Office)						
	Ceiling - Plaster/Drywall		558	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Tile/Sheet		558	SF	6	\$559	
	Lighting - Pendent/Surface		7	EA	7	\$0	
	Walls - Plaster/Drywall		966	SF	6	\$2,666	
Classro	oom #212 (Regular Classroom)						
	Ceiling - Plaster/Drywall		775	SF	4	\$11,670	Visible cracks on ceiling tiles
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	5	\$2,348	
	Floor - Wood		775	SF	5	\$11,337	
	Lighting - Pendent/Surface		10	EA	6	\$1,239	
	Marker Board		18	LF	7	\$0	
	Storage/ Closet		129	SF	6	\$935	



Building: Branch

-	ory: Classrooms	Lagetter	0	11	Decla	0	Commente
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroo	om #212 (Regular Classroom)			~-		* ****	
	Walls - Plaster/Drywall		1,164	SF	6	\$3,213	
Classroo	om #213 (Computer Lab)						
	AC Units		1	EA	6	\$496	
	Ceiling - Plaster/Drywall		750	SF	6	\$2,595	
	Chalk Board		8	LF	4	\$734	
	Doors - Transom Window		19	SF	6	\$322	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Wood		750	SF	5	\$10,972	
	Lighting - Pendent/Surface		10	EA	6	\$1,239	
	Marker Board		18	LF	6	\$386	
	Walls - Plaster/Drywall		340	SF	6	\$1,113	
	Walls - Plaster/Drywall		800	SF	4	\$8,054	cracks and peeling paint
	Wireless System		1	EA	7	\$0	
Classroo	om #214 (Library)						
	Casework		54	LF	7	\$0	
	Ceiling - Plaster/Drywall		837	SF	6	\$2,897	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Carpet		837	SF	7	\$0	
	Lighting - Pendent/Surface		10	EA	6	\$1,239	
	Marker Board		18	LF	7	\$0	
	Storage/ Closet		140	SF	6	\$1,015	
	Walls - Plaster/Drywall		1,173	SF	6	\$3,237	
lassroo	om #215 (Regular Classroom)						
	Ceiling - Plaster/Drywall		775	SF	4	\$11,670	water infiltration
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		775	SF	6	\$776	
	Lighting - Pendent/Surface		12	EA	6	\$1,487	
	Marker Board		22	LF	6	\$471	
	Storage/ Closet		107	SF	6	\$776	
	Walls - Plaster/Drywall		1,104	SF	5	\$8,367	Water damage along the wall
lassroo	om #216 (Regular Classroom)						
	Ceiling - Plaster/Drywall		725	SF	6	\$2,509	
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	

Building: Branch

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #216 (Regular Classroom)						
	Floor - Wood		725	SF	5	\$10,606	
	Lighting - Pendent/Surface		10	EA	6	\$1,239	
	Marker Board		18	LF	6	\$386	
	Walls - Plaster/Drywall		1,146	SF	6	\$3,163	
Classro	oom #217 (Regular Classroom)						
	Ceiling - Plaster/Drywall		775	SF	6	\$2,682	
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Wood		775	SF	6	\$5,464	
	Lighting - Pendent/Surface		10	EA	6	\$1,239	
	Marker Board		18	LF	6	\$386	
	Walls - Plaster/Drywall		1,182	SF	6	\$3,262	
Class	rooms Subtotal:					\$226,065	

Building: Branch

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Ceiling - Plaster/Drywall	110 Main Office	638	SF	6	\$2,208	
	Doors - Wood Doors inclu hw	110 Main Office	1	EA	6	\$301	
	Floor - Tile/Sheet	110 Main Office	638	SF	7	\$0	
	Lighting - Pendent/Surface	110 Main Office	10	EA	7	\$0	
	Walls - Plaster/Drywall	110 Main Office	1,083	SF	6	\$2,989	
	Ceiling - Plaster/Drywall	110A Office	208	SF	6	\$720	
	Doors - Wood Doors inclu hw	110A Office	1	EA	6	\$301	
	Floor - Tile/Sheet	110A Office	208	SF	6	\$208	
	Lighting - Pendent/Surface	110A Office	2	EA	7	\$0	
	Power Distribution	110A Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	110A Office	487	SF	6	\$1,344	
	Ceiling - Plaster/Drywall	111 Office	396	SF	6	\$1,370	
	Doors - Wood Doors inclu hw	111 Office	1	EA	7	\$0	
	Floor - Tile/Sheet	111 Office	396	SF	7	\$0	
	Lighting - Pendent/Surface	111 Office	7	EA	6	\$867	
	Power Distribution	111 Office	4	EA	7	\$0	
	Walls - Plaster/Drywall	111 Office	843	SF	6	\$2,327	



Building: Branch

e Suites/Offices g - Plaster/Drywall s - Transom Window S - Wood Doors inclu hw - Tile/Sheet ng - Pendent/Surface S - Plaster/Drywall g - Plaster/Drywall s - Wood Doors inclu hw - Tile/Sheet ng - Pendent/Surface rr Distribution ge/ Closet S - Plaster/Drywall Sink	112A Resource Room 112A Resource Room 112A Resource Room 112A Resource Room 112A Resource Room 112A Resource Room 117A Staff Lounge 117A Staff Lounge	336 9 1 336 5 837 197 1 197 2 6 50	SF EA SF EA SF EA SF EA EA	4 6 6 6 5 6 6 6 7	\$5,059 \$152 \$301 \$336 \$619 \$6,344 \$682 \$301 \$197	Cracks on ceiling tile, a possible liofe safety issue This rooms is used as storage.
s - Transom Window s - Wood Doors inclu hw - Tile/Sheet ng - Pendent/Surface - Plaster/Drywall g - Plaster/Drywall s - Wood Doors inclu hw - Tile/Sheet ng - Pendent/Surface rr Distribution ge/ Closet s - Plaster/Drywall Slnk	 112A Resource Room 117A Staff Lounge 	9 1 336 5 837 197 1 197 2 6	SF EA SF SF EA SF EA	6 6 5 6 6 6	\$152 \$301 \$336 \$619 \$6,344 \$682 \$301	
s - Wood Doors inclu hw - Tile/Sheet ng - Pendent/Surface - Plaster/Drywall g - Plaster/Drywall s - Wood Doors inclu hw - Tile/Sheet ng - Pendent/Surface rr Distribution ge/ Closet - Plaster/Drywall Slnk	 112A Resource Room 117A Staff Lounge 	1 336 5 837 197 1 197 2 6	EA SF SF SF EA SF EA	6 6 5 6 6	\$301 \$336 \$619 \$6,344 \$682 \$301	This rooms is used as storage.
 Tile/Sheet ng - Pendent/Surface Plaster/Drywall g - Plaster/Drywall s - Wood Doors inclu hw Tile/Sheet ng - Pendent/Surface ar Distribution ge/ Closet s - Plaster/Drywall Slnk 	 112A Resource Room 112A Resource Room 112A Resource Room 112A Resource Room 117A Staff Lounge 	336 5 837 197 1 197 2 6	SF EA SF EA SF EA	6 5 6 6	\$336 \$619 \$6,344 \$682 \$301	This rooms is used as storage.
ng - Pendent/Surface - Plaster/Drywall g - Plaster/Drywall - Wood Doors inclu hw - Tile/Sheet ng - Pendent/Surface r Distribution ge/ Closet - Plaster/Drywall - Slnk	 112A Resource Room 112A Resource Room 117A Staff Lounge 	5 837 197 1 197 2 6	EA SF EA SF EA	6 5 6 6	\$619 \$6,344 \$682 \$301	
s - Plaster/Drywall ig - Plaster/Drywall is - Wood Doors inclu hw - Tile/Sheet ng - Pendent/Surface or Distribution ge/ Closet s - Plaster/Drywall . SInk	112A Resource Room117A Staff Lounge117A Staff Lounge	837 197 1 197 2 6	SF SF EA SF EA	5 6 6	\$6,344 \$682 \$301	
g - Plaster/Drywall s - Wood Doors inclu hw - Tile/Sheet ng - Pendent/Surface or Distribution ge/ Closet s - Plaster/Drywall SInk	117A Staff Lounge117A Staff Lounge117A Staff Lounge117A Staff Lounge117A Staff Lounge117A Staff Lounge117A Staff Lounge	197 1 197 2 6	SF EA SF EA	6 6 6	\$682 \$301	
s - Wood Doors inclu hw - Tile/Sheet ng - Pendent/Surface rr Distribution ge/ Closet s - Plaster/Drywall - Slnk	117A Staff Lounge 117A Staff Lounge 117A Staff Lounge 117A Staff Lounge 117A Staff Lounge	1 197 2 6	EA SF EA	6 6	\$301	
- Tile/Sheet ng - Pendent/Surface r Distribution ge/ Closet s - Plaster/Drywall . SInk	117A Staff Lounge 117A Staff Lounge 117A Staff Lounge 117A Staff Lounge	197 2 6	SF EA	6		
ng - Pendent/Surface er Distribution ge/ Closet - Plaster/Drywall SInk	117A Staff Lounge 117A Staff Lounge 117A Staff Lounge	2 6	EA		\$197	
r Distribution ge/ Closet - Plaster/Drywall SInk	117A Staff Lounge 117A Staff Lounge	6		7		
ge/ Closet - Plaster/Drywall SInk	117A Staff Lounge				\$0	
- Plaster/Drywall SInk	0	50	EA	6	\$12,749	
SInk	117A Staff Lounge		SF	6	\$363	
SInk		705	SF	6	\$1,946	
n Disstan/Dravall	117A Staff Lounge	1	EA	5	\$1,508	
g - Plaster/Drywall	2.5 Floor East Office on Landing	135	SF	6	\$467	
s - Wood Doors inclu hw	2.5 Floor East Office on Landing	1	EA	4	\$3,413	Cracked door panels and peeling finish
- Epoxy/ Painted	2.5 Floor East Office on Landing	135	SF	6		
ng - Pendent/Surface	2.5 Floor East Office on Landing	1	EA	6	\$124	
s - Plaster/Drywall	2.5 Floor East Office on Landing	471	SF	5	\$3,570	
g - Plaster/Drywall	Basement	5,792	SF	6	\$31,971	
s - Wood Doors inclu hw	Basement	2	EA	6	\$602	
- Concrete Epoxy/ Painted	Basement	5,092	SF	6		
	Basement	9	EA	7		
	Basement	700	SF	6		
	Basement	1	EA	7	\$0	
	Basement	1	EA	6	\$6,510	
	Basement	10	LF	7	\$0	
	Basement	69	SF	6	\$500	
s - Plaster/Drywall	Basement	2,973	SF	6	\$8,205	
g - Plaster/Drywall	Basement	388	SF	6	\$1,343	
s - Steel Doors incl hw	Basement	2	EA	6		
- Concrete						
		9	EA	7	ΨIO	
	 Epoxy/ Painted ng - Pendent/Surface - Plaster/Drywall g - Plaster/Drywall g - Wood Doors inclu hw - Concrete Epoxy/ Painted ng - Pendent/Surface g - Curtain g - Curtain g - Flaster/Drywall g - Plaster/Drywall g - Plaster/Drywall g - Plaster/Drywall 	- Epoxy/ Painted 2.5 Floor East Office on Landing 2.5 Floor East O	- Epoxy/ Painted 2.5 Floor East Office on Landing 135 ng - Pendent/Surface 2.5 Floor East Office on Landing 1 2.5 Floor East Office on Landing 471 2.5 Floor East Office on Landing 471 g - Plaster/Drywall Basement 5,792 - Concrete Epoxy/ Painted Basement 5,092 ng - Pendent/Surface Basement 9 e Basement 9 e Basement 700 e Curtain Basement 1 e Lift Basement 1 e Stairs - Wood Basement 69 g - Plaster/Drywall Basement 69 e - Plaster/Drywall Basement 2,973 g - Plaster/Drywall Basement 240 - Steel Doors incl hw Basement 240 - Epoxy/ Painted Basement 148	- Epoxy/ Painted 2.5 Floor East Office on Landing 135 SF ng - Pendent/Surface 2.5 Floor East Office on Landing 1 EA - Plaster/Drywall 2.5 Floor East Office on Landing 471 SF - Wood Doors inclu hw Basement 5,792 SF - Wood Doors inclu hw Basement 5,092 SF ng - Pendent/Surface Basement 9 EA - Concrete Epoxy/ Painted Basement 9 EA - Concrete Second Basement 1 EA - Concrete Second Basement 1 EA - Stairs - Wood Basement 2,973 SF - Plaster/Drywall Basement 2,973 SF - Steel Doors incl hw Basement 2 - Steel Doors incl hw - 3 - Steel Doors incl hw - 3	- Epoxy/ Painted2.5 Floor East Office on Landing135SF6ng - Pendent/Surface2.5 Floor East Office on Landing1EA6- Plaster/Drywall2.5 Floor East Office on Landing471SF5g - Plaster/DrywallBasement5.792SF6- Concrete Epoxy/ PaintedBasement5.092SF6- Concrete Epoxy/ PaintedBasement9EA7eBasement9EA7eBasement1EA7eBasement1EA7eBasement1EA7eBasement1EA7eBasement1EA7eBasement10LF7ge/ClosetBasement69SF6e- Plaster/DrywallBasement2,973SF6g - Plaster/DrywallBasement2,973SF6e- ConcreteBasement2EA6- ConcreteBasement2EA6	- Epoxy/ Painted 2.5 Floor East Office on Landing 135 SF 6 \$71 ng - Pendent/Surface 2.5 Floor East Office on Landing 1 EA 6 \$124 2.5 Floor East Office on Landing 471 SF 5 \$3,570 g - Plaster/Drywall Basement 5,792 SF 6 \$31,971 - Wood Doors inclu hw Basement 2 EA 6 \$602 - Concrete Epoxy/ Painted Basement 5,092 SF 6 \$2,694 ng - Pendent/Surface Basement 9 EA 7 \$0 a East 7 \$0 a Curtain Basement 1 EA 7 \$0 Example 6 \$4,044 - Curtain Basement 1 EA 6 \$6,510 - Stairs - Wood Basement 69 SF 6 \$4,044 - Stairs - Wood Basement 69 SF 6 \$500 - Plaster/Drywall Basement 69 SF 6 \$500 - Plaster/Drywall Basement 2,973 SF 6 \$4,044 - Stairs - Wood Basement 2,973 SF 6 \$500 - Plaster/Drywall Basement 2,973 SF 6 \$1,343 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Stairs - Wood SF 6 \$4,044 - Steel Doors incl hw Basement 2,973 SF 6 \$1,343 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw Basement 2 EA 6 \$6,510 - Steel Doors incl hw - \$5,510 - Steel Doors incl A \$5,510 - Steel Doors incl hw - \$5,510 - Steel Doors incl hw - \$5,510 - Steel Doors incl A \$5,510 - Steel Doors incl hw - \$5,510 - Steel Doors incl hw - \$5,510 - Steel Doors incl hw -



Building: Branch

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Kitcher	1						
	Walls - Concrete Block	Basement	709	SF	6	\$2,078	
	Walls - Vinyl Coated Gypsum Panel	Basement	910	SF	7	\$0	
MDF_IC)F						
	Doors - Steel Doors incl hw	012A	1	EA	7	\$0	
	Finishes	012A	100	SF	5	\$1,614	
Machar	nical/ Service Rooms			-		÷)-	
wechai	Janitor's Closet	1st Floor	14	SF	6	\$100	JC West
	Storage Room	1st Floor	14	SF	6		1st West
	Janitor's Closet	2nd Floor	20	SF	5	\$323	
	Boiler Room	Basement		SF			2004
			806		5	\$13,001	Fire Duran Deces
	Mechanical/ Service Rooms	Basement	100	SF	6		Fire Pump Room
	Mechanical/ Service Rooms	Basement	77	SF	6	\$552	Elevator Equipment Room
	Mechanical/ Service Rooms	Basement	302	SF	6	\$2,164	
Restroo	om						
	Ceiling - Lay-in	1st Floor Unisex Accessible	42	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor Unisex Accessible	1	EA	7	\$0	
	Floor Drain	1st Floor Unisex Accessible	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor Unisex Accessible	42	SF	6	\$89	
	Hand Dryer	1st Floor Unisex Accessible	1	EA	7	\$0	
	Lavatory	1st Floor Unisex Accessible	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor Unisex Accessible	1	EA	7	\$0	
	Walls - Tile	1st Floor Unisex Accessible	265	SF	6	\$580	
	Water Closet	1st Floor Unisex Accessible	1	EA	6	\$336	
	Ceiling - Plaster/Drywall	1st Floor Unisex between 117A and 116	90	SF	6	\$311	
	Doors - Wood Doors inclu hw	1st Floor Unisex between 117A and 116	1	EA	7	\$0	
	Floor Drain	1st Floor Unisex between 117A and 116	1	EA	6	\$1,059	
	Floor - Tile	1st Floor Unisex between 117A and 116	90	SF	6	\$197	
	Lavatory	1st Floor Unisex between 117A and 116	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor Unisex between 117A and 116	12	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor Unisex between 117A and 116	94	SF	6	\$259	
	Walls - Tile	1st Floor Unisex between 117A and 116	282	SF	6	\$617	
	Water Closet	1st Floor Unisex between 117A and 116	1	EA	6	\$336	
	Ceiling - Plaster/Drywall	1st Floor	247	SF	6	\$855	
	Doors - Wood Doors inclu hw	1st Floor		EA	7	\$0 \$0	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor - Tile	1st Floor	247	SF	6	\$540	
			20	0.	Ŭ	φ040	



Building: Branch

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	om						
	Hand Dryer	1st Floor	1	EA	6	\$230	
	Lavatory	1st Floor	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st Floor	4	EA	6	\$496	
	Partitions	1st Floor	2	EA	6	\$594	
	Urinals	1st Floor	2	EA	6	\$672	
	Walls - Plaster/Drywall	1st Floor	157	SF	6	\$433	
	Walls - Tile	1st Floor	471	SF	6	\$1,031	
	Water Closet	1st Floor	2	EA	6	\$672	
	Ceiling - Plaster/Drywall	2nd Floor	342	SF	6	\$1,184	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor - Tile	2nd Floor	342	SF	6	\$748	
	Hand Dryer	2nd Floor	2	EA	7	\$0	
	Lavatory	2nd Floor	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd Floor	6	EA	6	\$743	
	Partitions	2nd Floor	3	EA	6	\$891	
	Walls - Plaster/Drywall	2nd Floor	202	SF	6	\$557	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	602	SF	6	\$1,360	
	Water Closet	2nd Floor	3	EA	6	\$1,008	
	Ceiling - Plaster/Drywall	Basement East Unisex	94	SF	6	\$325	
	Doors - Steel Doors incl hw	Basement East Unisex	1	EA	6	\$301	
	Floor Drain	Basement East Unisex	1	EA	6	\$1,059	
	Floor - Tile	Basement East Unisex	94	SF	6	\$206	
	Hand Dryer	Basement East Unisex	1	EA	7	\$0	
	Lavatory	Basement East Unisex	1	EA	6	\$320	
	Lighting - Pendent/Surface	Basement East Unisex	1	EA	4	\$541	Broken lens
	Walls - Concrete Block	Basement East Unisex	102	SF	6	\$299	
	Walls - Plaster/Drywall	Basement East Unisex	189	SF	6	\$522	
	Water Closet	Basement East Unisex	1	EA	6	\$336	
	Ceiling - Plaster/Drywall	Basement West Unisex	66	SF	6	\$228	
	Doors - Steel Doors incl hw	Basement West Unisex	1	EA	5	\$1,174	
	Floor Drain	Basement West Unisex	1	EA	6	\$1,059	
	Floor - Tile	Basement West Unisex	66	SF	6	\$144	
	Hand Dryer	Basement West Unisex	1	EA	6	\$230	
	Lavatory	Basement West Unisex	1	EA	6	\$320	
	Lighting - Pendent/Surface	Basement West Unisex	1	EA	7	\$0	
	Walls - Concrete Block	Basement West Unisex	48	SF	6	\$141	



Building: Branch

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Walls - Masonry	Basement West Unisex	36	SF	6	\$113	
	Walls - Plaster/Drywall	Basement West Unisex	60	SF	6	\$166	
	Water Closet	Basement West Unisex	1	EA	6	\$336	
	Ceiling - Plaster/Drywall	Basement	504	SF	6	\$1,744	
	Ceiling - Plaster/Drywall	Basement	511	SF	6	\$1,768	
	Floor Drain	Basement	1	EA	6	\$1,059	
	Floor Drain	Basement	1	EA	6	\$1,059	
	Floor - Tile	Basement	504	SF	6	\$1,103	
	Floor - Tile	Basement	511	SF	6	\$1,118	
	Hand Dryer	Basement	1	EA	5	\$590	
	Hand Dryer	Basement	1	EA	6	\$230	
	Hand Dryer	Basement	2	EA	6	\$460	
	Lavatory	Basement	3	EA	7	\$0	
	Lavatory	Basement	3	EA	6	\$959	
	Lighting - Pendent/Surface	Basement	9	EA	7	\$0	
	Lighting - Pendent/Surface	Basement	8	EA	7	\$0	
	Partitions	Basement	8	EA	6	\$2,375	
	Partitions	Basement	7	EA	6	\$2,078	
	Urinals	Basement	6	EA	6	\$2,016	
	Walls - Concrete Block	Basement	216	SF	6	\$633	
	Walls - Concrete Block	Basement	602	SF	6	\$1,765	
	Walls - Masonry	Basement	301	SF	6	\$947	
	Walls - Masonry	Basement	540	SF	5	\$22,317	
	Walls - Plaster/Drywall	Basement	49	SF	6	\$135	
	Water Closet	Basement	8	EA	7	\$0	
	Water Closet	Basement	1	EA	7	\$0	

Rooms (Other Than Classrooms) Subtotal:

\$208,886

Building: Branch

Group Item - Type	Location	Quantity	Unit	Rank	Cost Comment
Corridor					
Ceiling - Plaster/Drywall	1st Floor	1,168	SF	6	\$7,232
Doors - Steel Doors incl hw	1st Floor	4	EA	6	\$1,204
Drinking Fountains - Single Fountain	1st Floor	3	EA	6	\$827
Floor - Concrete Epoxy/ Painted	1st Floor	1,168	SF	6	\$568



Building: Branch

			-			-	-
roup Item - Type	Lc	ocation	Quantity	Unit	Rank	Cost	Comments
orridor							
Lighting - Pendent/Surface		st Floor	11	EA	6	\$1,363	
Walls - Plaster/Drywall	1s	st Floor	1,801	SF	6	\$7,984	
Ceiling - Plaster/Drywall		nd Floor	1,032	SF	6	\$6,390	
Drinking Fountains - Single Foun	ain 2r	nd Floor	3	EA	7	\$0	
Floor - Epoxy/ Painted	2r	nd Floor	1,032	SF	6	\$546	
Lighting - Pendent/Surface	2r	nd Floor	20	EA	6	\$2,478	
Walls - Plaster/Drywall	2r	nd Floor	1,854	SF	6	\$8,219	
tairs							
Ceiling - Plaster/Drywall	Ea	ast	680	SF	6	\$4,979	
Floor - Epoxy/ Painted	Ea	ast	506	SF	6	\$268	
Handrails	Ea	ast	110	LF	6	\$953	
Lighting - Pendent/Surface	Ea	ast	5	EA	6	\$619	
Stairs - Concrete	Ea	ast	352	LF	6	\$2,919	
Walls - Plaster/Drywall	Ea	ast	2,490	SF	6	\$6,872	
Ceiling - Plaster/Drywall	W	/est	680	SF	6	\$4,979	
Floor - Epoxy/ Painted	W	/est	506	SF	6	\$268	
Handrails	W	/est	110	LF	6	\$953	
Lighting - Pendent/Surface	W	/est	5	EA	6	\$619	
Stairs - Concrete	W	/est	352	LF	6	\$2,919	
Walls - Plaster/Drywall	W	/est	2,490	SF	6	\$6,872	
uilding Interior Subtotal:						\$70,032	
otal Building Cost					\$1	,843,428	
ITE							
ategory: Site							
roup Item - Type	Lc	ocation	Quantity	Unit	Rank	Cost	Comments
thletic							
Surface - Natural	Ea	ast	19,600	SF	6	\$16,256	
Surface - Natural	W	/est	38,400	SF	6	\$31,849	
ivil/Drainage							
Civil/ Drainage - Catch Basin	Er	ntire Site	17	EA	7	\$0	
Civil/ Drainage - Catch Basin	Er	ntire Site	1	EA	6	\$1,094	NE parking lot- not draining
Civil/ Drainage - Site Drain	Er	ntire Site	4	EA	6	\$1,241	branch doors 2,3,5,6- rout and clean



SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Civil/D	rainage						
	Civil/ Drainage - Site Manhole	Entire Site	13	EA	7	\$0	
Fencin	g						
	Fencing - Chain Link	Entire Site	536	LF	6	\$10,064	
	Fencing - Chain Link	Entire Site / Site West	80	LF	4	\$7,344	damaged along alley
	Fencing - New Standard Ornamental	Entire Site	2,919	LF	7	\$0	
Landso	cape						
	Benches	Entire Site	18	EA	6	\$7,741	paint steel benches
	Irrigation	Entire Site	143,882	SF	6	\$162,543	6 damaged heads were repaired
	Landscape - Grass	Entire Site	86,482	SF	6	\$71,728	
	Landscape - Hardscape- Concrete	Entire Site	4,686	SF	6	\$24,191	
	Landscape - Hardscape- Pavers	Entire Site / North East	3,312	SF	7	\$0	
	Parkway trees	Entire Site	18	EA	7	\$0	
	Retaining Wall - Concrete	Entire Site	150	SF	6	\$3,516	branch building- doors 2,3,5
	Trash Receptacles	Entire Site	9	EA	7	\$0	
	Walking Path - Asphalt	Entire Site / Site - East	3,400	SF	6	\$10,940	walkway between buildings
	Walking Path - Crushed Stone	Entire Site	4,460	SF	6	\$9,439	
Parking	g Lot						
	Concrete Curbs	Entire Site	733	LF	7	\$0	NE and SE lots
	Interior Plantings	Entire Site / North East	6	LF	7	\$0	
	Surface - Asphalt	Entire Site	15,877	SF	7	\$0	NE and SE lots; includes drve north of main building
	Surface - Concrete	Entire Site	2,295	SF	6	\$5,546	NE lot and NW of main building
	Trash Compactor	Entire Site	2	EA	7	\$0	site NE and SW
	Trash Enclosure - Chain Links	Entire Site / North East	966	SF	6	\$16,950	
	Trash Enclosure - Masonry	Entire Site / South West	627	SF	6	\$24,737	partially enclosed. 5 If of stone coping is missing.
	Vehicular Screening	Entire Site	86	LF	7	\$0	NE lot
Playgro	ound						
	Equipment - Pre K 3-5	North East	1	EA	5	\$44,233	deteriorating wood structure
	Equipment - School Age 5-12	South East / North	1	EA	6	\$3,546	
	Equipment - School Age 5-12	South East / South	2	EA	6	\$7,092	
	Equipment - Swingset	North East	1	EA	6	\$1,182	broken seat @ 1
	Equipment - Swingset	South East / North	1	EA	7	\$0	
	Surface - Poured Surface	North East	5,145	SF	4	\$122,721	cracked/deteriorated, pitted throughout
	Surface - Poured Surface	South East / North	4,488	SF	4	\$107,050	cracked/deteriorated, pitted throughout
	Surface - Poured Surface	South East / South	2,408	SF	5	\$33,091	cracked/deteriorated, pitted throughout

\$5,516,803

950 W 33rd Pl Chicago, IL 60608

SITE

Category: Site						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Sidewalks						
Sidewalks - Internal Walks	Entire Site	130	LF	7	\$0	site NE and site South
Sidewalks - Perimeter Sidewalks	Entire Site	12,549	SF	7	\$0	
Signage						
Flag Pole - Flag Pole	Site South and NE	2	EA	6	\$3,314	paint
Site Subtotal:					\$727,407	
Total Site Cost					\$727,407	

Campus Total ^{2 3}

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main			-	l	4	4	4	4		l		ł		
Computer Lab	Regular Classroom		306	306	1,035	1	2	6	111	48	40			
Gymnasium	Regular Classroom		106	106	1,079	0	0	2	148	74	50			
Library	Regular Classroom		305	305	2,490	2	32	79	259	130	40			
Regular Classroom	Regular Classroom		102	102	1,099	1	2	9	190	90	40			
Regular Classroom	Regular Classroom		103	103	1,099	1	2	9	190	90	40			
Regular Classroom	Regular Classroom		104	104	993	1	2	7	148	74	40			
Regular Classroom	Regular Classroom		105	105	1,008	1	2	9	148	74	40			
Regular Classroom	Regular Classroom		202	202	1,028	1	4	6	148	74	40			
Regular Classroom	Regular Classroom		203	203	1,099	1	2	8	190	95	40			Y
Regular Classroom	Regular Classroom		204	204	1,018	1	2	6	148	64	40			Y
Regular Classroom	Regular Classroom		205	205	950	1	2	6	148	74	40			
Regular Classroom	Regular Classroom		206	206	1,093	1	6	8	148	64	40			
Regular Classroom	Regular Classroom		302	302	1,028	0	1	20	148	74	40			
Regular Classroom	Regular Classroom		303	303	1,106	1	2	8	190	95	40			
Regular Classroom	Regular Classroom		304	304	1,041	0	4	8	148	74	40			
Branch														
Computer Lab	Regular Classroom		213		750	1	40	82	108	54	40	Ν	Ν	Ν
Library	Regular Classroom		214		837	0	2	8	189	94	40	Ν	N	N
Lunch Room	Regular Classroom		116		648	0	3	10	108	54	40	Ν	N	N
Office	Regular Classroom		211		558	3	3	8	189	94	40	Ν	N	N
Regular Classroom	Regular Classroom		113		720	1	4	10	96	48	40	Ν	N	N
Regular Classroom	Regular Classroom		114		884	2	2	6	189	94	40	Ν	Y	N
Regular Classroom	Regular Classroom		115		819	2	3	10	168	84	40	N	N	N
Regular Classroom	Regular Classroom		210		837	2	2	6	189	94	40	N	N	N
Regular Classroom	Regular Classroom		212		775	2	2	6	108	54	40	Ν	N	Ν
Regular Classroom	Regular Classroom		215		775	1	2	6	189	94	40	N	Y	Y
Regular Classroom	Regular Classroom		216		725	2	2	6	108	54	40	Ν	N	N
Regular Classroom	Regular Classroom		217		775	2	2	4	108	54	40	Ν	Y	N