

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|---------------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1957 | 1 | 13,369 | \$748,846 |
| 4-Classroom Modular | 2003 | 1 | 4,832 | \$163,050 |
| Addition | 1960 | 1 | 6,847 | \$274,241 |
| Linked Addition | 1996 | 1 | 15,130 | \$655,018 |
| SITE | | | | \$201,498 |
| Campus Total | | | 40,178 | \$2,042,654 |

Building: Main

Category: Building Exterior

| Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|--|--|--|--|---|
| | | | | | |
| #2-E | 1 | EA | 6 | \$631 | |
| #4-NW | 2 | EA | 6 | \$961 | |
| #5-NW | 1 | EA | 6 | \$481 | |
| #6-W | 2 | EA | 6 | \$961 | |
| #7-W | 1 | EA | 6 | \$481 | |
| #8-W | 1 | EA | 6 | \$481 | |
| #3-NE | 6 | EA | 6 | \$1,880 | |
| #3-NE | 2 | EA | 6 | \$1,092 | |
| #3-NE | 1 | EA | 6 | \$313 | |
| #2-E | 3 | LF | 6 | \$245 | |
| #5-NW | 3 | LF | 6 | \$245 | |
| #6-W | 6 | LF | 6 | \$491 | |
| #4-NW | 6 | LF | 6 | \$678 | |
| #8-W | 3 | LF | 6 | \$339 | |
| | | | | | |
| Entire Building | 508 | LF | 7 | \$0 | |
| | #2-E #4-NW #5-NW #6-W #7-W #8-W #3-NE #3-NE #3-NE #3-NE #2-E #2-E #5-NW #6-W #4-NW #8-W | #2-E 1 #4-NW 2 #5-NW 1 #6-W 2 #7-W 1 #8-W 1 #3-NE 6 #3-NE 2 #3-NE 1 #2-E 3 #5-NW 3 #6-W 6 #4-NW 6 #4-NW 6 #8-W 3 | #2-E 1 EA #4-NW 2 EA #5-NW 1 EA #6-W 2 EA #7-W 1 EA #8-W 1 EA #3-NE 6 EA #3-NE 1 EA #3-NE 2 EA #3-NE 1 EA #3-NE 1 EA #3-NE 3 LF #6-W 6 LF #6-W 6 LF #4-NW 6 LF #8-W 3 LF | #2-E 1 EA 6 #4-NW 2 EA 6 #5-NW 1 EA 6 #6-W 2 EA 6 #7-W 1 EA 6 #8-W 1 EA 6 #3-NE 6 EA 6 #3-NE 1 EA 6 #3-NE 2 EA 6 #3-NE 1 EA 6 #3-NE 3 LF 6 #3-NE 3 LF 6 #4-NW 6 LF 6 #4-NW 6 LF 6 #4-NW 3 LF 6 #8-W 3 LF 6 | #2-E 1 EA 6 \$631 #4-NW 2 EA 6 \$961 #5-NW 1 EA 6 \$961 #5-NW 1 EA 6 \$481 #6-W 2 EA 6 \$961 #7-W 1 EA 6 \$481 #8-W 1 EA 6 \$481 #3-NE 6 EA 6 \$1,880 #3-NE 1 EA 6 \$1,92 #3-NE 1 EA 6 \$1,092 #3-NE 1 EA 6 \$245 #6-W 3 LF 6 \$245 #6-W 6 LF 6 \$491 #4-NW 6 LF 6 \$339 #8-W 3 LF 6 \$339 |



Building: Main

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---|--------------------------------|----------|------|------|----------|--|
| Founda | tion | | | | | | |
| | Superstructure - Concrete | Entire Building | 13,369 | SF | 7 | \$0 | |
| Lighting | 3 | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 6 | EA | 5 | \$2,564 | Bad ballasts |
| Roof Sy | /stem | | | | | | |
| 11001 05 | Chimney - Brick Chimney- Concrete/ Mortar Liner | Upper Roof | 17 | LF | 6 | \$16,230 | |
| | Chimney - Metal Flue | Upper Roof | 27 | LF | 6 | \$4,270 | |
| | Coping - Metal | Main Roof | 461 | LF | 6 | \$14,806 | |
| | Coping - Metal | Upper Roof | 200 | LF | 6 | \$6,424 | |
| | Downspouts - Exterior Downspouts | Main Roof / North West | 15 | LF | 6 | \$498 | |
| | Downspouts - Interior Downspouts | Main Roof | 24 | LF | 6 | \$798 | |
| | Downspouts - Interior Downspouts | Upper Roof | 17 | LF | 6 | \$565 | |
| | Roof Structure - Concrete | Main Roof | 10,983 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | Upper Roof | 2,057 | SF | 7 | \$0 | |
| | Roof - Modified Bitumen | Main Roof | 9,483 | SF | 6 | \$89,229 | |
| | Roof - Modified Bitumen | Main Roof | 1,500 | SF | 5 | \$37,109 | |
| | Roof - Modified Bitumen | Upper Roof | 100 | SF | 5 | \$2,856 | |
| | Roof - Modified Bitumen | Upper Roof | 1,957 | SF | 6 | \$18,414 | |
| Walls | | | | | | | |
| | Canopy - Concrete/ Stucco | Entire Building | 1,129 | SF | 6 | \$37,359 | |
| | Canopy - Metal | Entire Building | 30 | SF | 6 | \$644 | |
| | Exterior Walls - Brick | Entire Building | 10 | SF | 5 | \$238 | step cracking |
| | Exterior Walls - Brick | Entire Building | 20 | SF | 5 | \$476 | Vertical cracks, gaps in mortar, open joints |
| | Exterior Walls - Brick | Entire Building | 4,890 | SF | 6 | \$32,866 | |
| | Exterior Walls - Precast Panel Wall | Entire Building | 102 | SF | 6 | \$686 | |
| | Exterior Walls - Precast Panel Wall | Entire Building / North Façade | 4 | SF | 5 | \$45 | spalling, shearing, exposed steel |
| Window | /S | | | | | | |
| | Curtain wall - Glazed Double Pane | Entire Building | 810 | SF | 6 | \$9,081 | |
| | Curtain wall - Insulated Panel | Entire Building / North Façade | 150 | SF | 6 | \$1,682 | |
| | Curtain wall - Louver | Entire Building | 15 | SF | 6 | \$168 | |
| | Guard - Guards perforated | Entire Building | 1,128 | SF | 6 | \$14,404 | |
| | Skylite - Lexan | Entire Building | 160 | SF | 6 | \$3,823 | |
| | Skylite - Lexan | Entire Building / North | 32 | SF | 5 | \$2,558 | broken pane |
| | Windows - Casement Aluminum Double-pane | Entire Building | 785 | SF | 6 | \$5,860 | |



Building: Main

| Category: | Building | Exterior |
|-----------|----------|----------|
|-----------|----------|----------|

| Froup Item - Type | | Location | Quantity | Unit | Rank | | Comments |
|----------------------------------|-------------------|-----------------------------------|----------|------|------|-----------|-------------------------------------|
| uilding Exterior Subtotal: | | | | | | \$312,931 | |
| Building: Main | | | | | | | |
| Category: Electrical System | | | | | | | |
| Group Item - Type | | Location | Quantity | Unit | Rank | Cost | Comments |
| Emergency System | | | | | | | |
| Emergency A/C Power - Corrid | ors and Stairs | Entire Building / 1st Floor | 1,620 | SF | 6 | \$486 | |
| Emergency A/C Power - Multip | urpose Room | Entire Building / 1st Floor | 1,560 | SF | 6 | \$580 | |
| Emergency A/C Power - Stude | nts Toilets | Entire Building / 1st Floor | 458 | SF | 6 | \$170 | |
| Emergency Battery Packs - Cor | ridors and Stairs | Entire Building | 3 | EA | 6 | \$608 | |
| Emergency Battery Packs - Gyr | n | Entire Building | 4 | EA | 6 | \$810 | |
| Emergency Battery Packs - Lur | chrooms | Entire Building | 2 | EA | 6 | \$405 | |
| Emergency Battery Packs - Stu | dents Toilets | Entire Building | 2 | EA | 6 | \$405 | |
| Exit Signs - Corridors and Stair | S | Entire Building / Boiler Room | 3 | EA | 6 | \$449 | |
| Exit Signs - Lunchroom | | Entire Building / 1st Floor | 2 | EA | 6 | \$299 | |
| Security System - CCTV | | Entire Site | 40,178 | SF | 6 | \$12,065 | serves all buildings |
| Security System - Intrusion De | ection | Entire Site | 40,178 | SF | 6 | \$10,342 | serves all buildings |
| lain Service | | | | | | | |
| Main Electrical Service - 1200 A | 120/208/3PH | Electrical Room | 1 | EA | 6 | \$5,078 | Three section Deadfront Switchboard |
| PA System | | 1st Floor / Entire Building | 40,178 | SF | 6 | \$13,215 | serves all buildings |
| ower Distribution | | | | | | | |
| Lighting and Power Panels - 10 | 0 A | Entire Building / Mechanical Room | 1 | EA | 6 | \$299 | EM, emergency AC power |
| Lighting and Power Panels - Al | bove 100 A | Entire Building / 1st Floor | 1 | EA | 6 | \$497 | LR-1 |
| Lighting and Power Panels - Al | oove 100 A | Entire Building / Boiler Room | 1 | EA | 6 | \$497 | PB |
| Lighting and Power Panels - Al | oove 100 A | Entire Building / Electrical Room | 1 | EA | 6 | \$497 | |
| Lighting and Power Panels - Al | oove 100 A | Entire Building / Electrical Room | 1 | EA | 6 | \$497 | PP1 |
| Lighting and Power Panels - Al | oove 100 A | Entire Building / Mechanical Room | 1 | EA | 6 | \$497 | LC |
| Main Distribution Panels - 400 | - 600 amp | Entire Building / Electrical Room | 1 | EA | 6 | \$528 | MAIN SWBD |
| Electrical System Subtotal: | | | | | | \$48,225 | |

Building: Main

Category: Safty System

| Group Item - Type | Location | Quantity Unit Rank | Cost Comments |
|--------------------------|-----------------------------------|--------------------|---------------|
| Fire Alarm | | | |
| Fire Alarm Strobe Lights | Mechanical Room / Entire Building | 13,369 SF 6 | \$4,779 |
| | | | |



Building: Main

| Category: Safty System | | | | | | |
|---|-------------------------------|----------|------|------|----------|--|
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Fire Alarm | | | | | | |
| Safty System Subtotal: | | | | | \$4,779 | |
| Building: Main | | | | | | |
| Category: Mechanical System | | | | | | |
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Air Conditioning | | | | | | |
| Chiller-Air Cooled-Scroll Type-Ground Mounted - 50 - 100 tons | Site West | 1 | EA | 6 | \$3,659 | serves the Main and Addition buildings |
| Heat Pump- Floor Mounted- Electric Heating & DX Cooling- Self Contained Air Cooled Compressor - Less than 3 tons | 1st Floor | 1 | EA | 6 | \$1,405 | serves MDF room |
| Pipes - Chilled Water Pipe- Steel | Site West / Entire Building | 550 | LF | 6 | \$1,038 | |
| Pressure Fill System | Site West | 1 | EA | 6 | \$1,405 | |
| Air Handling Systems | | | | | | |
| Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - Less than 5 tons | Roof | 2 | EA | 6 | \$3,795 | |
| Boiler Systems | | | | | | |
| Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH | Boiler Room | 2 | EA | 6 | \$4,093 | |
| Chemical Pot Feeder | Boiler Room | 1 | EA | 6 | \$725 | |
| Combustion Dampers | Boiler Room | 2 | EA | 6 | \$818 | |
| Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH | Boiler Room | 2 | EA | 6 | \$1,996 | |
| Water Fill System | Boiler Room | 1 | EA | 6 | \$1,168 | |
| Heating Devices | | | | | | |
| Cabinet Heaters - With Hot Water Coil | 1st Floor | 1 | EA | 6 | \$354 | |
| Unit Heater - Hot Water | Boiler Room | 1 | EA | 6 | \$279 | |
| Mechanical Plumbing | | | | | | |
| Hot Water Pump - Less than 10 | Boiler Room | 2 | EA | 6 | \$2,222 | |
| Hydronic Supply and Return - Steel | Entire Building | 500 | LF | 6 | \$38,388 | |
| Temperature Control | | | | | | |
| DDC System | Entire Building / Boiler Room | 13,369 | SF | 6 | \$7,647 | serves main and addition |
| Unit Ventilation | | | | | | |
| Unit Ventilators- Floor Mounted- Hot Water & Chilled Water Coils | 1st Floor / Entire Building | 17 | EA | 6 | \$21,211 | |
| Ventilation | | | | | | |
| Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Roof | 2 | EA | 6 | \$1,185 | |



Building: Main

| iroup Item - Type | Location | Quantity Unit Rank Cost Comments |
|---|----------|----------------------------------|
| /entilation | | |
| Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Roof | 1 EA 6 \$592 |

Mechanical System Subtotal:

Building: Main

Category: Plumbing System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------|----------|------|------|----------|----------|
| Hot Water | | | | | | |
| Gas Heater - 300001 - 600000 BTU/HR | Boiler Room | 1 | EA | 6 | \$310 | |
| Piping | | | | | | |
| Domestic Piping-Cold Water Horizontal Lines | Entire Building | 13.369 | SF | 6 | \$3,250 | |
| Domestic Piping-Hot Water Horizontal Lines | Entire Building | | SF | 6 | \$2,485 | |
| Domestic Piping-Hot Water Return Lines | Entire Building | 13,369 | SF | 6 | \$1,912 | |
| Sanitary Piping | Entire Building | 13,369 | SF | 6 | \$12,235 | |
| Storm Piping | Entire Building | 13,369 | SF | 6 | \$11,662 | |
| Vent Piping | Entire Building | 13,369 | SF | 6 | \$8,985 | |

Plumbing System Subtotal:

\$40,839

Building: Main

Category: Classrooms

| oup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------------------------|-----------|----------|------|------|---------|---|
| assroom #101 (Regular Classroom) | | | | | | |
| Casework | 1st Floor | 42 | LF | 6 | \$1,061 | |
| Ceiling - Plaster/Drywall | 1st Floor | 80 | SF | 6 | \$277 | |
| Ceiling - Splined | 1st Floor | 670 | SF | 5 | \$4,771 | water discoloration, tape holding in place, loose |
| Chalk Board | 1st Floor | 20 | LF | 4 | \$1,836 | |
| Doors - Side-lite | 1st Floor | 8 | SF | 6 | \$134 | |
| Doors - Transom Window | 1st Floor | 12 | SF | 6 | \$203 | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile/Sheet | 1st Floor | 750 | SF | 6 | \$751 | |
| Lighting - Pendent/Surface | 1st Floor | 20 | EA | 6 | \$2,478 | |
| Marker Board | 1st Floor | 10 | LF | 7 | \$0 | |
| Walls - Concrete Block | 1st Floor | 788 | SF | 6 | \$2,310 | |
| Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |



Building: Main

Category: Classrooms

| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|---------|---------------------|
| Classro | oom #103 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 42 | LF | 6 | \$1,061 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 80 | SF | 6 | \$277 | |
| | Ceiling - Splined | 1st Floor | 670 | SF | 6 | \$546 | |
| | Chalk Board | 1st Floor | 26 | LF | 4 | \$2,387 | |
| | Doors - Side-lite | 1st Floor | 8 | SF | 6 | \$134 | |
| | Doors - Transom Window | 1st Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor | 750 | SF | 6 | \$751 | |
| | Lighting - Pendent/Surface | 1st Floor | 20 | EA | 6 | \$2,478 | |
| | Walls - Concrete Block | 1st Floor | 788 | SF | 6 | \$2,310 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #105 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 42 | LF | 6 | \$1,061 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 80 | SF | 6 | \$277 | |
| | Ceiling - Splined | 1st Floor | 2 | SF | 5 | \$19 | water discoloration |
| | Ceiling - Splined | 1st Floor | 668 | SF | 6 | \$544 | |
| | Chalk Board | 1st Floor | 18 | LF | 4 | \$1,653 | |
| | Doors - Side-lite | 1st Floor | 8 | SF | 6 | \$134 | |
| | Doors - Transom Window | 1st Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor | 750 | SF | 6 | \$751 | |
| | Lighting - Pendent/Surface | 1st Floor | 20 | EA | 6 | \$2,478 | |
| | Marker Board | 1st Floor | 18 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 788 | SF | 6 | \$2,310 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #107 (Kindergarten) | | | | | | |
| | Casework | 1st Floor | 30 | LF | 6 | \$758 | |
| | Ceiling - Splined | 1st Floor | 854 | SF | 6 | \$696 | |
| | Ceiling - Splined | 1st Floor | 2 | SF | 5 | \$19 | water discoloration |
| | Chalk Board | 1st Floor | 20 | LF | 4 | \$1,836 | |
| | Doors - Side-lite | 1st Floor | 15 | SF | 6 | \$251 | |
| | Doors - Transom Window | 1st Floor | 18 | SF | 6 | \$305 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor | 856 | SF | 6 | \$857 | |
| | Lighting - Pendent/Surface | 1st Floor | 18 | EA | 6 | \$2,230 | |
| | Lighting - Wall Mounted | 1st Floor | 1 | EA | 6 | \$124 | |



Building: Main

Category: Classrooms

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|-----------|----------|------|------|----------|---------------------|
| lassroo | om #107 (Kindergarten) | | | | | | |
| | Marker Board | 1st Floor | 6 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 1,285 | SF | 6 | \$3,767 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| lassroo | om #108 (Computer Lab) | | | | | | |
| | Casework | 1st Floor | 30 | LF | 6 | \$758 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 80 | SF | 6 | \$277 | |
| | Ceiling - Splined | 1st Floor | 660 | SF | 6 | \$538 | |
| | Ceiling - Splined | 1st Floor | 10 | SF | 5 | \$97 | water discoloration |
| | Chalk Board | 1st Floor | 26 | LF | 4 | \$2,387 | |
| | Charging Station | 1st Floor | 1 | EA | 6 | \$485 | |
| | Doors - Side-lite | 1st Floor | 8 | SF | 6 | \$134 | |
| | Doors - Transom Window | 1st Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor | 750 | SF | 6 | \$751 | |
| | Lighting - Pendent/Surface | 1st Floor | 20 | EA | 6 | \$2,478 | |
| | Walls - Concrete Block | 1st Floor | 788 | SF | 6 | \$2,310 | |
| | Wireless System | 1st Floor | 1 | EA | 6 | \$372 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| lassroo | om #110 (Science Classroom) | | | | | | |
| | Casework | 1st Floor | 42 | LF | 6 | \$1,061 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 80 | SF | 6 | \$277 | |
| | Ceiling - Splined | 1st Floor | 670 | SF | 6 | \$546 | |
| | Chalk Board | 1st Floor | 30 | LF | 4 | \$2,754 | |
| | Doors - Side-lite | 1st Floor | 8 | SF | 6 | \$134 | |
| | Doors - Transom Window | 1st Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor | 750 | SF | 6 | \$751 | |
| | Lighting - Pendent/Surface | 1st Floor | 20 | EA | 6 | \$2,478 | |
| | Marker Board | 1st Floor | 8 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 788 | SF | 6 | \$2,310 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| | ooms Subtotal: | | | | | \$69,620 | |

Building: Main



John C Dore Elementary School 6108 S Natoma Ave Chicago, IL 60638

| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----|-----------------------------|---|----------|------|------|----------|---------------|
| | strative Suites/Offices | | | | | | |
| | Ceiling - Splined | 1st Floor-Counselor's Office 107 | 310 | SF | 6 | \$253 | |
| | Doors - Wood Doors inclu hw | 1st Floor-Counselor's Office 107 | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor-Counselor's Office 107 | 310 | SF | 6 | \$310 | |
| | Lighting - Pendent/Surface | 1st Floor-Counselor's Office 107 | 6 | EA | 6 | \$743 | |
| | Power Distribution | 1st Floor-Counselor's Office 107 | 12 | EA | 6 | \$25,499 | |
| | Walls - Concrete Block | 1st Floor-Counselor's Office 107 | 352 | SF | 6 | \$1,032 | |
| | Walls - Plaster/Drywall | 1st Floor-Counselor's Office 107 | 352 | SF | 6 | \$971 | |
| | Ceiling - Exposed | 1st Floor-Engineer's Office in Boiler Room | 95 | SF | 6 | \$141 | |
| | Floor - Concrete | 1st Floor-Engineer's Office in Boiler Room | 95 | SF | 6 | \$50 | |
| | Lighting - Pendent/Surface | 1st Floor-Engineer's Office in Boiler Room | 1 | EA | 6 | \$124 | |
| | Power Distribution | 1st Floor-Engineer's Office in Boiler Room | 4 | EA | 6 | \$8,500 | |
| | Walls - Masonry | 1st Floor-Engineer's Office in Boiler Room | 390 | SF | 6 | \$1,227 | |
| | Ceiling - Plaster/Drywall | 1st Floor-Main Office | 50 | SF | 6 | \$173 | |
| | Ceiling - Splined | 1st Floor-Main Office | 70 | SF | 6 | \$57 | |
| | Doors - Side-lite | 1st Floor-Main Office | 22 | SF | 6 | \$368 | Office window |
| | Doors - Transom Window | 1st Floor-Main Office | 20 | SF | 6 | \$339 | |
| | Doors - Wood Doors inclu hw | 1st Floor-Main Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor-Main Office | 120 | SF | 6 | \$120 | |
| | Lighting - Pendent/Surface | 1st Floor-Main Office | 2 | EA | 6 | \$248 | |
| | Power Distribution | 1st Floor-Main Office | 8 | EA | 6 | \$16,999 | |
| | Walls - Concrete Block | 1st Floor-Main Office | 440 | SF | 6 | \$1,290 | |
| | Ceiling - Plaster/Drywall | 1st Floor-Office 102 | 28 | SF | 6 | \$97 | |
| | Ceiling - Splined | 1st Floor-Office 102 | 150 | SF | 6 | \$122 | |
| | Doors - Wood Doors inclu hw | 1st Floor-Office 102 | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor-Office 102 | 178 | SF | 6 | \$178 | |
| | Lighting - Pendent/Surface | 1st Floor-Office 102 | 2 | EA | 6 | \$248 | |
| | Power Distribution | 1st Floor-Office 102 | 4 | EA | 6 | \$8,500 | |
| | Walls - Concrete Block | 1st Floor-Office 102 | 500 | SF | 6 | \$1,466 | |
| | Ceiling - Splined | 1st Floor-Office 104 | 230 | SF | 6 | \$187 | |
| | Doors - Wood Doors inclu hw | 1st Floor-Office 104 | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor-Office 104 | 230 | SF | 6 | \$503 | |
| | Lighting - Pendent/Surface | 1st Floor-Office 104 | 2 | EA | 6 | \$248 | |
| | Power Distribution | 1st Floor-Office 104 | 8 | EA | 6 | \$16,999 | |
| | Walls - Concrete Block | 1st Floor-Office 104 | 506 | SF | 6 | \$1,483 | |
| | Ceiling - Splined | 1st Floor-Principal's Office | 218 | SF | 6 | \$178 | |
| | Doors - Transom Window | 1st Floor-Principal's Office | 6 | SF | 6 | \$102 | |



Building: Main

| - | | Location | Quantity | l Ini+ | Pank | Cont | Comments |
|---------|--------------------------------------|--|----------|--------|-------|----------------|------------------------------|
| • | Item - Type | | Quantity | Unit | Railk | Cost | Comments |
| Aamini | istrative Suites/Offices | 1at Floor Dringingl's Office | A | EA | 6 | ¢004 | |
| | Doors - Wood Doors inclu hw | 1st Floor-Principal's Office | 1 | | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor-Principal's Office | 218 | SF | 6 | \$218 \$248 | |
| | Lighting - Pendent/Surface | 1st Floor-Principal's Office | 2 | EA | 6 | \$248 | |
| | Power Distribution | 1st Floor-Principal's Office | 4 | EA | 6 | \$8,500 | |
| | Storage/ Closet | 1st Floor-Principal's Office | 20 | SF | 6 | \$145 | |
| | Walls - Concrete Block | 1st Floor-Principal's Office | 590 | SF | 6 | \$1,730 | |
| Lunch a | & Multipurpose Room | | | | | | |
| | Ceiling - Splined | 1st Floor-Gymnasium | 1,560 | SF | 6 | \$1,272 | |
| | Doors - Side-lite | 1st Floor-Gymnasium | 80 | SF | 6 | \$1,337 | |
| | Doors - Transom Window | 1st Floor-Gymnasium | 10 | SF | 6 | \$169 | |
| | Doors - Wood Doors inclu hw | 1st Floor-Gymnasium | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | 1st Floor-Gymnasium | 1,560 | SF | 6 | \$1,562 | |
| | Lighting - Metal Halide/Sodium Vapor | 1st Floor-Gymnasium | 10 | EA | 6 | \$1,337 | |
| | Market Board | 1st Floor-Gymnasium | 6 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor-Gymnasium | 100 | SF | 6 | \$725 | |
| | Walls - Concrete Block | 1st Floor-Gymnasium | 15 | SF | 5 | \$211 | step cracking |
| | Walls - Concrete Block | 1st Floor-Gymnasium | 2,480 | SF | 6 | \$7,270 | |
| Mechar | nical/ Service Rooms | | | | | | |
| | Boiler Room | 1st Floor | 350 | SF | 6 | \$2,508 | |
| | Janitor's Closet | 1st Floor | 38 | SF | 6 | \$272 | |
| | Mechanical/ Service Rooms | 1st Floor | 400 | SF | 6 | \$2,866 | Chiller with exterior access |
| | Mechanical/ Service Rooms | 1st Floor | 250 | SF | 6 | \$1,791 | |
| | Storage Room | 1st Floor | 280 | SF | 6 | \$2,006 | |
| Restroo | om | | | | | | |
| | Accessories | 1st Floor-Counselor's Office 107 Restroom | 28 | SF | 6 | \$258 | |
| | Ceiling - Splined | 1st Floor-Counselor's Office 107 Restroom | 28 | SF | 5 | \$199 | missing all accoustical tile |
| | Doors - Wood Doors inclu hw | 1st Floor-Counselor's Office 107 Restroom | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor-Counselor's Office 107 Restroom | 28 | SF | 6 | \$59 | used as storage |
| | Lighting - Pendent/Surface | 1st Floor-Counselor's Office 107 Restroom | 1 | EA | 6 | \$124 | |
| | Walls - Concrete Block | 1st Floor-Counselor's Office 107 Restroom | 240 | SF | 6 | \$704 | |
| | Accessories | 1st Floor-Men's Restroom | 228 | SF | 6 | \$2,103 | |
| | | | | | | | |



Building: Main

| qı | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|---------------------------------|-------------------------------|----------|------|------|---------|----------|
| trooi | m | | | | | | |
| | Ceiling - Splined | 1st Floor-Men's Restroom | 228 | SF | 6 | \$186 | |
| | Doors - Wood Doors inclu hw | 1st Floor-Men's Restroom | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st Floor-Men's Restroom | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor-Men's Restroom | 228 | SF | 6 | \$483 | |
| | Hand Dryer | 1st Floor-Men's Restroom | 2 | EA | 6 | \$460 | |
| | Lavatory | 1st Floor-Men's Restroom | 5 | EA | 6 | \$1,598 | |
| | Lighting - Pendent/Surface | 1st Floor-Men's Restroom | 2 | EA | 6 | \$248 | |
| | Partitions | 1st Floor-Men's Restroom | 3 | EA | 6 | \$891 | |
| | Urinals | 1st Floor-Men's Restroom | 3 | EA | 6 | \$1,008 | |
| | Walls - Concrete Block | 1st Floor-Men's Restroom | 660 | SF | 6 | \$1,935 | |
| | Water Closet | 1st Floor-Men's Restroom | 3 | EA | 6 | \$1,008 | |
| | Accessories | 1st Floor-Office 102 Restroom | 22 | SF | 6 | \$203 | |
| | Ceiling - Splined | 1st Floor-Office 102 Restroom | 22 | SF | 6 | \$18 | |
| | Doors - Wood Doors inclu hw | 1st Floor-Office 102 Restroom | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor-Office 102 Restroom | 22 | SF | 6 | \$22 | |
| | Lavatory | 1st Floor-Office 102 Restroom | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 1st Floor-Office 102 Restroom | 1 | EA | 6 | \$124 | |
| | Walls - Concrete Block | 1st Floor-Office 102 Restroom | 190 | SF | 6 | \$557 | |
| | Water Closet | 1st Floor-Office 102 Restroom | 1 | EA | 6 | \$336 | |
| | Accessories | 1st Floor-Office 104 | 22 | SF | 6 | \$203 | |
| | Ceiling - Splined | 1st Floor-Office 104 | 22 | SF | 6 | \$18 | |
| | Doors - Wood Doors inclu hw | 1st Floor-Office 104 | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor-Office 104 | 22 | SF | 6 | \$22 | |
| | Lavatory | 1st Floor-Office 104 | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 1st Floor-Office 104 | 1 | EA | 6 | \$124 | |
| | Walls - Concrete Block | 1st Floor-Office 104 | 178 | SF | 6 | \$522 | |
| | Water Closet | 1st Floor-Office 104 | 1 | EA | 6 | \$336 | |
| | Accessories | 1st Floor-Women's Restroom | 230 | SF | 6 | \$2,121 | |
| | Ceiling - Splined | 1st Floor-Women's Restroom | 230 | SF | 6 | \$187 | |
| | Doors - Wood Doors inclu hw | 1st Floor-Women's Restroom | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st Floor-Women's Restroom | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor-Women's Restroom | 230 | SF | 6 | \$487 | |
| | Hand Dryer | 1st Floor-Women's Restroom | 2 | EA | 6 | \$460 | |
| | Lavatory | 1st Floor-Women's Restroom | 5 | EA | 6 | \$1,598 | |
| | Lighting - Pendent/Surface | 1st Floor-Women's Restroom | 2 | EA | 6 | \$248 | |
| | Partitions | 1st Floor-Women's Restroom | 5 | EA | 6 | \$1,485 | |
| | Walls - Concrete Block | 1st Floor-Women's Restroom | 645 | SF | 6 | \$1,891 | |



\$748,846

Building: Main

Category: Rooms (Other Than Classrooms)

| Group Item - Type | Location | Quantity | Unit | Rank | Cost Comments |
|--|----------------------------|----------|------|------|---------------|
| Restroom | | | | | |
| Water Closet | 1st Floor-Women's Restroom | 5 | EA | 6 | \$1,680 |
| ooms (Other Than Classrooms) Subtotal: | | | | | \$153,194 |

Building: Main

Category: Building Interior

| · | oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-------|--------------------------------------|-----------------|----------|------|------|---------|---|
| Dors - Store Front1st Floor2EA6\$2,416Drinking Fountains - Single Fountain1st Floor2EA6\$551Floor - Tile/Sheet1st Floor1,620SF6\$880Lighting - Pendent/Surface1st Floor30EA6\$3,717Walls - Concrete Block1st Floor2,985SF6\$8,751Walls - Masonry1st Floor780SF6\$2,454Walls - Vinyl Coated Gypsum Panel1st Floor330SF6\$911etyCamera Viewing StationEntire Building2EA6\$1,365Security CamerasEntire Building4EA6\$776 | rrido | · | | | | | | |
| Drinking Fountains - Single Fountain1st Floor2EA6\$551Floor - Tile/Sheet1st Floor1,620SF6\$880Lighting - Pendent/Surface1st Floor30EA6\$3,717Walls - Concrete Block1st Floor2,985SF6\$8,751Walls - Masonry1st Floor780SF6\$2,454Walls - Vinyl Coated Gypsum Panel1st Floor330SF6\$911etyCamera Viewing StationSecurity CamerasEntire Building2EA6\$1,365Location: Main Entrance Security Station Principal's Office/Main Office | | Ceiling - Splined | 1st Floor | 1,620 | SF | 6 | \$4,680 | |
| Floor - Tile/Sheet1st Floor1,620SF6\$880Lighting - Pendent/Surface1st Floor30EA6\$3,717Walls - Concrete Block1st Floor2,985SF6\$8,751Walls - Masonry1st Floor780SF6\$2,454Walls - Vinyl Coated Gypsum Panel1st Floor330SF6\$911terter Building2EA6\$1,365Location: Main Entrance Security Station Principal's Office/Main OfficeSecurity CamerasEntire Building4EA6\$776 | | Doors - Store Front | 1st Floor | 2 | EA | 6 | \$2,416 | |
| Lighting - Pendent/Surface1st Floor30EA6\$3,717Walls - Concrete Block1st Floor2,985SF6\$8,751Walls - Masonry1st Floor780SF6\$2,454Walls - Vinyl Coated Gypsum Panel1st Floor300SF6\$911etyCamera Viewing StationEntire Building2EA6\$1,365Location: Main Entrance Security Station Principal's Office/Main OfficeSecurity CamerasEntire Building4EA6\$776 | | Drinking Fountains - Single Fountain | 1st Floor | 2 | EA | 6 | \$551 | |
| Walls - Concrete Block1st Floor2,985SF6\$8,751Walls - Masonry1st Floor780SF6\$2,454Walls - Vinyl Coated Gypsum Panel1st Floor330SF6\$911etyCamera Viewing StationEntire Building2EA6\$1,365Location: Main Entrance Security Station Principal's Office/Main OfficeSecurity CamerasEntire Building4EA6\$776 | | Floor - Tile/Sheet | 1st Floor | 1,620 | SF | 6 | \$880 | |
| Walls - Masonry 1st Floor 780 SF 6 \$2,454 Walls - Vinyl Coated Gypsum Panel 1st Floor 330 SF 6 \$911 wood panels ety Camera Viewing Station Entire Building 2 EA 6 \$1,365 Location: Main Entrance Security Station Principal's Office/Main Office Security Cameras Entire Building 4 EA 6 \$776 | | Lighting - Pendent/Surface | 1st Floor | 30 | EA | 6 | \$3,717 | |
| Walls - Vinyl Coated Gypsum Panel 1st Floor 330 SF 6 \$911 wood panels ety Entire Building 2 EA 6 \$1,365 Location: Main Entrance Security Station Principal's Office/Main Office Security Cameras Entire Building 4 EA 6 \$776 | | Walls - Concrete Block | 1st Floor | 2,985 | SF | 6 | \$8,751 | |
| ety Camera Viewing Station Entire Building 2 EA 6 \$1,365 Location: Main Entrance Security Station Principal's Office/Main Office Security Cameras Entire Building 4 EA 6 \$776 | | Walls - Masonry | 1st Floor | 780 | SF | 6 | \$2,454 | |
| Camera Viewing Station Entire Building 2 EA 6 \$1,365 Location: Main Entrance Security Station Principal's Office/Main Office Security Cameras Entire Building 4 EA 6 \$776 | | Walls - Vinyl Coated Gypsum Panel | 1st Floor | 330 | SF | 6 | \$911 | wood panels |
| Principal's Office/Main Office Security Cameras Entire Building 4 EA 6 \$776 | ety | | | | | | | |
| | | Camera Viewing Station | Entire Building | 2 | EA | 6 | \$1,365 | Location: Main Entrance Security Station, Principal's Office/Main Office |
| Security Cameras Entire Building 4 EA 6 \$776 | | Security Cameras | Entire Building | 4 | EA | 6 | \$776 | |
| | | Security Cameras | Entire Building | 4 | EA | 6 | \$776 | |

Total Building Cost

Building: 4-Classroom Modular

Category: Building Exterior

| Location | Quantity Unit Rank | Cost Comments |
|-----------------|-----------------------------------|--|
| | | |
| #15-E | 2 EA 6 | \$961 |
| #16-W | 2 EA 6 | \$961 |
| | | |
| Entire Building | 280 LF 7 | \$0 |
| Entire Building | 4,832 SF 7 | \$0 |
| | #15-E #16-W Entire Building | #15-E 2 EA 6 #16-W 2 EA 6 Entire Building 280 LF 7 |



Building: 4-Classroom Modular

| Category: Building Exterior |
|-----------------------------|
|-----------------------------|

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---|-----------------|----------|------|------|----------|----------|
| Founda | tion | | | | | | |
| Lighting | 0 | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 8 | EA | 6 | \$2,310 | |
| Roof Sy | /stem | | | | | | |
| | Downspouts - Exterior Downspouts | Main Roof | 192 | LF | 6 | \$6,381 | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Main Roof | 4,852 | SF | 7 | \$0 | |
| | Roof - EPDM/ Synthetic Rubber | Main Roof | 200 | SF | 5 | \$5,225 | |
| | Roof - EPDM/ Synthetic Rubber | Main Roof | 4,652 | SF | 6 | \$39,382 | |
| Walls | | | | | | | |
| | Exterior Walls - Hardie Board | Entire Building | 3,378 | SF | 6 | \$0 | |
| Windov | vs | | | | | | |
| | Guard - Guards perforated | Entire Building | 288 | SF | 6 | \$3,678 | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 288 | SF | 6 | \$2,150 | |
| Buildi | ng Exterior Subtotal: | | | | | \$61,048 | |

Building Exterior Subtotal:

Building: 4-Classroom Modular

Category: Electrical System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|------------------------------|----------|------|------|---------|--|
| Emergency System | | | | | | |
| Emergency Battery Packs - Corridors and Stairs | Entire Building | 4 | EA | 6 | \$810 | |
| Emergency Battery Packs | Entire Building | 4 | | 6 | \$0 | One in each classroom |
| Exit Signs - Corridors and Stairs | Entire Building | 2 | EA | 6 | \$299 | |
| Exit Signs | Entire Building | 4 | | 6 | \$0 | One Exit sign in each of four classrooms |
| Main Service | | | | | | |
| Main Electrical Service - 800 A and 120/240/3PH | Entire Building / Site South | 1 | EA | 6 | \$3,570 | |
| Power Distribution | | | | | | |
| Lighting and Power Panels - Above 100 A | Entire Building | 2 | EA | 7 | \$0 | |
| Electrical System Subtotal: | | | | | \$4,680 | |
| Building: 4-Classroom Modular | | | | | | |
| Category: Safty System | | | | | | |
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| | | | | | | |



Building: 4-Classroom Modular

| Bulluling. +-Classicolli Mouulai | | | | | | |
|---|-----------------|----------|------|------|----------|--|
| Category: Safty System | | | | | | |
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Fire Alarm | | | | | | |
| Fire Alarm_System | Entire Building | 4,832 | SF | 4 | \$9,605 | no alarm panel and no strobe lights servicing the building |
| Sprinkler System | | | | | | |
| Sprinkler Heads | Entire Building | 4,832 | SF | 7 | \$0 | |
| Sprinkler Piping | Entire Building | 4,832 | SF | 6 | \$898 | |
| Wet Sprinkler System | Entire Building | 4,832 | SF | 6 | \$1,244 | |
| Safty System Subtotal: | | | | | \$11,747 | |
| Building: 4-Classroom Modular | | | | | | |
| Category: Mechanical System | | | | | | |
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Temperature Control | | | | | | |
| Electric Thermostat | Entire Building | 4 | EA | 6 | \$0 | |
| Unit Ventilation | | | | | | |
| Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling | Entire Building | 4 | EA | 6 | \$0 | |
| Ventilation | | | | | | |
| Exhaust Fans- Roof Mounted - Less than 500 CFM | Roof | 5 | EA | 6 | \$1,481 | |
| Mechanical System Subtotal: | | | | | \$1,481 | |
| Building: 4-Classroom Modular | | | | | | |
| Category: Plumbing System | | | | | | |
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Hot Water | | | | | | |
| Electric Heater - Less than 20 KW | Entire Building | 1 | EA | 6 | \$682 | |
| Piping | | | | | | |
| Domestic Bining Cold Water Herizontal Linco | Entire Duilding | 4 822 | СГ | 6 | ¢4 475 | |

| Domestic Piping-Cold Water Horizontal Lines | Entire Building | 4,832 | SF | 6 | \$1,175 |
|---|---|---|---|---|---|
| Domestic Piping-Hot Water Horizontal Lines | Entire Building | 4,832 | SF | 6 | \$898 |
| Domestic Piping-Hot Water Return Lines | Entire Building | 4,832 | SF | 6 | \$691 |
| Sanitary Piping | Entire Building | 4,832 | SF | 6 | \$4,422 |
| Storm Piping | Entire Building | 4,832 | SF | 6 | \$4,215 |
| Vent Piping | Entire Building | 4,832 | SF | 6 | \$3,248 |
| | Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Return Lines Sanitary Piping Storm Piping | Domestic Piping-Hot Water Horizontal LinesEntire BuildingDomestic Piping-Hot Water Return LinesEntire BuildingSanitary PipingEntire BuildingStorm PipingEntire Building | Domestic Piping-Hot Water Horizontal LinesEntire Building4,832Domestic Piping-Hot Water Return LinesEntire Building4,832Sanitary PipingEntire Building4,832Storm PipingEntire Building4,832 | Domestic Piping-Hot Water Horizontal LinesEntire Building4,832SFDomestic Piping-Hot Water Return LinesEntire Building4,832SFSanitary PipingEntire Building4,832SFStorm PipingEntire Building4,832SF | Domestic Piping-Hot Water Horizontal LinesEntire Building4,832SF6Domestic Piping-Hot Water Return LinesEntire Building4,832SF6Sanitary PipingEntire Building4,832SF6Storm PipingEntire Building4,832SF6 |



Building: 4-Classroom Modular

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------------------------------------|-----------|----------|------|------|----------|--------------------|
| Plumbing System Subtotal: | | | | | \$15,331 | |
| Building: 4-Classroom Modular | | | | | | |
| Category: Classrooms | | | | | | |
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Classroom #201 (Regular Classroom) | | | | | | |
| Ceiling - Lay-in | 1st Floor | 810 | SF | 6 | \$2,432 | Tile discoloration |
| Chalk Board | 1st Floor | 12 | LF | 4 | \$1,102 | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile | 1st Floor | 810 | SF | 6 | \$1,772 | |
| Lighting - Lay-in | 1st Floor | 16 | EA | 6 | \$1,904 | |
| Marker Board | 1st Floor | 11 | LF | 7 | \$0 | |
| Storage/ Closet | 1st Floor | 75 | SF | 6 | \$544 | |
| Student Lockers - Two Tiers | 1st Floor | 36 | EA | 6 | \$1,671 | |
| Walls - Vinyl Coated Gypsum Panel | 1st Floor | 852 | SF | 6 | \$2,351 | |
| Classroom #202 (Regular Classroom) | | | | | | |
| Ceiling - Lay-in | 1st Floor | 810 | SF | 6 | \$2,432 | Tile discoloration |
| Chalk Board | 1st Floor | 12 | LF | 4 | \$1,102 | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile | 1st Floor | 810 | SF | 6 | \$1,772 | |
| Lighting - Lay-in | 1st Floor | 16 | EA | 6 | \$1,904 | |
| Marker Board | 1st Floor | 11 | LF | 7 | \$0 | |
| Storage/ Closet | 1st Floor | 75 | SF | 6 | \$544 | |
| Student Lockers - Two Tiers | 1st Floor | 36 | EA | 6 | \$1,671 | |
| Walls - Vinyl Coated Gypsum Panel | 1st Floor | 852 | SF | 6 | \$2,351 | |
| Classroom #203 (Regular Classroom) | | | | | | |
| Ceiling - Lay-in | 1st Floor | 810 | SF | 6 | \$2,432 | Tile discoloration |
| Chalk Board | 1st Floor | 4 | LF | 4 | \$367 | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile | 1st Floor | 810 | SF | 6 | \$1,772 | |
| Lighting - Lay-in | 1st Floor | 16 | EA | 6 | \$1,904 | |
| Marker Board | 1st Floor | 20 | LF | 7 | \$0 | |
| Storage/ Closet | 1st Floor | 75 | SF | 6 | \$544 | |
| Student Lockers - Two Tiers | 1st Floor | 36 | EA | 6 | \$1,671 | |
| Walls - Vinyl Coated Gypsum Panel | 1st Floor | 852 | SF | 6 | \$2,351 | |



Building: 4-Classroom Modular

Category: Classrooms

| oup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------------|-----------|----------|------|------|-----------------------------|--------------------|
| assroom #204 (Regular Classroom) | | | | | | |
| Ceiling - Lay-in | 1st Floor | 810 | SF | 6 | \$2,432 | Tile discoloration |
| Chalk Board | 1st Floor | 12 | LF | 4 | \$1,102 | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile | 1st Floor | 810 | SF | 6 | \$1,772 | |
| Lighting - Lay-in | 1st Floor | 16 | EA | 6 | \$1,904 | |
| Marker Board | 1st Floor | 11 | LF | 7 | \$0 | |
| Student Lockers - Two Tiers | 1st Floor | 36 | EA | 6 | \$1,671 | |
| Walls - Vinyl Coated Gypsum Panel | 1st Floor | 852 | SF | 6 | \$2,351 | |
| | | | | | • · - • • • • | |

Classrooms Subtotal:

\$47,030

Building: 4-Classroom Modular

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------------|--------------------------|----------|------|------|---------|----------|
| Restroc | m | | | | | | |
| | Accessories | 1st floor-Boy's restroom | 150 | SF | 6 | \$1,384 | |
| | Ceiling - Splined | 1st floor-Boy's restroom | 150 | SF | 6 | \$122 | |
| | Doors - Wood Doors inclu hw | 1st floor-Boy's restroom | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st floor-Boy's restroom | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile/Sheet | 1st floor-Boy's restroom | 150 | SF | 6 | \$150 | |
| | Hand Dryer | 1st floor-Boy's restroom | 1 | EA | 6 | \$230 | |
| | Lavatory | 1st floor-Boy's restroom | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | 1st floor-Boy's restroom | 2 | EA | 6 | \$248 | |
| | Partitions | 1st floor-Boy's restroom | 2 | EA | 6 | \$594 | |
| | Urinals | 1st floor-Boy's restroom | 2 | EA | 6 | \$672 | |
| | Walls - Vinyl Coated Gypsum Panel | 1st floor-Boy's restroom | 466 | SF | 6 | \$1,286 | |
| | Water Closet | 1st floor-Boy's restroom | 2 | EA | 6 | \$672 | |
| | Accessories | 1st floor-Girl's Room | 150 | SF | 6 | \$1,384 | |
| | Ceiling - Splined | 1st floor-Girl's Room | 150 | SF | 6 | \$122 | |
| | Doors - Wood Doors inclu hw | 1st floor-Girl's Room | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st floor-Girl's Room | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile/Sheet | 1st floor-Girl's Room | 150 | SF | 6 | \$150 | |
| | Hand Dryer | 1st floor-Girl's Room | 1 | EA | 6 | \$230 | |
| | Lavatory | 1st floor-Girl's Room | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | 1st floor-Girl's Room | 2 | EA | 6 | \$248 | |
| | Partitions | 1st floor-Girl's Room | 4 | EA | 6 | \$1,188 | |
| | Walls - Vinyl Coated Gypsum Panel | 1st floor-Girl's Room | 466 | SF | 6 | \$1,286 | |



Building: 4-Classroom Modular

| Building: 4-Classroom Modular | | | | | | |
|---|--|------------------|----------------------------|-------------------------|--|----------|
| Category: Rooms (Other Than Classrooms) | | | | | | |
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Restroom | | | | | | |
| Water Closet | 1st floor-Girl's Room | 4 | EA | 6 | \$1,344 | |
| Rooms (Other Than Classrooms) Subtotal: | | | | | \$15,308 | |
| Building: 4-Classroom Modular | | | | | | |
| Category: Building Interior | | | | | | |
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Corridor | | | | | | |
| Ceiling - Splined | 1st Floor | 430 | SF | 6 | \$1,242 | |
| Doors - Steel Doors incl hw | 1st Floor | 4 | EA | 6 | \$1,204 | |
| Drinking Fountains - Double Fountain | 1st Floor | 1 | EA | 6 | \$336 | |
| Floor - Tile/Sheet | 1st Floor | 430 | SF | 6 | \$234 | |
| Lighting - Lay-in | 1st Floor | 5 | EA | 6 | \$595 | |
| Walls - Vinyl Coated Gypsum Panel | 1st Floor | 950 | SF | 6 | \$2,622 | |
| Safety | | | | | | |
| Security Cameras | Entire Building / West Entrances | 1 | EA | 6 | \$194 | |
| | | | | | | |
| Building Interior Subtotal: | | | | | \$6,427 | |
| Building Interior Subtotal: Total Building Cost | | | | | \$6,427 \$163,050 | |
| | | | | | | |
| Total Building Cost Building: Addition | | | | | | |
| Total Building Cost Building: Addition Category: Building Exterior | Location | Quantity | Unit | | \$163,050 | Comments |
| Total Building Cost Building: Addition | Location | Quantity | Unit | | \$163,050 | Comments |
| Total Building Cost Building: Addition Category: Building Exterior Group Item - Type | Location #14-E | Quantity | Unit | | \$163,050 | Comments |
| Total Building Cost Building: Addition Category: Building Exterior Group Item - Type Entrance | | | | Rank | \$163,050 Cost | Comments |
| Total Building Cost Building: Addition Category: Building Exterior Group Item - Type Entrance Exterior Doors - Exterior FRP Door | #14-E | 1 | EA | Rank | \$163,050 Cost \$631 | Comments |
| Total Building Cost Building: Addition Category: Building Exterior Group Item - Type Entrance Exterior Doors - Exterior FRP Door Exterior Doors - Exterior Steel Door | #14-E #9-W | 1 | EA EA | Rank 6 6 | \$163,050 Cost \$631 \$961 | Comments |
| Total Building Cost Building: Addition Category: Building Exterior Group Item - Type Entrance Exterior Doors - Exterior FRP Door Exterior Doors - Exterior Steel Door Exterior Doors - Side lite | #14-E #9-W #1-Main E | 1 2 6 | EA EA EA | Rank 6 6 6 | \$163,050 Cost \$631 \$961 \$1,880 | Comments |
| Total Building Cost Building: Addition Category: Building Exterior Group Item - Type Entrance Exterior Doors - Exterior FRP Door Exterior Doors - Exterior Steel Door Exterior Doors - Side lite Exterior Doors - Store Front | #14-E #9-W #1-Main E #1-Main E | 1 2 6 2 | EA EA EA EA | Rank 6 6 6 6 6 | \$163,050 Cost \$631 \$961 \$1,880 \$1,092 | Comments |
| Total Building Cost Building: Addition Category: Building Exterior Group Item - Type Entrance Exterior Doors - Exterior FRP Door Exterior Doors - Exterior Steel Door Exterior Doors - Side lite Exterior Doors - Store Front Exterior Doors - Transom Lite | #14-E #9-W #1-Main E #1-Main E #14-E | 1 2 6 2 | EA EA EA EA EA | Rank 6 6 6 6 6 6 | \$163,050 Cost \$631 \$961 \$1,880 \$1,092 \$313 | Comments |

Foundation

Foundation - Concrete

244 LF

7

\$0

Entire Building



Building: Addition

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|---------------------------------|----------|------|------|-----------|----------|
| Founda | ation | | | | | | |
| | Superstructure - Concrete | Entire Building | 6,847 | SF | 7 | \$0 | |
| Lightin | a | | | | | | |
| Lightin | Exterior Lighting - Wall Mounted | Entire Building | 6 | EA | 5 | \$2,564 | |
| | | Entre Building | 0 | LA | 0 | ψ2,004 | |
| Roof S | ystem | | | | | | |
| | Coping - Metal | Main Roof | 244 | LF | 6 | \$7,837 | |
| | Downspouts - Interior Downspouts | Main Roof | 24 | LF | 6 | \$798 | |
| | Roof Structure - Concrete | Main Roof | 6,847 | SF | 7 | \$0 | |
| | Roof - Modified Bitumen | Main Roof | 6,547 | SF | 6 | \$61,603 | |
| | Roof - Modified Bitumen | Main Roof | 300 | SF | 5 | \$8,567 | |
| Walls | | | | | | | |
| | Canopy - Concrete/ Stucco | Entire Building | 775 | SF | 6 | \$25,645 | |
| | Exterior Walls - Brick | Entire Building | 1,894 | SF | 6 | \$12,730 | |
| | Exterior Walls - Brick | Entire Building / Main Entrance | 2 | SF | 6 | \$18 | |
| Windov | vs | | | | | | |
| | Curtain wall - Glazed Double Pane | Entire Building | 432 | SF | 6 | \$4,843 | |
| | Curtain wall - Louver | Entire Building | 15 | SF | 6 | \$168 | |
| | Guard - Guards perforated | Entire Building | 432 | SF | 6 | \$5,517 | |
| | Lintels - Concrete | Entire Building | 64 | LF | 6 | \$0 | |
| | Windows - Casement Aluminum Double-pane | Entire Building | 432 | SF | 6 | \$3,225 | |
| 3uildi | ing Exterior Subtotal: | | | | | \$139,045 | |
| | 5 | | | | | ,, . | |
| Buildi | ing: Addition | | | | | | |
| | ory: Electrical System | | | | | | |
| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Emerge | ency System | | | | | | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 5 | EA | 6 | \$1,013 | |
| | Exit Signs - Corridors and Stairs | Entire Building | 4 | EA | 6 | \$599 | |
| | | 5 | | | | | |
| Dowor | | | | | 0 | ¢407 | LR-2 |
| Power | Linkfing and Device Device Above 100.4 | Easting Dividelity - | | | | \$707 | 18-2 |
| Power | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 6 | ψ+97 | |

Building: Addition



Category: Safty System

| Group Item - Type | Location | Quantity Unit | Rank | Cost Comments | |
|--------------------------|-----------------|---------------|------|---------------|--|
| Fire Alarm | | | | | |
| Fire Alarm Strobe Lights | Entire Building | 6,846 SF | 6 | \$2,447 | |
| Fire Alarm_System | Entire Building | 6,846 SF | 6 | \$3,329 | |
| Safty System Subtotal: | | | | \$5,776 | |

Building: Addition

Category: Mechanical System

| Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|--|--|---|--|--|
| | | | | | |
| Entire Building | 2 | EA | 6 | \$709 | |
| | | | | | |
| Entire Building | 220 | LF | 6 | \$16,891 | served from main building boilers |
| | | | | | |
| Entire Building | 6,847 | SF | 6 | \$3,916 | served from main building |
| | | | | | |
| Entire Building | 4 | EA | 6 | \$4,991 | |
| | | | | | |
| Roof | 1 | EA | 6 | \$592 | |
| Roof | 1 | EA | 6 | \$296 | |
| | | | | \$27.395 | |
| | Entire Building Entire Building Entire Building Entire Building Entire Building Roof | Entire Building 2 Entire Building 220 Entire Building 6,847 Entire Building 4 Roof 1 | Entire Building2EAEntire Building220LFEntire Building6,847SFEntire Building4EARoof1EA | Entire Building2EA6Entire Building220LF6Entire Building6,847SF6Entire Building4EA6Roof1EA6 | Entire Building2EA6\$709Entire Building220LF6\$16,891Entire Building6,847SF6\$3,916Entire Building4EA6\$4,991Roof1EA6\$592 |

Building: Addition

Category: Plumbing System

| ıp Item - Type | Location | Quantity | Unit | Rank | Cost Comments | |
|---|-----------------|----------|------|------|---------------|--|
| ng | | | | | | |
| Domestic Piping-Cold Water Horizontal Lines | Entire Building | 6,847 | SF | 6 | \$1,665 | |
| Domestic Piping-Hot Water Horizontal Lines | Entire Building | 6,847 | SF | 6 | \$1,273 | |
| Domestic Piping-Hot Water Return Lines | Entire Building | 6,847 | SF | 6 | \$979 | |
| Sanitary Piping | Entire Building | 6,847 | SF | 6 | \$6,266 | |
| Storm Piping | Entire Building | 6,847 | SF | 6 | \$5,973 | |
| Vent Piping | Entire Building | 6,847 | SF | 6 | \$4,602 | |

Plumbing System Subtotal:

\$20,757

Building: Addition

Category: Classrooms

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------------------------------------|-----------|----------|------|------|----------|---------------------|
| Classroom #111 (Special Education) | | | | | | |
| Casework | 1st Floor | 42 | LF | 6 | \$1,061 | |
| Ceiling - Lay-in | 1st Floor | 660 | SF | 6 | \$1,982 | |
| Ceiling - Lay-in | 1st Floor | 10 | SF | 5 | \$80 | water discoloration |
| Ceiling - Plaster/Drywall | 1st Floor | 80 | SF | 6 | \$277 | |
| Doors - Side-lite | 1st Floor | 8 | SF | 6 | \$134 | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile/Sheet | 1st Floor | 750 | SF | 6 | \$751 | |
| Lighting - Pendent/Surface | 1st Floor | 20 | EA | 6 | \$2,478 | |
| Marker Board | 1st Floor | 20 | LF | 7 | \$0 | |
| Walls - Concrete Block | 1st Floor | 788 | SF | 6 | \$2,310 | |
| Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classroom #112 (Regular Classroom) | | | | | | |
| Casework | 1st Floor | 42 | LF | 6 | \$1,061 | |
| Ceiling - Plaster/Drywall | 1st Floor | 80 | SF | 6 | \$277 | |
| Ceiling - Splined | 1st Floor | 670 | SF | 6 | \$546 | |
| Doors - Side-lite | 1st Floor | 8 | SF | 6 | \$134 | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile/Sheet | 1st Floor | 750 | SF | 6 | \$751 | |
| Lighting - Pendent/Surface | 1st Floor | 20 | EA | 6 | \$2,478 | |
| Marker Board | 1st Floor | 8 | LF | 7 | \$0 | |
| Walls - Concrete Block | 1st Floor | 788 | SF | 6 | \$2,310 | |
| Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classroom #114 (Pre School) | | | | | | |
| Casework | 1st Floor | 42 | LF | 6 | \$1,061 | |
| Ceiling - Lay-in | 1st Floor | 670 | SF | 6 | \$2,012 | |
| Ceiling - Plaster/Drywall | 1st Floor | 80 | SF | 6 | \$277 | |
| Doors - Side-lite | 1st Floor | 8 | SF | 6 | \$134 | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile/Sheet | 1st Floor | 750 | SF | 6 | \$751 | |
| Lighting - Pendent/Surface | 1st Floor | 20 | EA | 6 | \$2,478 | |
| Marker Board | 1st Floor | 10 | LF | 7 | \$0 | |
| Walls - Concrete Block | 1st Floor | 788 | SF | 6 | \$2,310 | |
| Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classrooms Subtotal: | | | | | \$27 690 | |

Classrooms Subtotal:

\$27,690



Building: Addition

| Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------------------------------|---|----------|------|------|---------|------------------------------------|
| & Multipurpose Room | | | | | | |
| Ceiling - Lay-in | 1st Floor-Food Service/Teacher's Lounge | 1,245 | SF | 6 | \$3,739 | |
| Doors - Side-lite | 1st Floor-Food Service/Teacher's Lounge | 15 | SF | 6 | \$251 | |
| Doors - Wood Doors inclu hw | 1st Floor-Food Service/Teacher's Lounge | 1 | EA | 6 | \$301 | |
| Floor - Tile/Sheet | 1st Floor-Food Service/Teacher's Lounge | 1,245 | SF | 6 | \$1,246 | |
| Lighting - Pendent/Surface | 1st Floor-Food Service/Teacher's Lounge | 24 | EA | 6 | \$2,973 | |
| Market Board | 1st Floor-Food Service/Teacher's Lounge | 10 | LF | 7 | \$0 | |
| Storage/ Closet | 1st Floor-Food Service/Teacher's Lounge | 32 | SF | 5 | \$516 | step cracking, water discoloration |
| Walls - Concrete Block | 1st Floor-Food Service/Teacher's Lounge | 940 | SF | 6 | \$2,756 | |
| Walls - Concrete Block | 1st Floor-Food Service/Teacher's Lounge | 5 | SF | 5 | \$70 | step cracking |
| Walls - Masonry | 1st Floor-Food Service/Teacher's Lounge | 152 | SF | 6 | \$478 | |
| nical/ Service Rooms | | | | | | |
| Janitor's Closet | 1st Floor | 30 | SF | 6 | \$215 | |
| Storage Room | 1st Floor | 465 | SF | 7 | \$0 | |
| oom | | | | | | |
| Accessories | 1st Floor | 130 | SF | 6 | \$1,199 | |
| Accessories | 1st Floor | 145 | SF | 6 | \$1,337 | |
| Ceiling - Lay-in | 1st Floor | 145 | SF | 6 | \$435 | |
| Ceiling - Lay-in | 1st Floor | 130 | SF | 6 | \$390 | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor Drain | 1st Floor | 1 | EA | 6 | \$1,059 | |
| Floor Drain | 1st Floor | 1 | EA | 6 | \$1,059 | |
| Floor - Tile Ceramic/ Porcelain | 1st Floor | 145 | SF | 6 | \$307 | |
| Floor - Tile Ceramic/ Porcelain | 1st Floor | 130 | SF | 6 | \$275 | |
| Hand Dryer | 1st Floor | 1 | EA | 6 | \$230 | |
| Hand Dryer | 1st Floor | 1 | EA | 6 | \$230 | |
| Lavatory | 1st Floor | 2 | EA | 6 | \$639 | |
| Lavatory | 1st Floor | 2 | EA | 6 | \$639 | |
| Lighting - Pendent/Surface | 1st Floor | 2 | EA | 6 | \$248 | |
| Lighting - Pendent/Surface | 1st Floor | 2 | EA | 6 | \$248 | |
| Partitions | 1st Floor | 2 | EA | 6 | \$594 | |
| Partitions | 1st Floor | 2 | EA | 6 | \$594 | |
| Urinals | 1st Floor | 2 | EA | 6 | \$672 | |
| Walls - Concrete Block | 1st Floor | 180 | SF | 6 | \$528 | |
| Walls - Concrete Block | 1st Floor | 210 | SF | 6 | \$616 | |
| Walls - Structural Glazed Tile | 1st Floor | 290 | SF | 6 | \$912 | |



Building: Addition

Category: Rooms (Other Than Classrooms)

| Group Item - Type | Location | Quantity | Unit | Rank | Cost Comments | |
|---|-----------|----------|------|------|---------------|--|
| Restroom | | | | | | |
| Walls - Structural Glazed Tile | 1st Floor | 290 | SF | 6 | \$912 | |
| Water Closet | 1st Floor | 1 | EA | 6 | \$336 | |
| Water Closet | 1st Floor | 2 | EA | 6 | \$672 | |
| Rooms (Other Than Classrooms) Subtotal: | | | | | \$27,280 | |

Building: Addition

Category: Building Interior

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------------|-------------------------------------|-------------|------|------|-----------|----------|
| Corridor | | | | | | |
| Ceiling - Lay-in | 1st Floor | 430 | SF | 6 | \$1,291 | |
| Doors - Steel Doors incl hw | 1st Floor | 4 | EA | 6 | \$1,204 | |
| Drinking Fountains - Double Fountain | 1st Floor | 2 | EA | 6 | \$672 | |
| Floor - Tile/Sheet | 1st Floor | 430 | SF | 6 | \$234 | |
| Lighting - Lay-in | 1st Floor | 5 | EA | 6 | 6 \$595 | |
| Walls - Vinyl Coated Gypsum Panel | 1st Floor | 950 | SF | 6 | \$2,622 | |
| Ceiling - Lay-in | 1st Floor | | SF | 6 | \$2,793 | |
| Ceiling - Plaster/Drywall | 1st Floor | | SF | 6 | \$731 | |
| Doors - Store Front | 1st Floor | 2 | EA | 6 | \$2,416 | |
| Drinking Fountains - Single Fountain | 1st Floor 1st Floor 1st Floor | 1 | EA | 6 | 6 \$276 | |
| Floor - Tile/Sheet | | 1,048 22 | SF | 6 | \$569 | |
| Lighting - Pendent/Surface | | | EA | 6 | 6 \$2,726 | |
| Walls - Concrete Block | 1st Floor | 590 | SF | 6 | \$1,730 | |
| Walls - Masonry | 1st Floor | 616 | SF | 6 | \$1,938 | |
| Walls - Plaster/Drywall | 1st Floor | 220 | SF | 6 | \$975 | |
| Walls - Structural Glazed Tile | 1st Floor | 840 | SF | 6 | \$2,643 | |
| afety | | | | | | |
| Security Cameras | Entire Building | 2 | EA | 6 | \$388 | |
| Security Cameras | Entire Building | 2 | EA | 6 | \$388 | |
| Building Interior Subtotal: | | | | | \$24,190 | |
| otal Building Cost | | | | | \$274,241 | |

Building: Linked Addition



Category: Building Exterior

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------|----------|------|------|----------|----------|
| Entrance | | | | | | |
| Exterior Doors - Exterior Steel Door | #11-S | 2 | EA | 6 | \$961 | |
| Exterior Doors - Exterior Steel Door | #12-E | 1 | EA | 6 | \$481 | |
| Exterior Doors - Store Front | #10-Link W | 2 | EA | 6 | \$1,092 | |
| Exterior Doors - Store Front | #13-Link E | 2 | EA | 6 | \$1,092 | |
| Exterior Doors - Transom Lite | #10-Link W | 2 | EA | 6 | \$627 | |
| Exterior Doors - Transom Lite | #13-Link E | 2 | EA | 6 | \$627 | |
| oundation | | | | | | |
| Foundation - Concrete | Entire Building | 570 | LF | 7 | \$0 | |
| Superstructure - Steel | Entire Building | 15,130 | SF | 7 | \$0 | |
| ighting | | | | | | |
| Exterior Lighting - Wall Mounted | Entire Building | 6 | EA | 5 | \$2,564 | |
| Roof System | | | | | | |
| Coping - Metal | Main Roof | 554 | LF | 6 | \$17,793 | |
| Coping - Metal | Link Roof | 15 | LF | 6 | \$482 | |
| Downspouts - Exterior Downspouts | Main Roof | 284 | LF | 6 | \$9,438 | |
| Downspouts - Interior Downspouts | Link Roof | 13 | LF | 6 | \$432 | |
| Parapet - 16" - 30" Height | Link Roof | 15 | LF | 6 | \$599 | |
| Roof Structure - Steel / Metal Deck/ Concrete Topping | Main Roof | 15,130 | SF | 7 | \$0 | |
| Roof Structure - Steel / Metal Deck/ Concrete Topping | Link Roof | 440 | SF | 7 | \$0 | |
| Roof - Metal | Main Roof | 19,669 | SF | 7 | \$0 | |
| Roof - Modified Bitumen | Link Roof | 440 | SF | 6 | \$4,140 | |
| Valls | | | | | | |
| Canopy - Metal | Entire Building | 21 | SF | 6 | \$451 | |
| Cornice - Metal Projecting | Entire Building | 1,140 | LF | 6 | \$39,532 | |
| Exterior Walls - Brick | Entire Building | 5,692 | SF | 6 | \$38,256 | |
| Exterior Walls - Stone-Cut | Entire Building | 217 | SF | 6 | \$1,458 | |
| Vindows | | | | | | |
| Curtain wall - Glazed Double Pane | Entire Building | 168 | SF | 6 | \$1,883 | |
| Curtain wall - Louver | Entire Building | 88 | SF | 6 | \$987 | |
| Guard - Guards perforated | Entire Building | 1,550 | SF | 6 | \$19,793 | |
| Lintels - Steel | Entire Building | 217 | LF | 6 | \$6,299 | |
| Windows - Sash Aluminum Double-pane | Entire Building | 1,550 | SF | 6 | \$11,570 | |

Building: Linked Addition



Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|-----------------------------------|----------|------|------|---------|--|
| Emerge | ncy System | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 1 | EA | 6 | \$408 | sourced through additional ComEd meter |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 2,220 | SF | 6 | \$667 | |
| | Emergency A/C Power - Students Toilets | Entire Building | 1,150 | SF | 6 | \$428 | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 7 | EA | 6 | \$1,418 | |
| | Exit Signs - Corridors and Stairs | Entire Building | 7 | EA | 6 | \$1,048 | |
| Main Se | ervice | | | | | | |
| | Main Electrical Service - 800 A and 120/208/3PH | Electrical Room | 1 | EA | 6 | \$3,570 | |
| | PA System | Entire Building | 15,130 | SF | 6 | \$4,976 | served by main building |
| Power I | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building / Electrical Room | 1 | EA | 6 | \$299 | CP-2 |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 6 | \$299 | EM-1, emergency AC power |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 1 | EA | 6 | \$497 | PP-3 |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 1 | EA | 6 | \$497 | PP-2 |
| | Lighting and Power Panels - Above 100 A | Entire Building / Mechanical Room | 1 | EA | 6 | \$497 | CP-1 |
| | Lighting and Power Panels - Above 100 A | Entire Building / Mechanical Room | 1 | EA | 6 | \$497 | LP-1 |

Electrical System Subtotal:

\$15,101

Cost Comments

Building: Linked Addition

Category: Safty System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--------------------------|-----------------------------------|----------|------|------|----------|---|
| Fire Ala | m | | | | | | |
| | Fire Alarm Panel | Entire Building / Electrical Room | 1 | EA | 6 | \$6,406 | |
| | Fire Alarm Strobe Lights | Entire Building | 15,130 | SF | 6 | \$5,409 | |
| | Fire Alarm_System | Entire Building | 35,346 | SF | 6 | \$17,185 | serves Main, Addition and Annex buildings |
| Sprinkle | r System | | | | | | |
| | Sprinkler Heads | Entire Building | 15,130 | SF | 7 | \$0 | |
| | Sprinkler Piping | Entire Building | 15,130 | SF | 7 | \$0 | |
| | Wet Sprinkler System | Entire Building | 15,130 | SF | 7 | \$0 | city pressure |
| Safty S | System Subtotal: | | | | | \$29,000 | |

Category: Mechanical System

| Group Item - Type |
|-------------------|
|-------------------|

DORE

Quantity Unit Rank

Location



Building: Linked Addition

Category: Mechanical System

| roup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|-------------------------------|----------|------|------|-----------|---|
| oiler Systems | | | | | | |
| Boiler Auxiliary- Non Condensing Hot Water - 2001 - 3000 MBH | Mechanical Room | 2 | EA | 5 | \$89,093 | |
| Chemical Pot Feeder | Mechanical Room | 1 | EA | 6 | \$725 | |
| Combustion Dampers | Mechanical Room | 2 | EA | 6 | \$818 | |
| Non Condensing- Flexible Tube- Atmospheric- Hot Water Boiler - 2001 - 3000 MBH | Mechanical Room | 2 | EA | 5 | \$120,265 | |
| Water Fill System | Mechanical Room | 1 | EA | 6 | \$1,168 | |
| eating Devices | | | | | | |
| Cabinet Heaters - With Hot Water Coil | Entire Building | 5 | EA | 6 | \$1,772 | mounted in the ceilings |
| Unit Heater - Hot Water | Mechanical Room / Boiler Room | 1 | EA | 6 | \$279 | |
| echanical Plumbing | | | | | | |
| Hot Water Pump - Less than 10 | Boiler Room | 1 | EA | 6 | \$1,111 | |
| Hot Water Pump - Less than 10 | Boiler Room | 1 | EA | 6 | \$1,111 | |
| Hydronic Supply and Return - Copper | Entire Building | 220 | LF | 6 | \$11,543 | |
| emperature Control | | | | | | |
| Electric Thermostat | Entire Building | 10 | EA | 6 | \$0 | Each univent and cabinet heater has its own built in thermostat |
| nit Ventilation | | | | | | |
| Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors | Entire Building | 10 | EA | 6 | \$12,477 | |
| entilation | | | | | | |
| Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Roof | 1 | EA | 6 | \$592 | |
| Exhaust Fans- Roof Mounted - Greater than 8000 CFM | Roof | 2 | EA | 6 | \$1,185 | |
| lechanical System Subtotal: | | | | | \$242,139 | |

Building: Linked Addition

Category: Plumbing System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost (| Comments |
|---|-----------------------------------|----------|------|------|---------|----------|
| Hot Water | | | | | | |
| Electric Heater - Less than 20 KW | Entire Building / Electrical Room | 1 | EA | 6 | \$682 | |
| Piping | | | | | | |
| Domestic Piping-Cold Water Horizontal Lines | Entire Building | 15,130 | SF | 6 | \$3,678 | |
| Domestic Piping-Hot Water Horizontal Lines | Entire Building | 15,130 | SF | 6 | \$2,813 | |
| Domestic Piping-Hot Water Return Lines | Entire Building | 15,130 | SF | 6 | \$2,164 | |

Building: Linked Addition

Category: Plumbing System

| Group Item - Type | Location | Quantity Unit Rank | Cost Comments | |
|---------------------------|-----------------|--------------------|---------------|--|
| Piping | | | | |
| Sanitary Piping | Entire Building | 15,130 SF 6 | \$13,847 | |
| Storm Piping | Entire Building | 15,130 SF 6 | \$13,198 | |
| Vent Piping | Entire Building | 15,130 SF 6 | \$10,169 | |
| Plumbing System Subtotal: | | | \$46,550 | |

Building: Linked Addition

Category: Classrooms

| oup l | tem - Type | Location | Quantity | Unit | Rank | Cost | Comments | | |
|--------|---------------------------------|-----------|----------|------|------|---------|----------|--|--|
| assroo | ssroom #113 (Regular Classroom) | | | | | | | | |
| (| Casework | 1st Floor | 30 | LF | 6 | \$758 | | | |
| (| Ceiling - Lay-in | 1st Floor | 845 | SF | 6 | \$2,538 | | | |
| (| Chalk Board | 1st Floor | 10 | LF | 4 | \$918 | | | |
| I | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | | | |
| I | Floor - Tile | 1st Floor | 845 | SF | 6 | \$1,849 | | | |
| I | _ighting - Lay-in | 1st Floor | 9 | EA | 6 | \$1,071 | | | |
| I | Marker Board | 1st Floor | 10 | LF | 7 | \$0 | | | |
| 1 | Nalls - Concrete Block | 1st Floor | 676 | SF | 6 | \$1,982 | | | |
| 1 | Nalls - Plaster/Drywall | 1st Floor | 240 | SF | 6 | \$662 | | | |
| ssroo | m #115 (Regular Classroom) | | | | | | | | |
| (| Casework | 1st Floor | 30 | LF | 6 | \$758 | | | |
| (| Ceiling - Lay-in | 1st Floor | 845 | SF | 6 | \$2,538 | | | |
| (| Chalk Board | 1st Floor | 10 | LF | 4 | \$918 | | | |
| I | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | | | |
| I | Floor - Tile | 1st Floor | 845 | SF | 6 | \$1,849 | | | |
| I | _ighting - Lay-in | 1st Floor | 9 | EA | 6 | \$1,071 | | | |
| I | Marker Board | 1st Floor | 10 | LF | 7 | \$0 | | | |
| 1 | Nalls - Concrete Block | 1st Floor | 676 | SF | 6 | \$1,982 | | | |
| 1 | Nalls - Plaster/Drywall | 1st Floor | 240 | SF | 6 | \$662 | | | |
| sroo | m #116 (Regular Classroom) | | | | | | | | |
| (| Casework | 1st Floor | 30 | LF | 6 | \$758 | | | |
| (| Ceiling - Lay-in | 1st Floor | 845 | SF | 6 | \$2,538 | | | |
| (| Chalk Board | 1st Floor | 10 | LF | 4 | \$918 | | | |
| I | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | | | |
| I | Floor - Tile | 1st Floor | 845 | SF | 6 | \$1,849 | | | |
| I | _ighting - Lay-in | 1st Floor | 9 | EA | 6 | \$1,071 | | | |

Building: Linked Addition

| unung. Emkeu Auune | / 1 | | | | | | |
|------------------------------|--------|-----------|----------|------|------|---------|----------|
| ategory: Classrooms | | | | | | | |
| roup Item - Type | | Location | Quantity | Unit | Rank | Cost | Comments |
| lassroom #116 (Regular Class | sroom) | | | | | | |
| Marker Board | | 1st Floor | 10 | LF | 7 | \$0 | |
| Walls - Concrete Block | | 1st Floor | 676 | SF | 6 | \$1,982 | |
| Walls - Plaster/Drywall | | 1st Floor | 240 | SF | 6 | \$662 | |
| lassroom #117 (Regular Class | sroom) | | | | | | |
| Casework | | 1st Floor | 30 | LF | 6 | \$758 | |
| Ceiling - Lay-in | | 1st Floor | 845 | SF | 6 | \$2,538 | |
| Chalk Board | | 1st Floor | 10 | LF | 4 | \$918 | |
| Doors - Steel Doors incl | hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile | | 1st Floor | 845 | SF | 6 | \$1,849 | |
| Lighting - Lay-in | | 1st Floor | 9 | EA | 6 | \$1,071 | |
| Marker Board | | 1st Floor | 10 | LF | 7 | \$0 | |
| Walls - Concrete Block | | 1st Floor | 676 | SF | 6 | \$1,982 | |
| Walls - Plaster/Drywall | | 1st Floor | 240 | SF | 6 | \$662 | |
| assroom #118 (Regular Class | sroom) | | | | | | |
| Casework | | 1st Floor | 30 | LF | 6 | \$758 | |
| Ceiling - Lay-in | | 1st Floor | 845 | SF | 6 | \$2,538 | |
| Chalk Board | | 1st Floor | 10 | LF | 4 | \$918 | |
| Doors - Steel Doors incl | hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile | | 1st Floor | 845 | SF | 6 | \$1,849 | |
| Lighting - Lay-in | | 1st Floor | 9 | EA | 6 | \$1,071 | |
| Marker Board | | 1st Floor | 10 | LF | 7 | \$0 | |
| Walls - Concrete Block | | 1st Floor | 676 | SF | 6 | \$1,982 | |
| Walls - Plaster/Drywall | | 1st Floor | 240 | SF | 6 | \$662 | |
| assroom #119 (Special Progr | am) | | | | | | |
| Ceiling - Lay-in | | 1st Floor | 158 | SF | 6 | \$474 | |
| Doors - Steel Doors incl | hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile | | 1st Floor | 158 | SF | 6 | \$346 | |
| Lighting - Lay-in | | 1st Floor | 2 | EA | 6 | \$238 | |
| Marker Board | | 1st Floor | 3 | LF | 7 | \$0 | |
| Walls - Concrete Block | | 1st Floor | 433 | SF | 6 | \$1,269 | |
| Walls - Plaster/Drywall | | 1st Floor | 236 | SF | 6 | \$651 | |
| assroom #120 (Regular Class | sroom) | | | | | | |
| Casework | | 1st Floor | 30 | LF | 6 | \$758 | |
| Ceiling - Lay-in | | 1st Floor | 845 | SF | 6 | \$2,538 | |
| Chalk Board | | 1st Floor | 10 | LF | 4 | \$918 | |
| | | | | | | - | |



Building: Linked Addition

| nun | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------|---|------------------------|------------|----------|--------|--------------------|----------|
| - | bom #120 (Regular Classroom) | Location | Quantity | Unit | Kulik | 0031 | Commonto |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 845 | SF | 6 | \$1,849 | |
| | Lighting - Lay-in | 1st Floor | 9 | EA | 6 | \$1,071 | |
| | Marker Board | 1st Floor | 10 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 676 | SF | 6 | \$1,982 | |
| | Walls - Plaster/Drywall | 1st Floor | 240 | SF | 6 | \$662 | |
| eero | oom #121 (Regular Classroom) | | 2.0 | 0. | Ũ | \$002 | |
| 3310 | Casework | 1st Floor | 30 | LF | 6 | \$758 | |
| | Ceiling - Lay-in | 1st Floor | 845 | SF | 6 | \$2,538 | |
| | Chalk Board | 1st Floor | 845 10 | SF LF | 6 4 | ¢2,536 918\$ | |
| | Doors - Steel Doors incl hw | 1st Floor | 10 | EA | 4 6 | \$918 \$301 | |
| | Floor - Tile | 1st Floor | 845 | SF | 6 | ہوچ \$1,849 | |
| | | 1st Floor | | | | \$1,049 \$1,071 | |
| | Lighting - Lay-in Marker Board | 1st Floor 1st Floor | 9 | EA | 6 | | |
| | Walls - Concrete Block | 1st Floor 1st Floor | 10 | LF SF | 7 | \$0 \$1 082 | |
| | Walls - Concrete Block Walls - Plaster/Drywall | 1st Floor 1st Floor | 676 240 | SF SF | 6 | \$1,982 \$662 | |
| | vvaiis - Master/Drywali | ISt Floor | 240 | 35 | 6 | \$00Z | |
| sro | oom #122 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 30 | LF | 6 | \$758 | |
| | Ceiling - Lay-in | 1st Floor | 845 | SF | 6 | \$2,538 | |
| | Chalk Board | 1st Floor | 10 | LF | 4 | \$918 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 845 | SF | 6 | \$1,849 | |
| | Lighting - Lay-in | 1st Floor | 9 | EA | 6 | \$1,071 | |
| | Marker Board | 1st Floor | 10 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 676 | SF | 6 | \$1,982 | |
| | Walls - Plaster/Drywall | 1st Floor | 240 | SF | 6 | \$662 | |
| sro | oom #123 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 30 | LF | 6 | \$758 | |
| | Ceiling - Lay-in | 1st Floor | 845 | SF | 6 | \$2,538 | |
| | Chalk Board | 1st Floor | 10 | LF | 4 | \$918 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 845 | SF | 6 | \$1,849 | |
| | Lighting - Lay-in | 1st Floor | 9 | EA | 6 | \$1,071 | |
| | Marker Board | 1st Floor | 10 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 676 | SF | 6 | \$1,982 | |
| | Walls - Plaster/Drywall | 1st Floor | 240 | SF | 6 | \$662 | |

Building: Linked Addition

| Category: | Classrooms |
|-----------|------------|
|-----------|------------|

| Group Ite | m - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------|----------------------------|-----------|----------|------|------|---------|---------------------|
| Classroom | #123 (Regular Classroom) | | | | | | |
| Classroom | #124 (Regular Classroom) | | | | | | |
| Ca | asework | 1st Floor | 30 | LF | 6 | \$758 | |
| Ce | eiling - Lay-in | 1st Floor | 845 | SF | 6 | \$2,538 | Water discoloration |
| Ch | nalk Board | 1st Floor | 10 | LF | 4 | \$918 | |
| Do | oors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Flo | por - Tile | 1st Floor | 845 | SF | 6 | \$1,849 | |
| Lig | ghting - Lay-in | 1st Floor | 9 | EA | 6 | \$1,071 | |
| Ma | arker Board | 1st Floor | 10 | LF | 7 | \$0 | |
| Wa | alls - Concrete Block | 1st Floor | 676 | SF | 6 | \$1,982 | |
| W | alls - Plaster/Drywall | 1st Floor | 240 | SF | 6 | \$662 | |
| Classroom | #126 (Special Program) | | | | | | |
| Ce | eiling - Lay-in | 1st Floor | 335 | SF | 6 | \$1,006 | |
| Do | oors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Flo | oor - Tile | 1st Floor | 335 | SF | 6 | \$733 | |
| Lig | ghting - Lay-in | 1st Floor | 3 | EA | 6 | \$357 | |
| W | alls - Concrete Block | 1st Floor | 282 | SF | 6 | \$827 | |
| W | alls - Plaster/Drywall | 1st Floor | 515 | SF | 6 | \$1,421 | |

Classrooms Subtotal:

\$108,703

Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost C | Comments |
|---------|-----------------------------|---|----------|------|------|---------|----------|
| Adminis | trative Suites/Offices | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor- Assistant Principal's Office | 180 | SF | 6 | \$623 | |
| | Doors - Steel Doors incl hw | 1st Floor- Assistant Principal's Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor- Assistant Principal's Office | 180 | SF | 6 | \$394 | |
| | Lighting - Pendent/Surface | 1st Floor- Assistant Principal's Office | 3 | EA | 6 | \$372 | |
| | Power Distribution | 1st Floor- Assistant Principal's Office | 4 | EA | 6 | \$8,500 | |
| | Walls - Concrete Block | 1st Floor- Assistant Principal's Office | 680 | SF | 6 | \$1,993 | |
| DF_ID | = | | | | | | |
| | AC Unit | 1st Floor | 1 | EA | 6 | \$496 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Finishes | 1st Floor | 75 | SF | 6 | \$535 | |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|----------------------------|----------|------|------|---------|-----------------------|
| /lechan | ical/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 32 | SF | 6 | \$229 | |
| | Mechanical/ Service Rooms | 1st Floor | 350 | SF | 6 | \$2,508 | |
| | Storage Room | 1st Floor | 75 | SF | 6 | \$537 | |
| Restroo | m | | | | | | |
| | Accessories | 1st Floor-Boy's Restroom | 575 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Floor-Boy's Restroom | 575 | SF | 7 | \$0 | |
| | Floor Drain | 1st Floor-Boy's Restroom | 2 | EA | 6 | \$2,118 | Drains appear clogged |
| | Floor - Concrete | 1st Floor-Boy's Restroom | 575 | SF | 7 | \$0 | |
| | Hand Dryer | 1st Floor-Boy's Restroom | 2 | EA | 7 | \$0 | |
| | Lavatory | 1st Floor-Boy's Restroom | 3 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 1st Floor-Boy's Restroom | 5 | EA | 7 | \$0 | |
| | Partitions | 1st Floor-Boy's Restroom | 3 | EA | 7 | \$0 | |
| | Urinals | 1st Floor-Boy's Restroom | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor-Boy's Restroom | 1,580 | SF | 7 | \$0 | |
| | Water Closet | 1st Floor-Boy's Restroom | 3 | EA | 7 | \$0 | |
| | Accessories | 1st Floor-Girl's Restroom | 575 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Floor-Girl's Restroom | 575 | SF | 7 | \$0 | |
| | Floor Drain | 1st Floor-Girl's Restroom | 2 | EA | 6 | \$2,118 | Drains appear clogged |
| | Floor - Concrete | 1st Floor-Girl's Restroom | 575 | SF | 7 | \$0 | |
| | Hand Dryer | 1st Floor-Girl's Restroom | 2 | EA | 7 | \$0 | |
| | Lavatory | 1st Floor-Girl's Restroom | 3 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 1st Floor-Girl's Restroom | 5 | EA | 7 | \$0 | |
| | Partitions | 1st Floor-Girl's Restroom | 9 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor-Girl's Restroom | 1,580 | SF | 7 | \$0 | |
| | Water Closet | 1st Floor-Girl's Restroom | 9 | EA | 7 | \$0 | |
| | Accessories | 1st Floor-Men's Restroom | 44 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Floor-Men's Restroom | 44 | SF | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor-Men's Restroom | 44 | SF | 7 | \$0 | |
| | Lavatory | 1st Floor-Men's Restroom | 1 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 1st Floor-Men's Restroom | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor-Men's Restroom | 250 | SF | 7 | \$0 | |
| | Water Closet | 1st Floor-Men's Restroom | 1 | EA | 7 | \$0 | |
| | Accessories | 1st floor-Women's Restroon | 44 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st floor-Women's Restroon | 44 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 1st floor-Women's Restroon | 1 | EA | 7 | \$0 | |
| | Floor Drain | 1st floor-Women's Restroon | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st floor-Women's Restroon | 44 | SF | 7 | \$0 | |



Building: Linked Addition

Category: Rooms (Other Than Classrooms)

| Group Item - Type | Location | Quantity | Unit | Rank | Cost Comments | |
|---|----------------------------|----------|------|------|---------------|--|
| Restroom | | | | | | |
| Lavatory | 1st floor-Women's Restroon | 1 | EA | 7 | \$0 | |
| Lighting - Lay-in | 1st floor-Women's Restroon | 1 | EA | 7 | \$0 | |
| Walls - Concrete Block | 1st floor-Women's Restroon | 250 | SF | 7 | \$0 | |
| Water Closet | 1st floor-Women's Restroon | 1 | EA | 7 | \$0 | |
| Rooms (Other Than Classrooms) Subtotal: | | | | | \$21,025 | |

Building: Linked Addition

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--------------------------------------|-----------------|----------|------|------|-----------|----------|
| Corridor | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 2,250 | SF | 6 | \$6,757 | |
| | Ceiling - Lay-in | 1st Floor | 5 | SF | 5 | \$45 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 80 | SF | 6 | \$495 | |
| | Doors - Steel Doors incl hw | 1st Floor | 8 | EA | 6 | \$2,408 | |
| | Drinking Fountains - Single Fountain | 1st Floor | 2 | EA | 6 | \$551 | |
| | Floor - Tile/Sheet | 1st Floor | 2,335 | SF | 6 | \$1,269 | |
| | Lighting - Lay-in | 1st Floor | 22 | EA | 6 | \$2,617 | |
| | Lighting - Pendent/Surface | 1st Floor | 1 | EA | 6 | \$124 | |
| | Walls - Concrete Block | 1st Floor | 10 | SF | 5 | \$141 | |
| | Walls - Concrete Block | 1st Floor | 4,748 | SF | 6 | \$13,919 | |
| | Walls - Plaster/Drywall | 1st Floor | 355 | SF | 6 | \$1,574 | |
| Safety | | | | | | | |
| | Camera Viewing Station | Entire Building | 1 | EA | 6 | \$683 | |
| | Security Cameras | Entire Building | 5 | EA | 6 | \$970 | |
| | Security Cameras | Entire Building | 2 | EA | 6 | \$388 | |
| Buildir | ng Interior Subtotal: | | | | | \$31,940 | |
| Total E | Building Cost | | | | | \$655,018 | |
| SITE | | | | | | | |
| Catego | ory: Site | | | | | | |
| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |



SITE

Category: Site

| Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------------|--|---|---|--|--|---|
| ainage | | | | | | |
| Civil/ Drainage - Catch Basin | Entire Site | 1 | EA | 7 | \$0 | Location: SE Site |
| Civil/ Drainage - Site Manhole | Entire Site | 2 | EA | 7 | \$0 | |
|] | | | | | | |
| Fencing - Chain Link | Entire Site / Site West | 320 | LF | 6 | \$6,008 | |
| Fencing - New Standard Ornamental | Entire Site | 1,505 | LF | 6 | \$48,014 | |
| ape | | | | | | |
| Benches | Entire Site / South | 4 | EA | 6 | \$1,720 | |
| Landscape - Grass | Entire Site | 1,600 | SF | 4 | \$4,027 | Location: At Modular; Bare soil |
| Landscape - Grass | Entire Site | 36,100 | SF | 6 | \$29,941 | |
| Landscape - Hardscape- Concrete | Entire Site | 648 | SF | 6 | \$3,345 | Location: At Trash Bins |
| Parkway trees | Entire Site | 43 | EA | 7 | \$0 | |
| Planting Beds/ Area | Entire Site | 3,610 | SF | 6 | \$5,937 | Location: Site West at Modular and Site Eas |
| Play Area - Asphalt/ Hardscape | Entire Site / Site West | 5,664 | SF | 6 | \$13,688 | |
| Trash Receptacles | Entire Site | 3 | EA | 6 | \$937 | |
| Lot | | | | | | |
| Concrete Curbs | NW Parking Lot / North West | 90 | LF | 6 | \$1,156 | |
| Interior Plantings | NW Parking Lot / Parking Lot | 70 | LF | 6 | \$2,978 | |
| Surface - Asphalt | NW Parking Lot | 700 | SF | 5 | \$4,134 | Location: drive aisles; cracks and pot holes |
| Surface - Asphalt | NW Parking Lot / North West | 18,750 | SF | 6 | \$45,313 | |
| pund | | | | | | |
| Equipment - Pre K 3-5 | SW Playground | 1 | EA | 7 | \$0 | |
| Equipment - School Age 5-12 | SE Playground | 1 | EA | 7 | \$0 | |
| Surface - Poured Surface | SE Playground | 2,330 | SF | 7 | \$0 | |
| Surface - Poured Surface | SW Playground | 1,815 | SF | 7 | \$0 | |
| lks | | | | | | |
| Sidewalks - Internal Walks | Entire Site | 80 | LF | 6 | \$1,110 | Location: Modular |
| Sidewalks - Internal Walks | Entire Site | 325 | LF | 6 | \$3,904 | some minor cracks |
| Sidewalks - Perimeter Sidewalks | Entire Site | 13,900 | SF | 6 | \$27,629 | cracks at E |
| e | | | | | | |
| Flag Pole - Flag Pole | Entire Site / North East | 1 | EA | 6 | \$1,657 | Rust |
| Marquee - Free Standing Back Lighted | Entire Site / East | 1 | EA | 6 | \$0 | |
| | ainage Civil/ Drainage - Catch Basin Civil/ Drainage - Site Manhole g Fencing - Chain Link Fencing - New Standard Ornamental ape Benches Landscape - Grass Landscape - Grass Landscape - Grass Landscape - Hardscape- Concrete Parkway trees Planting Beds/ Area Play Area - Asphalt/ Hardscape Trash Receptacles JLot Concrete Curbs Interior Plantings Surface - Asphalt Surface - Asphalt Surface - Asphalt Surface - Poured Surface Surface - Poured Surface Surface - Poured Surface Surface - Poured Surface Sidewalks - Internal Walks Sidewalks - Internal Walks Sidewalks - Perimeter Sidewalks | ainage Civil/ Drainage - Catch Basin Entire Site Civil/ Drainage - Site Manhole Entire Site Fencing - Chain Link Entire Site / Site West Fencing - New Standard Ornamental Entire Site ape Entire Site / South Benches Entire Site / South Landscape - Grass Entire Site Landscape - Grass Entire Site Landscape - Grass Entire Site Landscape - Hardscape- Concrete Entire Site Parkway trees Entire Site Play Area - Asphalt/ Hardscape Entire Site Vot Concrete Curbs NW Parking Lot / North West Interior Plantings NW Parking Lot / North West Surface - Asphalt NW Parking Lot / North West Surface - Asphalt NW Parking Lot / North West Surface - School Age 5-12 SE Playground Surface - Poured Surface SE Playground Surface - Poured Surface | ainage Civil/ Drainage - Catch Basin Entire Site 1 Civil/ Drainage - Site Manhole Entire Site 2 J Fencing - Chain Link Entire Site / Site West 320 Fencing - Chain Link Entire Site / Site West 320 ape Entire Site / South 4 Landscape - Grass Entire Site / South 4 Landscape - Grass Entire Site 36,100 Landscape - Hardscape-Concrete Entire Site 36,100 Landscape - Hardscape - Concrete Entire Site 43 Planting Beds/ Area Entire Site 3,610 Play Area - Asphalt/ Hardscape Entire Site 3,610 Play Area - Asphalt/ Hardscape Entire Site 3,610 Play Area - Asphalt/ Hardscape Entire Site 3 Lot Concrete Curbs NW Parking Lot / North West 90 Interior Plantings NW Parking Lot / North West 18,750 Surface - Asphalt NW Parking Lot / North West 18,750 Surface - Asphalt SW Playground 1 Equipment - Pre K 3-5 SW Playground 1 Gu | ainage Civil/ Drainage - Catch Basin Entire Site 1 EA Civil/ Drainage - Site Manhole Entire Site 2 EA J Fencing - Chain Link Entire Site / Site West 320 LF Fencing - New Standard Ornamental Entire Site / Site West 320 LF ape Entire Site / South 4 EA Landscape - Grass Entire Site / South 4 EA Landscape - Grass Entire Site 36,100 SF Landscape - Grass Entire Site 648 SF Parkway trees Entire Site 43 EA Planting Beds/ Area Entire Site 3,610 SF Play Area - Asphait Varea Entire Site 3,610 SF Interior Plantings Entire Site 3,640 SF Interior Plantings NW Parking Lot / North West 90 LF Surface - Asphait NW Parking Lot / North West 90 LF Interior Plantings NW Parking Lot / North West 18,750 SF Surface - Asphait NW Parking Lot / North West 18,750 | ainageCivil/ Drainage - Catch BasinEntire Site1EA7Civil/ Drainage - Site ManholeEntire Site2EA7gFencing - Chain LinkEntire Site / Site West320LF6Fencing - New Standard OrnamentalEntire Site / South4EA6Landscape - GrassEntire Site / South4EA6Landscape - GrassEntire Site300SF4Landscape - GrassEntire Site648SF6Landscape - GrassEntire Site648SF6Landscape - GrassEntire Site3610SF6Landscape - GrassEntire Site3640SF6Parking Beds/AreaEntire Site1864SF6Trash ReceptaclesEntire Site18C6JotConcrete CurbsNW Parking Lot / North West90LF6Surface - AsphaltNW Parking Lot / North West18.750SF6Surface - AsphaltNW Parking Lot / North West18.750SF7Surface - Aspha | ainage Entire Site 1 EA 7 \$00 Civil/ Drainage - Site Manhole Entire Site 2 EA 7 \$00 Civil/ Drainage - Site Manhole Entire Site 32 EA 7 \$00 Fencing - Chain Link Entire Site / Site West 320 LF 6 \$66,008 Fencing - New Standard Ornamental Entire Site / Site West 320 LF 6 \$64,014 ape Encines Entire Site / South 4 EA 6 \$1,720 Landscape - Grass Entire Site / South 4 EA 6 \$20,941 Landscape - Grass Entire Site 36,100 SF 6 \$23,941 Landscape - Grass Entire Site 36,100 SF 6 \$23,941 Landscape - Grass Entire Site 3,610 SF 6 \$23,941 Landscape - Grass Entire Site / Site West 5,664 SF 6 \$13,868 Plarking Beds/ Area Asphait/ Hardscape Entire Site / Site West 5,064 SF 6 \$13,868 Trash Rece |



Total Site Cost

\$201,498

\$2,042,654

Campus Total ^{2 3}

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------|-------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | | - | | | | | II | | | | | | |
| Computer Lab | Regular Classroom | 1st Floor | 108 | 108 | 750 | 1 | 46 | 112 | 200 | 64 | 40 | Ν | Y | Y |
| Kindergarten | Kindergarten | 1st Floor | 107 | 107 | 856 | 1 | 4 | 12 | 200 | 64 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 101 | 101 | 750 | 1 | 4 | 10 | 200 | 64 | 40 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 103 | 103 | 750 | 1 | 4 | 10 | 200 | 64 | 40 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 105 | 105 | 750 | 1 | 4 | 10 | 200 | 64 | 40 | Ν | Y | Y |
| Science Classroom | Regular Classroom | 1st Floor | 110 | 110 | 750 | 1 | 4 | 10 | 200 | 64 | 40 | Ν | Y | Ν |
| 4-Classroom Mod | lular | | | | | | | | | | | | | |
| Regular Classroom | Regular Classroom | 1st Floor | 201 | 201 | 810 | 1 | 2 | 16 | 50 | 27 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 202 | 202 | 810 | 1 | 2 | 16 | 50 | 27 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 203 | 203 | 810 | 1 | 2 | 16 | 50 | 27 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 204 | 204 | 810 | 1 | 2 | 16 | 50 | 27 | 40 | Ν | Y | Ν |
| Addition | | | | | | | | | | | | | | |
| Pre School | Regular Classroom | 1st Floor | 114 | 114 | 750 | 1 | 4 | 10 | 200 | 64 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 112 | 112 | 750 | 1 | 4 | 10 | 200 | 64 | 40 | Ν | N | Ν |
| Special Education | Regular Classroom | 1st Floor | 111 | 111 | 750 | 1 | 4 | 10 | 200 | 64 | 40 | Ν | Y | Ν |
| Linked Addition | | | | | | | | | | | | | | |
| Regular Classroom | Regular Classroom | 1st Floor | 113 | 122 | 845 | 1 | 7 | 14 | 102 | 51 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 115 | 108 | 845 | 1 | 7 | 14 | 102 | 51 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 116 | 121 | 845 | 1 | 7 | 14 | 102 | 51 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 117 | 107 | 845 | 1 | 7 | 14 | 102 | 51 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 118 | 104 | 845 | 1 | 7 | 14 | 102 | 51 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 120 | 103 | 845 | 1 | 7 | 14 | 102 | 51 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 121 | 108 | 845 | 1 | 7 | 14 | 102 | 51 | 40 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 122 | 102 | 845 | 1 | 7 | 14 | 102 | 51 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 123 | 105 | 845 | 1 | 7 | 14 | 102 | 51 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 124 | 101 | 845 | 1 | 7 | 14 | 102 | 51 | 40 | Ν | Y | N |
| Special Program | Office | 1st Floor | 119 | 128 | 158 | 1 | 3 | 8 | 0 | 0 | 40 | Ν | Y | N |
| Special Program | Office | 1st Floor | 126 | 109 | 335 | 1 | 3 | 10 | 34 | 17 | 40 | Ν | Y | Ν |