

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1918	4	175,571	\$7,544,821
Addition	1939	4	62,986	\$4,820,891
SITE				\$197,107
Campus Total			238,557	\$12,562,819

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entranc	e						
	Entrance Control - Audio and Video	10	1	EA	4	\$5,381	not operable
	Entrance Control - Audio and Video	3	1	EA	4	\$5,381	not operable
	Exterior Doors - Exterior Steel Door	10	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	11	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	12	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	13	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	2	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	3	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	4	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	5	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	6	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	7	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	8	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	9	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	Boiler House	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	Transformer Vault	2	EA	5	\$2,683	corroded
	Exterior Doors - Transom Lite	2	2	EA	5	\$1,643	alligatoring paint
	Exterior Doors - Transom Lite	3	3	EA	6	\$940	
	Exterior Stairs - Concrete	10	6	LF	5	\$657	spalling, cracked



Building: Main

Category: Building Exterior

Group	b Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrar	nce						
	Exterior Stairs - Concrete	11	9	LF	6	\$736	
	Exterior Stairs - Concrete	13	6	LF	5	\$657	spalling, loose concrete
	Exterior Stairs - Concrete	2	6	LF	6	\$491	
	Exterior Stairs - Concrete	3	9	LF	6	\$736	
	Exterior Stairs - Concrete	4	9	LF	6	\$736	
	Exterior Stairs - Concrete	5	9	LF	6	\$736	
	Exterior Stairs - Concrete	6	9	LF	6	\$736	
	Exterior Stairs - Concrete	7	9	LF	6	\$736	
	Exterior Stairs - Concrete	8	9	LF	6	\$736	
	Exterior Stairs - Concrete	9	6	LF	6	\$491	
Found	dation						
	Foundation - Masonry	Entire Building	1,094	LF	7	\$0	
	Superstructure - Steel with Clay Tile Arch	Entire Building	175,571	SF	7	\$0	
Lighti	ng						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	7	\$0	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	5	\$1,710	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	6	\$866	
Roof :	System						
	Chimney - Brick Chimney- Concrete/ Mortar Liner	А	30	LF	6	\$28,640	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	F / East	50	LF	4	\$281,598	step cracking, gaps in masonry. Strapped.
	Chimney - Brick Chimney- Concrete/ Mortar Liner	F / East	40	LF	5	\$114,063	open joints, minor step cracking
	Chimney - Metal Flue	В	30	LF	6	\$4,744	
	Coping - Clay Tile	В	268	LF	6	\$8,608	
	Coping - Clay Tile	C / North Façade	45	LF	6	\$1,445	
	Coping - Clay Tile	D	73	LF	6	\$2,345	
	Coping - Clay Tile	E	125	LF	6	\$4,015	
	Coping - Clay Tile	F	315	LF	6	\$10,117	
	Coping - Metal	G / West Façade	22	LF	6	\$707	gutter
	Downspouts - Exterior Downspouts	А	540	LF	6	\$17,946	
	Downspouts - Exterior Downspouts	B / Courtyard	25	LF	4	\$3,387	downspout leaking and water is leaking into interior at that location
	Downspouts - Exterior Downspouts	B / East Façade	232	LF	6	\$7,710	
	Downspouts - Exterior Downspouts	C / North Façade	10	LF	6	\$332	
	Downspouts - Interior Downspouts	F	81	LF	7	\$0	
	Downspouts - Interior Downspouts	н	10	LF	7	\$0	
	Parapet - Parapet > 30"	В	218	LF	6	\$13,935	



Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof Sy	/stem						
	Parapet - Parapet > 30"	B / South	50	LF	5	\$16,412	bulging
	Parapet - Parapet > 30"	C / North Façade	45	LF	6	\$2,876	
	Parapet - Parapet > 30"	D	73	LF	7	\$0	
	Parapet - Parapet > 30"	E	125	LF	7	\$0	
	Parapet - Parapet > 30"	F	315	LF	6	\$20,135	
	Roof Structure - Steel with Clay Tile Arch	A	18,846	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	В	15,846	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	С	2,565	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	D	2,022	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	E	3,720	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	F	4,800	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	G	396	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Н	1,920	SF	7	\$0	
	Roof - Asphalt Shingle	A	15,356	SF	5	\$158,325	peeling, missing shingles
	Roof - EPDM/ Synthetic Rubber	В	15,846	SF	4	\$409,009	bubbling, splitting, corroded flashing, spongy
	Roof - EPDM/ Synthetic Rubber	C	2,565	SF	4	\$66,206	bubbling, spongy
	Roof - EPDM/ Synthetic Rubber	D	2,022	SF	4	\$52,191	bubbling, spongy
	Roof - EPDM/ Synthetic Rubber	E	3,720	SF	4	\$96,019	bubbling, spongy
	Roof - EPDM/ Synthetic Rubber	F	4,800	SF	4	\$123,895	bubbling, spongy
	Roof - EPDM/ Synthetic Rubber	G	396	SF	4	\$10,221	bubbling, spongy
	Roof - EPDM/ Synthetic Rubber	Н	1,920	SF	4	\$49,558	bubbling, spongy
	Roof - Metal	A	250	SF	5	\$7,697	metal decorative roofs- corroded, open joints
	Roof - Metal	A	3,240	SF	4	\$155,583	corroded, leaking
Walls							
	Cornice - Metal Projecting	Entire Building	577	LF	5	\$86,810	corroded, no paint
	Exterior Walls - Brick	Entire Building	49,203	SF	6	\$330,693	
	Exterior Walls - Brick	Entire Building	2,590	SF	4	\$426,444	bulging
	Exterior Walls - Stone-Cut	Entire Building	1,585	SF	6	\$10,653	
	Exterior Walls - Terra Cotta	Entire Building	500	SF	6	\$3,361	
Windov	/S						
	Guard - Guards perforated	Entire Building	525	SF	6	\$6,704	
	Lintels - Brick	Entire Building / East Façade	305	LF	6	\$0	
	Lintels - Steel	Entire Building	238	LF	4	\$107,758	corroded, bulging, displacing brick
	Lintels - Stone	Entire Building	653	LF	6	\$0	
	Lintels - Stone	Entire Building / West Façade	15	LF	4	\$5,452	crack at brick/stone connection
	Windows - Insulated Panel	Entire Building / West Façade	40	SF	7	\$0	



Building: Main

Category: Building Exterior

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ndows						
Windows - Insulated Panel	Entire Building / West Façade	2,052	SF	6	\$15,317	
Windows - Louver	Entire Building / East Façade	40	SF	6	\$299	
Windows - Sash Aluminum Double-pane	Entire Building	8,719	SF	6	\$65,084	
Windows - Sash Aluminum Double-pane	Entire Building	2,092	SF	7	\$0	

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	1,632	SF	6	\$863	
	Emergency A/C Power - Corridors and Stairs	Entire Building	25,937	SF	6	\$7,789	All lights functional, per engineer
	Emergency A/C Power - Gym	Entire Building	11,814	SF	6	\$4,392	
	Emergency A/C Power - Pool	Entire Building	2,450	SF	6	\$911	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	6	EA	7	\$0	Batteries charged
	Emergency Battery Packs - Corridors and Stairs	Entire Building	28	EA	7	\$0	Batteries charged
	Emergency Battery Packs - Pool	Entire Building	2	EA	7	\$0	Batteries charged
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	7	\$0	Batteries charged
	Exit Signs - Auditoium	Entire Building	12	EA	2	\$6,546	School does not have an emergency generator or UPS and signs do not have battery backup
	Exit Signs - Corridors and Stairs	Entire Building	30	EA	2	\$16,365	School does not have an emergency generator or UPS and signs do not have battery backup
	Exit Signs - Gym	Entire Building	6	EA	2	\$3,470	School does not have an emergency generator or UPS and signs do not have battery backup
	Exit Signs - Lunchroom	Entire Building	6	EA	2	\$3,273	School does not have an emergency generator or UPS and signs do not have battery backup
	Exit Signs - Pool	Entire Building	1	EA	2	\$568	School does not have an emergency generator or UPS and signs do not have battery backup
Main S	ervice						
	Main Electrical Service - 800 A and 120/208/3PH	Boiler Room	1	EA	4	\$26,688	Panel is greater than 50 years of age and deteriorated
Power	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	10	EA	6	\$2,991	
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	\$0	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	\$4,849	Panel is old and significantly deteriorated
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	\$1,988	

Building: Main

Category:	Electrical	System
-----------	------------	--------

Category: Electrical System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Power Distribution						
Lighting and Power Panels - Above 100 A	Entire Building	7	EA	7	\$0	
Main Distribution Panels - Greater than 600 amp	Entire Building	2	EA	7	\$0	
Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	\$503	
Electrical System Subtotal:					\$81,196	
Building: Main						
Category: Safty System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm						
Fire Alarm Strobe Lights	Entire Building	175,571	SF	4	\$238,513	Served by panel in addition building
Safty System Subtotal:					\$238,513	

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Cor	ditioning						
	Condensing Unit- Ground Mounted - 5-10 tons	Courtyard	1	EA	7	\$0	
	Condensing Unit- Ground Mounted - Less than 5 tons	Courtyard	4	EA	7	\$0	
Air Har	dling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000	Mechanical Room	1	EA	4	\$157,410	Fan installed in cold deck to increase air flow to two zones.
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000	Mechanical Room	1	EA	5	\$78,608	Serves classrooms, auditorium, and pool area. Unit can maintain space temperatures; however, motor is old, coils leak, and exterior is deteriorating
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - Greater than 35000 cfm	Mechanical Room	1	EA	5	\$95,595	Unit can maintain space temperatures; however, motor is old, coils leak, and exterior is deteriorating
	Air Handling Unit- Package Single Zone- Indoor- Electric and DX Cooling Coil - Less than 4000 cfm	1st Floor	1	EA	5	\$20,373	Serves offices in basement
	Air Intake	1st Floor / West Façade	1	EA	6	\$5,765	
	Air Intake	Mechanical Room / South Courtyard	1	EA	4	\$17,616	Intake is stuck in current position
	Air Intake	Mechanical Room / West Courtyard	1	EA	4	\$17,616	Intake is stuck in current position
	Air Intake	Mechanical Room / West Courtyard Facades	1	EA	6	\$5,765	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	4	\$39,696	Auxiliaries are in poor condition. Housing walls deteriorated, coils are leaking severely, unit is not sealed



Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Han	dling Systems						
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	4	\$39,696	Auxiliaries are in poor condition. Housing walls deteriorated, coils are leaking severely, unit is not sealed
	Auxiliaries - Greater than 35000 cfm	Mechanical Room	1	EA	4	\$45,482	Auxiliaries are in poor condition. Housing walls deteriorated, coils are leaking severely, unit is not sealed
	Fan Coil Unit- Celing Mounted - Electric	Basement	4	EA	7	\$0	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	4	\$0	No return duct or shaft
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	4	\$0	No return duct or shaft to roof
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	4	\$0	No return duct or shaft
	Zone Dampers	Mechanical Room	18	EA	5	\$34,444	2 dampers propped open
	Zone Dampers	Mechanical Room	8	EA	5	\$15,308	
	Zone Dampers	Mechanical Room	31	EA	5	\$59,320	
Boiler S	Systems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - Greater than 300 HP	Boiler Room	2	EA	5	\$51,050	
	Chemical Feed System	Boiler Room / Mechanical Room	2	EA	6	\$2,156	
	Combustion Dampers	Boiler Room	2	EA	5	\$5,104	
	Condensate Pump	Boiler Room / Entire Building	3	EA	6	\$6,063	
	Feed Water Pumps and Tank	Boiler Room / Mechanical Room	1	EA	6	\$2,545	Pumps in good condition, tank shows no signs of leaking
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - Greater than 300 HP	Boiler Room	2	EA	5	\$51,050	Serves main and addition
	Piping - Condensate Pipe- Steel	Boiler Room	734	LF	4	\$207,961	All mechanical piping in poor condition, per engineer. Leaks and clamps installed.
	Piping - Steam Pipe- Steel	Boiler Room	734	LF	4	\$215,949	All mechanical piping in poor condition, per engineer. Leaks and clamps installed.
	Steam Traps	Boiler Room / Entire Building	84	EA	5	\$110,452	Per engineer, overall condition of steam traps are good. A few could be refurbished.
Gas Bo	oster						
	Gas Booster	Boiler Room	2	EA	6	\$998	
Heating	Devices						
	Fin Tube - Steam	Entire Building	61	LF	6	\$576	
	Unit Heater - Electric	Entire Building / Basement	2	EA	4	\$4,002	Unit heater is old and in poor condition. Located in locker rooms.
	Unit Heater - Steam	Entire Building	3	EA	5	\$2,728	
	Wall Heater - Electric	Entire Building	27	EA	5	\$14,488	



Building: Main

Category: Mechanical System

Group Item - Type		Location	Quantity	Unit	Rank	Cost	Comments
Temperature Control							
Thermostats - Pneumatic		Entire Building	49	EA	6	\$0	Served from pneumatic system in addition
Thermostats - Pneumatic		Entire Building	8	EA	4	\$5,898	Thermostats damaged and in poor condition. Served from pneumatic system in addition
Ventilation							
Exhaust Fans- Indoor - 1501 - 8000	CFM	Entire Building / 3rd Floor	4	EA	6	\$2,370	Serve lunch room
Exhaust Fans- Indoor - 1501 - 8000	CFM	Entire Building / Attic	1	EA	6	\$592	
Exhaust Fans- Indoor - 1501 - 8000	CFM	Entire Building / Basement	4	EA	4	\$25,568	Exhaust fans are greater than 15 years of age and in poor condition. Serve locker room and pool
Exhaust Fans- Indoor - 500 - 1500 (CFM	Entire Building / Attic	1	EA	4	\$4,245	Fan is greater than 15 years of age and in poor condition
Exhaust Fans- Indoor - Greater than	8000 CFM	Entire Building / Basement	1	EA	6	\$592	
Exhaust Fans- Roof Mounted - 1501	- 8000 CFM	Entire Building / Roof	3	EA	6	\$1,777	
Exhaust Fans- Roof Mounted - 500	- 1500 CFM	Entire Building / Roof	1	EA	6	\$592	
Type I Exhaust Hood- Kitchen		Entire Building / 3rd Floor	1	EA	2	\$28,265	High temperature kitchen equipment are located outside the hood
Type II Exhaust Hood- Warming Kite	chen	Entire Building / 3rd Floor	1	EA	6	\$920	
Machanical Quatam Quiktatak					.	070 005	

Mechanical System Subtotal:

\$1,378,635

Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lot Wat	er						
	Gas Heater - 150000 - 300000 BTU/HR	Entire Building / 3rd Floor	1	EA	5	\$2,249	
	Gas Heater - 150000 - 300000 BTU/HR	Entire Building / Boiler Room	1	EA	4	\$19,938	Heater greater than 15 years of age and in poor condition
	Gas Heater - 300001 - 600000 BTU/HR	Entire Building / Boiler Room	1	EA	4	\$34,950	Heater greater than 15 years of age and in poor condition. Serve main and addition.
	Hot Water Storage Tank_Gas - 501 - 1000 Gallons	Entire Building / Boiler Room	1	EA	6	\$678	No issues with tank, per engineer
	Hot Water Storage Tank_Gas - 501 - 1000 Gallons	Entire Building / Boiler Room	1	EA	4	\$26,246	Tank is abandoned and not needed
ping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	175,571	SF	7	\$0	Plumbing systems upgraded.
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	175,571	SF	7	\$0	Plumbing systems upgraded.
	Domestic Piping-Cold Water Risers	Entire Building	175,571	SF	7	\$0	Plumbing systems upgraded.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	175,571	SF	7	\$0	Plumbing systems upgraded.
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	175,571	SF	7	\$0	Plumbing systems upgraded.
	Domestic Piping-Hot Water Return Lines	Entire Building	175,571	SF	4	\$150,640	



Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Hot Water Return Risers	Entire Building	175,571	SF	4	\$85,363	
	Sanitary Piping	Entire Building	175,571	SF	6	\$160,683	
	Storm Piping	Entire Building	175,571	SF	6	\$153,151	
	Vent Piping	Entire Building	175,571	SF	6	\$118,001	
Pool Sy	rstems						
	Pool Drain Piping	Mechanical Room	85	LF	7	\$0	Pool drained and not used.
	Pool Filtration System including Pump	Mechanical Room	3	EA	7	\$0	Pool drained and not used.
	Pool Hot Water Heater - Gas Fired	Mechanical Room	1	EA	5	\$2,924	Heater in fair condition. Currently no signs of corrosion. Pool drained and not used.
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Entire Building / Mechanical Room	1	EA	6	\$1,446	HW booster. Serves main and addition.
	Pumps - Domestic Booster Pump-Simplex	Entire Building / Mechanical Room	1	EA	6	\$1,446	CHW booster. Serves main and addition.
	Pumps - Ejector-Duplex	Entire Building / Boiler Room	1	EA	6	\$1,387	2 pumps, 1 pit
	Pumps - Sump-Duplex	Entire Building / 1st Floor	1	EA	6	\$1,387	

Plumbing System Subtotal:

\$760,487

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroo	om #019 (Pre School)						
	Casework		8	LF	6	\$202	
	Ceiling - Lay-in		1,054	SF	7	\$0	
	Chalk Board		12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Carpet		310	SF	6	\$661	
	Floor - Tile		744	SF	6	\$1,628	
	Lighting - Lay-in		18	EA	7	\$0	
	Marker Board		16	LF	7	\$0	
	Walls - Plaster/Drywall		912	SF	6	\$2,517	
	Work Sink		2	EA	6	\$758	
Classroo	om #021 (Regular Classroom)						
	Ceiling - Lay-in		868	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Carpet		224	SF	6	\$477	

Building: Main

Category:	Classrooms
-----------	------------

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #021 (Regular Classroom)						
	Floor - Tile		644	SF	7	\$0	
	Lighting - Lay-in		24	EA	6	\$2,855	
	Marker Board		22	LF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel		783	SF	6	\$2,161	partially covered with plastic panels.
	Work Sink		1	EA	6	\$379	
Classro	om #023 (Regular Classroom)						
	Ceiling - Lay-in		990	SF	7	\$0	
	Doors - Steel Doors incl hw		1	EA	6	\$301	
	Floor - Tile		990	SF	6	\$2,166	
	Lighting - Lay-in		18	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		819	SF	6	\$2,260	
Classro	om #112 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		8	LF	4	\$3,713	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		675	SF	7	\$0	
	Chalk Board		24	LF	4	\$2,203	obsolete material
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		3	EA	5	\$3,522	
	Floor - Tile		675	SF	6	\$1,477	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		17	LF	7	\$0	
	Walls - Plaster/Drywall		861	SF	6	\$2,376	
Classro	om #117 (Other Instructional Use)						
	Ceiling - Plaster/Drywall	1st Floor	154	SF	6	\$533	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Carpet	1st Floor	154	SF	6	\$328	
	Lighting - Pendent/Surface	1st Floor	4	EA	6	\$496	
	Walls - Plaster/Drywall	1st Floor	347	SF	6	\$958	
Classro	om #118 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		8	LF	5	\$1,673	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		620	SF	7	\$0	
	Chalk Board		10	LF	4	\$918	obsolete material

Building: Main

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	bom #118 (Regular Classroom)			•••••		••••	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Carpet		300	SF	5	\$1,540	
	Floor - Tile		320	SF	5	\$1,437	cracked tile; separating seams
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		20	LF	7	\$0	
	Walls - Plaster/Drywall		835	SF	6		peeling paint
assro	oom #120 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		8	LF	5	\$1,673	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		620	SF	7	\$0	
	Chalk Board		10	LF	4	\$918	obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		620	SF	5		cracked and chipped tile
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		940	SF	6	\$2,594	cracked plaster & peeling paint
assro	oom #122 (Regular Classroom)						
	AC Units		2	EA	6	\$991	
	Casework		28	LF	6	\$707	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		1,245	SF	7	\$0	
	Doors - Transom Window		27	SF	6	\$457	
	Doors - Wood Doors inclu hw		3	EA	6	\$903	
	Floor - Carpet		456	SF	5	\$2,341	
	Floor - Tile		800	SF	6	\$1,750	
	Lighting - Lay-in		27	EA	6	\$3,212	
	Marker Board		28	LF	7	\$0	
	Walls - Plaster/Drywall		1,256	SF	5	\$9,519	cracked plaster & peeling paint
issro	oom #126 (Regular Classroom)						
	AC Units		2	EA	6	\$991	
	Casework		8	LF	5	\$1,673	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		1,329	SF	7	\$0	
	Chalk Board		4	LF	4	\$367	obsolete material
	Doors - Transom Window		18	SF	6	\$305	

Building: Main

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	om #126 (Regular Classroom)	Location	Quantity	Onit	Kalik	0031	Comments
01033100	Doors - Wood Doors inclu hw		3	EA	6	\$903	
	Floor - Carpet		378	SF	6	\$805	
	Floor - Tile		1,000	SF	5	\$4,490	
	Lighting - Lay-in		34	EA	7	φ-,-50 \$0	
	Marker Board		18	LF	7	\$0	
	Walls - Plaster/Drywall		578	SF	5	\$2,554	cracked plaster & peeling paint
	Walls - Plaster/Drywall		800	SF	6	\$2,204 \$2,208	cracked plaster & peening paint
	Walls - Flaster/Drywall		000	01	0	ψ2,200	
Classro	om #127 (Computer Lab)						
	AC Units		2	EA	7	\$0	
	Casework		16	LF	6	\$404	
	Ceiling - Lay-in		1,074	SF	7	\$0	
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Tile		1,074	SF	6	\$2,350	
	Lighting - Lay-in		21	EA	7	\$0	
	Marker Board		32	LF	7	\$0	
	Walls - Plaster/Drywall		1,200	SF	6	\$3,312	
	Wireless System		1	EA	7	\$0	
Classro	om #129 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		884	SF	7	\$0	
	Ceiling - Plaster/Drywall		34	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		908	SF	6	\$1,987	
	Floor - Tile		10	SF	4	\$130	broken/damaged tiles
	Lighting - Lay-in		21	EA	7	\$0	-
	Marker Board		24	LF	7	\$0	
	Storage/ Closet		136	SF	6	\$986	
	Walls - Plaster/Drywall		1,340	SF	6	\$3,698	
Classro	om #131 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		884	SF	7	\$0	
	Ceiling - Plaster/Drywall		34	SF	7	\$0	
	Celling - Plaster/Drywall		J 1	0	1	U U	

Building: Main

un	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	om #131 (Regular Classroom)	Location	Quantity	Unit	Nalik	0031	Comments
55100	Floor - Tile		918	SF	6	\$2,008	
	Lighting - Lay-in		21	EA	7	\$2,008 \$0	
	Marker Board		24	LF	7	\$0 \$0	
	Storage/ Closet		136	SF	6	\$986	
	Walls - Plaster/Drywall		1,340	SF	6	\$3,698	
			1,340	01	0	ψ0,090	
	om #133 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		884	SF	7	\$0	
	Ceiling - Plaster/Drywall		34	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		900	SF	6	\$1,969	
	Floor - Tile		18	SF	4	\$233	cracked or broken tile
	Lighting - Lay-in		21	EA	7	\$0	
	Marker Board		24	LF	7	\$0	
	Storage/ Closet		136	SF	6	\$986	
	Walls - Plaster/Drywall		1,340	SF	5	\$10,156	
ssroo	om #135 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		14	LF	4	\$6,498	deteriorated finishes, damaged
	Ceiling - Lay-in		884	SF	7	\$0	
	Ceiling - Plaster/Drywall		34	SF	7	\$0	
	Chalk Board		14	LF	4	\$1,285	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Weight/ Fitness Room Floor Matting		918	SF	7	\$0	
	Lighting - Lay-in		21	EA	7	\$0	
	Marker Board		28	LF	7	\$0	
	Storage/ Closet		136	SF	5	\$2,194	
	Walls - Plaster/Drywall		1,340	SF	6	\$3,698	
ssroo	om #137 (Music Room)						
	AC Units		1	EA	7	\$0	
	Casework		40	LF	5	\$8,363	
	Ceiling - Lay-in		900	SF	7	\$0	
	Ceiling - Plaster/Drywall		90	SF	7	\$0	
	Doors - Transom Window		258	SF	6	\$4,368	

Building: Main

-	ory: Classrooms		•		D.	•	0
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	bom #137 (Music Room)		000	05	7	^	
	Floor - Wood		990	SF	7	\$0	
	Lighting - Lay-in		18	EA	7	\$0 \$0 5 4 5	
	Walls - Plaster/Drywall		922	SF	6	\$2,545	
lassro	oom #209 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		8	LF	5	\$1,673	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		690	SF	7	\$0	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		690	SF	6	\$4,864	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		20	LF	7	\$0	
	Walls - Plaster/Drywall		430	SF	5	\$1,900	cracked and damaged plaster; peeling paint
	Walls - Plaster/Drywall		500	SF	6	\$1,380	
lassro	oom #210 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		8	LF	5	\$1,673	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		612	SF	7	\$0	
	Chalk Board		14	LF	4	\$1,285	obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Wood		612	SF	5	\$8,953	warped floor boards; damaged finish
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		391	SF	5	\$1,728	cracked plaster; peeling paint
	Walls - Plaster/Drywall		500	SF	6	\$1,380	
lassro	oom #211 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		8	LF	5	\$1,673	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		690	SF	7	\$0	
	Chalk Board		12	LF	4	\$1,102	obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		690	SF	6	\$4,864	

Building: Main

Category: Classrooms Group Item - Type Location Quantity Unit Rank **Cost Comments** Classroom #211 (Regular Classroom) Lighting - Lay-in 14 FA 7 \$0 LF 7 \$0 Marker Board 20 5 Walls - Plaster/Drywall 430 SF \$1,900 cracked plaster; peeling paint Walls - Plaster/Drywall SF 6 \$1.380 500 Classroom #212 (Store Room) AC Units 1 ΕA 6 \$496 Casework 8 LF 5 \$1,673 damaged & deteriorating finish, veneer and hardware \$0 Ceiling - Lay-in SF 7 675 SF Doors - Transom Window 18 6 \$305 glazing missing Doors - Wood Doors inclu hw 3 ΕA 6 \$903 Floor - Wood 675 SF 5 \$9,875 warped boards & damaged finish Lighting - Lay-in 7 \$0 ΕA 14 7 Marker Board 18 LF \$0 Walls - Plaster/Drywall 861 SF 6 \$2,376 Classroom #213 (Regular Classroom) AC Units ΕA \$496 1 6 5 Casework 8 LF \$1,673 damaged & deteriorating finish, veneer and hardware Ceiling - Lay-in SF 7 \$0 690 Chalk Board 12 LF 4 \$1.102 obsolete material Doors - Transom Window 9 SF 6 \$152 Doors - Wood Doors inclu hw 1 ΕA 6 \$301 Floor - Wood SF 5 \$10,094 warped wood and damaged finish 690 7 \$0 Lighting - Lay-in 14 ΕA Marker Board 20 LF 7 \$0 SF Walls - Plaster/Drywall 930 6 \$2,567 Classroom #215 (Store Room) AC Units ΕA 6 \$496 1 LF 5 Casework 8 \$1,673 damaged & deteriorating finish, veneer and hardware SF 7 \$0 Ceiling - Lay-in 690 SF 6 \$152 Doors - Transom Window 9 Doors - Wood Doors inclu hw 5 \$1,174 ΕA 1 5 Floor - Wood 690 SF \$10,094 warped boards and damaged finish Lighting - Lay-in ΕA 7 \$0 14 7 \$0 Marker Board 31 LF

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	om #215 (Store Room)	2004.011	quantity	•••••	. Carine	0001	
	Walls - Plaster/Drywall		330	SF	5	\$1.458	cracked plaster & peeling paint
	Walls - Plaster/Drywall		600	SF	6	\$1,656	
lassro	om #218 (Science Lab Level 1)						
5140010	AC Units		2	EA	7	\$0	
	Casework		- 81	LF	6	\$2,046	
	Ceiling - Lay-in		1,355	SF	7	\$0	
	Chalk Board		5	LF	4	\$459	obsolete material
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Tile		1,355	SF	5	\$6,084	cracked, chipped and missing tile
	Lighting - Lay-in		36	EA	7	\$0	
	Marker Board		45	LF	7	\$0	
	Storage/ Closet		125	SF	6	\$906	
	Walls - Plaster/Drywall		417	SF	5	\$1,843	cracked plaster & peeling paint
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
	Work Sink		4	EA	5	\$6,031	
Classro	om #222 (Regular Classroom)						
	AC Units		2	EA	6	\$991	
	Casework		149	LF	6	\$3,763	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		1,640	SF	7	\$0	hardward
	Chalk Board		6	LF	4	\$551	obsolete material
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Tile		1,640	SF	6	\$3,588	
	Lighting - Lay-in		34	EA	7	\$0	
	Marker Board		12	LF	7	\$0	
	Walls - Plaster/Drywall		317	SF	5		peeling paint
	Walls - Plaster/Drywall		1,300	SF	6	\$3,588	
lassro	om #227 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		900	SF	7	\$0	
	Ceiling - Plaster/Drywall		32	SF	7	\$0	
	Chalk Board		24	LF	4	\$2,203	obsolete material
	Doors - Side-lite		44	SF	6	\$736	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	

Building: Main

GroupIter. TypeLocationCostCommentsFloar-Tile192SF7S0Lighterg -Layin21SF7S0Marker Beard20LF7S0Walls - Plaster/Dynall26SF4S7.85Categorie X, Categorie M, Categorie	-			Quantities	I lest	Dert	0	Commente
Pior - Trie 92 PF 7 90 Liphing - Lay-in 21 PA 7 90 Marker Board 20 LF 7 90 Storage / Cleaet 136 SF 6 \$3936 Wals - Plaster/Drywall 50 SF 4 \$735 cracks in wall Wals - Plaster/Drywall 50 SF 4 \$5436 \$5753 cracks in wall AC Units 1 EA S \$595 \$5753 cracks in wall Caling - Lay-in 1229 SF 7 \$50 \$5753 \$5753 Dores - Transom Window 18 SF 6 \$9035 \$5753 \$5753 Dores - Wood Doors inclu In// 1293 SF 6 \$5035 \$5753 Uprimg - Lay-in 1307 SF 6 \$5234 \$5753 Marker Board 17 LF 6 \$5777 \$50 Caling - Lay-in 1307 SF 5 \$514 <th>-</th> <th></th> <th>Location</th> <th>Quantity</th> <th>Unit</th> <th>Rank</th> <th>Cost</th> <th>Comments</th>	-		Location	Quantity	Unit	Rank	Cost	Comments
Liphing - Lay-inCFSSSMarker Ford13SF650988Valle - Plaster/Dynall10SF650988Valle - Plaster/Dynall10SF650988AC Units11SF650988Caesorot10SF650988Caesorot10SF7500Caesorot12S75005009Caeling - Lay-in12SF7500Caeling - Lay-in12SF85009Const Coord During Waldow13S652711Coord Coord In Waldow13S652711Update David14S652711Update David14S652711Update David17LF65305Caesorot17LF65305AC Units18S7500Caesorot18S7500Caesorot18S7500Caesorot18S7500Caesorot18S5554,16Caesorot18S5554,16Caesorot18S5554,16Caesorot18S5554,16Caesorot18S5554,16Caesorot18<	Classro							
Markar DoardMarkar DoardFFFSSStorage Closet100SF6\$986\$986Wale - PlasterDywall100SF6\$930cacks in wallClassour100SF7\$000\$000\$100<								
Storage Closet 138 87 6 S98 7 8 Walls - PlasterDywall 100 57 6 \$333 cracke in wall AC Units AC Units 6 \$496 \$308 - AC Units 130 47 6 \$496 - Caserwork 30 47 6 \$496 - Caserwork 161 47 8 57 - \$400 Caserwork 163 47 6 \$436 -								
Walls - Pitester/Dynall565766stabilityWalls - Pitester/Dynall1,10057653.0057A C Units154654.00654.00Casework1.20577505050.00C Units1.205775050.0050.00C Datalk Board1.6057653.0050.0050.00Doors - Transen Window1.2057653.0050.00Doors - Wood Doors inclu hw1.2057653.0050.00Doors - Wood Doors inclu hw1.2057653.0050.00Doors - Wood Doors inclu hw1.2057653.0050.00Pitor - Tile1.2057653.0050.0050.00Marker Board157653.0050.0050.00Caling - Lay-in15775050.0050.00C Caling - Lay-in90057750.0050.0050.00C Caling - Lay-in157750.0050.0050.00C Caling - Lay-in157 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>								
Walls - Plaster/Dywall 1100 SF 6 \$3,036 Casework AC Unis Casework 30 Calak Koard 103 SF 6 \$5456 Chark Koard 118 SF 6 \$5030 Doors - Transon Window 138 SF 6 \$5030 Doors - Wood Doors indu hw 1238 SF 6 \$5030 Doors - Wood Doors indu hw 1238 SF 6 \$5030 Marke Board 1300 SF 6 \$5303 AC Unis Casework 7 S 5 \$50 \$5000 \$5000 \$50000 \$50000 \$500000 \$5000000000000000000000000000000000000		-						
Classroom #229 (At Room) I EA 6 \$446 AC Units 1 EA 6 \$476 Casework 120 SF 7 500 Chalk Board 16 LF 4 \$1.480 obsidee material Doors - Transom Window 18 SF 6 \$300 Doors - Transom Window 3 EA 6 \$903 Doors - Wood Doors indu hw 3 EA 6 \$304 Harter Board 17 LF 6 \$3364 Walls - Plaster/Drywall 130 SF 7 \$30 AC Units 1 EA 7 \$30 Casework 70 LF 6 \$3147 Casework 70 LF 6 \$3147 Valls - Plaster/Drywall 28 F 7 \$30 Casework 7 LF 6 \$3147 Casework 7 S0 \$4 \$223 \$4 Casework 7 S0 \$5 \$4 \$304								cracks in wall
AC Units 1 EA 6 \$496 Casework 30 LF 6 \$575 Caling - Lay-in 1.29 SF 7 \$50 Chaik Board 16 LF 4 \$1,469 obsolete material Doors - Transon Whow 18 SF 6 \$305 Doors - Wood Doors inclu hw 3 EA 6 \$903 Floor - Tile 1.239 SF 6 \$32,711 Lighting - Lay-in 30 EA 7 \$0 Marker Board 17 LF 6 \$33,607 Walls - Plaster/Dywall 1,007 SF 6 \$33,607 Clinits 1 LF 7 \$0 \$36,607 Casework 7 LF 6 \$37,607 Caling - Lay-in 1 EA 7 \$0 Casework 7 LF 6 \$37,67 Caling - Lay-in 22 SF 7 \$0		Walls - Plaster/Drywall		1,100	SF	6	\$3,036	
Casework130LF60\$758Celing - Layin1.28SF7\$00Chark Board1.6LF4\$1.40Doors - Transon Window3SF6\$2.51Doors - Wood Doors inclu hw3SF6\$2.711Floor - Tile1.293SF6\$2.711Marker Board1.00SF6\$2.711Marker Board1.00SF6\$2.51Marker Board1.00SF6\$2.51Casework1.00SF6\$2.51Casework7LF7\$00Celing - Layin900SF7\$00Casework7LF6\$7.60Casework7SF7\$00Celing - Layin900SF7\$00Casework1SF6\$3.76Casework1SF6\$3.76Casework1SF6\$3.60Chark Board24SF5\$4.165Doors - Side-line4SF6\$3.60Doors - Side-line1SF7\$00Doors - Side-line1SF7\$00Doors - Side-line1SF6\$3.60Doors - Side-line1SF6\$3.60Doors - Side-line1SF6\$3.60Marker Board1SF7\$00Marker Board1SF <td>Classro</td> <td>oom #228 (Art Room)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Classro	oom #228 (Art Room)						
Ceiling - Lay-in1.23SF7%0Chaik Board16154\$1.40\$000000000000000000000000000000000000		AC Units		1	EA	6	\$496	
Chaik Board16LF4\$1,460obsolute materialDoors - Transon Window38SF6\$303Doors - Wood Doors inclu hw3SF6\$203Floor - Tile1,239SF6\$24,71Marker Board1,307SF6\$346Walls - Plaster/Dryvall1,307SF6\$346AC Units1F6\$177Casework7LF6\$177Caling - Lay-in28SF7\$00Caling - Lay-in900SF7\$00Caling - Lay-in28SF7\$00Coling - Lay-in28SF7\$00Coling - Lay-in28SF7\$00Colors - Side-life28SF7\$00Doors - Side-life28SF7\$00Doors - Side-life29SF7\$00Doors - Side-life29SF7\$00Doors - Side-life29SF7\$00Doors - Side-life29SF7\$00Marker Board21SF7\$00Marker Board21SF7\$00Marker Board21SF7\$00Marker Board21SF7\$00Marker Board21SF7\$00Marker Board21SF7\$00Marker Board21SF7\$00 </td <td></td> <td>Casework</td> <td></td> <td>30</td> <td>LF</td> <td>6</td> <td>\$758</td> <td></td>		Casework		30	LF	6	\$758	
Doors - Transon Window 18 SF 6 S305 Doors - Wood Doors inclu hw 3 54 6 S297 Floor - Tile 1.239 SF 6 S271 Lighting - Lay-in 30 EA 7 S00 Walls - Plaster/Drywall 1.37 LF 6 S2364 Catsroom #220 (Reguta Classroom) 57 5 S364 AC Units 7 LF 6 S177 Cating - Plaster/Drywall 7 LF 6 S177 Cating - Plaster/Drywall 30 SF 7 S00 Colling - Plaster/Drywall 32 SF 7 S00 Colling - Plaster/Drywall 32 SF 5 S418 Doors - Side-life 33 SF 5 S418 Doors - Side-life 33 SF 5 S418 Doors - Wood Doors inclu hw 11 SF 5 S428 Doors - Wood Doors inclu hw 31 SF 7		Ceiling - Lay-in		1,239	SF	7	\$0	
Doors - Wood Doors inclu hw 3 EA 6 \$903 Floor - Tile 1,299 SF 6 \$2,711 Lighting - Lay-in 30 EA 7 \$360 Marker Board 17 LF 6 \$3361 Walls - Plaster/Dryvall 10 LF 6 \$3607 Classroom #229 (Regular Classroom) 1 EA 7 \$50 Caswork 1 EA 7 \$50 \$50 Caswork 1 EA 7 \$50 \$50 Casmod Coars inclu hw 1 EA 7 \$50 \$50 Caswork 7 LF 7 \$50 \$60 \$50 \$60 \$50 \$50 \$60 \$50 \$60 \$50 \$60 <td></td> <td>Chalk Board</td> <td></td> <td>16</td> <td>LF</td> <td>4</td> <td>\$1,469</td> <td>obsolete material</td>		Chalk Board		16	LF	4	\$1,469	obsolete material
Floor - Tile 1,239 SF 6 \$2,711 Lighting - Lay-in 30 E 7 \$0 Marker Board 1,00 SF 6 \$3,607 Classroom 1,00 SF 6 \$3,607 Classroom AC Units 7 KF 6 \$3,607 Casework 1 E/ 7 \$0 \$5 Caling - Lay-in 00 SF 7 \$0 \$5 Ceiling - Lay-in 32 SF 7 \$00 \$5 Coling - Plaster/Drywall 32 SF 7 \$00 \$5 Coling - Plaster/Drywall 32 SF 7 \$00 \$5 Doors - Side-Ite 4 SF 7 \$00 \$5 Doors - Wood Doors inclu hw 1 E/ 7 \$00 \$5 Age Plaster/Drywall Lighting - Lay-in \$2 SF 7 \$00 Marker Board Storage / Closet \$1 <t< td=""><td></td><td>Doors - Transom Window</td><td></td><td>18</td><td>SF</td><td>6</td><td>\$305</td><td></td></t<>		Doors - Transom Window		18	SF	6	\$305	
Lighting - Lay-in 30 EA 7 \$0 Marker Board 17 V 6 \$3.64 Walls - Plaster/Drywall 0.07 V V S3.66 Conscrete Conscre		Doors - Wood Doors inclu hw		3	EA	6	\$903	
Marker Board 17 LF 6 \$364 Walls - Plaster/Drywall 1,007 SF 6 \$3.607 Classroom AC Units 1 EA 7 \$50 Casework 7 LF 6 \$177 Ceiling - Lay-in 000 SF 7 \$00 Ceiling - Plaster/Drywall 22 SF 7 \$00 Ceiling - Plaster/Drywall 22 SF 7 \$00 Chilk Board 24 LF 4 \$2233 Charlk Board 24 LF 4 \$2203 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 932 SF 7 \$00 Marker Board 20 LF 7 \$00 Marker Board 20 LF 7 \$00 Marker Board 20 LF 7 \$00 Walls - Plaster/Drywall EA 7 \$0		Floor - Tile		1,239	SF	6	\$2,711	
Walls - Plaster/Drywall1,370SF6\$3,607ClastroomtAC Units1EA7\$0Casework7LF6\$177Cainig - Lay-in90SF7\$0Ceiling - Plaster/Drywall32SF7\$0Chalk Board24LF4\$2,203Doors - Sidel-lite332SF6\$736Doors - Nood Doors inclu hw1EA7\$0Floor - Tile932SF5\$4,4185Catage Closet21EA7\$0Marker Board20LF7\$0Storage/ Closet11EA7\$0Walls - Plaster/Drywall100SF6\$3,037Casemork21EA7\$0Marker Board21EA7\$0Marker Board21EA7\$0Marker Board10SF6\$3,037Walls - Plaster/Drywall100SF6\$3,037Marker Board100SF6\$3,037Marker Board10SF6\$3,037Marker Board10SF6\$3,037Marker Board10SF6\$3,037Marker Board10SF55Marker Board10SF6\$3,037Marker Board10SF6\$3,037Marker Board10SF5 <td></td> <td>Lighting - Lay-in</td> <td></td> <td>30</td> <td>EA</td> <td>7</td> <td>\$0</td> <td></td>		Lighting - Lay-in		30	EA	7	\$0	
Classroom #229 (Regular Classroom) I		Marker Board		17	LF	6	\$364	
AC Units 1 EA 7 \$0 Casework 7 LF 6 \$177 Ceiling - Lay-in 900 SF 7 \$0 Coors - Side-lite 24 LF 4 \$22,03 Doors - Side-lite 44 SF 6 \$736 Doors - Side-lite 44 SF 6 \$736 Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 932 SF 7 \$0 Marker Board 21 EA 7 \$0 Marker Board 20 LF 7 \$0 Storage/ Closet 136 SF 7 \$0 Walls - Plaster/Drywall 50 SF 4 \$735 Walls - Plaster/Drywall 50 SF 4 \$735 Walls - Plaster/Drywall 50 SF 4 \$735 Marker Board 1,00 SF 4 \$735 cracks in wall Walls - Plaster/Drywall 1,00 SF 4 \$735 cracks in wall		Walls - Plaster/Drywall		1,307	SF	6	\$3,607	
Casework 7 IF 6 \$177 Ceiling - Lay-in 900 SF 7 \$0 Ceiling - Plaster/Drywall 32 SF 7 \$0 Chalk Board 24 IF 4 \$2,203 Doors - Side-lite 44 SF 6 \$3736 Doors - Wood Doors inclu hw 1 EA 6 \$4145 Floor - Tile 932 SF 5 \$41,85 cracked tiles throughout Lighting - Lay-in 21 EA 7 \$0 stronge/Closet Marker Board 20 LF 7 \$0 stronge/Closet stronge/C	Classro	oom #229 (Regular Classroom)						
Ceiling - Lay-in 900 SF 7 \$0 Ceiling - Plaster/Drywall 32 SF 7 \$0 Chalk Board 24 LF 4 \$2,203 Doors - Side-lite 44 SF 6 \$3736 Doors - Side-lite 44 SF 6 \$3301 Doors - Side-lite 44 SF 5 \$4,485 cracked tiles throughout Eloor - Tile 932 SF 7 \$0 \$1 \$2,203 \$1 \$1 \$1 \$2 \$2 \$1 \$1 \$1 \$2 \$1 \$1 \$1 \$1 \$2 \$1 \$1 \$1 \$1 \$1 \$2 \$1 \$		AC Units		1	EA	7	\$0	
Ceiling - Plaster/Drywall 32 SF 7 \$0 Chalk Board 24 LF 4 \$2,203 Doors - Side-lite 44 SF 6 \$301 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 932 SF 5 \$4,185 cracked tiles throughout Lighting - Lay-in 20 LF 7 \$0 \$0 Marker Board 20 LF 7 \$0 \$0 Storage/Closet 136 SF 7 \$0 Walls - Plaster/Drywall 50 SF 6 \$3,03 Casework 10 SF 6 \$253 Casework 10 LF 6 \$253 Ceiling - Lay-in 1,23 <td< td=""><td></td><td>Casework</td><td></td><td>7</td><td>LF</td><td>6</td><td>\$177</td><td></td></td<>		Casework		7	LF	6	\$177	
Chalk Board 24 LF 4 \$2,203 Doors - Side-lite 44 SF 6 \$736 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 932 SF 5 \$4,185 cracked tiles throughout Lighting - Lay-in 21 EA 7 \$0 Marker Board 20 LF 7 \$0 Storage/ Closet 136 SF 7 \$0 Walls - Plaster/Drywall 50 SF 4 \$735 cracks in wall Walls - Plaster/Drywall 51 6 \$3,036 stack in wall Classroom 11 EA 7 \$0 Classroom #230 (Regular Classroom) 5 6 \$3,036 AC Units 1 EA 7 \$0 Casework 10 LF 6 \$253 Ceiling - Lay-in 1,233 SF 7 \$0		Ceiling - Lay-in		900	SF	7	\$0	
Doors - Side-lite 44 8F 6 \$736 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 932 SF 5 \$4,185 cracked tiles throughout Lighting - Lay-in 21 EA 7 \$0 Marker Board 20 LF 7 \$0 Storage/ Closet 136 SF 7 \$0 Walls - Plaster/Drywall 50 SF 4 \$73.03 Walls - Plaster/Drywall 50 SF 6 \$3.03 Classroom 1100 SF 6 \$3.03 Classework 100 SF 6 \$3.03 Casework 10 LF 6 \$2.53 Caling - Lay-in 1,233 SF 7 \$0		Ceiling - Plaster/Drywall		32	SF	7	\$0	
Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 932 SF 5 \$41,85 cracked tiles throughout Lighting - Lay-in 21 EA 7 \$0 Marker Board 20 LF 7 \$0 Storage/ Closet 136 SF 7 \$0 Walls - Plaster/Drywall 50 SF 4 \$735 cracks in wall Walls - Plaster/Drywall 58 6 \$3,036 \$100		Chalk Board		24	LF	4	\$2,203	
Floor - Tile932SF5\$4,185cracked tiles throughoutLighting - Lay-in21EA7\$0Marker Board20LF7\$0Storage/ Closet136SF7\$0Walls - Plaster/Drywall50SF4\$735cracks in wallWalls - Plaster/Drywall50SF6\$3,036\$1Classroom #230 (Regular Classroom)SF6\$3,036\$1\$1AC Units1EA7\$0\$1\$1Casework10LF6\$253\$1\$2Ceiling - Lay-in1,233SF7\$0\$1		Doors - Side-lite		44	SF	6	\$736	
Lighting - Lay-in21EA7\$0Marker Board20LF7\$0Storage/ Closet136SF7\$0Walls - Plaster/Drywall50SF4\$735cracks in wallWalls - Plaster/Drywall1,100SF6\$3,036Classroom/AC Units1EA7\$0Casework10LF6\$253Ceiling - Lay-in1,233SF7\$0		Doors - Wood Doors inclu hw		1	EA	6	\$301	
Marker Board20LF7\$0Storage/ Closet136SF7\$0Walls - Plaster/Drywall50SF4\$735cracks in wallWalls - Plaster/Drywall1,100SF6\$3,036Classroom #230 (Regular Classroom)AC Units1EA7\$0Casework10LF6\$253Ceiling - Lay-in1,233SF7\$0		Floor - Tile		932	SF	5	\$4,185	cracked tiles throughout
Storage/ Closet136SF7\$0Walls - Plaster/Drywall50SF4\$735cracks in wallWalls - Plaster/Drywall1,100SF6\$3,036\$3,036Classroom/AC Units1EA7\$0Casework10LF6\$253Ceiling - Lay-in1,233SF7\$0		Lighting - Lay-in		21	EA	7	\$0	
Walls - Plaster/Drywall50SF4\$735cracks in wallWalls - Plaster/Drywall1,100SF6\$3,036Classroom #230 (Regular Classroom)AC Units1EA7\$0Casework10LF6\$253Ceiling - Lay-in1,233SF7\$0		Marker Board		20	LF	7	\$0	
Walls - Plaster/Drywall1,100SF6\$3,036Classroom #230 (Regular Classroom)AC Units1EA7\$0Casework10LF6\$253Ceiling - Lay-in1,233SF7\$0		Storage/ Closet		136	SF	7	\$0	
Classroom #230 (Regular Classroom) AC Units 1 EA 7 \$0 Casework 10 LF 6 \$253 Ceiling - Lay-in 1,233 SF 7 \$0		Walls - Plaster/Drywall		50	SF	4	\$735	cracks in wall
AC Units 1 EA 7 \$0 Casework 10 LF 6 \$253 Ceiling - Lay-in 1,233 SF 7 \$0		Walls - Plaster/Drywall		1,100	SF	6	\$3,036	
AC Units 1 EA 7 \$0 Casework 10 LF 6 \$253 Ceiling - Lay-in 1,233 SF 7 \$0	Classro	oom #230 (Regular Classroom)						
Ceiling - Lay-in 1,233 SF 7 \$0				1	EA	7	\$0	
Ceiling - Lay-in 1,233 SF 7 \$0		Casework		10	LF	6	\$253	
		Ceiling - Lay-in		1,233	SF			

Building: Main

Classroom #20 (Regular Classroom) 2 K 6 S0 Doors inclu hw 23 SF 4 S2378 heles/hips in the Floor Tile 23 SF 4 S2378 heles/hips in the Lighting Layin 30 EA 7 S0 Storage Closet 153 SF 6 S2780 Walls - Plaster/Dywall 200 SF 6 S2760 Walls - Plaster/Dywall 200 SF 6 S2760 Walls - Plaster/Dywall 200 SF 7 S0 Cearry S13 (Regular Classroom) 28 SF 7 S0 Cearry Flaster/Dywall 200 SF 7 S0 Cearry Flaster/Dywall 200 SF 7 S0 Doors - Stde-tife 4 SF 6 S373 Doors - Wood Doors inclu hw 29 SF 7 S0 Hoar - Tile ST 7 S0 Storage Closet Walls - Plaster/Dyw	-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Doors - Wood Doors indu hw 2 EA 6 \$602 Floor - Tile 1,000 SF 6 \$2,379 holescinips in the Ploor - Tile 1,000 SF 6 \$2,188 Lighting - Layin 30 EA 7 \$0 Marker Board 18 LF 7 \$0 Storage Closet 13,00 SF 6 \$1,109 Walls - Plaster/Dywall 280 SF 5 \$1,237 Classroom #21 (Reguar Classroom) 280 SF 7 \$0 Calling - Plaster/Dywall 900 SF 7 \$0 Calling - Plaster/Dywall 90 SF 7 \$0 Calling - Plaster/Dywall 32 SF 7 \$0 Calling - Plaster/Dywall 32 SF 7 \$0 Calling - Plaster/Dywall 32 SF 5 \$4,415 Doors - Vood Doors indu hw 1 F 6 \$3101 Floor - Tile 32	-			quantity	0		0001	
Floor - Tile 32 SF 4 \$2,18 heles/chips in tile Lighting - Layin 30 EA 7 30 Marker Board 158 SF 6 \$2,183 Marker Board 158 SF 6 \$2,183 Walls - Plaster/Dywall 1000 SF 6 \$2,183 Walls - Plaster/Dywall 1000 SF 6 \$2,183 Cascom/file 1 EA 7 \$1,000 Cascom/file 1 EA 7 \$300 Doors Solde/life 3 SF 7 \$300 Doors Solde/life 4 EA 7 \$300 Doors Solde/life 4 EA 7 \$300 Marker Board 1 EA 7 \$300 Doors Solde/life<	elabere			2	FA	6	\$602	
Floor - Tile 1,000 SF 6 \$2,18 Lighting - Lay-in 30 Lif 7 \$30 Maker Board 163 SF 6 \$3,179 Walls - Plaster/Dywall 1,000 SF 6 \$3,776 Walls - Plaster/Dywall 200 SF 5 \$3,2760 Casework 7 LF 6 \$3,776 Doors - Side-file 32 SF 7 \$30 Doors - Side-file 32 SF 5 \$4,135 cacked tiles throughout Lighting - Lay-in 32 SF 5 \$4,135 cacked tiles throughout Lighting - Lay-in 32 SF 5 \$4,135 cacked tiles throughout Lighting - Lay-in								holes/chips in tile
Lighting - Lay-in 30 EA 7 \$00 Natker Board 18 LF 7 \$00 Storage/Cleaset 15.0 \$F 6 \$2,700 Walls - Plaster/Dywall 100 \$F 6 \$2,700 Clastroent 231 (Regular Classroom) 5F 6 \$2,700 Clastroent 231 (Regular Classroom) 5F 7 \$00 Caling - Lay-in 000 \$F 7 \$00 Caling - Lay-in 000 \$F 7 \$00 Controls 2F 7 \$00 \$000 \$1000 \$1000 \$10000 \$100000 \$100000 \$1000000000000000000000000000000000000								
Marker Board 16 LF 7 SO Name Board 150 SF 6 \$1,109 Walls - Plaster/Drywall 100 SF 6 \$2,270 Classroom #31 (Regular Classroom) 28 5 \$1,137 Classroom #31 (Regular Classroom) 8 7 \$1,07 AC Unis 5 \$1,137 \$1,081 Casework 7 LF 6 \$1,177 Casework 7 LF 6 \$1,177 Caling - Layin 30 SF 7 \$00 Doors - Side-life 32 SF 6 \$3,73 Doors - Side-life 32 SF 7 \$00 Marker Board 4 LF 7 \$00 Marker Board 110 SF 6 \$3,108 Valls - Plaster/Drywall 1100 SF 6 \$3,108 Valls - Plaster/Drywall 1100 SF 7 \$00 Marker Board 110				-				
Storage/ Closet 153 SF 6 \$1.103 Walls - Plaster/Dywall 1,000 SF 6 \$2.760 Classroom #231 (Regular Classroom) 7 \$50 \$1.500 Classroom #231 (Regular Classroom) 1 EA 7 \$00 \$50 \$1.500 Caling - Layin 900 SF 7 \$00 \$50 \$1.500 Doors - Wood Doors inclu hw 1 EA 6 \$3.01 \$500					LF			
Walls - Plaster/Dywall 1,000 SF 6 S2.760 Walls - Plaster/Dywall 28 5 5 51.23 Colume Casework 7 LF 6 S1.77 Caling - Layin 32 SF 7 S0 Caling - Ibaster/Drywall 32 SF 7 S0 Doors - Side-life 44 SF 6 S1.77 Doors - Side-life 32 SF 7 S0 Doors - Side-life 44 SF 6 S2.760 Doors - Side-life 32 SF 7 S0 Doors - Side-life 44 SF 6 S2.760 Marker Board 16 SF 7 S0 Marker Board 16 SF 7 S0 Walls - Plaster/Dywall 1100 SF 6 S2.30 Walls - Plaster/Dywall 1100 SF 7 S0 Caling - Layin 2 SF 7 S0 Caling - Layin 2 SF 7 S0 <td></td> <td></td> <td></td> <td></td> <td>SF</td> <td></td> <td></td> <td></td>					SF			
Walls - Plaster/Dywall 28 8 5 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$		-		1,000	SF	6		
Classroom #231 (Regular Classroom) I <thi< th=""> I I</thi<>		-			SF	5		
AC Units 1 EA 7 S0 Casework 7 LF 6 \$177 Colling - Lay-in 900 SF 7 \$0 Doors - Side-life 44 SF 6 \$331 Doors - Side-life 932 SF 5 \$4,185 cracked tiles throughout Lighting - Lay-in 21 EA 7 \$00 Marker Board 44 LF 7 \$0 Storage/Closet 18 SF 7 \$00 Walls - Plaster/Drywall 55 F 4 \$75 cracked tiles throughout Walls - Plaster/Drywall 24 LF 7 \$00 cracked tiles throughout Walls - Plaster/Drywall 55 F 4 \$75 cracked tiles throughout Walls - Plaster/Drywall 10 SF 7 \$00 cracked tiles throughout Casework 7 LF 6 \$320 cracked tiles throughout stern to the	Classro							
Casework 7 F 6 \$177 Ceiling - Layin 900 SF 7 \$00 Ceiling - Plaster/Drywall 32 SF 6 \$736 Doors - Side-lite 44 SF 6 \$736 Doors - Wood Doors inclu hw 1 EA 6 \$736 Floor - Tile 932 SF 7 \$00 Marker Board 44 LF 7 \$00 Marker Plaster/Drywall 518 \$7 \$0 \$00 Walls - Plaster/Drywall 518 \$7 \$0 \$00 Walls - Plaster/Drywall 518 \$7 \$0 \$00 Walls - Plaster/Drywall 518 \$7 \$0 \$00 Cassroot 7 LF \$6 \$37.30 Cassroot 5				1	EA	7	\$0	
Ceiling - Plaster/Drywall 32 SF 7 \$000000000000000000000000000000000000				7	LF	6		
Ceiling - Plaster/Drywall 32 SF 7 \$000 Doors - Side-life 44 SF 6 \$7736 Doors - Nood Doors inclu hw 1 EA 6 \$3014 Floor - Tile 32 SF 7 \$00 Lighting - Lay-in 21 EA 7 \$00 Marker Board 41 LF 7 \$00 Storage/ Closet 11 16 \$5 7 \$00 Walls - Plaster/Drywall 50 \$F 7 \$00 \$000000000000000000000000000000000000		Ceiling - Lay-in		900	SF	7	\$0	
Doors - Side-life 44 SF 6 \$736 Doors - Wood Doors inclu hw 1 EA 6 \$\$301 Floor - Tile 332 SF 5 \$\$4,185 cracked tiles throughout Lighting - Lay-in 321 EA 7 \$\$0 \$\$ Marker Board 44 LF 7 \$\$0 \$\$ Walls - Plaster/Drywall 50 SF 4 \$\$75 \$\$ \$				32	SF	7		
Floor - Tile 932 SF 5 \$4,185 cracked tiles throughout Lighting - Lay-in 21 EA 7 \$00 Marker Board 44 LF 7 \$00 Storage/ Closet 136 SF 4 \$7 \$00 Walls - Plaster/Drywall 55 4 \$735 cracks in wall Valls - Plaster/Drywall 5F 6 \$177 \$00 Classroom #233 (Regular Classroom) 7 LF 6 \$177 Casework 7 KF 6 \$177 Ceiling - Lay-in 900 SF 7 \$00 Ceiling - Iay-in 900 SF 7 \$00 Ceiling - Iay-in 900 SF 7 \$00 Doors - Side-life 4 ST 6 \$3736 Doors - Nood Doors inclu hw 1 EA 6 \$3736 Lighting - Lay-in 4 SF 5 \$4,185 cracks in floors Lighting - Lay-in 1 EA 7 \$00 S66 \$3736 S66				44	SF	6		
Lighting - Lay-in 21 EA 7 \$0 Marker Board 44 LF 7 \$0 Storage/ Closet 136 \$F 7 \$0 Walls - Plaster/Drywall 50 \$F 4 \$735 cracks in wall Walls - Plaster/Drywall 100 \$F 6 \$3.036 Classroom Classroom AC Units 1 EA 7 \$0 Casework 7 LF 6 \$177 Ceiling - Lay-in 900 SF 7 \$0 Ceiling - Plaster/Drywall 32 SF 7 \$0 Doors - Side-lite 32 SF 5 \$4,185 cracks in floors Doors - Wood Doors inclu hw 1 EA 7 \$0 \$1 \$4 \$F \$5 \$4,185 cracks in floors Floor - Tile 932 SF 5 \$4,185 cracks in floors \$1 \$2 \$4 \$735 \$2 Marker Board 44 LF 7 \$0		Doors - Wood Doors inclu hw		1	EA	6	\$301	
Marker Board 44 LF 7 \$0 Storage/Closet 136 SF 7 \$00 Walls - Plaster/Drywall 50 SF 6 \$33,03 Walls - Plaster/Drywall 1,100 SF 6 \$31,03 Casework 7 LF 6 \$177 Ceiling - Lay-in 900 SF 7 \$0 Doors - Side-lite 32 SF 7 \$0 Doors - Side-lite 44 SF 6 \$317 Floor - Tile 32 SF 7 \$0 Marker Board 1 EA 6 \$330 Floor - Tile 332 SF 7 \$0 Marker Board 4 LF 7 \$0 Marker Board 44 LF 7 \$0 Marker Board 16 SF 7		Floor - Tile		932	SF	5	\$4,185	cracked tiles throughout
Storage/ Closet136SF7%0Walls - Plaster/Drywall50SF4\$735cracks in wallWalls - Plaster/Drywall1100SF6\$3,036ClassroomAC Units1EA7\$0Casework7LF6\$177Ceiling - Lay-in900SF7\$0Coors - Side-lite44SF6\$736Doors - Side-lite44SF6\$301Floor - Tile932SF5\$4,185Lighting - Lay-in932SF7\$0Doors - Side-lite44SF6\$301Doors - Side-lite932SF5\$4,185Color Sinclu hw1EA7\$0Floor - Tile932SF7\$0Storage/ Closet136SF7\$0Walls - Plaster/Drywall136SF7\$0Walls - Plaster/Drywall130SF4\$735Kurde Doard14LF7\$0Walls - Plaster/Drywall55\$4,185cracks in wallWalls - Plaster/Drywall5S4\$735\$1Walls - Plaster/Drywall5S4\$735\$1Walls - Plaster/Drywall5S4\$735\$1Walls - Plaster/Drywall5S4\$735\$1Walls - Plaster/Drywall5S4		Lighting - Lay-in		21	EA	7	\$0	
Walls - Plaster/Drywall 50 SF 4 \$735 cracks in wall Walls - Plaster/Drywall 1100 SF 6 \$3,36 \$3,36 Classroom AC Units 1 EA 7 \$0 Casework 7 LF 6 \$177 Ceiling - Lay-in 32 SF 7 \$0 Doors - Side-lite 32 SF 7 \$0 Doors - Side-lite 4 SF 6 \$373 Floor - Tile 84 SF 5 \$4,155 racks in floors Lighting - Lay-in 21 EA 7 \$0 \$1 <td< td=""><td></td><td>Marker Board</td><td></td><td>44</td><td>LF</td><td>7</td><td>\$0</td><td></td></td<>		Marker Board		44	LF	7	\$0	
Walls - Plaster/Drywall 1,100 SF 6 \$3,306 Classroom 42 1,100 SF 6 \$3,036 AC Units 1 EA 7 \$0 Casework 7 LF 6 \$177 Ceiling - Lay-in 900 SF 7 \$0 Doors - Side-lite 44 SF 6 \$773 Doors - Side-lite 44 SF 6 \$736 Doors - Side-lite 44 SF 6 \$736 Doors - Side-lite 44 SF 6 \$736 Doors - Side-lite 44 SF 5 \$4,185 cracks in floors Lighting - Lay-in 24 6 \$736 \$0 Marker Board 24 17 \$0 \$0 Storage/ Closet 136 SF 7 \$0 \$0 Walls - Plaster/Drywall 5 5 \$4 \$735 \$0 Walls - Plaster/Drywall 5 6 \$33.03 \$0 \$0 Walls - Plaster/Drywall SF		Storage/ Closet		136	SF	7	\$0	
Classroom #233 (Regular Classroom) I EA 7 \$0 AC Units 1 EA 7 \$0 Casework 7 LF 6 \$177 Ceiling - Lay-in 900 SF 7 \$0 Ceiling - Plaster/Drywall 32 SF 7 \$0 Doors - Side-lite 44 SF 6 \$3736 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 932 SF 5 \$4,185 cracks in floors Lighting - Lay-in 21 EA 7 \$0 \$0 Marker Board 44 LF 7 \$0 \$0 Storage/ Closet 136 SF 7 \$0 Walls - Plaster/Drywall 50 SF 4 \$735 cracks in wall Walls - Plaster/Drywall 10 SF 6 \$3,036 \$1		Walls - Plaster/Drywall		50	SF	4	\$735	cracks in wall
AC Units 1 EA 7 \$0 Casework 7 LF 6 \$177 Ceiling - Lay-in 900 SF 7 \$0 Ceiling - Plaster/Drywall 32 SF 7 \$0 Doors - Side-lite 32 SF 6 \$736 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 932 SF 5 \$4,185 cracks in floors Lighting - Lay-in 21 EA 7 \$0 Marker Board 44 LF 7 \$0 Storage/ Closet 136 SF 7 \$0 Walls - Plaster/Drywall 50 SF 4 \$735 cracks in wall Walls - Plaster/Drywall 1,100 SF 6 \$3,036 \$3,036		Walls - Plaster/Drywall		1,100	SF	6	\$3,036	
Casework 7 LF 6 \$177 Ceiling - Lay-in 900 SF 7 \$0 Ceiling - Plaster/Drywall 32 SF 7 \$0 Doors - Side-lite 44 SF 6 \$736 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 932 SF 5 \$4,185 cracks in floors Lighting - Lay-in 21 EA 7 \$0 \$0 Marker Board 44 LF 7 \$0 \$0 Storage/ Closet 136 SF 7 \$0 Walls - Plaster/Drywall 50 SF 4 \$735 cracks in wall Walls - Plaster/Drywall 50 SF 6 \$3,036 \$1 Classroom #235 (Regular Classroom) 50 S 6 \$3,036 \$1	Classro	oom #233 (Regular Classroom)						
Ceiling - Lay-in 900 SF 7 \$0 Ceiling - Plaster/Drywall 32 SF 7 \$0 Doors - Side-lite 44 SF 6 \$736 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 932 SF 5 \$4,185 cracks in floors Lighting - Lay-in 21 EA 7 \$0 \$16 Marker Board 44 LF 7 \$0 \$16 Storage/ Closet 136 SF 7 \$0 Walls - Plaster/Drywall 50 SF 4 \$736 Walls - Plaster/Drywall 50 SF 6 \$3,031		AC Units		1	EA	7	\$0	
Ceiling - Plaster/Drywall 32 SF 7 \$0 Doors - Side-lite 44 SF 6 \$736 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 932 SF 5 \$4,185 cracks in floors Lighting - Lay-in 21 EA 7 \$0 Marker Board 44 LF 7 \$0 Storage/ Closet 136 SF 7 \$0 Walls - Plaster/Drywall 50 SF 4 \$735 cracks in wall Walls - Plaster/Drywall 50 SF 6 \$3,036 SF 5 \$3,036		Casework		7	LF	6	\$177	
Doors - Side-lite44SF6\$736Doors - Wood Doors inclu hw1EA6\$301Floor - Tile932SF5\$4,185cracks in floorsLighting - Lay-in21EA7\$0Marker Board44LF7\$0Storage/ Closet136SF7\$0Walls - Plaster/Drywall50SF4\$735cracks in wallWalls - Plaster/Drywall1,100SF6\$3,036Storacks in wall		Ceiling - Lay-in		900	SF	7	\$0	
Doors - Wood Doors inclu hw1EA6\$301Floor - Tile932SF5\$4,185cracks in floorsLighting - Lay-in21EA7\$0Marker Board44LF7\$0Storage/ Closet136SF7\$0Walls - Plaster/Drywall50SF4\$735cracks in wallWalls - Plaster/Drywall1,100SF6\$3,036		Ceiling - Plaster/Drywall		32	SF	7	\$0	
Floor - Tile932SF5\$4,185cracks in floorsLighting - Lay-in21EA7\$0Marker Board44LF7\$0Storage/ Closet136SF7\$0Walls - Plaster/Drywall50SF4\$735cracks in wallWalls - Plaster/Drywall1,100SF6\$3,036				44	SF	6		
Lighting - Lay-in21EA7\$0Marker Board44LF7\$0Storage/ Closet136SF7\$0Walls - Plaster/Drywall50SF4\$735cracks in wallWalls - Plaster/Drywall1,100SF6\$3,036Classroom #235 (Regular Classroom)		Doors - Wood Doors inclu hw		1	EA	6	\$301	
Marker Board 44 LF 7 \$0 Storage/ Closet 136 SF 7 \$0 Walls - Plaster/Drywall 50 SF 4 \$735 cracks in wall Walls - Plaster/Drywall 1,100 SF 6 \$3,036				932	SF	5		cracks in floors
Storage/ Closet 136 SF 7 \$0 Walls - Plaster/Drywall 50 SF 4 \$735 cracks in wall Walls - Plaster/Drywall 1,100 SF 6 \$3,036				21	EA	7		
Walls - Plaster/Drywall 50 SF 4 \$735 cracks in wall Walls - Plaster/Drywall 1,100 SF 6 \$3,036				44	LF	7		
Walls - Plaster/Drywall 1,100 SF 6 \$3,036 Classroom #235 (Regular Classroom) 5 5		-		136	SF	7	\$0	
Classroom #235 (Regular Classroom)		-			-	4		cracks in wall
		Walls - Plaster/Drywall		1,100	SF	6	\$3,036	
	Classro	oom #235 (Regular Classroom)						
AC Units 1 EA 7 \$0		AC Units		1	EA	7	\$0	

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #235 (Regular Classroom)						
	Ceiling - Lay-in		1,080	SF	7	\$0	
	Chalk Board		18	LF	4	\$1,653	
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		380	SF	4	\$3,880	cupped/loose tile
	Floor - Tile		700	SF	5	\$3,143	
	Lighting - Lay-in		21	EA	7	\$0	
	Lighting - Pendent/Surface		1	EA	7	\$0	
	Marker Board		28	LF	7	\$0	
	Walls - Plaster/Drywall		1,180	SF	7	\$0	
Classrc	oom #318 (Science Lab Level 2)						
	AC Units		2	EA	6	\$991	
	Casework		66	LF	6	\$1,667	
	Ceiling - Lay-in		1,325	SF	7	\$0	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		1,325	SF	6	\$2,899	
	Gas Line		2	EA	6	\$1,018	
	Lighting - Lay-in		36	EA	7	\$0	
	Marker Board		12	LF	6	\$257	
	Storage/ Closet		84	SF	6	\$609	
	Walls - Plaster/Drywall		1,228	SF	6	\$3,389	
	Walls - Plaster/Drywall		30	SF	5	\$153	peeling paint
	Work Sink		3	EA	6	\$1,137	
Classrc	oom #319 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		8	LF	6	\$202	
	Ceiling - Lay-in		1,068	SF	6	\$3,207	
	Ceiling - Lay-in		20	SF	5	\$160	water stains
	Chalk Board		10	LF	4	\$918	obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		1,088	SF	6	\$7,670	
	Lighting - Lay-in		21	EA	7	\$0	
	Marker Board		28	LF	6	\$600	
	Walls - Plaster/Drywall		1,129	SF	6	\$3,116	

Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #321 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		10	LF	6	\$253	
	Ceiling - Lay-in		1,148	SF	6	\$3,447	
	Ceiling - Lay-in		8	SF	4		missign tile, water damage.
	Chalk Board		14	LF	4		obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		1,156	SF	6	\$8,150	
	Lighting - Lay-in		21	EA	7	\$0	
	Marker Board		30	LF	6	\$643	
	Walls - Plaster/Drywall		676	SF	6	\$1,866	
Classro	oom #323 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		16	LF	6	\$404	
	Ceiling - Lay-in		1,020	SF	7	\$0	
	Chalk Board		16	LF	4	\$1,469	obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		1,020	SF	6	\$7,191	
	Lighting - Lay-in		18	EA	7	\$0	
	Marker Board		24	LF	7	\$0	
	Walls - Plaster/Drywall		566	SF	5	\$4,290	cracks on wall
	Walls - Plaster/Drywall		403	SF	6	\$1,320	Wood Paneling wall
Classro	oom #327 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		890	SF	7	\$0	
	Ceiling - Plaster/Drywall		36	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		916	SF	6	\$2,004	
	Floor - Tile		10	SF	4	\$130	cracks in tile
	Lighting - Lay-in		21	EA	7	\$0	
	Marker Board		26	LF	7	\$0	
	Storage/ Closet		144	SF	7	\$0	
	Walls - Plaster/Drywall		1,075	SF	6	\$2,967	
	,		.,		-	,	

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #329 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		890	SF	7	\$0	
	Ceiling - Plaster/Drywall		36	SF	7	\$0	
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		36	SF	4	\$309	cracked tiles
	Floor - Wood		890	SF	7	\$0	
	Lighting - Lay-in		21	EA	7	\$0	
	Marker Board		26	LF	7	\$0	
	Storage/ Closet		144	SF	6	\$1,044	
	Walls - Plaster/Drywall		1,075	SF	6	\$2,967	
Classro	oom #331 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		890	SF	7	\$0	
	Ceiling - Plaster/Drywall		36	SF	7	\$0	
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Weight/ Fitness Room Floor Matting		926	SF	6	\$4,846	
	Lighting - Lay-in		21	EA	7	\$0	
	Marker Board		26	LF	7	\$0	
	Storage/ Closet		144	SF	5	\$2,323	
	Walls - Plaster/Drywall		1,000	SF	6	\$2,760	
	Walls - Plaster/Drywall		75	SF	4	\$1,103	cracks in wall
Classro	oom #333 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	5	\$1,464	
	Ceiling - Lay-in		890	SF	7	\$0	
	Ceiling - Plaster/Drywall		36	SF	7	\$0	
	Chalk Board		12	LF	4	\$1,102	
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		926	SF	6	\$6,528	
	Lighting - Lay-in		21	EA	7	\$0	
	Marker Board		26	LF	7	\$0	

Building: Main

Categ	jory: Classrooms						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #333 (Regular Classroom)						
	Storage/ Closet		144	SF	5	\$2,323	
	Walls - Plaster/Drywall		75	SF	4	\$1,103	cracks in wall
	Walls - Plaster/Drywall		1,000	SF	6	\$2,760	
Classro	oom #335 (Computer Lab)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		890	SF	7	\$0	
	Ceiling - Plaster/Drywall		36	SF	7	\$0	
	Chalk Board		12	LF	4	\$1,102	
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		926	SF	6	\$2,026	
	Lighting - Lay-in		21	EA	7	\$0	
	Marker Board		26	LF	7	\$0	
	Storage/ Closet		144	SF	7	\$0	
	Walls - Plaster/Drywall		1,075	SF	6	\$2,967	
Classro	oom #in Boy's Gym (Weight)						
	Ceiling - Plaster/Drywall	1st Floor	30	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Carpet	1st Floor	30	SF	6	\$64	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	70	SF	7	\$0	
	Walls - Tile Ceramic/ Porcelain	1st Floor	144	SF	6	\$325	
	Work Sink	1st Floor	1	EA	7	\$0	This is a Water Closet!
-							

Classrooms Subtotal:

\$448,635

Building: Main

Group Item - Type	Location	Quantity	Unit	Rank	Cost Comments	
Administrative Suites/Offices						
Ceiling - Lay-in	025 Office Reception	366	SF	7	\$0	
Doors - Wood Doors inclu hw	025 Office Reception	1	EA	7	\$O	
Floor - Tile	025 Office Reception	326	SF	7	\$O	
Floor - Tile Quarry	025 Office Reception	40	SF	6	\$85	
Lighting - Lay-in	025 Office Reception	8	EA	7	\$0	



Building: Main

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	trative Suites/Offices						
	Walls - Metal Panel	025 Office Reception	540	SF	7	\$0	fabric
	Work SInk	025 Office Reception	1	EA	5	\$1,508	
	Ceiling - Lay-in	025A	76	SF	7	\$0	
	Doors - Wood Doors inclu hw	025A	1	EA	7	\$0	
	Floor - Tile	025A	76	SF	7	\$0	
	Lighting - Lay-in	025A	2	EA	7	\$0	
	Power Distribution	025A	10	EA	7	\$0	
	Walls - Metal Panel	025A	256	SF	7	\$0	vinyl
	Work Sink	025A	1	EA	7	\$0	
	Ceiling - Lay-in	025B	90	SF	7	\$0	
	Doors - Wood Doors inclu hw	025B	1	EA	7	\$0	
	Floor - Tile	025B	90	SF	7	\$0	
	Lighting - Lay-in	025B	2	EA	7	\$0	
	Power Distribution	025B	10	EA	7	\$0	
	Walls - Metal Panel	025B	50	SF	6	\$453	fabric
	Walls - Metal Panel	025B	240	SF	7	\$0	vinyl
	Work Sink	025B	1	EA	7	\$0	
	Ceiling - Lay-in	025C	168	SF	7	\$0	
	Doors - Wood Doors inclu hw	025C	1	EA	7	\$0	
	Floor - Tile	025C	168	SF	7	\$0	
	Lighting - Lay-in	025C	2	EA	7	\$0	
	Power Distribution	025C	6	EA	7	\$0	
	Walls - Metal Panel	025C	384	SF	7	\$0	fabric
	Work SInk	025C	1	EA	7	\$0	
	Ceiling - Lay-in	025D	170	SF	7	\$0	
	Doors - Wood Doors inclu hw	025D	1	EA	7	\$0	
	Floor - Tile	025D	170	SF	7	\$0	
	Lighting - Lay-in	025D	2	EA	7	\$0	
	Power Distribution	025D	8	EA	7	\$0	
	Walls - Metal Panel	025D	384	SF	7	\$0	fabric
	Ceiling - Lay-in	025E	170	SF	7	\$0	
	Doors - Wood Doors inclu hw	025E	1	EA	7	\$0	
	Floor - Tile	025E	170	SF	7	\$0	
	Lighting - Lay-in	025E	2	EA	7	\$0	
	Power Distribution	025E	8	EA	7	\$0	
	Walls - Metal Panel	025E	360	SF	7	\$0	fabric
	Ceiling - Lay-in	031A	85	SF	7	\$0	



Building: Main

Jp Ite	em - Type	Location	Quantity	Unit	Rank	Cost	Comments
inistra	tive Suites/Offices						
Do	oors - Wood Doors inclu hw	031A	1	EA	6	\$301	
Flo	oor - Carpet	031A	85	SF	6	\$181	
Liç	ghting - Lay-in	031A	2	EA	6	\$238	
Pc	ower Distribution	031A	2	EA	6	\$4,250	
W	alls - Plaster/Drywall	031A	248	SF	6	\$684	
AC	C Unit	114 Office	1	EA	6	\$496	
Ce	eiling - Lay-in	114 Office	209	SF	7	\$0	
Do	oors - Transom Window	114 Office	18	SF	5	\$762	missing glazing
Do	pors - Wood Doors inclu hw	114 Office	2	EA	6	\$602	
Flo	oor - Tile	114 Office	209	SF	6	\$457	
Liç	ghting - Lay-in	114 Office	4	EA	7	\$0	
Pc	ower Distribution	114 Office	19	EA	6	\$40,373	10 outlets taped over
W	alls - Plaster/Drywall	114 Office	200	SF	5	\$884	cracked plaster & peeling paint
W	alls - Plaster/Drywall	114 Office	400	SF	6	\$1,104	
AC	C Unit	116 Tech Room, adj to classroom 118	1	EA	7	\$0	
Ce	eiling - Lay-in	116 Tech Room, adj to classroom 118	255	SF	7	\$0	
Do	oors - Wood Doors inclu hw	116 Tech Room, adj to classroom 118	1	EA	7	\$0	
Flo	oor - Tile	116 Tech Room, adj to classroom 118	255	SF	6	\$558	
Liç	ghting - Lay-in	116 Tech Room, adj to classroom 118	6	EA	7	\$0	
Pc	ower Distribution	116 Tech Room, adj to classroom 118	10	EA	7	\$0	
W	alls - Plaster/Drywall	116 Tech Room, adj to classroom 118	217	SF	5	\$959	cracked plaster & peeling paint
W	alls - Plaster/Drywall	116 Tech Room, adj to classroom 118	400	SF	6	\$1,104	
AC	C Unit	119 Social Room	2	EA	6	\$991	
Ce	eiling - Lay-in	119 Social Room	1,179	SF	6	\$3,541	
Do	pors - Transom Window	119 Social Room	18	SF	6	\$305	
Do	oors - Wood Doors inclu hw	119 Social Room	2	EA	6	\$602	
Flo	oor - Tile	119 Social Room	1,179	SF	6	\$2,580	
Liç	ghting - Lay-in	119 Social Room	22	EA	7	\$0	
Pc	ower Distribution	119 Social Room	4	EA	6	\$8,500	
St	orage/ Closet	119 Social Room	77	SF	6	\$558	
W	alls - Plaster/Drywall	119 Social Room	1,290	SF	6	\$3,560	
Ce	eiling - Splined	119A Kitchenette	203	SF	6	\$165	
Do	oors - Wood Doors inclu hw	119A Kitchenette	1	EA	6	\$301	
Flo	oor - Tile	119A Kitchenette	203	SF	6	\$444	
Liç	ghting - Pendent/Surface	119A Kitchenette	5	EA	7	\$0	
	ower Distribution	119A Kitchenette	10	EA	6	\$21,249	
W	alls - Plaster/Drywall	119A Kitchenette	657	SF	6	\$1,813	



Building: Main

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Work SInk	119A Kitchenette	1	EA	6	\$508	
	Ceiling - Plaster/Drywall	124A Girls Gym Office	249	SF	4	\$3,749	water damage and peeling paint
	Doors - Wood Doors inclu hw	124A Girls Gym Office	1	EA	6	\$301	
	Floor - Tile	124A Girls Gym Office	249	SF	6	\$545	
	Lighting - Pendent/Surface	124A Girls Gym Office	6	EA	6	\$743	
	Walls - Plaster/Drywall	124A Girls Gym Office	972	SF	6	\$2,683	
	Ceiling - Plaster/Drywall	125 - Counseling Office	194	SF	7	\$0	
	Doors - Side-lite	125 - Counseling Office	66	SF	6	\$1,103	
	Doors - Transom Window	125 - Counseling Office	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	125 - Counseling Office	1	EA	6	\$301	
	Floor - Carpet	125 - Counseling Office	194	SF	7	\$0	
	Lighting - Pendent/Surface	125 - Counseling Office	4	EA	7	\$0	
	Power Distribution	125 - Counseling Office	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	125 - Counseling Office	600	SF	6	\$1,656	
	Walls - Plaster/Drywall	125 - Counseling Office	100	SF	5	\$442	
	Ceiling - Plaster/Drywall	225 Office	193	SF	7	\$0	
	Doors - Side-lite	225 Office	60	SF	6	\$1,003	
	Doors - Transom Window	225 Office	6	SF	6	\$102	
	Doors - Wood Doors inclu hw	225 Office	1	EA	5	\$1,174	
	Floor - Carpet	225 Office	193	SF	6	\$411	
	Lighting - Pendent/Surface	225 Office	4	EA	6	\$496	
	Power Distribution	225 Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	225 Office	416	SF	6	\$1,148	
	Ceiling - Lay-in	317 Office	180	SF	7	\$0	
	Doors - Transom Window	317 Office	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	317 Office	1	EA	6	\$301	
	Floor - Carpet	317 Office	180	SF	5	\$924	
	Lighting - Lay-in	317 Office	4	EA	7	\$0	
	Power Distribution	317 Office	3	EA	6	\$6,375	
	Walls - Plaster/Drywall	317 Office	498	SF	6	\$1,374	
	Ceiling - Lay-in	325 Counseling Office	326	SF	7	\$0	
	Doors - Side-lite	325 Counseling Office	40	SF	6	\$669	
	Doors - Transom Window	325 Counseling Office	6	SF	6	\$102	
	Doors - Wood Doors inclu hw	325 Counseling Office	1	EA	6	\$301	
	Floor - Carpet	325 Counseling Office	326	SF	5	\$1,674	
	Lighting - Lay-in	325 Counseling Office	4	EA	7	\$0	
	Lighting - Lay-in	325 Counseling Office	2	EA	6	\$238	



Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
dminis	strative Suites/Offices						
	Walls - Plaster/Drywall	325 Counseling Office	614	SF	6	\$1,695	
	Work SInk	325 Counseling Office	1	EA	5	\$1,508	non-operational and cracked
	Ceiling - Plaster/Drywall	Boys Gym Office	180	SF	6	\$623	
	Doors - Wood Doors inclu hw	Boys Gym Office	1	EA	5	\$1,174	
	Floor - Tile	Boys Gym Office	180	SF	6	\$394	
	Lighting - Pendent/Surface	Boys Gym Office	3	EA	7	\$0	
	Storage/ Closet	Boys Gym Office	136	SF	5	\$2,194	
	Walls - Plaster/Drywall	Boys Gym Office	731	SF	6	\$2,017	
	Work SInk	Boys Gym Office	1	EA	6	\$508	
	AC Unit	Kitchen Office	1	EA	5	\$1,826	
	Ceiling - Lay-in	Kitchen Office	310	SF	7	\$0	
	Ceiling - Lay-in	Kitchen Office	12	SF	4	\$169	stained
	Doors - Wood Doors inclu hw	Kitchen Office	1	EA	6	\$301	
	Floor - Tile	Kitchen Office	322	SF	7	\$0	
	Lighting - Lay-in	Kitchen Office	4	EA	7	\$0	
	Power Distribution	Kitchen Office	8	EA	6	\$16,999	
	Storage/ Closet	Kitchen Office	350	SF	6	\$2,538	
	Walls - Masonry	Kitchen Office	310	SF	7	\$0	
	Walls - Plaster/Drywall	Kitchen Office	285	SF	6	\$787	
uditor	ium & Theater						
	AC Unit	1st Floor	2	EA	6	\$991	
	Ceiling - Lay-in	1st Floor	1,632	SF	6	\$4,901	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	1,632	SF	7	\$0	
	Lighting - Lay-in	1st Floor	30	EA	7	\$0	
	Main Floor Seating	1st Floor	158	EA	6	\$27,479	
	Stage	1st Floor	408	SF	6	\$2,357	
	Stage-Stairs - Wood	1st Floor	12	LF	6	\$141	
	Walls - Plaster/Drywall	1st Floor	1,259	SF	6	\$5,995	
	Balcony Seating		583	EA	6	\$101,393	
	Ceiling - Plaster/Drywall		3,600	SF	7	\$0	Main
	Ceiling - Plaster/Drywall		1,500	SF	7	\$0	Under balcony
	Ceiling - Plaster/Drywall		3,700	SF	7	\$0	Balcony
	Doors - Wood Doors inclu hw		12	EA	6	\$3,612	
	Floor - Concrete		4,400	SF	6	\$2,328	Main floor
	Floor - Wood		3,700	SF	6	\$26,085	



Building: Main

up	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
itori	um & Theater						
	Lighting - Pendent/Surface		20	EA	7	\$0	
	Main Floor Seating		612	EA	6	\$106,437	
	Sound System		1	EA	7	\$0	
	Stage		1,200	SF	7	\$0	Wood
	Stage Curtain		3	EA	6	\$0	
	Stage Lighting System		1	EA	7	\$0	
	Stage-Stairs - Wood		54	LF	6	\$634	
	Walls - Plaster/Drywall		5,700	SF	7	\$0	Balcony
	Walls - Plaster/Drywall		3,900	SF	7	\$0	Main
	Walls - Plaster/Drywall		3,800	SF	7	\$0	Stage
nnas	sia						
	Ceiling - Plaster/Drywall	124 South (Girls) Gym	3,200	SF	6	\$17,663	
	Doors - Transom Window	124 South (Girls) Gym	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	124 South (Girls) Gym	4	EA	6	\$1,204	
	Floor - Wood	124 South (Girls) Gym	3,200	SF	6	\$22,560	
	Lighting - Pendent/Surface	124 South (Girls) Gym	12	EA	7	\$0	
	Storage/ Closet	124 South (Girls) Gym	414	SF	6	\$3,002	
	Walls - Plaster/Drywall	124 South (Girls) Gym	3,767	SF	5	\$28,550	
	Walls - Structural Glazed Tile	124 South (Girls) Gym	1,891	SF	6	\$5,949	
	Ceiling - Plaster/Drywall	North (Boys) Gym	100	SF	4	\$3,363	Water damage
	Ceiling - Plaster/Drywall	North (Boys) Gym	8,200	SF	7	\$0	Ceiling High
	Ceiling - Plaster/Drywall	North (Boys) Gym	3,400	SF	6	\$22,268	
	Doors - Wood Doors inclu hw	North (Boys) Gym	4	EA	4	\$13,652	Damaged and worn
	Floor - Wood	North (Boys) Gym	8,000	SF	6	\$56,399	
	Lighting - Pendent/Surface	North (Boys) Gym	28	EA	7	\$0	
	Scoreboards	North (Boys) Gym	1	EA	7	\$0	
	Walls - Masonry	North (Boys) Gym	4,400	SF	6	\$13,842	Glazed
	Walls - Plaster/Drywall	North (Boys) Gym	4,400	SF	7	\$0	Track level
hen							
	Ceiling - Lay-in	1st Floor	26	SF	5	\$207	
	Ceiling - Lay-in	1st Floor	1,900	SF	7	\$0	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	5	\$1,174	
	Floor - Tile Quarry	1st Floor	126	SF	4	\$6,923	Cracked
	Floor - Tile Quarry	1st Floor	1,800	SF	6	\$3,810	
	Lighting - Pendent/Surface	1st Floor	1	EA	5	\$183	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Kitchen	l						
	Lighting - Pendent/Surface	1st Floor	21	EA	6	\$2,602	
	Walls - Plaster/Drywall	1st Floor	90	SF	4	\$1,323	Water damage
	Walls - Plaster/Drywall	1st Floor	1,900	SF	6	\$5,244	
	Walls - Structural Glazed Tile	1st Floor	230	SF	7	\$0	
	Ceiling - Plaster/Drywall	Dishwashing Room	264	SF	7	\$0	
	Doors - Wood Doors inclu hw	Dishwashing Room	1	EA	6	\$301	
	Floor - Tile Quarry	Dishwashing Room	264	SF	6	\$559	
	Lighting - Pendent/Surface	Dishwashing Room	4	EA	7	\$0	
	Storage/ Closet	Dishwashing Room	16	SF	7	\$0	
	Walls - Tile Ceramic/ Porcelain	Dishwashing Room	742	SF	6	\$1,676	
	Ceiling - Exposed	Serving Room	190	SF	6	\$283	
	Ceiling - Lay-in	Serving Room	1,350	SF	7	\$0	
	Doors - Wood Doors inclu hw	Serving Room	4	EA	7	\$0	
	Floor - Tile Quarry	Serving Room	1,540	SF	6	\$3,259	
	Lighting - Lay-in	Serving Room	20	EA	7	\$0	
	Lighting - Pendent/Surface	Serving Room	20	EA	7	\$0	
	Serving Line	Serving Room	105	LF	7	\$0	
	Walls - Plaster/Drywall	Serving Room	950	SF	6	\$2,622	
Library							
	AC Unit	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	935	LF	5	\$195,490	
	Ceiling - Lay-in	2nd Floor	1,869	SF	7	\$0	
	Ceiling - Lay-in	2nd Floor	8	SF	4	\$112	water damage
	Doors - Transom Window	2nd Floor	27	SF	4	\$2,064	missing glazing
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	\$0	
	Floor - Carpet	2nd Floor	2,840	SF	5	\$14,580	
	Lighting - Lay-in	2nd Floor	60	EA	7	\$0	
	Storage/ Closet	2nd Floor	378	SF	6	\$2,741	
	Walls - Plaster/Drywall	2nd Floor	1,877	SF	6	\$5,180	
Locker/	Shower Room						
	Accessories	Basement off Pool	1,090	SF	6	\$4,271	
	Benches, ped mounted	Basement off Pool	60	LF	5	\$16,485	
	Ceiling - Plaster/ Drywall	Basement off Pool	1,090	SF	7	\$0	
	Doors - Wood Doors inclu hw	Basement off Pool	3	EA	5	\$3,522	
	Doors - Wood Doors inclu hw	Basement off Pool	1	EA	6	\$301	
	Floor Drain	Basement off Pool	1	EA	6	\$1,059	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker	/Shower Room						
	Floor - Concrete	Basement off Pool	275	SF	5	\$472	
	Floor - Tile Ceramic/ Porcelain	Basement off Pool	815	SF	6	\$1,725	
	Hand Dryer	Basement off Pool	2	EA	5	\$1,181	non-operational
	Hand Dryer	Basement off Pool	3	EA	6	\$690	
	Lavatory	Basement off Pool	1	EA	5	\$3,763	
	Lighting - Pendent/Surface	Basement off Pool	26	EA	6	\$3,221	
	Partitions	Basement off Pool	13	EA	6	\$3,860	
	Showers	Basement off Pool	9	EA	5	\$24,430	non-operational
	Student Lockers - One Tier	Basement off Pool	24	EA	6	\$2,228	
	Walls - Masonry	Basement off Pool	120	SF	5	\$4,959	
	Walls - Metal Panel	Basement off Pool	400	SF	4	\$39,891	Stone Panel - erroded/damaged panels
	Walls - Plaster/Drywall	Basement off Pool	390	SF	6	\$1,076	
	Walls - Tile Ceramic/ Porcelain	Basement off Pool	1,000	SF	6	\$2,259	
	Water Closet	Basement off Pool	1	EA	6	\$336	
Lunch	& Multipurpose Room						
	AC Unit	123 Commons	2	EA	6	\$991	
	Ceiling - Lay-in	123 Commons	1,632	SF	7	\$0	
	Chalk Board	123 Commons	5	LF	4	\$459	obsolete material
	Doors - Transom Window	123 Commons	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	123 Commons	2	EA	6	\$602	
	Floor - Wood	123 Commons	1,632	SF	6	\$11,505	
	Lighting - Lay-in	123 Commons	30	EA	7	\$0	
	Market Board	123 Commons	24	LF	6	\$514	
	Stage	123 Commons	408	SF	6	\$2,357	
	Walls - Plaster/Drywall	123 Commons	1,259	SF	6	\$3,475	
	Ceiling - Exposed	332 Lunchroom	320	SF	6	\$476	skylight
	Ceiling - Lay-in	332 Lunchroom	4,680	SF	7	\$0	
	Ceiling - Plaster/Drywall	332 Lunchroom	800	SF	6	\$2,768	
	Doors - Transom Window	332 Lunchroom	40	SF	6	\$677	
	Doors - Wood Doors inclu hw	332 Lunchroom	4	EA	5	\$4,696	
	Floor - Tile	332 Lunchroom	100	SF	4	\$1,297	cracked/broken
	Floor - Tile	332 Lunchroom	5,700	SF	6	\$12,471	
	Lighting - Pendent/Surface	332 Lunchroom	4	EA	6	\$496	
	Lighting - Pendent/Surface	332 Lunchroom	90	EA	7	\$0	
	Walls - Plaster/Drywall	332 Lunchroom	3,100	SF	6	\$8,556	
	Ceiling - Lay-in	3rd Floor Teachers' Lunchroom	560	SF	7	\$0	
	Ceiling - Plaster/Drywall	3rd Floor Teachers' Lunchroom	40	SF	7	\$0	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Lunch	& Multipurpose Room						
	Doors - Wood Doors inclu hw	3rd Floor Teachers' Lunchroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	3rd Floor Teachers' Lunchroom	1	EA	4	\$3,413	missing
	Floor - Tile	3rd Floor Teachers' Lunchroom	580	SF	6	\$1,269	
	Floor - Tile	3rd Floor Teachers' Lunchroom	20	SF	4	\$259	cracked/damaged
	Lighting - Pendent/Surface	3rd Floor Teachers' Lunchroom	3	EA	6	\$372	
	Lighting - Pendent/Surface	3rd Floor Teachers' Lunchroom	9	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor Teachers' Lunchroom	1,110	SF	7	\$0	
MDF_I	DF						
	AC Unit	217 MDF	1	EA	7	\$0	
	Doors - Steel Doors incl hw	217 MDF	1	EA	7	\$0	
	Finishes	217 MDF	98	SF	5	\$1,582	
	Ventilation and Cooling	217 MDF	1	EA	7	\$0	
Mecha	nical/ Service Rooms						
	Janitor's Closet	1st Floor (north half)	18	SF	6	\$129	Janitor's closet in NE boys restroom.
	Janitor's Closet	1st Floor (north half)	7	SF	6	\$50	Janitor's closet next to class 127
	Storage Room	1st Floor (north half)	90	SF	6	\$645	3 storage rooms between auditorium and corridor
	Janitor's Closet	2nd Floor (north half)	7	SF	5	\$113	next to class 227
	Janitor's Closet	2nd Floor (north half)	18	SF	6	\$129	in boy's restroom north
	Storage Room	2nd Floor	214	SF	6	\$1,533	rm 214
	Janitor's Closet	3rd Floor (north half)	18	SF	6	\$129	in Boys restroom north
	Janitor's Closet	3rd Floor (north half)	7	SF	5	\$113	next to class 327
	Mechanical/ Service Rooms	3rd Floor (north half)	90	SF	6	\$645	Projection Booth in Auditorium
	Mechanical/ Service Rooms	Basement (north half)	370	SF	5	\$5,968	Filter Room
	Mechanical/ Service Rooms	Basement (north half)	2,300	SF	4	\$64,103	Engine Room #1 on plan. Heaving concrete slab at drain. All mechanical equipment and ductwork has peeling paint throughout.
	Storage Room	Basement (north half)	2,500	SF	7	\$0	former Boy's Locker Room
	Storage Room	Basement (north half)	375	SF	5	\$6,049	Storage room #1 between girl's dressing and boy locker room
	Storage Room	Basement (north half)	1,015	SF	6	\$7,272	028 - former Girl's Locker Room (south)
	Storage Room	Basement (north half)	160	SF	7	\$0	031B
	Storage Room	Basement (north half)	440	SF	7	\$0	031
	Storage Room	Basement (north half)	1,760	SF	5	\$28,390	027 - former Girl's Locker Room (north)
	Storage Room	Basement (north half)	272	SF	5	\$4,387	Storage room south of Engine Room #1 + west of warm air chamber.
	Boiler Room	Basement	2,317	SF	5	\$37,374	in basement
	Mechanical/ Service Rooms	Basement	350	SF	5		basement engine room



Building: Main

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lechani	ical/ Service Rooms						
	Storage Room	Basement	464	SF	6	\$3,324	NW portion of 'Oil Tank Room' currently being used for storage
	Storage Room	Basement	362	SF	5	\$5,839	SE portion of 'Oil Tank Room' currently being used for storage: peeling paint & efflorescing wall
	Storage Room	Basement	279	SF	6	\$1,999	basement storage room south of engine room
ool & N	Natatorium						
	Bleachers Seating/Plank Seating	1st Floor	6	EA	6	\$174	
	Ceiling - Exposed	1st Floor	2,450	SF	5	\$6,727	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	Stainless
	Doors - Steel Doors incl hw	1st Floor	2	EA	5	\$2,348	
	Lighting - Pendent/Surface	1st Floor	40	EA	6	\$4,956	
	Pool Basin	1st Floor	1,500	SF	5	\$164,350	Inoperable
	Pool Deck	1st Floor	950	SF	5	\$24,018	Concrete
	Pool Deck Drains	1st Floor	4	EA	6	\$1,688	
	Walls - Concrete Block	1st Floor	420	SF	5	\$4,312	
	Walls - Masonry	1st Floor	330	SF	5	\$16,097	Glazed
	Walls - Masonry	1st Floor	1,000	SF	6	\$3,146	
estroo	m						
	Accessories	025F	38	SF	6	\$350	
	Ceiling - Lay-in	025F	38	SF	7	\$0	
	Doors - Wood Doors inclu hw	025F	1	EA	7	\$0	
	Floor - Tile/Sheet	025F	38	SF	7	\$0	
	Lavatory	025F	1	EA	6	\$320	
	Lighting - Lay-in	025F	1	EA	7	\$0	
	Walls - Metal Panel	025F	180	SF	7	\$0	Fabric wrapped.
	Water Closet	025F	1	EA	7	\$0	
	Accessories	025G	38	SF	6	\$350	
	Ceiling - Lay-in	025G	38	SF	7	\$0	
	Doors - Wood Doors inclu hw	025G	1	EA	7	\$0	
	Floor - Tile	025G	8	SF	5	\$39	
	Floor - Tile	025G	30	SF	7	\$0	
	Lavatory	025G	1	EA	7	\$0	
	Lighting - Lay-in	025G	1	EA	7	\$0	
	Walls - Metal Panel	025G	75	SF	7	\$0	vinyl
	Walls - Metal Panel	025G	100	SF	7	\$0	fabric
	Water Closet	025G	1	EA	7	\$0	



Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
stroo	m						
	Ceiling - Plaster/Drywall	124B Girls Gym Office West Toilet	20	SF	6	\$69	
	Doors - Wood Doors inclu hw	124B Girls Gym Office West Toilet	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	124B Girls Gym Office West Toilet	20	SF	6	\$42	
	Lavatory	124B Girls Gym Office West Toilet	1	EA	6	\$320	
	Lighting - Pendent/Surface	124B Girls Gym Office West Toilet	1	EA	7	\$0	
	Partitions	124B Girls Gym Office West Toilet	1	EA	6	\$297	
	Walls - Plaster/Drywall	124B Girls Gym Office West Toilet	204	SF	5	\$1,546	
	Water Closet	124B Girls Gym Office West Toilet	1	EA	6	\$336	
	Accessories	124C Girls Gym Office East Toilet	30	SF	5	\$594	missing
	Ceiling - Plaster/Drywall	124C Girls Gym Office East Toilet	30	SF	6	\$104	
	Doors - Wood Doors inclu hw	124C Girls Gym Office East Toilet	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	124C Girls Gym Office East Toilet	30	SF	6	\$63	
	Lavatory	124C Girls Gym Office East Toilet	1	EA	6	\$320	
	Lighting - Pendent/Surface	124C Girls Gym Office East Toilet	1	EA	7	\$0	
	Partitions	124C Girls Gym Office East Toilet	1	EA	6	\$297	
	Walls - Plaster/Drywall	124C Girls Gym Office East Toilet	254	SF	6	\$701	
	Water Closet	124C Girls Gym Office East Toilet	1	EA	6	\$336	
	Accessories	1st Floor (in Girl's Restroom)	28	SF	6	\$258	
	Ceiling - Plaster/Drywall	1st Floor (in Girl's Restroom)	28	SF	7	\$0	
	Doors - Steel Doors incl hw	1st Floor (in Girl's Restroom)	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	1st Floor (in Girl's Restroom)	28	SF	7	\$0	
	Lavatory	1st Floor (in Girl's Restroom)	1	EA	5	\$1,590	
	Lighting - Pendent/Surface	1st Floor (in Girl's Restroom)	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor (in Girl's Restroom)	75	SF	7	\$0	
	Walls - Structural Glazed Tile	1st Floor (in Girl's Restroom)	1	SF	4	\$122	Broken.
	Walls - Structural Glazed Tile	1st Floor (in Girl's Restroom)	124	SF	7	\$0	
	Water Closet	1st Floor (in Girl's Restroom)	1	EA	7	\$0	
	Accessories	1st Floor	250	SF	6	\$2,306	
	Accessories	1st Floor	320	SF	6	\$2,952	
	Ceiling - Plaster/Drywall	1st Floor	320	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	250	SF	7	\$0	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor	320	SF	6	\$677	
	Floor - Tile Ceramic/ Porcelain	1st Floor	250	SF	6	\$529	
	Hand Dryer	1st Floor	2	EA	7	\$0	
	Hand Dryer	1st Floor	2	EA	7	\$0	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments		
Restroc	Restroom								
	Lavatory	1st Floor	1	EA	6	\$320	3 spouts		
	Lavatory	1st Floor	1	EA	6	\$320	3 spouts		
	Lighting - Pendent/Surface	1st Floor	6	EA	7	\$0			
	Lighting - Pendent/Surface	1st Floor	6	EA	7	\$0			
	Partitions	1st Floor	6	EA	7	\$0			
	Partitions	1st Floor	5	EA	7	\$0			
	Urinals	1st Floor	4	EA	7	\$0			
	Walls - Plaster/Drywall	1st Floor	360	SF	7	\$0			
	Walls - Plaster/Drywall	1st Floor	100	SF	6	\$327	vinyl		
	Walls - Plaster/Drywall	1st Floor	290	SF	7	\$0			
	Walls - Structural Glazed Tile	1st Floor	266	SF	6	\$837			
	Walls - Structural Glazed Tile	1st Floor	310	SF	6	\$975			
	Walls - Structural Glazed Tile	1st Floor	1	SF	4	\$122	missing		
	Walls - Tile Ceramic/ Porcelain	1st Floor	180	SF	6	\$407			
	Walls - Tile Ceramic/ Porcelain	1st Floor	314	SF	7	\$0			
	Water Closet	1st Floor	6	EA	7	\$0			
	Water Closet	1st Floor	5	EA	7	\$0			
	Accessories	2nd Floor Kitchen North Unisex	80	SF	7	\$0			
	Ceiling - Plaster/Drywall	2nd Floor Kitchen North Unisex	80	SF	7	\$0			
	Doors - Wood Doors inclu hw	2nd Floor Kitchen North Unisex	1	EA	6	\$301			
	Floor - Tile Ceramic/ Porcelain	2nd Floor Kitchen North Unisex	80	SF	6	\$169			
	Lavatory	2nd Floor Kitchen North Unisex	1	EA	6	\$320			
	Lighting - Pendent/Surface	2nd Floor Kitchen North Unisex	1	EA	6	\$124			
	Partitions	2nd Floor Kitchen North Unisex	1	EA	6	\$297			
	Walls - Plaster/Drywall	2nd Floor Kitchen North Unisex	345	SF	6	\$952			
	Water Closet	2nd Floor Kitchen North Unisex	1	EA	6	\$336			
	Accessories	2nd Floor Kitchen South Unisex	32	SF	6	\$295			
	Ceiling - Plaster/Drywall	2nd Floor Kitchen South Unisex	32	SF	7	\$0			
	Doors - Wood Doors inclu hw	2nd Floor Kitchen South Unisex	1	EA	6	\$301			
	Floor - Tile Ceramic/ Porcelain	2nd Floor Kitchen South Unisex	32	SF	6	\$68			
	Lavatory	2nd Floor Kitchen South Unisex	1	EA	6	\$320			
	Lighting - Pendent/Surface	2nd Floor Kitchen South Unisex	1	EA	7	\$0			
	Walls - Plaster/Drywall	2nd Floor Kitchen South Unisex	150	SF	6	\$414			
	Walls - Tile Ceramic/ Porcelain	2nd Floor Kitchen South Unisex	10	SF	4	\$323	Damaged and missing ceramic tile below toilet.		
	Walls - Tile Ceramic/ Porcelain	2nd Floor Kitchen South Unisex	80	SF	6	\$181			
	Water Closet	2nd Floor Kitchen South Unisex	1	EA	6	\$336			
	Accessories	2nd Floor Women (in Girl's Restroom)	28	SF	6	\$258			



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om se						
	Ceiling - Plaster/Drywall	2nd Floor Women (in Girl's Restroom)	28	SF	7	\$0	
	Doors - Steel Doors incl hw	2nd Floor Women (in Girl's Restroom)	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Women (in Girl's Restroom)	28	SF	6	\$59	
	Lavatory	2nd Floor Women (in Girl's Restroom)	1	EA	5	\$1,590	
	Lighting - Pendent/Surface	2nd Floor Women (in Girl's Restroom)	1	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor Women (in Girl's Restroom)	75	SF	7	\$0	
	Walls - Structural Glazed Tile	2nd Floor Women (in Girl's Restroom)	125	SF	7	\$0	
	Water Closet	2nd Floor Women (in Girl's Restroom)	1	EA	7	\$0	
	Accessories	2nd Floor	250	SF	6	\$2,306	
	Accessories	2nd Floor	320	SF	6	\$2,952	
	Ceiling - Plaster/Drywall	2nd Floor	250	SF	7	\$0	
	Ceiling - Plaster/Drywall	2nd Floor	320	SF	7	\$0	
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	250	SF	6	\$529	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	320	SF	6	\$677	
	Hand Dryer	2nd Floor	2	EA	7	\$0	
	Hand Dryer	2nd Floor	2	EA	6	\$460	
	Lavatory	2nd Floor	1	EA	6	\$320	3 spouts
	Lavatory	2nd Floor	1	EA	6	\$320	3 spouts
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	6	EA	6	\$743	
	Partitions	2nd Floor	6	EA	7	\$0	
	Partitions	2nd Floor	5	EA	7	\$0	
	Urinals	2nd Floor	4	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	290	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	100	SF	6	\$327	
	Walls - Plaster/Drywall	2nd Floor	360	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	124	SF	6	\$406	vinyl
	Walls - Structural Glazed Tile	2nd Floor	310	SF	6	\$975	
	Walls - Structural Glazed Tile	2nd Floor	266	SF	6	\$837	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	314	SF	7	\$0	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	180	SF	6	\$407	
	Water Closet	2nd Floor	5	EA	7	\$0	
	Accessories	3rd Floor Men (in Boy's Restroom)	36	SF	6	\$332	
	Ceiling - Plaster/Drywall	3rd Floor Men (in Boy's Restroom)	36	SF	7	\$0	
	Doors - Steel Doors incl hw	3rd Floor Men (in Boy's Restroom)	1	EA	7	\$0	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	m						
	Floor - Tile Ceramic/ Porcelain	3rd Floor Men (in Boy's Restroom)	36	SF	7	\$0	
	Lavatory	3rd Floor Men (in Boy's Restroom)	1	EA	6	\$320	
	Lighting - Pendent/Surface	3rd Floor Men (in Boy's Restroom)	1	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor Men (in Boy's Restroom)	70	SF	6	\$193	
	Walls - Structural Glazed Tile	3rd Floor Men (in Boy's Restroom)	115	SF	7	\$0	
	Walls - Tile Ceramic/ Porcelain	3rd Floor Men (in Boy's Restroom)	36	SF	7	\$0	
	Water Closet	3rd Floor Men (in Boy's Restroom)	1	EA	7	\$0	
	Accessories	3rd Floor Women (in Girl's Restroom)	28	SF	6	\$258	
	Ceiling - Plaster/Drywall	3rd Floor Women (in Girl's Restroom)	28	SF	7	\$0	
	Doors - Steel Doors incl hw	3rd Floor Women (in Girl's Restroom)	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Women (in Girl's Restroom)	28	SF	6	\$59	
	Lavatory	3rd Floor Women (in Girl's Restroom)	1	EA	5	\$1,590	
	Lighting - Pendent/Surface	3rd Floor Women (in Girl's Restroom)	1	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor Women (in Girl's Restroom)	75	SF	7	\$0	
	Walls - Structural Glazed Tile	3rd Floor Women (in Girl's Restroom)	125	SF	7	\$0	
	Water Closet	3rd Floor Women (in Girl's Restroom)	1	EA	7	\$0	
	Accessories	3rd Floor	262	SF	6	\$2,417	
	Accessories	3rd Floor	320	SF	6	\$2,952	
	Ceiling - Plaster/Drywall	3rd Floor	320	SF	7	\$0	
	Ceiling - Plaster/Drywall	3rd Floor	262	SF	7	\$0	
	Floor Drain	3rd Floor	1	EA	6	\$1,059	
	Floor Drain	3rd Floor	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	262	SF	6	\$554	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	320	SF	6	\$677	
	Hand Dryer	3rd Floor	2	EA	7	\$0	
	Hand Dryer	3rd Floor	2	EA	7	\$0	
	Lavatory	3rd Floor	1	EA	6	\$320	w/3 spouts
	Lavatory	3rd Floor	1	EA	6	\$320	w/3 spouts
	Lighting - Pendent/Surface	3rd Floor	5	EA	6	\$619	
	Lighting - Pendent/Surface	3rd Floor	6	EA	6	\$743	
	Partitions	3rd Floor	4	EA	7	\$0	
	Partitions	3rd Floor	6	EA	7	\$0	
	Urinals	3rd Floor	4	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	360	SF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	230	SF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	86	SF	6	\$282	vinyl
	Walls - Plaster/Drywall	3rd Floor	124	SF	6		



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	om						
	Walls - Structural Glazed Tile	3rd Floor	310	SF	6	\$975	
	Walls - Structural Glazed Tile	3rd Floor	266	SF	6	\$837	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	190	SF	7	\$0	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	174	SF	6	\$393	
	Water Closet	3rd Floor	6	EA	7	\$0	
	Water Closet	3rd Floor	4	EA	7	\$0	
	Accessories	Auditorium Men	112	SF	6	\$1,033	
	Ceiling - Plaster/Drywall	Auditorium Men	112	SF	7	\$0	
	Doors - Wood Doors inclu hw	Auditorium Men	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	Auditorium Men	2	SF	4	\$77	holes from panel partitions
	Floor - Tile Ceramic/ Porcelain	Auditorium Men	110	SF	6	\$233	
	Lavatory	Auditorium Men	1	EA	6	\$320	
	Lighting - Pendent/Surface	Auditorium Men	4	EA	7	\$0	
	Partitions	Auditorium Men	1	EA	7	\$0	
	Urinals	Auditorium Men	1	EA	7	\$0	
	Walls - Plaster/Drywall	Auditorium Men	160	SF	7	\$0	
	Walls - Structural Glazed Tile	Auditorium Men	58	SF	6	\$182	
	Walls - Tile Ceramic/ Porcelain	Auditorium Men	310	SF	7	\$0	
	Water Closet	Auditorium Men	1	EA	7	\$0	
	Accessories	Auditorium Women	104	SF	6	\$959	
	Ceiling - Plaster/Drywall	Auditorium Women	104	SF	7	\$0	
	Doors - Wood Doors inclu hw	Auditorium Women	1	EA	5	\$1,174	
	Floor - Tile Ceramic/ Porcelain	Auditorium Women	104	SF	6	\$220	
	Lavatory	Auditorium Women	1	EA	6	\$320	
	Lighting - Lay-in	Auditorium Women	3	EA	6	\$357	
	Partitions	Auditorium Women	2	EA	7	\$0	
	Walls - Plaster/Drywall	Auditorium Women	140	SF	7	\$0	
	Walls - Structural Glazed Tile	Auditorium Women	56	SF	6	\$176	
	Walls - Tile Ceramic/ Porcelain	Auditorium Women	10	SF	4	\$383	missing or broken
	Walls - Tile Ceramic/ Porcelain	Auditorium Women	240	SF	7	\$0	
	Water Closet	Auditorium Women	2	EA	7	\$0	
	Accessories	Basement SE Unisex	50	SF	6	\$461	toilet paper, mirror, soap
	Benches	Basement SE Unisex	5	LF	6	\$72	
	Ceiling - Plaster/Drywall	Basement SE Unisex	50	SF	6	\$173	
	Doors - Wood Doors inclu hw	Basement SE Unisex	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Basement SE Unisex	50	SF	6	\$106	
	Lavatory	Basement SE Unisex	1	EA	6	\$320	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Lighting - Pendent/Surface	Basement SE Unisex	2	EA	7	\$0	
	Walls - Masonry	Basement SE Unisex	69	SF	6	\$217	
	Walls - Structural Glazed Tile	Basement SE Unisex	140	SF	6	\$440	
	Walls - Tile	Basement SE Unisex	50	SF	7	\$0	
	Water Closet	Basement SE Unisex	1	EA	6	\$336	
	Accessories	Basement	260	SF	6	\$2,398	
	Accessories	Basement	240	SF	6	\$2,214	paper towel dispenser, soap, toilet paper.
	Ceiling - Plaster/Drywall	Basement	240	SF	6	\$831	
	Ceiling - Plaster/Drywall	Basement	60	SF	5	\$645	
	Ceiling - Plaster/Drywall	Basement	200	SF	7	\$0	
	Floor Drain	Basement	1	EA	6	\$1,059	
	Floor Drain	Basement	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Basement	240	SF	6	\$508	
	Floor - Tile Ceramic/ Porcelain	Basement	240	SF	6	\$508	
	Floor - Tile Ceramic/ Porcelain	Basement	23	SF	6	\$84	Stairs - Concrete
	Hand Dryer	Basement	2	EA	7	\$0	
	Hand Dryer	Basement	2	EA	6	\$460	
	Lavatory	Basement	1	EA	6	\$320	3 spouts
	Lavatory	Basement	1	EA	6	\$320	
	Lighting - Pendent/Surface	Basement	4	EA	7	\$0	
	Lighting - Pendent/Surface	Basement	4	EA	7	\$0	
	Partitions	Basement	3	EA	7	\$0	
	Partitions	Basement	3	EA	6	\$891	
	Urinals	Basement	4	EA	7	\$0	
	Walls - Plaster/Drywall	Basement	400	SF	7	\$0	
	Walls - Plaster/Drywall	Basement	76	SF	6	\$249	vinyl
	Walls - Structural Glazed Tile	Basement	588	SF	6	\$1,850	
	Walls - Structural Glazed Tile	Basement	400	SF	6	\$1,258	
	Walls - Tile Ceramic/ Porcelain	Basement	220	SF	7	\$0	
	Water Closet	Basement	3	EA	6	\$1,008	
	Water Closet	Basement	3	EA	7	\$0	
	Ceiling - Plaster/Drywall	Boys Gym Office Toilet Southeast	20	SF	6	\$69	
	Doors - Wood Doors inclu hw	Boys Gym Office Toilet Southeast	1	EA	6	\$301	
	Floor - Tile	Boys Gym Office Toilet Southeast	20	SF	6	\$44	
	Lavatory	Boys Gym Office Toilet Southeast	1	EA	6	\$320	
	Lighting - Pendent/Surface	Boys Gym Office Toilet Southeast	1	EA	6	\$124	
	Partitions	Boys Gym Office Toilet Southeast	1	EA	6	\$297	



\$1,560,016

Building: Main

Category: Rooms (Other Than Classrooms)

Group It	em - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
V	Valls - Plaster/Drywall	Boys Gym Office Toilet Southeast	204	SF	5	\$1,546	
V	Vater Closet	Boys Gym Office Toilet Southeast	1	EA	6	\$336	
С	Ceiling - Plaster/Drywall	Boys Gym Toilet in Weight Room	30	SF	6	\$104	
D	Doors - Wood Doors inclu hw	Boys Gym Toilet in Weight Room	1	EA	6	\$301	
F	loor - Tile Ceramic/ Porcelain	Boys Gym Toilet in Weight Room	30	SF	6	\$63	
Li	avatory	Boys Gym Toilet in Weight Room	1	EA	6	\$320	
Li	ighting - Pendent/Surface	Boys Gym Toilet in Weight Room	1	EA	6	\$124	
Р	Partitions	Boys Gym Toilet in Weight Room	1	EA	6	\$297	
V	Valls - Plaster/Drywall	Boys Gym Toilet in Weight Room	254	SF	6	\$701	
V	Vater Closet	Boys Gym Toilet in Weight Room	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Ceiling - Exposed	1st floor toilet room vestibule adjacent to room 118	63	SF	5	\$173	
	Doors - Wood Doors include hw	1st floor toilet room vestibule adjacent to room 118	1	EA	5	\$1,174	
	Floor - Tile/Sheet	1st floor toilet room vestibule adjacent to room 118	62	SF	6	\$34	vct/vat
	Lighting - Pendent/Surface	1st floor toilet room vestibule adjacent to room 118	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st floor toilet room vestibule adjacent to room 118	312	SF	6	\$1,383	
	Ceiling - Lay-in	1st North (Half of addition)	2,915	SF	6	\$8,754	
	Floor - Tile/Sheet	1st North (Half of addition)	2,915	SF	6	\$1,584	
	Lighting - Lay-in	1st North (Half of addition)	10	EA	6	\$1,190	
	Student Lockers - One Tier	1st North (Half of addition)	37	EA	6	\$3,435	
	Walls - Plaster/Drywall	1st North (Half of addition)	1,877	SF	6	\$8,321	
	Ceiling - Lay-in	2nd North (Half of Addition)	1,098	SF	6	\$3,297	
	Floor - Tile/Sheet	2nd North (Half of Addition)	1,098	SF	6	\$597	
	Lighting - Lay-in	2nd North (Half of Addition)	10	EA	6	\$1,190	
	Student Lockers - One Tier	2nd North (Half of Addition)	36	EA	6	\$3,342	
	Walls - Plaster/Drywall	2nd North (Half of Addition)	1,637	SF	6	\$7,257	
	Ceiling - Lay-in	3rd (Half of Addition)	1,098	SF	6	\$3,297	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Floor - Tile/Sheet	3rd (Half of Addition)	1,098	SF	6	\$597	
	Lighting - Lay-in	3rd (Half of Addition)	9	EA	7	\$0	
	Walls - Plaster/Drywall	3rd (Half of Addition)	1,325	SF	6	\$5,874	
	Ceiling - Plaster/Drywall	Auditorium Corridor - Basement (North Half) / Basement	135	SF	7	\$0	
	Floor - Concrete	Auditorium Corridor - Basement (North Half) / Basement	135	SF	6	\$71	
	Lighting - Pendent/Surface	Auditorium Corridor - Basement (North Half) / Basement	1	EA	7	\$0	
	Stairs - Concrete Stairs	Auditorium Corridor - Basement (North Half) / Basement	30	LF	6	\$249	
	Walls - Plaster/Drywall	Auditorium Corridor - Basement (North Half) / Basement	600	SF	7	\$0	
	Ceiling - Plaster/Drywall	Auditorium Lobby - Basement / Basement	2,025	SF	7	\$0	
	Doors - Wood Doors include hw	Auditorium Lobby - Basement / Basement	15	EA	6	\$4,515	
	Floor - Terrazzo	Auditorium Lobby - Basement / Basement	2,025	SF	7	\$0	
	Lighting - Pendent/Surface	Auditorium Lobby - Basement / Basement	12	EA	7	\$0	
	Walls - Plaster/Drywall	Auditorium Lobby - Basement / Basement	21,494	SF	7	\$0	
	Ceiling - Plaster/Drywall	Basement	2,711	SF	5	\$34,154	
	Doors - Steel Doors incl hw	Basement	2	EA	6	\$602	
	Floor - Concrete Epoxy/ Painted	Basement	2,711	SF	6	\$1,318	
	Lighting - Pendent/Surface	Basement	22	EA	6	\$2,726	
	Walls - Plaster/Drywall	Basement	3,422	SF	6	\$15,170	
	Ceiling - Plaster/Drywall	Corridor for Music Rooms - 1st Floor (North Half) / 1st Floor	1,047	SF	7	\$0	
	Floor - Tile/Sheet	Corridor for Music Rooms - 1st Floor (North Half) / 1st Floor	1,047	SF	7	\$0	
	Lighting - Pendent/Surface	Corridor for Music Rooms - 1st Floor (North Half) / 1st Floor	11	EA	7	\$0	
	Walls - Plaster/Drywall	Corridor for Music Rooms - 1st Floor (North Half) / 1st Floor	11,792	SF	7	\$0	
	Ceiling - Splined	Corridor in Main Office	53	SF	7	\$0	
	Floor - Carpet	Corridor in Main Office	53	SF	7	\$0	
	Lighting - Pendent/Surface	Corridor in Main Office	2	EA	7	\$0	
	Walls - Plaster/Drywall	Corridor in Main Office	160	SF	7	\$0	
	Ceiling - Lay-in	Main Corridor - 1st Floor (North Half) / 1st Floor	3,568	SF	7	\$0	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido)r						
	Drinking Fountains - Single Water Cooler	Main Corridor - 1st Floor (North Half) / 1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	Main Corridor - 1st Floor (North Half) / 1st Floor	3,568	SF	7	\$0	
	Lighting - Lay-in	Main Corridor - 1st Floor (North Half) / 1st Floor	39	EA	7	\$0	
	Stairs - Terrazzo	Main Corridor - 1st Floor (North Half) / 1st Floor	175	LF	7	\$0	Stairs are covered in asphalt.
	Walls - Plaster/Drywall	Main Corridor - 1st Floor (North Half) / 1st Floor	39,468	SF	7	\$0	
	Ceiling - Lay-in	Main Corridor - 2nd Floor (North Half) / 2nd Floor	3,012	SF	7	\$0	
	Drinking Fountains - Single Fountain	Main Corridor - 2nd Floor (North Half) / 2nd Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	Main Corridor - 2nd Floor (North Half) / 2nd Floor	3,012	SF	7	\$0	
	Lighting - Lay-in	Main Corridor - 2nd Floor (North Half) / 2nd Floor	29	EA	7	\$0	
	Walls - Plaster/Drywall	Main Corridor - 2nd Floor (North Half) / 2nd Floor	32,206	SF	7	\$0	
	Ceiling - Lay-in	Main Corridor - 3rd Floor (North Half) / 3rd Floor	2,481	SF	7	\$0	
	Drinking Fountains - Single Fountain	Main Corridor - 3rd Floor (North Half) / 3rd Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	Main Corridor - 3rd Floor (North Half) / 3rd Floor	2,481	SF	7	\$0	
	Lighting - Lay-in	Main Corridor - 3rd Floor (North Half) / 3rd Floor	29	EA	7	\$0	
	Walls - Plaster/Drywall	Main Corridor - 3rd Floor (North Half) / 3rd Floor	27,126	SF	7	\$0	
	Ceiling - Exposed	Main Corridor - Basement (North Half) / Basement	3,984	SF	7	\$0	
	Floor - Asphalt Floor	Main Corridor - Basement (North Half) / Basement	3,984	SF	6	\$6,039	
	Lighting - Pendent/Surface	Main Corridor - Basement (North Half) / Basement	42	EA	7	\$0	
	Stairs - Concrete Stairs	Main Corridor - Basement (North Half) / Basement	211	LF	7	\$0	Stairs are covered in asphalt.
	Walls - Plaster/Drywall	Main Corridor - Basement (North Half) / Basement	40,490	SF	7	\$0	
	Ceiling - Plaster/Drywall	Vestibule @ Auditorium Lobby - Basement (North Half) / Basement	456	SF	7	\$0	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Floor - Terrazzo	Vestibule @ Auditorium Lobby - Basement (North Half) / Basement	426	SF	6	\$3,576	
	Floor - Terrazzo	Vestibule @ Auditorium Lobby - Basement (North Half) / Basement	30	SF	4	\$2,713	damaged and deteriorated
	Lighting - Pendent/Surface	Vestibule @ Auditorium Lobby - Basement (North Half) / Basement	5	EA	7	\$0	
	Walls - Plaster/Drywall	Vestibule @ Auditorium Lobby - Basement (North Half) / Basement	4,778	SF	7	\$0	
	Ceiling - Plaster/Drywall	Vestibule at Pool - basement level	60	SF	7	\$0	
	Doors - Wood Doors include hw	Vestibule at Pool - basement level	1	EA	5	\$1,174	
	Floor - Concrete Epoxy/ Painted	Vestibule at Pool - basement level	60	SF	5	\$103	
	Lighting - Pendent/Surface	Vestibule at Pool - basement level	1	EA	6	\$124	
	Walls - Plaster/Drywall	Vestibule at Pool - basement level	60	SF	6	\$316	
	Walls - Plaster/Drywall	Vestibule at Pool - basement level	120	SF	4	\$1,208	efflorescence. water damage
Safety							
	Camera Viewing Station		2	EA	7	\$0	
	Security Cameras		3	EA	7	\$0	
	Security Cameras		23	EA	7	\$0	Basement 5, 1st Floor 6, 2nd Floor 6, 3rd Floor 6 = total 23 (quantities are approximate, based on building engineer's recollection)
	Security Cameras		3	EA	7	\$0	
Stairs							
	Ceiling - Plaster/Drywall	#1	981	SF	7	\$0	
	Floor - Terrazzo	#1	765	SF	7	\$0	Asphalt coating.
	Floor - Tile/Sheet	#1	163	SF	7	\$0	
	Handrails	#1	150	LF	7	\$0	
	Lighting - Pendent/Surface	#1	17	EA	7	\$0	
	Stairs - Terrazzo	#1	133	LF	7	\$0	
	Stairs - Terrazzo	#1	329	LF	7	\$0	Asphalt coating.
	Walls - Plaster/Drywall	#1	29,942	SF	7	\$0	
	Ceiling - Lay-in	#2	600	SF	7	\$0	
	Ceiling - Plaster/Drywall	#2	450	SF	5	\$6,615	
	Floor - Terrazzo	#2	300	SF	5	\$11,291	Epoxy coating.
	Floor - Tile/Sheet	#2	630	SF	7	\$0	
	Handrails	#2	186	LF	6	\$1,612	
	Lighting - Lay-in	#2	2	EA	7	\$0	
	Lighting - Pendent/Surface	#2	6	EA	7	\$0	
	Stairs - Terrazzo	#2	550	LF	5	\$29,824	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Stairs - Terrazzo	#2	16	LF	4	\$5,266	Terrazzo cracked/missing.
	Walls - Plaster/Drywall	#2	2,350	SF	6	\$7,696	
	Walls - Plaster/Drywall	#2	2,350	SF	7	\$0	
	Ceiling	#9	53	SF	7	\$0	Metal
	Ceiling - Plaster/Drywall	#9	373	SF	7	\$0	
	Floor	#9	53	SF	6	\$0	Metal
	Floor - Concrete	#9	410	SF	6	\$217	
	Handrails	#9	78	LF	6	\$676	
	Lighting - Pendent/Surface	#9	2	EA	7	\$0	
	Lighting - Wall Mounted	#9	1	EA	5	\$169	Incandescent
	Stairs - Concrete	#9	203	LF	6	\$1,684	
	Stairs - Concrete	#9	4	LF	4	\$628	Cracked/missing concrete
	Walls - Plaster/Drywall	#9	2,652	SF	7	\$0	
	Floor - Concrete	Boy's Gym (SE corner)	42	SF	5	\$192	
	Handrails	Boy's Gym (SE corner)	52	LF	7	\$0	
	Lighting - Pendent/Surface	Boy's Gym (SE corner)	1	EA	5	\$183	
	Stairs - Concrete	Boy's Gym (SE corner)	117	LF	5	\$11,593	
	Walls - Masonry	Boy's Gym (SE corner)	540	SF	7	\$0	
	Walls - Masonry	Boy's Gym (SE corner)	10	SF	5	\$572	
	Ceiling - Lay-in	Boy's Gym @ NE corner	186	SF	7	\$0	
	Floor - Concrete	Boy's Gym @ NE corner	70	SF	6	\$37	
	Floor - Concrete	Boy's Gym @ NE corner	36	SF	5	\$69	
	Handrails	Boy's Gym @ NE corner	82	LF	6	\$711	
	Lighting - Pendent/Surface	Boy's Gym @ NE corner	1	EA	4	\$541	missing fixture.
	Lighting - Pendent/Surface	Boy's Gym @ NE corner	2	EA	6	\$248	
	Stairs	Boy's Gym @ NE corner	140	LF	7	\$0	painted steel stair
	Walls - Plaster/Drywall	Boy's Gym @ NE corner	1,600	SF	6	\$4,416	
	Ceiling - Lay-in	South Stair	192	SF	6	\$577	
	Ceiling - Plaster/Drywall	South Stair	156	SF	6	\$1,142	
	Floor - Epoxy/ Painted	South Stair	28	SF	5	\$128	
	Floor - Tile	South Stair	120	SF	5	\$539	
	Handrails	South Stair	188	LF	6	\$1,629	
	Lighting - Lay-in	South Stair	6	EA	7	\$0	
	Stairs - Concrete	South Stair	510	LF	5	\$50,533	
	Walls - Plaster/Drywall	South Stair	1,280	SF	5	\$5,839	
	Ceiling - Plaster/Drywall	Stair #3 (on plan)	830	SF	7	\$0	
	Floor - Terrazzo	Stair #3 (on plan)	424	SF	7	\$0	



Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Floor - Terrazzo	Stair #3 (on plan)	260	SF	5	\$11,570	
	Floor - Tile Ceramic/ Porcelain	Stair #3 (on plan)	70	SF	6	\$469	
	Handrails	Stair #3 (on plan)	186	LF	6	\$1,612	
	Lighting - Pendent/Surface	Stair #3 (on plan)	10	EA	7	\$0	
	Stairs - Terrazzo	Stair #3 (on plan)	493	LF	7	\$0	
	Stairs - Terrazzo	Stair #3 (on plan)	105	LF	5	\$5,694	
	Walls - Plaster/Drywall	Stair #3 (on plan)	500	SF	6	\$1,637	
	Walls - Plaster/Drywall	Stair #3 (on plan)	2,500	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	Stair #3 (on plan)	320	SF	7	\$0	
	Ceiling - Plaster/Drywall	SW Stair	107	SF	7	\$0	
	Floor - Concrete Epoxy/ Painted	SW Stair	343	SF	6	\$167	
	Floor - Tile	SW Stair	263	SF	6	\$143	
	Handrails	SW Stair	194	LF	6	\$1,681	
	Lighting - Pendent/Surface	SW Stair	9	EA	6	\$1,115	
	Stairs - Concrete	SW Stair	451	LF	6	\$3,741	epoxy coat
	Walls - Plaster/Drywall	SW Stair	2,650	SF	5	\$12,089	
Buildi	ng Interior Subtotal:					\$310,097	

Building Interior Subtotal:

Total Building Cost

\$7,544,821

Building: Addition

pup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
rance						
Entrance Control - Audio and Video	1 - Main	1	EA	4	\$5,381	not operable
Entrance Control - Audio and Video	15	1	EA	4	\$5,381	not operable
Entrance Control - Audio and Video	16	1	EA	4	\$5,381	not operable
Exterior Doors - Exterior Steel Door	1 - Main	3	EA	6	\$1,442	
Exterior Doors - Exterior Steel Door	15	2	EA	6	\$961	
Exterior Doors - Exterior Steel Door	16	2	EA	6	\$961	
Exterior Doors - Exterior Steel Door	17	2	EA	5	\$2,683	
Exterior Doors - Transom Lite	16	5	EA	5	\$4,108	alligatoring paint
Exterior Doors - Transom Lite	17	2	EA	6	\$627	
Exterior Stairs - Stone	15	6	LF	5	\$1,627	cracking, spalling, chipped edges
Exterior Stairs - Stone	16	6	LF	6	\$678	



Building: Addition

Category: Building Exterior

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
unda	tion						
	Foundation - Concrete	Entire Building	825	LF	7	\$0	
	Superstructure - Concrete	Entire Building	62,986	SF	7	\$0	
ghting	3						
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	5	\$855	Broken lesne on light
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	6	\$289	
of Sy	vstem						
	Coping - Clay Tile	2	47	LF	6	\$1,510	
	Coping - Stone	1	628	LF	6	\$20,170	
	Downspouts - Interior Downspouts	1	413	LF	7	\$0	
	Downspouts - Interior Downspouts	3	20	LF	7	\$0	
	Parapet - Parapet > 30"	1	579	LF	7	\$0	
	Parapet - Parapet > 30"	1 / Entire Building	49	LF	4	\$67,307	spalling brick, open joints, loose mortar
	Parapet - Parapet > 30"	2	47	LF	7	\$0	
	Roof Structure - Concrete	1	15,522	SF	7	\$0	
	Roof Structure - Concrete	2	1,880	SF	7	\$0	
	Roof Structure - Concrete	3	893	SF	7	\$0	
	Roof - EPDM/ Synthetic Rubber	1	15,022	SF	4	\$387,740	bubbling, spongy
	Roof - EPDM/ Synthetic Rubber	2	1,880	SF	4	\$48,526	bubbling, spongy
	Roof - EPDM/ Synthetic Rubber	3	893	SF	4	\$23,050	bubbling, spongy
	Roof - Metal	1	500	SF	5	\$13,778	corroded
alls							
	Exterior Walls - Brick	Entire Building	23,469	SF	7	\$0	
	Exterior Walls - Stone-Cut	Entire Building	6,178	SF	6	\$41,522	
ndow	/s						
	Guard - Guards perforated	Entire Building	293	SF	6	\$3,742	
	Lintels - Steel	Entire Building	16	LF	7	\$0	
	Lintels - Stone	Entire Building	674	LF	7	\$0	
	Windows - Insulated Panel	Entire Building	1,012	SF	4	\$96,743	part of lexan system, active leaking reported throughout
	Windows - Sash Lexan/ Glass Double-pane	Entire Building	4,875	SF	4	\$639,891	actively leaking, 90% reported to be inoperable
	ng Exterior Subtotal:				¢	1,374,350	

_

Building: Addition Category: Electrical System



Jose De Diego Elementary Community Academy

1313 N Claremont Ave Chicago, IL 60622

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emergency System						
Automatic Transfer Switch	Electrical Room	1	EA	6	\$408	
Emergency A/C Power - Corridors and Stairs	Entire Building	13,410	SF	6	\$4,027	All lights functional, per engineer
Emergency Battery Packs - Corridors and Stairs	Entire Building	14	EA	7	\$0	
Emergency Battery Packs - Students Toilets	Entire Building	7	EA	7	\$0	
Exit Signs - Corridors and Stairs	Entire Building	15	EA	2	\$8,182	School does not have an emergency generator or UPS and signs do not have battery backup
Security System - CCTV	Entire Building	238,557	SF	6	\$71,639	Serves main and addition
Main Service						
Independent Electrical Service for emergency power	Electrical Room	1	EA	6	\$2,921	
Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	\$10,867	Panel serves main and addition. Panel is 31 years of age
PA System	Entire Building	238,557	SF	6	\$78,461	Serves both main and addition.
Power Distribution						
Lighting and Power Panels - 100 A	Entire Building	9	EA	7	\$0	
Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	\$0	
Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	\$1,491	
Electrical System Subtotal:					\$178,594	
Building: Addition						
Category: Safty System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm		-				
Fire Alarm Panel	Entire Building / Electrical Room	1	EA	4	\$49,477	Serves both main and addition. Panel is greater than 20 years of age and cannot be upgraded.
Fire Alarm Strobe Lights	Entire Building	62,986	SF	4	\$85,566	
Fire Alarm_System	Entire Building	238,557	SF	4	\$474,180	Serves both main and addition.
Safty System Subtotal:					\$609,223	
Building: Addition						
Category: Mechanical System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Conditioning						
Condensing Unit- Ground Mounted - Less than 5 tons	Courtyard	3	EA	7	\$0	



Building: Addition

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Han	dling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000	Mechanical Room	1	EA	5	\$78,608	Unit can maintain space temperatures; however, motor is old, coils leak, and exterior is deteriorating
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000	Mechanical Room	1	EA	5	\$78,608	Unit can maintain space temperatures; however, motor is old, coils leak, and exterior is deteriorating
	Air Intake	Mechanical Room / Roof	1	EA	4	\$17,616	OA damper stuck
	Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	4	\$39,696	Unit can maintain space temperatures; however, motor is old, coils leak, and exterior is deteriorating
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	4	\$39,696	Auxiliaries are in poor condition. Housing walls deteriorated, coils are leaking severely, unit is not sealed
	Fan Coil Unit- Celing Mounted - Electric	Basement	3	EA	7	\$0	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	7	\$0	Return from attic
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	5	\$131,341	No return duct.
	Zone Dampers	Mechanical Room	26	EA	5	\$49,752	
	Zone Dampers	Mechanical Room	27	EA	5	\$51,666	
Heating	Devices						
	Fin Tube - Steam	Entire Building	10	LF	6	\$94	
	Radiators - Steam	Entire Building	4	EA	5	\$6,701	Old steam radiators
	Wall Heater - Electric	Entire Building	26	EA	5	\$13,951	Heater is old and in poor condition
Mechar	nical Plumbing						
	Condensate-Steel or Galvanized	Entire Building	500	LF	5	\$81,910	Piping in poor condition. Many leaks and clamps installed.
	Condensate-Steel or Galvanized	Entire Building	500	LF	5	\$81,910	Piping in poor condition. Many leaks and clamps installed.
Temper	rature Control						
	Pneumatic System	Entire Building	238,557	SF	5	\$822,139	Engineer has no issues with pneumatic system. No air leaks in system. System serves main and addition.
	Thermostats - Pneumatic	Entire Building	43	EA	6	\$0	Engineer has no issues with thermostats
Ventilat	tion						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building / Attic	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / 1st Floor	2	EA	6	\$1,185	Serve transformer room
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	3	EA	6	\$1,777	
Mecha	anical System Subtotal:				\$	1,503,602	



\$239,586

1313 N Claremont Ave Chicago, IL 60622

Building: Addition

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	62,986	SF	7	\$0	Plumbing systems upgraded.
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	62,986	SF	7	\$0	Plumbing systems upgraded.
	Domestic Piping-Cold Water Risers	Entire Building	62,986	SF	7	\$0	Plumbing systems upgraded.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	62,986	SF	7	\$0	Plumbing systems upgraded.
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	62,986	SF	7	\$0	Plumbing systems upgraded.
	Domestic Piping-Hot Water Return Lines	Entire Building	62,986	SF	4	\$54,042	
	Domestic Piping-Hot Water Return Risers	Entire Building	62,986	SF	4	\$30,624	
	Sanitary Piping	Entire Building	62,986	SF	6	\$57,645	
	Storm Piping	Entire Building	62,986	SF	6	\$54,943	
	Vent Piping	Entire Building	62,986	SF	6	\$42,333	

Plumbing System Subtotal:

Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #001 (Regular Classroom)						
	Casework		7	LF	6	\$177	delaminating doors
	Ceiling - Plaster/Drywall		1,188	SF	6	\$4,111	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Tile		1,188	SF	6	\$2,599	
	Lighting - Pendent/Surface		22	EA	6	\$2,726	
	Walls - Masonry		996	SF	6	\$3,133	
	Work Sink		1	EA	6	\$379	
Classro	om #005 (Regular Classroom)						
	Ceiling - Plaster/Drywall		1,145	SF	6	\$3,962	
	Doors - Wood Doors inclu hw		3	EA	6	\$903	
	Floor - Carpet		286	SF	5	\$1,468	potential trip hazard
	Floor - Tile		859	SF	6	\$1,879	
	Lighting - Pendent/Surface		20	EA	6	\$2,478	
	Marker Board		14	LF	6	\$300	
	Walls - Masonry		998	SF	5	\$41,244	Peeling/efflorescing Paint, exposing brick foundation wall; masonry dust on walls
	Walls - Plaster/Drywall		249	SF	6	\$687	
Classro	om #007 (Regular Classroom)						
	Ceiling - Lay-in		650	SF	7	\$0	

Building: Addition

Category:	Classrooms
-----------	------------

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #007 (Regular Classroom)						
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		650	SF	6	\$1,422	
	Lighting - Lay-in		10	EA	7	\$0	
	Marker Board		12	LF	7	\$0	
	Walls - Masonry		551	SF	5	\$22,771	
	Work Sink		2	EA	7	\$0	
Classro	oom #101 (Regular Classroom)						
	AC Units		2	EA	7	\$0	
	Casework		26	LF	5	\$5,436	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		999	SF	7	\$0	
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Tile		999	SF	5	\$4,486	
	Lighting - Lay-in		20	EA	7	\$0	
	Marker Board		19	LF	7	\$0	
	Walls - Plaster/Drywall		522	SF	5	\$2,307	
	Walls - Plaster/Drywall		600	SF	6	\$1,656	
	Work Sink		2	EA	6	\$758	
Classro	oom #102 (Regular Classroom)						
	AC Units		2	EA	7	\$0	
	Casework		5	LF	7	\$0	
	Casework		6	LF	5	\$1,254	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		1,425	SF	7	\$0	
	Doors - Transom Window		18	SF	5	\$762	delaminating veneer
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Tile		1,592	SF	5	\$7,148	cracked; chipped throughout @ nails from wood flooring below
	Lighting - Lay-in		40	EA	7	\$0	
	Marker Board		20	LF	7	\$0	
	Storage/ Closet		167	SF	5	\$2,694	
	Walls - Plaster/Drywall		513	SF	5	\$2,267	cracked plaster & peeling paint
	Walls - Plaster/Drywall		600	SF	6	\$1,656	
	Work Sink		1	EA	6	\$379	
Classro	oom #105 (Regular Classroom)						
	AC Units		2	EA	7	\$0	

Building: Addition

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
assro	oom #105 (Regular Classroom)						
	Casework		27	LF	5	\$5,645	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		999	SF	7	\$0	
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Carpet		399	SF	6	\$850	
	Floor - Tile		600	SF	5	\$2,694	cracked and damaged tiles
	Lighting - Lay-in		20	EA	7	\$0	
	Marker Board		14	LF	7	\$0	
	Walls - Plaster/Drywall		1,122	SF	6	\$3,097	
assro	oom #112 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		10	LF	6	\$253	
	Ceiling - Lay-in		690	SF	7	\$0	
	Chalk Board		44	LF	4	\$4,039	obsolete material
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Tile		690	SF	5	\$3,098	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		18	LF	7	\$0	
	Walls - Plaster/Drywall		861	SF	6	\$2,376	
issro	oom #201 (Regular Classroom)						
	AC Units		2	EA	7	\$0	
	Casework		27	LF	5	\$5,645	damaged hardware and finish
	Ceiling - Lay-in		999	SF	7	\$0	
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Wood		999	SF	6	\$7,043	
	Lighting - Lay-in		20	EA	7	\$0	
	Marker Board		16	LF	7	\$0	
	Walls - Plaster/Drywall		522	SF	5	\$2,307	peeling paint
	Walls - Plaster/Drywall		600	SF	6	\$1,656	
assro	oom #202 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Ceiling - Lay-in		950	SF	7	\$0	
	Doors - Transom Window		9	SF	6	\$152	

Building: Addition

	ing. Addition						
	ory: Classrooms						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #202 (Regular Classroom)						
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		960	SF	6	\$6,768	
	Lighting - Lay-in		18	EA	7	\$0	
	Marker Board		12	LF	7	\$0	
	Walls - Plaster/Drywall		490	SF	5	\$2,165	
	Walls - Plaster/Drywall		600	SF	6	\$1,656	
Classro	oom #204 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		8	LF	5	\$1,673	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		667	SF	7	\$0	
	Chalk Board		5	LF	4	\$459	obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Wood		667	SF	6	\$4,702	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		16	LF	7	\$0	
	Walls - Plaster/Drywall		912	SF	6	\$2,517	peeling paint
Classro	oom #205 (Regular Classroom)						
	AC Units		2	EA	6	\$991	
	Casework		27	LF	5	\$5,645	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		999	SF	7	\$0	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Wood		999	SF	6	\$7,043	
	Lighting - Lay-in		20	EA	7	\$0	
	Marker Board		15	LF	7	\$0	
	Walls - Plaster/Drywall		1,131	SF	6	\$3,121	
Classro	oom #207 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		8	LF	5	\$1,673	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in		690	SF	7	\$0	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		690	SF	6	\$4,864	

Building: Addition

-	jory: Classrooms						
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #207 (Regular Classroom)						
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		20	LF	7	\$0	
	Walls - Plaster/Drywall		330	SF	5	\$1,458	cracked and peeling paint
	Walls - Plaster/Drywall		600	SF	6	\$1,656	
Classro	oom #209 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		8	LF	5	\$1,673	damaged finish & hardware
	Ceiling - Lay-in		690	SF	7	\$0	
	Chalk Board		22	LF	4	\$2,020	obsolete material
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		690	SF	6	\$4,864	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		20	LF	7	\$0	
	Walls - Plaster/Drywall		930	SF	6	\$2,567	
Classro	oom #210 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		8	LF	5	\$1,673	damaged finish and hardware
	Ceiling - Lay-in		612	SF	7	\$0	
	Chalk Board		14	LF	4	\$1,285	obsolete material
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		612	SF	6	\$4,315	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		891	SF	6	\$2,459	
Classro	oom #211 (Special Program)						
	AC Units		1	EA	7	\$0	
	Casework		10	LF	5	\$2,091	damaged finish & hardware
	Ceiling - Lay-in		660	SF	7	\$0	
	Chalk Board		20	LF	4	\$1,836	obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Weight/ Fitness Room Floor Matting		660	SF	6	\$3,454	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
				SF			

Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #212 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		10	LF	6	\$253	
	Ceiling - Lay-in		690	SF	7	\$0	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Wood		690	SF	6	\$4,864	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		18	LF	7	\$0	
	Walls - Plaster/Drywall		861	SF	6	\$2,376	
Classro	oom #213 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		10	LF	5	\$2,091	damaged finish & hardware
	Ceiling - Lay-in		660	SF	7	\$0	
	Chalk Board		20	LF	4	\$1,836	obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		660	SF	6	\$4,653	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		870	SF	6	\$2,401	
Classro	oom #215 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		10	LF	5	\$2,091	damaged finish & hardware
	Ceiling - Lay-in		690	SF	7	\$0	
	Chalk Board		8	LF	4	\$734	obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		690	SF	6	\$4,864	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		34	LF	7	\$0	
	Walls - Plaster/Drywall		370	SF	5	\$1,635	
	Walls - Plaster/Drywall		500	SF	6	\$1,380	
Classro	oom #302 (Store Room)						
	AC Units		1	EA	6	\$496	
	Casework		40	LF	6	\$1,010	
	Ceiling - Lay-in		642	SF	6	\$1,928	

Building: Addition

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #302 (Store Room)						
	Chalk Board		6	LF	4	\$551	obsolete material
	Doors - Transom Window		6	SF	6	\$102	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		642	SF	6	\$1,405	
	Lighting - Lay-in		12	EA	7	\$0	
	Marker Board		6	LF	7	\$0	
	Storage/ Closet		221	SF	6	\$1,602	
	Walls - Plaster/Drywall		430	SF	6	\$1,187	
	Walls - Structural Glazed Tile		330	SF	6	\$1,038	
	Work Sink		1	EA	6	\$379	
Classro	oom #303/301 (Other Instructional Use)						
	AC Units		2	EA	6	\$991	
	Casework		5	LF	7	\$0	
	Ceiling - Lay-in		740	SF	7	\$0	
	Ceiling - Plaster/Drywall		500	SF	7	\$0	
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Tile		1,240	SF	7	\$0	
	Lighting - Lay-in		13	EA	7	\$0	
	Marker Board		8	LF	7	\$0	
	Storage/ Closet		99	SF	7	\$0	
	Walls - Plaster/Drywall		1,320	SF	6	\$3,643	
	Work Sink		1	EA	7	\$0	
Classro	oom #304 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		25	LF	6	\$631	
	Ceiling - Lay-in		668	SF	7	\$0	
	Chalk Board		12	LF	4	\$1,102	obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		668	SF	6	\$4,709	
	Lighting - Lay-in		12	EA	7	\$0	
	Marker Board		8	LF	6	\$171	
	Walls - Plaster/Drywall		808	SF	6	\$2,230	
	Work Sink		1	EA	6	\$379	

Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #305 (Computer Lab)						
	AC Units		2	EA	6	\$991	
	Casework		10	LF	6	\$253	
	Ceiling - Lay-in		968	SF	7	\$0	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		968	SF	6	\$2,118	
	Lighting - Lay-in		18	EA	7	\$0	
	Marker Board		16	LF	7	\$0	
	Storage/ Closet		30	SF	6	\$218	
	Walls - Plaster/Drywall		1,059	SF	6	\$2,923	
	Wireless System		1	EA	6	\$372	
Classro	oom #307 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		9	LF	6	\$227	
	Ceiling - Lay-in		682	SF	7	\$0	
	Chalk Board		6	LF	4	\$551	obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		682	SF	6	\$4,808	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		18	LF	7	\$0	
	Walls - Plaster/Drywall		890	SF	6	\$2,456	
Classro	oom #309 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		10	LF	5	\$2,091	
	Ceiling - Lay-in		660	SF	7	\$0	
	Chalk Board		5	LF	4	\$459	obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		660	SF	6	\$4,653	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		20	LF	6	\$428	
	Walls - Plaster/Drywall		870	SF	6	\$2,401	
Classro	oom #310 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		8	LF	6	\$202	

Building: Addition

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	om #310 (Regular Classroom)						
	Ceiling - Lay-in		620	SF	7	\$0	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		620	SF	7	\$0	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		32	LF	7	\$0	
	Walls - Plaster/Drywall		850	SF	6	\$2,346	
assroo	om #311 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		10	LF	5	\$2,091	
	Ceiling - Lay-in		660	SF	7	\$0	
	Chalk Board		5	LF	4	\$459	obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		660	SF	7	\$0	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		20	LF	7	\$0	
	Walls - Plaster/Drywall		870	SF	6	\$2,401	
lassroo	om #312 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		10	LF	6	\$253	
	Ceiling - Lay-in		690	SF	7	\$0	
	Chalk Board		12	LF	4	\$1,102	obsolete material
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Wood		690	SF	7	\$0	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		20	LF	6	\$428	
	Walls - Plaster/Drywall		839	SF	6	\$2,316	
assro	om #313 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		24	LF	6	\$606	
	Ceiling - Lay-in		660	SF	7	\$0	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		660	SF	6	\$1,444	

Building: Addition

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #313 (Regular Classroom)						
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		24	LF	6	\$514	
	Walls - Plaster/Drywall		870	SF	6	\$2,401	
Classro	om #315 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		2	LF	6	\$51	
	Ceiling - Lay-in		672	SF	7	\$0	
	Chalk Board		12	LF	4	\$1,102	obsolete material
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		672	SF	6	\$1,470	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		14	LF	6	\$300	
	Walls - Plaster/Drywall		890	SF	6	\$2,456	

Classrooms Subtotal:

\$354,881

Building: Addition

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comme
dministrative Suites/Offices						
Ceiling - Plaster/Drywall	009 Social Worker	135	SF	6	\$467	
Doors - Wood Doors inclu hw	009 Social Worker	1	EA	6	\$301	
Floor - Carpet	009 Social Worker	135	SF	6	\$288	
Lighting - Pendent/Surface	009 Social Worker	3	EA	6	\$372	
Walls - Plaster/Drywall	009 Social Worker	366	SF	6	\$1,010	
AC Unit	011 Basement North Break Room (Assistant Engineer's Office on plan)	1	EA	6	\$496	
Ceiling - Plaster/Drywall	011 Basement North Break Room (Assistant Engineer's Office on plan)	270	SF	6	\$934	
Doors - Wood Doors inclu hw	011 Basement North Break Room (Assistant Engineer's Office on plan)	1	EA	6	\$301	
Floor - Tile/Sheet	011 Basement North Break Room (Assistant Engineer's Office on plan)	270	SF	6	\$270	
Lighting - Pendent/Surface	011 Basement North Break Room (Assistant Engineer's Office on plan)	6	EA	6	\$743	
Power Distribution	011 Basement North Break Room (Assistant Engineer's Office on plan)	2	EA	6	\$4,250	



Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	trative Suites/Offices						
	Walls - Plaster/Drywall	011 Basement North Break Room (Assistant Engineer's Office on plan)	620	SF	6	\$1,711	
	Ceiling - Exposed	013	300	SF	5	\$824	
	Doors - Wood Doors inclu hw	013	1	EA	5	\$1,174	
	Floor - Tile/Sheet	013	300	SF	6	\$300	
	Lighting - Pendent/Surface	013	6	EA	7	\$0	
	Power Distribution	013	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	013	770	SF	7	\$0	
	AC Unit	015 - Basement Engineer's Office	1	EA	7	\$0	
	Ceiling - Plaster/Drywall	015 - Basement Engineer's Office	26	SF	5	\$325	
	Ceiling - Plaster/Drywall	015 - Basement Engineer's Office	320	SF	7	\$0	
	Doors - Wood Doors inclu hw	015 - Basement Engineer's Office	1	EA	6	\$301	
	Floor - Carpet	015 - Basement Engineer's Office	346	SF	6	\$737	
	Lighting - Pendent/Surface	015 - Basement Engineer's Office	10	EA	7	\$0	
	Power Distribution	015 - Basement Engineer's Office	8	EA	7	\$0	
	Storage/ Closet	015 - Basement Engineer's Office	160	SF	6	\$1,160	
	Walls - Plaster/Drywall	015 - Basement Engineer's Office	570	SF	7	\$0	
	AC Unit	107/109	1	EA	6	\$496	
	Ceiling - Lay-in	107/109	690	SF	6	\$2,072	
	Doors - Transom Window	107/109	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	107/109	2	EA	6	\$602	
	Floor - Tile	107/109	690	SF	6	\$1,510	
	Lighting - Lay-in	107/109	20	EA	7	\$0	
	Power Distribution	107/109	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	107/109	879	SF	6	\$2,426	
	AC Unit	107/109A- North Office	1	EA	6	\$496	
	Ceiling - Lay-in	107/109A- North Office	99	SF	6	\$297	
	Doors - Wood Doors inclu hw	107/109A- North Office	1	EA	6	\$301	
	Floor - Carpet	107/109A- North Office	99	SF	7	\$0	
	Lighting - Lay-in	107/109A- North Office	4	EA	7	\$0	
	Power Distribution	107/109A- North Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	107/109A- North Office	344	SF	6	\$949	
	AC Unit	107/109B- Center Office	1	EA	6	\$496	
	Ceiling - Lay-in	107/109B- Center Office	121	SF	6	\$363	
	Doors - Wood Doors inclu hw	107/109B- Center Office	1	EA	6	\$301	
	Floor - Carpet	107/109B- Center Office	121	SF	7	\$0	
	Lighting - Lay-in	107/109B- Center Office	4	EA	7	\$0	
	Power Distribution	107/109B- Center Office	8	EA	7	\$0	



Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Walls - Plaster/Drywall	107/109B- Center Office	349	SF	6	\$963	
	AC Unit	107/109C- South Office	1	EA	6	\$496	
	Ceiling - Lay-in	107/109C- South Office	108	SF	6	\$324	
	Doors - Wood Doors inclu hw	107/109C- South Office	1	EA	6	\$301	
	Floor - Carpet	107/109C- South Office	108	SF	6	\$230	
	Lighting - Lay-in	107/109C- South Office	4	EA	6	\$476	
	Power Distribution	107/109C- South Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	107/109C- South Office	864	SF	6	\$2,385	
	AC Unit	110 Office	1	EA	6	\$496	
	Ceiling - Lay-in	110 Office	464	SF	7	\$0	
	Doors - Wood Doors inclu hw	110 Office	1	EA	6	\$301	
	Floor - Wood	110 Office	464	SF	7	\$0	
	Lighting - Lay-in	110 Office	14	EA	7	\$0	
	Power Distribution	110 Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	110 Office	769	SF	6	\$2,122	
	Ceiling - Lay-in	114 Office	200	SF	7	\$0	
	Doors - Transom Window	114 Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	114 Office	1	EA	5	\$1,174	
	Floor - Tile	114 Office	200	SF	6	\$438	
	Lighting - Lay-in	114 Office	3	EA	7	\$0	
	Power Distribution	114 Office	12	EA	5	\$46,220	
	Walls - Plaster/Drywall	114 Office	687	SF	6	\$1,896	
	Ceiling - Lay-in	203 Speech Office	285	SF	7	\$0	
	Doors - Transom Window	203 Speech Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	203 Speech Office	1	EA	5	\$1,174	
	Floor - Tile	203 Speech Office	285	SF	6	\$624	
	Lighting - Lay-in	203 Speech Office	4	EA	7	\$0	
	Power Distribution	203 Speech Office	6	EA	7	\$0	
	Walls - Plaster/Drywall	203 Speech Office	600	SF	7	\$0	
	Work SInk	203 Speech Office	1	EA	5	\$1,508	
	AC Unit	214 Work Room/Storage	1	EA	4	\$6,086	AC unit not is not to AC standards.
	Ceiling - Lay-in	214 Work Room/Storage	198	SF	6	\$595	
	Doors - Transom Window	214 Work Room/Storage	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	214 Work Room/Storage	1	EA	6	\$301	
	Floor - Tile	214 Work Room/Storage	198	SF	6	\$433	
	Lighting - Lay-in	214 Work Room/Storage	4	EA	7	\$0	
	Power Distribution	214 Work Room/Storage	2	EA	6	\$4,250	



Building: Addition

up Item - Typ	0e	Location	Quantity	Unit	Rank	Cost	Comments
ninistrative Sui	tes/Offices						
Walls - Pla	aster/Drywall	214 Work Room/Storage	492	SF	6	\$1,358	
Ceiling - L	_ay-in	314 Work Room-Storage	198	SF	6	\$595	
Doors - Tr	ansom Window	314 Work Room-Storage	9	SF	6	\$152	
Doors - W	ood Doors inclu hw	314 Work Room-Storage	1	EA	6	\$301	
Floor - Ca	rpet	314 Work Room-Storage	198	SF	6	\$422	
Lighting -	Lay-in	314 Work Room-Storage	4	EA	7	\$0	
Walls - Pla	aster/Drywall	314 Work Room-Storage	492	SF	6	\$1,358	
AC Unit		Main Office	2	EA	6	\$991	
Ceiling - L	_ay-in	Main Office	660	SF	7	\$0	
Doors - Tr	ansom Window	Main Office	18	SF	6	\$305	
Doors - W	ood Doors inclu hw	Main Office	2	EA	6	\$602	
Floor - Tile		Main Office	660	SF	6	\$1,444	
Lighting -	Lay-in	Main Office	21	EA	6	\$2,498	
Power Dis	tribution	Main Office	22	EA	6	\$46,747	
Storage/ C	loset	Main Office	12	SF	6	\$87	
Storage/ C	Closet	Main Office	15	SF	6	\$109	Storage B
Storage/ C	Closet	Main Office	12	SF	6	\$87	Storage A
Walls - Pla	aster/Drywall	Main Office	792	SF	6	\$2,186	
AC Unit		North Conference Room in Ma (Assistant Principal's Office o		EA	6	\$496	
Ceiling - L	ay-in	North Conference Room in Ma (Assistant Principal's Office o	ain Office 60	SF	6	\$180	
Doors - W	ood Doors inclu hw	North Conference Room in Ma (Assistant Principal's Office o	ain Office 1	EA	6	\$301	
Floor - Ca	rpet	North Conference Room in Ma (Assistant Principal's Office o	ain Office 60	SF	6	\$128	
Lighting -	Lay-in	North Conference Room in Ma (Assistant Principal's Office o		EA	6	\$714	
Power Dis	tribution	North Conference Room in Ma (Assistant Principal's Office o		EA	6	\$12,749	
Walls - Pla	aster/Drywall	North Conference Room in Ma (Assistant Principal's Office o		SF	6	\$1,281	
AC Unit		Principal's Office	1	EA	7	\$0	
Ceiling - L	_ay-in	Principal's Office	260	SF	7	\$0	
Ceiling - F	Plaster/Drywall	Principal's Office	20	SF	7	\$0	
Ceiling - S	Splined	Principal's Office	301	SF	7	\$0	
Doors - W	ood Doors inclu hw	Principal's Office	2	EA	7	\$0	
Doors - W	ood Doors inclu hw	Principal's Office	2	EA	6	\$602	
Floor - Ca	rpet	Principal's Office	310	SF	7	\$0	



Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	strative Suites/Offices						
	Lighting - Lay-in	Principal's Office	6	EA	7	\$0	
	Lighting - Pendent/Surface	Principal's Office	2	EA	7	\$0	
	Power Distribution	Principal's Office	8	EA	7	\$0	
	Storage/ Closet	Principal's Office	18	SF	7	\$0	
	Walls - Plaster/Drywall	Principal's Office	820	SF	7	\$0	
	AC Unit	South Copy Room in Main Office (Office #2 on plan)	1	EA	6	\$496	
	Ceiling - Lay-in	South Copy Room in Main Office (Office #2 on plan)	300	SF	7	\$0	
	Doors - Wood Doors inclu hw	South Copy Room in Main Office (Office #2 on plan)	1	EA	6	\$301	
	Floor - Tile	South Copy Room in Main Office (Office #2 on plan)	300	SF	6	\$656	
	Lighting - Lay-in	South Copy Room in Main Office (Office #2 on plan)	7	EA	7	\$0	
	Power Distribution	South Copy Room in Main Office (Office #2 on plan)	4	EA	6	\$8,500	
	Storage/ Closet	South Copy Room in Main Office (Office #2 on plan)	32	SF	6	\$232	
	Walls - Plaster/Drywall	South Copy Room in Main Office (Office #2 on plan)	576	SF	6	\$1,590	
Mechar	nical/ Service Rooms						
	Air Intake Plenums	Service Rooms	83	SF	6	\$514	at south
	Air Intake Plenums	Service Rooms	400	SF	7	\$0	adjacent to engine room @ north of addition
	Boiler Room	Service Rooms	2,317	SF	6	\$16,600	
	Janitor's Closet	Service Rooms	56	SF	6	\$401	1st Floor JC
	Janitor's Closet	Service Rooms	64	SF	6	\$459	JC 3rd South
	Janitor's Closet	Service Rooms	56	SF	6	\$401	2nd Floor JC
	Loading Docks	Service Rooms	812	SF	6	\$5,817	Engine Room
	Mechanical/ Service Rooms	Service Rooms	520	SF	7	\$0	'switch board room'
	Mechanical/ Service Rooms	Service Rooms	334	SF	5	\$5,388	engine room
	Mechanical/ Service Rooms	Service Rooms	221	SF	6	\$1,583	"chemical room"
	Mechanical/ Service Rooms	Service Rooms	936	SF	6	\$6,706	"pump & tank room"
	Mechanical/ Service Rooms	Service Rooms	6	SF	6	\$0	1st Floor Mechanical Room
	Storage Room	Service Rooms	280	SF	7	\$0	east storain ge room adjacent to SW exit door
	Storage Room	Service Rooms	750	SF	6	\$5,373	east storage room adjacent to SW exit stairway
	Storage Room	Service Rooms	52	SF	5	\$839	closet off of 'chemical room'
	Storage Room	Service Rooms	198	SF	6	\$1,419	Storage 2 inside basement storage
	Storage Room	Service Rooms	38	SF	6	\$272	Basement Storage



Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechar	nical/ Service Rooms						
	Storage Room	Service Rooms	1,040	SF	6	\$7,451	Basement Storage (Girls gymnasium on floor plan)
	Storage Room	Service Rooms	345	SF	6	\$2,472	maintenance room storage @ north end of main corridor
	Storage Room	Service Rooms	196	SF	6	\$1,404	north of 'pump & tank room'
	Storage Room	Service Rooms	80	SF	5	\$1,290	Storage 1 inside basement storage
	Vaults	Service Rooms	130	SF	6	\$931	In Main Office
Prep Ro	oom						
	Casework	103 Prep Room	14	LF	5	\$2,927	damaged & deteriorating finish, veneer and hardware
	Ceiling - Lay-in	103 Prep Room	300	SF	7	\$0	
	Doors - Transom Window	103 Prep Room	9	SF	7	\$0	
	Doors - Wood Doors inclu hw	103 Prep Room	2	EA	6	\$602	
	Floor - Tile	103 Prep Room	300	SF	5	\$1,347	cracked
	Lighting - Lay-in	103 Prep Room	4	EA	7	\$0	
	Walls - Plaster/Drywall	103 Prep Room	251	SF	5	\$1,109	cracked plaster & peeling paint
	Walls - Plaster/Drywall	103 Prep Room	400	SF	6	\$1,104	
	Work Sink	103 Prep Room	1	EA	6	\$379	
Restroc	om						
	Accessories	001A	23	SF	7	\$0	mirror, toilet paper, soap dispenser.
	Ceiling - Exposed	001A	23	SF	6	\$34	
	Doors - Wood Doors inclu hw	001A	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	001A	23	SF	6	\$49	
	Lavatory	001A	1	EA	7	\$0	
	Lighting - Metal Halide/Sodium Vapor	001A	1	EA	7	\$0	
	Walls - Plaster/Drywall	001A	62	SF	6	\$171	
	Walls - Tile	001A	124	SF	7	\$0	
	Water Closet	001A	1	EA	7	\$0	
	Accessories	011A Basement North Break Room Toilet	55	SF	6	\$507	Mirror, soap dispenser.
	Ceiling - Plaster/Drywall	011A Basement North Break Room Toilet	55	SF	6	\$190	
	Doors - Steel Doors incl hw	011A Basement North Break Room Toilet	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	011A Basement North Break Room Toilet	55	SF	6	\$116	
	Lavatory	011A Basement North Break Room Toilet	1	EA	6	\$320	
	Lighting - Pendent/Surface	011A Basement North Break Room Toilet	1	EA	6	\$124	



Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Partitions	011A Basement North Break Room Toilet	1	EA	6	\$297	
	Showers	011A Basement North Break Room Toilet	1	EA	6	\$311	
	Walls - Plaster/Drywall	011A Basement North Break Room Toilet	96	SF	6	\$265	
	Walls - Structural Glazed Tile	011A Basement North Break Room Toilet	77	SF	6	\$242	
	Walls - Tile	011A Basement North Break Room Toilet	126	SF	6	\$276	
	Water Closet	011A Basement North Break Room Toilet	1	EA	7	\$0	
	Accessories	013A Unisex Toilet	56	SF	6	\$517	
	Ceiling - Exposed	013A Unisex Toilet	56	SF	5	\$154	
	Doors - Steel Doors incl hw	013A Unisex Toilet	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	013A Unisex Toilet	56	SF	6	\$119	
	Lavatory	013A Unisex Toilet	1	EA	5	\$1,590	
	Lighting - Pendent/Surface	013A Unisex Toilet	1	EA	6	\$124	
	Partitions	013A Unisex Toilet	1	EA	5	\$751	
	Showers	013A Unisex Toilet	1	EA	4	\$4,720	Wall panels deteriorated.
	Walls - Plaster/Drywall	013A Unisex Toilet	100	SF	6	\$276	
	Walls - Structural Glazed Tile	013A Unisex Toilet	54	SF	6	\$170	
	Walls - Tile Ceramic/ Porcelain	013A Unisex Toilet	154	SF	6	\$348	
	Water Closet	013A Unisex Toilet	1	EA	6	\$336	
	Accessories	103A (in prep room next to 105)	25	SF	5	\$495	missing
	Ceiling - Plaster/Drywall	103A (in prep room next to 105)	25	SF	6	\$87	
	Doors - Wood Doors inclu hw	103A (in prep room next to 105)	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	103A (in prep room next to 105)	25	SF	6	\$53	
	Lavatory	103A (in prep room next to 105)	1	EA	5	\$1,590	
	Lighting - Pendent/Surface	103A (in prep room next to 105)	1	EA	7	\$0	
	Walls - Plaster/Drywall	103A (in prep room next to 105)	70	SF	7	\$0	
	Walls - Tile Ceramic/ Porcelain	103A (in prep room next to 105)	70	SF	7	\$0	
	Water Closet	103A (in prep room next to 105)	1	EA	7	\$0	
	Accessories	1st Floor Women's Unisex	40	SF	6	\$369	Mirror, soap dispenser, paper towel dispenser.
	Ceiling - Plaster/Drywall	1st Floor Women's Unisex	40	SF	6	\$138	
	Doors - Wood Doors inclu hw	1st Floor Women's Unisex	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Floor Women's Unisex	40	SF	6	\$85	
	Lavatory	1st Floor Women's Unisex	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor Women's Unisex	1	EA	7	\$0	



Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Partitions	1st Floor Women's Unisex	2	EA	6	\$594	
	Walls - Structural Glazed Tile	1st Floor Women's Unisex	231	SF	6	\$727	
	Water Closet	1st Floor Women's Unisex	2	EA	6	\$672	
	Accessories	1st Floor	300	SF	6	\$2,767	mirror, soap, toilet paper
	Accessories	1st Floor	194	SF	6	\$1,789	
	Ceiling - Plaster/Drywall	1st Floor	194	SF	6	\$671	
	Ceiling - Plaster/Drywall	1st Floor	300	SF	7	\$0	
	Floor Drain	1st Floor	2	EA	6	\$2,118	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor	194	SF	6	\$411	
	Floor - Tile Ceramic/ Porcelain	1st Floor	300	SF	6	\$635	
	Hand Dryer	1st Floor	2	EA	7	\$0	
	Hand Dryer	1st Floor	2	EA	6	\$460	
	Lavatory	1st Floor	1	EA	6	\$320	
	Lavatory	1st Floor	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor	5	EA	6	\$619	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	\$0	
	Partitions	1st Floor	2	EA	6	\$594	
	Partitions	1st Floor	7	EA	6	\$2,078	
	Urinals	1st Floor	5	EA	6	\$1,680	
	Walls - Plaster/Drywall	1st Floor	225	SF	6	\$621	
	Walls - Plaster/Drywall	1st Floor	93	SF	6	\$257	
	Walls - Structural Glazed Tile	1st Floor	190	SF	6	\$598	
	Walls - Structural Glazed Tile	1st Floor	100	SF	6	\$315	
	Walls - Tile	1st Floor	91	SF	6	\$199	
	Walls - Tile	1st Floor	420	SF	6	\$919	
	Water Closet	1st Floor	2	EA	6	\$672	
	Water Closet	1st Floor	7	EA	6	\$2,352	
	Accessories	2nd Floor Men	40	SF	6	\$369	mirror, soap dispenser, paper towel dispenser.
	Ceiling - Plaster/Drywall	2nd Floor Men	40	SF	6	\$138	
	Doors - Wood Doors inclu hw	2nd Floor Men	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Men	40	SF	6	\$85	
	Lavatory	2nd Floor Men	1	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor Men	1	EA	6	\$124	
	Partitions	2nd Floor Men	1	EA	6	\$297	
	Walls - Structural Glazed Tile	2nd Floor Men	139	SF	7	\$0	
	Walls - Tile	2nd Floor Men	100	SF	7	\$0	



Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Water Closet	2nd Floor Men	1	EA	6	\$336	
	Accessories	2nd Floor	300	SF	6	\$2,767	mirror, soap, toilet paper
	Accessories	2nd Floor	194	SF	6	\$1,789	Soap, toilet paper
	Ceiling - Plaster/Drywall	2nd Floor	300	SF	6	\$1,038	
	Ceiling - Plaster/Drywall	2nd Floor	194	SF	7	\$0	
	Floor Drain	2nd Floor	2	EA	6	\$2,118	
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	300	SF	6	\$635	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	194	SF	6	\$411	
	Hand Dryer	2nd Floor	2	EA	7	\$0	
	Hand Dryer	2nd Floor	2	EA	6	\$460	
	Lavatory	2nd Floor	1	EA	6	\$320	
	Lavatory	2nd Floor	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	\$0	
	Partitions	2nd Floor	2	EA	6	\$594	
	Partitions	2nd Floor	7	EA	6	\$2,078	
	Urinals	2nd Floor	5	EA	6	\$1,680	
	Walls - Plaster/Drywall	2nd Floor	93	SF	6	\$257	
	Walls - Plaster/Drywall	2nd Floor	240	SF	6	\$662	
	Walls - Structural Glazed Tile	2nd Floor	140	SF	7	\$0	
	Walls - Structural Glazed Tile	2nd Floor	154	SF	6	\$484	
	Walls - Tile	2nd Floor	133	SF	7	\$0	
	Walls - Tile	2nd Floor	490	SF	6	\$1,072	
	Water Closet	2nd Floor	2	EA	6	\$672	
	Water Closet	2nd Floor	7	EA	6	\$2,352	
	Accessories	302A	40	SF	6	\$369	mirror
	Ceiling - Plaster/Drywall	302A	40	SF	7	\$0	
	Doors - Wood Doors inclu hw	302A	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	302A	40	SF	6	\$85	
	Lavatory	302A	1	EA	6	\$320	
	Lighting - Pendent/Surface	302A	1	EA	7	\$0	
	Walls - Plaster/Drywall	302A	68	SF	6	\$188	
	Walls - Tile	302A	97	SF	6	\$212	
	Water Closet	302A	1	EA	6	\$336	
	Accessories	3rd Floor Women	63	SF	6	\$581	Mirror, soap dispenser, paper towel dispenser.
	Ceiling - Plaster/Drywall	3rd Floor Women	63	SF	6	\$218	



Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Doors - Wood Doors inclu hw	3rd Floor Women	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Women	63	SF	6	\$133	
	Lavatory	3rd Floor Women	1	EA	6	\$320	
	Lighting - Pendent/Surface	3rd Floor Women	2	EA	6	\$248	
	Partitions	3rd Floor Women	1	EA	6	\$297	
	Walls - Structural Glazed Tile	3rd Floor Women	49	SF	6	\$154	
	Walls - Tile	3rd Floor Women	154	SF	6	\$337	
	Water Closet	3rd Floor Women	1	EA	6	\$336	
	Accessories	3rd Floor	300	SF	6	\$2,767	mirror, soap
	Accessories	3rd Floor	200	SF	6	\$1,845	soap, toilet paper
	Ceiling - Plaster/Drywall	3rd Floor	300	SF	7	\$0	
	Ceiling - Plaster/Drywall	3rd Floor	200	SF	7	\$0	
	Floor Drain	3rd Floor	1	EA	6	\$1,059	
	Floor Drain	3rd Floor	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	200	SF	6	\$423	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	300	SF	6	\$635	
	Hand Dryer	3rd Floor	2	EA	7	\$0	
	Hand Dryer	3rd Floor	2	EA	7	\$0	
	Lavatory	3rd Floor	1	EA	6	\$320	
	Lavatory	3rd Floor	1	EA	6	\$320	
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	\$0	
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	\$0	
	Partitions	3rd Floor	7	EA	6	\$2,078	
	Partitions	3rd Floor	2	EA	6	\$594	
	Urinals	3rd Floor	5	EA	6	\$1,680	
	Walls - Plaster/Drywall	3rd Floor	93	SF	6	\$257	
	Walls - Plaster/Drywall	3rd Floor	225	SF	7	\$0	
	Walls - Structural Glazed Tile	3rd Floor	140	SF	6	\$440	
	Walls - Structural Glazed Tile	3rd Floor	190	SF	7	\$0	
	Walls - Tile	3rd Floor	420	SF	7	\$0	
	Walls - Tile	3rd Floor	133	SF	6	\$291	
	Water Closet	3rd Floor	7	EA	6	\$2,352	
	Water Closet	3rd Floor	2	EA	6	\$672	
	Accessories	Engineer Toilet Room	62	SF	7	\$0	
	Ceiling - Exposed	Engineer Toilet Room	62	SF	6	\$92	
	Doors - Wood Doors inclu hw	Engineer Toilet Room	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	Engineer Toilet Room	62	SF	6	\$131	



Building: Addition

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Lavatory	Engineer Toilet Room	1	EA	6	\$320	
	Lighting - Pendent/Surface	Engineer Toilet Room	1	EA	7	\$0	
	Showers	Engineer Toilet Room	1	EA	6	\$311	
	Walls - Plaster/Drywall	Engineer Toilet Room	80	SF	7	\$0	
	Walls - Tile Ceramic/ Porcelain	Engineer Toilet Room	80	SF	7	\$0	
	Water Closet	Engineer Toilet Room	1	EA	6	\$336	
	Accessories	Main Office Unisex	28	SF	6	\$258	Mirror, toilet paper, soap dispenser
	Ceiling - Plaster/Drywall	Main Office Unisex	28	SF	6	\$97	
	Doors - Wood Doors inclu hw	Main Office Unisex	1	EA	6	\$301	
	Floor - Tile	Main Office Unisex	28	SF	6	\$61	
	Lavatory	Main Office Unisex	1	EA	6	\$320	
	Lighting - Pendent/Surface	Main Office Unisex	1	EA	6	\$124	
	Walls - Plaster/Drywall	Main Office Unisex	177	SF	6	\$489	
	Water Closet	Main Office Unisex	1	EA	6	\$336	
	Accessories	Principal's Office Toilet	34	SF	6	\$314	
	Ceiling - Plaster/Drywall	Principal's Office Toilet	34	SF	7	\$0	
	Doors - Wood Doors inclu hw	Principal's Office Toilet	1	EA	7	\$0	
	Floor - Tile/Sheet	Principal's Office Toilet	34	SF	7	\$0	
	Lavatory	Principal's Office Toilet	1	EA	6	\$320	
	Lighting - Pendent/Surface	Principal's Office Toilet	1	EA	7	\$0	
	Walls - Plaster/Drywall	Principal's Office Toilet	170	SF	7	\$0	
	Water Closet	Principal's Office Toilet	1	EA	7	\$0	

Rooms (Other Than Classrooms) Subtotal:

\$380,175

Building: Addition

J	· · · · · · · · · · · · · · · · · · ·						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Ceiling - Lay-in	1st North	1,764	SF	6	\$5,297	
	Drinking Fountains - Single Fountain	1st North	3	EA	6	\$827	
	Floor - Tile/Sheet	1st North	1,764	SF	6	\$959	
	Lighting - Lay-in	1st North	20	EA	6	\$2,380	
	Student Lockers - One Tier	1st North	39	EA	6	\$3,621	
	Walls - Plaster/Drywall	1st North	1,680	SF	6	\$7,447	
	Ceiling - Lay-in	1st South	840	SF	7	\$0	
	Floor - Tile/Sheet	1st South	840	SF	6	\$456	



Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Lighting - Lay-in	1st South	11	EA	7	\$0	
	Student Lockers - One Tier	1st South	60	EA	6	\$5,570	
	Walls - Plaster/Drywall	1st South	1,397	SF	6	\$6,193	
	Ceiling - Lay-in	2nd North	1,877	SF	7	\$0	
	Drinking Fountains - Single Fountain	2nd North	3	EA	6	\$827	
	Floor - Tile/Sheet	2nd North	1,877	SF	6	\$1,020	
	Lighting - Lay-in	2nd North	18	EA	7	\$0	
	Student Lockers - One Tier	2nd North	106	EA	6	\$9,841	
	Walls - Plaster/Drywall	2nd North	1,732	SF	6	\$7,678	
	Ceiling - Lay-in	2nd South	852	SF	7	\$0	
	Doors - Transom Window	2nd South	24	EA	6	\$406	
	Doors - Wood Doors include hw	2nd South	2	EA	6	\$602	
	Floor - Tile/Sheet	2nd South	852	SF	6	\$463	
	Lighting - Lay-in	2nd South	11	EA	7	\$0	
	Student Lockers - One Tier	2nd South	60	EA	7	\$0	
	Walls - Plaster/Drywall	2nd South	1,438	SF	6	\$6,375	
	Ceiling - Lay-in	3rd North	1,877	SF	7	\$0	
	Drinking Fountains - Single Fountain	3rd North	2	EA	6	\$551	
	Floor - Tile/Sheet	3rd North	1,877	SF	6	\$1,020	
	Lighting - Lay-in	3rd North	18	EA	7	\$0	
	Student Lockers - One Tier	3rd North	138	EA	6	\$12,811	
	Walls - Plaster/Drywall	3rd North	1,732	SF	6	\$7,678	
	Ceiling - Lay-in	3rd South	840	SF	6	\$2,523	
	Doors - Transom Window	3rd South	18	EA	6	\$305	
	Doors - Wood Doors include hw	3rd South	2	EA	6	\$602	
	Floor - Tile/Sheet	3rd South	840	SF	6	\$456	
	Lighting - Lay-in	3rd South	11	EA	7	\$0	
	Student Lockers - One Tier	3rd South	64	EA	7	\$0	
	Walls - Plaster/Drywall	3rd South	1,354	SF	6	\$6,002	
	Ceiling - Plaster/Drywall	Basement	3,386	SF	6	\$20,966	
	Doors - Steel Doors incl hw	Basement	9	EA	6	\$2,709	
	Floor - Epoxy/ Painted	Basement	3,332	SF	6	\$1,763	
	Floor - Tile Ceramic/ Porcelain	Basement	54	SF	6	\$151	
	Lighting - Pendent/Surface	Basement	18	EA	7	\$0	
	Walls - Masonry	Basement	759	SF	6	\$2,388	
	Walls - Plaster/Drywall	Basement	1,163	SF	6	\$5,156	



Building: Addition

						Comments
Camera Viewing Station		2	EA	7	\$0	
Security Cameras		3	EA	7	\$0	
Ceiling - Plaster/Drywall	East Stair	241	SF	6	\$1,765	cracked plaster & peeling paint
Floor - Epoxy/ Painted	East Stair	18	SF	6	\$10	
Floor - Terrazzo	East Stair	279	SF	6	\$2,342	
Handrails	East Stair	188	LF	6	\$1,629	
Lighting - Pendent/Surface	East Stair	6	EA	6	\$743	
Stairs - Terrazzo	East Stair	468	LF	6	\$4,343	
Walls - Plaster/Drywall	East Stair	300	SF	5	\$1,604	cracked plaster & peeling paint
Walls - Plaster/Drywall	East Stair	1,695	SF	6	\$4,678	
Ceiling - Lay-in	SE Stair	331	SF	7	\$0	
Ceiling - Plaster/Drywall	SE Stair	120	SF	5	\$1,764	
Floor - Epoxy/ Painted	SE Stair	175	SF	5	\$798	
Floor - Terrazzo	SE Stair	225	SF	6	\$1,889	
Floor - Tile	SE Stair	102	SF	6	\$55	
Handrails	SE Stair	136	LF	6	\$1,179	
Lighting - Lay-in	SE Stair	4	EA	7	\$0	
Lighting - Pendent/Surface	SE Stair	7	EA	6	\$867	
Stairs - Terrazzo	SE Stair	480	LF	6	\$4,455	
Walls - Plaster/Drywall	SE Stair	500	SF	5	\$2,674	
Walls - Plaster/Drywall	SE Stair	1,955	SF	6	\$5,396	
Ceiling - Lay-in	SW Stair	458	SF	7	\$0	
Ceiling - Plaster/Drywall	SW Stair	275	SF	6	\$2,013	
Floor - Epoxy/ Painted	SW Stair	572	SF	6	\$303	
Floor - Terrazzo	SW Stair	319	SF	6	\$2,678	
Floor - Tile	SW Stair	284	SF	6	\$154	
Handrails	SW Stair	190	LF	6	\$1,647	
Lighting - Lay-in	SW Stair	2	EA	7	\$0	
Lighting - Pendent/Surface	SW Stair	11	EA	7	\$0	
Stairs - Terrazzo	SW Stair	520	LF	6	\$4,826	
Walls - Plaster/Drywall	SW Stair	2,640	SF	6	\$7,286	
Walls - Structural Glazed Tile	SW Stair	108	SF	6	\$340	
	Ceiling - Plaster/Drywall Floor - Epoxy/ Painted Floor - Terrazzo Handrails Lighting - Pendent/Surface Stairs - Terrazzo Walls - Plaster/Drywall Walls - Plaster/Drywall Ceiling - Lay-in Ceiling - Plaster/Drywall Floor - Epoxy/ Painted Floor - Terrazzo Floor - Tile Handrails Lighting - Lay-in Lighting - Pendent/Surface Stairs - Terrazzo Walls - Plaster/Drywall Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Floor - Epoxy/ Painted Floor - Terrazzo Floor - Tile Handrails Lighting - Pendent/Surface Stairs - Terrazzo Floor - Tile Handrails Lighting - Pendent/Surface Stairs - Terrazzo Floor - Tile Handrails Lighting - Lay-in Lighting - Pendent/Surface Stairs - Terrazzo Walls - Plaster/Drywall	Ceiling - Plaster/DrywallEast StairFloor - Epoxy/ PaintedEast StairFloor - TerrazzoEast StairHandrailsEast StairLighting - Pendent/SurfaceEast StairStairs - TerrazzoEast StairWalls - Plaster/DrywallEast StairCeiling - Lay-inSE StairCighting - Lay-inSE StairFloor - TerrazzoSE StairFloor - TileSE StairHandrailsSE StairLighting - Lay-inSE StairLighting - Pendent/SurfaceSE StairStairs - TerrazzoSE StairWalls - Plaster/DrywallSE StairWalls - Plaster/DrywallSE StairCeiling - Lay-inSW StairCeiling - Lay-inSW StairCigling - Lay-inSW StairCeiling - Plaster/DrywallSW StairCeiling - Plaster/DrywallSW StairFloor - Epoxyl PaintedSW StairFloor - TileSW StairFloor - TileSW StairHandrailsSW StairLighting - Lay-inSW StairLighting - Lay-inSW StairLighting - Lay-inSW StairLighting - Lay-inSW StairLighting - Plaster/DrywallSW StairFloor - Tile<	Ceiling - Plaster/DrywallEast Stair241Floor - Eproxyl PaintedEast Stair18Floor - TerrazzoEast Stair279HandrailsEast Stair279Lighting - Pendent/SurfaceEast Stair188Lighting - Pendent/SurfaceEast Stair6Stairs - TerrazzoEast Stair468Walls - Plaster/DrywallEast Stair300Walls - Plaster/DrywallEast Stair300Ceiling - Lay-inSE Stair120Floor - Epoxyl PaintedSE Stair120Floor - TerrazzoSE Stair120Floor - TileSE Stair120HandrailsSE Stair136Lighting - Lay-inSE Stair4Lighting - Lay-inSW Stair4Lighting - Plaster/DrywallSE Stair195Ceiling - Lay-inSW Stair275Ploor - Epoxyl PaintedSW Stair319Floor - Epoxyl PaintedSW Stair284HandraisSW Stair219Lighting - Lay-inSW Stair219Lighti	Ceiling - Plaster/DrywallEast Stair241SFFloor - Epoxyl PaintedEast Stair18SFFloor - TerrazzoEast Stair279SFHandrailsEast Stair279SFLighting - Pendent/SurfaceEast Stair188LFWalls - Plaster/DrywallEast Stair468LFWalls - Plaster/DrywallEast Stair300SFCeiling - Lay-inSE Stair1,895SFCeiling - Plaster/DrywallEast Stair1,205SFCort - TerrazzoSE Stair120SFFloor - Epoxyl PaintedSE Stair120SFFloor - TerrazzoSE Stair120SFFloor - TerrazzoSE Stair120SFFloor - TerrazzoSE Stair120SFFloor - TerrazzoSE Stair120SFFloor - TileSE Stair120SFHandrailsSE Stair120SFLighting - Lay-inSE Stair120SFValls - Plaster/DrywallSE Stair4EALighting - Lay-inSW Stair190SFCeiling - Plaster/DrywallSE Stair195SFCeiling - Plaster/DrywallSW Stair275SFFloor - TileSW Stair275SFFloor - TerrazzoSW Stair284SFCeiling - Plaster/DrywallSW Stair284SFCeiling - Plaster/DrywallSW Stair284SFCeiling - Pla	Celling - Plaster/DrywallEast Stair241SF6Floor - Epoxy/ PaintedEast Stair18SF6Floor - TerrazzoEast Stair279SF6HandrailsEast Stair188LF6Lighting - Pendent/SurfaceEast Stair188LF6Stairs - TerrazzoEast Stair6EA6Stairs - TerrazzoEast Stair300SF5Walls - Plaster/DrywallEast Stair300SF7Celling - Plaster/DrywallEast Stair1,695SF6Celling - Plaster/DrywallSE Stair120SF5Floor - Epoxy/ PaintedSE Stair120SF5Floor - TerrazzoSE Stair120SF6Celling - Plaster/DrywallSE Stair120SF6Floor - TerrazzoSE Stair120SF6Floor - TileSE Stair120SF6HandrailsSE Stair136LF6Lighting - Lay-inSE Stair136LF6Valls - Plaster/DrywallSE Stair300SF5Valls - Plaster/DrywallSE Stair136LF6Valls - Plaster/DrywallSE Stair136LF6Valls - Plaster/DrywallSE Stair5566Celling - Plaster/DrywallSE Stair136SF7Celling - Plaster/DrywallSE Stair136SF7	Ceiling - Plaster/Drywall East Stair 241 SF 6 \$1,765 Floor - Epoxy/ Painted East Stair 18 SF 6 \$10 Floor - Terrazzo East Stair 18 SF 6 \$1,629 Lighting - Pendent/Surface East Stair 188 LF 6 \$1,629 Lighting - Pendent/Surface East Stair 168 LF 6 \$1,629 Lighting - Pendent/Surface East Stair 1695 SF 6 \$4,343 Valls - Plaster/Drywall East Stair 300 SF 5 \$1,664 Valls - Plaster/Drywall East Stair 1095 SF 6 \$4,473 Ceiling - Lay-in SE Stair 120 SF 5 \$1,664 Floor - Forazzo SE Stair 120 SF 5 \$1,889 Floor - Tile SE Stair 122 SF 6 \$1,819 Floor - Tile SE Stair 136 LF 6 \$1,517 Hand



Jose De Diego Elementary Community Academy

1313 N Claremont Ave Chicago, IL 60622

Total Building Cost

SITE

\$4,820,891

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	ainage						
	Civil/ Drainage - Catch Basin	Entire Site	4	EA	6	\$4,375	
	Civil/ Drainage - Site Manhole	Entire Site	17	EA	6	\$25,377	
encing	1						
	Fencing - Chain Link	Entire Site / Site - East	30	LF	6	\$563	at trash compactor
	Fencing - Guard Rail	Entire Site / South East	169	LF	5	\$4,850	alley- bent, warped
	Fencing - New Standard Ornamental	Entire Site	363	LF	6	\$11,581	
	Fencing - Old Standard Ornamental	Entire Site / Site West	296	LF	6	\$15,323	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site / Site South	129	LF	6	\$1,692	at playlot
_andsc	ape						
	Landscape - Hardscape- Concrete	Entire Site	2,202	SF	6	\$11,367	
	Landscape - Hardscape- Concrete	Entire Site	1,468	SF	5	\$16,101	cracking, spalling
	Parkway trees	Entire Site	28	EA	7	\$0	
	Parkway trees	Entire Site / Site North	3	EA	4	\$7,872	stumps
	Trash Receptacles	Entire Site	6	EA	6	\$1,874	
Parking	Lot						
	Surface - Asphalt	Southeast Site	17,343	SF	6	\$41,913	slight alligatoring of pavement throughout
	Trash Compactor	Southeast Site / Site - East	1	EA	6	\$0	
	Trash Enclosure - Chain Links	Southeast Site	364	SF	6	\$6,387	
Playgro	und						
	Equipment - School Age 5-12	South	1	EA	7	\$0	
	Surface - Poured Surface	South	6,560	SF	7	\$0	
Sidewa	ks						
	Sidewalks - Perimeter Sidewalks	Entire Site	24,064	SF	6	\$47,832	
Signag)						
	Flag Pole - Building Mounted Flag Pole	Entire Site / West Façade	1	EA	7	\$0	
	Flag Pole - Flag Pole	Entire Site / Site South	1	EA	7	\$0	at playlot
	Marquee - Free Standing Back lighted w/ LED	Entire Site / South West	1	EA	7	\$0	
Site S	ubtotal:	Little Site / Sodin West	•	LA		\$197,107	



Jose De Diego Elementary Community Academy

1313 N Claremont Ave Chicago, IL 60622

\$197,107

\$12,562,819

Total Site Cost

Campus Total ^{2 3}

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main	-											ļ		
Art Room	Regular Classroom		228	228	1,239	1	2	8	120	60	40	Ν	Ν	Ν
Computer Lab	Regular Classroom		127	127	1,074	1	39	134	170	42	40	Ν	Y	Ν
Computer Lab	Regular Classroom		335	335	1,070	1	2	15	170	42	40	Ν	Y	Ν
Music Room	Regular Classroom		137	137	990	1	0	8	240	65	40	Ν	Ν	Ν
Other Instructional Use	Other Instructional Use	1st Floor	117	117	154	0	0	2	64	32	40	Ν	Ν	Ν
Pre School	Regular Classroom		019	N/A	1,054	1	1	8	42	21	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		021	N/A	868	0	1	10	60	30	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		023	N/A	990	1	1	8	84	42	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		112	112	675	1	2	6	150	75	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		118	118	620	1	2	8	125	63	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		120	120	620	1	1	9	100	50	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		122	122	1,245	1	2	6	175	88	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		126	126	1,329	1	2	8	200	100	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		129	129	1,054	1	1	7	170	42	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		131	131	1,054	1	0	7	170	42	40	Ν	Y	Y
Regular Classroom	Regular Classroom		133	133	1,054	1	0	7	170	42	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		135	135	1,054	1	2	11	170	42	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		209	209	690	1	1	6	150	75	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		210	210	612	1	1	6	150	75	40	Ν	Y	Y
Regular Classroom	Regular Classroom		211	211	690	1	1	6	150	75	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		213	213	690	1	1	6	150	75	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		222	222	1,640	1	2	4	150	75	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		227	227	1,068	1	0	11	168	45	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		229	229	1,068	1	0	11	168	45	40	Ν	Y	Y
Regular Classroom	Regular Classroom		230	230	1,386	1	2	8	104	22		Ν	Ν	Ν
Regular Classroom	Regular Classroom		231	231	1,068	1	0	11	168	45	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		233	233	1,068	1	0	11	168	45	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		235	235	1,080	1	2	13	168	45		Ν	Y	Ν
Regular Classroom	Regular Classroom		319	N/A	1,088	1	1	11	140	70	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		321	N/A	1,156	0	1	5	140	80	40	N	Ν	N
Regular Classroom	Regular Classroom		323	N/A	1,020	1	1	4	140	70	40	N	N	N
Regular Classroom	Regular Classroom		327	N/A	1,070	1	0	11	170	42	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		329	N/A	1,070	1	0	11	170	42	40	N	Y	N
Regular Classroom	Regular Classroom		331	N/A	1,070	1	0	11	170	42	40	N	Y	N
Regular Classroom	Regular Classroom		333	N/A	1,070	1	0	11	170	42	40	Ν	Y	Ν
Science Lab Level 1	Science Lab Level 1		218	218	1,480	1	1	10	300	150	40	N	Y	N
Science Lab Level 2	Science Lab Level 2		318	N/A	1,409	0	1	30	211	105	40	N	Ν	Ν

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main	-	+				1	1	II				1		4
Store Room	Regular Classroom		212	212	675	1	1	12	150	75	40	Ν	Y	Ν
Store Room	Regular Classroom		215	215	690	1	1	6	150	75	40	Ν	Ν	Ν
Weight	Store Room	1st Floor	in Boy's Gym		30							Ν	Ν	Ν
Addition														
Computer Lab	Regular Classroom		305	N/A	998	1	43	80	210	70	40	Ν	Y	Ν
Other Instructional Use	Other Instructional Use		303/301	N/A	1,340	0	2	18	300	150	40	Ν	Y	N
Regular Classroom	Regular Classroom		001	N/A	1,188	1	1	12	100	50	40	N	Ν	N
Regular Classroom	Regular Classroom		005	N/A	1,145	1	2	14	150	75	40	N	Y	N
Regular Classroom	Regular Classroom		007	N/A	650	1	1	6	100	50	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		101	101	999	1	1	12	180	90	40	N	Y	N
Regular Classroom	Regular Classroom		102	102	1,592	1	1	8	360	180	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		105	105	999	1	1	12	225	113	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		112	112	690	0	1	6	70	40	40	Y	Y	Y
Regular Classroom	Regular Classroom		201	201	999	1	1	12	225	113	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		202	203	960	1	1	8	245	123	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		204	204	667	1	1	4	150	75	40	Ν	Y	Y
Regular Classroom	Regular Classroom		205	205	999	1	21	43	165	66	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		207	207	690	1	1	6	150	75	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		209	209	690	1	1	6	140	70	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		210	210	612	1	1	6	140	70	40	Ν	Y	Y
Regular Classroom	Regular Classroom		212	212	690	0	1	8	140	70	40	Y	Y	Y
Regular Classroom	Regular Classroom		213	213	660	1	1	6	140	70	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		215	215	690	1	1	6	140	70	40	Ν	N	Ν
Regular Classroom	Regular Classroom		304	N/A	668	1	1	8	140	70	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		307	307	682	1	1	6	140	70	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		309	309	660	1	1	6	140	70	40	N	Ν	Ν
Regular Classroom	Regular Classroom		310	N/A	620	1	1	6	140	70	40	Ν	Ν	Y
Regular Classroom	Regular Classroom		311	N/A	660	1	1	6	140	70	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		312	N/A	690	0	1	20	140	70	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		313	N/A	660	1	1	6	140	70	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		315	N/A	672	1	1	6	140	70	40	N	Ν	Ν
Special Program	Regular Classroom		211	211	660	1	1	6	140	70	40	N	N	Ν
Store Room	Regular Classroom		302	N/A	863	0	1	8	112	56	40	Ν	Ν	Ν