

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1929	3	106,900
Addition 1	1965	3	73,900
Addition 2	1974	1	37,400
Campus Total			218,200

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	Door 1 - Southeast	1	EA	6	2-5 years	
	Exterior Doors - Exterior Steel Door	Door 1 - Southeast	2	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	Door 1 - Southeast	1	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	Door 1 - Southeast	90	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	Door 1 - Southeast	15	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 13 - East center	1	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	Door 13 - East center	3	LF	6	6-10 years	
	Exterior Doors - Exterior Wood Door	Door 2 - Northeast	2	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	Door 2 - Northeast	1	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	Door 2 - Northeast	90	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	Door 2 - Northeast	15	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 5 - Courtyard north	1	EΑ	5	0-1 year	Frame rusted.
	Exterior Doors - Transom Lite	Door 5 - Courtyard north	1	EΑ	5	0-1 year	Large amount of rust
	Exterior Stairs - Concrete	Door 5 - Courtyard north	60	LF	6	10+ years	· ·
	Exterior Stairs - Concrete	Door 5 - Courtyard north	7	LF	5	0-1 year	Cracked.
	Stair Handrail - Steel_Stair Handrail	Door 5 - Courtyard north	20	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	Door 5.1 - Courtyard north	1	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	Door 5.1 - Courtyard north	2	EA	4	0-1 year	Broken.
	Exterior Doors - Overhead Rolling/ Garage	Door 5.2 - Courtyard center	1	EΑ	6	6-10 years	
	Door	·				•	
	Entrance Control - Audio and Video	Door 6 - Courtyard center	1	EA	6	2-5 years	
	Exterior Doors - Exterior Steel Door	Door 6 - Courtyard center	1	EA	6	6-10 years	
		•				•	



Categor	ry : Exterior		В	uilding	: Main				
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Exterior Doors - Exterior Steel Door	Door 7 - Courtyard south	1	EA	5	0-1 year	Worn frame.		
	Exterior Doors - Transom Lite	Door 7 - Courtyard south	1	EA	5	0-1 year	Worn.		
	Exterior Stairs - Concrete	Door 7 - Courtyard south	60	LF	6	10+ years	5		
	Exterior Stairs - Concrete	Door 7 - Courtyard south	7	LF	4	0-1 year	Broken and cracked.		
	Stair Handrail - Steel_Stair Handrail	Door 7 - Courtyard south	20	LF	5	2-5 years			
undatio	on								
	Foundation - Concrete	Entire Building	953	LF	7	10+ years			
	Superstructure - Concrete	Entire Building	106,900	SF	7	10+ years			
.htina									
hting	Exterior Lighting - Parapet or Roof Mounted	Entire Building	2	EA	6	2-5 years			
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	3	EA	5	0-1 year	Broken, missing bulb.		
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	2-5 years	, 3		
of Sys	tem.								
,	Access Ladder - Metal	Roof 1 - Main	5	EA	7	6-10 years			
	Coping - Metal	Roof 1 - Main	350	LF	6	6-10 years			
	Coping - Stone	Roof 1 - Main	190	LF	6	10+ years			
	Coping - Terra Cotta	Roof 1 - Main	550	LF	6	10+ years			
	Downspouts - Exterior Downspouts	Roof 1 - Main	450	LF	6	6-10 years			
	Parapet - Parapet < 16" Height	Roof 1 - Main	350	LF	7	10+ years			
	Parapet - Parapet > 30"	Roof 1 - Main	540	LF	7	10+ years			
	Roof - EPDM/ Synthetic Rubber	Roof 1 - Main	24,830	SF	6	10+ years			
	Roof - EPDM/ Synthetic Rubber	Roof 1 - Main	20	SF	4	0-1 year	Roof leak northwest		
	Roof Hatch - Metal	Roof 1 - Main	4	ĒΑ	7	6-10 years			
	Roof Structure - Concrete	Roof 1 - Main	24,850	SF	7	10+ years			
	Coping - Metal	Roof 2 - Lower West	167	LF	6	6-10 years			
	Downspouts - Exterior Downspouts	Roof 2 - Lower West	41	LF	6	6-10 years			
	Parapet - Parapet < 16" Height	Roof 2 - Lower West	167	LF	7	6-10 years			
	Roof - EPDM/ Synthetic Rubber	Roof 2 - Lower West	1,487	SF	6	6-10 years			
	Roof Structure - Concrete	Roof 2 - Lower West	1,487	SF	7	6-10 years			
	Coping - Terra Cotta	Roof 3 - Lower South & North	150	LF	6	10+ years			
	Downspouts - Interior Downspouts	Roof 3 - Lower South & North	65	LF	7	10+ years			
	Parapet - 16" - 30" Height	Roof 3 - Lower South & North	150	LF	7	10+ years			
	Roof - EPDM/ Synthetic Rubber	Roof 3 - Lower South & North	1,300	SF	6	10+ years			
	Roof Structure - Concrete	Roof 3 - Lower South & North	1,300	SF	7	10+ years			
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 4 - Lower West	55	LF	6	10+ years			
	Liner		30		Ū	, Jours			
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 4 - Lower West	20	LF	4	0-1 year	Major cracks in brick north side		
	Liner	. 100. 1 201101 17001	20		•	o i youi	sjor ordene in brien florin side		
	Coping - Terra Cotta	Roof 4 - Lower West	188	LF	6	10+ years			
	Downspouts - Interior Downspouts	Roof 4 - Lower West	120	LF	7	10+ years			



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	Roof 4 - Lower West	188	LF	7	10+ years	
	Roof - EPDM/ Synthetic Rubber	Roof 4 - Lower West	2,985	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 4 - Lower West	2,985	SF	7	10+ years	
	Coping - Terra Cotta	Roof 5 - Lower North	43	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 5 - Lower North	20	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 5 - Lower North	43	LF	6	10+ years	
	Roof - EPDM/ Synthetic Rubber	Roof 5 - Lower North	300	SF	6	10+ years	
	Roof Structure - Concrete	Roof 5 - Lower North	300	SF	7	10+ years	
Walls							
	Cheek-Wall - Concrete	Entire Building	40	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	35,900	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	20	SF	4	0-1 year	Large cracks on northeast corner
	Exterior Walls - Terra Cotta	Entire Building	5,890	SF	6	10+ years	3
	Exterior Walls - Terra Cotta	Entire Building	300	SF	5	10+ years	
Vindow	S						
	Guard - Guards perforated	Entire Building	3,190	SF	7	6-10 years	
	Lintels - Steel	Entire Building	219	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	900	LF	6	10+ years	
	Windows - Casement Steel	Entire Building	840	SF	5	0-1 year	Windows leak
	Windows - Decorative	Entire Building	45	SF	4	0-1 year	Windows leak
	Windows - Sash Aluminum Double-pane	Entire Building	9,970	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
-	UPS - Less than 30 KW	2nd Floor	1	EA	6	6-10 years	MDF room.
	Automatic Transfer Switch	ATS Room inside Boiler Room	2	EA	6	10+ years	
	Security System - CCTV	Entire Building	106,900	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	106,900	SF	6	10+ years	
	Exit Signs - Auditoium	Entire Building	13	EA	6	10+ years	
	Exit Signs - Corridors and Stairs	Entire Building	23	EA	6	10+ years	Many are LEDs
	Exit Signs - Gym	Entire Building	4	EA	6	10+ years	•
	Exit Signs - Gym	Entire Building	4	EA	6	10+ years	
	Emergency A/C Power - Auditoium and	Entire Building	6,580	SF	6	10+ years	
	Aisle Lighting						
	Emergency A/C Power - Corridors and	Entire Building	11,380	SF	6	10+ years	
	Stairs						
	Emergency A/C Power - Gym	Entire Building	6,240	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	2,880	SF	6	10+ years	
	Emergency Generator- Outdoor- Diesel - 60	Site West	1	EA	4	0-1 year	Serves main and additions. Per the



Catego	ry : Electrical		В	uilding	: Main		
0	Name Toma		0	HOM	Danila	Recommend	0
Group	- 100 KW	Location	Quantity	UOM	Rank	Replacement	Comments building engineer the generator is currently not working.
Main Sei	vice						
	Main Electrical Service - Greater than 3000 A 120/208/3PH	Boiler Room	1	EA	6	10+ years	Also serves additions
	Independent Electrical Service for emergency power	Boiler Room	1	EA	6	10+ years	
	PA System	Entire Building	106,900	SF	5	6-10 years	Also serve additions. Speakers are deteriorating
Power D	stribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	5	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	8	EΑ	6	10+ years	
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	•	
			1			10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EΑ	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	2-5 years	Corroded
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	3	0-1 year	live, exposed bus bar
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
		Logotion				Recommend	Comments
Group Fire Alar	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	Also serves additions
	Fire Alarm Strobe Lights	Entire Building	106,900	SF	6	10+ years	7 1130 3CT VC3 addition3
	Fire Alarm_System	Entire Building	106,900	SF	6	-	
	File Alaim_System	Entire Building	100,900	SI	O	10+ years	
Catego	ry : Mechanical		В	uilding	: Main	D	
Group Air Cond	Item - Type itionina	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Condensing Unit- Ground Mounted - Less than 5 tons	Central Courtyard	1	EA	7	10+ years	Mitsubishi mini split, 3 ton, 2017 installation



Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Hand	ling Systems						
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm	Gym Mechanical Room	1	EA	6	6-10 years	Serves the gym. Ductwork corroding and paint peeling.
	Air Intake	Gym Mechanical Room	1	EA	6	10+ years	
	Auxiliaries - 4000 - 8000 cfm	Gym Mechanical Room	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Gym Mechanical Room	25	LF	6	10+ years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	10+ years	Serves auditorium and locker room
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	10+ years	
	Zone Dampers	Mechanical Room	5	EA	5	6-10 years	Manually controlled, difficult to move, corroded
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years	Serves south classrooms and offices
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	6	10+ years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	5	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	10+ years	
	Zone Dampers	Mechanical Room	21	EA	6	10+ years	Frequent manual adjustments needed
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	5	10+ years	Serves north classrooms and offices
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	6	10+ years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	6	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	10+ years	
	Zone Dampers	Mechanical Room	23	EA	6	10+ years	Some manual adjustments required
Boiler Sy	rstems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	1	EA	6	10+ years	
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - Greater than 300 HP	Boiler Room	1	EA	5	2-5 years	Frequent maintenance required
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	3	EA	6	10+ years	2 for boilers and other for hot water



Catego	ry : Mechanical		В	uilding	: Main		. 5
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
					_		heaters
	Condensate Pump	Boiler Room	1	EΑ	6	10+ years	4 average total 0 at 0 UD 0 at 4 5 UD
	Feed Water Pumps and Tank Non Condensing- Fire Tube- Scotch Marine-	Boiler Room Boiler Room	1	EA EA	6 6	10+ years 10+ years	4 pumps total, 2 at 2 HP, 2 at 1.5 HP Serves main building and heat
	Steam- Low Pressure Boiler - 151 - 200 HP	boller Room	ı	EA	0	10+ years	exchanger for Addition 1. Back-up boiler for summer use.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - Greater than 300 HP	Boiler Room	1	EA	6	10+ years	Serves main building and heat exchanger for Addition 1.
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	6	10+ years	
	Steam Traps	Boiler Room	56	EA	5	6-10 years	Frequent maintenance is required
	Vacuum Pump	Boiler Room	1	EA	5	6-10 years	Frequent repairs are required
_Heat Ex	changers						
	Heat Exchanger - Steam to Hot Water Shell Type	Boiler Room	1	EA	6	10+ years	Serves addition 1.
_Heating	Devices						
	Radiators - Steam	Entire Building	14	EA	5	6-10 years	Radiators need painting, no temperature control
	Wall Heater - Electric	Entire Building	6	EA	6	10+ years	Mostly in restrooms
	Wall Heater - Electric	Entire Building	1	EA	4	0-1 year	Cover needs to be installed
_Mechani	cal Plumbing						
	Hydronic Supply and Return - Copper	Basement	150	LF	6	10+ years	Also serves addition, from heat exchanger
	Hot Water Pump - Less than 10	Boiler Room	4	EA	5	6-10 years	Near heat exchanger, serve Addition 1.
_Tempera	ature Control						
·	Electric Thermostat	Entire Building	1	EA	6	10+ years	In MDF room serves ductless split system.
	Pneumatic System	Entire Building	106,900	SF	4	2-5 years	More than 30 years old, Replace with DDC
	Thermostats - Pneumatic	Entire Building	46	EA	6	6-10 years	Calibration needed
	Thermostats - Pneumatic	Entire Building	4	EA	4	1-2 years	Damaged, missing covers
_Ventilation							
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Gym mechanical room.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	4	EA	4	0-1 year	Corroded
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	4	0-1 year	Corroded



NY N	Schools					6	200 S Hamlin AVENUE, Chicago, IL 60629
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	CFM		_		_		
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	5	EA	5	10+ years	Frequent maintenance required
	CFM						
0-1	ma a Diamah in n		.	! - !	. 84-:		
Catego	ry : Plumbing			uilding	: wain	Decemmend	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	-	Location	Quantity	OCIVI	IVAIIN	Replacement	Comments
Hot Wate		Dellas Desas	4			0.40	
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	5	6-10 years	Cleaning of burners required. Serves
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	2	EA	4	2 E vooro	main and addition 1.
	Gas neater - 300001 - 600000 BTO/HK	Boller Room	2	EA	4	2-5 years	Significantly aged but working. Serves main and addition 1.
	Hot Water Storage Tank_Gas - 201 - 500	Boiler Room	1	EA	6	10+ years	Serves main and addition 1.
	Gallons	Bolici Room		L/\	O	TOT years	
_Piping							
1 0	Domestic Piping-Cold Water Horizontal	Entire Building	106,900	SF	6	10+ years	Older building has a few pipe clamps
	Lines	G	•			·	
	Domestic Piping-Cold Water Risers	Entire Building	106,900	SF	6	10+ years	
	Domestic Piping-Cold Water from Risers to	Entire Building	106,900	SF	6	10+ years	
	Fixtures						
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	106,900	SF	6	10+ years	
	Domestic Piping-Hot Water Return Lines	Entire Building	106,900	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	106,900	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	106,900	SF	6	10+ years	
	Fixtures	Fatina Duildian	400,000	C.E.	•	40	
	Sanitary Piping	Entire Building	106,900	SF	6	10+ years	
	Storm Piping	Entire Building	106,900	SF	6	10+ years	
	Vent Piping	Entire Building	106,900	SF	6	10+ years	
Pumps							
adımba	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	6	10+ years	Serves main and additions.
	Pumps - Sump-Duplex	Mechanical Room	1	EA	6	10+ years	Cleaning of pit needed
	po Gamp Bapton			_, .	J	.o. youro	c.csmg or premoded
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	AC Unit	100 Discipline Office	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	100 Discipline Office	770	SF	6	10+ years	
	Doors - Transom Window	100 Discipline Office	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	100 Discipline Office	2	EA	6	10+ years	
	Floor - Carpet	100 Discipline Office	700	SF	6	6-10 years	







Building: Main Category: Room Recommend Location Group Item - Type Quantity **UOM** Rank Replacement Comments Floor - Tile 100 Discipline Office 70 SF 10+ vears 6 100 Discipline Office EΑ 6 6-10 years Lighting - Pendent/Surface 12 Walls - Plaster/Drywall 100 Discipline Office 1.420 SF 6 10+ years 101 Counseling Office EΑ 7 AC Unit 6-10 years SF Ceiling - Plaster/Drywall 101 Counseling Office 740 6 10+ years SF Doors - Transom Window 101 Counseling Office 8 6 10+ years Doors - Wood Doors inclu hw 101 Counseling Office 2 EΑ 6 10+ years SF Floor - Carpet 101 Counseling Office 740 6 6-10 years Lighting - Pendent/Surface 101 Counseling Office 12 EΑ 6 6-10 years Power Distribution 101 Counseling Office 20 EΑ 6 6-10 years Walls - Metal Panel 101 Counseling Office 300 SF 6 10+ vears Walls - Plaster/Drywall 101 Counseling Office 1,130 SF 6 10+ years Ceiling - Plaster/Drywall 102 Assistant Principal Office 220 SF 6 10+ years SF 6 Doors - Side-lite 102 Assistant Principal Office 48 10+ years Doors - Transom Window 102 Assistant Principal Office 8 SF 6 10+ years Doors - Wood Doors inclu hw 2 EΑ 6 102 Assistant Principal Office 10+ years SF 7 Floor - Wood 102 Assistant Principal Office 220 6-10 years Lighting - Pendent/Surface 102 Assistant Principal Office 2 EΑ 6 6-10 years 6 Power Distribution 102 Assistant Principal Office EΑ 6 6-10 years Walls - Plaster/Drywall 102 Assistant Principal Office 600 SF 6 10+ years Work SInk 102 Assistant Principal Office 1 EΑ 7 6-10 years 2 7 AC Unit 102 Waiting Area EΑ 6-10 years SF Ceiling - Plaster/Drywall 102 Waiting Area 165 6 10+ years Doors - Transom Window SF 102 Waiting Area 8 6 10+ years Doors - Wood Doors inclu hw EΑ 6 102 Waiting Area 1 10+ years Floor - Carpet 102 Waiting Area 165 SF 6 6-10 years Minor staining. Lighting - Pendent/Surface 102 Waiting Area 2 EΑ 6 6-10 years Power Distribution 102 Waiting Area 4 EΑ 6 6-10 years SF 7 Storage/ Closet 102 Waiting Area 80 10+ years Walls - Plaster/Drywall 102 Waiting Area 655 SF 6 10+ years AC Unit 102B Copy Room EΑ 5 2-5 years 1 Ceiling - Plaster/Drywall 102B Copy Room 185 SF 6 10+ years Doors - Transom Window 102B Copy Room SF 10+ years 8 6 Doors - Wood Doors inclu hw 102B Copy Room 1 EΑ 6 10+ years 102B Copy Room SF Floor - Carpet 185 6 6-10 years Lighting - Pendent/Surface 102B Copy Room EΑ 6 2 6-10 years Power Distribution 102B Copy Room 10 EΑ 6 6-10 years Walls - Plaster/Drywall 102B Copy Room SF 600 6 10+ years SF Ceiling - Plaster/Drywall 3rd Floor Gym Office 130 7 10+ years 3rd Floor Gvm Office SF Doors - Side-lite 24 7 10+ years Doors - Wood Doors inclu hw 3rd Floor Gym Office 1 EΑ 7 10+ years 3rd Floor Gvm Office 130 SF Floor - Tile 6 10+ years Lighting - Pendent/Surface 3rd Floor Gym Office 2 EΑ 7 10+ years 7 Power Distribution 3rd Floor Gym Office 6 EΑ 10+ years



Catego	Category : Room		В	Building : Main			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	3rd Floor Gym Office	420	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor Office Across from	84	SF	7	10+ years	
		Classroom 303 Psychologist					
	Ceiling - Plaster/Drywall	3rd Floor Office Across from	10	SF	5	0-1 year	Minor water damage observed.
		Classroom 303 Psychologist			_		
	Doors - Transom Window	3rd Floor Office Across from	6	SF	7	10+ years	
	D W 1D : 1.1	Classroom 303 Psychologist	4	_^	-	40	
	Doors - Wood Doors inclu hw	3rd Floor Office Across from	1	EA	7	10+ years	
	Florin Comments	Classroom 303 Psychologist	0.4	0.	7	40	
	Floor - Concrete	3rd Floor Office Across from	94	SF	7	10+ years	
	Lighting Dandont/Curfoss	Classroom 303 Psychologist	2	ГΛ	7	10	
	Lighting - Pendent/Surface	3rd Floor Office Across from Classroom 303 Psychologist	2	EA	7	10+ years	
	Power Distribution	3rd Floor Office Across from	2	EA	7	10+ years	
	Power Distribution	Classroom 303 Psychologist	۷	EA	,	10+ years	
	Walls - Plaster/Drywall	3rd Floor Office Across from	578	SF	7	10+ years	
	Walls - I laster/Drywall	Classroom 303 Psychologist	370	Oi	,	10+ years	
	Walls - Plaster/Drywall	3rd Floor Office Across from	20	SF	5	0-1 year	Minor water damage observed.
	walls Tlaster/Drywall	Classroom 303 Psychologist	20	O.	0	o i yeai	willor water damage observed.
	Ceiling - Exposed	Basement Engineer's Office	249	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement Engineer's Office	1	EΑ	6	10+ years	
	Floor - Tile	Basement Engineer's Office	249	SF	6	2-5 years	Floors dirty.
	Lighting - Pendent/Surface	Basement Engineer's Office	2	ĒΑ	6	6-10 years	
	Power Distribution	Basement Engineer's Office	6	EA	6	6-10 years	
	Walls - Concrete Block	Basement Engineer's Office	570	SF	6	10+ years	
	Ceiling - Plaster/Drywall	JROTC office in 1st fl gym	120	SF	6	10+ years	
	Doors - Wood Doors inclu hw	JROTC office in 1st fl gym	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	JROTC office in 1st fl gym	120	SF	6	10+ years	
	Lighting - Pendent/Surface	JROTC office in 1st fl gym	2	EA	6	6-10 years	
	Power Distribution	JROTC office in 1st fl gym	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	JROTC office in 1st fl gym	50	SF	6	10+ years	
	Walls - Structural Glazed Tile	JROTC office in 1st fl gym	331	SF	6	10+ years	
	AC Unit	Library Conference Room	1	EA	7	6-10 years	
	Ceiling - Lay-in	Library Conference Room	374	SF	6	10+ years	
	Doors - Side-lite	Library Conference Room	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Library Conference Room	1	EA	6	10+ years	
	Floor - Carpet	Library Conference Room	374	SF	5	2-5 years	
	Lighting - Pendent/Surface	Library Conference Room	4	EΑ	7	6-10 years	
	Power Distribution	Library Conference Room	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Library Conference Room	820	SF	6	10+ years	
	Ceiling - Lay-in	Library Office	220	SF	7	10+ years	
	Doors - Side-lite	Library Office	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Library Office	1	EA	7	10+ years	
	Floor - Carpet	Library Office	220	SF	7	6-10 years	





Catego	ry : Room		В	uilding	: Main		5200 S Hallilli AVENUE, Chicago, ic 60629
J				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Library Office	2	EA	7	10+ years	
	Power Distribution	Library Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Library Office	470	SF	7	10+ years	
	AC Unit	Main Office	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	710	SF	6	10+ years	
	Doors - Transom Window	Main Office	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	10+ years	
	Floor - Wood	Main Office	710	SF	7	10+ years	
	Lighting - Pendent/Surface	Main Office	14	EA	6	6-10 years	
	Power Distribution	Main Office	10	EΑ	6	6-10 years	
	Storage/ Closet	Main Office	140	SF	5	10+ years	
	Walls - Plaster/Drywall	Main Office	1,420	SF	6	10+ years	
	AC Unit	Main Office - Conference Room	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office - Conference Room	156	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office - Conference Room	1	EA	6	10+ years	
	Floor - Wood	Main Office - Conference Room	156	SF	7	10+ years	
	Lighting - Pendent/Surface	Main Office - Conference Room	4	EA	6	6-10 years	
	Power Distribution	Main Office - Conference Room	6	EA	6	6-10 years	
	Walls - Plaster/Drywall	Main Office - Conference Room	500	SF	6	10+ years	
	AC Unit	Principal's Office	1	ĒΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	Principal's Office	275	SF	5	10+ years	Paint chipping and peeling.
	Doors - Transom Window	Principal's Office	8	SF	6	10+ years	11 3 1 3
	Doors - Wood Doors inclu hw	Principal's Office	2	EA	6	10+ years	
	Floor - Wood	Principal's Office	275	SF	7	10+ years	
	Lighting - Pendent/Surface	Principal's Office	6	EΑ	6	6-10 years	
	Power Distribution	Principal's Office	16	EA	6	6-10 years	
	Walls - Plaster/Drywall	Principal's Office	870	SF	6	10+ years	
Auditoriu	ım & Theater						
	Balcony Seating	1st Floor	144	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	6,580	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	10	EΑ	6	10+ years	
	Floor - Tile	1st Floor	5,225	SF	6	10+ years	
	Floor - Wood	1st Floor	1,355	SF	6	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor	5	EA	6	6-10 years	
	Main Floor Seating	1st Floor	512	EΑ	7	10+ years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage Curtain	1st Floor	8	EΑ	7	6-10 years	
	Stage Lighting System	1st Floor	1	EΑ	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	8	LF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	7,210	SF	6	10+ years	
Gvmnas	ia						
_ суппаз	Bleacher Seating	1st Floor	68	EA	6	6-10 years	
	Dieacher Seathig	13(1100)	00	LA	U	0-10 years	





Catego	ry : Room		В	uilding	: Main		200 6 Hamili Avenoe, Gilleage, ile 00023
, i						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	2,880	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	6	EA	6	10+ years	
	Floor - Wood	1st Floor	2,880	SF	4	0-1 year	Floor scraped and has damage throughout.
	Lighting - Metal Halide/Sodium Vapor	1st Floor	8	EA	6	6-10 years	3
	Storage/ Closet	1st Floor	240	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	4,144	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,421	SF	6	10+ years	
	Bleacher Seating	3rd Floor	272	EA	7	10+ years	
	Ceiling - Exposed	3rd Floor	6,240	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	6	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	6,240	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	36	ĒΑ	7	10+ years	
	Scoreboards	3rd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	3,955	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	2,030	SF	7	10+ years	
			_,			, , , , , , , , , , , , , , , , , , , ,	
Library	AC Unit	1st Floor	3	EA	7	6-10 years	
	Casework	1st Floor	140	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,905	SF	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Carpet	1st Floor	1,905	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	36	EA	7	10+ years	
	Storage/ Closet	1st Floor	180	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,550	SF	7	10+ years	
	•	1001	1,000	Ö.	,	101 youro	
Locker/S	hower Room	3rd Floor Boys Gym locker	1,660	SF	7	10+ years	
	Accessories Benches, ped mounted	3rd Floor Boys Gym locker	1,000	LF	7 7	•	
	Ceiling - Plaster/Drywall	3rd Floor Boys Gym locker	1,660	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Boys Gym locker		EA	7	10+ years 10+ years	
		3rd Floor Boys Gym locker	2 1,660	SF		•	
	Floor - Tile Ceramic/ Porcelain Floor Drain	3rd Floor Boys Gym locker		Sr EA	7 7	10+ years	
			5 1	EA	7	10+ years	
	Lavatory Lighting - Lay-in	3rd Floor Boys Gym locker 3rd Floor Boys Gym locker	4	EA EA	7 7	10+ years	
		3rd Floor Boys Gym locker		EA	7	10+ years	
	Lighting - Pendent/Surface Partitions	3rd Floor Boys Gym locker 3rd Floor Boys Gym locker	29 1	EA EA	7 7	10+ years	
	Showers	3rd Floor Boys Gym locker 3rd Floor Boys Gym locker	12	EA EA	7 7	10+ years	
		3rd Floor Boys Gym locker 3rd Floor Boys Gym locker		SF	7	10+ years	
	Storage/ Closet		150			10+ years	
	Student Lockers - One Tier	3rd Floor Boys Gym locker	100	EΑ	7 7	10+ years	
	Student Lockers - Two Tier Walls - Structural Glazed Tile	3rd Floor Boys Gym locker 3rd Floor Boys Gym locker	415 3,150	EA SF	7 7	10+ years 10+ years	
	vvaus - Suuciniai Cila/EO TIIE	alu Figor Doys GVIII locker	3 130	OΓ	,	iut veais	




Category : Room		В	uilding	: Main		<u> </u>		
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Water Closet	3rd Floor Boys Gym locker	1	EA	7	10+ years		
Lunch &	Multipurpose Room							
Lancina	AC Unit	121A Teacher Cafeteria	2	EA	7	6-10 years		
	Ceiling - Lay-in	121A Teacher Cafeteria	850	SF	6	10+ years		
	Doors - Transom Window	121A Teacher Cafeteria	16	SF	6	10+ years		
	Doors - Wood Doors inclu hw	121A Teacher Cafeteria	4	EA	6	•		
	Floor - Tile			SF		10+ years		
		121A Teacher Cafeteria	848		6	10+ years	One also diffe	
	Floor - Tile	121A Teacher Cafeteria	2	SF	4	0-1 year	Cracked tile.	
	Lighting - Lay-in	121A Teacher Cafeteria	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	121A Teacher Cafeteria	12	EA	6	6-10 years		
	Walls - Plaster/Drywall	121A Teacher Cafeteria	1,510	SF	6	10+ years		
MDF_ID	F							
_	Doors - Transom Window	2nd Floor	6	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years		
	Finishes	2nd Floor	233	SF	7	6-10 years	Paint scuffed up.	
	Other Cooling Unit	2nd Floor	1	EΑ	7	10+ years	Ductless split system. 2017	
	Other Gooming Critic	2114 1 1001	·	L/\	•	101 youro	installation.	
	WO : D							
iviecnani	cal/ Service Rooms	4 4 🖂	400	05		40	NI d	
	Janitor's Closet	1st Floor	100	SF	5	10+ years	North	
	Janitor's Closet	1st Floor	100	SF	5	10+ years	South	
	Storage Room	1st Floor	62	SF	5	10+ years	PE Storage 119E	
	Storage Room	1st Floor	693	SF	5	10+ years	Upper portion of boiler room	
	Storage Room	1st Floor	180	SF	5	10+ years	Library Storage Room	
	Storage Room	1st Floor	100	SF	5	10+ years	102 Storage Room	
	Storage Room	1st Floor	312	SF	5	10+ years	PE Storage 119G	
	Vaults	1st Floor	157	SF	5	10+ years	103A	
	Janitor's Closet	2nd Floor	30	SF	5	2-5 years	Paint chipping, peeling, cracking throughout.	
	Janitor's Closet	2nd Floor	30	SF	5	10+ years	anoughout	
	Storage Room	2nd Floor	107	SF	5	10+ years		
	Storage Room	2nd Floor	107	SF	5	10+ years		
	Storage Room	2nd Floor	251	SF	5	10+ years		
	Janitor's Closet	3rd Floor	33	SF	5	10+ years	North	
	Janitor's Closet Janitor's Closet	3rd Floor	43	SF SF	5 5	10+ years 10+ years	South	
	Mechanical/ Service Rooms	3rd Floor	45	SF	5 5	-	Electrical Room 307D	
				SF SF		10+ years		
	Mechanical/ Service Rooms	3rd Floor	602		5	10+ years	Gym Mechanical Room	
	Storage Room	3rd Floor	16	SF	7	10+ years	New storage room outside of 305	
	Storage Room	3rd Floor	16	SF	7	10+ years	New storage room outside of 302	
	Storage Room	3rd Floor	26	SF	5	10+ years	300B	
	Storage Room	3rd Floor	168	SF	5	10+ years	Gym 306C	





Catego	Category : Room			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage Room	3rd Floor	33	SF	5	10+ years	307C
	Storage Room	3rd Floor	308	SF	5	10+ years	Gym 306F
	Storage Room	3rd Floor	550	SF	5	10+ years	Gym 306D
	Storage Room	3rd Floor	44	SF	5	10+ years	305C
	Air Intake Plenums	Basement	960	SF	5	10+ years	
	Air Tunnel	Basement	3,000	SF	5	10+ years	
	Auditorium Plenums	Basement	6,300	SF	5	10+ years	
	Boiler Room	Basement	3,800	SF	5	10+ years	
	Crawl Space - Unfinished	Basement	12,460	SF	5	10+ years	
	Storage Room	Basement	379	SF	5	10+ years	
	•					j	
Prep Ro		2074			7	40	
	Casework	307A	60	LF	7	10+ years	
	Ceiling - Plaster/Drywall	307A	245	SF	7	10+ years	
	Doors - Wood Doors inclu hw	307A	1	EA	7	10+ years	
	Floor - Tile	307A	245	SF	7	10+ years	
	Lighting - Pendent/Surface	307A	4	EA	7	10+ years	
	Walls - Plaster/Drywall	307A	816	SF	7	10+ years	
	Work Sink	307A	1	EA	7	10+ years	
Restroor	n						
Kestrool	Accessories	1st FL Men's Staff Restroom Near	50	SF	7	10+ years	
	Ceiling - Lay-in	Library 1st FL Men's Staff Restroom Near	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Library 1st FL Men's Staff Restroom Near	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Library 1st FL Men's Staff Restroom Near	50	SF	6	10+ years	
	Lavatory	Library 1st FL Men's Staff Restroom Near	1	EA	6	6-10 years	
	Lighting - Wall Mounted	Library 1st FL Men's Staff Restroom Near	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Library 1st FL Men's Staff Restroom Near Library	212	SF	6	10+ years	
	Water Closet	1st FL Men's Staff Restroom Near Library	1	EA	6	6-10 years	
	Accessories	1st FL Women's Staff	50	SF	7	10+ years	
	Ceiling - Lay-in	1st FL Women's Staff	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FL Women's Staff	1	ĒΑ	6	10+ years	
	Floor - Tile/Sheet	1st FL Women's Staff	50	SF	7	10+ years	
	Lavatory	1st FL Women's Staff	1	EA	6	6-10 years	
	Lighting - Wall Mounted	1st FL Women's Staff	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st FL Women's Staff	212	SF	6	10+ years	
	Trails I lactor Dry Wall	Total E Womon's Otali	212	51	O	ioi youis	







Category: Room **Building: Main** Recommend Location Group Item - Type Quantity UOM Rank Replacement **Comments** Water Closet 1st FL Women's Staff EΑ 6-10 years 6 250 SF 7 6-10 years Accessories 1st Floor Boy's Restroom Ceiling - Plaster/Drywall 1st Floor Boy's Restroom 250 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor Boy's Restroom 2 EΑ 6 10+ years SF Floor - Tile Ceramic/ Porcelain 1st Floor Boy's Restroom 250 6 10+ years Floor Drain EΑ 7 1st Floor Boy's Restroom 10+ years 1 Hand Dryer 1st Floor Boy's Restroom 2 EΑ 7 6-10 years Lavatory 1st Floor Boy's Restroom 2 EΑ 6 6-10 years Lighting - Pendent/Surface 1st Floor Boy's Restroom 4 EΑ 6 6-10 years 2 **Partitions** 1st Floor Boy's Restroom FΑ 7 10+ years Urinals 1st Floor Boy's Restroom 6 EΑ 6 6-10 years Walls - Structural Glazed Tile 1st Floor Boy's Restroom 800 SF 6 10+ years Water Closet 1st Floor Boy's Restroom 2 EΑ 6 6-10 years SF 5 Accessories 1st Floor Girl's Restroom 250 2-5 years Ceiling - Plaster/Drywall SF 6 1st Floor Girl's Restroom 250 10+ years Doors - Wood Doors inclu hw FΑ 6 1st Floor Girl's Restroom 2 10+ years 1st Floor Girl's Restroom SF Floor - Tile Ceramic/ Porcelain 250 6 6-10 years Floor Drain 1st Floor Girl's Restroom 1 EΑ 7 6-10 years 2 1st Floor Girl's Restroom EΑ 6 6-10 years Lavatory Lighting - Pendent/Surface 1st Floor Girl's Restroom 4 EΑ 6 6-10 years **Partitions** 1st Floor Girl's Restroom 8 EΑ 7 6-10 years SF Walls - Structural Glazed Tile 1st Floor Girl's Restroom 800 6 10+ years EΑ 6 Water Closet 1st Floor Girl's Restroom 8 6-10 years Accessories SF 2nd Floor across from 202 Girls 258 7 6-10 years Storage Ceiling - Plaster/Drywall 2nd Floor across from 202 Girls 258 SF 5 10+ years Storage Doors - Wood Doors inclu hw 2nd Floor across from 202 Girls 2 EΑ 6 10+ years Storage Floor - Tile Ceramic/ Porcelain 2nd Floor across from 202 Girls 258 SF 5 10+ years Storage 2nd Floor across from 202 Girls Floor Drain EΑ 7 1 10+ vears Storage Lighting - Pendent/Surface 2nd Floor across from 202 Girls FΑ 6 6-10 years Storage 2nd Floor across from 202 Girls **Partitions** 7 EΑ 5 6-10 years Storage Walls - Structural Glazed Tile 2nd Floor across from 202 Girls 837 SF 5 10+ years Storage SF Accessories 3rd FL Gvm Office Restroom 30 7 10+ vears SF Ceiling - Plaster/Drywall 3rd FL Gym Office Restroom 30 7 10+ years Doors - Wood Doors inclu hw 3rd FL Gvm Office Restroom FΑ 7 1 10+ years Floor - Tile 3rd FL Gym Office Restroom 30 SF 6 10+ years Lavatory 3rd FL Gym Office Restroom EΑ 7 10+ years





Catego	ry : Room		В	uilding			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd FL Gym Office Restroom	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd FL Gym Office Restroom	133	SF	7	10+ years	
	Water Closet	3rd FL Gym Office Restroom	1	EA	7	10+ years	
	Accessories	3rd Floor Boy's Restroom Across 310	258	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor Boy's Restroom Across 310	258	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Boy's Restroom Across 310	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Boy's Restroom Across 310	258	SF	6	10+ years	
	Floor Drain	3rd Floor Boy's Restroom Across 310	1	EA	7	10+ years	
	Lavatory	3rd Floor Boy's Restroom Across 310	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor Boy's Restroom Across 310	4	EA	6	6-10 years	
	Partitions	3rd Floor Boy's Restroom Across 310	2	EA	7	6-10 years	
	Urinals	3rd Floor Boy's Restroom Across 310	6	EA	6	6-10 years	
	Walls - Structural Glazed Tile	3rd Floor Boy's Restroom Across 310	837	SF	6	10+ years	
	Water Closet	3rd Floor Boy's Restroom Across 310	2	EA	6	6-10 years	
	Accessories	In Principal's Office	22	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Principal's Office	22	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Principal's Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Principal's Office	22	SF	6	10+ years	
	Lavatory	In Principal's Office	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	In Principal's Office	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	In Principal's Office	24	SF	6	10+ years	
	Water Closet	In Principal's Office	1	EA	6	6-10 years	
	Ceiling - Plaster/Drywall	In Programming Office	22	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Programming Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Programming Office	22	SF	6	10+ years	
	Lavatory	In Programming Office	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	In Programming Office	1	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	In Programming Office	190	SF	6	10+ years	
	Water Closet	In Programming Office	1	EA	6	6-10 years	
	Accessories	Music Storage 304A	320	SF	7	10+ years	Currently used as storage. Building engineer confirmed plumbing fixtures are still live.
	Ceiling - Plaster/Drywall	Music Storage 304A	320	SF	7	10+ years	





Catego	ategory : Room			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Transom Window	Music Storage 304A	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Music Storage 304A	2	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Music Storage 304A	320	SF	7	10+ years	
	Floor Drain	Music Storage 304A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Music Storage 304A	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	Music Storage 304A	771	SF	7	10+ years	
Catego	ry : Classroom		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Quantity	UOIVI	Naiik	Replacement	Comments
Classroc	om #108 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,085	SF	6	10+ years	
	Chalk Board	1st Floor	14	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Carpet	1st Floor	1,085	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	. 8	EA	6	6-10 years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,210	SF	6	10+ years	
Classroo	om #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	770	SF	6	10+ years	
	Chalk Board	1st Floor	14	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	·	SF	6	•	
			766 6	SF	4	10+ years	Tiles missing and shinned
	Floor - Tile	1st Floor				0-1 year	Tiles missing and chipped.
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,000	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	220	SF	4	0-1 year	Extensive damage around windows.
Classroo	om #110 (Special Education)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Casework	1st Floor	4	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	350	SF	6	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor	350	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	6	6-10 years	
	Lighting i chacht our lace	1301 1001	-	L/\	J	o io years	



Catego	Category : Classroom		В	uilding	: Main		
<u> </u>						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	180	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	550	SF	6	10+ years	Paint chipping and peeling.
	Walls - Plaster/Drywall	1st Floor	35	SF	4	0-1 year	Damage to walls.
_Classroo	om #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	6	10+ years	
	Chalk Board	2nd Floor	53	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	770	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,220	SF	6	10+ years	
_Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	770	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,220	SF	6	10+ years	
_Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	770	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,210	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	





Category : Classroom			В	uilding			
_						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	770	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,220	SF	6	10+ years	
lassroc	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	770	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,215	SF	6	•	Paint chipping and peeling
	Walls - Plastel/Drywall	2110 F1001	1,215	SF	O	6-10 years	throughout.
	Walls - Plaster/Drywall	2nd Floor	5	SF	4	0-1 year	Hole in wall near window.
lassroc	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	766	SF	6	-	
			4	SF	4	10+ years	Tile missing
	Floor - Tile	2nd Floor	=			0-1 year	Tile missing.
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	100	SF	4	0-1 year	Damage to wall near windows.
lassroc	m #206 (Regular Classroom)	0.15				0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	5	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Tile	2nd Floor	764	SF	6	10+ years	
	Floor - Tile	2nd Floor	6	SF	4	0-1 year	Tile missing.
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	6	6-10 years	ŭ
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,220	SF	6	10+ years	
laceroo	om #207 (Regular Classroom)						
Sidssive	AC Units	2nd Floor	1	ГΛ	7	6-10 years	
			•	EA LF		•	
	Casework	2nd Floor	9		6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	5	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	770	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,220	SF	6	10+ years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	770	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	10+ years	
	Floor - Tile	2nd Floor	770	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor 2nd Floor		LF			
	Walls Distor/Dravell		16		6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	850	SF	6	10+ years	
Classroo	om #209 (Special Education)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	268	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	12	SF	4	0-1 year	Tiles damaged and separating.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	-
	Floor - Tile	2nd Floor	287	SF	6	10+ years	
	Floor - Tile	2nd Floor	3	SF	4	0-1 year	Tile missing below window.
	Lighting - Pendent/Surface	2nd Floor	6	ĒΑ	6	6-10 years	Ŭ
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	565	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Damage to wall below window.
Classror	om #210 (Science Lab Level 1)						
<i>J</i> 18331UC	AC Units	2nd Floor	2	EA	7	6-10 years	
	AO Offica	2110 1 1001	2	LA	,	0-10 years	






Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	60	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	930	SF	4	0-1 year	Lay in tiles missing
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Eye Wash Station	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	930	SF	6	10+ years	
	Gas Line	2nd Floor	5	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	7	LF	6	6-10 years	
	Science Lab Fume Hood	2nd Floor	1	EA	3	1-2 years	Noisy, repair required. Labs to be remodeled
	Science Lab Shower	2nd Floor	1	EA	7	6-10 years	Tomodolod
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years	
	Work Sink	2nd Floor	11	EA	7	6-10 years	
		2110 1 1001		_, 、	•	o io youio	
lassroo	m #300 (Science)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	28	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	750	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	20	SF	4	0-1 year	Water damage observed.
	Chalk Board	3rd Floor	14	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	770	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	250	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	670	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
lassroo	om #302 (Science)						
	AC Units	3rd Floor	1	EA	7	10+ years	
	Casework	3rd Floor	120	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,085	SF	7	10+ years	
	Chalk Board	3rd Floor	14	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	2	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,085	SF	7	10+ years	
	Gas Line	3rd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	10+ years	
	Storage/ Closet	3rd Floor	97	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,210	SF	7	10+ years	
	Work Sink	3rd Floor	4	EA	7	10+ years	
lassroo	om #303 (Science)						





Catego	ry : Classroom		В	uilding	: Main		200 o Hamili Averoe, onicago, le 00025
J	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	28	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	770	SF	7	10+ years	Paint chipping and peeling throughout.
	Chalk Board	3rd Floor	14	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	770	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	970	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	250	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #305 (Science)						
	AC Units	3rd Floor	1	EA	7	10+ years	
	Casework	3rd Floor	120	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,085	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,085	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	10+ years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	97	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,210	SF	7	10+ years	
	Work Sink	3rd Floor	3	EA	7	10+ years	
_Classroo	om #307 (Science)						
	AC Units	3rd Floor	1	EA	7	10+ years	
	Casework	3rd Floor	120	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,085	SF	7	10+ years	
	Chalk Board	3rd Floor	7	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,085	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	22	EA	7	10+ years	
	Storage/ Closet	3rd Floor	97	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,210	SF	7	10+ years	
	Work Sink	3rd Floor	3	EA	7	10+ years	
Classroo	om #308 (Science)						
	Casework	3rd Floor	28	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	770	SF	7	10+ years	
	Chalk Board	3rd Floor	14	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	





Catego	ry : Classroom		В	uilding	: Main		200 S Hamlin AVENUE, Chicago, IL 60629
Culogo	.,		_	aag		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	3rd Floor	770	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,220	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #310 (Science Lab Level 1)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	120	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,085	SF	7	10+ years	
	Chalk Board	3rd Floor	14	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,085	SF	7	10+ years	
	Gas Line	3rd Floor	29	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	22	EΑ	7	10+ years	
	Science Lab Elements	3rd Floor	1,085	SF	7	10+ years	
	Science Lab Fume Hood	3rd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,210	SF	7	10+ years	
	Work Sink	3rd Floor	15	EA	7	10+ years	
Catego	ry : Interior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	3,216	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	4,720	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	60	SF	4	0-1 year	Water damage observed.
	Doors - Wood Doors include hw	1st Floor	4	EA	6	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	2	EA	5	6-10 years	
	Floor - Terrazzo	1st Floor	875	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	7,052	SF	5	6-10 years	
	Lighting - Pendent/Surface	1st Floor	87	EA	6	6-10 years	
	Stairs - Terrazzo	1st Floor	12	LF	6	10+ years	
	Student Lockers - One Tier	1st Floor	224	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	4,266	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,715	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	5,496	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,095	SF	6	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor	2	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	700	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,395	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	40	EA	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	158	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,900	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	2,668	SF	6	10+ years	







Catego	Category : Interior		В	uilding	: Main		200 S Hallilli AVENUE, Chicago, iL 60629
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd Floor	3,090	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	4	0-1 year	Water damage around roof hatch/ladder.
	Ceiling - Splined	3rd Floor	465	SF	6	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	2	EA	5	10+ years	
	Floor - Terrazzo	3rd Floor	500	SF	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	3,065	SF	5	10+ years	
	Lighting - Pendent/Surface	3rd Floor	40	EA	6	6-10 years	
	Student Lockers - One Tier	3rd Floor	158	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,850	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	50	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	3,948	SF	6	10+ years	
Safety							
-	Camera Viewing Station	1st Floor	4	EA	7	6-10 years	
	Metal Dedector	1st Floor	2	EA	7	6-10 years	
	Security Cameras	1st Floor	2	EA	7	6-10 years	
	Security Cameras	1st Floor	10	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	Exit stair from Gym North	307	SF	6	10+ years	
	Floor - Terrazzo	Exit stair from Gym North	252	SF	6	10+ years	
	Handrails	Exit stair from Gym North	117	LF	7	10+ years	
	Lighting - Pendent/Surface	Exit stair from Gym North	4	EA	7	6-10 years	
	Lighting - Wall Mounted	Exit stair from Gym North	1	EA	6	6-10 years	
	Stairs - Terrazzo	Exit stair from Gym North	50	LF	6	10+ years	
	Walls - Plaster/Drywall	Exit stair from Gym North	1,680	SF	6	10+ years	
	Walls - Structural Glazed Tile	Exit stair from Gym North	1,000	SF	6	10+ years	
	Walls - Structural Glazed Tile	Exit stair from Gym North	120	SF	5	10+ years	
	Ceiling - Plaster/Drywall	Exit stair from Gym South	307	SF	6	10+ years	
	Floor - Terrazzo	Exit stair from Gym South	252	SF	6	10+ years	
	Handrails	Exit stair from Gym South	117	LF	7	10+ years	
	Lighting - Pendent/Surface	Exit stair from Gym South	4	EA	7	6-10 years	
	Lighting - Wall Mounted	Exit stair from Gym South	1	EA	7	6-10 years	
	Stairs - Terrazzo	Exit stair from Gym South	502	LF	6	10+ years	
	Walls - Structural Glazed Tile	Exit stair from Gym South	1,120	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North East Stair	355	SF	6	10+ years	
	Floor - Terrazzo	North East Stair	255	SF	6	10+ years	
	Handrails - Plaster/Drywall	North East Stair	115	SF	6	10+ years	
	Lighting - Pendent/Surface	North East Stair	2	EA	7	6-10 years	
	Stairs - Terrazzo	North East Stair	58	LF	6	10+ years	
	Walls - Plaster/Drywall	North East Stair	1,130	SF	6	10+ years	
	Walls - Structural Glazed Tile	North East Stair	760	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North West Stair	355	SF	6	10+ years	
	John 19 1 143(GI/DI) Wall	HOILII WOOL OLUII	555	OI.	U	ioi yeais	



Catego	ry : Interior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	North West Stair	255	SF	6	10+ years	
	Handrails	North West Stair	115	LF	7	10+ years	
	Lighting - Pendent/Surface	North West Stair	2	EA	7	6-10 years	
	Stairs - Terrazzo	North West Stair	58	LF	6	10+ years	
	Walls - Plaster/Drywall	North West Stair	580	SF	6	10+ years	
	Walls - Structural Glazed Tile	North West Stair	870	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South East Stair	330	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South East Stair	25	SF	5	10+ years	
	Floor - Terrazzo	South East Stair	255	SF	6	10+ years	
	Handrails	South East Stair	115	LF	7	10+ years	
	Lighting - Pendent/Surface	South East Stair	2	EA	7	6-10 years	
	Stairs - Terrazzo	South East Stair	58	LF	6	10+ years	
	Walls - Plaster/Drywall	South East Stair	1,130	SF	6	10+ years	
	Walls - Structural Glazed Tile	South East Stair	760	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South West Stair	355	SF	6	10+ years	
	Floor - Terrazzo	South West Stair	255	SF	6	10+ years	
	Handrails	South West Stair	115	LF	7	10+ years	
	Lighting - Pendent/Surface	South West Stair	2	EA	6	6-10 years	
	Stairs - Terrazzo	South West Stair	58	LF	6	10+ years	
	Walls - Plaster/Drywall	South West Stair	580	SF	6	10+ years	
	Walls - Structural Glazed Tile	South West Stair	870	SF	6	10+ years	



Category : Exterior Suilding : Addition 1	
Exterior Doors - Exterior Steel Door Door 12 - South 3 EA 6 6-10 years Exterior Stairs - Concrete Door 12 - South 57 LF 6 6-10 years Stair Handrail - Steel_Stair Handrail Door 12 - South 6 LF 5 2-5 years Exterior Doors - Exterior Wood Door Door 3 - Northeast 3 EA 6 6-10 years Exterior Doors - Transom Lite Door 3 - Northeast 3 EA 6 6-10 years	
Exterior Doors - Exterior Steel Door Door 12 - South 3 EA 6 6-10 years Exterior Stairs - Concrete Door 12 - South 57 LF 6 6-10 years Stair Handrail - Steel_Stair Handrail Door 12 - South 6 LF 5 2-5 years Exterior Doors - Exterior Wood Door Door 3 - Northeast 3 EA 6 6-10 years Exterior Doors - Transom Lite Door 3 - Northeast 3 EA 6 6-10 years	
Exterior Stairs - Concrete Door 12 - South 57 LF 6 6-10 years Stair Handrail - Steel_Stair Handrail Door 12 - South 6 LF 5 2-5 years Exterior Doors - Exterior Wood Door Door 3 - Northeast 3 EA 6 6-10 years Exterior Doors - Transom Lite Door 3 - Northeast 3 EA 6 6-10 years	
Exterior Stairs - Concrete Door 12 - South 57 LF 6 6-10 years Stair Handrail - Steel_Stair Handrail Door 12 - South 6 LF 5 2-5 years Exterior Doors - Exterior Wood Door Door 3 - Northeast 3 EA 6 6-10 years Exterior Doors - Transom Lite Door 3 - Northeast 3 EA 6 6-10 years	
Stair Handrail - Steel_Stair Handrail Door 12 - South 6 LF 5 2-5 years Exterior Doors - Exterior Wood Door Door 3 - Northeast 3 EA 6 6-10 years Exterior Doors - Transom Lite Door 3 - Northeast 3 EA 6 6-10 years	
Exterior Doors - Exterior Wood Door Door 3 - Northeast 3 EA 6 6-10 years Exterior Doors - Transom Lite Door 3 - Northeast 3 EA 6 6-10 years	
Exterior Doors - Transom Lite Door 3 - Northeast 3 EA 6 6-10 years	
Stair Handrail - Steel_Stair Handrail Door 3 - Northeast 18 LF 6 6-10 years	
Exterior Doors - Exterior Wood Door Door 4 - Northwest 3 EA 6 6-10 years	
Exterior Stairs - Concrete Door 4 - Northwest 79 LF 6 6-10 years	
Stair Handrail - Steel_Stair Handrail Door 4 - Northwest 18 LF 5 1-2 years Rust at base.	
Exterior Doors - Exterior Wood Door Door 7.5 - Courtyard basement 1 EA 6 6-10 years	
Exterior Stairs - Concrete Door 7.5 - Courtyard basement 64 LF 6 6-10 years	
Stair Handrail - Steel_Stair Handrail Door 7.5 - Courtyard basement 20 LF 5 2-5 years	
_Foundation	
Foundation - Concrete Entire Building 744 LF 7 10+ years	
	ling entrance 12
Superstructure - Concrete Entire Building 73,900 SF 7 10+ years	g
the state of the s	
Lighting	
Exterior Lighting - Parapet or Roof Mounted Entire Building 13 EA 6 2-5 years	
Exterior Lighting - Wall Mounted Entire Building 8 EA 6 2-5 years	
Roof System Access Ladder - Metal Roof 1 - North 1 EA 7 10+ years	
Downspouts - Interior Downspouts Roof 1 - North 105 LF 7 6-10 years	
	accessible, conditions illar roofs of building.
Roof Hatch - Metal Roof 1 - North 1 EA 7 10+ years	
Roof Structure - Steel / Metal Deck/ Roof 1 - North 12,526 SF 7 10+ years	
Concrete Topping	
Access Ladder - Metal Roof 2 - South 1 EA 7 10+ years	
Coping - Metal Roof 2 - South 473 LF 6 6-10 years	
Downspouts - Interior Downspouts Roof 2 - South 70 LF 7 6-10 years	
Roof - EPDM/ Synthetic Rubber Roof 2 - South 10,692 SF 4 0-1 year Worn	
Roof Hatch - Metal Roof 2 - South 1 EA 7 10+ years	
Roof Structure - Steel / Metal Deck/ Roof 2 - South 10,692 SF 7 10+ years	
Concrete Topping	
Coping - Terra Cotta Roof 3 - Lower South 28 LF 6 6-10 years	
Downspouts - Interior Downspouts Roof 3 - Lower South 15 LF 6 2-5 years	



Catego	Category : Exterior			Building : Addition 1					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Parapet - 16" - 30" Height	Roof 3 - Lower South	28	LF	6	10+ years			
	Roof - EPDM/ Synthetic Rubber	Roof 3 - Lower South	1,632	SF	6	2-5 years	Temporary patch.		
	Roof Structure - Steel / Metal Deck/	Roof 3 - Lower South	90	SF	7	10+ years			
	Concrete Topping								
	Coping - Stone	Roof 4 - Lower South East	23	LF	6	10+ years			
	Coping - Terra Cotta	Roof 4 - Lower South East	150	LF	6	10+ years			
	Downspouts - Interior Downspouts	Roof 4 - Lower South East	54	LF	7	6-10 years			
	Parapet - 16" - 30" Height	Roof 4 - Lower South East	23	LF	6	6-10 years			
	Roof - Modified Bitumen	Roof 4 - Lower South East	2,127	SF	5	2-5 years			
	Roof Structure - Steel / Metal Deck/	Roof 4 - Lower South East	2,127	SF	7	10+ years			
	Concrete Topping								
	Coping - Metal	Roof 5 - Lower Northeast	15	LF	6	6-10 years			
	Downspouts - Exterior Downspouts	Roof 5 - Lower Northeast	30	LF	6	6-10 years			
	Roof - EPDM/ Synthetic Rubber	Roof 5 - Lower Northeast	200	SF	6	6-10 years			
	Roof Structure - Steel / Metal Deck/	Roof 5 - Lower Northeast	200	SF	7	10+ years			
	Concrete Topping					•			
	Coping - Stone	Roof 6 - Lower Roof East	46	LF	7	10+ years			
	Downspouts - Exterior Downspouts	Roof 6 - Lower Roof East	20	LF	6	6-10 years			
	Parapet - Parapet < 16" Height	Roof 6 - Lower Roof East	46	LF	7	10+ years			
	Roof - Modified Bitumen	Roof 6 - Lower Roof East	160	SF	5	2-5 years			
	Roof Structure - Steel / Metal Deck/	Roof 6 - Lower Roof East	160	SF	7	10+ years			
	Concrete Topping					·			
Walls									
	Canopy - Metal	Entire Building	380	SF	6	6-10 years			
	Canopy - Metal	Entire Building	76	SF	4	0-1 year	Rusted.		
	Cheek-Wall - Concrete	Entire Building	10	SF	6	10+ years			
	Exterior Walls - Brick	Entire Building	16,556	SF	6	10+ years			
	Exterior Walls - Brick	Entire Building	465	SF	4	0-1 year	Brick cracking at columns between		
							windows		
	Exterior Walls - Stone-Cut	Entire Building	639	SF	6	10+ years			
	Exterior Walls - Stucco	Entire Building	50	SF	4	0-1 year	Loose & damaged		
Windows									
	Guard - Guards perforated	Entire Building	1,560	SF	7	6-10 years			
	Lintels - Steel	Entire Building	1,593	LF	6	6-10 years			
	Windows - Sash Aluminum Double-pane	Entire Building	10,675	SF	6	6-10 years			
•			_						
Catego	ry : Electrical		В	uilding	: Additi	on 1 Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
•	ncy System		quantity	00	TUMIN	. topiasoniont			
merger	Security System - CCTV	Entire Building	72 000	SF	6	6 10 years			
	Security System - COTV	Entire Building	73,900	SF	6	6-10 years			



Catego	ry : Electrical		В	uilding	: Addition	on 1	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security System - Intrusion Detection	Entire Building	73,900	SF	6	10+ years	
	Exit Signs - Corridors and Stairs	Entire Building	19	EΑ	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	4	EA	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	12,291	SF	6	10+ years	
	Stairs	3	, -			,	
	Emergency A/C Power - Lunchrooms	Entire Building	5,128	SF	6	10+ years	
/lain Se	rvice						
	PA System	Entire Building	73,900	SF	5	6-10 years	Served from Main building
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	ΕA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EΑ	4	1-2 years	More than 40 years old, corroding
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	More than to years old, correcting
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	2-5 years	Janitor Closet.
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	•	Janitor Closet.
	amp	Entire Building	I	LA	O	10+ years	
Catego	ry : Fire Protection		В	uilding	: Additio	on 1	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alaı	m		•			•	
nc / la		Entire Building	73 900	SF	6	10+ vears	
no Alai	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	73,900 73,900	SF SF	6 6	10+ years 10+ years	
	Fire Alarm Strobe Lights		73,900	SF		10+ years	
	Fire Alarm Strobe Lights Fire Alarm_System		73,900	SF	6	10+ years	
Catego	Fire Alarm Strobe Lights Fire Alarm_System		73,900	SF	6	10+ years	Comments
Catego Group	Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical	Entire Building	73,900 B	SF uilding	6 : Additio	10+ years on 1 Recommend	Comments
Catego Group	Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical Item - Type	Entire Building	73,900 B	SF uilding	6 : Additio	10+ years on 1 Recommend	Comments Serves the FCU.
Catego Group Air Cond	Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical Item - Type ditioning Condensing Unit- Roof Mounted - Less	Entire Building Location	73,900 B Quantity	SF uilding UOM	6 : Addition	10+ years on 1 Recommend Replacement	
Catego Group Air Cond	Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical Item - Type ditioning Condensing Unit- Roof Mounted - Less than 5 tons	Entire Building Location	73,900 B Quantity	SF uilding UOM	6 : Addition	10+ years on 1 Recommend Replacement	



Catego	ry : Mechanical		В	uildina	: Additi		250 O Hamili Avenoe, Officago, ie 55025
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Indoor- Hot Water Coils - 4000-8000 cfm		•			•	ductwork is uninsulated.
	Air Intake	Crawl Space - North	1	EA	6	10+ years	
	Indoor Return Fans- Centrifugal Inline - Less	Crawl Space - North	1	EA	5	2-5 years	
	than 5000 CFM	·				•	
	Air Handling Unit-Package Single Zone-	Crawl Space - South	1	EA	5	2-5 years	Unit 2. Constant volume. Supply
	Indoor- Hot Water Coils - 8001-12000 cfm						ductwork is uninsulated.
	Air Intake	Crawl Space - South	1	EA	6	10+ years	
	Air Handling Unit-Package Single Zone-	Crawl Space - South	1	EA	5	2-5 years	Unit 3. Constant volume. Supply
	Indoor- Hot Water Coils - 4000-8000 cfm						ductwork is uninsulated.
	Air Intake	Crawl Space - South	1	EΑ	6	10+ years	
	Indoor Return Fans- Centrifugal Inline - Less	Crawl Space - South	1	EA	5	2-5 years	
	than 5000 CFM						
Heating	Devices						
	Fin Tube - Hot Water	Entire Building	300	LF	6	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	6	EA	6	10+ years	Need painting
		9	•		-	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	·····g
_Mechani	cal Plumbing						
	Hydronic Supply and Return - Copper	Entire Building	800	LF	6	10+ years	
_Tempera	ature Control						
·	Electric Thermostat	Entire Building	2	EA	6	10+ years	Serves the newer unit ventilators.
	Pneumatic System	Entire Building	73,900	SF	5	6-10 years	Many locations are manually
	•	Ğ	·			•	controlled
	Thermostats - Pneumatic	Entire Building	47	EA	5	6-10 years	Need calibration
_Unit Ven	tilation						
OTHE VEH	Unit Ventilators- Ceiling Mounted- Hot Water	2nd Floor	2	EA	5	2-5 years	
	Heating Coils Only	2110 1 1001	2	LA	3	2-5 years	
	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	2	EA	7	10+ years	
	Heating Coils Only	Entire Ballating	2	LA	,	10+ years	
	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	45	EA	4	2-5 years	Frequent maintenance is required
	Heating Coils Only	Entire Banaring	.0		•	2 0 ,00.0	rioquent maintenance le required
_Ventilatio	on.						
_venuali	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	5	EA	5	6-10 years	
	CFM	Entire building	5	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	5	6-10 years	
	CFM	Ŭ			-	,	
	Exhaust Fans- Roof Mounted - Greater than	Entire Building	4	EA	6	6-10 years	
	8000 CFM	Č				,	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	In kitchen, No fire supression system
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	ΕA	5	6-10 years	in servery
	3	Ŭ				,	•

Campus Name: Hubbard HS Page : 28 of 60 Assessment Date: 07/24/2019





Building: Addition 1 Category : Mechanical Recommend

Group Item - Type Location Quantity UOM Rank Replacement Comments

Category: Plumbing Building: Addition 1

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Piping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	73,900	SF	6	10+ years	
	Domestic Piping-Cold Water Risers	Entire Building	73,900	SF	6	10+ years	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	73,900	SF	6	10+ years	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	73,900	SF	6	10+ years	
	Domestic Piping-Hot Water Return Lines	Entire Building	73,900	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	73,900	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	73,900	SF	6	10+ years	
	Sanitary Piping	Entire Building	73,900	SF	6	10+ years	
	Storm Piping	Entire Building	73,900	SF	6	10+ years	
	Vent Piping	Entire Building	73,900	SF	6	10+ years	
Pumps							

Pumps - Sump-Duplex EΑ Basement 6 10+ years

Category: Room **Building: Addition 1**

outegory : Itooin			Building : Addition 1							
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments			
	rative Suites/Offices					processor proces				
	AC Unit	1st FL-Nurse office	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	1st FL-Nurse office	275	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st FL-Nurse office	2	EA	6	10+ years				
	Floor - Tile	1st FL-Nurse office	275	SF	6	6-10 years				
	Lighting - Pendent/Surface	1st FL-Nurse office	3	EA	6	6-10 years				
	Power Distribution	1st FL-Nurse office	10	EA	6	6-10 years				
	Walls - Concrete Block	1st FL-Nurse office	650	SF	6	10+ years				
	AC Unit	211A Social Work	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	211A Social Work	275	SF	6	10+ years				
	Doors - Wood Doors inclu hw	211A Social Work	1	EA	6	10+ years				
	Floor - Carpet	211A Social Work	275	SF	4	0-1 year	Carpet, stained, and dirty throughout			
	Lighting - Pendent/Surface	211A Social Work	3	EA	6	6-10 years				
	Power Distribution	211A Social Work	10	EA	6	6-10 years				
	Walls - Concrete Block	211A Social Work	650	SF	6	10+ years				
	AC Unit	219 Asst. Principals Office	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	219 Asst. Principals Office	275	SF	6	10+ years				
	Doors - Wood Doors inclu hw	219 Asst. Principals Office	1	EA	6	10+ years				



Catego	ry : Room		В	uilding	: Additi		200 3 Hamili Avende, Chicago, ie 00029
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Carpet	219 Asst. Principals Office	275	SF	6	6-10 years	
	Lighting - Pendent/Surface	219 Asst. Principals Office	3	EA	6	6-10 years	
	Power Distribution	219 Asst. Principals Office	10	EA	6	6-10 years	
	Walls - Concrete Block	219 Asst. Principals Office	650	SF	6	10+ years	
	AC Unit	222 - Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	222 - Office	252	SF	6	10+ years	
	Doors - Wood Doors inclu hw	222 - Office	1	EA	6	10+ years	
	Floor - Tile	222 - Office	252	SF	6	10+ years	
	Lighting - Pendent/Surface	222 - Office	3	EΑ	6	6-10 years	
	Power Distribution	222 - Office	6	EA	6	6-10 years	
	Walls - Concrete Block	222 - Office	597	SF	6	10+ years	
	AC Unit	2nd Floor Admin Office Across From 226	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Admin Office Across From 226	507	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Admin Office Across From 226	2	EA	6	10+ years	
	Floor - Carpet	2nd Floor Admin Office Across From 226	445	SF	4	1-2 years	Carpet is stained and worn.
	Floor - Tile	2nd Floor Admin Office Across From 226	62	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Admin Office Across From 226	2	EA	7	6-10 years	
	Power Distribution	2nd Floor Admin Office Across From 226	6	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor Admin Office Across From 226	963	SF	6	10+ years	
	AC Unit	327	1	EA	7	6-10 years	
	Ceiling - Lay-in	327	275	SF	6	10+ years	
	Doors - Transom Window	327	1	SF	6	10+ years	
	Floor - Tile	327	275	SF	6	6-10 years	
	Lighting - Lay-in	327	3	EA	6	6-10 years	
	Power Distribution	327	10	EA	6	10+ years	
	Walls - Concrete Block	327	650	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Kitchen Office	80	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Office	1	EΑ	6	10+ years	
	Floor - Tile Quarry	Kitchen Office	80	SF	6	10+ years	
	Lighting - Pendent/Surface	Kitchen Office	2	EA	6	6-10 years	
	Power Distribution	Kitchen Office	4	EA	6	6-10 years	
	Walls - Structural Glazed Tile	Kitchen Office	350	SF	6	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	960	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	



Catego	ry : Room		B	uilding	: Additi	on 1			
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile Quarry	1st Floor	930	SF	6	10+ years			
	Floor - Tile Quarry	1st Floor	30	SF	4	0-1 year	Tile missing.		
	Lighting - Pendent/Surface	1st Floor	19	EA	6	6-10 years			
	Storage/ Closet	1st Floor	120	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	1,880	SF	6	10+ years			
ocker/S	Shower Room								
	Accessories	Athletic Team Room B09	855	SF	7	6-10 years			
	Benches, ped mounted	Athletic Team Room B09	24	LF	7	10+ years			
	Ceiling - Plaster/Drywall	Athletic Team Room B09	855	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Athletic Team Room B09	3	EA	6	10+ years			
	Floor - Epoxy/ Painted	Athletic Team Room B09	595	SF	4	0-1 year	Epoxy is heavily work in high traffi		
	Flaga Tila Ognassia/ Bassalais	A461-4:- T D D00	000	0.	7	40	areas.		
	Floor - Tile Ceramic/ Porcelain	Athletic Team Room B09	260	SF	7	10+ years			
	Floor Drain	Athletic Team Room B09	1	EA	7	10+ years			
	Hand Dryer	Athletic Team Room B09	1	EA	5	2-5 years			
	Lavatory	Athletic Team Room B09	1	EA	6	6-10 years	Service sink.		
	Lighting - Pendent/Surface	Athletic Team Room B09	8	EA	6	6-10 years			
	Showers	Athletic Team Room B09	8	EA	7	6-10 years			
	Storage/ Closet	Athletic Team Room B09	60	SF	5	10+ years			
	Student Lockers - One Tier	Athletic Team Room B09	48	EA	7	10+ years			
	Student Lockers - Two Tier	Athletic Team Room B09	16	EA	7	10+ years			
	Urinals	Athletic Team Room B09	1	EA	6	6-10 years			
	Walls - Structural Glazed Tile	Athletic Team Room B09	2,080	SF	7	10+ years			
	Water Closet	Athletic Team Room B09	1	EA	6	6-10 years			
unch &	Multipurpose Room								
	Ceiling - Splined	1st Floor	4,024	SF	6	10+ years			
	Ceiling - Splined	1st Floor	4	SF	4	0-1 year	Water damage		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	G		
	Floor - Tile	1st Floor	4,028	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	[′] 61	EA	7	6-10 years			
	Serving Line	1st Floor	16	LF	6	6-10 years			
	Walls - Structural Glazed Tile	1st Floor	4,580	SF	6	10+ years			
	Ceiling - Plaster/Drywall	1st floor JROTC	1,500	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st floor JROTC	2	EΑ	6	10+ years			
	Floor - Tile	1st floor JROTC	1,500	SF	4	0-1 year	Floor has holes and is damaged		
	Lighting - Pendent/Surface	1st floor JROTC	20	EA	7	6-10 years	throughout.		
	Market Board	1st floor JROTC	12	LF	6	•			
				SF		6-10 years			
	Storage/ Closet	1st floor JROTC	60		7	10+ years			
	Walls - Concrete Block	1st floor JROTC	400	SF	6	10+ years			
	Walls - Structural Glazed Tile	1st floor JROTC	1,000	SF	6	10+ years			



Catego	Category : Room			Building : Addition 1					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Mechani	cal/ Service Rooms								
	Janitor's Closet	1st Floor	122	SF	5	10+ years	North		
	Janitor's Closet	1st Floor	135	SF	5	10+ years	South		
	Storage Room	1st Floor	225	SF	5	10+ years	Science Storage 109D		
	Storage Room	1st Floor	168	SF	5	10+ years	PE Storage 119A		
	Janitor's Closet	2nd Floor	77	SF	7	10+ years			
	Janitor's Closet	2nd Floor	57	SF	4	0-1 year	Ceiling damaged.		
	Storage Room	2nd Floor	389	SF	7	10+ years			
	Janitor's Closet	3rd Floor	157	SF	5	10+ years	South		
	Janitor's Closet	3rd Floor	202	SF	5	10+ years	North		
	Storage Room	3rd Floor	601	SF	5	10+ years	Art Storage 320A		
	Crawl Space - Unfinished	Basement	73,000	SF	7	10+ years			
	Mechanical/ Service Rooms	Basement	285	SF	7	10+ years			
	Storage Room	Basement	250	SF	7	10+ years	PE Storage B11		
	Storage Room	Basement	34	SF	7	10+ years	Basement Storage Room Next to		
							Restroom		
Restroor		4 (5) 011				40			
	Accessories	1st FL - Girls	290	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st FL - Girls	290	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st FL - Girls	2	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st FL - Girls	290	SF	6	10+ years			
	Floor Drain	1st FL - Girls	1	EΑ	7	10+ years			
	Hand Dryer	1st FL - Girls	2	EA	7	6-10 years			
	Lavatory	1st FL - Girls	2	EA	6	10+ years			
	Lighting - Pendent/Surface	1st FL - Girls	4	EA	7	6-10 years			
	Partitions	1st FL - Girls	6	EA	7	10+ years			
	Walls - Structural Glazed Tile	1st FL - Girls	760	SF	6	10+ years			
	Water Closet	1st FL - Girls	6	EA	6	10+ years			
	Accessories	1st FL - Nurse Office	80	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st FL - Nurse Office	80	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st FL - Nurse Office	1	EA	6	10+ years			
	Floor - Tile	1st FL - Nurse Office	80	SF	6	10+ years			
	Floor Drain	1st FL - Nurse Office	1	EA	7	10+ years			
	Lavatory	1st FL - Nurse Office	1	EA	6	10+ years			
	Lighting - Pendent/Surface	1st FL - Nurse Office	1	EA	7	6-10 years			
	Partitions	1st FL - Nurse Office	2	EA	7	10+ years			
	Walls - Concrete Block	1st FL - Nurse Office	340	SF	6	10+ years			
	Water Closet	1st FL - Nurse Office	2	EA	6	10+ years			
	Accessories	1st FI - Boys	290	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st FI - Boys	290	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st FI - Boys	2	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st FI - Boys	290	SF	6	10+ years			
	Floor Drain	1st FI - Boys	1	EA	7	10+ years			







Building: Addition 1 Category : Room

Category : Room Building : Addition 1							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Hand Dryer	1st FI - Boys	2	EΑ	7	6-10 years	
	Lavatory	1st FI - Boys	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st FI - Boys	4	EA	7	6-10 years	
	Partitions	1st Fl - Boys	4	EA	7	10+ years	
	Urinals	1st FI - Boys	4	EA	6	10+ years	
	Walls - Structural Glazed Tile	1st FI - Boys	760	SF	6	10+ years	
	Water Closet	1st FI - Boys	4	EA	6	10+ years	
	Accessories	1st floor girls inside locker room	70	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st floor girls inside locker room	70	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor girls inside locker room	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor girls inside locker room	70	SF	6	10+ years	
	Floor Drain	1st floor girls inside locker room	1	EA	7	10+ years	
	Lavatory	1st floor girls inside locker room	2	EA	6	10+ years	
	Lighting - Lay-in	1st floor girls inside locker room	1	EΑ	7	6-10 years	
	Partitions	1st floor girls inside locker room	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st floor girls inside locker room	250	SF	6	10+ years	
	Water Closet	1st floor girls inside locker room	2	EA	6	10+ years	
	Accessories	211A Women staff	60	SF	7	10+ years	
	Ceiling - Plaster/Drywall	211A Women staff	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	211A Women staff	1	ĒΑ	6	10+ years	
	Floor - Tile	211A Women staff	60	SF	6	10+ years	
	Lavatory	211A Women staff	1	ĒΑ	5	10+ years	
	Lighting - Pendent/Surface	211A Women staff	1	EA	6	6-10 years	
	Partitions	211A Women staff	2	EA	5	10+ years	
	Walls - Concrete Block	211A Women staff	318	SF	6	10+ years	
	Water Closet	211A Women staff	2	ĒΑ	6	10+ years	
	Accessories	2nd FL across 226 Men staff -	80	SF	7	10+ years	
		Admin Office				, , , , , ,	
	Ceiling - Plaster/Drywall	2nd FL across 226 Men staff -	80	SF	6	10+ years	
	John S. Martin L. J. Martin L.	Admin Office		-	-	, , , , , , , , , , , , , , , , , , , ,	
	Doors - Wood Doors inclu hw	2nd FL across 226 Men staff -	1	EA	6	10+ years	
		Admin Office			-	, , , , , , , , , , , , , , , , , , , ,	
	Floor - Tile	2nd FL across 226 Men staff -	80	SF	6	10+ years	
		Admin Office		-	-	, , , , , , , , , , , , , , , , , , , ,	
	Floor Drain	2nd FL across 226 Men staff -	1	EA	7	10+ years	
		Admin Office	-		•	, , , , , , , , , , , , , , , , , , , ,	
	Lavatory	2nd FL across 226 Men staff -	1	EA	6	10+ years	
		Admin Office	•		Ū	.o. you.o	
	Lighting - Pendent/Surface	2nd FL across 226 Men staff -	1	EA	6	6-10 years	
	Lighting 1 ondong curiaco	Admin Office	•	_, .	Ū	o ro youro	
	Partitions	2nd FL across 226 Men staff -	1	EA	7	10+ years	
	. Gradono	Admin Office	•	_/ \	•	101 yours	
	Urinals	2nd FL across 226 Men staff -	2	EA	6	10+ years	
	oa.o	Admin Office	2	_/ \	3	101 yours	
		, tariiii Onioo					







Building: Addition 1 Category: Room

legoi y	. Room		Building : Addition 1					
	_					Recommend		
	tem - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
,	Walls - Concrete Block	2nd FL across 226 Men staff - Admin Office	340	SF	6	10+ years		
,	Water Closet	2nd FL across 226 Men staff - Admin Office	1	EA	6	10+ years		
,	Accessories	2nd Floor Boys Next to 220, Converted to Music Storage	320	SF	7	10+ years		
(Ceiling - Plaster/Drywall	2nd Floor Boys Next to 220, Converted to Music Storage	320	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor Boys Next to 220, Converted to Music Storage	2	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys Next to 220, Converted to Music Storage	320	SF	6	10+ years		
	Floor Drain	2nd Floor Boys Next to 220, Converted to Music Storage	1	EA	7	10+ years		
I	Lighting - Pendent/Surface	2nd Floor Boys Next to 220, Converted to Music Storage	4	EA	6	6-10 years		
,	Walls - Structural Glazed Tile	2nd Floor Boys Next to 220, Converted to Music Storage	771	SF	6	10+ years		
	Accessories	2nd across 214 Girls	320	SF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd across 214 Girls	320	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd across 214 Girls	3	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd across 214 Girls 2nd across 214 Girls	320	SF	6	10+ years		
	Floor Drain	2nd across 214 Girls 2nd across 214 Girls	320 1	EA	7	10+ years		
	_avatory	2nd across 214 Girls 2nd across 214 Girls	4	EA	6	10+ years		
	Lighting - Pendent/Surface	2nd across 214 Girls	4	EA	6	6-10 years		
	Partitions	2nd across 214 Girls 2nd across 214 Girls	7	EA	7	10+ years		
	Walls - Structural Glazed Tile	2nd across 214 Girls	771	SF	6	10+ years		
	Water Closet	2nd across 214 Girls	7	EA	6	10+ years		
	Accessories	3rd Floor Girls Next to 318, Converted to Storage	320	SF	7	10+ years		
(Ceiling - Plaster/Drywall	3rd Floor Girls Next to 318, Converted to Storage	320	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor Girls Next to 318, Converted to Storage	3	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor Girls Next to 318, Converted to Storage	320	SF	6	10+ years		
ا	_avatory	3rd Floor Girls Next to 318, Converted to Storage	4	EA	5	10+ years		
	Lighting - Pendent/Surface	3rd Floor Girls Next to 318, Converted to Storage	4	EA	6	6-10 years		
,	Walls - Structural Glazed Tile	3rd Floor Girls Next to 318, Converted to Storage	771	SF	6	10+ years		
,	Water Closet	3rd Floor Girls Next to 318, Converted to Storage	7	EA	6	10+ years		







Building: Addition 1 Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement **Comments** Accessories 3rd Floor Men's Inside 314 80 SF 10+ vears 7 80 SF Ceiling - Plaster/Drywall 3rd Floor Men's Inside 314 6 10+ years Doors - Wood Doors inclu hw 3rd Floor Men's Inside 314 1 EΑ 6 10+ years Floor - Tile 80 SF 6 3rd Floor Men's Inside 314 10+ years Lavatory 3rd Floor Men's Inside 314 1 EΑ 6 10+ years Lighting - Pendent/Surface 3rd Floor Men's Inside 314 1 EΑ 6 6-10 years **Partitions** 3rd Floor Men's Inside 314 EΑ 7 10+ years 1 Urinals 3rd Floor Men's Inside 314 1 EΑ 6 10+ years Walls - Concrete Block 3rd Floor Men's Inside 314 290 SF 6 10+ years Water Closet 3rd Floor Men's Inside 314 EΑ 6 10+ years 1 Accessories 3rd near 327 Unisex 80 SF 7 10+ years Ceiling - Lay-in 3rd near 327 Unisex 80 SF 6 10+ years Doors - Wood Doors inclu hw 3rd near 327 Unisex EΑ 6 1 10+ years SF 7 Floor - Tile 3rd near 327 Unisex 80 10+ years Floor Drain 3rd near 327 Unisex EΑ 7 1 10+ years FΑ Lavatory 3rd near 327 Unisex 1 6 10+ years Lighting - Lay-in 3rd near 327 Unisex 1 EΑ 6 6-10 years Partitions 3rd near 327 Unisex 2 EΑ 7 10+ years Walls - Concrete Block SF 3rd near 327 Unisex 340 6 10+ years Water Closet 3rd near 327 Unisex 2 EΑ 6 10+ years Accessories Basement Inside Storage 34 SF 7 6-10 years Basement Inside Storage SF Ceiling - Plaster/Drywall 34 6 10+ years Doors - Wood Doors inclu hw 6 Basement Inside Storage EΑ 6-10 years Missing louver. SF Floor - Concrete Basement Inside Storage 34 7 10+ years EΑ 6 6-10 years Lavatory Basement Inside Storage 1 Lighting - Pendent/Surface Basement Inside Storage 1 EΑ 6 6-10 years Walls - Concrete Block SF Basement Inside Storage 176 6 10+ years Water Closet Basement Inside Storage EΑ 6 6-10 years

Category : Classroom Building : Addition 1

						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Classroom #111 (Regular Classroom)										
	AC Units	1st Floor	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor	736	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years				
	Floor - Tile	1st Floor	736	SF	6	10+ years				
	Lighting - Pendent/Surface	1st Floor	18	EΑ	6	6-10 years				
	Marker Board	1st Floor	20	LF	6	6-10 years				
	Walls - Concrete Block	1st Floor	975	SF	6	10+ years				
_Classroom #112 (Regular Classroom)										
	AC Units	1st Floor	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor	736	SF	6	10+ years				

Campus Name: Hubbard HS Page : 35 of 60 Assessment Date: 07/24/2019





Category : Classroom			В	Building : Addition 1					
_			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years			
	Floor - Tile	1st Floor	736	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	18	EA	6	6-10 years			
	Marker Board	1st Floor	20	LF	6	6-10 years			
	Walls - Concrete Block	1st Floor	975	SF	6	10+ years			
Classroo	om #113 (Science Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	115	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	1,107	SF	6	10+ years			
	Chalk Board	1st Floor	5	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years			
	Floor - Tile	1st Floor	1,107	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	27	EA	6	6-10 years			
	Marker Board	1st Floor	 8	LF	6	6-10 years			
	Walls - Concrete Block	1st Floor	1,185	SF	6	10+ years			
	Work Sink	1st Floor	3	EA	7	6-10 years			
Classroo	om #114 (Science Classroom)								
Ciassioc	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	18	LF	6	10+ years			
	Casework Ceiling - Plaster/Drywall	1st Floor	550	SF	6	10+ years			
	Chalk Board	1st Floor	20	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	20	EA	6	10+ years			
	Floor - Tile	1st Floor	550	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years			
	Marker Board	1st Floor	8	LF	6	6-10 years			
	Storage/ Closet	1st Floor	60	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	815	SF	6	10+ years			
	Work Sink	1st Floor	1	EA	7	6-10 years			
Classes	was #445 (Decider Classics)								
Ciassion	om #115 (Regular Classroom)	4 of Eleca		ΕΛ	7	0.40.4005			
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	16	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	1,107	SF	6	10+ years			
	Chalk Board	1st Floor	4	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years			
	Floor - Tile	1st Floor	1,107	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	27	EA	6	6-10 years			
	Marker Board	1st Floor	8	LF	6	6-10 years			
	Walls - Concrete Block	1st Floor	1,185	SF	6	10+ years			
	Work Sink	1st Floor	3	EA	7	6-10 years			



Catego	Category : Classroom		В	uilding	: Additi		200 O Hamili Avenoe, Officago, 12 00023
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #116 (Computer Lab)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	18	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	550	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	550	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	18	LF	6	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	815	SF	6	10+ years	
_Classroo	m #117 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	736	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	736	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	959	SF	6	10+ years	
	Walls - Concrete Block	1st Floor	16	SF	5	2-5 years	Cracked CMU/mortar cracks.
Classroo	m #120 (Art Room)						
	Ceiling - Lay-in	1st Floor	1,107	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,107	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	27	EA	6	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,185	SF	6	10+ years	
	Work Sink	1st Floor	3	EA	7	6-10 years	
Classroo	m #122 (Regular Classroom)						
	Casework	1st Floor	48	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,107	SF	6	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,107	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	27	EA	6	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,185	SF	6	10+ years	
	Work Sink	1st Floor	3	EA	7	6-10 years	
Classroo	m #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	



Catego	Category : Classroom		Building : Addition 1					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Casework	2nd Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	736	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	736	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years		
	Marker Board	2nd Floor	20	LF	6	6-10 years		
	Walls - Concrete Block	2nd Floor	975	SF	6	10+ years		
Classroo	om #212 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	736	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	736	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years		
	Marker Board	2nd Floor	20	LF	6	6-10 years		
			975	SF	6	•		
	Walls - Concrete Block	2nd Floor	975	5F	ь	10+ years		
Classroo	om #213 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	8	LF	6	10+ years		
	Ceiling - Splined	2nd Floor	736	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	736	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years		
	Marker Board	2nd Floor	20	LF	6	6-10 years		
	Walls - Concrete Block	2nd Floor	975	SF	6	10+ years		
Classroo	om #214 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	736	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years		
	Floor - Tile	2nd Floor	736	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years		
	Marker Board	2nd Floor	20	LF	6	6-10 years		
	Walls - Concrete Block	2nd Floor	975	SF	6	10+ years		
Classro	om #215 (Regular Classroom)							
CidaaiUl	AC Units	2nd Floor	4	EA	7	6-10 years		
			1	LF	7	•		
	Casework	2nd Floor	8		6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	736	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		





Classroom	Item - Type Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Concrete Block	Location 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	Quantity 736 18	UOM SF	Rank	Recommend Replacement	Comments
Classroom	Floor - Tile Lighting - Pendent/Surface Marker Board	2nd Floor 2nd Floor 2nd Floor	736 18				Comments
Classroom	Lighting - Pendent/Surface Marker Board	2nd Floor 2nd Floor	18	SF	_		
Classroom	Marker Board	2nd Floor			6	10+ years	
Classroom				EA	6	6-10 years	
Classroom	Walls - Concrete Block	2nd Floor	20	LF	6	6-10 years	
		ZIIU FIOOI	975	SF	6	10+ years	
	n #216 (Computer Lab)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,107	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	1,107	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	27	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	1,185	SF	6	10+ years	
	Wireless System	2nd Floor	1,100	EA	7	6-10 years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
lassroon	n #217 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	736	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	736	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	975	SF	6	10+ years	
lassroom	n #218 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	643	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	643	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	5	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	960	SF	6	10+ years	
lassroom	n #220 (Music Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	1,500	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1,300	EA	6	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	2nd Floor 2nd Floor	1,500	SF	6	10+ years 10+ years	
	Lighting - Pendent/Surface	2nd Floor	1,500	EA	6	6-10 years	



Catego	Category : Classroom		Building : Addition 1					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Marker Board	2nd Floor	20	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	30	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	585	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	585	SF	6	10+ years		
_Classroo	om #221 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years		
	Ceiling - Splined	2nd Floor	2,311	SF	6	10+ years		
	Ceiling - Splined	2nd Floor	2	SF	4	0-1 year	Water damage observed.	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years	Trater damage executed.	
	Floor - Tile	2nd Floor	2,313	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	31	EA	6	6-10 years		
	Marker Board	2nd Floor	8	LF	6	6-10 years		
	Walls - Concrete Block	2nd Floor	1,150	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,150	SF	6	10+ years		
	vvalis - Flastel/Drywali	2110 11001	1,150	SI	O	10+ years		
Classroo	om #223 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years		
	Casework	2nd Floor	36	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years		
	Chalk Board	2nd Floor	40	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years		
	Floor - Tile	2nd Floor	1,120	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	30	EA	6	6-10 years		
	Walls - Concrete Block	2nd Floor	980	SF	6	10+ years		
	Work Sink	2nd Floor	1	EA	7	6-10 years		
Classroo	om #225 (Computer Lab)							
	AC Units	2nd Floor	4	EA	7	6-10 years		
	Casework	2nd Floor	32	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	1,500	SF	6	10+ years		
	Chalk Board	2nd Floor	20	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	10+ years		
	Floor - Tile	2nd Floor	1,500	SF	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor		EA	6	6-10 years		
	Marker Board	2nd Floor	36 8	LF				
	Walls - Concrete Block	2nd Floor 2nd Floor		SF	6	6-10 years		
			1,170 1		6 7	10+ years		
	Work Sink	2nd Floor	1	EA	1	6-10 years		
Classroo	om #226 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	8	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	736	SF	6	10+ years		



Catego	Category : Classroom		Building : Addition 1					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	736	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years		
	Marker Board	2nd Floor	20	LF	6	6-10 years		
	Walls - Concrete Block	2nd Floor	975	SF	6	10+ years		
Classroo	om #311 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Ceiling - Lay-in	3rd Floor	736	SF	6	10+ years		
	Chalk Board	3rd Floor	40	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	736	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	21	EA	6	6-10 years		
	Marker Board	3rd Floor	40	LF	6	6-10 years		
	Walls - Concrete Block	3rd Floor	975	SF	6	-		
		3rd Floor	50	SF	6	10+ years		
	Walls - Plaster/Drywall	31d Floor	50	SF	0	10+ years		
Classroo	om #312 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Ceiling - Lay-in	3rd Floor	736	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	736	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	18	EA	6	6-10 years		
	Marker Board	3rd Floor	20	LF	6	6-10 years		
	Walls - Concrete Block	3rd Floor	975	SF	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor	50	SF	5	10+ years		
Classroo	om #313 (Computer Lab)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	AC Units	3rd Floor	1	EA	5	6-10 years		
	Ceiling - Lay-in	3rd Floor	1,120	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years		
	Floor - Tile	3rd Floor	1,120	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	30	EA	6	6-10 years		
	Marker Board	3rd Floor		LF	6			
			20		-	6-10 years		
	Walls - Concrete Block	3rd Floor	1,135	SF	6	10+ years		
	Work Sink	3rd Floor	1	EA	7	6-10 years		
Classroo	om #314 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Ceiling - Lay-in	3rd Floor	736	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	736	SF	6	10+ years		



Catego	Category : Classroom		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	3	EA	6	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	975	SF	6	10+ years	
Classroc	om #315 (Computer Lab)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,120	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	. 2	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,120	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	30	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	1,135	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	36	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classros	om #316 (Computer Lab)						
Classiuc	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	20	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	1,107	SF	6	10+ years 10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1,107	EA	6	•	
		3rd Floor		SF		10+ years	
	Floor - Tile		1,107		6	10+ years	
	Lighting - Lay-in	3rd Floor	27	EΑ	6	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	1,185	SF	6	10+ years	
	Wireless System	3rd Floor	1	EA	4	0-1 year	Electrical outlets on floor not working need to be replaced
	Work Sink	3rd Floor	1	EA	7	6-10 years	·
Classroc	om #317 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	736	SF	6	10+ years	Tile pushed up out of place.
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	736	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	ĒA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	975	SF	6	10+ years	
Classroo	om #318 (Computer Lab)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	1,120	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1,120	Sr EA	6	10+ years 10+ years	
	Floor - Tile	3rd Floor		SF	6	•	
	FIOUI - TIIE	วเน เเบปโ	1,120	SF	О	10+ years	



Category : Classroom		Building : Addition 1					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	30	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	1,325	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	om #319 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	736	SF	6	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	736	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	6	6-10 years	
	Marker Board	3rd Floor	40	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	975	SF	6	10+ years	
	vvalis Concrete Block	010 1 1001	373	Oi.	J	101 years	
Classroo	om #320 (Choral Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	32	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,107	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,102	SF	6	10+ years	
	Floor - Tile	3rd Floor	5	SF	4	0-1 year	Chipped/missing tiles.
	Lighting - Lay-in	3rd Floor	27	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor	1,185	SF	6	10+ years	
Classroo	om #322 (Band Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	40	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,238	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	12	SF	5	0-1 year	Tiles scraped/scuffed.
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,247	SF	6	10+ years	
	Floor - Tile	3rd Floor	3	SF	4	0-1 year	Tile chipped/missing.
	Lighting - Lay-in	3rd Floor	37	EA	6	6-10 years	The employ/mosting.
	Walls - Concrete Block	3rd Floor	1,250	SF	6	10+ years	
	Work Sink	3rd Floor	1,230	EA	7	6-10 years	
		3.331	•	_, ,	•	2 . 2 , 3	
Classroo	om #323 (Art Room)	0.15		F ^		0.40	
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	75	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,120	SF	6	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	



Catego	Category : Classroom		В	Building : Addition 1					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	3rd Floor	2	EΑ	6	10+ years			
	Floor - Tile	3rd Floor	1,120	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	30	EA	6	6-10 years			
	Walls - Concrete Block	3rd Floor	1,150	SF	6	10+ years			
	Walls - Plaster/Drywall	3rd Floor	50	SF	6	6-10 years	Paint chipping and peeling above sink.		
	Work Sink	3rd Floor	2	EA	7	6-10 years			
Classroo	om #324 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Ceiling - Lay-in	3rd Floor	375	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years			
	Floor - Tile	3rd Floor	375	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	6	EA	6	6-10 years			
	Marker Board	3rd Floor	8	LF	6	6-10 years			
	Walls - Concrete Block	3rd Floor	700	SF	6	10+ years			
Classroo	om #325 (Art Room)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	75	LF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	1,120	SF	6	10+ years			
	Chalk Board	3rd Floor	8	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years			
	Floor - Tile	3rd Floor	1,110	SF	6	10+ years	01: 1/ : : :		
	Floor - Tile	3rd Floor	10	SF	4	0-1 year	Chipped/ missing tiles		
	Instructional Surface	3rd Floor	10	LF	6	10+ years			
	Lighting - Lay-in	3rd Floor	30	EA SF	6	6-10 years			
	Walls - Concrete Block Work Sink	3rd Floor 3rd Floor	980 2	Sr EA	6 7	10+ years			
	WORK SILIK	310 11001	2	EA	1	6-10 years			
_Classroo	om #326 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Ceiling - Lay-in	3rd Floor	736	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years			
	Floor - Tile	3rd Floor	736	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	18	EA	6	6-10 years			
	Marker Board	3rd Floor	20	LF	6	6-10 years			
	Walls - Concrete Block	3rd Floor	959	SF	6	10+ years	One should be a secretar blook		
	Walls - Concrete Block	3rd Floor	6	SF	5	0-1 year	Cracked concrete block.		



Catego	ry : Interior		Building : Addition 1					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
<u>Corridor</u>								
	Ceiling - Lay-in	1st Floor	228	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	3,993	SF	6	10+ years		
	Doors - Store Front	1st Floor	3	EA	6	10+ years		
	Doors - Transom Window	1st Floor	18	SF	6	10+ years		
	Doors - Wood Doors include hw	1st Floor	4	EA	6	10+ years		
	Drinking Fountains - Single Fountain	1st Floor	3	EA	4	1-2 years		
	Drinking Fountains - Single Water Cooler	1st Floor	1	EA	5	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor	312	SF	6	10+ years		
	Floor - Tile/Sheet	1st Floor	4,023	SF	5	10+ years		
	Lighting - Lay-in	1st Floor	52	EA	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	2	EA	6	6-10 years		
	Student Lockers - One Tier	1st Floor	100	EA	6	10+ years		
	Walls - Concrete Block	1st Floor	1,235	SF	6	10+ years		
	Walls - Structural Glazed Tile	1st Floor	4,940	SF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	3,993	SF	6	10+ years		
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	10+ years		
	Floor - Tile/Sheet	2nd Floor	3,993	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	52	EA	6	6-10 years		
	Student Lockers - One Tier	2nd Floor	116	EA	6	10+ years		
	Walls - Concrete Block	2nd Floor	1,235	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	309	SF	5	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	4,940	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	4,025	SF	6	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	4	EA	6	10+ years		
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	10+ years		
	Floor - Tile/Sheet	3rd Floor	3,983	SF	5	10+ years		
	Floor - Tile/Sheet	3rd Floor	10	SF	4	0-1 year	Tiles chipped/missing.	
	Lighting - Lay-in	3rd Floor	52	EA	6	6-10 years		
	Student Lockers - One Tier	3rd Floor	124	EA	6	10+ years		
	Walls - Concrete Block	3rd Floor	1,235	SF	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor	309	SF	5	10+ years		
	Walls - Structural Glazed Tile	3rd Floor	4,940	SF	6	10+ years		
Safety								
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years		
	Metal Dedector	Entire Building	1	EΑ	7	6-10 years		
	Security Cameras	Entire Building	3	EΑ	7	6-10 years		
	Security Cameras	Entire Building	3	EA	7	6-10 years		
Stairs								
Sidils	Ceiling - Plaster/Drywall	Basement North	210	SF	6	10+ years		
	Floor - Concrete	Basement North	80	SF	5	10+ years		
	1 loo. Golloroto	Dasoment North	00	Oi.	3	ioi yeais		



Catego	ry : Interior		Building : Addition 1						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Handrails	Basement North	42	LF	5	10+ years			
	Lighting - Pendent/Surface	Basement North	1	EΑ	6	6-10 years			
	Stairs - Concrete	Basement North	20	LF	6	10+ years			
	Walls - Concrete Block	Basement North	945	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Basement South	210	SF	6	10+ years			
	Floor - Concrete	Basement South	80	SF	5	10+ years			
	Handrails	Basement South	42	LF	5	10+ years			
	Lighting - Pendent/Surface	Basement South	1	EA	7	6-10 years			
	Stairs - Concrete	Basement South	20	LF	6	10+ years			
	Walls - Concrete Block	Basement South	945	SF	6	10+ years			
	Ceiling - Lay-in	North Stair	705	SF	6	10+ years			
	Floor - Terrazzo	North Stair	610	SF	6	10+ years			
	Handrails	North Stair	132	LF	5	10+ years			
	Lighting - Lay-in	North Stair	5	EA	6	6-10 years			
	Lighting - Wall Mounted	North Stair	2	EA	6	6-10 years			
	Stairs - Terrazzo	North Stair	66	LF	6	10+ years			
	Walls - Concrete Block	North Stair	1,216	SF	6	10+ years			
	Walls - Structural Glazed Tile	North Stair	1,216	SF	6	10+ years			
	Ceiling - Lay-in	South Stair	705	SF	6	10+ years			
	Floor - Terrazzo	South Stair	610	SF	6	10+ years			
	Handrails	South Stair	132	LF	4	0-1 year	Handrail on 2nd floor loose		
	Lighting - Lay-in	South Stair	5	EA	6	6-10 years			
	Lighting - Wall Mounted	South Stair	2	EA	6	6-10 years			
	Stairs - Terrazzo	South Stair	36	LF	6	10+ years			
	Walls - Concrete Block	South Stair	1,216	SF	6	10+ years			
	Walls - Structural Glazed Tile	South Stair	1,216	SF	6	10+ years			





Category : Exterior **Building: Addition 2**

Category . Exterior			ananng	. Additiv	Recommend	
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Location	Quantity	COM	Italik	Replacement	Comments
Entrance Exterior Pages - Exterior Steel Page	Door 40 North	0	ΕΛ		0.40	
Exterior Doors - Exterior Steel Door	Door 10 - North	2	EA	6	6-10 years	
Exterior Stairs - Concrete	Door 10 - North	18	LF	6	6-10 years	
Stair Handrail - Steel_Stair Handrail	Door 10 - North	12	LF	5	2-5 years	
Exterior Doors - Exterior Steel Door	Door 11 - South	2	EΑ	6	6-10 years	
Exterior Doors - Transom Lite	Door 11 - South	1	EA	6	6-10 years	
Exterior Stairs - Concrete	Door 11 - South	40	LF	6	10+ years	
Stair Handrail - Steel_Stair Handrail	Door 11 - South	12	LF	5	2-5 years	-
Exterior Doors - Exterior Steel Door	Door 14 - Roof	1	EA	5	1-2 years	Threshold deteriorated
Entrance Control - Audio and Video	Door 8 - North courtyard	1	EA	6	2-5 years	
Exterior Doors - Exterior Steel Door	Door 8 - North courtyard	4	EA	6	6-10 years	
Exterior Doors - Transom Lite	Door 8 - North courtyard	4	EA	6	6-10 years	
Exterior Stairs - Concrete	Door 8 - North courtyard	38	LF . –	6	10+ years	
Exterior Stairs - Concrete	Door 8 - North courtyard	2	LF	5	0-1 year	Cracked to the side of stairs.
Ramp Handrail - Steel_Ramp Handrail	Door 8 - North courtyard	30	LF	5	2-5 years	
Ramps - Concrete	Door 8 - North courtyard	30	LF	6	6-10 years	
Stair Handrail - Steel_Stair Handrail	Door 8 - North courtyard	20	LF	5	2-5 years	
Exterior Doors - Exterior Wood Door	Door 9 - Northeast gym		EA	6	6-10 years	
Exterior Stairs - Concrete	Door 9 - Northeast gym	14	LF . –	6	10+ years	
Stair Handrail - Steel_Stair Handrail	Door 9 - Northeast gym	10	LF	5	2-5 years	
Foundation						
Foundation - Concrete	Entire Building	552	LF	7	10+ years	
Foundation - Concrete	Entire Building	50	LF	5	0-1 year	Entrance 12 Sinking/ Settling
Foundation - Concrete	Entire Building	40	LF	5	0-1 year	Entrance 10 Sinking/ Settling
Superstructure - Metal Deck/ Concrete	Entire Building	37,400	SF	7	10+ years	Littratice to Sinking/ Setting
Topping	Littine Ballating	37,400	O.	,	101 years	
. 5FF9						
ighting						
Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	6	2-5 years	
Exterior Lighting - Wall Mounted	Entire Building	12	EA	6	2-5 years	
Roof System						
Access Ladder - Metal	Roof 1	2	EA	7	10+ years	
Chimney - Metal Flue	Roof 1	15	LF	6	6-10 years	
Coping - Metal	Roof 1	600	LF	6	6-10 years	
Coping - Metal	Roof 1	78	LF	4	1-2 years	Rusted.
Downspouts - Interior Downspouts	Roof 1	180	LF	6	2-5 years	
Parapet - Parapet < 16" Height	Roof 1	678	LF	6	6-10 years	
Roof - Asphalt Gravel Ballast	Roof 1	20,507	SF	6	2-5 years	
Roof - Asphalt Gravel Ballast	Roof 1	2,000	SF	4	0-1 year	Leak center of roof
Roof Hatch - Metal	Roof 1	2	ĒΑ	7	10+ years	
					•	



Catego	ry : Exterior		В	uilding	: Additi		200 o Hamili Avervoe, Onicago, le 00025
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Roof Structure - Steel / Metal Deck/	Roof 1	22,507	SF	7	10+ years	
	Concrete Topping						
	Coping - Metal	Roof 2 - Lower Northwest	108	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof 2 - Lower Northwest	12	LF	7	6-10 years	
	Parapet - Parapet < 16" Height	Roof 2 - Lower Northwest	108	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof 2 - Lower Northwest	2,158	SF	4	0-1 year	Frequent leaks
	Roof Structure - Steel / Metal Deck/	Roof 2 - Lower Northwest	2,158	SF	7	10+ years	
	Concrete Topping						
	Coping - Metal	Roof 3 - Southeast	109	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof 3 - Southeast	17	LF	7	6-10 years	
	Parapet - Parapet < 16" Height	Roof 3 - Southeast	109	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof 3 - Southeast	5,138	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	Roof 3 - Southeast	5,138	SF	7	10+ years	
	Concrete Topping						
Walls							
	Cheek-Wall - Concrete	Entire Building	20	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	20,020	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	280	SF	4	0-1 year	Large cracks and settling.
	Exterior Walls - Prefabricated Metal Panel	Entire Building	120	SF	6	10+ years	
	Wall						
	Exterior Walls - Prefabricated Metal Panel	Entire Building	230	SF	4	0-1 year	Worn and loose.
	Wall						
_Windows							
	Guard - Guards perforated	Entire Building	360	SF	6	6-10 years	
	Lintels - Steel	Entire Building	50	LF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	360	SF	6	6-10 years	
	•	<u> </u>				,	
Catego	ry : Electrical		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	cy System		, ,				
	Security System - CCTV	Entire Building	37,400	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	37,400	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	4	EΑ	6	6-10 years	
	Exit Signs - Gym	Entire Building	5	EΑ	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Pool	Entire Building	3	EΑ	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	5,575	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	7,830	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	4,000	SF	6	10+ years	Building is served by a diesel electric



Catego	ry : Electrical		В	uilding	: Addition		
_			<u> </u>			Recommend	_
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							generator
ower D	istribution						
<u> </u>	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	ĒΑ	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EΑ	6	10+ years	
	PA System	Mechanical Room	37,400	SF	6	10+ years	Served from main building
						•	3
atego	ry : Fire Protection		В	uilding	: Addition	on 2 Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar							
	Fire Alarm Strobe Lights	Entire Building	37,400	SF	6	10+ years	
	Fire Alarm_System	Entire Building	37,400	SF	6	10+ years	
	m Maakaniaal		D	: 1 - 1 :	. A .1 .1:4:	0	
atego	ry : Mechanical		В	uilding	: Addition	on 2 Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	-						
	Condensing Unit- Roof Mounted - 5-10	Roof	1	EA	6	10+ years	Serves the lunchroom.
	tons						
	Condensing Unit- Roof Mounted - 5-10	Roof	1	EA	5	2-5 years	Needs frequent maintenance. Serve
	tons						the pool unit.
Air Hand	ling Systems						
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	5	6-10 years	Serves the pool.
	Indoor- Hot Water and DX Cooling Coils -					·	•
	8001-12000 cfm						
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Auxiliaries - 8001-12000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	5	6-10 years	Serves the gym.
	Indoor- Hot Water Coils - 8001-12000 cfm						
	Air Intake	Mechanical Room	1	EA	5	10+ years	Showing signs of corrosion
		Mechanical Room	1	EA	5	6-10 years	
	Auxiliaries - 8001-12000 cfm				5	6-10 years	Serves the girls locker room.
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	5	,	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - Less than 4000		1	EA	3	,	•
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - Less than 4000 cfm	Mechanical Room	1		3	•	,
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - Less than 4000 cfm Air Intake	Mechanical Room Mechanical Room	1	EA	6	10+ years	·
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - Less than 4000 cfm	Mechanical Room	1 1 1		6 5 5	•	Needs frequent maintenance. Serve

Campus Name: Hubbard HS Page : 49 of 60 Assessment Date: 07/24/2019



Category : Mechanical			В	Building	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Indoor- Hot Water Coils - 4000-8000 cfm		_			<u>-</u>	the lunchroom.
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Auxiliaries - 4000-8000 cfm	Mechanical Room	1	EΑ	5	2-5 years	
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	5	6-10 years	Corves the hous looker room
		wechanical Room	1	EA	5	6-10 years	Serves the boys locker room.
	Indoor- Hot Water Coils - Less than 4000						
	cfm						
	Air Intake	Mechanical Room	1	EA	6	6-10 years	Showing signs of corrosion
	Auxiliaries - Less than 4000 cfm	Mechanical Room	1	EA	5	6-10 years	
Boiler Sy	ystems						
	Boiler Auxiliary- Condensing Hot Water -	Mechanical Room	2	EA	7	10+ years	2017 installation, Fulton
	1001 - 2000 HP					·	
	Chemical Pot Feeder	Mechanical Room	1	EA	6	10+ years	
	Combustion Dampers	Mechanical Room	2	EΑ	6	10+ years	
	Condensing- Hot Water Boiler - 1001 - 2000	Mechanical Room	2	EA	7		2017 installation Fulton
	MBH	Mechanical Room	2	EA	,	10+ years	2017 installation, Fulton
	Water Fill System	Mechanical Room	2	EA	7	10+ years	
Heating	Devices						
·	Wall Heater - Electric	Entire Building	4	EA	5	2-5 years	Older
	Unit Heater - Hot Water	Mechanical Room	1	EΑ	6	10+ years	
	Fin Tube - Hot Water	Pool	150	LF	6	6-10 years	
Mechani	cal Plumbing						
IVICCITATII	Hydronic Supply and Return - Copper	Entire Building	150	LF	6	10+ years	
						•	
	Hot Water Pump - Less than 10	Mechanical Room	2	EA	7	10+ years	
Tempera	ature Control						
	Pneumatic System	Entire Building	37,400	SF	5	10+ years	sections manually controlled
	Thermostats - Pneumatic	Entire Building	6	EA	5	10+ years	Need calibration
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	2	EA	7	10+ years	Replaced in 2017
	CFM	g	_		•	,	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	7	EA	6	6-10 years	
	CFM						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than	Entire Building	1	EA	4	1-2 years	Housing looks corroded and possibly
	500 CFM						collapsed.
Catego	ry : Plumbing		В	Building	: Additi	on 2	
Group	·	Location	Quantity	UOM	Rank		Comments
J. 7 WP						. 1000	



						Replacement	
Hot Wat	er						
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	3	EA	5	2-5 years	Periodic cleaning of burners required
Piping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	37,400	SF	6	10+ years	
	Domestic Piping-Cold Water Risers	Entire Building	37,400	SF	6	10+ years	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	37,400	SF	6	10+ years	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	37,400	SF	6	10+ years	
	Domestic Piping-Hot Water Return Lines	Entire Building	37,400	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	37,400	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	37,400	SF	6	10+ years	
	Sanitary Piping	Entire Building	37,400	SF	6	6-10 years	
	Storm Piping	Entire Building	37,400	SF	6	10+ years	
	Vent Piping	Entire Building	37,400	SF	6	10+ years	
Pool Sys	stems						
	Pool Drain Piping	1st Floor	50	LF	6	10+ years	
	Pool Filtration System including Pump	1st Floor	1	EA	6	10+ years	
	Pool Hot Water Heater - Gas Fired	1st Floor	1	EA	5	2-5 years	Frequent maintenance required
	Pool Supply and Return Piping	1st Floor	100	LF	6	10+ years	·

Category: Room **Building: Addition 2**

	Landian	Overtitue	HOM	Dank	Recommend	Comments
pe	Location	Quantity	UOM	Rank	Replacement	Comments
es/Offices						
Lay-in	125B - PE Office	105	SF	6	10+ years	
Side-lite	125B - PE Office	24	SF	6	10+ years	
Vood Doors inclu hw	125B - PE Office	1	EA	6	10+ years	
le	125B - PE Office	105	SF	6	10+ years	
- Lay-in	125B - PE Office	1	EA	6	6-10 years	
stribution	125B - PE Office	4	EA	6	10+ years	
oncrete Block	125B - PE Office	375	SF	6	10+ years	
Lay-in	Football Coach Office (now PE Storage 124J)	231	SF	6	10+ years	
Vood Doors inclu hw	Football Coach Office (now PE Storage 124J)	1	EA	6	10+ years	
le	Football Coach Office (now PE Storage 124J)	231	SF	6	10+ years	
- Lay-in	Football Coach Office (now PE	2	EA	6	6-10 years	
stribution	Football Coach Office (now PE Storage 124J)	4	EA	6	10+ years	
stribut	ion	()	ion Football Coach Office (now PE 4	ion Football Coach Office (now PE 4 EA	ion Football Coach Office (now PE 4 EA 6	ion Football Coach Office (now PE 4 EA 6 10+ years



Catego	ry : Room		В	uilding	: Additi	on 2	<u> </u>
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	Football Coach Office (now PE Storage 124J)	630	SF	6	10+ years	
	Ceiling - Lay-in	Gym Office	125	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gym Office	1	EA	6	10+ years	
	Floor - Tile	Gym Office	125	SF	6	10+ years	
	Lighting - Lay-in	Gym Office	2	ĒΑ	6	6-10 years	
	Power Distribution	Gym Office	4	EΑ	6	10+ years	
	Walls - Concrete Block	Gym Office	415	SF	6	10+ years	
_Gymnasi	ia						
	Bleacher Seating	1st Floor	520	EA	6	10+ years	
	Ceiling - Lay-in	1st Floor	7,830	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	830	SF	4	0-1 year	Tiles missing and cracked.
	Doors - Wood Doors inclu hw	1st Floor	6	EA	6	10+ years	
	Floor - Wood	1st Floor	7,000	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	44	EA	6	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Storage/ Closet	1st Floor	230	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	8,600	SF	6	10+ years	
	Wallo Collerate Blook	10(1)001	0,000	O.	Ü	io. youro	
Locker/S	Shower Room						
	Accessories	Boy's Locker Room	3,041	SF	7	10+ years	
	Benches, ped mounted	Boy's Locker Room	40	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Boy's Locker Room	3,041	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boy's Locker Room	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boy's Locker Room	3,016	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boy's Locker Room	25	SF	5	10+ years	
	Floor Drain	Boy's Locker Room	27	EA	7	10+ years	
	Hand Dryer	Boy's Locker Room	2	EA	7	6-10 years	
	Lavatory	Boy's Locker Room	3	EA	6	10+ years	
	Lighting - Pendent/Surface	Boy's Locker Room	30	EΑ	7	6-10 years	
	Partitions	Boy's Locker Room	3	EA	7	10+ years	
	Showers	Boy's Locker Room	22	EA	7	10+ years	
	Storage/ Closet	Boy's Locker Room	96	SF	7	10+ years	
	Student Lockers - One Tier	Boy's Locker Room	120	EA	6	10+ years	
	Urinals	Boy's Locker Room	3	EA	6	10+ years	
	Walls - Concrete Block	Boy's Locker Room	6,460	SF	6	10+ years	
	Water Closet	Boy's Locker Room	3	EA	6	10+ years	
	Accessories	Girl's Locker Room	3,041	SF	7	10+ years	
	Benches, ped mounted	Girl's Locker Room	,	SF LF	6	10+ years 10+ years	
			40	SF	_	•	
	Ceiling - Plaster/Drywall	Girl's Locker Room	3,041		6	10+ years	
	Doors - Wood Doors inclu hw	Girl's Locker Room	2 2 2 4 4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain Floor Drain	Girl's Locker Room Girl's Locker Room	3,041 16	SF EA	6 7	10+ years 10+ years	





Catego	ry : Room		В	uilding	: Additi	on 2	
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hand Dryer	Girl's Locker Room	6	EΑ	7	6-10 years	
	Lavatory	Girl's Locker Room	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Girl's Locker Room	30	EA	7	6-10 years	
	Partitions	Girl's Locker Room	4	EA	7	10+ years	
	Showers	Girl's Locker Room	11	EA	7	10+ years	
	Storage/ Closet	Girl's Locker Room	96	SF	7	10+ years	
	Student Lockers - One Tier	Girl's Locker Room	120	ĒΑ	6	10+ years	
	Walls - Concrete Block	Girl's Locker Room	6,460	SF	6	10+ years	
	Water Closet	Girl's Locker Room	4	EA	6	10+ years	
unch &	Multipurpose Room						
	Ceiling - Lay-in	003 - Lunchroom	4,000	SF	6	10+ years	
	Doors - Wood Doors inclu hw	003 - Lunchroom	4	EΑ	6	10+ years	
	Floor - Tile	003 - Lunchroom	4,000	SF	6	10+ years	
	Lighting - Lay-in	003 - Lunchroom	45	EΑ	7	6-10 years	
	Walls - Concrete Block	003 - Lunchroom	2,250	SF	6	10+ years	
	Walls - Concrete Block	003 - Lunchroom	30	SF	5	10+ years	
	Ceiling - Lay-in	003 - Lunchroom (Serving Area)	660	SF	6	10+ years	
	Doors - Wood Doors inclu hw	003 - Lunchroom (Serving Area)	5	EA	6	10+ years	
	Floor - Tile	003 - Lunchroom (Serving Area)	660	SF	6	10+ years	
	Lighting - Lay-in	003 - Lunchroom (Serving Area)	16	EA	7	6-10 years	
	Serving Line	003 - Lunchroom (Serving Area)	54	LF	6	6-10 years	
	Walls - Concrete Block	003 - Lunchroom (Serving Area)	980	SF	6	10+ years	
	Walls - Concrete Block	003 - Lunchroom (Serving Area)	20	SF	5	•	
	Ceiling - Lay-in	2nd FL - Weight Room	550	SF	6	10+ years 10+ years	
		2nd FL - Weight Room 2nd FL - Weight Room		SF			
	Ceiling - Splined		1,130	SF SF	6	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	2nd FL - Weight Room	1,680		7	10+ years	
	Lighting - Pendent/Surface	2nd FL - Weight Room	20	EA	5	6-10 years	
	Walls - Concrete Block	2nd FL - Weight Room	1,704	SF	6	10+ years	
/lechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	25	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	41	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	355	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	70	SF	7	10+ years	
	Storage Room	1st Floor	174	SF	7	10+ years	PE Storage Rooms.
	Mechanical/ Service Rooms	2nd Floor	7,076	SF	7	10+ years	
	Storage Room	2nd Floor	1,155	SF	5	10+ years	
	Crawl Space - Unfinished	Basement	35,000	SF	7	10+ years	
ool & N	latatorium						
	Accessories	1st Floor	6,910	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	6,910	SF	6	10+ years	
	- indicinally main	.555.	2,210	٥.	Ü	,	





Catego	ry : Room		В	uilding	: Additi	on 2	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	6,910	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	31	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor	7	EA	6	6-10 years	
	Pool Basin	1st Floor	3,874	SF	6	10+ years	
	Pool Deck	1st Floor	3,040	SF	6	10+ years	
	Pool Deck Drains	1st Floor	8	EA	7	10+ years	
	Storage/ Closet	1st Floor	105	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	6,980	SF	6	10+ years	
_Restroor	n						
	Accessories	125 A - Unisex	155	SF	7	10+ years	
	Ceiling - Plaster/Drywall	125 A - Unisex	155	SF	6	10+ years	
	Doors - Wood Doors inclu hw	125 A - Unisex	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	125 A - Unisex	155	SF	6	10+ years	
	Lavatory	125 A - Unisex	1	ĒΑ	6	10+ years	
	Lighting - Pendent/Surface	125 A - Unisex	1	EA	6	6-10 years	
	Walls - Concrete Block	125 A - Unisex	420	SF	6	10+ years	
	Water Closet	125 A - Unisex	1	ĒΑ	6	10+ years	
	Accessories	125 B - PE Office	65	SF	7	10+ years	
	Ceiling - Plaster/Drywall	125 B - PE Office	65	SF	6	10+ years	
	Doors - Wood Doors inclu hw	125 B - PE Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	125 B - PE Office	65	SF	6	10+ years	
	Floor Drain	125 B - PE Office	1	EA	7	6-10 years	
	Lavatory	125 B - PE Office	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	125 B - PE Office	1	EA	6	6-10 years	
	Walls - Concrete Block	125 B - PE Office	315	SF	6	10+ years	
	Water Closet	125 B - PE Office	1	EA	6	10+ years	
	Accessories	2nd FL - Boys	315	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd FL - Boys	315	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd FL - Boys	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd FL - Boys 2nd FL - Boys	315	SF	6	10+ years	
		2nd FL - Boys 2nd FL - Boys	1	EA	7		
	Floor Drain	2nd FL - Boys 2nd FL - Boys	2	EA	6	10+ years	
	Lavatory				_	10+ years	
	Lighting - Pendent/Surface	2nd FL - Boys	3	EΑ	6	6-10 years	
	Partitions	2nd FL - Boys	2	EΑ	7	10+ years	
	Urinals	2nd FL - Boys	2	EA	6	10+ years	
	Walls - Concrete Block	2nd FL - Boys	700	SF	6	10+ years	
	Water Closet	2nd FL - Boys	2	EA	6	10+ years	
	Accessories	2nd FL - Girls	315	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd FL - Girls	315	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd FL - Girls	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd FL - Girls	315	SF	6	10+ years	
	Floor Drain	2nd FL - Girls	1	EA	7	10+ years	







Building: Addition 2 Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Hand Dryer 2nd FL - Girls EΑ 6-10 years 7 2nd FL - Girls 2 EΑ 6 10+ years Lavatory Lighting - Pendent/Surface 2nd FL - Girls 3 EΑ 6 6-10 years Partitions 3 EΑ 5 2nd FL - Girls 10+ years SF Walls - Concrete Block 2nd FL - Girls 700 6 10+ years Water Closet EΑ 2nd FL - Girls 3 6 10+ years Accessories Gym Office (Coach Locker room) SF 7 10+ years 189 SF Ceiling - Plaster/Drywall Gym Office (Coach Locker room) 89 6 10+ years Doors - Wood Doors inclu hw Gym Office (Coach Locker room) 1 EΑ 6 10+ years Gym Office (Coach Locker room) SF Floor - Tile Ceramic/ Porcelain 189 6 10+ years Gvm Office (Coach Locker room) Floor Drain 10+ years 2 EΑ 7 Lighting - Pendent/Surface Gym Office (Coach Locker room) 3 EΑ 5 6-10 years Gym Office (Coach Locker room) Showers 4 EΑ 5 10+ years Gym Office (Coach Locker room) EΑ 6 Student Lockers - One Tier 11 10+ years Gym Office (Coach Locker room) Walls - Concrete Block SF 580 6 10+ years Walls - Concrete Block Gym Office (Coach Locker room) SF 5 20 10+ years

Category : Interior Building : Addition 2

Catego	ry : interior	Building : Addition 2							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor									
	Ceiling - Lay-in	1st Floor	3,143	SF	6	10+ years			
	Ceiling - Lay-in	1st Floor	64	SF	5	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	168	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years			
	Drinking Fountains - Single Fountain	1st Floor	2	EA	5	10+ years			
	Drinking Fountains - Single Water Cooler	1st Floor	1	EA	5	10+ years			
	Floor - Terrazzo	1st Floor	66	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	102	SF	6	10+ years			
	Floor - Tile/Sheet	1st Floor	3,207	SF	5	10+ years			
	Floor - Tile/Sheet	1st Floor	50	SF	5	10+ years			
	Lighting - Lay-in	1st Floor	22	EA	6	6-10 years			
	Walls - Concrete Block	1st Floor	4,618	SF	6	10+ years			
	Ceiling - Lay-in	2nd Gym Corridor	705	SF	6	10+ years			
	Ceiling - Lay-in	2nd Gym Corridor	10	SF	5	10+ years			
	Drinking Fountains - Single Fountain	2nd Gym Corridor	1	EA	5	10+ years			
	Floor - Carpet	2nd Gym Corridor	715	SF	6	6-10 years			
	Lighting - Lay-in	2nd Gym Corridor	8	EA	7	6-10 years			
	Walls - Concrete Block	2nd Gym Corridor	1,350	SF	6	10+ years			
	Ceiling - Lay-in	Gym Corridor	765	SF	6	10+ years			
	Drinking Fountains - Single Fountain	Gym Corridor	2	EA	5	6-10 years			
	Floor - Tile Ceramic/ Porcelain	Gym Corridor	150	SF	6	10+ years			
	Floor - Tile/Sheet	Gym Corridor	615	SF	7	10+ years			
	Lighting - Lay-in	Gym Corridor	8	EA	7	6-10 years			

Campus Name: Hubbard HS Page : 55 of 60 Assessment Date: 07/24/2019



Catego	ry : Interior		Building : Addition 2						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	Walls - Concrete Block	Gym Corridor	1,458	SF	6	10+ years			
Safety									
,	Metal Dedector	Entire Building	1	EA	7	6-10 years			
	Security Cameras	Entire Building	5	EA	7	6-10 years			
	Security Cameras	Entire Building	1	EA	7	6-10 years			
Stairs									
	Ceiling - Lay-in	North Stair	115	SF	5	10+ years			
	Floor - Tile	North Stair	16	SF	6	10+ years			
	Handrails	North Stair	40	LF	5	10+ years			
	Lighting - Lay-in	North Stair	1	EA	7	6-10 years			
	Lighting - Wall Mounted	North Stair	2	EA	7	6-10 years			
	Stairs - Terrazzo	North Stair	22	LF	6	10+ years			
	Walls - Concrete Block	North Stair	720	SF	6	10+ years			
	Ceiling - Lay-in	South Stair	110	SF	6	10+ years			
	Floor - Tile	South Stair	102	SF	6	10+ years			
	Handrails	South Stair	40	LF	5	10+ years			
	Lighting - Lay-in	South Stair	1	EA	6	6-10 years			
	Lighting - Wall Mounted	South Stair	2	EA	6	6-10 years			
	Stairs - Terrazzo	South Stair	20	LF	6	10+ years			
	Walls - Concrete Block	South Stair	720	SF	6	10+ years			



Catego	ry : Site		В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	7	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	9	EA	7	10+ years	
_Fencing							
	Fencing - Chain Link	Entire Site	770	LF	7	6-10 years	
	Fencing - Chain Link	Entire Site	20	LF	5	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	788	LF	7	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	8	LF	4	0-1 year	Fencing bent.
_Landsca	1						
	Landscape - Grass	Entire Site	36,260	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	2,380	SF	5	0-1 year	Cracking throughout.
	Landscape - Hardscape- Concrete	Entire Site	2,375	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	685	SF	4	0-1 year	Entrance 10 concrete sinking sloped
							into building, potential foundation and
							water issues
	Parkway trees	Entire Site	54	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	1,350	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	250	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	13	SF	4	0-1 year	Broken and cracked.
	Trash Receptacles	Entire Site	2	EA	6	6-10 years	
Parking							
	Surface - Asphalt	Site northwest	17,330	SF	5	10+ years	-
	Surface - Asphalt	Site northwest	6,190	SF	4	0-1 year	Potholes.
	Surface - Concrete	Site northwest	560	SF	6	10+ years	
	Trash Compactor	Site northwest	1	EA	6	10+ years	
_Sidewall	(8						
_Oldowan	Sidewalks - Perimeter Sidewalks	Entire Site	13,620	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	3,310	SF	5	0-1 year	Cracking throughout.
			·			•	
_Signage							
	Flag Pole - Building Mounted Flag Pole	East	1	EA	7	10+ years	
	Marquee - Free Standing Back lighted w/	East	1	EA	7	10+ years	
	LED	_					
	Monument - Building Mounted Cut Letter	East	3	EA	4	0-1 year	Letters loose.
	Sign						





1 It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

Campus Name: Hubbard HS Page: 58 of 60 Assessment Date: 07/24/2019





Classroom Summary					1				
				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Regular Classroom	Regular Classroom	1st Floor	108	108	1,085	186	90	N	Υ
Regular Classroom	Regular Classroom	1st Floor	109	109	770	132	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	770	132	60	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	770	132	60	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	770	132	60	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	770	132	60	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	770	132	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	770	132	60	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	770	132	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	770	132	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	770	132	60	N	Υ
Science	Regular Classroom	3rd Floor	300	300	770	132	60	N	Υ
Science	Regular Classroom	3rd Floor	303	303	770	132	60	N	N
Science	Regular Classroom	3rd Floor	308	308	770	132	60	N	Υ
Science	Science Classroom	3rd Floor	302	302	1,085	198	90	N	N
Science	Science Classroom	3rd Floor	305	305	1,085	198	90	N	Υ
Science	Science Classroom	3rd Floor	307	307	1,085	198	90	N	Υ
Science Lab Level 1	Science Lab Level 1	2nd Floor	210	210	930	80	40	N	Υ
Science Lab Level 1	Science Lab Level 1	3rd Floor	310	310	1,085	198	90	N	N
Special Education	Regular Classroom	1st Floor	110	110	350	66	30	N	N
Special Education	Regular Classroom	2nd Floor	209	208	290	66	30	N	N
Building : Addition 1									
Art Room	Regular Classroom	1st Floor	120	120	1,107	96	48	N	Υ
Art Room	Regular Classroom	3rd Floor	323	323	1,207	144	72	N	Υ
Art Room	Regular Classroom	3rd Floor	325	325	1,120	144	72	N	Υ
Band Room	Regular Classroom	3rd Floor	322	322	1,250	192	96	N	N
Choral Room	Regular Classroom	3rd Floor	320	320	1,107	96	48	N	N
Computer Lab	Computer Lab	1st Floor	116	116	550	72	36	N	N
Computer Lab	Regular Classroom	2nd Floor	216	216	1,107	144	72	N	N
Computer Lab	Regular Classroom	2nd Floor	225	225	1,500	192	96	N	Υ
Computer Lab	Regular Classroom	3rd Floor	313	313	1,120	144	72	N	Υ
Computer Lab	Regular Classroom	3rd Floor	315	315	1,120	144	72	N	Υ
Computer Lab	Regular Classroom	3rd Floor	316	316	1,107	144	72	N	Υ
Computer Lab	Regular Classroom	3rd Floor	318	318	1,120	48	24	N	Υ
Music Room	Regular Classroom	2nd Floor	220	220	1,500	192	96	N	N
Regular Classroom	Other Instructional Use	3rd Floor	314	MR	736	96	48	N	N
Regular Classroom	Regular Classroom	1st Floor	111	111	736	96	48	N	Υ





Classroom Summary

Olassi oom oammary			_	Floor Plan	_	Glazed	Operable		_
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	1st Floor	112	112	736	96	48	N	Υ
Regular Classroom	Regular Classroom	1st Floor	115	115	1,107	144	72	N	Υ
Regular Classroom	Regular Classroom	1st Floor	117	117	736	96	48	N	Υ
Regular Classroom	Regular Classroom	1st Floor	122	122	1,107	144	72	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	211	211	736	96	48	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	212	212	736	96	48	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	213	213	736	96	48	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	214	214	736	96	48	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	215	215	736	96	48	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	217	217	736	96	48	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	218	218	643	96	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	221	222	2,313	252	126	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	223	223	1,120	144	72	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	226	226	736	96	48	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	311	311	736	96	48	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	312	312	736	96	48	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	317	317	736	96	48	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	319	319	736	96	48	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	324	324	375	48	24	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	326	326	736	96	48	N	N
Science Classroom	Regular Classroom	1st Floor	113	113	1,107	144	72	N	N
Science Classroom	Regular Classroom	1st Floor	114	114	550	72	36	N	N