

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1913	4	251,299
Addition (Telpochcalli)	1921	2	40,822
Campus Total			292,121

Catego	Category : Exterior			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1 - Main	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	1 - Main	9	EA	6	10+ years	
	Exterior Doors - Transom Lite	1 - Main	9	EA	6	10+ years	
	Exterior Stairs - Concrete	1 - Main	408	LF	5	1-2 years	Cracking and chipping.
	Stair Handrail - Steel_Stair Handrail	1 - Main	24	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	15 East	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	15 East	3	EA	6	10+ years	
	Exterior Stairs - Concrete	15 East	34	LF	6	10+ years	
	Exterior Stairs - Concrete	15 East	2	LF	5	0-1 year	Cracking and chipping.
	Stair Handrail - Steel_Stair Handrail	15 East	2	LF	6	10+ years	5 11 5
	Exterior Doors - Exterior Steel Door	15 south	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	15 south	3	EA	6	10+ years	
	Exterior Stairs - Concrete	15 south	36	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	15 south	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	2 South	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	2 South	3	EA	6	10+ years	
	Exterior Stairs - Concrete	2 South	52	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	2 South	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	2 west	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	2 west	3	EA	6	10+ years	
	Exterior Stairs - Concrete	2 west	52	LF	6	10+ years	
	Exterior Stairs - Concrete	2 west	4	LF	5	0-1 year	Cracking and chipping.
	Stair Handrail - Steel_Stair Handrail	2 west	3	LF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Exterior Doors - Exterior Steel Door	3 north west	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	3 north west	3	EA	6	10+ years	
	Exterior Stairs - Concrete	3 north west	56	LF	6	10+ years	
	Exterior Stairs - Concrete	3 north west	4	LF	5	0-1 year	Cracking and chipping.
	Stair Handrail - Steel_Stair Handrail	3 north west	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	4 north west	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	5 north	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	6 north	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	East Vault Door 1	1	EA	6	10+ years	
	Exterior Stairs - Concrete	East Vault Door 1	20	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	East Vault Door 2	2	EA	6	10+ years	
	Exterior Stairs - Concrete	East Vault Door 2	36	LF	6	10+ years	
Foundat	ion						
	Foundation - Masonry	Entire Building	1,305	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	251,299	SF	7	10+ years	
ighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	13	EA	7	6-10 years	
Roof Sys	stem						
	Access Ladder - Metal	A - Main Roof	2	EA	7	10+ years	
	Access Ladder - Metal	A - Main Roof	1	EA	5	2-5 years	Old and outdated
	Chimney - Brick Chimney- Concrete/ Mortar Liner	A - Main Roof	20	LF	7	10+ years	
	Coping - Stone	A - Main Roof	1,532	LF	7	10+ years	
	Downspouts - Exterior Downspouts	A - Main Roof	189	LF	7	10+ years	
	Downspouts - Interior Downspouts	A - Main Roof	140	LF	7	10+ years	
	Parapet - 16" - 30" Height	A - Main Roof	896	LF	7	10+ years	
	Parapet - Parapet > 30"	A - Main Roof	636	LF	7	10+ years	
	Roof - Modified Bitumen	A - Main Roof	56,458	SF	7	10+ years	
	Roof Hatch - Metal	A - Main Roof	3	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	A - Main Roof	56,458	SF	7	10+ years	
	Access Ladder - Metal	B	1	EA	7	10+ years	
	Coping - Stone	B	188	LF	7	10+ years	
	Downspouts - Exterior Downspouts	B	10	LF	7	10+ years	
	Parapet - 16" - 30" Height	B	188	LF	7	10+ years	
	Roof - Asphalt Shingle	В	5,810	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	В	5,810	SF	7	10+ years	
	Downspouts - Exterior Downspouts	С	5,810	LF	7	10+ years	
	Roof - Metal	C	25 6,006	SF	7		
				SF		10+ years	
	Roof Structure - Steel with Clay Tile Arch Access Ladder - Metal	C D	6,006 1	SF EA	7 7	10+ years 10+ years	
				ΕA			



Recommend	Catego	ry : Exterior		В	uilding	: Main		
Coping - Metal D 328 LF 7 10+ years Downspotts - Exterior Downspotts D 328 LF 7 10+ years Roof - Modified Bitumen D 328 LF 7 10+ years Roof - Modified Bitumen D 4,992 SF 7 10+ years Coping - Clay Tile E 63 LF 7 10+ years Roof - Modified Bitumen E 5,859 SF 7 10+ years Roof - Modified Bitumen F 780 SF 7 10+ years Roof - Modified Bitumen F 780 SF 7 10+ years Downspouts - Exterior Downspouts G 324 LF 7 10+ years Roof - Modified Bitumen G 3,544 SF 7 10+ years Roof Structure - Steel with Clay Tile Arch G 3,544 SF 7 10+ years Roof - Modified Bitumen H 280 SF 7 10+ years R							Recommend	
Downspouts Exterior Downspouts D 12 LF 7 10+ years Roof - Modified Bitumen D 4,992 SF 7 10+ years Roof Structure - Steel with Clay Tile Arch D 4,992 SF 7 10+ years Parapet - 16' - 30' Height E 63 LF 7 10+ years Roof Structure - Steel with Clay Tile Arch E 15,859 SF 7 10+ years Roof Structure - Steel with Clay Tile Arch F 700 SF 7 10+ years Roof Structure - Steel with Clay Tile Arch G 39 LF 7 10+ years Downspouts - Exterior Downspouts G 39 LF 7 10+ years Downspouts - Exterior Downspouts G 334 SF 7 10+ years Downspouts - Exterior Downspouts H 220 LF 7 10+ years Roof Structure - Steel with Clay Tile Arch G 3344 SF 7 10+ years Downspouts - Exterior Downspouts	Group		Location	Quantity	UOM	Rank	Replacement	Comments
Parapit-16'- 30' HeightD32.8LF710- yearsRoof Mudfied BitumenD4.992SF710- yearsRoof Structure - Steel with Clay Tile ArchD4.992SF710- yearsParapat - 16' - 30' HeightE6.3LF710- yearsRoof Mudfied BitumenE15.859SF710- yearsRoof Mudfied BitumenF780SF710- yearsRoof Mudfied BitumenF780SF710- yearsRoof Structure - Steel with Clay Tile ArchF780SF710- yearsCoping - Clay TileG32LF710- yearsDownspoutsF780SF710- yearsRoof Mudfied BitumenG3.54SF710- yearsRoof Mudfied BitumenG3.54SF710- yearsRoof Structure - Steel with Clay Tile ArchH280SF710- yearsRoof Structure - Steel with Clay Tile ArchH280SF710- yearsRoof Mudfied BitumenH280SF710- yearsRoof Mudfied BitumenI7010- years10- yearsRoof Mudfied BitumenI7010- yearsRoof Mudfied BitumenI7010- yearsRoof Mudfied BitumenI3.354SF710- yearsRoof Mudfied BitumenI3.354SF710- years <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>10+ years</td> <td></td>							10+ years	
Roof - Modified Bitumen D 4.992 House SF 7 10+ years Coping - Clay Tile Parapet - 16* - 30" Height E 63 LF 7 10+ years Roof - Modified Bitumen E 63 LF 7 10+ years Roof - Modified Bitumen E 15.859 SF 7 10+ years Roof Structure - Steel with Clay Tile Arch F 7 10+ years Roof Structure - Steel with Clay Tile Arch F 7 10+ years Downspouts - Exterior Downspouts G 12 LF 7 10+ years Parapet - 16* - 30" Height G 334 SF 7 10+ years Roof Modified Bitumen G 3344 SF 7 10+ years Roof Modified Bitumen H 250 LF 7 10+ years Downspouts - Exterior Downspouts H 260 SF 7 10+ years Roof Structure - Steel with Clay Tile Arch H 280 SF 7 10+ years Downspou								
Roof Structure - Steel with Clay Tile Arch D 4.92 Bit Model SF 7 10+ years Parapet - 16' - 30' Height E 63 LF 7 10+ years Roof - Modified Bitumen E 58.89 SF 7 10+ years Roof - Modified Bitumen F 7800 10+ years 10+ years Roof - Modified Bitumen F 7800 SF 7 10+ years Downspouts - Exterior Downspouts G 39 LF 7 10+ years Boor - Modified Bitumen G 334 SF 7 10+ years Roof - Modified Bitumen G 3343 SF 7 10+ years Roof - Modified Bitumen H 280 SF 7 10+ years Roof Structure - Steel with Clay Tile Arch H 280 SF 7 10+ years Roof Structure - Steel with Clay Tile Arch H 280 SF 7 10+ years Roof Structure - Steel with Clay Tile Arch H 280 SF 7							•	
Coping - Clay TileE63LF710+ yearsParapet - 16" - 30" HeightE15.859SF710+ yearsRoof - Modified BlumenF780SF710+ yearsRoof - Modified BlumenF780SF710+ yearsRoof Structure - Steel with Clay Tile ArchF780SF710+ yearsCoping - Clay TileG39LF710+ yearsDownspouts - Exterior DownspoutsG12LF710+ yearsRoof Structure - Steel with Clay Tile ArchG3344SF710+ yearsRoof Structure - Steel with Clay Tile ArchG3.344SF710+ yearsDownspouts - Exterior DownspoutsH220SF710+ yearsRoof Structure - Steel with Clay Tile ArchH280SF710+ yearsDownspouts - Exterior DownspoutsI40LF710+ yearsRoof Modified BlumenH280SF710+ yearsRoof Modified BlumenI79LF710+ yearsParapet 16" - 30" HeightI79LF710+ yearsRoof Modified BlumenI5,135SF710+ yearsRoof Modified BlumenI5,135SF710+ yearsRoof Modified BlumenI3,338SF710+ yearsRoof Modified BlumenI1,333SF710+ yearsRoof Mo								
Parapet-16*-20*HeightE63LF710+ yearsRoof Modified BitumenF5,859SF710+ yearsRoof Structure - Steel with Clay Tile ArchF780SF710+ yearsRoof Structure - Steel with Clay Tile ArchF780SF710+ yearsDownspouts - Exterior DownspoutsG39LF710+ yearsDownspouts - Exterior DownspoutsG38LF710+ yearsRoof - Modified BitumenG334SF710+ yearsRoof - Modified BitumenG3344SF710+ yearsRoof - Modified BitumenG3344SF710+ yearsRoof - Modified BitumenH280SF710+ yearsRoof Structure - Steel with Clay Tile ArchH280SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
Roof - Modified BitumenE15,859SF710+ yearsRoof - Modified BitumenF780SF710+ yearsRoof Structure - Steel with Clay Tile ArchF780SF710+ yearsDownspouts - Exterior DownspoutsG12LF710+ yearsDownspouts - Exterior DownspoutsG39LF710+ yearsRoof Structure - Steel with Clay Tile ArchG39LF710+ yearsRoof - Modified BitumenG3,354SF710+ yearsRoof Structure - Steel with Clay Tile ArchG3,354SF710+ yearsDownspouts - Exterior DownspoutsH280SF710+ yearsRoof Structure - Steel with Clay Tile ArchH280SF710+ yearsDownspouts - Exterior DownspoutsI40LF710+ yearsRoof - Modified BitumenI79LF710+ yearsDownspouts - Exterior DownspoutsI40LF710+ yearsRoof - Modified BitumenI5135SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof - Modified BitumenL18,33SF								
Roof Structure - Steel with Clay Tile ArchE5859SF710+ yearsRoof Modified BitumenF780SF710+ yearsDownspouts- Exterior DownspoutsG12LF710+ yearsDownspouts - Exterior DownspoutsG12LF710+ yearsParapet - 16' - 30' HeightG39LF710+ yearsRoof Modified BitumenG3364SF710+ yearsDownspouts - Exterior DownspoutsH25LF710+ yearsRoof Modified BitumenH280SF710+ yearsRoof Structure - Steel with Clay Tile ArchH280SF710+ yearsRoof Modified BitumenI5135SF710+ yearsRoof Modified BitumenI5135SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3638SF710+ yearsRoof Modified BitumenJ3638SF710+ yearsRoof Modified BitumenL18.4710+ years10+ yearsRoof Modified Bitume								
Roof -Modified BitumenF780SF710+ yearsRoof Structure - Steel with Clay TileG39LF710+ yearsDownspouts - Exterior DownspoutsG12LF710+ yearsParapet - 16' - 30' HeightG39LF710+ yearsRoof - Modified BitumenG3364SF710+ yearsRoof - Modified BitumenG3364SF710+ yearsRoof - Modified BitumenH280SF710+ yearsRoof Structure - Steel with Clay Tile ArchH280SF710+ yearsRoof Structure - Steel with Clay Tile ArchH280SF710+ yearsDownspouts - Exterior DownspoutsI40LF710+ yearsParapet - 16' - 30' HeightI79LF710+ yearsDownspouts - Exterior DownspoutsI40LF710+ yearsParapet - 16' - 30' HeightI79LF710+ yearsRoof Structure - Steel with Clay Tile Arch36.38SF710+ yearsRoof Structure - Steel with Clay Tile Arch36.38SF710+ yearsRoof Structure - Steel with Clay Tile Arch1EA710+ yearsRoof Structure - Steel with Clay Tile Arch20LF710+ yearsRoof Structure - Steel with Clay Tile Arch1EA710+ yearsRoof Structure - Steel with Clay Tile Arch118.33 </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
Roof Structure - Steel with Clay Tile ArchF780SF710 - yearsDownspouts - Exterior DownspoutsG12LF710 - yearsParapet - 16' - 30' HeightG39LF710 - yearsRoof - Modified BitumenG3,354SF710 - yearsDownspouts - Exterior DownspoutsG3,354SF710 - yearsDownspouts - Exterior DownspoutsH25LF710 - yearsDownspouts - Exterior DownspoutsH280SF710 - yearsRoof - Modified BitumenH280SF710 - yearsRoof - Modified BitumenH280SF710 - yearsRoof - Modified BitumenH280SF710 - yearsDownspouts - Exterior DownspoutsI40LF710 - yearsParapet - 16' - 30' HeightI79LF710 - yearsRoof - Modified BitumenI5135SF710 - yearsRoof - Modified BitumenJ3,638SF710 - yearsRoof - Modified BitumenJ3,638SF710 - yearsRoof - Modified BitumenK20LF710 - yearsRoo								
Coping - Clay TileG39LF710+ yearsDownspouts - Exterior DownspoutsG39LF710+ yearsRoof - Modified BitumenG3,354SF710+ yearsRoof Structure - Steel with Clay Tile ArchG3,354SF710+ yearsDownspouts - Exterior DownspoutsH25LF710+ yearsRoof - Modified BitumenH280SF710+ yearsRoof - Modified BitumenH280SF710+ yearsRoof - Modified BitumenH280SF710+ yearsDownspouts - Exterior DownspoutsI40LF710+ yearsParapet - 16* - 30* HeightI79LF710+ yearsRoof - Modified BitumenJ5,135SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof - Modified BitumenK20LF710+ yearsRoof - Modified BitumenK20LF710+ yearsRoof - Modified BitumenK <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>10+ years</td> <td></td>							10+ years	
DownspoutsC typeC12LF710+ yearsParapet -16" - 30" HeightG3,354SF710+ yearsRoof Modified BitumenG3,354SF710+ yearsDownspouts- Steel with Clay Tile ArchG3,354SF710+ yearsDownspoutsSteterior DownspoutsH280SF710+ yearsRoof - Modified BitumenH280SF710+ yearsRoof Structure - Steel with Clay Tile ArchH280SF710+ yearsDownspoutsI79LF710+ yearsCoping - Clay TileI79LF710+ yearsDownspoutsI40LF710+ yearsRoof - Modified BitumenI5,135SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof - Modified BitumenK20LF710+ yearsRoof - Modified BitumenL1,833SF								
Parapet - 16" - 30" HeightG39LF710- yearsRoof Modified BitumenG3,354SF710- yearsRoof Structure - Steel with Clay Tile ArchG3,354SF710- yearsRoof - Modified BitumenH280SF710- yearsRoof - Modified BitumenH280SF710- yearsCoping - Clay TileH280SF710- yearsDownspouts - Exterior DownspoutsI40LF710- yearsDownspouts - Exterior DownspoutsI40LF710- yearsRoof - Modified BitumenI5,135SF710- yearsRoof - Modified BitumenJ3,638SF710- yearsRoof Structure - Steel with Clay Tile ArchI5,135SF710- yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710- yearsRoof Structure - Steel with Clay Tile ArchK20LF710- yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710- yearsRoo								
Roof - Modified BitumenG3.354SF710- yearsRoof Structure - Steel with Clay Tile ArchG3.354SF710+ yearsBornspouts - Exterior DownspoutsH280SF710+ yearsRoof Structure - Steel with Clay Tile ArchH280SF710+ yearsCoping - Clay TileI79LF710+ yearsDownspouts - Exterior DownspoutsI79LF710+ yearsParapet - 16" - 30" HeightI79LF710+ yearsRoof Structure - Steel with Clay Tile ArchI5, 135SF710+ yearsRoof Structure - Steel with Clay Tile ArchI5, 135SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1EA710+ yearsRoof Structure - Steel with Clay Tile ArchK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof - Modified BitumenL1,833SF </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
Roof Structure - Steel with Clay Tile ArchG3,354SF710+ yearsDownspouts - Exterior DownspoutsH280SF710+ yearsRoof - Modified BitumenH280SF710+ yearsCoping - Clay TileI79LF710+ yearsDownspouts - Exterior DownspoutsI40LF710+ yearsDownspouts - Exterior DownspoutsI79LF710+ yearsParapet - 16' - 30'' HeightI79LF710+ yearsRoof - Modified BitumenI5,135SF710+ yearsRoof Structure - Steel with Clay Tile ArchI5,135SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsRoof - Modified BitumenK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile						7	10+ years	
DownspoutsExterior DownspoutsH25LF710+ yearsRoof - Modified BitumenH280SF710+ yearsCoping - Clay TileI79LF710+ yearsDownspouts - Exterior DownspoutsI79LF710+ yearsParapet - 16" - 30" HeightI79LF710+ yearsRoof - Modified BitumenI5,135SF710+ yearsRoof Structure - Steel with Clay Tile ArchI5,135SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchK20LF710+ yearsParapet - 16" - 30" HeightK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF7 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
Roof - Modified BitumenH280SF710+ yearsRoof Structure - Steel with Clay Tile ArchH280SF710+ yearsDownspouts - Exterior DownspoutsI79LF710+ yearsParapet - 16" - 30" HeightI79LF710+ yearsRoof - Modified BitumenI5,135SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsAccess Ladder - MetalK20LF710+ yearsRoof - Modified BitumenK20LF710+ yearsParapet - 16" - 30" HeightK20LF710+ yearsRoof - Modified BitumenK650SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof - Modified BitumenM17LF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof - Modified BitumenM77LF710+ yearsRoof - Modified BitumenM72LF710+ yearsRoof - Modified BitumenM </td <td></td> <td>Roof Structure - Steel with Clay Tile Arch</td> <td></td> <td></td> <td></td> <td>7</td> <td>10+ years</td> <td></td>		Roof Structure - Steel with Clay Tile Arch				7	10+ years	
Roof Structure - Steel with Clay Tile ArchH280SF710+ yearsCoping - Clay TileI79LF710+ yearsDownspouts - Exterior DownspoutsI40LF710+ yearsParapet - 16" - 30" HeightI5,135SF710+ yearsRoof - Modified BitumenI5,135SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsAccess Ladder - MetalK20LF710+ yearsCoping - Clay TileK20LF710+ yearsParapet - 16" - 30" HeightK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Modified BitumenL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchM72SF710+ yearsRoof Structure		Downspouts - Exterior Downspouts	Н	25		7	10+ years	
Coping - Clay TileI79LF710- yearsDownspouts - Exterior DownspoutsI40LF710+ yearsParapet - 16" - 30" HeightI79LF710+ yearsRoof - Modified BitumenI5,135SF710+ yearsRoof Structure - Steel with Clay Tile ArchI5,135SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsAccess Ladder - MetalK1EA710+ yearsCoping - Clay TileK20LF710+ yearsParapet - 16" - 30" HeightK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchM17LF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof - Modified BitumenM20<		Roof - Modified Bitumen	Н	280	SF	7	10+ years	
Downspouts- Exterior DownspoutsI40LF710+ yearsParapet - 16' - 30'' HeightI79LF710+ yearsRoof - Modified Bitumen15,135SF710+ yearsRoof Structure - Steel with Clay Tile ArchI5,135SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsAccess Ladder - MetalK1EA710+ yearsCoping - Clay TileK20LF710+ yearsParapet - 16' - 30'' HeightK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Modified BitumenL1,833SF710+ yearsRoof Modified BitumenL1,833SF710+ yearsRoof Modified BitumenM17LF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchM20LF710+ yearsRoof Structure - Steel with Clay Tile ArchN20LF710+ yearsRoof S		Roof Structure - Steel with Clay Tile Arch	Н	280	SF	7	10+ years	
Parapet - 16" - 30" HeightI79LF710+ yearsRoof - Modified BitumenI5,135SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsCoping - Clay TileK20LF710+ yearsParapet - 16" - 30" HeightK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchM17LF710+ yearsRoof - Modified BitumenM17LF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof - Modified BitumenN275SF710+ yearsRoof - Modified BitumenN275SF710+ yearsRoof - Medified BitumenN </td <td></td> <td>Coping - Clay Tile</td> <td>I</td> <td>79</td> <td>LF</td> <td>7</td> <td>10+ years</td> <td></td>		Coping - Clay Tile	I	79	LF	7	10+ years	
Roof - Modified BitumenI5,135SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsRoof Structure - Steel with Clay TileK1EA710+ yearsAccess Ladder - MetalK1EA710+ yearsCoping - Clay TileK20LF710+ yearsParapet - 16" - 30" HeightK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchM17LF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof Structure - Steel with Clay Tile Arch		Downspouts - Exterior Downspouts	I	40	LF	7	10+ years	
Roof Structure - Steel with Clay Tile ArchI5,135SF710+ yearsRoof - Modified BitumenJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsAccess Ladder - MetalK1EA710+ yearsCoping - Clay TileK20LF710+ yearsParapet - 16' - 30" HeightK20LF710+ yearsRoof - Modified BitumenK650SF710+ yearsRoof - Modified BitumenK650SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsCoping - Clay TileM17LF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof - Modified BitumenN20LF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsRoof - Modified BitumenN275SF710+ yearsRoof - Modified BitumenN275SF710+ yearsRoof - Modified BitumenQ2,707SF710+ yearsRoof - Modified B		Parapet - 16" - 30" Height	I	79	LF	7	10+ years	
Roof - Modified BitumenJ3,638SF710+ yearsRoof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsAccess Ladder - MetalK1EA710+ yearsCoping - Clay TileK20LF710+ yearsParapet - 16" - 30" HeightK20LF710+ yearsRoof - Modified BitumenK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof - Modified BitumenM17LF710+ yearsRoof Structure - Steel with Clay Tile ArchM17LF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof - Modified BitumenN275SF710+ yearsRoof - MetalN275SF710+ yearsRoof - MetalN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenQ2,707SF710+ yearsRoof - Modified BitumenP </td <td></td> <td>Roof - Modified Bitumen</td> <td>I</td> <td>5,135</td> <td></td> <td>7</td> <td>10+ years</td> <td></td>		Roof - Modified Bitumen	I	5,135		7	10+ years	
Roof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsAccess Ladder - MetalK1EA710+ yearsCoping - Clay TileK20LF710+ yearsParapet - 16" - 30" HeightK20LF710+ yearsRoof - Modified BitumenK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchK17LF710+ yearsRoof Structure - Steel with Clay Tile ArchM17LF710+ yearsParapet - 16" - 30" HeightM17LF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsRoof - Modified BitumenM20LF710+ yearsRoof - MetalN275SF710+ yearsRoof - MetalN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenO2,707SF710+ yea		Roof Structure - Steel with Clay Tile Arch	I	5,135	SF	7	10+ years	
Roof Structure - Steel with Clay Tile ArchJ3,638SF710+ yearsAccess Ladder - MetalK1EA710+ yearsCoping - Clay TileK20LF710+ yearsParapet - 16" - 30" HeightK20LF710+ yearsRoof - Modified BitumenK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchM17LF710+ yearsRoof Structure - Steel with Clay Tile ArchM17LF710+ yearsRoof Structure - Steel with Clay Tile ArchM17LF710+ yearsRoof - Modified BitumenM17LF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsRoof - Medified BitumenN20LF710+ yearsRoof - MetalN275SF710+ yearsRoof - MetalN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenQ2,707SF710+ yearsRoof - Modified BitumenP2,707SF710+ years		Roof - Modified Bitumen	J	3,638	SF	7	10+ years	
Access Ladder - MetalK1EA710+ yearsCoping - Clay TileK20LF710+ yearsParapet - 16" - 30" HeightK20LF710+ yearsRoof - Modified BitumenK20LF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchM17LF710+ yearsRoof Structure - Steel with Clay Tile ArchM17LF710+ yearsParapet - 16" - 30" HeightM17LF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsRoof - MetalN275SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ yearsRoof - Modified BitumenP936		Roof Structure - Steel with Clay Tile Arch	J	3,638	SF	7		
Parapet - 16" - 30" HeightK20LF710+ yearsRoof - Modified BitumenK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchM17LF710+ yearsParapet - 16" - 30" HeightM17LF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsRoof - Modified BitumenN275SF710+ yearsRoof - MetalN275SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ yearsRoof - Modified BitumenP936SF710+ years			К		EA	7		
Parapet - 16" - 30" HeightK20LF710+ yearsRoof - Modified BitumenK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsCoping - Clay TileM17LF710+ yearsParapet - 16" - 30" HeightM17LF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchM20LF710+ yearsRoof - Modified BitumenM275SF710+ yearsRoof - Modified BitumenN275SF710+ yearsRoof - MetalN275SF710+ yearsRoof - MetalN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ yearsRoof - Modified BitumenP936SF710+ years		Coping - Clay Tile	K	20	LF	7	10+ years	
Roof - Modified BitumenK650SF710+ yearsRoof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsCoping - Clay TileM17LF710+ yearsParapet - 16" - 30" HeightM17LF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsDownspouts - Exterior DownspoutsN20LF710+ yearsRoof - MetalN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - MetalN275SF710+ yearsRoof - MetalN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ yearsRoof - Modified BitumenP936SF710+ years			K	20	LF	7		
Roof Structure - Steel with Clay Tile ArchK650SF710+ yearsRoof - Modified BitumenL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsCoping - Clay TileM17LF710+ yearsParapet - 16" - 30" HeightM17LF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsDownspouts - Exterior DownspoutsN20LF710+ yearsRoof - Medified BitumenN275SF710+ yearsRoof - MetalN275SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ yearsRoof - Modified BitumenP936SF710+ years			К		SF	7	•	
Roof - Modified BitumenL1,833SF710+ yearsRoof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsCoping - Clay TileM17LF710+ yearsParapet - 16" - 30" HeightM17LF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsDownspouts - Exterior DownspoutsN20LF710+ yearsRoof - MetalN275SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ yearsRoof - Modified BitumenP936SF710+ years		Roof Structure - Steel with Clay Tile Arch	K	650	SF	7	10+ years	
Roof Structure - Steel with Clay Tile ArchL1,833SF710+ yearsCoping - Clay TileM17LF710+ yearsParapet - 16" - 30" HeightM17LF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsDownspouts - Exterior DownspoutsN20LF710+ yearsRoof - MetalN275SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof - MetalN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ years		-	L	1,833	SF	7	-	
Coping - Clay TileM17LF710+ yearsParapet - 16" - 30" HeightM17LF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsDownspouts - Exterior DownspoutsN20LF710+ yearsRoof - MetalN275SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ years			L		SF			
Parapet - 16" - 30" HeightM17LF710+ yearsRoof - Modified BitumenM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsDownspouts - Exterior DownspoutsN20LF710+ yearsRoof - MetalN275SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ years								
Roof - Modified BitumenM782SF710+ yearsRoof Structure - Steel with Clay Tile ArchM782SF710+ yearsDownspouts - Exterior DownspoutsN20LF710+ yearsRoof - MetalN275SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ years			Μ	17	LF		•	
Roof Structure - Steel with Clay Tile ArchM782SF710+ yearsDownspouts - Exterior DownspoutsN20LF710+ yearsRoof - MetalN275SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ years			М		SF			
DownspoutsExterior DownspoutsN20LF710+ yearsRoof - MetalN275SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ years								
Roof - MetalN275SF710+ yearsRoof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ years					-			
Roof Structure - Steel with Clay Tile ArchN275SF710+ yearsRoof - Modified BitumenO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ years							•	
Roof - Modified BitumenO2,707SF710+ yearsRoof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ years								
Roof Structure - Steel with Clay Tile ArchO2,707SF710+ yearsRoof - Modified BitumenP936SF710+ years		•					•	
Roof - Modified Bitumen P 936 SF 7 10+ years							,	
					-			
					-			
			-	550	0.	,	ie. youro	



Catego	ry : Exterior		В	uilding	: Main		· · · · · · · · · · · · · · · · · · ·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Malla							
Walls	Cheek-Wall - Stone	Entire Building	360	SF	7	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	1,541	LF	7	10+ years	
	Exterior Walls - Brick	Entire Building	78,370	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	19,555	SF	7	10+ years	
	Exterior Walls - Stucco	Entire Building	850	SF	7	10+ years	
		-				-	
Windows							
	Guard - Guards perforated	Entire Building	7,752	SF	7	10+ years	
	Lintels - Brick	Entire Building	24	LF	7	10+ years	
	Lintels - Steel	Entire Building	2,460	LF	7	10+ years	
	Skylite - Glass Double-Pane	Entire Building	1,375	SF	7	10+ years	
	Windows - Decorative	Entire Building	288	SF SF	7	10+ years	
	Windows - Louver Windows - Sash Aluminum Double-pane	Entire Building Entire Building	144 28,664	SF	7 7	10+ years 10+ years	
	Windows - Sash Aluminum Double-pane	Entite Building	20,004	эг	/	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	3	EA	6	10+ years	
	Exit Signs - Auditoium	Entire Building	16	EA	5	2-5 years	
	Exit Signs - Corridors and Stairs	Entire Building	54	EA	5	2-5 years	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	4	0-1 year	Not illuminated at time of assessment
	Exit Signs - Gym	Entire Building	8	EA	5	2-5 years	
	Exit Signs - Lunchroom	Entire Building	4	EA	5	2-5 years	
	Exit Signs - Pool	Entire Building	4	EA	5	2-5 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	8,576	SF	6	10+ years	
	Emergency A/C Power - Corridors and	Entire Building	43,017	SF	6	10+ years	
	Stairs	Entire Building	-0,017	01	0	TO+ years	
	Emergency A/C Power - Gym	Entire Building	16,083	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	12,000	SF	6	10+ years	
	Emergency A/C Power - Multipurpose	Entire Building	3,199	SF	6	10+ years	
	Room	C C				·	
	Emergency A/C Power - Pool	Entire Building	3,613	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	4,850	SF	6	10+ years	
	Security System - CCTV	Entire Building	251,299	SF	6	6-10 years	Serves main and addition
	Security System - Intrusion Detection	Entire Building	251,299	SF	6	6-10 years	One system for main and addition
	Emergency Battery Packs - Pool	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	7	6-10 years	
	Emergency Generator- Outdoor- Natural	Site - East	1	EA	6	6-10 years	



Catego	ry : Electrical		B	uilding	: Main		i0 W 24th BOULEVARD, Chicago, IL 60623
Gulogo				anang		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas - 151 - 200 KW						
Main Se							
	Main Electrical Service - 2000 A	Electrical Room	1	EA	6	2-5 years	
	120/240/3PH Main Floating Service Creater than 2000	Electrical Beam	1	EA	6		Single phase 2401/
	Main Electrical Service - Greater than 3000 A 120/240/3PH	Electrical Room	I	EA	6	2-5 years	Single phase 240V
	Independent Electrical Service for	Electrical Room	1	EA	6	10+ years	
	emergency power				-	,	
	PA System	Entire Building	251,299	SF	4	1-2 years	Serves main only, System is old, has problems in some rooms and needs continuous attention, many repairs have been made to speakers and wiring, engineer has a PO for a diagnostic assessment
_Power D	Distribution						
	Lighting and Power Panels - 100 A	Mechanical Room	18	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Mechanical Room	1	EA	6	6-10 years	Panel is blocked by storage rack
	Lighting and Power Panels - 100 A	Mechanical Room	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Mechanical Room	1	EA	4	2-5 years	Fuse box older than 40 years
	Lighting and Power Panels - 100 A	Mechanical Room	1	EA	4	0-1 year	Not labeled, taped-on breakers are evidence of nuisance trips, electrical tape used to block empty breaker bays
	Lighting and Power Panels - Above 100 A	Mechanical Room	5	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Mechanical Room	1	EA	4	2-5 years	Fuse box older than 40 years
	Lighting and Power Panels - Above 100 A	Mechanical Room	1	EA	4	0-1 year	Live front fuse panel older than 40 y. o.
	Lighting and Power Panels - Above 100 A	Mechanical Room	1	EA	4	0-1 year	Live front circuit breaker panel
	Lighting and Power Panels - Above 100 A	Mechanical Room	1	EA	4	0-1 year	Live front fuse panel older than 40 y.
	Lighting and Power Panels - Above 100 A	Mechanical Room	1	EA	4	0-1 year	Live front fuse panel older than 40 y. o., latch broken cover can't be secured
	Lighting and Power Panels - Above 100 A	Mechanical Room	1	EA	3	0-1 year	Live front fuse panel older than 40 y. o., blocked by storage rack, significant corrosion on contacts
	Lighting and Power Panels - Above 100 A	Mechanical Room	3	EA	3	0-1 year	Live front fuse panel older than 40 y. o.,
	Main Distribution Panels - 400 - 600 amp	Mechanical Room	6	EA	7	6-10 years	,
	Main Distribution Panels - 400 - 600 amp	Mechanical Room	1	EA	4	1-2 years	Significant rust on all components, missing breaker handle
	Main Distribution Panels - 400 - 600 amp	Mechanical Room	1	EA	4	1-2 years	Nuisance trips becoming more



Catego	ry : Electrical		B	uilding	: Main		
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Main Distribution Panels - 400 - 600 amp	Mechanical Room	1	EA	2	0-1 year	frequent as kitchen equipment ages, possibly undersized for the load Live front fuse box greater than 40 y. o., nearly caught fire last year per onsite POC, turned off and not currently in use
	Transformers - 120/240 - 120/208	Mechanical Room	1	EA	6	10+ years	
	Transformers - 120/240 - 120/208	Mechanical Room	1	EA	4	2-5 years	Archaic 220 - 240 type
	Transformers - 277/480 - 120/240	Mechanical Room	1	EA	6	2-5 years	
					-	,	
Catego	ry : Fire Protection		В	uilding	: Main		
_			-			Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar				F A	0	4.0	
	Fire Alarm Panel	Electrical Room	1	EA	3	1-2 years	Serves main and addition, panel in trouble alarm
	Fire Alarm_System	Electrical Room	251,299	SF	4	1-2 years	No strobes, panel in trouble
				0.	·)	
Catego	ry : Mechanical		В	uilding	: Main		
0	Hama Tama		Owentites		Daula	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	Condensing Unit- Roof Mounted - Less	Roof	4	EA	6	10, , , , , , , , , , , , , , , , , , ,	
	than 5 tons	ROOI	4	EA	0	10+ years	
Air Hand	lling Systems						
	Fan Coil Unit- Celing Mounted - Electric	1st Floor	4	EA	6	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm	1st Floor - AHU-1	1	EA	4	0-1 year	AHU1 serves classrooms in SE all floors and S of gym 1, coil leaks and/or coils that are valved off and cannot be used due to leaks, steam valve leaks external to valves, condensate pipe leaks, rusty fan shaft, old motor
	Air Intake	1st Floor - AHU-1	1	EA	4	0-1 year	No filters on intake, most outdoor air dampers are stuck either open or closed with no way to control them
	Auxiliaries - 30001 - 45000 cfm	1st Floor - AHU-1	1	EA	4	0-1 year	Bypass dampers blocked open, pneumatic controls defunct, floor cracked and heaving, clutter in plenum chambers, hot deck access door crashes into directional fin in west chamber, hole in wall of west



Group

Maria Saucedo Elementary Scholastic Academy 2850 W 24th BOULEVARD, Chicago, IL 60623

Building : Main Category : Mechanical Recommend Item - Type Location Quantity UOM Rank Replacement Comments warm deck metal wall, floor plates loose and wobbly Return Duct Work - Indoor- Vertical Shaft 1st Floor - AHU-1 100 LF 5 10+ years and Ducts Zone Dampers 1st Floor - AHU-1 23 ΕA 4 0-1 year Fully manual control, pneumatics are defunct, many dampers blocked with wood blocks, bent damper blades, peeling paint on dampers, at least one damper blade broken free from housina 1st Floor - AHU-2 1 ΕA 0-1 year AHU2 serves classrooms in SW all Air Handling Unit- Built Up-Multi Zone-4 Double Delivery- Steam Coils - 30001 floors, W library, and pool, rust in 45000 cfm bottom of fan housing evidence of seepage, coil leaks and/or coils that are valved off and cannot be used due to leaks, steam valve leaks external to valves, condensate pipe leaks, rusty fan shaft, old motor Air Intake 1st Floor - AHU-2 ΕA No filters on intake, most outdoor air 1 4 0-1 year dampers are stuck either open or closed with no way to control them per onsite POC Auxiliaries - 30001 - 45000 cfm 1st Floor - AHU-2 1 EΑ 4 0-1 year Rotten wood access door, Bypass dampers blocked open, pneumatic controls defunct, floor cracked and heaving, clutter in plenum chambers. floor plates loose and wobbly 1st Floor - AHU-2 100 LF Return Duct Work - Indoor- Vertical Shaft 5 10+ years and Ducts Zone Dampers 1st Floor - AHU-2 24 ΕA 4 0-1 year Fully manual control, pneumatics are defunct, many dampers blocked with wood blocks, bent damper blades. peeling paint on dampers, at least one damper blade broken free from housing ΕA Air Handling Unit- Built Up-Multi Zone-1st Floor - AHU-3 1 4 0-1 year AHU3 serves classrooms in NW all floors, and girls locker room, coil Double Delivery- Steam Coils - 30001 -45000 cfm leaks and/or coils that are valved off and cannot be used due to leaks. steam valve leaks external to valves. condensate pipe leaks, rusty fan shaft, old motor. Air Intake 1st Floor - AHU-3 1 ΕA 4 0-1 year No filters on intake, most outdoor air dampers are stuck either open or



Catego	ry : Mechanical		B	Building	: Main	2030 W 24th DOOLE VARD, Chicago, ie 00023		
_			-			Recommend	• ·	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments closed with no way to control them per onsite POC	
	Auxiliaries - 30001 - 45000 cfm	1st Floor - AHU-3	1	EA	4	0-1 year	Bypass dampers blocked open, pneumatic controls defunct, floor cracked and heaving, clutter in plenum chambers, rusty mechanical pipes under coils, valve handles missing or removed, wood doors rotted, plenum sheet metal housings starting to come apart	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	1st Floor - AHU-3	100	LF	5	10+ years	3 1 1 1	
	Zone Dampers	1st Floor - AHU-3	27	EA	4	0-1 year	Fully manual control, pneumatics are defunct, many dampers blocked with wood blocks, bent damper blades, peeling paint on dampers, at least one damper blade broken free from housing	
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm	1st Floor - AHU-4	1	EA	4	0-1 year	AHU4 serves classrooms in NE all floors cafeteria East and gym 1 north, leaks and/or coils that are valved off and cannot be used due to leaks, steam valve leaks external to valves, condensate pipe leaks, rusty fan shaft, old motor	
	Air Intake	1st Floor - AHU-4	1	EA	4	0-1 year	No filters on intake, most outdoor air dampers are stuck either open or closed with no way to control them per onsite POC	
	Auxiliaries - 30001 - 45000 cfm	1st Floor - AHU-4	1	EA	4	0-1 year	Bypass dampers blocked open, pneumatic controls defunct, small section of masonry crumbling, clutter in plenum chambers, sheet metal plenum housing coming apart	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	1st Floor - AHU-4	100	LF	5	10+ years		
	Zone Dampers	1st Floor - AHU-4	25	EA	4	0-1 year	Fully manual control, pneumatics are defunct, many dampers blocked with wood blocks, bent damper blades, peeling paint on dampers, at least one damper blade broken free from housing	
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm	Attic	1	EA	5	2-5 years	NE attic serves gym 2	



Catego	ategory : Mechanical		В	Building : Main					
	-					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Air Intake Indoor Return Fans- Centrifugal Squirrel	Attic	1	EA EA	4 5	0-1 year 2-5 years	Outdoor air dampers are stuck open or closed with no control per POC, filters missing from frame Serves AHU in NE attic		
	Cage - Less than 5000 CFM					-			
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mezzanine - AHU-5	1	EA	4	0-1 year	AHU5 serves 1st floor corridors and classrooms on north hall, west side, coil leaks and/or coils that are valved off and cannot be used due to leaks, steam valve leaks external to valves, condensate pipe leaks		
	Air Intake	Mezzanine - AHU-5	1	EA	4	0-1 year	No filters on intake, most outdoor air dampers are stuck either open or closed with no way to control them, AHU 5, 6, and 7 intakes are separated only by wooden doors		
	Auxiliaries - 15001 - 25000 cfm	Mezzanine - AHU-5	1	EA	4	0-1 year	Bypass dampers removed, pneumatic controls defunct, peeling paint, hole in fan outlet housing sheet metal, bypass damper in plenum room stuck closed		
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mezzanine - AHU-5	1	LF	5	10+ years			
	Zone Dampers	Mezzanine - AHU-5	9	EA	5	2-5 years	Fully manual control, pneumatics are defunct		
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mezzanine - AHU-6	1	EA	4	0-1 year	AHU6 serves corridors and classrooms on 1st floor north hallway, east side, coil leaks and/or coils that are valved off and cannot be used due to leaks, steam valve leaks external to valves, condensate pipe leaks		
	Air Intake	Mezzanine - AHU-6	1	EA	4	0-1 year	No filters on intake, most outdoor air dampers are stuck either open or closed with no way to control them, AHU 5, 6, and 7 intakes are separated only by wooden doors		
	Auxiliaries - 15001 - 25000 cfm	Mezzanine - AHU-6	1	EA	4	0-1 year	Bypass dampers stuck open, pneumatic controls defunct, peeling paint from fan housing, plenum chamber bypass damper stuck closed		
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mezzanine - AHU-6	1	LF	5	10+ years			
	Zone Dampers	Mezzanine - AHU-6	9	EA	5	2-5 years	Fully manual control, pneumatics are		



Group

Category : Mechanical

Maria Saucedo Elementary Scholastic Academy 2850 W 24th BOULEVARD, Chicago, IL 60623

Recommend Item - Type Location Quantity UOM Rank Replacement Comments defunct Air Handling Unit- Built Up- Single Zone-ΕA Mezzanine - AHU-7 4 0-1 year AHU7 serves auditorium, coil leaks 1 Steam Coils - 25001 - 35000 cfm and/or coils that are valved off and cannot be used due to leaks, steam valve leaks external to valves, condensate pipe leaks, steam valve fills bucket twice daily when heating system is operating Air Intake Mezzanine - AHU-7 1 ΕA 4 0-1 year No filters on intake, most outdoor air dampers are stuck either open or closed with no way to control them. AHU 5, 6, and 7 intakes are separated only by wooden doors Auxiliaries - 25001 - 35000 cfm Mezzanine - AHU-7 1 EΑ 4 0-1 year Bypass dampers blocked open, pneumatic controls defunct Return Duct Work - Indoor- Vertical Shaft Mezzanine - AHU-7 LF 100 5 10+ years and Ducts Roof Top Unit-Single Zone-Roof Mounted-Roof 2 ΕA 6 10+ years Serve orchestra room DX Cooling Only with Self Contained Compressor - Less than 5 tons Boiler Systems FΑ Condensate Pump Entire Building 1 5 6-10 years One pump has been removed and blinded off Condensate Pump Entire Building 1 EA 5 2-5 years **Condensate Pump** ΕA 1-2 years Entire Building 1 4 Pump housings heavily degraded, one pump is disconnected from return pipe EΑ One pump has been removed and Condensate Pump Entire Building 1 3 0-1 year blinded off, housing leaking onto floor, heavy rust on pump LF Lots of condensate leaks, especially Piping - Condensate Pipe- Steel 1.500 3 Entire Building 1-2 years in pipe tunnels per onsite POC, lots of pipe clamps Piping - Steam Pipe- Steel LF 5 2-5 years Entire Building 1,500 Steam Traps Entire Building 160 EΑ 6 2-5 years Heating Devices Radiators - Steam 2nd Floor ΕA 5 6-10 years 1 5 LF Fin Tube - Steam Entire Building 22 6-10 years 5 ΕA 5 Unit Heater - Steam Entire Building 2-5 years Wall Heater - Electric Entire Building 6 ΕA 5 2-5 years Wall Heater - Electric Entire Building 1 ΕA 4 1-2 years Old, cover off, fins bent,

Building : Main

Wall Heater - Electric

1

ΕA

2

0-1 year

Entire Building

Cover off, fan missing, pull box



Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
							scorched
Tempera	ature Control						
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	Serve rooms 143 and 144 FCUs
	Pneumatic System	Entire Building	241,402	SF	3	0-1 year	Connected to compressor in addition system doesn't hold pressure and is totally inoperable, heating control is completely manual
	Thermostats - Pneumatic	Entire Building	121	EA	4	0-1 year	System doesn't hold pressure, thermostats are nonfunctional
Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	5	2-5 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	4	1-2 years	Excessive vibration, significant fan housing rust
	Exhaust Fans- Indoor - Greater than 8000 CFM	Entire Building	1	EA	5	2-5 years	3 1 1
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	5	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	High roof
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	2	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	4	0-1 year	Housing severely damaged in recer storm
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	5	6-10 years	Buzzing noise
	Roof Mounted Duct Work	Entire Building	50	LF	6	6-10 years	Minor denting and ponding
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No suppression, very old hood
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wat							
	Electric Heater - Less than 20 KW	1st Floor	1	EA	6	10+ years	Serves rooms 143, 144, student toilets



Catego	Category : Plumbing		В	uilding	: Main			
			•			Recommend	0	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Piping	Domestic Piping-Cold Water Horizontal Lines	Entire Building	251,299	SF	4	1-2 years	No known active leaks but many pipe clamps are in use, some piping has been replaced in attic but most is original to buildingâ€"100 y.o.	
	Domestic Piping-Cold Water Risers	Entire Building	251,299	SF	4	1-2 years	No known active leaks but many pipe clamps are in use, some piping has been replaced in attic but most is original to buildingâ€"100 y.o.	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	251,299	SF	4	1-2 years	No known active leaks but many pipe clamps are in use, some piping has been replaced in attic but most is original to buildingâ€"100 y.o.	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	251,299	SF	4	1-2 years	No known active leaks but many pipe clamps are in use, some piping has been replaced in attic but most is original to buildingâ€"100 y.o.	
	Domestic Piping-Hot Water Return Lines	Entire Building	251,299	SF	4	1-2 years	No known active leaks but many pipe clamps are in use, some piping has been replaced in attic but most is original to building—100 y.o.	
	Domestic Piping-Hot Water Return Risers	Entire Building	251,299	SF	4	1-2 years	No known active leaks but many pipe clamps are in use, some piping has been replaced in attic but most is original to buildingâ€"100 y.o.	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	251,299	SF	4	1-2 years	No known active leaks but many pipe clamps are in use, some piping has been replaced in attic but most is original to buildingâ€"100 y.o.	
	Sanitary Piping	Entire Building	251,299	SF	5	2-5 years	5 5 ,	
	Storm Piping	Entire Building	251,299	SF	5	2-5 years		
	Vent Piping	Entire Building	251,299	SF	5	2-5 years		
Pool Sys	stems							
,	Pool Drain Piping	1st Floor	200	LF	6	2-5 years		
	Pool Filtration System including Pump	1st Floor	1	EA	4	1-2 years	Open air type filter is old clogs easily, significant corrosion on tank shell	
	Pool Hot Water Heater - Steam Heat Exchanger	1st Floor	1	EA	5	2-5 years		
	Pool Supply and Return Piping	1st Floor	200	LF	4	1-2 years	Some piping is galvanized, some copper, all is corroded	

Pumps



Maria Saucedo Elementary Scholastic Academy

2850 W 24th BOULEVARD	, Chicago,	IL 60623

Catego	ry : Plumbing		B	uilding	: Main		
0	Kenne Terrer	Less them	Owentites		Daula	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Pumps - Sump-Duplex	1st Floor	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	1st Floor	1	EA	6	6-10 years	Elevator pit pump

Category : Room

Building		Main
Dununiy	٠	Iviaiii

alego				unung	. wam			
oup	Hom Tuno	Lesstion	Quantity	UOM	Donk	Recommend	Commonto	
-	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ninist	rative Suites/Offices							
	Ceiling - Plaster/Drywall	102 - Office Ass't Principal	195	SF	6	10+ years		
	Doors - Transom Window	102 - Office Ass't Principal	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	102 - Office Ass't Principal	2	EA	7	10+ years		
	Floor - Tile	102 - Office Ass't Principal	195	SF	6	10+ years		
	Lighting - Pendent/Surface	102 - Office Ass't Principal	4	EA	6	6-10 years		
	Power Distribution	102 - Office Ass't Principal	2	EA	7	10+ years		
	Walls - Plaster/Drywall	102 - Office Ass't Principal	850	SF	6	10+ years		
	AC Unit	107- Principal's Office	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	107- Principal's Office	343	SF	6	10+ years		
	Doors - Steel Doors incl hw	107- Principal's Office	1	EA	7	10+ years		
	Doors - Wood Doors inclu hw	107- Principal's Office	2	EA	7	10+ years		
	Floor - Carpet	107- Principal's Office	415	SF	6	6-10 years		
	Lighting - Pendent/Surface	107- Principal's Office	5	EA	6	6-10 years		
	Power Distribution	107- Principal's Office	6	EA	7	10+ years		
	Storage/ Closet	107- Principal's Office	72	SF	7	10+ years		
	Walls - Plaster/Drywall	107- Principal's Office	1,019	SF	6	10+ years		
	Ceiling - Plaster/Drywall	109-Open Office	75	SF	6	10+ years		
	Doors - Transom Window	109-Open Office	9	SF	6	10+ years		
	Doors - Wood Doors inclu hw	109-Open Office	1	EA	6	10+ years		
	Floor - Tile	109-Open Office	375	SF	6	10+ years		
	Lighting - Pendent/Surface	109-Open Office	7	EA	6	6-10 years		
	Power Distribution	109-Open Office	4	EA	7	10+ years		
	Walls - Plaster/Drywall	109-Open Office	859	SF	6	10+ years		
	Ceiling - Exposed	109A - East Office	87	SF	6	10+ years		
	Doors - Side-lite	109A - East Office	20	SF	7	10+ years		
	Doors - Wood Doors inclu hw	109A - East Office	1	EA	7	10+ years		
	Floor - Tile	109A - East Office	87	SF	6	10+ years		
	Lighting - Pendent/Surface	109A - East Office	2	EA	6	6-10 years		
	Power Distribution	109A - East Office	4	EA	7	10+ years		
	Walls - Plaster/Drywall	109A - East Office	331	SF	6	10+ years		
	Ceiling - Plaster/Drywall	109B - Middle office	87	SF	6	10+ years		
	Doors - Side-lite	109B - Middle office	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	109B - Middle office	1	EA	7	10+ years		
	Floor - Tile	109B - Middle office	87	SF	6	10+ years		
	Lighting - Pendent/Surface	109B - Middle office	2	EA	6	6-10 years		
	Power Distribution	109B - Middle office	4	EA	7	10+ years		
	Walls - Plaster/Drywall	109B - Middle office	331	SF	6	10+ years		
			501	0.	U U	ior yourd		



Catego	ory : Room		В	uilding	: Main		
j-	· • • • • • • • • • • • • • • • • • • •					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Ceiling - Plaster/Drywall	109C-West Office	87	SF	6	10+ years	
	Doors - Transom Window	109C-West Office	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	109C-West Office	1	EA	7	10+ years	
	Floor - Tile	109C-West Office	87	SF	6	10+ years	
	Lighting - Pendent/Surface	109C-West Office	2	EA	6	6-10 years	
	Power Distribution	109C-West Office	2	EA	7	10+ years	
	Storage/ Closet	109C-West Office	4	SF	7	10+ years	
	Walls - Plaster/Drywall	109C-West Office	352	SF	6	10+ years	
	Walls - Plaster/Drywall	109C-West Office	10	SF	4	1-2 years	Hole.
	Ceiling - Splined	117 - Office	670	SF	6	10+ years	
	Doors - Side-lite	117 - Office	96	SF	7	10+ years	
	Doors - Transom Window	117 - Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	117 - Office	7	EA	7	10+ years	
	Floor - Tile	117 - Office	670	SF	6	10+ years	
	Lighting - Pendent/Surface	117 - Office	12	EA	6	6-10 years	
	Power Distribution	117 - Office	14	EA	7	10+ years	
	Walls - Plaster/Drywall	117 - Office	709	SF	6	10+ years	
	Ceiling - Plaster/Drywall	121 - Conf Room	329	SF	6	10+ years	
	Doors - Transom Window	121 - Conf Room	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	121 - Conf Room	1	EA	7	10+ years	
	Floor - Tile	121 - Conf Room	329	SF	6	10+ years	
	Lighting - Pendent/Surface	121 - Conf Room	5	EA	6	6-10 years	
	Power Distribution	121 - Conf Room	4	EA	7	10+ years	
	Walls - Plaster/Drywall	121 - Conf Room	709	SF	6	10+ years	
	Ceiling - Plaster/Drywall	124 - Teachers Lounge/Office	336	SF	6	10+ years	
	Doors - Transom Window	124 - Teachers Lounge/Office	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	124 - Teachers Lounge/Office	3	EA	7	10+ years	
	Floor - Wood	124 - Teachers Lounge/Office	336	SF	6	10+ years	
	Lighting - Pendent/Surface	124 - Teachers Lounge/Office	6	EA	6	6-10 years	
	Power Distribution	124 - Teachers Lounge/Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	124 - Teachers Lounge/Office	903	SF	6	10+ years	
	Work SInk	124 - Teachers Lounge/Office	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	128 - Women Teachers Rest Room	255	SF	6	10+ years	
		(Used as Storage)					
	Doors - Wood Doors inclu hw	128 - Women Teachers Rest Room	2	EA	7	10+ years	
		(Used as Storage)					
	Floor - Tile	128 - Women Teachers Rest Room	255	SF	6	10+ years	
		(Used as Storage)					
	Lighting - Pendent/Surface	128 - Women Teachers Rest Room	5	EA	6	6-10 years	
		(Used as Storage)					
	Walls - Plaster/Drywall	128 - Women Teachers Rest Room	750	SF	6	10+ years	
		(Used as Storage)					
	Ceiling - Plaster/Drywall	128B - Office	242	SF	6	10+ years	
	Doors - Wood Doors inclu hw	128B - Office	3	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main			
J	-		Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
•	Floor - Tile	128B - Office	242	SF	6	10+ years		
	Lighting - Pendent/Surface	128B - Office	5	EA	6	6-10 years		
	Power Distribution	128B - Office	4	EA	7	10+ years		
	Storage/ Closet	128B - Office	6	SF	7	10+ years		
	Walls - Plaster/Drywall	128B - Office	576	SF	6	10+ years		
	AC Unit	1st Flr - Main Office Reception	2	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Flr - Main Office Reception	701	SF	7	10+ years		
	Doors - Transom Window	1st Flr - Main Office Reception	18	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Flr - Main Office Reception	2	EA	7	10+ years		
	Floor - Carpet	1st Flr - Main Office Reception	701	SF	6	6-10 years		
	Floor - Tile	1st Flr - Main Office Reception	300	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Flr - Main Office Reception	18	EA	6	6-10 years		
	Power Distribution	1st Flr - Main Office Reception	6	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Flr - Main Office Reception	1,012	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Flr - Main Office Work Room	144	SF	6	10+ years		
	Doors - Side-lite	1st Flr - Main Office Work Room	36	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Flr - Main Office Work Room	1	EA	7	10+ years		
	Floor - Carpet	1st Flr - Main Office Work Room	144	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st Flr - Main Office Work Room	4	EA	6	6-10 years		
	Power Distribution	1st Flr - Main Office Work Room	4	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Flr - Main Office Work Room	285	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Flr - Pool Office	241	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st Flr - Pool Office	1	EA	7	10+ years		
	Doors - Wood Doors inclu hw	1st Flr - Pool Office	2	EA	7	10+ years		
	Floor - Terrazzo	1st Flr - Pool Office	241	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Flr - Pool Office	3	EA	6	6-10 years		
	Power Distribution	1st Flr - Pool Office	4	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Flr - Pool Office	650	SF	6	10+ years		
	Ceiling - Splined	2nd Floor Kitchen Office	82	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor Kitchen Office	1	EA	7	10+ years		
	Floor - Tile	2nd Floor Kitchen Office	82	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor Kitchen Office	2	EA	6	6-10 years		
	Power Distribution	2nd Floor Kitchen Office	4	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor Kitchen Office	301	SF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor Library Office	199	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor Library Office	1	EA	7	10+ years		
	Floor - Tile	2nd Floor Library Office	199	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor Library Office	4	ĒA	6	6-10 years		
	Power Distribution	2nd Floor Library Office	4	EA	7	10+ years		
	Storage/ Closet	2nd Floor Library Office	100	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor Library Office	572	SF	6	10+ years		
	Work Sink	2nd Floor Library Office	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	Main Gym Office	225	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Main Gym Office	1	EA	7	10+ years		



Cataga					Mair	200	50 W 24th BOULEVARD, Chicago, IL 60623
Catego	ry : Room		В	uilding	: wain	Doopmmand	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Floor - Wood	Main Gym Office	225	SF	6	10+ years	Comments
	Lighting - Pendent/Surface	Main Gym Office	4	EA	6	6-10 years	
	Power Distribution	Main Gym Office	8	EA	7	10+ years	
	Walls - Concrete Block	Main Gym Office	40	SF	6	10+ years	
	Walls - Plaster/Drywall	Main Gym Office	500	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Records Room	240	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Records Room	240	EA	7	10+ years	
	Floor - Tile	Records Room	240	SF	6	10+ years	
	Lighting - Pendent/Surface	Records Room	240	EA	6	6-10 years	
	Power Distribution	Records Room	4	EA	7	10+ years	
	Storage/ Closet	Records Room	20	SF	7	10+ years	
	Walls - Plaster/Drywall	Records Room	20 640	SF	6	10+ years	
	Walls - Flastel/Drywall	Recolds Room	040	ЗГ	0	10+ years	
Auditoriu	um & Theater						
	Balcony Seating	1st Floor	506	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	8,576	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	22	EA	7	10+ years	
	Floor - Carpet	1st Floor	6,575	SF	6	6-10 years	
	Floor - Wood	1st Floor	2,001	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	35	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	39	EA	6	6-10 years	
	Main Floor Seating	1st Floor	1,062	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	1,462	SF	7	10+ years	
	Stage Curtain	1st Floor	8	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	120	LF	6	10+ years	
	Stairs - Asphalt	1st Floor	40	LF	6	10+ years	
	Storage/ Closet	1st Floor	350	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,912	SF	6	10+ years	
Gymnas	ia						
	Ceiling - Plaster/Drywall	2nd Floor Girls Gym	4,983	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Girls Gym	7	EA	7	10+ years	
	Floor - Wood	2nd Floor Girls Gym	4,983	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girls Gym	24	EA	6	6-10 years	
	Storage/ Closet	2nd Floor Girls Gym	301	SF	7	10+ years	
	Walls - Masonry	2nd Floor Girls Gym	3,900	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Girls Gym	2,121	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Main Gym	12,072	SF	6	10+ years	
	Doors - Steel Doors incl hw	Main Gym	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	Main Gym	9	EA	7	10+ years	
	Floor - Tile	Main Gym	3,000	SF	6	10+ years	
	Floor - Wood	Main Gym	9,072	SF	6	10+ years	
		•				2	



					- M.c.'	285	60 W 24th BOULEVARD, Chicago, IL 60623
Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Metal Halide/ High Pressure	Main Gym	26	EA	6	6-10 years	
	Sodium					0.40	
	Lighting - Pendent/Surface	Main Gym	11	EA	6	6-10 years	
	Lighting - Wall Mounted	Main Gym	21	EA	6	6-10 years	
	Scoreboards	Main Gym	1	EA	7	6-10 years	
	Storage/ Closet	Main Gym	360	SF	7	10+ years	
	Walls - Concrete Block	Main Gym	830	SF	6	10+ years	
	Walls - Masonry	Main Gym	2,500	SF SF	6	10+ years	
	Walls - Plaster/Drywall	Main Gym	4,200	SF	6	10+ years	
12 to be an							
Kitchen	Ceiling - Splined	2nd Floor	1,300	SF	6	10	
	Doors - Wood Doors inclu hw	2nd Floor	1,300	EA	7	10+ years 10+ years	
	Floor - Tile Quarry	2nd Floor	1,300	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1,300	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	310	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,212	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Fir - Kitchen storage @ Lunch	466	SF	6	10+ years	
	Colling Thatal, Drywall	Room	100	01	Ŭ	ior youro	
	Doors - Transom Window	2nd Flr - Kitchen storage @ Lunch	18	SF	7	10+ years	
		Room	10	01	,	ior youro	
	Doors - Wood Doors inclu hw	2nd Flr - Kitchen storage @ Lunch	2	EA	7	10+ years	
		Room	-	_/ `		ie yeare	
	Floor - Tile Quarry	2nd Flr - Kitchen storage @ Lunch	466	SF	6	10+ years	
		Room			-	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	Lighting - Pendent/Surface	2nd Flr - Kitchen storage @ Lunch	9	EA	6	6-10 years	
	5 5	Room				,	
	Walls - Plaster/Drywall	2nd Flr - Kitchen storage @ Lunch	1,133	SF	6	10+ years	
	·	Room					
Library							
	Casework	201	687	LF	7	10+ years	
	Ceiling - Lay-in	201	3,978	SF	6	10+ years	
	Doors - Wood Doors inclu hw	201	7	EA	7	10+ years	
	Floor - Tile	201	3,978	SF	6	10+ years	
	Lighting - Pendent/Surface	201	62	EA	6	10+ years	
	Storage/ Closet	201	24	SF	7	10+ years	
	Walls - Plaster/Drywall	201	2,967	SF	6	10+ years	
l ocker/9	Shower Room						
	Accessories	1st Flr Boys @ Gym (NOT USED)	1,574	SF	5	2-5 years	
	Benches, ped mounted	1st Flr Boys @ Gym (NOT USED)	138	LF	7	10+ years	
	Ceiling - Exposed	1st Flr Boys @ Gym (NOT USED)	400	SF	6	10+ years	
	J 1	· · · · · · · · · · · · · · · · · · ·			-	, ,	



	ry : Room		R	uilding	• Main	200	0 W 24th BOULEVARD, Chicago, iL 60623
Juicgo				unung	. mant	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.000	Ceiling - Plaster/Drywall	1st Flr Boys @ Gym (NOT USED)	1,174	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fir Boys @ Gym (NOT USED)	2	EA	6	10+ years	
	Doors - Wood Doors inclu hw	1st Flr Boys @ Gym (NOT USED)	4	EA	6	10+ years	
	Floor - Concrete	1st Flr Boys @ Gym (NOT USED)	1,486	SF	5	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Flr Boys @ Gym (NOT USED)	88	SF	6	10+ years	
	Floor Drain	1st Flr Boys @ Gym (NOT USED)	8	EA	7	10+ years	
	Lavatory	1st Flr Boys @ Gym (NOT USED)	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Flr Boys @ Gym (NOT USED)	46	EA	6	6-10 years	
	Partitions	1st Flr Boys @ Gym (NOT USED)	2	EA	7	10+ years	
	Student Lockers - Two Tier	1st Flr Boys @ Gym (NOT USED)	1,100	EA	5	6-10 years	
	Student Lockers - Two Tier	1st Flr Boys @ Gym (NOT USED)	110	EA	5	6-10 years	
	Urinals	1st FIr Boys @ Gym (NOT USED)	3	EA	7	10+ years	
	Walls - Concrete Block	1st FIr Boys @ Gym (NOT USED)	250	SF	7	10+ years	
	Walls - Plaster/Drywall	1st FIr Boys @ Gym (NOT USED)	2,740	SF	6	10+ years	
	Water Closet	1st FIr Boys @ Gym (NOT USED)	2	EA	6	10+ years	
	Accessories	1st Flr Boys' @ Pool	617	SF	7	6-10 years	
	Benches, ped mounted	1st Flr Boys' @ Pool	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Flr Boys' @ Pool	617	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Flr Boys' @ Pool	1	EA	7	10+ years	
	Floor - Terrazzo	1st Flr Boys' @ Pool	292	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Flr Boys' @ Pool	325	SF	6	10+ years	
	Floor Drain	1st Flr Boys' @ Pool	4	EA	7	10+ years	
	Hand Dryer	1st Flr Boys' @ Pool	1	EA	7	6-10 years	
	Lavatory	1st Flr Boys' @ Pool	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Flr Boys' @ Pool	10	EA	6	6-10 years	
	Partitions	1st Flr Boys' @ Pool	1	EA	7	10+ years	
	Showers	1st Flr Boys' @ Pool	8	EA	7	10+ years	
	Student Lockers - Two Tier	1st Flr Boys' @ Pool	74	EA	7	10+ years	
	Urinals	1st Flr Boys' @ Pool	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Flr Boys' @ Pool	885	SF	6	10+ years	
	Water Closet	1st Flr Boys' @ Pool	1	EA	7	10+ years	
	Accessories	1st Flr Girls @ Pool	3,002	SF	7	6-10 years	
	Benches, ped mounted	1st Flr Girls @ Pool	132	LF	7	10+ years	
	Ceiling - Exposed	1st Flr Girls @ Pool	3,002	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Flr Girls @ Pool	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Flr Girls @ Pool	4	EA	7	10+ years	
	Floor - Concrete	1st Flr Girls @ Pool	3,002	SF	5	10+ years	
	Floor Drain	1st FIr Girls @ Pool	10	ĒA	7	10+ years	
	Hand Dryer	1st Flr Girls @ Pool	24	EA	7	6-10 years	
	Lavatory	1st Flr Girls @ Pool	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Fir Girls @ Pool	65	EA	6	6-10 years	
	Partitions	1st Flr Girls @ Pool	29	EA	7	10+ years	
	Showers	1st Fir Girls @ Pool	24	EA	5	2-5 years	
	Storage/ Closet	1st Fir Girls @ Pool	54	SE	7	10± vears	

Storage/ Closet

54

SF

7

10+ years

1st FIr Girls @ Pool



Catego	ry : Room		В	uilding	: Main		
						Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	1st FIr Girls @ Pool	760	EA	5	10+ years	
	Student Lockers - Two Tier	1st Flr Girls @ Pool	1,000	EA	5	10+ years	
	Walls - Plaster/Drywall	1st FIr Girls @ Pool	2,688	SF	6	10+ years	
	Water Closet	1st Flr Girls @ Pool	5	EA	7	10+ years	
	Accessories	Staff 128	100	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff 128	320	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Staff 128	2	EA	7	10+ years	
	Floor - Tile/Sheet	Staff 128	320	SF	7	10+ years	
	Floor Drain	Staff 128	1	EA	7	10+ years	
	Lavatory	Staff 128	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Staff 128	5	EA	6	6-10 years	
	Partitions	Staff 128	1	EA	5	10+ years	
	Showers	Staff 128	1	EA	4	1-2 years	Missing.
	Student Lockers - One Tier	Staff 128	8	EA	7	10+ years	5
	Walls - Plaster/Drywall	Staff 128	820	SF	6	10+ years	
	Walls - Plaster/Drywall	Staff 128	20	SF	4	1-2 years	Plaster missing
	Water Closet	Staff 128	1	EA	6	10+ years	3
unch &	Multipurpose Room Ceiling - Lay-in	2nd Floor Student Dining Area	11,000	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor Student Dining Area 2nd Floor Student Dining Area	426	SF	6		
	Doors - Wood Doors inclu hw	2nd Floor Student Dining Area 2nd Floor Student Dining Area	420	EA	7	10+ years 10+ years	
	Floor - Tile	2nd Floor Student Dining Area 2nd Floor Student Dining Area		SF	6	•	
	Lighting - Pendent/Surface	2nd Floor Student Dining Area 2nd Floor Student Dining Area	11,426 355	EA	6	10+ years	
	Serving Line	2nd Floor Student Dining Area 2nd Floor Student Dining Area	180		7	6-10 years 10+ years	
	Walls - Plaster/Drywall	2nd Floor Student Dining Area	5,449	SF	6	10+ years	
	AC Unit	2nd Floor Teachers Lunchroom	5,449	EA	7	•	
	Ceiling - Splined	2nd Floor Teachers Lunchroom	674	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor Teachers Lunchroom	1	EA	7	10+ years	
	Floor - Tile	2nd Floor Teachers Lunchroom	674	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Teachers Lunchroom	12	EA	6	10+ years 6-10 years	
	Walls - Plaster/Drywall			SF	6	•	
	Ceiling - Lay-in	2nd Floor Teachers Lunchroom 3rd flr, Rm 300	1,215	SF	-	10+ years	
	Chalk Board	3rd flr, Rm 300	1,785	LF	6	10+ years	
	Doors - Transom Window		8	SF	4 7	2-5 years	
	Doors - Wood Doors inclu hw	3rd flr, Rm 300 2rd flr, Rm 200	48 4	EA	7	10+ years	
	Floor - Wood Doors Inclu nw	3rd flr, Rm 300 3rd flr, Rm 300		SF	6	10+ years	
		3rd flr, Rm 300	1,785 24	EA		10+ years	
	Lighting - Lay-in Market Board			LF	6 7	6-10 years	
	Market Board	3rd flr, Rm 300	6	LF SF		6-10 years	
	Storage/ Closet	3rd flr, Rm 300 3rd flr, Rm 200	60 2 207		7	10+ years	
	Walls - Plaster/Drywall	3rd flr, Rm 300	2,297	SF	6	10+ years	
DF_ID							
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	



Catego	ry : Room		R	uilding	• Main		0 W 24th BOULEVARD, Chicago, IL 6062
Jacyo				anang	. mann	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
noup	Finishes	2nd Floor	243	SF	7	10+ years	Comments
	Window AC Unit	2nd Floor	240	EA	7	6-10 years	
		21011001	1	LA	'	0-10 years	
lechani	cal/ Service Rooms						
	Air Intake Plenums	1st Floor - East half	300	SF	7	10+ years	
	Janitor's Closet	1st Floor - East half	18	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor - East half	640	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor - East half	53	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor - East half	1,000	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor - East half	1,000	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor - East half	730	SF	7	10+ years	
	Storage Room	1st Floor - East half	1,170	SF	7	10+ years	
	Vaults	1st Floor - East half	300	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Fir-Freight Elevator & Lobby	319	SF	7	10+ years	
	Janitor's Closet	2nd Floor	16	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	28	SF	7		
						10+ years	
	Janitor's Closet	3rd Floor Janitor Closet @ Student Toilet Rooms	42	SF	7	10+ years	
001 & N	latatorium						
	Bleachers Seating/Plank Seating	1st Floor	175	EA	7	10+ years	
	Ceiling - Exposed	1st Floor	3,613	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	5,015	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	2,117	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2,117	EA	6	6-10 years	
						•	
	Pool Basin	1st Floor	1,496	SF	7	10+ years	
	Pool Deck	1st Floor	2,117	SF	7	10+ years	
	Pool Deck Drains	1st Floor	4	EA	7	10+ years	
	Storage/ Closet	1st Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,694	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,952	SF	6	10+ years	
rep Ro	om						
-	Casework	216A - Science Prep/Storage Room with Vault	26	LF	7	10+ years	
	Ceiling - Plaster/Drywall	216A - Science Prep/Storage Room with Vault	183	SF	6	10+ years	
	Doors - Wood Doors inclu hw	216A - Science Prep/Storage Room with Vault	4	EA	7	10+ years	
	Floor - Tile	216A - Science Prep/Storage Room with Vault	75	SF	6	10+ years	
	Lighting - Lay-in	216A - Science Prep/Storage Room with Vault	1	EA	6	6-10 years	



Catego	ory : Room		В	uilding	: Main		
				5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	216A - Science Prep/Storage Room	2	EA	6	6-10 years	
		with Vault					
	Walls - Plaster/Drywall	216A - Science Prep/Storage Room	457	SF	6	10+ years	
		with Vault			_		
	Casework	220A - Science Prep	28	LF	7	10+ years	
	Ceiling - Plaster/Drywall	220A - Science Prep	159	SF	6	10+ years	
	Doors - Side-lite	220A - Science Prep	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	220A - Science Prep	2	EA	7	10+ years	
	Floor - Carpet	220A - Science Prep	159	SF	6	6-10 years	
	Lighting - Pendent/Surface	220A - Science Prep	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	220A - Science Prep	524	SF	6	10+ years	
	Work Sink	220A - Science Prep	1	EA	7	6-10 years	
		222 - Science Prep with Vault	26	LF	7	10+ years	
	Ceiling - Plaster/Drywall	222 - Science Prep with Vault	183	SF	6	10+ years	
	Doors - Wood Doors inclu hw	222 - Science Prep with Vault	1	EA	7	10+ years	
	Floor - Carpet	222 - Science Prep with Vault	75	SF	6	6-10 years	
	Floor - Tile	222 - Science Prep with Vault	108	SF	6	10+ years	
	Lighting - Lay-in	222 - Science Prep with Vault	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	222 - Science Prep with Vault	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	222 - Science Prep with Vault	457	SF	6	10+ years	
	Work Sink	222 - Science Prep with Vault	1	EA LF	7	6-10 years	
		224A - In Science Class Room 224	28		7	10+ years	
	Ceiling - Plaster/Drywall	224A - In Science Class Room 224	159	SF SF	6	10+ years	
	Doors - Side-lite	224A - In Science Class Room 224	28		7	10+ years	
	Doors - Wood Doors inclu hw	224A - In Science Class Room 224	2	EA	7	10+ years	
	Floor - Carpet	224A - In Science Class Room 224	159	SF	6	6-10 years	
	Lighting - Pendent/Surface	224A - In Science Class Room 224	2	EA SF	6	6-10 years	
	Walls - Plaster/Drywall	224A - In Science Class Room 224	524		6	10+ years	
	Work Sink	224A - In Science Class Room 224	1	EA	7	6-10 years	
	Casework	3rd flr between CR 304 & 302	36	LF SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd flr between CR 304 & 302	266		6	10+ years	
	Doors - Steel Doors incl hw	3rd flr between CR 304 & 302	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	3rd flr between CR 304 & 302	2	EA	7	10+ years	
	Floor - Tile	3rd flr between CR 304 & 302	266	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd flr between CR 304 & 302	3	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd flr between CR 304 & 302	777	SF	6	10+ years	
	Work Sink	3rd flr between CR 304 & 302	1	EA LF	7	6-10 years	
	Casework	3rd flr between CR 305 & 309	36 266	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd flr between CR 305 & 309		EA	6 7	10+ years	
	Doors - Steel Doors incl hw	3rd flr between CR 305 & 309	1			10+ years	
	Doors - Wood Doors inclu hw	3rd flr between CR 305 & 309	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	3rd flr between CR 305 & 309	1	EA SF	7	10+ years	
	Floor - Tile	3rd flr between CR 305 & 309	266 3	-	6 6	10+ years	
	Lighting - Pendent/Surface	3rd flr between CR 305 & 309	3	EA	O	6-10 years	



Category : Room			В	uilding	: Main				
			_			Recommend	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
neup	Walls - Plaster/Drywall	3rd flr between CR 305 & 309	777	SF	6	10+ years	••••••••		
	Work Sink	3rd flr between CR 305 & 309	1	EA	7	10+ years			
				-/ (•	lot youro			
estroo	m								
	Accessories	102	72	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	102	72	SF	6	10+ years			
	Doors - Wood Doors inclu hw	102	1	EA	7	10+ years			
	Floor - Concrete	102	72	SF	5	10+ years			
	Lavatory	102	1	ΕA	7	10+ years			
	Lighting - Pendent/Surface	102	1	EA	6	6-10 years			
	Partitions	102	1	EA	5	10+ years			
	Walls - Plaster/Drywall	102	240	SF	6	10+ years			
	Water Closet	102	1	EA	7	10+ years			
	Accessories	116 Pre-K Unisex	33	SF	7	6-10 years			
	Ceiling - Lay-in	116 Pre-K Unisex	33	SF	6	10+ years			
	Doors - Wood Doors inclu hw	116 Pre-K Unisex	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	116 Pre-K Unisex	33	SF	6	10+ years			
	Lavatory	116 Pre-K Unisex	1	EA	7	10+ years			
	Lighting - Pendent/Surface	116 Pre-K Unisex	1	EA	6	6-10 years			
	Walls - Plaster/Drywall	116 Pre-K Unisex	132	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	116 Pre-K Unisex	86	SF	6	10+ years			
	Water Closet	116 Pre-K Unisex	1	EA	7	10+ years			
	Accessories	128 Womens	36	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	128 Womens	36	SF	6	10+ years			
	Doors - Wood Doors inclu hw	128 Womens	1	EA	7	10+ years			
	Floor - Tile	128 Womens	36	SF	6	10+ years			
		128 Womens	2	EA	7				
	Lavatory	128 Womens	2	EA		10+ years			
	Lighting - Pendent/Surface	128 Womens		EA	6	6-10 years			
	Lighting - Wall Mounted		2	EA	6 7	6-10 years			
	Partitions	128 Womens		SF		10+ years			
	Walls - Plaster/Drywall	128 Womens	94		6	10+ years			
	Water Closet	128 Womens	1	EA	7	10+ years			
	Accessories	128c Mens	37	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	128c Mens	37	SF	6	10+ years			
	Doors - Wood Doors inclu hw	128c Mens	1	EA	7	10+ years			
	Floor - Tile	128c Mens	37	SF	6	10+ years			
	Lighting - Wall Mounted	128c Mens	1	EA	6	6-10 years			
	Partitions	128c Mens	1	EA	7	10+ years			
	Urinals	128c Mens	1	EA	7	10+ years			
	Walls - Plaster/Drywall	128c Mens	200	SF	6	10+ years			
	Water Closet	128c Mens	1	EA	7	10+ years			
	Accessories	130 Pre-K Unisex	30	SF	7	6-10 years			
	Ceiling - Lay-in	130 Pre-K Unisex	30	SF	6	10+ years			
	Doors - Wood Doors inclu hw	130 Pre-K Unisex	1	EA	7	10+ years			



Catego	ry : Room		В	uilding	: Main		
j-	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	130 Pre-K Unisex	30	SF	6	10+ years	
	Lavatory	130 Pre-K Unisex	1	EA	7	10+ years	
	Lighting - Pendent/Surface	130 Pre-K Unisex	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	130 Pre-K Unisex	170	SF	6	10+ years	
	Water Closet	130 Pre-K Unisex	1	EA	7	10+ years	
	Accessories	143 Unisex Toilet	54	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	143 Unisex Toilet	54	SF	6	10+ years	
	Doors - Wood Doors inclu hw	143 Unisex Toilet	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	143 Unisex Toilet	54	SF	6	10+ years	
	Floor Drain	143 Unisex Toilet	1	EA	7	10+ years	
	Hand Dryer	143 Unisex Toilet	1	EA	7	6-10 years	
	Lavatory	143 Unisex Toilet	1	EA	7	10+ years	
	Lighting - Pendent/Surface	143 Unisex Toilet	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	143 Unisex Toilet	75	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	143 Unisex Toilet	189	SF	6	10+ years	
	Water Closet	143 Unisex Toilet	1	EA	7	10+ years	
	Accessories	144 Unisex Toilet	54	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	144 Unisex Toilet	54	SF	6	10+ years	
	Doors - Wood Doors inclu hw	144 Unisex Toilet	1	ĒA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	144 Unisex Toilet	54	SF	6	10+ years	
	Floor Drain	144 Unisex Toilet	1	ĒA	7	10+ years	
	Hand Dryer	144 Unisex Toilet	1	EA	7	6-10 years	
	Lavatory	144 Unisex Toilet	1	EA	7	10+ years	
	Lighting - Pendent/Surface	144 Unisex Toilet	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	144 Unisex Toilet	75	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	144 Unisex Toilet	189	SF	6	10+ years	
	Water Closet	144 Unisex Toilet	1	ĒA	7	10+ years	
	Accessories	1st Floor NE Corridor (Female Help	68	SF	7	6-10 years	
		on plan)		•	•		
	Ceiling - Plaster/Drywall	1st Floor NE Corridor (Female Help	308	SF	6	10+ years	
		on plan)	000	0.	Ũ	io: youro	
	Doors - Wood Doors inclu hw	1st Floor NE Corridor (Female Help	2	EA	7	10+ years	
		on plan)	-		•	io: youro	
	Floor - Tile	1st Floor NE Corridor (Female Help	296	SF	6	10+ years	
		on plan)	200	01	0	ior youro	
	Floor - Tile	1st Floor NE Corridor (Female Help	12	SF	4	0-1 year	Cracked/chipped.
		on plan)	12	01	-	0 i yeai	oracica, cripped.
	Floor Drain	1st Floor NE Corridor (Female Help	1	EA	7	10+ years	
		on plan)	1	LA	'	TOF years	
	Lavatory	1st Floor NE Corridor (Female Help	1	EA	7	10+ years	
	Lavatory	on plan)	I	LA	'	ior years	
	Lighting - Pendent/Surface	1st Floor NE Corridor (Female Help	5	EA	6	6-10 years	
	Lighting - Fendent/Sunace	on plan)	5	LA	U	0-10 years	
	Partitions	1st Floor NE Corridor (Female Help	1	EA	5	6-10 years	
			I	EA	5	0-10 years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		on plan)					
	Walls - Plaster/Drywall	1st Floor NE Corridor (Female Help	965	SF	6	10+ years	
		on plan)					
	Water Closet	1st Floor NE Corridor (Female Help	1	EA	6	10+ years	
		on plan)		~-	_		
	Accessories	1st Floor NE Girls (Boys on plan)	331	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor NE Girls (Boys on plan)	331	SF SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted Floor Drain	1st Floor NE Girls (Boys on plan) 1st Floor NE Girls (Boys on plan)	331 1	EA	7 7	10+ years	
	Lavatory	1st Floor NE Girls (Boys on plan)	2	EA	7	10+ years 10+ years	
	Lighting - Pendent/Surface	1st Floor NE Girls (Boys on plan)	2	EA	6	6-10 years	
	Partitions	1st Floor NE Girls (Boys on plan)	9	EA	7	10+ years	
	Walls - Concrete Block	1st Floor NE Girls (Boys on plan)	144	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor NE Girls (Boys on plan)	144	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor NE Girls (Boys on plan)	288	SF	6	10+ years	
	Water Closet	1st Floor NE Girls (Boys on plan)	9	EA	7	10+ years	
	Accessories	1st Floor NW Girls (Boys on plan)	331	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor NW Girls (Boys on plan)	331	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor NW Girls (Boys on plan)	331	SF	7	10+ years	
	Floor Drain	1st Floor NW Girls (Boys on plan)	1	EA	7	10+ years	
	Lavatory	1st Floor NW Girls (Boys on plan)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor NW Girls (Boys on plan)	8	EA	6	6-10 years	
	Partitions	1st Floor NW Girls (Boys on plan)	9	EA	7	10+ years	
	Walls - Concrete Block	1st Floor NW Girls (Boys on plan)	144	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor NW Girls (Boys on plan)	144	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor NW Girls (Boys on plan)	288	SF	6	6-10 years	
	Water Closet	1st Floor NW Girls (Boys on plan)	9	EA	7	10+ years	
	Accessories	1st Floor SE Boys (Girls on plan)	349	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor SE Boys (Girls on plan)	349	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor SE Boys (Girls on plan)	349	SF	7	10+ years	
	Floor Drain	1st Floor SE Boys (Girls on plan)	1	EA EA	7 7	10+ years	
	Lavatory	1st Floor SE Boys (Girls on plan)	2 8		6	10+ years	
	Lighting - Pendent/Surface Partitions	1st Floor SE Boys (Girls on plan) 1st Floor SE Boys (Girls on plan)	o 2	EA EA	6 7	6-10 years	
	Urinals	1st Floor SE Boys (Girls on plan)	2	EA	7	10+ years 10+ years	
	Walls - Concrete Block	1st Floor SE Boys (Girls on plan)	144	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor SE Boys (Girls on plan)	144	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor SE Boys (Girls on plan)	288	SF	6	10+ years	
	Water Closet	1st Floor SE Boys (Girls on plan)	200	EA	7	10+ years	
	Accessories	1st Floor SW Boys (Girls on plan)	349	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor SW Boys (Girls on plan)	349	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor SW Boys (Girls on plan)	349	SF	5	10+ years	
	Floor Drain	1st Floor SW Boys (Girls on plan)	1	EA	7	10+ years	
	Lavatory	1st Floor SW Boys (Girls on plan)	2	EA	7	10+ years	



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Lighting - Pendent/Surface 1st Floor SW Boys (Girls on plan) 8 ΕA 6 6-10 vears 1st Floor SW Boys (Girls on plan) 2 ΕA 7 Partitions 10+ vears Urinals 1st Floor SW Boys (Girls on plan) 7 EΑ 7 10+ years 1st Floor SW Boys (Girls on plan) SF Walls - Concrete Block 144 6 10+ years SF Walls - Plaster/Drywall 1st Floor SW Boys (Girls on plan) 144 6 10+ years SF 1st Floor SW Boys (Girls on plan) 6 Walls - Tile Ceramic/ Porcelain 288 10+ years Water Closet 1st Floor SW Boys (Girls on plan) ΕA 7 2 10+ years SF Accessories 2nd Floor Gym Office/219.5A Toilet 100 7 6-10 years room in Office/Storage SF Ceiling - Plaster/Drywall 2nd Floor Gvm Office/219.5A Toilet 100 6 10+ years room in Office/Storage Doors - Wood Doors inclu hw 2nd Floor Gym Office/219.5A Toilet 1 EA 7 10+ years room in Office/Storage Floor - Tile Ceramic/ Porcelain 2nd Floor Gym Office/219.5A Toilet 100 SF 6 10+ years room in Office/Storage 2nd Floor Gym Office/219.5A Toilet EΑ Lavatory 1 7 10+ years room in Office/Storage Lighting - Pendent/Surface 2nd Floor Gym Office/219.5A Toilet 1 EΑ 6 6-10 years room in Office/Storage Partitions 2nd Floor Gym Office/219.5A Toilet 1 ΕA 7 10+ years room in Office/Storage Showers 2nd Floor Gym Office/219.5A Toilet 1 EA 7 10+ years room in Office/Storage Walls - Plaster/Drywall 2nd Floor Gym Office/219.5A Toilet 391 SF 6 6-10 years room in Office/Storage Water Closet 2nd Floor Gvm Office/219.5A Toilet 1 ΕA 7 10+ years room in Office/Storage 2nd Floor NE Girls (Boys on plan) 331 SF 7 Accessories 6-10 years Ceiling - Plaster/Drywall 2nd Floor NE Girls (Boys on plan) SF 331 6 10+ years Floor - Concrete Epoxy/ Painted 2nd Floor NE Girls (Boys on plan) 311 SF 7 10+ years Floor Drain 2nd Floor NE Girls (Boys on plan) ΕA 7 10+ vears 1 Lavatorv 2nd Floor NE Girls (Boys on plan) 2 ΕA 7 10+ vears Lighting - Pendent/Surface 2nd Floor NE Girls (Boys on plan) 8 FΑ 6 6-10 years 2nd Floor NE Girls (Boys on plan) 9 ΕA 7 Partitions 10+ years SF Walls - Concrete Block 2nd Floor NE Girls (Boys on plan) 144 6 10+ years SF 6 Walls - Plaster/Drywall 2nd Floor NE Girls (Boys on plan) 144 10+ years SF Walls - Tile Ceramic/ Porcelain 2nd Floor NE Girls (Boys on plan) 288 6 10+ years Water Closet 2nd Floor NE Girls (Boys on plan) 7 9 EΑ 10+ years SF Accessories 2nd Floor NW (Help Locker Room 214 7 6-10 years on plan) Ceiling - Plaster/Drywall 2nd Floor NW (Help Locker Room 214 SF 6 10+ years on plan) Doors - Wood Doors inclu hw 2nd Floor NW (Help Locker Room EA 7 10+ years 1

on plan)



Catego	ry : Room		В	uilding	: Main		
e alege			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor NW (Help Locker Room	214	SF	6	10+ years	
		on plan)				,	
	Hand Dryer	2nd Floor NW (Help Locker Room	1	EA	7	6-10 years	
		on plan)					
	Lavatory	2nd Floor NW (Help Locker Room	1	EA	7	10+ years	
		on plan)					
	Lighting - Pendent/Surface	2nd Floor NW (Help Locker Room	3	EA	6	6-10 years	
		on plan)			_		
	Student Lockers - One Tier	2nd Floor NW (Help Locker Room	19	EA	7	10+ years	
		on plan)	050	05	0	40	
	Walls - Plaster/Drywall	2nd Floor NW (Help Locker Room	359	SF	6	10+ years	
	Water Closet	on plan) 2nd Floor NW (Help Locker Room	1	EA	7	6 10 vooro	
	Water Closet	on plan)	1	EA	/	6-10 years	
	Accessories	2nd Floor NW Girls (Boys on plan)	331	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor NW Girls (Boys on plan)	331	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	2nd Floor NW Girls (Boys on plan)	321	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	2nd Floor NW Girls (Boys on plan)	10	SF	4	1-2 years	Peeling paint with cracks
	Floor Drain	2nd Floor NW Girls (Boys on plan)	1	EA	7	10+ years	
	Lavatory	2nd Floor NW Girls (Boys on plan)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor NW Girls (Boys on plan)	8	EA	6	6-10 years	
	Partitions	2nd Floor NW Girls (Boys on plan)	9	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor NW Girls (Boys on plan)	144	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor NW Girls (Boys on plan)	144	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor NW Girls (Boys on plan)	288	SF	6	10+ years	
	Water Closet	2nd Floor NW Girls (Boys on plan)	9	EA	7	10+ years	
	Accessories	2nd Floor SE Boys (Girls on plan)	349	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor SE Boys (Girls on plan)	349	SF	6	10+ years	
	Floor - Concrete	2nd Floor SE Boys (Girls on plan)	349	SF	7	10+ years	
	Floor Drain	2nd Floor SE Boys (Girls on plan)	1	EA	7	10+ years	
	Lavatory	2nd Floor SE Boys (Girls on plan)	2 7	EA EA	7	10+ years	
	Lighting - Pendent/Surface Partitions	2nd Floor SE Boys (Girls on plan) 2nd Floor SE Boys (Girls on plan)	2	EA	6 7	6-10 years 10+ years	
	Urinals	2nd Floor SE Boys (Girls on plan) 2nd Floor SE Boys (Girls on plan)	2	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor SE Boys (Girls on plan)	, 144	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor SE Boys (Girls on plan)	144	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor SE Boys (Girls on plan)	288	SF	6	10+ years	
	Water Closet	2nd Floor SE Boys (Girls on plan)	200	EA	7	10+ years	
	Accessories	2nd Floor SW Boys (Girls on plan)	349	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor SW Boys (Girls on plan)	349	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	2nd Floor SW Boys (Girls on plan)	349	SF	7	10+ years	
	Floor Drain	2nd Floor SW Boys (Girls on plan)	1	EA	7	10+ years	
	Lavatory	2nd Floor SW Boys (Girls on plan)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor SW Boys (Girls on plan)	6	EA	'	6-10 years	



atego	ry : Room		B	uilding	: Main		
-						Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Partitions	2nd Floor SW Boys (Girls on plan)	2	EA	7	10+ years	
	Urinals	2nd Floor SW Boys (Girls on plan)	7	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor SW Boys (Girls on plan)	144	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor SW Boys (Girls on plan)	144	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor SW Boys (Girls on plan)	288	SF	6	10+ years	
	Water Closet	2nd Floor SW Boys (Girls on plan)	2	EA	7	10+ years	
	Accessories	3rd Floor NE Girls (Boys on plan)	331	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor NE Girls (Boys on plan)	331	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	3rd Floor NE Girls (Boys on plan)	331	SF	7	10+ years	
	Floor Drain	3rd Floor NE Girls (Boys on plan)	1	EA	7	6-10 years	
	Lavatory	3rd Floor NE Girls (Boys on plan)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor NE Girls (Boys on plan)	8	EA	6	6-10 years	
	Partitions	3rd Floor NE Girls (Boys on plan)	9	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor NE Girls (Boys on plan)	144	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor NE Girls (Boys on plan)	144	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor NE Girls (Boys on plan)	288	SF	6	10+ years	
	Water Closet	3rd Floor NE Girls (Boys on plan)	9	ĒA	7	10+ years	
	Accessories	3rd Floor NW Girls (Boys on plan)	331	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor NW Girls (Boys on plan)	331	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	3rd Floor NW Girls (Boys on plan)	331	SF	5	10+ years	
	Floor Drain	3rd Floor NW Girls (Boys on plan)	1	EA	7	10+ years	
	Lavatory	3rd Floor NW Girls (Boys on plan)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor NW Girls (Boys on plan)	8	EA	6	6-10 years	
	Partitions	3rd Floor NW Girls (Boys on plan)	9	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor NW Girls (Boys on plan)	144	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor NW Girls (Boys on plan)	144	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor NW Girls (Boys on plan)	288	SF	6	10+ years	
	Water Closet	3rd Floor NW Girls (Boys on plan)	9	EA	7	10+ years	
	Accessories	3rd Floor SE Boys (Girls on plan)	349	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor SE Boys (Girls on plan)	349	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	3rd Floor SE Boys (Girls on plan)	349	SF	7	10+ years	
	Floor Drain	3rd Floor SE Boys (Girls on plan)	1	EA	7	10+ years	
	Lavatory	3rd Floor SE Boys (Girls on plan)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor SE Boys (Girls on plan)	8	EA	6	6-10 years	
	Partitions	3rd Floor SE Boys (Girls on plan)	o 2	EA	7	10+ years	
	Urinals	3rd Floor SE Boys (Girls on plan)	7	EA	7	•	
				SF	6	10+ years	
	Walls - Concrete Block	3rd Floor SE Boys (Girls on plan)	144	SF	-	10+ years	
	Walls - Plaster/Drywall	3rd Floor SE Boys (Girls on plan)	144		6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor SE Boys (Girls on plan)	288	SF	6	10+ years	
	Water Closet	3rd Floor SE Boys (Girls on plan)	2	EA	7	10+ years	
		3rd Floor SW Boys (Girls on plan)	349	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor SW Boys (Girls on plan)	349	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	3rd Floor SW Boys (Girls on plan)	349	SF	7	10+ years	
	Floor Drain	3rd Floor SW Boys (Girls on plan)	1	EA	7	10+ years	



Category : Room **Building : Main** Recommend Quantity Group Item - Type Location UOM Rank Replacement Comments Lavatorv 3rd Floor SW Boys (Girls on plan) 2 ΕA 10+ vears 7 3rd Floor SW Boys (Girls on plan) 8 ΕA 6-10 vears Lighting - Pendent/Surface 6 Partitions 3rd Floor SW Boys (Girls on plan) 2 FΑ 7 10+ years 3rd Floor SW Boys (Girls on plan) 6 7 Urinals ΕA 10+ years SF Walls - Concrete Block 3rd Floor SW Boys (Girls on plan) 144 6 10+ years SF 3rd Floor SW Boys (Girls on plan) Walls - Plaster/Drywall 144 6 10+ years Walls - Tile Ceramic/ Porcelain 3rd Floor SW Boys (Girls on plan) 288 SF 6 10+ years Water Closet 3rd Floor SW Boys (Girls on plan) 2 EΑ 7 10+ vears Accessories Main Gym Office Toilet Room 70 SF 7 6-10 years SF Ceiling - Plaster/Drvwall Main Gvm Office Toilet Room 70 6 10+ vears Main Gvm Office Toilet Room Doors - Wood Doors inclu hw 1 ΕA 7 10+ vears Floor - Tile Ceramic/ Porcelain Main Gym Office Toilet Room 70 SF 6 10+ years Main Gym Office Toilet Room ΕA 7 10+ years Lavatory 1 Lighting - Pendent/Surface Main Gym Office Toilet Room 1 EΑ 6 6-10 years Partitions Main Gym Office Toilet Room ΕA 7 1 10+ years Main Gym Office Toilet Room FΑ Showers 1 4 0-1 year Missing. SF 6 Walls - Masonry Main Gvm Office Toilet Room 210 10+ vears SF Walls - Plaster/Drywall Main Gvm Office Toilet Room 200 6 10+ years Main Gvm Office Toilet Room ΕA Water Closet 1 7 10+ vears Accessories Mens East of Lobby 180 SF 7 6-10 years Ceiling - Plaster/Drywall Mens East of Lobby 180 SF 6 10+ years 7 Doors - Wood Doors inclu hw Mens East of Lobby 1 EΑ 10+ years SF Floor - Tile Ceramic/ Porcelain Mens East of Lobby 180 6 10+ years 7 Floor Drain Mens East of Lobby FΑ 10+ years 1 EΑ 7 Lavatorv Mens East of Lobby 1 10+ years Lighting - Pendent/Surface Mens East of Lobby 4 FΑ 6 6-10 years 7 Partitions Mens East of Lobby 1 ΕA 10+ years Mens East of Lobby 4 ΕA 7 Urinals 10+ years Walls - Plaster/Drywall SF Mens East of Lobby 540 6 10+ years Water Closet Mens East of Lobby ΕA 7 10+ years 1 West of front lobby 90 SF 7 6-10 years Accessories SF Ceiling - Plaster/Drvwall West of front lobby 90 6 10+ vears FΑ 7 Doors - Wood Doors inclu hw West of front lobby 1 10+ vears Floor - Tile Ceramic/ Porcelain West of front lobby 90 SF 6 10+ years 3 7 Lavatory West of front lobby EΑ 10+ years Lighting - Pendent/Surface 3 ΕA West of front lobby 6 6-10 years 2 Partitions West of front lobby EΑ 5 10+ years Walls - Plaster/Drywall SF West of front lobby 360 6 10+ years Water Closet West of front lobby 2 EΑ 7 10+ years SF Accessories in Office 107 Principal Office 40 7 6-10 years in Office 107 Principal Office SF Ceiling - Plaster/Drywall 40 6 10+ years Doors - Wood Doors inclu hw in Office 107 Principal Office FΑ 7 1 10+ vears Floor - Tile in Office 107 Principal Office 40 SF 6 10+ years

Lavatory

in Office 107 Principal Office

ΕA

1

7

10+ years



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	in Office 107 Principal Office	1	EA	6	6-10 years	
	Partitions	in Office 107 Principal Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	in Office 107 Principal Office	212	SF	6	10+ years	
	Water Closet	in Office 107 Principal Office	1	EA	7	10+ years	

Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #104 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	94	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	982	SF	6	10+ years	
	Doors - Transom Window	1st Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	982	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,465	SF	6	10+ years	
Classroo	m #106 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,088	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,088	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,570	SF	6	10+ years	
Classroo	m #116 (Pre School)						
	AC Units	1st Floor	2	EA	7	2-5 years	
	Casework	1st Floor	23	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	626	SF	6	10+ years	
	Doors - Transom Window	1st Floor	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	626	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,208	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	m #118 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	665	SF	6	10+ years	



Jatego	ategory : Classroom		В	uilding	: Main		
_						Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	1st Floor	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	665	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,184	SF	6	10+ years	
Classroo	m #119 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	680	SF	6	10+ years	
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	7	10+ years	
	Floor - Tile	1st Floor	680	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,120	SF	6	10+ years	
Nooroo	m #123 (Kindergarten)						
1992100	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	673	SF	6	10+ years	
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7		
	Doors - Wood Doors inclu hw	1st Floor	9	EA	7	10+ years	
						10+ years	
	Floor - Wood	1st Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	17	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,116	SF	6	10+ years	
Classroo	m #125 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	680	SF	6	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	680	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
		1st Floor	1,120	SF	6	10+ years	



Catego	ory : Classroom		В	uilding	: Main		W 24th BOOLE VAND, Officago, IE 00020
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,354	SF	6	10+ years	
	Doors - Transom Window	1st Floor	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	1,354	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,731	SF	6	10+ years	
Classroo	om #127 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	673	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	5	EA	7	10+ years	
	Floor - Wood Doors meld hw	1st Floor	673	SF	6	10+ years	
		1st Floor	12	EA		6-10 years	
	Lighting - Pendent/Surface		12		6		
	Marker Board	1st Floor			7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,116	SF	6	10+ years	
Classroo	om #130 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,644	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,644	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	6	6-10 years	
	Storage/ Closet	1st Floor	430	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,227	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #133 (Store Room)						
	Ceiling - Exposed	1st Floor	1,885	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years	
	Floor - Concrete	1st Floor	1,885	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	32	EA	6	6-10 years	
	Storage/ Closet	1st Floor	275	SF	7	10+ years	
	Walls - Masonry	1st Floor	2,600	SF	6	10+ years	
Classroo	om #143 (Other Instructional Use)						
	Ceiling - Exposed	1st Floor	430	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,200	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
		13(1100)	5		1	io+ years	



Cateoo	ategory : Classroom			uilding	: Main		
Julioge				anang	. main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	1,630	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	44	EA	6	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Walls - Masonry	1st Floor	2.770	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	230	SF	6	10+ years	
	Work Sink	1st Floor	230	EA	7	10+ years	
lassro	om #144 (Other Instructional Use)						
	Casework	1st Floor	52	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	375	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,000	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	285	SF	6	10+ years	
	Doors - Side-lite	1st Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	ĒA	7	10+ years	
	Floor - Tile	1st Floor	1,645	SF	6	10+ years	
	Floor - Tile	1st Floor	15	SF	4	1-2 years	Broken tiles
	Lighting - Pendent/Surface	1st Floor	30	EA	6	6-10 years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Masonry	1st Floor	2,100	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	290	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
lassroo	om #202 (Computer Lab)						
	AC Units	2nd Floor	4	EA	7	10+ years	
	Casework	2nd Floor	44	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,247	SF	6	10+ years	
	Chalk Board	2nd Floor	5	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,247	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	36	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	58	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,403	SF	6	10+ years	
	Wireless System	2nd Floor	[′] 1	EA	7	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
lassro	om #206 (Computer Lab)						
i accirci	AC Units	2nd Floor	4	EA	7	6-10 years	
<u></u>		2nd Floor	38	LF	7	10+ years	
	Casework	2110 F1001				-	
	Casework Ceiling - Plaster/Drywall	2nd Floor	1,247	SF	6	10+ years	
			1,247 5	SF LF	6 4	10+ years 2-5 years	
	Ceiling - Plaster/Drywall	2nd Floor				•	
	Ceiling - Plaster/Drywall Chalk Board	2nd Floor 2nd Floor	5	LF	4	2-5 years	



Category : Classroom			В	uilding	: Main		
-	-			-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Storage/ Closet	2nd Floor	58	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,410	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
lassroo	m #212 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	673	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	17	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,059	SF	6	10+ years	
Classroo	m #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	21	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	673	SF	6	10+ years	
	Chalk Board	2nd Floor	31	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,146	SF	6	10+ years	
Classroo	m #214 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	680	SF	6	10+ years	
	Chalk Board	2nd Floor	36	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	5	EA	7	10+ years	
	Floor - Wood	2nd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,189	SF	6	10+ years	
lassroo	m #215 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
		2110 1 1001	2		'		



Catego	ry : Classroom		В	uilding	: Main		
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Ceiling - Plaster/Drywall	2nd Floor	673	SF	6	10+ years	
	Chalk Board	2nd Floor	31	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,146	SF	6	10+ years	
Classroo	m #216 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	80	LF	7	10+ years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,062	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,062	SF	6	10+ years	
	Gas Line	2nd Floor	10	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,348	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
	Work Sink	2nd Floor	2	EA	7	6-10 years	
Classroo	m #217 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	673	SF	6	10+ years	
	Chalk Board	2nd Floor	9	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years	
	Floor - Wood	2nd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒA	6	6-10 years	
	Marker Board	2nd Floor	5	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years	
Classroo	m #219 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	680	SF	6	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	680	SF	6	10+ years	



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,130	SF	6	10+ years	
						2	
lassroo	m #220 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	25	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	602	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	602	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,131	SF	6	10+ years	
	-		, -			,	
lassroc	m #221 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	673	SF	6	10+ years	
	Chalk Board	2nd Floor	5	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years	
lassroo	m #223 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	680	SF	6	10+ years	
	Chalk Board	2nd Floor	7	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	680	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	6	LA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,116	SF	6	6-10 years	
		21011001	1,110	0	0	0 10 years	
lassroc	m #224 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	50	LF	7	10+ years	
	Casework	2nd Floor	121	LF	7	10+ years	



Category : Classroom			В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	1,062	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	862	SF	6	10+ years	
	Gas Line	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	28	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,316	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #225 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	680	SF	6	10+ years	
	Chalk Board	2nd Floor	9	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	680	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years	
Classroo	om #226 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	673	SF	6	10+ years	
	Chalk Board	2nd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,116	SF	6	10+ years	
Classroc	om #227 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	680	SF	6	10+ years	
	Chalk Board	2nd Floor	9	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	680	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years	
<u></u>							
	m #228 (Regular Classroom)		2	Ξ.		0.40	
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	42	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	779	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	779	SF	4	0-1 year	Chipping, cracking throughout.
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,169	SF	6	10+ years	
Classroo	m #302 (Science Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	84	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	985	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	985	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	28	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,474	SF	6	10+ years	
	Work Sink	3rd Floor	3	EA	7	6-10 years	
	Work Sink		5	LA	,	0-10 years	
Classroo	m #304 (Science Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	98	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,152	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,152	SF	6	10+ years	
	Gas Line	3rd Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	27	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,647	SF	6	10+ years	
	Work Sink	3rd Floor	3	EA	7	6-10 years	
Classroo	m #305 (Science Classroom)						
	AC Units	3rd Floor	3	EA	7	6-10 years	
	Casework	3rd Floor	87	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,027	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		o w 2 har BOOLE Wates, omongo, ie ooolo
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,027	SF	6	10+ years	
	Gas Line	3rd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	28	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,512	SF	6	10+ years	
	Work Sink	3rd Floor	3	EA	7	6-10 years	
Classroo	om #308 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	16	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	703	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	. <u> </u>	EA	7	10+ years	
	Floor - Wood	3rd Floor	703	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,267	SF	6	10+ years	
			.,	•	Ū	let yeare	
Classroo	om #309 (Science Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	94	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,128	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,128	SF	6	10+ years	
	Gas Line	3rd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	27	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,621	SF	6	10+ years	
	Work Sink	3rd Floor	3	EA	7	6-10 years	
Classroo	om #310 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	703	SF	6	10+ years	
	Chalk Board	3rd Floor	5	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	703	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Martor Board		20		'	o io youio	



Catego	Category : Classroom		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	1,225	SF	6	10+ years	
						-	
lassroo	m #311 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	703	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	703	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,267	SF	6	10+ years	
						-	
Classroo	m #312 (Regular Classroom)				_	10	
	AC Units	3rd Floor	2	EA	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	441	SF	6	10+ years	
	Chalk Board	3rd Floor	5	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years	
	Floor - Wood	3rd Floor	441	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	6	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	990	SF	6	10+ years	
lassroc	m #313 (Art Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	154	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,143	SF	6	10+ years	
	Chalk Board	3rd Floor	11	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	- 1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,143	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	27	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	22	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,138	SF	6	10+ years	
	Work Sink	3rd Floor	7	EA	6 5	2-5 years	
	WOR SINK	310 F1001	/	EA	5	2-5 years	
lassroo	m #314 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	703	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
				J		Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Tile	3rd Floor	703	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,225	SF	6	10+ years	
lassroo	om #315 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	703	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,225	SF	6	10+ years	
Classroo	om #316 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	11	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	673	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒA	7	10+ years	
	Floor - Wood	3rd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	ĒA	6	6-10 years	
	Marker Board	3rd Floor	29	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,199	SF	6	10+ years	
Classroo	om #317 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	62	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,140	SF	6	10+ years	
	Chalk Board	3rd Floor	5	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,140	SF	5	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	6	6-10 years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,589	SF	6	10+ years	
	-		1,005	01	Ū	Tor years	
lassroo	om #318 (Regular Classroom) AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	21				
		3rd Floor 3rd Floor		SF	7	10+ years	
	Ceiling - Plaster/Drywall Chalk Board		1,015	SF LF	6	10+ years	
	UTIAIK DUALU	3rd Floor	3	LF	4	2-5 years	



Catego	ory : Classroom		B	uilding	: Main		
_			• • • •			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,015	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	6	6-10 years	
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,498	SF	6	10+ years	
lassroo	om #320 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	673	SF	6	10+ years	
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	ĒA	6	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,199	SF	6	10+ years	
	AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	2 54 1,140 12 1 1,140 21 18	EA LF SF EA SF EA LF	7 7 6 7 6 6 7	6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,612	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
assroo	om #322 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	19	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,015	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,015	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	6	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,498	SF	6		



Catogo	ry : Classroom		D	uilding	· Main	200	50 W 24th BOULEVARD, Chicago, IL 60623
Calego	ry . Classiooni		В	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	AC Units	3rd Floor	2	EA	7	6-10 years	Comments
	Casework	3rd Floor	7	LA	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	500	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw		2	EA			
		3rd Floor			7	10+ years	
	Floor - Tile	3rd Floor	500	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	11	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	735	SF	6	10+ years	
Classroo	om #326 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	673	SF	6	10+ years	
	Chalk Board	3rd Floor	34	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	ĒA	6	6-10 years	
	Marker Board	3rd Floor	17	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,199	SF	6	10+ years	
Closeror	om #327 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
		3rd Floor	114	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,143	SF LF	6	10+ years	
	Chalk Board	3rd Floor	9		4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,143	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	19	EA	6	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	45	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,686	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	5	6-10 years	
Classroo	om #328 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
_	-			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,279	SF	6	10+ years	
	- -					-	
lassroo	m #329 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	23	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,279	SF	6	10+ years	
	-					2	
lassroo	m #331 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	648	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	648	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,171	SF	6	10+ years	
laseroo	m #332 (Regular Classroom)						
///////////////////////////////////////	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	109	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,322	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,322	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	35	EA	6	6-10 years	
	Marker Board	3rd Floor	9	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	22	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,931	SF	6	10+ years	
			1,301	0	0	IOF years	
lassroo	m #333 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	970	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main	285	
outogo				anang	. main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	3rd Floor	970	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	6	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	56	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,506	SF	6	10+ years	
			1,000	0.	Ũ	let youro	
lassroo	m #334 (Other Instructional Use)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	96	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,354	SF	6	10+ years	
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,354	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	5	EA	4	1-2 years	Damaged light fixture
	Lighting - Pendent/Surface	3rd Floor	29	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	22	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,965	SF	6	10+ years	
			.,		-	, e e g e en e	
lassroo	m #335 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	37	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,026	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,026	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	30	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,506	SF	6	10+ years	
lassroo	m #336 (Regular Classroom)						
1000100	AC Units	3rd Floor	3	EA	7	6-10 years	
	Casework	3rd Floor	37	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,026	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,026	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	30	EA	6	6-10 years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,506	SF	6	10+ years	
	trails Flaster/Drywall		1,000	0	0	ior years	
lassroo	m #337 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	



Catego	Category : Classroom			uilding	• Main	200	50 W 24th BOULEVARD, Chicago, IL 60623
Juicyu				anang	. mann	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Ceiling - Plaster/Drywall	3rd Floor	704	SF	6	10+ years	Commente
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	704	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	ĒA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,225	SF	6	10+ years	
Classroo	om #338 (Special Program)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	360	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	360	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	6	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	929	SF	6	10+ years	
Classroo	om #339 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	672	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	672	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
Classroo	om #340 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	672	SF	6	10+ years	
	Chalk Board	3rd Floor	3	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	672	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	19	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	



Catego	ory : Classroom		В	uilding	: Main		o w 24th DOOLE WAYD, Onleago, ie 00020
e alege	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	om #341 (Regular Classroom)					•	
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	672	SF	6	10+ years	
	Chalk Board	3rd Floor	27	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	672	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
	Walls - Flaster/Drywall		1,191	01	0	TO+ years	
Classroo	om #342 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	672	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	672	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
Classro	om #343 (Regular Classroom)						
_0/255100	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	672	SF	6	10+ years	
	Chalk Board	3rd Floor	29	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	29 70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	70	EA	7	10+ years	
	Floor - Wood Doors meld hw	3rd Floor	672	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	8	LA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
			1,101	0.	U	ior youro	
Classroo	om #344 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	672	SF	6	10+ years	
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	672	SF	6	10+ years	



Caterra			2850 W 24th BOULEVARD, Chicago, IL 6062 Building : Main						
atego	ry : Classroom		В	ullaing	: wan	- ·			
			-			Recommend			
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years			
	Marker Board	3rd Floor	14	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years			
lassroo	om #346 (Regular Classroom)								
	AC Units	3rd Floor	2	EA	7	6-10 years			
	Casework	3rd Floor	7	LF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	672	SF	6	10+ years			
	Chalk Board	3rd Floor	12	LF	4	2-5 years			
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Wood	3rd Floor	672	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years			
	Marker Board	3rd Floor	10	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years			
lassror	om #400 (Band Room)								
1233100	Casework	4th Floor	16	LF	7	10+ years			
	Casework Ceiling - Lay-in	4th Floor	2,396	SF	6				
	Ceiling - Lay-in	4th Floor	2,390	SF	4	10+ years	Water demoge		
	Chalk Board	4th Floor	4 22	LF		1-2 years	Water damage		
	Doors - Steel Doors incl hw	4th Floor		EA	4 7	2-5 years			
			2	SF	6	10+ years			
	Floor - Wood	4th Floor 4th Floor	2,400	SF LF	-	10+ years			
	Instrument Storage Casework		16	EA	7	10+ years			
	Lighting - Lay-in	4th Floor	36		6	6-10 years			
	Marker Board	4th Floor	22	LF	7	6-10 years			
	Storage/ Closet	4th Floor	53	SF	7	10+ years			
	Storage/ Closet	4th Floor	53	SF	7	10+ years			
	Storage/ Closet	4th Floor	28	SF	7	10+ years			
	Storage/ Closet	4th Floor	28	SF	5	10+ years			
	Walls - Plaster/Drywall	4th Floor	2,986	SF	6	10+ years			
atego	ry : Interior		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
orridor									
	Ceiling - Plaster/Drywall	1st FIr BOH (next to 133)	450	SF	6	10+ years			
	Doors - Wood Doors include hw	1st FIr BOH (next to 133)	2	EA	7	10+ years			
	Floor - Concrete	1st FIr BOH (next to 133)	250	SF	7	10+ years			
	Floor - Tile/Sheet	1st Flr BOH (next to 133)	200	SF	7	10+ years			
			•		•	0.40			

Lighting - Pendent/Surface

Walls - Plaster/Drywall

Ceiling - Plaster/Drywall

ΕA

SF

SF

6

1,900

133

6

6

6

6-10 years

10+ years

10+ years

1st Flr BOH (next to 133)

1st Flr BOH (next to 133)

1st Flr between Gym + Locker



Category : Interior			В	uilding	: Main		0 W 24th BOULEVARD, Chicago, IL 60623
e alege						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Room	-			-	
	Doors - Wood Doors include hw	1st Flr between Gym + Locker	2	EA	7	10+ years	
		Room					
	Floor - Tile/Sheet	1st Flr between Gym + Locker	133	SF	7	10+ years	
		Room					
	Lighting - Pendent/Surface	1st Flr between Gym + Locker	2	EA	6	6-10 years	
		Room	450	05	0	40	
	Walls - Plaster/Drywall	1st Flr between Gym + Locker	450	SF	6	10+ years	
	Ceiling Europeed	Room	400	05	0	10	
	Ceiling - Exposed	1st Flr to Class 130 (each side) 1st Flr to Class 130 (each side)	132	SF SF	6 7	10+ years	
	Doors - Transom Window Doors - Wood Doors include hw	1st Fir to Class 130 (each side)	14 4	EA	7	10+ years 10+ years	
	Floor - Concrete	1st Fir to Class 130 (each side)	77	SF	7	10+ years	
	Floor - Tile/Sheet	1st Fir to Class 130 (each side)	63	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Fir to Class 130 (each side)	3	EA	6	6-10 years	
	Stairs - Concrete Stairs	1st Fir to Class 130 (each side)	60	LF	7	10+ years	
	Walls - Masonry	1st Fir to Class 130 (each side)	788	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Flr @ Kitchen "Passage"	219	SF	6	10+ years	
	Doors - Wood Doors include hw	2nd Flr @ Kitchen "Passage"	1	EA	7	10+ years	
	Floor - Concrete	2nd Flr @ Kitchen "Passage"	219	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Flr @ Kitchen "Passage"	3	EA	6	6-10 years	
	Walls - Metal Panel	2nd Flr @ Kitchen "Passage"	315	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Flr @ Kitchen "Passage"	715	SF	6	10+ years	
	Ceiling - Exposed	First Floor Corridors	1,600	SF	6	10+ years	
	Ceiling - Plaster/Drywall	First Floor Corridors	19,241	SF	6	10+ years	
	Doors - Steel Doors incl hw	First Floor Corridors	3	EA	7	10+ years	
	Doors - Transom Window	First Floor Corridors	72	SF	7	10+ years	
	Doors - Wood Doors include hw	First Floor Corridors	8	EA	7	10+ years	
	Drinking Fountains - Single Fountain	First Floor Corridors	12	EA	7	6-10 years	
	Floor - Terrazzo	First Floor Corridors	3,173	SF SF	7	10+ years	
	Floor - Tile/Sheet Lighting - Pendent/Surface	First Floor Corridors First Floor Corridors	16,100 200	EA	7 6	10+ years	
	Student Lockers - One Tier	First Floor Corridors	200 745	EA	7	6-10 years 10+ years	
	Walls - Plaster/Drywall	First Floor Corridors	25,635	SF	6	10+ years	
	Ceiling - Plaster/Drywall	First Floor Main Entry Vestibule	25,035	SF	6	10+ years	
	Doors - Transom Window	First Floor Main Entry Vestibule	81	SF	7	10+ years	
	Doors - Wood Doors include hw	First Floor Main Entry Vestibule	9	EA	7	10+ years	
	Floor - Terrazzo	First Floor Main Entry Vestibule	200	SF	7	10+ years	
	Floor - Tile/Sheet	First Floor Main Entry Vestibule	60	SF	7	10+ years	
	Lighting - Pendent/Surface	First Floor Main Entry Vestibule	6	EA	6	6-10 years	
	Walls - Plaster/Drywall	First Floor Main Entry Vestibule	390	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Second Floor Corridors	10,464	SF	6	10+ years	
	Doors - Transom Window	Second Floor Corridors	72	SF	7	10+ years	
	Doors - Wood Doors include hw	Second Floor Corridors	8	EA	7	10+ years	



Catego	ry : Interior		B	Building : Main				
-	· · · · · · · · · · · · · · · · · · ·					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Drinking Fountains - Single Fountain	Second Floor Corridors	4	EA	7	6-10 years		
	Floor - Tile/Sheet	Second Floor Corridors	10,464	SF	7	10+ years		
	Lighting - Pendent/Surface	Second Floor Corridors	119	EA	6	6-10 years		
	Student Lockers - One Tier	Second Floor Corridors	551	EA	7	10+ years		
	Walls - Plaster/Drywall	Second Floor Corridors	16,999	SF	6	10+ years		
	Ceiling - Plaster/Drywall	Third Floor Corridors	12,188	SF	6	10+ years		
	Doors - Wood Doors include hw	Third Floor Corridors	4	EA	7	10+ years		
	Drinking Fountains - Single Fountain	Third Floor Corridors	4	EA	7	6-10 years		
	Floor - Tile/Sheet	Third Floor Corridors	3,456	SF	7	10+ years		
	Floor - Tile/Sheet	Third Floor Corridors	8,732	SF	7	10+ years		
	Lighting - Pendent/Surface	Third Floor Corridors	158	EA	6	6-10 years		
	Student Lockers - One Tier	Third Floor Corridors	648	EA	7	10+ years		
	Walls - Plaster/Drywall	Third Floor Corridors	21,251	SF	6	10+ years		
Safety								
Duroty	Camera Viewing Station	Entire Building	1	EA	7	6-10 years		
	Security Cameras	Entire Building	3	EA	7	6-10 years		
	Security Cameras	Entire Building	11	EA	7	6-10 years		
	Security Cameras	Entire Building	2	EA	7	6-10 years		
Stairs								
orano	Ceiling - Plaster/Drywall	Girls Gym - NE Stairway	350	SF	6	10+ years		
	Floor - Terrazzo	Girls Gym - NE Stairway	375	SF	6	10+ years		
	Handrails	Girls Gym - NE Stairway	64	LF	7	10+ years		
	Lighting - Pendent/Surface	Girls Gym - NE Stairway	3	EA	6	6-10 years		
	Lighting - Wall Mounted	Girls Gym - NE Stairway	1	EA	6	6-10 years		
	Stairs - Terrazzo	Girls Gym - NE Stairway	28	LF	6	10+ years		
	Walls - Plaster/Drywall	Girls Gym - NE Stairway	1,287	SF	6	10+ years		
	Ceiling - Plaster/Drywall	Girls gym-SW	270	SF	6	10+ years		
	Floor - Terrazzo	Girls gym-SW	210	SF	6	10+ years		
	Handrails	Girls gym-SW	64	LF	7	10+ years		
	Lighting - Pendent/Surface	Girls gym-SW	3	EA	6	6-10 years		
	Lighting - Wall Mounted	Girls gym-SW	1	EA	6	6-10 years		
	Stairs - Terrazzo	Girls gym-SW	149	LF	6	10+ years		
	Walls - Plaster/Drywall	Girls gym-SW	595	SF	6	10+ years		
	Ceiling - Plaster/Drywall	Main Entry Stairs (East)	756	SF	6	10+ years		
	Floor - Asphalt	Main Entry Stairs (East)	54	SF	6	10+ years		
	Floor - Tile	Main Entry Stairs (East)	547	SF	6	10+ years		
	Handrails	Main Entry Stairs (East)	581	LF	7	10+ years		
	Lighting - Pendent/Surface	Main Entry Stairs (East)	8	EA	6	6-10 years		
	Lighting - Wall Mounted	Main Entry Stairs (East)	4	EA	6	6-10 years		
	Stairs - Asphalt	Main Entry Stairs (East)	448	LF	6	10+ years		
	Walls - Plaster/Drywall	Main Entry Stairs (East)	2,216	SF	6	10+ years		
	Ceiling - Plaster/Drywall	Main Entry Stairs (West)	756	SF	6	10+ years		



Category : InteriorBuilding : MainGroupItem - TypeLocationQuantityWinGroupItem - TypeLocationQuantityUOMRankReplacementCommentsFloor - AsphaltMain Entry Stairs (West)54SF610+ years610+ yearsFloor - TileMain Entry Stairs (West)547SF610+ years610+ yearsHandrailsMain Entry Stairs (West)581LF710+ years610+ yearsLighting - Pendent/SurfaceMain Entry Stairs (West)8EA66-10 years6Stairs - AsphaltMain Entry Stairs (West)5EA610+ years6Walls - Plaster/DrywallMain Entry Stairs (West)2,216SF610+ years6Valls - Plaster/DrywallNortheast Stairwell728SF610+ years7Floor - TileNortheast Stairwell672SF610+ years6Floor - TileNortheast Stairwell672SF610+ years6HandrailsNortheast Stairwell6EA66-10 years6HandrailsNortheast Stairwell6EA66-10 years6HandrailsNortheast Stairwell6EA66-10 years6HandrailsNortheast Stairwell6EA66-10 years6Hand	
Floor - AsphaltMain Entry Stairs (West)54SF610+ yearsFloor - TileMain Entry Stairs (West)547SF610+ yearsHandrailsMain Entry Stairs (West)581LF710+ yearsLighting - Pendent/SurfaceMain Entry Stairs (West)8EA66-10 yearsLighting - Wall MountedMain Entry Stairs (West)5EA66-10 yearsStairs - AsphaltMain Entry Stairs (West)5EA610+ yearsWalls - Plaster/DrywallMain Entry Stairs (West)2,216SF610+ yearsCeiling - Plaster/DrywallMain Entry Stairs (West)2,216SF610+ yearsFloor - Concrete Epoxy/ PaintedNortheast Stairwell728SF610+ yearsFloor - TileNortheast Stairwell672SF610+ yearsHandrailsNortheast Stairwell175LF710+ yearsLighting - Pendent/SurfaceNortheast Stairwell6EA66-10 yearsHandrailsNortheast Stairwell5EA66-10 yearsLighting - Wall MountedNortheast Stairwell5EA66-10 yearsLighting - Wall Moun	
Floor - AsphaltMain Entry Stairs (West)54SF610+ yearsFloor - TileMain Entry Stairs (West)547SF610+ yearsHandrailsMain Entry Stairs (West)581LF710+ yearsLighting - Pendent/SurfaceMain Entry Stairs (West)8EA66-10 yearsLighting - Wall MountedMain Entry Stairs (West)5EA66-10 yearsStairs - AsphaltMain Entry Stairs (West)448LF610+ yearsWalls - Plaster/DrywallMain Entry Stairs (West)2,216SF610+ yearsCeiling - Plaster/DrywallMain Entry Stairs (West)2,216SF610+ yearsFloor - Concrete Epoxy/ PaintedNortheast Stairwell728SF610+ yearsFloor - TileNortheast Stairwell672SF610+ yearsHandrailsNortheast Stairwell175LF710+ yearsLighting - Pendent/SurfaceNortheast Stairwell6EA66-10 yearsHandrailsNortheast Stairwell5EA66-10 yearsLighting - Wall MountedNortheast Stairwell5EA66-10 yearsLighting - Wall Mo	
HandrailsMain Entry Stairs (West)581LF710+ yearsLighting - Pendent/SurfaceMain Entry Stairs (West)8EA66-10 yearsLighting - Wall MountedMain Entry Stairs (West)5EA66-10 yearsStairs - AsphaltMain Entry Stairs (West)448LF610+ yearsWalls - Plaster/DrywallMain Entry Stairs (West)2,216SF610+ yearsCeiling - Plaster/DrywallNortheast Stairwell728SF610+ yearsFloor - Concrete Epoxy/ PaintedNortheast Stairwell140SF710+ yearsFloor - TileNortheast Stairwell672SF610+ yearsHandrailsNortheast Stairwell175LF710+ yearsLighting - Pendent/SurfaceNortheast Stairwell6EA66-10 yearsLighting - Wall MountedNortheast Stairwell5EA66-10 yearsLighting - Wall MountedNortheast Stairwell5EA66-10 yearsLighting - Wall MountedNortheast Stairwell5EA66-10 yearsStairs - AsphaltNortheast Stairwell429LF610+ years	
Lighting - Pendent/SurfaceMain Entry Stairs (West)8EA66-10 yearsLighting - Wall MountedMain Entry Stairs (West)5EA66-10 yearsStairs - AsphaltMain Entry Stairs (West)448LF610+ yearsWalls - Plaster/DrywallMain Entry Stairs (West)2,216SF610+ yearsCeiling - Plaster/DrywallMortheast Stairwell728SF610+ yearsFloor - Concrete Epoxy/ PaintedNortheast Stairwell140SF710+ yearsFloor - TileNortheast Stairwell672SF610+ yearsHandrailsNortheast Stairwell175LF710+ yearsLighting - Pendent/SurfaceNortheast Stairwell6EA66-10 yearsLighting - Wall MountedNortheast Stairwell5EA66-10 yearsStairs - AsphaltNortheast Stairwell5EA610+ yearsStairs - AsphaltNortheast Stairwell429LF610+ years	
Lighting - Wall MountedMain Entry Stairs (West)5EA66-10 yearsStairs - AsphaltMain Entry Stairs (West)448LF610+ yearsWalls - Plaster/DrywallMain Entry Stairs (West)2,216SF610+ yearsCeiling - Plaster/DrywallNortheast Stairwell728SF610+ yearsFloor - Concrete Epoxy/ PaintedNortheast Stairwell140SF710+ yearsFloor - TileNortheast Stairwell672SF610+ yearsHandrailsNortheast Stairwell175LF710+ yearsLighting - Pendent/SurfaceNortheast Stairwell6EA66-10 yearsLighting - Wall MountedNortheast Stairwell5EA66-10 yearsStairs - AsphaltNortheast Stairwell429LF610+ years	
Lighting - Wall MountedMain Entry Stairs (West)5EA66-10 yearsStairs - AsphaltMain Entry Stairs (West)448LF610+ yearsWalls - Plaster/DrywallMain Entry Stairs (West)2,216SF610+ yearsCeiling - Plaster/DrywallNortheast Stairwell728SF610+ yearsFloor - Concrete Epoxy/ PaintedNortheast Stairwell140SF710+ yearsFloor - TileNortheast Stairwell672SF610+ yearsHandrailsNortheast Stairwell175LF710+ yearsLighting - Pendent/SurfaceNortheast Stairwell6EA66-10 yearsLighting - Wall MountedNortheast Stairwell5EA66-10 yearsStairs - AsphaltNortheast Stairwell429LF610+ years	
Walls - Plaster/DrywallMain Entry Stairs (West)2,216SF610+ yearsCeiling - Plaster/DrywallNortheast Stairwell728SF610+ yearsFloor - Concrete Epoxy/ PaintedNortheast Stairwell140SF710+ yearsFloor - TileNortheast Stairwell672SF610+ yearsHandrailsNortheast Stairwell175LF710+ yearsLighting - Pendent/SurfaceNortheast Stairwell6EA66-10 yearsLighting - Wall MountedNortheast Stairwell5EA66-10 yearsStairs - AsphaltNortheast Stairwell429LF610+ years	
Ceiling - Plaster/DrywallNortheast Stairwell728SF610+ yearsFloor - Concrete Epoxy/ PaintedNortheast Stairwell140SF710+ yearsFloor - TileNortheast Stairwell672SF610+ yearsHandrailsNortheast Stairwell175LF710+ yearsLighting - Pendent/SurfaceNortheast Stairwell6EA66-10 yearsLighting - Wall MountedNortheast Stairwell5EA66-10 yearsStairs - AsphaltNortheast Stairwell429LF610+ years	
Floor - Concrete Epoxy/ PaintedNortheast Stairwell140SF710+ yearsFloor - TileNortheast Stairwell672SF610+ yearsHandrailsNortheast Stairwell175LF710+ yearsLighting - Pendent/SurfaceNortheast Stairwell6EA66-10 yearsLighting - Wall MountedNortheast Stairwell5EA66-10 yearsStairs - AsphaltNortheast Stairwell429LF610+ years	
Floor - TileNortheast Stairwell672SF610+ yearsHandrailsNortheast Stairwell175LF710+ yearsLighting - Pendent/SurfaceNortheast Stairwell6EA66-10 yearsLighting - Wall MountedNortheast Stairwell5EA66-10 yearsStairs - AsphaltNortheast Stairwell429LF610+ years	
HandrailsNortheast Stairwell175LF710+ yearsLighting - Pendent/SurfaceNortheast Stairwell6EA66-10 yearsLighting - Wall MountedNortheast Stairwell5EA66-10 yearsStairs - AsphaltNortheast Stairwell429LF610+ years	
Lighting - Pendent/SurfaceNortheast Stairwell6EA66-10 yearsLighting - Wall MountedNortheast Stairwell5EA66-10 yearsStairs - AsphaltNortheast Stairwell429LF610+ years	
Lighting - Wall MountedNortheast Stairwell5EA66-10 yearsStairs - AsphaltNortheast Stairwell429LF610+ years	
Stairs - Asphalt Northeast Stairwell 429 LF 6 10+ years	
Walls - Plaster/Drywall Northeast Stairwell 2,666 SF 6 10+ years	
Ceiling - Plaster/Drywall Northwest Stairwell 728 SF 6 10+ years	
Floor - Concrete Epoxy/ Painted Northwest Stairwell 140 SF 7 10+ years	
Floor - Tile Northwest Stairwell 672 SF 6 10+ years	
Handrails Northwest Stairwell 175 LF 7 10+ years	
Lighting - Pendent/Surface Northwest Stairwell 6 EA 6 6-10 years	
Lighting - Wall Mounted Northwest Stairwell 5 EA 6 6-10 years	
Stairs - Asphalt Northwest Stairwell 429 LF 6 10+ years	
Walls - Metal Panel Northwest Stairwell 80 SF 6 10+ years	
Walls - Plaster/Drywall Northwest Stairwell 2,266 SF 6 10+ years	
Ceiling - Exposed South East 875 SF 6 10+ years	
Ceiling - Plaster/Drywall South East 800 SF 6 10+ years	
Floor - Concrete Epoxy/ Painted South East 340 SF 7 10+ years	
Floor - Tile South East 16 SF 6 10+ years	
Floor - Tile South East 900 SF 6 10+ years	
Handrails South East 286 LF 7 10+ years	
Handrails South East 144 LF 5 6-10 years	
Lighting - Wall Mounted South East 14 EA 6 6-10 years	
Stairs - Asphalt South East 560 LF 6 10+ years	
Stairs - Concrete South East 50 LF 7 10+ years	
Walls - Plaster/DrywallSouth East3,800SF610+ years	
Ceiling - Exposed South West 875 SF 6 10+ years	
Ceiling - Plaster/Drywall South West 800 SF 6 10+ years	
Floor - Concrete Epoxy/ Painted South West 340 SF 7 10+ years	
Floor - TileSouth West800SF610+ years	
Floor - TileSouth West116SF610+ years	
HandrailsSouth West286LF710+ years	
Handrails South West 144 LF 5 6-10 years	
Lighting - Wall Mounted South West 14 EA 6 6-10 years	
Stairs - Asphalt South West 560 LF 6 10+ years	



Catego	Category : Interior			uilding	: Main				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
Ī	Stairs - Concrete Walls - Plaster/Drywall	South West South West	50 3,800	LF SF	7 6	10+ years 10+ years			
Vertical	Vertical Conveyance								
	Elevator - Freight Elevator	1st to 3rd floors	1	EA	7	10+ years			



Category : Exterior Building : Addition (Telpochcalli) Recommend Location **Replacement** Comments Item - Type Quantity UOM Group Rank Entrance FΑ 7 Exterior Doors - Overhead Rolling/ Garage 10 Garage Door 1 10+ years Door LF Exterior Stairs - Concrete 10 Garage Door 8 4 0-1 year Cracking and chipping. **Exterior Stairs - Concrete** 10 Garage Door 8 LF 4 0-1 year Cracking and chipping. Exterior Doors - Exterior Steel Door 11 north 1 ΕA 7 10+ years Exterior Stairs - Concrete 11 north 12 LF 4 0-1 year Cracking and chipping. Exterior Doors - Exterior Steel Door 12 south 3 EΑ 6 10+ years Exterior Doors - Transom Lite 12 south 3 ΕA 6 10+ vears LF Exterior Stairs - Concrete 12 south 9 5 0-1 year Cracking and chipping. 1 FΑ 6 Entrance Control - Audio and Video 13 south 10+ vears 2 Exterior Doors - Exterior Steel Door 13 south EΑ 6 10+ years Exterior Doors - Side lite 6 13 south 1 EΑ 10+ years Exterior Stairs - Concrete 13 south 9 1 F 5 0-1 year Cracking and chipping. 2 ΕA Exterior Doors - Exterior Steel Door 14 south 6 10+ years 2 Exterior Doors - Side lite 14 south ΕA 6 10+ years 3 Exterior Doors - Transom Lite FΑ 6 10+ years 14 south Exterior Doors - Exterior Steel Door 7 north 3 ΕA 6 10+ vears 3 Exterior Doors - Transom Lite 7 north FΑ 6 10+ years **Exterior Stairs - Concrete** 21 LF 6 10+ years 7 north Exterior Doors - Exterior Steel Door 3 ΕA 10+ years 8 north 6 Exterior Stairs - Concrete 16 LF 6 8 north 10+ years 2 LF Exterior Stairs - Concrete 8 north 5 0-1 year Cracked concrete/ spalling Exterior Doors - Overhead Rolling/ Garage FΑ 9 Garage Door 1 6 10+ years Door LF 7 Ramps - Concrete 9 Garage Door 6 10+ years Exterior Doors - Exterior Steel Door Fire escape door south 1 EΑ 6 10+ years Fire Escape LF Fire Escape South Façade 50 6 10+ years Foundation Foundation - Concrete Entire Building LF 7 775 10+ years Superstructure - Concrete Entire Building 40,822 SF 7 10+ years Liahtina Exterior Lighting - Parapet or Roof Mounted Entire Building 7 ΕA 7 6-10 years Roof System Access Ladder - Metal O 7 1 ΕA 10+ years Chimney - Brick Chimney- Concrete/ Mortar LF Q 80 7 10+ vears Was fixed. Tuck point Liner



Catego	ry : Exterior		Building : Addition (Telpochcalli)					
	.,		_			Recommend	,	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Coping - Stone	Q	938	LF	7	10+ years		
	Downspouts - Interior Downspouts	Q	200	LF	7	10+ years		
	Parapet - 16" - 30" Height	Q	262	LF	7	10+ years		
	Parapet - Parapet > 30"	Q	676	LF	7	10+ years		
	Roof - Modified Bitumen	Q	20,411	SF	6	10+ years		
	Roof Hatch - Metal	Q	1	EA	5	1-2 years	Rusted.	
	Roof Structure - Concrete	Q	20,411	SF	7	10+ years		
Walls								
	Cornice - Cast Stone	Entire Building	938	LF	7	10+ years		
	Exterior Walls - Brick	Entire Building	10,677	SF	7	10+ years		
	Exterior Walls - Stone-Cast	Entire Building	7,660	SF	7	10+ years		
	Exterior Walls - Stucco	Entire Building	180	SF	7	10+ years		
		-				-		
Windows	s Guard - Guards perforated	Entire Building	2,970	SF	6	10+ years		
	Lintels - Steel	Entire Building	2,970	LF		10+ years		
				SF	6	•		
	Windows - Louver	Entire Building	108	SF	6 6	10+ years		
	Windows - Sash Aluminum Double-pane	Entire Building	10,530	ЪГ	0	10+ years		
Catego	ry : Electrical		В	uilding	: Additi	on (Telpochca	lli)	
•	H					Recommend	0	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Emerger	ncy System							
	Exit Signs - Corridors and Stairs	Entire Building	17	EA	6	2-5 years		
	Emergency Battery Packs - Corridors and Stairs	Entire Building	15	EA	6	6-10 years		
	Security System - CCTV	Entire Building	40,822	SF	5	6-10 years	Cameras on exterior only except 1 in	
					_		link to main building	
	Security System - Intrusion Detection	Entire Building	40,822	SF	6	6-10 years	One system for main and addition	
	Emergency A/C Power - Corridors and Stairs	Entire Building	8,141	SF	6	10+ years		
	Emergency A/C Power - Students Toilets	Entire Building	955	SF	6	10+ years		
Main Se	rvice							
	PA System	Entire Building	40,822	SF	5	6-10 years	Serves addition only	
Power D	Distribution							
	Lighting and Power Panels - 100 A	Entire Building	4	EA	7	10+ years		
				- <i>i</i> · ·				
		Entire Building	2	FA	6	10+ vears	Not labelled	
	Lighting and Power Panels - 100 A	Entire Building Entire Building	2	EA FA	6 6	10+ years 6-10 years	Not labelled	
		Entire Building Entire Building Entire Building	2 3 1	EA EA EA	6 6 4	10+ years 6-10 years 0-1 year	Not labelled Live front fuse panel older than 40 y.	



Catego	ry : Electrical		B	2850 W 24th BOULEVARD, Chicago, IL 60623 Building : Addition (Telpochcalli)				
calege				anang	.,	Recommend	,	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	2	0-1 year	Live front fuse panel greater than 40 y.o.	
	Main Distribution Panels - 400 - 600 amp Transformers - 277/480 - 120/240	Entire Building Entire Building	1 1	EA EA	7 4	10+ years 2-5 years	Old	
Catego	Category : Fire Protection		В	uilding	: Additi	on (Telpochca	lli)	
				-		Recommend	·	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Fire Alar	m							
	Fire Alarm_System	Entire Building	40,822	SF	4	1-2 years	Runs off main building fire panel	
Catego	ry : Mechanical		В	uilding	: Additi	on (Telpochca	lli)	
						Recommend		
Group	ltem - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Air Cond								
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	2	EA	6	6-10 years		
Air Hand	lling Systems							
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	2	EA	6	6-10 years		
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Plenum - AHU-10	1	EA	4	0-1 year	AHU10 serves addition Classrooms 254-260	
	Air Intake	Plenum - AHU-10	1	EA	4	0-1 year	No filters, OA damper stuck in its current position due to failed pneumatic system	
	Auxiliaries - 8001 - 15000 cfm	Plenum - AHU-10	1	EA	4	0-1 year	Door between intake and coil chamber doesn't latch, short-circuits fan airflow back to intake, crumbling masonry and peeling paint	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Plenum - AHU-10	100	LF	5	10+ years		
	Zone Dampers	Plenum - AHU-10	11	EA	4	0-1 year	Pneumatics are defunct, manual control only, old rusty dampers	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Plenum - AHU-8	1	EA	4	0-1 year	AHU 8 serves classrooms 152, 251, 151, 162, 262	
	Air Intake	Plenum - AHU-8	1	EA	4	0-1 year	No filters, OA damper stuck in its current position due to failed pneumatic system	
	Auxiliaries - 8001 - 15000 cfm	Plenum - AHU-8	1	EA	5	2-5 years		
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Plenum - AHU-8	100	LF	5	10+ years		
	Zone Dampers	Plenum - AHU-8	5	EA	4	0-1 year	Pneumatics are defunct, manual control only, old rusty dampers	



Building : Addition (Telpochcalli) Category : Mechanical Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Air Handling Unit- Built Up-Multi Zone-Plenum - AHU-9 FΑ 4 0-1 vear AHU9 serves classrooms 154, 155A. 1 Steam Coils - 8001 - 15000 cfm 155B, 253, 262, 264, and offices, coil partially blocked with cardboard, one or more coils either leaks or is valved off to prevent leaks ΕA Air Intake Plenum - AHU-9 1 4 0-1 year Shares intake with AHU10, no fillers, OA damper stuck in its current position due to failed pneumatic system Auxiliaries - 8001 - 15000 cfm Plenum - AHU-9 ΕA 2-5 vears 1 5 Return Duct Work - Indoor- Vertical Shaft Plenum - AHU-9 100 LF 5 10+ vears and Ducts 7 ΕA Zone Dampers Plenum - AHU-9 4 0-1 year Pneumatics are defunct, manual control only, old rusty dampers Boiler Systems Boiler Room 2 ΕA Boiler Auxiliary- Scotch Marine- Steam Low 5 6-10 years Rust on blowdown pipes, flue elbows Pressure Boiler - Greater than 300 HP Boiler Auxiliary- Scotch Marine- Steam Low Boiler Room 1 ΕA 3 0-1 year Boiler 1 decommissioned Pressure Boiler - Greater than 300 HP Chemical Feed System Boiler Room 1 ΕA 6 6-10 years Combustion Dampers Boiler Room 3 ΕA 6 6-10 vears Feed Water Pumps and Tank Boiler Room 1 FΑ 4 1-2 years Several pumps are nonfunctional per onsite POC, significant rust on pipes. fittings, and pumps **Boiler Room** 2 ΕA 6 Serve main and addition Non Condensing- Fire Tube- Scotch Marine-10+ years Steam- Low Pressure Boiler - Greater than 300 HP Boiler Room FΑ 2 Non Condensing- Fire Tube- Scotch Marine-1 0-1 year Boiler 1 is decommissioned and used Steam- Low Pressure Boiler - Greater than for parts, cannot be run, not needed 300 HP to heat the building, building heat adequate on one boiler most days Piping - Condensate Pipe- Steel Boiler Room 400 LF 3 1-2 years Lots of condensate leaks, especially in pipe tunnel per onsite POC, lots of pipe clamps Piping - Steam Pipe- Steel Boiler Room 400 LF 3 1-2 years Leaks, especially in pipe tunnel per onsite POC Boiler Room FΑ 5 Steam Traps 25 2-5 years Vacuum Pump Boiler Room 1 ΕA 4 1-2 vears Vacuum system must be babysat when running, engineers cannot leave the building with the boilers on because of the unreliability of the

vacuum system



Catego	ry : Mechanical		Building : Addition (Telpochcalli)				
Ŭ	•			Ŭ		Recommend	,
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Heating	Devices						
•	Radiators - Steam	Engineer's Office and Lunch Room	7	EA	5	6-10 years	
	Unit Heater - Gas	Entire Building	1	EA	5	2-5 years	
	Wall Heater - Electric	Entire Building	1	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	3	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	1	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	5	2-5 years	
	Wall Heater - Electric	Entire Building	1	EA	5	2-5 years	
	Wall Heater - Electric	Entire Building	1	EA	5	2-5 years	
	Wall Heater - Electric	Entire Building	2	EA	4	1-2 years	Old, covers missing
	Wall Heater - Electric	Entire Building	2	EA	4	1-2 years	Old heaters, cover off
Tempera	ature Control						
•	Electric Thermostat	Entire Building	2	EA	6	2-5 years	Serve FCUs
	Pneumatic System	Entire Building	40,722	SF	3	0-1 year	Serves main and addition, system
							doesn't hold pressure, inoperable despite brand new compressor
	Thermostats - Pneumatic	Entire Building	23	EA	4	0-1 year	despite brand new compressor
Ventilati	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	

Category : Plumbing

Catego	Category : Plumbing			Building : Addition (Telpochcalli)				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Hot Wate	er							
	Gas Heater - Greater than 600000 BTU/HR	Boiler Room	1	EA	5	2-5 years	Serves main and addition	
	Gas Heater - Greater than 600000 BTU/HR	Boiler Room	1	EA	3	0-1 year	Heater is nonfunctional, has been down for some time, is 29 y.o.	
	Hot Water Storage Tank_Gas - 501 - 1000 Gallons	Boiler Room	2	EA	5	6-10 years		
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	40,822	SF	4	1-2 years	No known active leaks but many pipe clamps are in use, original piping remains in most of building is 90 v.o.	
	Domestic Piping-Cold Water Risers	Entire Building	40,822	SF	4	1-2 years	No known active leaks but many pipe clamps are in use, original piping remains in most of building is 90 y.o.	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	40,822	SF	4	1-2 years	No known active leaks but many pipe clamps are in use, original piping	



Catego	ry : Plumbing		В	Building : Addition (Telpochcalli)					
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
							remains in most of building is 90 y.		
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	40,822	SF	4	1-2 years	No known active leaks but many pi		
							clamps are in use, original piping		
			40.000	05		4.0	remains in most of building is 90 y.		
	Domestic Piping-Hot Water Return Lines	Entire Building	40,822	SF	4	1-2 years	No known active leaks but many pi		
							clamps are in use, original piping		
	Domestic Piping-Hot Water Return Risers	Entire Building	40,822	SF	4	1-2 years	remains in most of building is 90 y. No known active leaks but many pi		
	Domestic Fipling-hot Water Return Risers	Entite Building	40,022	36	4	1-2 years	clamps are in use, original piping		
							remains in most of building is 90 y.		
	Domestic Piping-Hot Water from Risers to	Entire Building	40,822	SF	4	1-2 years	No known active leaks but many pi		
	Fixtures	g	,	•	•)	clamps are in use, original piping		
							remains in most of building is 90 y.		
	Sanitary Piping	Entire Building	40,822	SF	5	2-5 years			
	Storm Piping	Entire Building	40,822	SF	5	2-5 years			
	Vent Piping	Entire Building	40,822	SF	5	2-5 years			
umps	Dumpa Domostia Resistar Dump Durlay	Doilor Doom		۲A	4	2 E veore	Cignificant correction on both survey		
	Pumps - Domestic Booster Pump-Duplex	Boiler Room	1	EA	4	2-5 years	Significant corrosion on both pump		
							both motors, all visible pipe fittings old equipment		

Catego	ry : Room	Building : Addition (Telpochcalli)					
Group	Itom Tuno	Location	Quantity	UOM	Bonk	Recommend	Comments
Group	Item - Type	Location	Quantity		Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Splined	159- Office	347	SF	6	10+ years	
	Doors - Wood Doors inclu hw	159- Office	2	EA	7	10+ years	
	Floor - Tile	159- Office	347	SF	6	10+ years	
	Lighting - Pendent/Surface	159- Office	6	EA	6	6-10 years	
	Power Distribution	159- Office	2	EA	7	10+ years	
	Storage/ Closet	159- Office	44	SF	7	10+ years	
	Walls - Plaster/Drywall	159- Office	716	SF	6	10+ years	
	AC Unit	159A - Interior Office	1	EA	7	6-10 years	
	Ceiling - Splined	159A - Interior Office	55	SF	6	10+ years	
	Doors - Side-lite	159A - Interior Office	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	159A - Interior Office	1	EA	7	10+ years	
	Floor - Tile	159A - Interior Office	55	SF	6	10+ years	
	Lighting - Pendent/Surface	159A - Interior Office	1	EA	6	6-10 years	
	Power Distribution	159A - Interior Office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	159A - Interior Office	288	SF	6	10+ years	
	AC Unit	159B - Interior Office	1	EA	7	6-10 years	
	Ceiling - Splined	159B - Interior Office	97	SF	6	10+ years	
	Doors - Wood Doors inclu hw	159B - Interior Office	1	EA	7	10+ years	



Catego	ry : Room		Building : Addition (Telpochcalli)						
	,		_			Recommend	,		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	Floor - Tile	159B - Interior Office	97	SF	6	10+ years			
	Lighting - Pendent/Surface	159B - Interior Office	2	EA	6	6-10 years			
	Power Distribution	159B - Interior Office	4	EA	7	10+ years			
	Walls - Plaster/Drywall	159B - Interior Office	399	SF	6	10+ years			
	AC Unit	159C-Interior Office	1	EA	7	6-10 years			
	Ceiling - Splined	159C-Interior Office	41	SF	6	10+ years			
	Doors - Side-lite	159C-Interior Office	16	SF	7	10+ years			
	Doors - Wood Doors inclu hw	159C-Interior Office	1	EA	7	10+ years			
	Floor - Tile	159C-Interior Office	41	SF	6	10+ years			
	Lighting - Pendent/Surface	159C-Interior Office	1	EA	6	6-10 years			
	Power Distribution	159C-Interior Office	2	EA	7	10+ years			
	Walls - Plaster/Drywall	159C-Interior Office	217	SF	6	10+ years			
	Ceiling - Splined	160BCopy/Work Room in Main	315	SF	6	10+ years			
		Office				-			
	Doors - Wood Doors inclu hw	160BCopy/Work Room in Main Office	2	EA	7	10+ years			
	Floor - Tile	160BCopy/Work Room in Main Office	315	SF	6	10+ years			
	Lighting - Pendent/Surface	160BCopy/Work Room in Main Office	7	EA	6	6-10 years			
	Power Distribution	160BCopy/Work Room in Main Office	7	EA	7	10+ years			
	Walls - Plaster/Drywall	160BCopy/Work Room in Main Office	598	SF	6	10+ years			
	AC Unit	1st Floor Main Office - Reception Area	1	EA	7	6-10 years			
	Ceiling - Splined	1st Floor Main Office - Reception Area	247	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor Main Office - Reception Area	1	EA	7	10+ years			
	Floor - Tile	1st Floor Main Office - Reception Area	247	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor Main Office - Reception Area	3	EA	6	6-10 years			
	Power Distribution	1st Floor Main Office - Reception Area	4	EA	7	10+ years			
	Storage/ Closet	1st Floor Main Office - Reception Area	15	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor Main Office - Reception Area	537	SF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor Supervising Engineer	115	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor Supervising Engineer	1	EA	7	10+ years			
	Floor - Tile	1st Floor Supervising Engineer	115	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor Supervising Engineer	2	ĒA	6	6-10 years			



Category : Room **Building : Addition (Telpochcalli)** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Power Distribution 1st Floor Supervising Engineer 2 ΕA 10+ vears 7 Storage/ Closet 1st Floor Supervising Engineer SF 7 12 10+ years Walls - Masonry 1st Floor Supervising Engineer 250 SF 7 10+ years Walls - Plaster/Drywall 1st Floor Supervising Engineer SF 246 6 10+ years 7 AC Unit 267 - Engineer 2 above Boiler Room 1 EΑ 6-10 years SF Ceiling - Lay-in 267 - Engineer 2 above Boiler Room 291 6 10+ years Ceiling - Lay-in 267 - Engineer 2 above Boiler Room 9 SF 4 0-1 year Water damage. Doors - Wood Doors inclu hw 267 - Engineer 2 above Boiler Room 1 ΕA 7 10+ years Floor - Tile 267 - Engineer 2 above Boiler Room 300 SF 6 10+ years ΕA 267 - Engineer 2 above Boiler Room 4 6 6-10 vears Lighting - Lay-in Power Distribution 267 - Engineer 2 above Boiler Room 4 ΕA 7 10+ vears Storage/ Closet 267 - Engineer 2 above Boiler Room 100 SF 7 10+ years 267 - Engineer 2 above Boiler Room 700 SF 6 10+ years Walls - Plaster/Drywall SF 5 Walls - Plaster/Drywall 267 - Engineer 2 above Boiler Room 20 0-1 year Water damage. 2nd Floor - boiler room (East) ΕA 7 AC Unit 1 6-10 years Office/Lounge 2nd Floor - boiler room (East) SF Ceiling - Lay-in 344 6 10+ years Office/Lounae 2nd Floor - boiler room (East) Doors - Wood Doors inclu hw ΕA 7 1 10+ years Office/Lounge Floor - Tile 2nd Floor - boiler room (East) 344 SF 6 10+ years Office/Lounge 2nd Floor - boiler room (East) Lighting - Lay-in 8 EΑ 6 6-10 years Office/Lounge Power Distribution 2nd Floor - boiler room (East) ΕA 7 4 10+ years Office/Lounae 2nd Floor - boiler room (East) 10+ years Storage/ Closet 180 SF 7 Office/Lounge 2nd Floor - boiler room (East) SF Walls - Plaster/Drywall 564 6 10+ years Office/Lounge 2nd Floor - boiler room (East) SF Walls - Plaster/Drywall 30 4 1-2 years Water damage. Office/Lounae 7 AC Unit Chief Engineer's Office FΑ 1 6-10 years Ceiling - Plaster/Drywall Chief Engineer's Office 224 SF 6 10+ years Doors - Wood Doors inclu hw 7 Chief Engineer's Office 1 ΕA 10+ years Chief Engineer's Office SF Floor - Tile 224 6 10+ years ΕA Lighting - Pendent/Surface Chief Engineer's Office 5 6 6-10 years Power Distribution Chief Engineer's Office 7 6 ΕA 10+ years Storage/ Closet Chief Engineer's Office 56 SF 7 10+ years Walls - Plaster/Drvwall SF Chief Engineer's Office 670 6 10+ vears AC Unit Principal's Office in Main Office 1 ΕA 7 6-10 years Ceiling - Lay-in Principal's Office in Main Office 203 SF 6 10+ vears Doors - Wood Doors inclu hw Principal's Office in Main Office EΑ 7 10+ years 1 SF Floor - Tile Principal's Office in Main Office 203 6 10+ years



Catego	ry : Room		Building : Addition (Telpochcalli)				
	•			3		Recommend	·
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Principal's Office in Main Office	3	EA	6	6-10 years	
	Power Distribution	Principal's Office in Main Office	8	EA	7	10+ years	
	Storage/ Closet	Principal's Office in Main Office	81	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office in Main Office	395	SF	6	10+ years	
MDF_ID	F						
_	Doors - Wood Doors inclu hw	164A- MDF Room	1	EA	7	10+ years	
	Finishes	164A- MDF Room	105	SF	7	10+ years	
	Other Cooling Unit	164A- MDF Room	1	EA	5	6-10 years	
Mechani	cal/ Service Rooms						
	Boiler Room	1st Floor	1,200	SF	7	10+ years	
	Janitor's Closet	1st Floor	32	SF	7	10+ years	
	Loading Docks	1st Floor	400	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	1,500	SF	7	10+ years	
	Storage Room	1st Floor	1,500	SF	7	10+ years	
	Janitor's Closet	2nd Floor	20	SF	7	10+ years	
	Storage Room	2nd Floor	25	SF	7	10+ years	
Restroor	n						
	Accessories	1st Floor	440	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	550	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	440	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	4	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	6	6-10 years	
	Partitions	1st Floor	9	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	300	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	263	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	105	SF	6	10+ years	
	Water Closet	1st Floor	9	ĒA	7	10+ years	
	Accessories	1st Floor	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	25	SF	6	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	198	SF	6	10+ years	
	Walls - Vinyi Coaled Gypsull Faller Water Closet	1st Floor	190	EA	7	10+ years	
				SF			
	Accessories	267	105		7	6-10 years	
	Ceiling - Plaster/Drywall	267	105	SF	6	10+ years	
	Doors - Wood Doors inclu hw	267	1	EA	7	10+ years	



Catego	Category : Room			Building : Addition (Telpochcalli)					
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	267	105	SF	6	10+ years			
	Floor Drain	267	1	EA	7	10+ years			
	Lavatory	267	2	EA	7	10+ years			
	Lighting - Pendent/Surface	267	1	EA	6	6-10 years			
	Lighting - Wall Mounted	267	1	EA	6	6-10 years			
	Partitions	267	1	EA	5	6-10 years			
	Showers	267	1	EA	5	6-10 years			
	Walls - Plaster/Drywall	267	220	SF	6	10+ years			
	Walls - Plaster/Drywall	267	20	SF	5	0-1 year	Damage around toilet.		
	Water Closet	267	1	EA	7	10+ years			
	Accessories	2nd Floor	475	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	540	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	475	SF	6	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Hand Dryer	2nd Floor	2	EA	7	6-10 years			
	Lavatory	2nd Floor	4	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	11	EA	6	6-10 years			
	Partitions	2nd Floor	2	EA	7	10+ years			
	Urinals	2nd Floor	8	EA	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	408	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	980	SF	6	10+ years			
	Water Closet	2nd Floor	2	EA	7	10+ years			
	Accessories	2nd Floor	22	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	22	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	22	SF	6	10+ years			
	Lavatory	2nd Floor	1	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years			
	Walls - Masonry	2nd Floor	12	SF	7	10+ years			
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	112	SF	6	10+ years			
	Water Closet	2nd Floor	1	EA	7	6-10 years			
	Accessories	2nd Floor Engineer's Lounge	75	SF	5	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor Engineer's Lounge	75	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor Engineer's Lounge	1	ĒA	7	10+ years			
	Floor - Tile	2nd Floor Engineer's Lounge	75	SF	6	10+ years			
	Lavatory	2nd Floor Engineer's Lounge	1	ĒA	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor Engineer's Lounge	2	EA	6	6-10 years			
	Lighting - Wall Mounted	2nd Floor Engineer's Lounge	1	EA	6	6-10 years			
	Partitions	2nd Floor Engineer's Lounge	1	EA	5	6-10 years			
	Showers	2nd Floor Engineer's Lounge	1	EA	5	6-10 years			
	Walls - Plaster/Drywall	2nd Floor Engineer's Lounge	280	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor Engineer's Lounge	200	SF	5	0-1 year	Water damage.		
	Water Closet	2nd Floor Engineer's Lounge	1	EA	7	10+ years			
			1		'	ior years			



Catego	ry : Room		В	Building : Addition (Telpochcalli)					
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Accessories	Boiler Room	40	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Boiler Room	40	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Boiler Room	1	EA	7	10+ years			
	Floor - Concrete Epoxy/ Painted	Boiler Room	40	SF	5	10+ years			
	Lavatory	Boiler Room	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Boiler Room	1	EA	6	6-10 years			
	Walls - Plaster/Drywall	Boiler Room	250	SF	6	10+ years			
	Water Closet	Boiler Room	1	EA	7	10+ years			
	Accessories	Chief Engineer's Office	36	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Chief Engineer's Office	36	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Chief Engineer's Office	1	EA	7	10+ years			
	Floor - Tile	Chief Engineer's Office	36	SF	6	10+ years			
	Lavatory	Chief Engineer's Office	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Chief Engineer's Office	1	EA	6	6-10 years			
	Student Lockers - One Tier	Chief Engineer's Office	1	EA	7	10+ years			
	Walls - Plaster/Drywall	Chief Engineer's Office	228	SF	6	10+ years	Paint cracking and peeling throughout.		
	Water Closet	Chief Engineer's Office	1	EA	7	10+ years	-		
Catego	ry : Classroom		В	uilding	: Additi	on (Telpochcal	li)		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	m #151 (Kindergarten)								
	AC Units	1st Floor	3	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	911	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	911	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	27	EA	6	6-10 years			
	Marker Board	1st Floor	26	LF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,586	SF	6	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
						-			

Class

ssroom #152 (Art Room)					
AC Units	1st Floor	2	EA	7	6-10 years
Casework	1st Floor	7	LF	7	10+ years
Ceiling - Plaster/Drywall	1st Floor	619	SF	6	10+ years
Chalk Board	1st Floor	10	LF	4	2-5 years
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years
Floor - Wood	1st Floor	619	SF	6	10+ years
Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years
Marker Board	1st Floor	24	LF	7	6-10 years
Walls - Plaster/Drywall	1st Floor	1,279	SF	6	10+ years



Catego	ry : Classroom		В	uilding	: Additi	on (Telpochca	III)
				Ŭ		Recommend	,
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #154 (Regular Classroom)						
	AC Units	1st Floor	3	EA	7	6-10 years	
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	<u>9</u> 91	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	911	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	ĒA	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,588	SF	6	10+ years	
			-,	•	-	, ,	
Classroo	om #155 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	825	SF	6	10+ years	
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	6	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,512	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classro	om #156 (Regular Classroom)						
_01035104	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	728	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	728	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,666	SF	6	10+ years	
	Walle Thaten Brywall		1,000	01	Ũ	ior youro	
Classroo	om #160 (Kindergarten)						
	Ceiling - Splined	1st Floor	596	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	596	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	6	6-10 years	
	Marker Board	1st Floor	5	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	968	SF	6	10+ years	
Classro	om #162 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	25	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	875	SF	6	10+ years	
			013	0	U	ioi youio	



	ry : Classroom		B	Building : Addition (Telpochcalli)					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Chalk Board	1st Floor	15	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Wood	1st Floor	875	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	22	EA	6	6-10 years			
	Marker Board	1st Floor	15	LF	7	6-10 years			
	Storage/ Closet	1st Floor	72	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,591	SF	6	10+ years			
	Work Sink	1st Floor	2	EA	7	10+ years			
lassroo	om #164 (Computer Lab)								
	AC Units	1st Floor	4	EA	7	6-10 years			
	Ceiling - Lay-in	1st Floor	625	SF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	100	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	775	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	14	EA	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor	3	EA	6	6-10 years			
	Marker Board	1st Floor	12	LF	7	6-10 years			
	Storage/ Closet	1st Floor	85	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,029	SF	6	10+ years			
Classroo	om #251 (Regular Classroom)								
	AC Units	2nd Floor	3	EA	7	6-10 years			
				LF	7	10+ years			
	Casework	2nd Floor	25						
	Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	25 880			•			
	Ceiling - Plaster/Drywall	2nd Floor	880	SF	6	10+ years			
	Ceiling - Plaster/Drywall Doors - Transom Window	2nd Floor 2nd Floor	880 12	SF SF	6 7	10+ years 10+ years			
	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw	2nd Floor 2nd Floor 2nd Floor	880 12 1	SF SF EA	6 7 7	10+ years 10+ years 10+ years			
	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile	2nd Floor 2nd Floor 2nd Floor 2nd Floor	880 12 1 880	SF SF EA SF	6 7 7 6	10+ years 10+ years 10+ years 10+ years			
	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	880 12 1 880 18	SF SF EA SF EA	6 7 6 6	10+ years 10+ years 10+ years 10+ years 6-10 years			
	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	880 12 1 880 18 28	SF SF EA SF EA LF	6 7 6 6 7	10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years			
	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	880 12 1 880 18	SF SF EA SF EA	6 7 6 6	10+ years 10+ years 10+ years 10+ years 6-10 years	Water damage.		
Classroo	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	880 12 1 880 18 28 1,358	SF SF EA SF LF SF	6 7 6 6 7 6	10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	Water damage.		
Classroo	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Walls - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	880 12 1 880 18 28 1,358 15	SF SF EA SF LF SF	6 7 6 6 7 6 4	10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 1-2 years	Water damage.		
Classroo	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Walls - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	880 12 1 880 18 28 1,358 15 2	SF EA SF EA LF SF SF	6 7 6 6 7 6 4 7	10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	Water damage.		
Classroo	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Walls - Plaster/Drywall om #252 (Regular Classroom) AC Units Casework	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	880 12 1 880 18 28 1,358 15	SF EA SF EA LF SF SF EA	6 7 6 6 7 6 4	10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 1-2 years 6-10 years	Water damage.		
Classroo	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Walls - Plaster/Drywall om #252 (Regular Classroom) AC Units	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	880 12 1 880 18 28 1,358 15 2 6	SF EA SF EA LF SF SF EA LF	6 7 6 6 7 6 4 7 7 7	10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 1-2 years 6-10 years 10+ years 10+ years 10+ years	Water damage.		
Classroo	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Walls - Plaster/Drywall om #252 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Chalk Board	2nd Floor 2nd Floor	880 12 1 880 18 28 1,358 15 2 6 588 10	SF EA SF EA LF SF EA LF SF LF	6 7 6 6 7 6 4 7 7 6 4	10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 1-2 years 6-10 years 10+ years 10+ years 10+ years 2-5 years	Water damage.		
Classroo	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Walls - Plaster/Drywall om #252 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window	2nd Floor 2nd Floor	880 12 1 880 18 28 1,358 15 2 6 588	SF EA SF EA SF EA LF SF LF SF	6 7 6 6 7 6 4 7 7 6	10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 1-2 years 6-10 years 10+ years 10+ years 10+ years 2-5 years 10+ years	Water damage.		
Classroo	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Walls - Plaster/Drywall Om #252 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	880 12 1 880 18 28 1,358 15 2 6 588 10 12 1	SF EA EF SF EA LF SF EA LF F SF EA LF F A	6 7 6 6 7 6 4 7 7 6 4 7 7	10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 1-2 years 6-10 years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years	Water damage.		
Classroo	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Walls - Plaster/Drywall om #252 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window	2nd Floor 2nd Floor	880 12 1 880 18 28 1,358 15 2 6 588 10 12	SF EA SF EA SF EA LF SF LF SF	6 7 6 6 7 6 4 7 7 6 4 7	10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 1-2 years 6-10 years 10+ years 10+ years 10+ years 2-5 years 10+ years	Water damage.		



Catego	ry : Classroom		В	Building : Addition (Telpochcalli)					
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	2nd Floor	1,001	SF	6	10+ years			
Classroo	m #253 (Regular Classroom)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	6	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	588	SF	6	10+ years			
	Chalk Board	2nd Floor	28	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years			
	Floor - Wood	2nd Floor	588	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	10	EA	6	6-10 years			
	Marker Board	2nd Floor	12	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,001	SF	6	10+ years			
01									
Jassroo	<u>m #254 (Regular Classroom)</u> AC Units	2nd Floor	2	Г۸	7	6.10 veere			
				EA LF		6-10 years			
	Casework	2nd Floor	6		7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	588	SF	6	10+ years			
	Chalk Board	2nd Floor	18	LF	4	2-5 years			
	Doors - Side-lite	2nd Floor	3	SF	7	10+ years			
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Wood	2nd Floor	588	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	10	EA	6	6-10 years			
	Marker Board	2nd Floor	18	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,001	SF	6	10+ years			
Classroo	m #255 (Regular Classroom)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	6	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	588	SF	6	10+ years			
	Chalk Board	2nd Floor	6	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Wood	2nd Floor	588	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	10	EA	6	6-10 years			
	Marker Board	2nd Floor	28	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,001	SF	6	10+ years			
Classroo	m #256 (Regular Classroom)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	6	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	588	SF	6	10+ years			



Catego	ry : Classroom		В	Building : Addition (Telpochcalli)					
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Chalk Board	2nd Floor	19	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Wood	2nd Floor	588	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	10	EA	6	6-10 years			
	Marker Board	2nd Floor	23	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,001	SF	6	10+ years			
lassroo	om #257 (Regular Classroom)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	15	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	1,176	SF	6	10+ years			
	Chalk Board	2nd Floor	, 16	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒA	7	10+ years			
	Floor - Carpet	2nd Floor	1,176	SF	6	6-10 years			
	Lighting - Lay-in	2nd Floor	23	ĒA	6	6-10 years			
	Marker Board	2nd Floor	16	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	24	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,056	SF	6	10+ years			
						-			
Classroo	om #258 (Regular Classroom)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	12	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	1,028	SF	6	10+ years			
	Chalk Board	2nd Floor	28	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Carpet	2nd Floor	1,028	SF	6	6-10 years			
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years			
		2nd Floor	20	LF	7	6-10 years			
	Marker Board		-	-					
	Storage/ Closet	2nd Floor	24	SF	7	10+ years			
			-	SF SF	7 6	10+ years 10+ years			
lassroo	Storage/ Closet Walls - Plaster/Drywall om #259 (Regular Classroom)	2nd Floor 2nd Floor	24	SF	6	10+ years			
Classroo	Storage/ Closet Walls - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor	24	SF EA					
lassroo	Storage/ Closet Walls - Plaster/Drywall om #259 (Regular Classroom) AC Units Casework	2nd Floor 2nd Floor	24 1,000 1 6	SF EA LF	6	10+ years			
Classroo	Storage/ Closet Walls - Plaster/Drywall om #259 (Regular Classroom) AC Units	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	24 1,000 1 6 588	SF EA LF SF	6	10+ years 6-10 years			
lassroo	Storage/ Closet Walls - Plaster/Drywall om #259 (Regular Classroom) AC Units Casework	2nd Floor 2nd Floor 2nd Floor 2nd Floor	24 1,000 1 6	SF EA LF SF LF	6 7 7	10+ years 6-10 years 10+ years			
lassroo	Storage/ Closet Walls - Plaster/Drywall om #259 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	24 1,000 1 6 588	SF EA LF SF	6 7 7 6	10+ years 6-10 years 10+ years 10+ years			
lassroo	Storage/ Closet Walls - Plaster/Drywall om #259 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Chalk Board	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	24 1,000 1 6 588 19	SF EA LF SF LF	6 7 7 6 4	10+ years 6-10 years 10+ years 10+ years 2-5 years 10+ years			
assroo	Storage/ Closet Walls - Plaster/Drywall om #259 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Side-lite	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	24 1,000 1 6 588 19 3	SF EA LF SF LF SF	6 7 7 6 4 7	10+ years 6-10 years 10+ years 10+ years 2-5 years 10+ years 10+ years			
Classroo	Storage/ Closet Walls - Plaster/Drywall om #259 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Side-lite Doors - Transom Window	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	24 1,000 1 6 588 19 3 16	SF EA LF SF LF SF SF	6 7 7 6 4 7 7 7	10+ years 6-10 years 10+ years 10+ years 2-5 years 10+ years			



Group

Category : Classroom

Item - Type Marker Board

Walls - Plaster/Drywall

Ceiling - Plaster/Drywall Doors - Side-lite

Doors - Transom Window Doors - Wood Doors inclu hw

Lighting - Pendent/Surface

Walls - Plaster/Drywall

Classroom #260 (Regular Classroom) AC Units Casework

Maria Saucedo Elementary Scholastic Academy

	2850 W 24th BOULEVARD, Chicago, IL 60623							
	В	uilding	: Additie	on (Telpochcal	lli)			
		_		Recommend				
Location	Quantity	UOM	Rank	Replacement	Comments			
2nd Floor	13	LF	7	6-10 years				
2nd Floor	1,001	SF	6	10+ years				
2nd Floor	3	EA	7	6-10 years				
2nd Floor	39	LF	7	10+ years				
2nd Floor	864	SF	6	10+ years				
2nd Floor	3	SF	7	10+ years				
2nd Floor	16	SF	7	10+ years				
2nd Floor	1	EA	7	10+ years				
2nd Floor	864	SF	6	10+ years				
2nd Floor	24	EA	6	6-10 years				
2nd Floor	20	LF	7	6-10 years				
2nd Floor	1,124	SF	6	10+ years				

Classroom #262 (Science Classroom)

Floor - Wood

Marker Board

lassroom #262 (Science Classroom)					
AC Units	2nd Floor	3	EA	7	6-10 years
Casework	2nd Floor	45	LF	7	10+ years
Ceiling - Plaster/Drywall	2nd Floor	1,008	SF	6	10+ years
Doors - Side-lite	2nd Floor	14	SF	7	10+ years
Doors - Transom Window	2nd Floor	10	SF	7	10+ years
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years
Floor - Tile	2nd Floor	1,008	SF	6	10+ years
Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years
Marker Board	2nd Floor	19	LF	7	6-10 years
Walls - Plaster/Drywall	2nd Floor	1,389	SF	6	10+ years
Work Sink	2nd Floor	1	EA	7	6-10 years
lassroom #264 (Regular Classroom)					
AC Units	2nd Floor	3	EA	7	6-10 years
Casework	2nd Floor	12	LF	7	10+ years
Ceiling - Plaster/Drywall	2nd Floor	880	SF	6	10+ years
Chalk Board	2nd Floor	12	LF	4	2-5 years
Doors - Transom Window	2nd Floor	12	SF	7	10+ years
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years
Floor - Wood	2nd Floor	880	SF	6	10+ years
Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years
Marker Board	2nd Floor	28	LF	7	6-10 years
Walls - Plaster/Drywall	2nd Floor	1,373	SF	6	10+ years
5					-



Building : Addition (Telpochcalli)					
ents					
IIIIS					



Catego	ry : Interior		В	uilding	: Additie	on (Telpochcal	li)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	South Stair	2	EA	6	6-10 years	
	Lighting - Wall Mounted	South Stair	4	EA	6	6-10 years	
	Stairs - Asphalt	South Stair	168	LF	6	10+ years	
	Walls - Plaster/Drywall	South Stair	2,024	SF	6	10+ years	



Category : Site			В	uilding	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	6	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	3	0-1 year	Collapsed catch basin
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	3	0-1 year	Collapsed catch basin
	Civil/ Drainage - Site Manhole	Entire Site	14	EA	6	10+ years	
Fencing							
Cheing	Fencing - Chain Link	Entire Site	298	LF	6	10+ years	
	Fencing - Guard Rail	Entire Site	864	LF	6	10+ years	
	Fencing - Guard Rail	Entire Site	3	LF	4	0-1 year	Bent.
	Fencing - New Standard Ornamental	Entire Site	515	LF	6	10+ years	Dent.
	Fencing - New Standard Ornamental		10	LF	4		Bont
	rending - New Standard Ornamental	Entire Site	10	LF	4	0-1 year	Bent.
Landscap							
	Benches	Entire Site	4	EA	6	10+ years	
	Landscape - Grass	Entire Site	21,234	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	7,934	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	700	SF	4	0-1 year	Cracking and uneven.
	Landscape - Hardscape- Pavers	Entire Site	250	SF	6	10+ years	
	Parkway trees	Entire Site	28	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	450	SF	6	10+ years	
	Play Area - Asphalt/ Hardscape	Entire Site	10.384	SF	4	1-2 years	Cracking and holes.
	Trash Receptacles	Entire Site	4	EA	6	10+ years	
Parking L	ot						
	Concrete Curbs	Entire Site	170	LF	6	10+ years	
	Surface - Asphalt	Entire Site	88,585	SF	6	10+ years	
	Surface - Asphalt	Entire Site	50	SF	4	0-1 year	Cracking, holes, uneven.
Playgrou	ad						
Flaygrou	Equipment - School Age 5-12	East Facade of Main Building	1	EA	6	10+ years	
	Surface - Poured Surface	East Facade of Main Building	2,520	SF	6	10+ years	
Sidewalk	s						
	Sidewalks - Perimeter Sidewalks	Entire Site	33,171	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	2,019	SF	4	0-1 year	Cracking and uneven.
Signage							
0	Flag Pole - Flag Pole	South	1	EA	7	10+ years	
	Marquee - Building Mounted Back Lighted	South	1	EA	7	10+ years	
	w/ LED				•		

Chicago Public Schools		Maria Saucedo Elementary Scholastic Academy 2850 W 24th BOULEVARD, Chicago, IL 60623					
Category : Site		Building : Site					
Group Item - Type	Location	Recommend Quantity UOM Rank Replacement Comments					

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	j.				(/				
Art Room	Other Instructional Use	3rd Floor	313	313	1,165	240	100	N	N
Band Room	Band Room	4th Floor	400	400	2,400	830	164	N	N
Computer Lab	Other Instructional Use	2nd Floor	202	202	1,247	400	200	Y	Y
Computer Lab	Other Instructional Use	2nd Floor	206	206	1,247	367	184	Y	N
Computer Lab	Science Lab Level 3	2nd Floor	216	216	1,062	330	165	Y	N
Faculty Lounge	Regular Classroom	1st Floor	126	126	1,354	180	90		
Kindergarten	Office	1st Floor	119	119	680	150	48	N	N
Kindergarten	Regular Classroom	1st Floor	123	123	673	200	150	Y	N
Kindergarten	Regular Classroom	1st Floor	125	125	6,801,	150	48	N	N
_					080				
Kindergarten	Regular Classroom	1st Floor	127	127	673	200	100	Y	N
Kindergarten	Science Classroom	1st Floor	104	104	982	216	90	N	N
Other Instructional Use	Art Room	3rd Floor	334	334	1,376	276	84	N	Y
Other Instructional Use	Laboratory/Shop	1st Floor	143	143	1,630	375	100	N	N
Other Instructional Use	Laboratory/Shop	1st Floor	144	144	1,660	375	100	N	N
Pre School	Laboratory/Shop	1st Floor	130	130	1,644	420	131	N	N
Pre School	Regular Classroom	1st Floor	116	116	626	120	50	N	N
Pre School	Regular Classroom	1st Floor	118	118	665	144	60	N	N
Pre School	Science Classroom	1st Floor	106	106	1,088	192	80	N	N
Regular Classroom	Art Room	3rd Floor	332	332	1,344	276	84	N	N
Regular Classroom	Office	3rd Floor	312	312	441	96	40	N	Ν
Regular Classroom	Other Instructional Use	2nd Floor	220	220	602	200	100	Y	Ν
Regular Classroom	Other Instructional Use	3rd Floor	314	314	703	144	60	N	N
Regular Classroom	Other Instructional Use	3rd Floor	315	315	703	144	60	N	Ν
Regular Classroom	Other Instructional Use	3rd Floor	317	317	1,140	253	77	N	Y
Regular Classroom	Other Instructional Use	3rd Floor	321	321	1,140	230	70	N	Ν
Regular Classroom	Other Instructional Use	3rd Floor	323	323	500	115	35	N	N
Regular Classroom	Other Instructional Use	3rd Floor	327	327	1,188	207	63	N	N
Regular Classroom	Other Instructional Use	3rd Floor	335	335	1,026	207	63	N	Y
Regular Classroom	Other Instructional Use	3rd Floor	336	336	1,026	207	63	N	Y
Regular Classroom	Regular Classroom	2nd Floor	212	212	673	225	112	Y	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	673	150	75	Y	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	673	120	60	Y	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	673	150	75	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	217	217	673	200	100	Y	N
Regular Classroom	Regular Classroom	2nd Floor	219	219	680	150	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	221	221	673	200	100	N	N
Regular Classroom	Regular Classroom	2nd Floor	223	223	680	150	48	Y	Y



Classroom Summary

Classroom Summary	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	2nd Floor	225	225	680	150	48	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	226	226	673	200	100	Y	N
Regular Classroom	Regular Classroom	2nd Floor	227	227	680	150	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	228	228	779	220	110	Y	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	703	102	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	703	144	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	703	102	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	316	316	673	138	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	318	318	1,015	207	63	N	Y
Regular Classroom	Regular Classroom	3rd Floor	320	320	673	138	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	322	322	1,015	207	63	N	Y
Regular Classroom	Regular Classroom	3rd Floor	326	326	673	138	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	328	328	720	107	33	N	Y
Regular Classroom	Regular Classroom	3rd Floor	329	329	720	107	33	N	N
Regular Classroom	Regular Classroom	3rd Floor	331	331	648	138	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	333	333	1,026	207	63	N	N
Regular Classroom	Regular Classroom	3rd Floor	337	337	704	144	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	339	339	672	144	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	340	340	672	144	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	341	341	672	144	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	342	342	672	144	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	343	343	672	144	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	344	344	672	144	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	346	346	672	144	60	N	N
Regular Classroom	Science Lab Level 3	2nd Floor	224	222/224	1,062	225	72	N	N
Science Classroom	Science Lab Level 3	3rd Floor	302	302	985	207	63	N	Ν
Science Classroom	Science Lab Level 3	3rd Floor	304	306	1,152	207	63	N	Ν
Science Classroom	Science Lab Level 3	3rd Floor	305	305	1,027	207	63	N	Y
Science Classroom	Science Lab Level 3	3rd Floor	309	309	1,128	207	63	N	N
Special Program	Office	3rd Floor	338	338	360	72	30	N	N
Store Room	Laboratory/Shop	1st Floor	133	133	1,885	336	105	N	N

Building : Addition (Telpoo	hcalli)								
Art Room	Regular Classroom	1st Floor	152	NA	619	200	100	Y	N
Computer Lab	Regular Classroom	1st Floor	164	164	775	267	133	Y	Y
Kindergarten	Other Instructional Use	1st Floor	151	151	911	300	150	Y	N
Kindergarten	Pre School	1st Floor	162	162	875	200	100	Y	N
Kindergarten	Regular Classroom	1st Floor	160	159	596	200	100	Y	Y
Pre School	Office	1st Floor	155	NA	825	267	133	Y	Y
Regular Classroom	Music Room	2nd Floor	251	251	880	120	54	N	N
Regular Classroom	Other Instructional Use	1st Floor	154	153	911	300	150	Y	Y



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Other Instructional Use	2nd Floor	257	257	1,200	252	63	N	N
Regular Classroom	Regular Classroom	1st Floor	156	NA (Rec. Room)	728	233	112	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	252	252	588	80	38	N	N
Regular Classroom	Regular Classroom	2nd Floor	253	253	588	80	38	N	N
Regular Classroom	Regular Classroom	2nd Floor	254	254	588	80	38	N	N
Regular Classroom	Regular Classroom	2nd Floor	255	255	588	80	38	N	N
Regular Classroom	Regular Classroom	2nd Floor	256	256	588	80	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	259	259	588	80	38	N	Y
Regular Classroom	Regular Classroom	2nd Floor	260	260	864	120	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	264	264	880	120	54	N	N
Regular Classroom	Science	2nd Floor	258	258	1,052	224	54	N	N
Science Classroom	Science Classroom	2nd Floor	262	262	1,008	120	54	N	N