

Facility Assessment Report

This report contains a summary of the results from the facility assessment completed on the date noted in the document footer below. This report will roll-up each assessed item with identical rank and total the quantity into a single line, regardless of item location (for location data, see the detailed report). Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | | | | | |
|----------------|------------------|------------------|-----------------------|---------------|--|--|--|--|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need | | | | |
| Main | 1926 | 2 | 66,649 | \$4,357,962 | | | | |
| Annex | 1972 | 2 | 21,061 | \$1,365,220 | | | | |
| Modular 1 | 1997 | 1 | 1,726 | \$169,440 | | | | |
| Modular 2 | 1997 | 1 | 1,726 | \$155,903 | | | | |
| Modular 3 | 1999 | 1 | 1,726 | \$165,826 | | | | |
| Modular 4 | 1999 | 1 | 1,726 | \$168,630 | | | | |
| SITE | | | | \$564,931 | | | | |
| Campus Total | | | 94,614 | \$6,947,912 | | | | |

Building: Main

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|--|----------|------|------|----------|
| Entrance | | | | | |
| | Entrance Control - Audio and Video | 1 | EA | 5 | \$1,567 |
| | Exterior Doors - Exterior FRP Door | 10 | EA | 6 | \$6,314 |
| | Exterior Doors - Exterior Stainless Steel Door | 1 | EA | 6 | \$546 |
| | Exterior Doors - Exterior Steel Door | 1 | EA | 4 | \$3,823 |
| | Exterior Doors - Exterior Steel Door | 1 | EA | 5 | \$1,341 |
| | Exterior Doors - Exterior Steel Door | 4 | EA | 6 | \$1,922 |
| | Exterior Doors - Transom Lite | 10 | EA | 6 | \$3,133 |
| | Exterior Stairs - Concrete | 16 | LF | 4 | \$2,617 |
| | Exterior Stairs - Concrete | 240 | LF | 6 | \$19,624 |
| | Exterior Stairs - Stone | 6 | LF | 5 | \$1,627 |
| | Exterior Stairs - Stone | 31 | LF | 6 | \$3,503 |
| | Ramp Handrail - Steel_Ramp Handrail | 148 | LF | 6 | \$1,283 |
| | Ramps - Concrete | 65 | LF | 5 | \$34,555 |



Building: Main

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------|---|-----------|------|------|---------------------------|
| Entrance | | | | | |
| | Stair Handrail - Steel_Stair Handrail | 62 | LF | 6 | \$537 |
| Foundation | | | | | |
| | Foundation - Concrete | 2 | LF | 5 | \$0 |
| | Foundation - Concrete | 1,436 | LF | 7 | \$0 |
| | Superstructure - Concrete | 20 | SF | 5 | \$0 |
| | Superstructure - Concrete | 66,629 | SF | 7 | \$0 |
| Lighting | | | | | |
| Lighting | Exterior Lighting - Parapet or Roof Mounted | 10 | EA | 6 | \$5,365 |
| | Exterior Lighting - Wall Mounted | 8 | EA | 6 | \$2,310 |
| De of Svotom | | | | | |
| Roof System | Chimney - Metal Flue | 87 | LF | 6 | \$13,759 |
| | Coping - Terra Cotta | 1,317 | LF | 6 | \$42,299 |
| | Downspouts - Interior Downspouts | 425 | LF | 6 | \$42,295 \$14,124 |
| | Parapet - 16" - 30" Height | 420 | LF | 5 | \$14,124 |
| | | 45 572 | LF | | |
| | Parapet - 16" - 30" Height | | | 6 | \$22,854 |
| | Parapet - Parapet < 16" Height | 150 | LF | 6 | \$3,196 |
| | Parapet - Parapet > 30" | 37 | LF | 5 | \$9,129 |
| | Parapet - Parapet > 30" | 523 | LF | 6 | \$33,431 |
| | Roof - Asphalt Shingle | 2,580 | SF | 5 | \$26,601 |
| | Roof - Modified Bitumen | 26,693 | SF | 5 | \$561,495 |
| | Roof - Modified Bitumen | 2,950 | SF | 6 | \$27,758 |
| | Roof Structure - Concrete | 31,436 | SF | 7 | \$0 |
| Walls | | | | | |
| | Cheek-Wall - Stone | 15 | SF | 4 | \$2,903 |
| | Cheek-Wall - Stone | 90 | SF | 5 | \$2,142 |
| | Cornice - Terra Cotta | 2,142 | LF | 6 | \$74,279 |
| | Exterior Walls - Brick | 62 | SF | 4 | \$10,208 |
| | Exterior Walls - Brick | 117 | SF | 5 | \$2,786 |
| | Exterior Walls - Brick | 39,338 | SF | 6 | \$264,391 |
| | Exterior Walls - Stone-Cast | 1,071 | SF | 6 | \$7,198 |
| | Exterior Walls - Terra Cotta | 4 | SF | 4 | \$2,595 |
| | Exterior Walls - Terra Cotta | 6 | SF | 5 | \$94 |
| | Exterior Walls - Terra Cotta | 1,471 | SF | 6 | \$9,887 |
| Windows | | | | | |
| | Curtain wall - Glazed Double Pane | 100 | SF | 6 | \$1,121 |
| | | | | | Assessment Date: 0/40/201 |



Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------|-------------------------------------|----------|------|------|-------------|
| Windows | | | | | |
| | Guard - Guards wire guard | 3,080 | SF | 6 | \$39,331 |
| | Lintels - Steel | 665 | LF | 6 | \$19,304 |
| | Lintels - Terra Cotta | 40 | LF | 6 | \$0 |
| | Windows - Sash Aluminum Double-pane | 160 | SF | 5 | \$8,619 |
| | Windows - Sash Aluminum Double-pane | 6,080 | SF | 6 | \$45,385 |
| Building Exte | erior Subtotal: | | | | \$1,345,918 |

Building Exterior Subtotal:

Building: Main

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|--|----------|------|------|----------|
| Emergency System | | | | | |
| | Automatic Transfer Switch | 1 | EA | 4 | \$8,200 |
| | Emergency Battery Packs - Corridors and Stairs | 4 | EA | 6 | \$810 |
| | Emergency Battery Packs - Gym | 2 | EA | 6 | \$405 |
| | Exit Signs - Auditoium | 6 | EA | 6 | \$898 |
| | Exit Signs - Corridors and Stairs | 20 | EA | 6 | \$2,995 |
| | Exit Signs - Gym | 8 | EA | 6 | \$1,259 |
| | Security System - CCTV | 66,649 | SF | 6 | \$20,015 |
| | Security System - Intrusion Detection | 66,649 | SF | 6 | \$17,155 |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 6 | \$2,921 |
| | Main Electrical Service - 1200 A 120/208/3PH | 1 | EA | 6 | \$5,078 |
| | PA System | 66,649 | SF | 6 | \$21,921 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 2 | EA | 6 | \$598 |
| | Lighting and Power Panels - Above 100 A | 6 | EA | 6 | \$2,982 |
| | Main Distribution Panels - 400 - 600 amp | 4 | EA | 6 | \$2,111 |
| Electrical Syster | m Subtotal: | | | | \$87,348 |

Electrical System Subtotal:

Building: Main

| Category: Safty Sys | em | | | | |
|---------------------|-------------|----------|------|------|------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |



Building: Main

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------|--------------------------|----------|------|------|----------|
| Fire Alarm | | | | | |
| | Fire Alarm Panel | 1 | EA | 6 | \$6,406 |
| | Fire Alarm Strobe Lights | 66,649 | SF | 4 | \$90,543 |
| | Fire Alarm_System | 66,649 | SF | 6 | \$32,405 |

Safty System Subtotal:

Building: Main

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|---|----------|------|------|-----------|
| Air Handling System | S | | | | |
| | Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm | 2 | EA | 5 | \$48,165 |
| | Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm | 2 | EA | 5 | \$111,297 |
| | Air Intake | 4 | EA | 5 | \$29,883 |
| | Auxiliaries - 25001 - 35000 cfm | 2 | EA | 5 | \$33,155 |
| | Auxiliaries - 4000 - 8000 cfm | 2 | EA | 5 | \$27,045 |
| | Reheat Boxes - Reheat Boxes with Steam Coil | 14 | EA | 5 | \$60,036 |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | 600 | LF | 4 | \$C |
| | Zone Dampers | 30 | EA | 5 | \$63,785 |
| Boiler Systems | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 50 - 75 HP | 2 | EA | 5 | \$17,017 |
| | Chemical Feeder | 1 | EA | 5 | \$3,075 |
| | Combustion Dampers | 2 | EA | 5 | \$5,104 |
| | Condensate Pump | 4 | EA | 5 | \$72,784 |
| | Feed Water Pumps and Tank | 1 | EA | 5 | \$36,450 |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP | 2 | EA | 5 | \$17,017 |
| | Piping - Condensate Pipe- Steel | 400 | LF | 5 | \$4,879 |
| | Piping - Steam Pipe- Steel | 400 | LF | 5 | \$5,634 |
| | Steam Traps | 65 | EA | 5 | \$85,468 |
| Heating Devices | | | | | |
| | Radiators - Steam | 10 | EA | 5 | \$16,753 |
| | Unit Heater - Electric | 2 | EA | 5 | \$2,015 |
| | Wall Heater - Electric | 12 | EA | 5 | \$6,439 |
| Temperature Contro | I Contraction of the second | | | | |
| | Pneumatic System | 66,649 | SF | 4 | \$346,921 |
| | Thermostats - Pneumatic | 30 | EA | 4 | \$22,117 |



Building: Main

| Category: Me Group | chanical System Item - Type | Quantity | Unit | Rank | Cost |
|-----------------------|---|----------|------|------|-------------|
| Ventilation | | quantity | Unit | | 0051 |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 5 | EA | 6 | \$2,962 |
| Mechanical S | system Subtotal: | | | | \$1,018,001 |

-

Building: Main

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------|--|----------|------|------|-----------|
| Hot Water | | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | 1 | EA | 4 | \$19,938 |
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 66,649 | SF | 6 | \$13,343 |
| | Domestic Piping-Cold Water Horizontal Lines | 66,649 | SF | 6 | \$16,202 |
| | Domestic Piping-Cold Water Risers | 66,649 | SF | 6 | \$12,390 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 66,649 | SF | 6 | \$10,484 |
| | Domestic Piping-Hot Water Horizontal Lines | 66,649 | SF | 6 | \$12,390 |
| | Domestic Piping-Hot Water Return Lines | 66,649 | SF | 6 | \$9,531 |
| | Domestic Piping-Hot Water Return Risers | 66,649 | SF | 6 | \$9,531 |
| | Sanitary Piping | 66,649 | SF | 4 | \$231,599 |
| | Storm Piping | 66,649 | SF | 4 | \$230,646 |
| | Vent Piping | 66,649 | SF | 4 | \$162,977 |
| Pumps | | | | | |
| | Pumps - Sump-Duplex | 1 | EA | 5 | \$7,535 |
| Plumbing Sys | tem Subtotal: | | | | \$736,565 |

Building: Main Category: Classrooms

| ealegely! el | | | | | |
|-----------------|-----------------------------|----------|------|------|---------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Computer Lab (1 | 1 room) | | | | |
| | AC Units | 1 | EA | 6 | \$496 |
| | Casework | 6 | LF | 6 | \$152 |
| | Ceiling - Plaster/Drywall | 712 | SF | 5 | \$6,526 |
| | Charging Station | 2 | EA | 6 | \$969 |
| | Doors - Transom Window | 9 | SF | 6 | \$152 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | | | | | |



Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|-----------------------------|----------|------|------|----------|
| Computer Lab (1 | room) | | | | |
| | Floor - Carpet | 712 | SF | 6 | \$1,517 |
| | Lighting - Pendent/Surface | 12 | EA | 7 | \$0 |
| | Marker Board | 46 | LF | 6 | \$985 |
| | Storage/ Closet | 6 | SF | 6 | \$44 |
| | Walls - Plaster/Drywall | 842 | SF | 4 | \$8,477 |
| | Wireless System | 1 | EA | 7 | \$0 |
| Office (2 rooms) | | | | | |
| | AC Units | 1 | EA | 4 | \$6,086 |
| | AC Units | 1 | EA | 6 | \$496 |
| | Casework | 6 | LF | 6 | \$152 |
| | Ceiling - Plaster/Drywall | 1,483 | SF | 6 | \$5,132 |
| | Doors - Transom Window | 18 | SF | 6 | \$305 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Carpet | 1,015 | SF | 6 | \$2,163 |
| | Floor - Wood | 468 | SF | 6 | \$3,299 |
| | Lighting - Pendent/Surface | 22 | EA | 7 | \$0 |
| | Marker Board | 12 | LF | 6 | \$257 |
| | Walls - Plaster/Drywall | 1,749 | SF | 6 | \$4,827 |
| | Work Sink | 1 | EA | 6 | \$379 |
| Regular Classroo | om (16 rooms) | | | | |
| | Casework | 90 | LF | 6 | \$2,273 |
| | Ceiling - Lay-in | 712 | SF | 6 | \$2,138 |
| | Ceiling - Plaster/Drywall | 4,984 | SF | 5 | \$45,685 |
| | Ceiling - Plaster/Drywall | 4,990 | SF | 6 | \$17,268 |
| | Chalk Board | 303 | LF | 4 | \$27,817 |
| | Doors - Transom Window | 144 | SF | 6 | \$2,438 |
| | Doors - Wood Doors inclu hw | 16 | EA | 6 | \$4,816 |
| | Floor - Carpet | 712 | SF | 6 | \$1,517 |
| | Floor - Wood | 9,970 | SF | 6 | \$70,288 |
| | Lighting - Lay-in | 9 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 180 | EA | 7 | \$0 |
| | Marker Board | 336 | LF | 6 | \$7,198 |
| | Storage/ Closet | 158 | SF | 6 | \$1,146 |
| | Walls - Plaster/Drywall | 1,684 | SF | 4 | \$16,953 |
| | Walls - Plaster/Drywall | 6,736 | SF | 5 | \$51,052 |
| | Walls - Plaster/Drywall | 5,052 | SF | 6 | \$13,943 |
| | vvalis - Master/Drywali | 5,052 | 51 | б | |



Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|-----------------------------|----------|------|------|-----------|
| Science Classroom | (1 room) | | | | |
| | Casework | 8 | LF | 6 | \$202 |
| | Ceiling - Plaster/Drywall | 780 | SF | 6 | \$2,699 |
| | Doors - Transom Window | 9 | SF | 6 | \$152 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Wood | 780 | SF | 6 | \$5,499 |
| | Lighting - Pendent/Surface | 14 | EA | 7 | \$0 |
| | Marker Board | 18 | LF | 6 | \$386 |
| | Storage/ Closet | 42 | SF | 6 | \$305 |
| | Walls - Plaster/Drywall | 918 | SF | 6 | \$2,534 |
| | Work Sink | 1 | EA | 6 | \$379 |
| Special Education (| 1 room) | | | | |
| | Ceiling - Lay-in | 694 | SF | 6 | \$2,084 |
| | Doors - Transom Window | 9 | SF | 6 | \$152 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Carpet | 694 | SF | 6 | \$1,479 |
| | Lighting - Lay-in | 12 | EA | 7 | \$0 |
| | Marker Board | 12 | LF | 6 | \$257 |
| | Storage/ Closet | 40 | SF | 6 | \$290 |
| | Walls - Plaster/Drywall | 783 | SF | 6 | \$2,161 |
| Classrooms Su | btotal: | | | | \$327,028 |

Classrooms Subtotal:

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|-----------------------------|----------|------|------|---------|
| Administrative S | uites/Offices | | | | |
| | AC Unit | 1 | EA | 6 | \$496 |
| | AC Unit | 1 | EA | 7 | \$0 |
| | Ceiling - Plaster/Drywall | 618 | SF | 5 | \$5,665 |
| | Ceiling - Plaster/Drywall | 1,708 | SF | 6 | \$5,911 |
| | Doors - Wood Doors inclu hw | 6 | EA | 6 | \$1,806 |
| | Floor - Carpet | 1,261 | SF | 6 | \$2,687 |
| | Floor - Terrazzo | 311 | SF | 6 | \$680 |
| | Floor - Tile | 618 | SF | 6 | \$1,352 |
| | Floor - Wood | 136 | SF | 6 | \$959 |
| | Lighting - Pendent/Surface | 32 | EA | 7 | \$0 |



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|--------------------------------------|----------|------|------|----------|
| Administrative S | uites/Offices | | | | |
| | Power Distribution | 32 | EA | 6 | \$67,996 |
| | Storage/ Closet | 176 | SF | 6 | \$1,276 |
| | Walls - Plaster/Drywall | 160 | SF | 5 | \$1,213 |
| | Walls - Plaster/Drywall | 2,194 | SF | 6 | \$6,055 |
| | Walls - Structural Glazed Tile | 365 | SF | 6 | \$1,148 |
| Auditorium & The | eater | | | | |
| | Balcony Seating | 94 | EA | 6 | \$16,348 |
| | Ceiling - Plaster/Drywall | 2,710 | SF | 5 | \$62,780 |
| | Doors - Steel Doors incl hw | 2 | EA | 6 | \$602 |
| | Floor - Concrete Epoxy/ Painted | 2,710 | SF | 6 | \$1,434 |
| | Lighting - Pendent/Surface | 30 | EA | 7 | \$0 |
| | Main Floor Seating | 288 | EA | 6 | \$50,088 |
| | Stage | 528 | SF | 6 | \$3,050 |
| | Stage Curtain | 2 | EA | 6 | \$0 |
| | Stage Lighting System | - 1 | EA | 6 | \$8,077 |
| | Stage-Stairs - Wood | 12 | LF | 6 | \$141 |
| | Stairs - Terrazzo | 12 | LF | 6 | \$92 |
| | Walls - Plaster/Drywall | 3,197 | SF | 5 | \$27,659 |
| Gymnasia | | | | | |
| | Ceiling - Plaster/Drywall | 30 | SF | 4 | \$1,009 |
| | Ceiling - Plaster/Drywall | 2,728 | SF | 6 | \$15,058 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Wood | 2,758 | SF | 6 | \$19,444 |
| | Lighting - Metal Halide/Sodium Vapor | 10 | EA | 6 | \$1,337 |
| | Walls - Plaster/Drywall | 40 | SF | 4 | \$892 |
| | Walls - Plaster/Drywall | 1,979 | SF | 6 | \$5,462 |
| Library | | | | | |
| | AC Unit | 1 | EA | 4 | \$6,086 |
| | AC Unit | 1 | EA | 6 | \$496 |
| | Casework | 60 | LF | 6 | \$1,515 |
| | Ceiling - Plaster/Drywall | 1,446 | SF | 5 | \$13,254 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Carpet | 1,446 | SF | 6 | \$3,081 |
| | Lighting - Pendent/Surface | 28 | EA | 7 | \$0 |
| | Storage/ Closet | 6 | SF | 6 | \$44 |
| | Walls - Plaster/Drywall | 1,706 | SF | 5 | \$12,930 |
| | | | | | |



Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|---------------------------------|----------|------|------|----------|
| Library | | | | | |
| MDF_IDF | | | | | |
| | AC Unit | 1 | EA | 6 | \$496 |
| | Doors - Steel Doors incl hw | 1 | EA | 6 | \$301 |
| | Finishes | 166 | SF | 5 | \$2,680 |
| Mechanical/ Servi | ce Rooms | | | | |
| | Janitor's Closet | 54 | SF | 6 | \$387 |
| | Storage Room | 788 | SF | 6 | \$5,645 |
| Restroom | | | | | |
| | Accessories | 2,417 | SF | 6 | \$22,293 |
| | Ceiling - Plaster/Drywall | 82 | SF | 5 | \$752 |
| | Ceiling - Plaster/Drywall | 2,335 | SF | 6 | \$8,081 |
| | Doors - Steel Doors incl hw | 16 | EA | 6 | \$4,816 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Tile Ceramic/ Porcelain | 67 | SF | 5 | \$1,070 |
| | Floor - Tile Ceramic/ Porcelain | 2,350 | SF | 6 | \$4,974 |
| | Floor Drain | 8 | EA | 6 | \$8,473 |
| | Hand Dryer | 8 | EA | 6 | \$1,840 |
| | Lavatory | 16 | EA | 6 | \$5,114 |
| | Lighting - Pendent/Surface | 1 | EA | 6 | \$124 |
| | Lighting - Pendent/Surface | 33 | EA | 7 | \$0 |
| | Partitions | 27 | EA | 6 | \$8,017 |
| | Urinals | 14 | EA | 6 | \$4,704 |
| | Walls - Plaster/Drywall | 52 | SF | 5 | \$394 |
| | Walls - Plaster/Drywall | 1,404 | SF | 6 | \$3,875 |
| | Walls - Structural Glazed Tile | 1,372 | SF | 6 | \$4,316 |
| | Water Closet | 32 | EA | 6 | \$10,751 |

Rooms (Other Than Classrooms) Subtotal:

Category: Building Interior

| 5 | j | | | | |
|----------|-----------------------------|----------|------|------|----------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Corridor | | | | | |
| | Ceiling - Plaster/Drywall | 10,248 | SF | 6 | \$63,455 |
| | Doors - Steel Doors incl hw | 4 | EA | 6 | \$1,204 |
| | | | | | |

\$449,030



Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|--------------------------------------|----------|------|------|-------------|
| Corridor | | | | | |
| | Doors - Wood Doors include hw | 4 | EA | 6 | \$1,204 |
| | Drinking Fountains - Double Fountain | 4 | EA | 6 | \$1,344 |
| | Floor - Terrazzo | 2,050 | SF | 6 | \$17,208 |
| | Floor - Tile/Sheet | 8,200 | SF | 6 | \$4,456 |
| | Lighting - Pendent/Surface | 68 | EA | 7 | \$0 |
| | Student Lockers - One Tier | 438 | EA | 6 | \$40,662 |
| | Walls - Plaster/Drywall | 18,885 | SF | 6 | \$83,717 |
| Safety | | | | | |
| | Camera Viewing Station | 1 | EA | 6 | \$683 |
| | Security Cameras | 9 | EA | 6 | \$1,746 |
| Stairs | | | | | |
| | Ceiling - Plaster/Drywall | 2,160 | SF | 6 | \$15,815 |
| | Floor - Terrazzo | 880 | SF | 6 | \$7,387 |
| | Floor - Tile/Sheet | 280 | SF | 6 | \$152 |
| | Handrails | 256 | LF | 6 | \$2,218 |
| | Lighting - Pendent/Surface | 16 | EA | 7 | \$0 |
| | Stairs - Terrazzo | 120 | LF | 6 | \$1,114 |
| | Walls - Plaster/Drywall | 8,100 | SF | 6 | \$22,355 |
| Building Interi | Building Interior Subtotal: | | | | |
| Tatal Duildin n | - Occid | | | | ¢4.057.000 |
| Total Building | Cost | | | | \$4,357,962 |
| Building: Anno | A Y | | | | |

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------|--------------------------------------|----------|------|------|---------|
| Entrance | | | | | |
| | Exterior Doors - Exterior FRP Door | 6 | EA | 6 | \$3,788 |
| | Exterior Doors - Exterior Steel Door | 3 | EA | 6 | \$1,442 |
| | Exterior Doors - Transom Lite | 6 | EA | 6 | \$1,880 |
| | Exterior Stairs - Concrete | 3 | LF | 5 | \$329 |
| | Exterior Stairs - Concrete | 17 | LF | 6 | \$1,390 |
| Foundation | | | | | |
| | Foundation - Concrete | 531 | LF | 7 | \$0 |
| | Superstructure - Concrete | 21,061 | SF | 7 | \$0 |



Building: Annex

| Category: Buil | ding Exterior | | | | |
|----------------|---|----------|------|------|-----------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Foundation | | | | | |
| Lighting | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | 5 | EA | 6 | \$2,683 |
| | Exterior Lighting - Wall Mounted | 2 | EA | 4 | \$2,060 |
| | Exterior Lighting - Wall Mounted | 8 | EA | 6 | \$2,310 |
| Roof System | | | | | |
| | Coping - Metal | 607 | LF | 6 | \$19,496 |
| | Downspouts - Interior Downspouts | 88 | LF | 6 | \$2,925 |
| | Roof - Asphalt Gravel Ballast | 13,527 | SF | 4 | \$379,135 |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 13,527 | SF | 7 | \$0 |
| Walls | | | | | |
| | Exterior Walls - Precast Panel Wall | 12 | SF | 5 | \$134 |
| | Exterior Walls - Precast Panel Wall | 11,682 | SF | 6 | \$78,515 |
| Windows | | | | | |
| | Curtain wall - Glazed Double Pane | 18 | SF | 6 | \$202 |
| | Curtain wall - Louver | 216 | SF | 6 | \$2,422 |
| | Guard - Guards wire guard | 576 | SF | 6 | \$7,355 |
| | Lintels - Steel | 222 | LF | 6 | \$6,444 |
| | Windows - Casement Aluminum Double-pane | 54 | SF | 6 | \$403 |
| | Windows - Casement Lexan | 72 | SF | 6 | \$537 |
| | Windows - Sash Aluminum Double-pane | 1,332 | SF | 6 | \$9,943 |
| Building Exter | ior Subtotal: | | | | \$523,392 |

Building: Annex

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|--|----------|------|------|---------|
| Emergency System | | | | | |
| | Automatic Transfer Switch | 1 | EA | 6 | \$408 |
| | Emergency Battery Packs - Corridors and Stairs | 4 | EA | 6 | \$810 |
| | Exit Signs - Corridors and Stairs | 26 | EA | 6 | \$3,893 |
| | Exit Signs - Lunchroom | 8 | EA | 6 | \$1,198 |
| | Security System - CCTV | 21,061 | SF | 6 | \$6,325 |
| | Security System - Intrusion Detection | 21,061 | SF | 6 | \$5,421 |



Category: Electrical System

| 0 | | 0 | 1114 | David | 0 |
|--------------------|--|----------|------|-------|----------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 6 | \$2,921 |
| | Main Electrical Service - 1200 A 120/208/3PH | 1 | EA | 6 | \$5,078 |
| | PA System | 21,061 | SF | 6 | \$6,927 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - Above 100 A | 5 | EA | 6 | \$2,485 |
| | Main Distribution Panels - 400 - 600 amp | 1 | EA | 6 | \$528 |
| Electrical Systen | n Subtotal: | | | | \$35,994 |

Building: Annex

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|--------------------------|----------|------|------|----------|
| Fire Alarm | | | | | |
| | Fire Alarm Panel | 1 | EA | 6 | \$6,406 |
| | Fire Alarm Strobe Lights | 21,061 | SF | 6 | \$7,529 |
| | Fire Alarm_System | 21,061 | SF | 6 | \$10,240 |
| Sprinkler System | | | | | |
| | Sprinkler Heads | 21,061 | SF | 7 | \$0 |
| | Sprinkler Piping | 21,061 | SF | 6 | \$3,915 |
| | Wet Sprinkler System | 21,061 | SF | 6 | \$5,421 |
| Safty System S | ubtotal: | | | | \$33,511 |

Safty System Subtotal:

Building: Annex

Category: Mechanical System

| Item - Type | Quantity | Unit | Rank | Cost |
|--|---|--|--|--|
| | | | | |
| Condensing Unit- Ground Mounted - Less than 5 tons | 1 | EA | 6 | \$3,334 |
| | | | | |
| Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 11 - 20 tons | 1 | EA | 5 | \$17,658 |
| | | | | |
| Unit Heater - Electric | 4 | EA | 6 | \$1,111 |
| Wall Heater - Electric | 12 | EA | 6 | \$1,667 |
| | Condensing Unit- Ground Mounted - Less than 5 tons Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 11 - 20 tons Unit Heater - Electric | Condensing Unit- Ground Mounted - Less than 5 tons 1 Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained 1 Compressor - 11 - 20 tons 4 | Condensing Unit- Ground Mounted - Less than 5 tons 1 EA Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained 1 EA Unit Heater - Electric 4 EA | Condensing Unit- Ground Mounted - Less than 5 tons 1 EA 6 Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained 1 EA 5 Unit Heater - Electric 4 EA 6 |



Building: Annex

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|---|----------|------|------|-----------|
| Temperature Control | | | | | |
| | DDC System | 21,061 | SF | 4 | \$133,419 |
| | Thermostats - DDC | 14 | EA | 6 | \$0 |
| Unit Ventilation | | | | | |
| | Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor | 14 | EA | 5 | \$138,331 |
| Ventilation | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | 1 | EA | 7 | \$0 |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 3 | EA | 7 | \$0 |
| | Type I Exhaust Hood- Kitchen | 1 | EA | 6 | \$1,248 |
| Mechanical Syste | m Subtotal: | | | | \$296,768 |

Building: Annex

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------|--|----------|------|------|----------|
| Hot Water | | | | | |
| | Electric Heater - Greater than 50 KW | 1 | EA | 6 | \$682 |
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 21,026 | SF | 6 | \$4,209 |
| | Domestic Piping-Cold Water Horizontal Lines | 21,026 | SF | 6 | \$5,111 |
| | Domestic Piping-Cold Water Risers | 21,026 | SF | 6 | \$3,909 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 21,026 | SF | 6 | \$3,307 |
| | Domestic Piping-Hot Water Horizontal Lines | 21,026 | SF | 6 | \$3,909 |
| | Domestic Piping-Hot Water Return Lines | 21,026 | SF | 6 | \$3,007 |
| | Domestic Piping-Hot Water Return Risers | 21,026 | SF | 6 | \$3,007 |
| | Sanitary Piping | 21,026 | SF | 6 | \$19,243 |
| | Storm Piping | 21,026 | SF | 6 | \$18,341 |
| | Vent Piping | 21,026 | SF | 6 | \$14,132 |
| Plumbing Sys | tem Subtotal: | | | | \$78,857 |

| Building: Annex | | | | | |
|---------------------|-------------|----------|------|------|------|
| Category: Classroon | IS | | | | |
| Group | Item - Type | Quantity | Unit | Rank | Cost |



Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------------|-----------------------------|----------|------|------|----------------|
| Computer Lab (1 roo | om) | | | | |
| | Casework | 18 | LF | 6 | \$455 |
| | Ceiling - Lay-in | 720 | SF | 6 | \$2,162 |
| | Chalk Board | 12 | LF | 4 | \$1,102 |
| | Charging Station | 1 | EA | 6 | \$485 |
| | Doors - Steel Doors incl hw | 1 | EA | 6 | \$301 |
| | Floor - Carpet | 720 | SF | 6 | \$1,534 |
| | Lighting - Lay-in | 10 | EA | 7 | \$0 |
| | Marker Board | 16 | LF | 6 | \$343 |
| | Walls - Concrete Block | 243 | SF | 6 | \$712 |
| | Walls - Metal Panel | 728 | SF | 6 | \$5,434 |
| | Wireless System | 1 | EA | 6 | \$372 |
| | Work Sink | 1 | EA | 6 | \$379 |
| Kindonnerten (4. noor | | | | | |
| Kindergarten (1 roo | Casework | 48 | LF | 6 | \$1,212 |
| | Ceiling - Lay-in | 992 | SF | 6 | \$2,979 |
| | Doors - Steel Doors incl hw | 1 | EA | 6 | \$301 |
| | Floor - Carpet | 992 | SF | 6 | \$2,114 |
| | Lighting - Lay-in | 14 | EA | 7 | \$0 |
| | Marker Board | | LF | 6 | \$343 |
| | Storage/ Closet | 16 24 | SF | 6 | \$343 \$174 |
| | Walls - Concrete Block | | SF | | |
| | | 291 | | 6 | \$853 |
| | Walls - Metal Panel | 872 | SF | 6 | \$6,509 |
| | Work Sink | 1 | EA | 6 | \$379 |
| Pre School (1 room) | | | | | |
| | Casework | 16 | LF | 6 | \$404 |
| | Ceiling - Lay-in | 1,448 | SF | 6 | \$4,348 |
| | Chalk Board | 6 | LF | 4 | \$551 |
| | Doors - Steel Doors incl hw | 3 | EA | 6 | \$903 |
| | Floor - Tile | 1,448 | SF | 6 | \$3,168 |
| | Lighting - Lay-in | 21 | EA | 7 | \$0 |
| | Marker Board | 12 | LF | 6 | \$257 |
| | Storage/ Closet | 120 | SF | 6 | \$870 |
| | Walls - Concrete Block | 351 | SF | 6 | \$1,029 |
| | Walls - Metal Panel | 1,352 | SF | 6 | \$10,092 |
| Regular Classroom | (8 rooms) | | | | |
| | Casework | 230 | LF | 6 | \$5,808 |



Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|-----------------------------|----------|------|------|-----------|
| Regular Classro | om (8 rooms) | | | | |
| | Ceiling - Lay-in | 5,980 | SF | 6 | \$17,958 |
| | Chalk Board | 60 | LF | 4 | \$5,508 |
| | Doors - Steel Doors incl hw | 8 | EA | 6 | \$2,408 |
| | Floor - Carpet | 5,980 | SF | 6 | \$12,742 |
| | Lighting - Lay-in | 74 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 10 | EA | 7 | \$0 |
| | Marker Board | 116 | LF | 6 | \$2,485 |
| | Storage/ Closet | 132 | SF | 6 | \$957 |
| | Walls - Concrete Block | 2,096 | SF | 6 | \$6,144 |
| | Walls - Metal Panel | 6,274 | SF | 6 | \$46,833 |
| | Work Sink | 3 | EA | 6 | \$1,137 |
| Classrooms | Subtotal: | | | | \$151,745 |

Classrooms Subtotal:

Building: Annex

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|-----------------------------|----------|------|------|----------|
| Administrative Sui | tes/Offices | | | | |
| | Ceiling - Lay-in | 673 | SF | 6 | \$2,021 |
| | Doors - Steel Doors incl hw | 2 | EA | 6 | \$602 |
| | Floor - Carpet | 575 | SF | 6 | \$1,225 |
| | Floor - Tile | 98 | SF | 6 | \$214 |
| | Lighting - Lay-in | 8 | EA | 6 | \$952 |
| | Power Distribution | 12 | EA | 6 | \$25,499 |
| | Walls - Concrete Block | 216 | SF | 6 | \$633 |
| | Walls - Metal Panel | 968 | SF | 6 | \$7,226 |
| Gymnasia | | | | | |
| | Ceiling - Lay-in | 1,907 | SF | 6 | \$5,727 |
| | Doors - Steel Doors incl hw | 4 | EA | 6 | \$1,204 |
| | Floor - Tile | 1,907 | SF | 6 | \$4,172 |
| | Lighting - Lay-in | 40 | EA | 6 | \$4,759 |
| | Sound System | 1 | EA | 6 | \$41,654 |
| | Walls - Concrete Block | 2,355 | SF | 6 | \$6,904 |
| | Walls - Metal Panel | 785 | SF | 6 | \$5,860 |
| Kitchen | | | | | |
| | Ceiling - Lay-in | 1,578 | SF | 6 | \$4,739 |



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|---------------------------------|----------|------|------|---------|
| Kitchen | | | | | |
| | Doors - Steel Doors incl hw | 3 | EA | 6 | \$903 |
| | Floor - Tile | 1,578 | SF | 6 | \$3,453 |
| | Lighting - Lay-in | 27 | EA | 6 | \$3,212 |
| | Serving Line | 12 | LF | 6 | \$714 |
| | Storage/ Closet | 180 | SF | 6 | \$1,305 |
| | Walls - Concrete Block | 768 | SF | 6 | \$2,251 |
| | Walls - Metal Panel | 768 | SF | 6 | \$5,733 |
| Locker/Shower Roo | m | | | | |
| | Accessories | 134 | SF | 6 | \$525 |
| | Ceiling - Lay-In | 134 | SF | 6 | \$402 |
| | Doors - Steel Doors incl hw | 2 | EA | 6 | \$602 |
| | Floor - Tile/Sheet | 134 | SF | 6 | \$134 |
| | Lavatory | 1 | EA | 6 | \$320 |
| | Lighting - Pendent/Surface | 2 | EA | 6 | \$248 |
| | Student Lockers - One Tier | 6 | EA | 6 | \$557 |
| | Walls - Metal Panel | 540 | SF | 6 | \$4,031 |
| | Water Closet | 1 | EA | 6 | \$336 |
| MDF_IDF | | | | | |
| | Doors - Steel Doors incl hw | 1 | EA | 6 | \$301 |
| | Finishes | 97 | SF | 6 | \$692 |
| | Ventilation and Cooling | 1 | EA | 6 | \$1,855 |
| Mechanical/ Service | Rooms | | | | |
| | Janitor's Closet | 64 | SF | 6 | \$459 |
| | Mechanical/ Service Rooms | 184 | SF | 6 | \$1,318 |
| | Vaults | 118 | SF | 6 | \$845 |
| Restroom | | | | | |
| | Accessories | 751 | SF | 6 | \$6,927 |
| | Ceiling - Lay-in | 751 | SF | 6 | \$2,255 |
| | Doors - Steel Doors incl hw | 11 | EA | 6 | \$3,311 |
| | Floor - Tile Ceramic/ Porcelain | 751 | SF | 6 | \$1,589 |
| | Floor Drain | 2 | EA | 6 | \$2,118 |
| | Hand Dryer | 4 | EA | 6 | \$920 |
| | Lavatory | 7 | EA | 6 | \$2,237 |
| | Lighting - Lay-in | 7 | EA | 6 | \$833 |
| | Partitions | 7 | EA | 6 | \$2,078 |



Building: Annex

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|---|----------|------|------|---------|
| Restroom | | | | | |
| | Urinals | 3 | EA | 6 | \$1,008 |
| | Walls - Concrete Block | 444 | SF | 6 | \$1,492 |
| | Walls - Metal Panel | 1,100 | SF | 6 | \$8,211 |
| | Water Closet | 9 | EA | 6 | \$3,024 |
| Rooms (Othe | Rooms (Other Than Classrooms) Subtotal: | | | | |

Building: Annex

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|--------------------------------------|----------|------|------|----------|
| Corridor | | | | | |
| | Ceiling - Lay-in | 2,071 | SF | 6 | \$6,219 |
| | Doors - Steel Doors incl hw | 6 | EA | 6 | \$1,806 |
| | Drinking Fountains - Single Fountain | 2 | EA | 6 | \$551 |
| | Floor - Carpet | 1,398 | SF | 6 | \$2,979 |
| | Floor - Tile/Sheet | 673 | SF | 6 | \$366 |
| | Lighting - Lay-in | 8 | EA | 6 | \$952 |
| | Lighting - Lay-in | 6 | EA | 7 | \$0 |
| | Walls - Metal Panel | 3,920 | SF | 6 | \$29,261 |
| Stairs | | | | | |
| | Ceiling - Lay-in | 504 | SF | 6 | \$1,514 |
| | Floor - Carpet | 240 | SF | 6 | \$511 |
| | Floor - Tile | 240 | SF | 6 | \$130 |
| | Handrails | 128 | LF | 6 | \$1,109 |
| | Lighting - Lay-in | 6 | EA | 7 | \$0 |
| | Lighting - Wall Mounted | 4 | EA | 7 | \$0 |
| | Stairs - Terrazzo | 60 | LF | 6 | \$557 |
| | Walls - Metal Panel | 2,600 | SF | 6 | \$19,408 |
| Building Interi | or Subtotal: | | | | \$65,363 |

Building Interior Subtotal:

Total Building Cost

Building: Modular 1

Category: Building Exterior



Edward Coles Elementary Language Academy

8441 S Yates Blvd Chicago, IL 60617

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|---|----------|------|------|-----------|
| Entrance | | | | | |
| | Exterior Doors - Exterior Steel Door | 2 | EA | 5 | \$2,683 |
| | Exterior Doors - Exterior Steel Door | 1 | EA | 6 | \$481 |
| | Exterior Stairs - Steel or Aluminum | 32 | LF | 4 | \$6,913 |
| | Ramp Handrail - Steel_Ramp Handrail | 60 | LF | 6 | \$520 |
| | Ramps - Steel or Aluminum | 27 | LF | 5 | \$14,517 |
| | Stair Handrail - Steel_Stair Handrail | 40 | LF | 6 | \$347 |
| Foundation | | | | | |
| | Superstructure - Steel | 1,726 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 2 | EA | 6 | \$577 |
| Roof System | | | | | |
| | Coping - Metal | 187 | LF | 6 | \$6,006 |
| | Downspouts - Exterior Downspouts | 22 | LF | 6 | \$731 |
| | Roof - Metal | 1,960 | SF | 6 | \$26,262 |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 1,726 | SF | 7 | \$0 |
| Walls | | | | | |
| | Exterior Walls - Wood Siding | 2,057 | SF | 4 | \$43,005 |
| Windows | | | | | |
| | Guard - Guards perforated | 40 | SF | 6 | \$511 |
| | Windows - Casement Aluminum | 40 | SF | 6 | \$299 |
| Building Exterior | ^r Subtotal: | | | | \$102,852 |

Building: Modular 1

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|--|----------|------|------|-------|
| Emergency System | | | | | |
| | Emergency A/C Power - Corridors and Stairs | 64 | SF | 6 | \$19 |
| | Emergency Battery Packs - Corridors and Stairs | 4 | EA | 6 | \$810 |
| | Exit Signs - Corridors and Stairs | 4 | EA | 6 | \$599 |
| | Security System - CCTV | 1,726 | SF | 6 | \$518 |
| | Security System - Intrusion Detection | 1,726 | SF | 6 | \$444 |
| Main Service | | | | | |
| | PA System | 1,726 | SF | 6 | \$568 |



Building: Modular 1

| Category: Elec Group | ctrical System Item - Type | Quantity | Unit | Rank | Cost |
|-------------------------|-----------------------------------|----------|------|------|-------------------------|
| Power Distribution | | | | | |
| Electrical Syst | Lighting and Power Panels - 100 A | 2 | EA | 6 | \$598 \$3,557 |

Electrical System Subtotal:

Building: Modular 1

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------|----------------------|----------|------|---------|---------|
| Fire Alarm | | | | | |
| | Fire Alarm_System | 1,726 | SF | 4 | \$3,431 |
| Sprinkler System | | | | | |
| | Sprinkler Heads | 1,726 | SF | 7 | \$0 |
| | Sprinkler Piping | 1,726 | SF | 6 | \$321 |
| | Wet Sprinkler System | 1,726 | SF | 6 | \$444 |
| Safty System Subtotal: | | | | \$4,196 | |

Building: Modular 1

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|--|----------|------|------|----------|
| Temperature Control | | | | | |
| | Thermostats - DDC | 2 | EA | 6 | \$0 |
| Unit Ventilation | | | | | |
| | Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor | 2 | EA | 5 | \$19,762 |
| Ventilation | | | | | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 3 | EA | 4 | \$5,826 |
| Mechanical System | n Subtotal: | | | | \$25,588 |

Mechanical System Subtotal:

Building: Modular 1

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------|-----------------------------------|----------|------|------|-------|
| Hot Water | | | | | |
| | Electric Heater - Less than 20 KW | 1 | EA | 6 | \$682 |



| Category: | Plumbing | System |
|-----------|----------|--------|
|-----------|----------|--------|

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|---|----------|------|------|---------|
| Piping | | | | | |
| | Domestic Piping-Cold Water Horizontal Lines | 1,726 | SF | 6 | \$420 |
| | Domestic Piping-Hot Water Horizontal Lines | 1,726 | SF | 6 | \$321 |
| | Domestic Piping-Hot Water Return Lines | 1,726 | SF | 6 | \$247 |
| | Sanitary Piping | 1,726 | SF | 6 | \$1,580 |
| | Storm Piping | 1,726 | SF | 6 | \$1,506 |
| | Vent Piping | 1,726 | SF | 6 | \$1,160 |
| Plumbing Sy | stem Subtotal: | | | | \$5,915 |

Plumbing System Subtotal:

Building: Modular 1

| Category: 0 | Classrooms |
|-------------|------------|
|-------------|------------|

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------|-----------------------------------|----------|----------|------|---------|
| Regular Classro | om (2 rooms) | | | | |
| | Ceiling - Lay-in | 1,536 | SF | 6 | \$4,613 |
| | Chalk Board | 24 | LF | 4 | \$2,203 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Carpet | 768 | SF | 6 | \$1,636 |
| | Floor - Tile | 768 | SF | 6 | \$1,680 |
| | Lighting - Pendent/Surface | 40 | EA | 6 | \$4,956 |
| | Storage/ Closet | 72 | SF | 6 | \$522 |
| | Walls - Vinyl Coated Gypsum Panel | 1,798 | SF | 6 | \$4,962 |
| Classrooms Subtotal: | | | \$21,175 | | |

Building: Modular 1

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|-----------------------------------|----------|------|------|---------|
| Restroom | | | | | |
| | Accessories | 96 | SF | 6 | \$885 |
| | Ceiling - Lay-in | 96 | SF | 6 | \$288 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Tile | 96 | SF | 6 | \$210 |
| | Lavatory | 2 | EA | 6 | \$639 |
| | Lighting - Pendent/Surface | 2 | EA | 6 | \$248 |
| | Walls - Vinyl Coated Gypsum Panel | 476 | SF | 6 | \$1,314 |
| | Water Closet | 2 | EA | 6 | \$672 |



Building: Modular 1

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-----------------------|----------|------|------|---------|
| Rooms (Other Than | Classrooms) Subtotal: | | | | \$4,858 |

Building: Modular 1

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------------------|--------------------------------------|----------|------|------|---------|
| Corridor | | | | | |
| | Ceiling - Lay-in | 64 | SF | 6 | \$192 |
| | Drinking Fountains - Single Fountain | 1 | EA | 6 | \$276 |
| | Floor - Tile/Sheet | 64 | SF | 6 | \$35 |
| | Lighting - Pendent/Surface | 2 | EA | 7 | \$0 |
| | Walls - Vinyl Coated Gypsum Panel | 289 | SF | 6 | \$798 |
| Building Interior Subtotal: | | | | | \$1,300 |

Total Building Cost \$169,440

Building: Modular 2

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|---|----------|------|------|----------|
| Entrance | | | | | |
| | Exterior Doors - Exterior Steel Door | 2 | EA | 5 | \$2,683 |
| | Exterior Doors - Exterior Steel Door | 1 | EA | 6 | \$481 |
| | Exterior Stairs - Steel or Aluminum | 32 | LF | 4 | \$6,913 |
| | Stair Handrail - Steel_Stair Handrail | 40 | LF | 6 | \$347 |
| Foundation | | | | | |
| | Superstructure - Steel | 1,726 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 2 | EA | 6 | \$577 |
| Roof System | | | | | |
| | Coping - Metal | 187 | LF | 6 | \$6,006 |
| | Downspouts - Exterior Downspouts | 22 | LF | 6 | \$731 |
| | Roof - Metal | 1,960 | SF | 6 | \$26,262 |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 1,726 | SF | 7 | \$0 |



Building: Modular 2

| Group | Item - Type | Quantity | Unit | Rank | Cost | |
|-----------------------------|------------------------------|----------|------|------|----------|--|
| Walls | | | | | | |
| | Exterior Walls - Wood Siding | 2,057 | SF | 4 | \$43,005 | |
| Windows | | | | | | |
| | Guard - Guards perforated | 40 | SF | 6 | \$511 | |
| | Windows - Casement Aluminum | 40 | SF | 6 | \$299 | |
| Building Exterior Subtotal: | | | | | | |

Building: Modular 2

Category: Electrical System

| 0 / | | | | | |
|-----------------------------|--|----------|------|------|---------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Emergency System | | | | | |
| | Emergency A/C Power - Corridors and Stairs | 64 | SF | 6 | \$19 |
| | Emergency Battery Packs - Corridors and Stairs | 4 | EA | 6 | \$810 |
| | Exit Signs - Corridors and Stairs | 4 | EA | 6 | \$599 |
| | Security System - CCTV | 1,726 | SF | 6 | \$518 |
| | Security System - Intrusion Detection | 1,726 | SF | 6 | \$444 |
| Main Service | | | | | |
| | PA System | 1,726 | SF | 6 | \$568 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 2 | EA | 6 | \$598 |
| Electrical System Subtotal: | | | | | \$3,557 |

Building: Modular 2

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|--------------------------|----------|------|------|---------|
| Fire Alarm | | | | | |
| | Fire Alarm Strobe Lights | 1,726 | SF | 4 | \$2,345 |
| | Fire Alarm_System | 1,726 | SF | 4 | \$3,431 |
| Sprinkler System | | | | | |
| | Sprinkler Heads | 1,726 | SF | 7 | \$0 |
| | Sprinkler Piping | 1,726 | SF | 6 | \$321 |
| | Wet Sprinkler System | 1,726 | SF | 6 | \$444 |



| Category: Sa | afty System | | | | |
|--------------|-------------|----------|------|------|---------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Safty System | n Subtotal: | | | | \$6,541 |

Building: Modular 2

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|--|----------|------|------|----------|
| • | | Quantity | onit | Nank | 0031 |
| Temperature Contr | rol | | | | |
| | Thermostats - DDC | 2 | EA | 6 | \$0 |
| Unit Ventilation | | | | | |
| | Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor | 2 | EA | 5 | \$19,762 |
| Ventilation | | | | | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 3 | EA | 4 | \$5,826 |
| Mechanical Sv | stem Subtotal: | | | | \$25,588 |

Building: Modular 2

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------|---|----------|------|------|---------|
| Hot Water | | | | | |
| | Electric Heater - Less than 20 KW | 1 | EA | 6 | \$682 |
| Piping | | | | | |
| | Domestic Piping-Cold Water Horizontal Lines | 1,727 | SF | 6 | \$420 |
| | Domestic Piping-Hot Water Horizontal Lines | 1,726 | SF | 6 | \$321 |
| | Domestic Piping-Hot Water Return Lines | 1,726 | SF | 6 | \$247 |
| | Sanitary Piping | 1,726 | SF | 6 | \$1,580 |
| | Storm Piping | 1,726 | SF | 6 | \$1,506 |
| | Vent Piping | 1,726 | SF | 6 | \$1,160 |
| Plumbing Syst | tem Subtotal: | | | | \$5 915 |

Plumbing System Subtotal:

| \$5 | .91 | Ę |
|-----|-----|---|
| | | |

Building: Modular 2

| Category: Classrooms | | | | | | | | |
|-------------------------|-----------------------------|----------|------|------|---------|--|--|--|
| Group | Item - Type | Quantity | Unit | Rank | Cost | | | |
| Regular Classroom (2 ro | Regular Classroom (2 rooms) | | | | | | | |
| | Ceiling - Lay-in | 1,536 | SF | 6 | \$4,613 | | | |

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|-----------------------------------|----------|------|------|----------|
| Regular Classro | om (2 rooms) | | | | |
| | Chalk Board | 12 | LF | 4 | \$1,102 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Carpet | 768 | SF | 6 | \$1,636 |
| | Floor - Tile | 768 | SF | 6 | \$1,680 |
| | Lighting - Pendent/Surface | 40 | EA | 6 | \$4,956 |
| | Marker Board | 12 | LF | 6 | \$257 |
| | Storage/ Closet | 72 | SF | 6 | \$522 |
| | Walls - Vinyl Coated Gypsum Panel | 1,798 | SF | 6 | \$4,962 |
| Classrooms | Subtotal: | | | | \$20,330 |

Classrooms Subtotal:

Building: Modular 2

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|-----------------------------------|----------|------|------|---------|
| Restroom | | | | | |
| | Accessories | 96 | SF | 6 | \$885 |
| | Ceiling - Lay-in | 96 | SF | 6 | \$288 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Tile | 96 | SF | 6 | \$210 |
| | Lavatory | 2 | EA | 6 | \$639 |
| | Lighting - Pendent/Surface | 2 | EA | 6 | \$248 |
| | Walls - Vinyl Coated Gypsum Panel | 476 | SF | 6 | \$1,314 |
| | Water Closet | 2 | EA | 6 | \$672 |
| Rooms (Othe | r Than Classrooms) Subtotal: | | | | \$4,858 |

Building: Modular 2

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|--------------------------------------|----------|------|------|-------|
| Corridor | | | | | |
| | Ceiling - Lay-in | 64 | SF | 6 | \$192 |
| | Drinking Fountains - Single Fountain | 1 | EA | 6 | \$276 |
| | Floor - Tile/Sheet | 64 | SF | 6 | \$35 |
| | Lighting - Pendent/Surface | 2 | EA | 7 | \$0 |
| | Walls - Vinyl Coated Gypsum Panel | 289 | SF | 6 | \$798 |



\$155,903

Building: Modular 2

| Category: Bu | ilding Interior | | | | |
|----------------------|-----------------|----------|------|------|---------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Building Inte | rior Subtotal: | | | | \$1,300 |
| | | | | | |

Total Building Cost

Building: Modular 3

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|---|----------|------|------|----------|
| Entrance | | | | | |
| | Exterior Doors - Exterior Steel Door | 1 | EA | 5 | \$1,341 |
| | Exterior Doors - Exterior Steel Door | 2 | EA | 6 | \$961 |
| | Exterior Stairs - Steel or Aluminum | 48 | LF | 6 | \$185 |
| | Ramp Handrail - Steel_Ramp Handrail | 90 | LF | 6 | \$780 |
| | Ramps - Steel or Aluminum | 40 | LF | 6 | \$6,009 |
| | Stair Handrail - Steel_Stair Handrail | 50 | LF | 6 | \$433 |
| Foundation | | | | | |
| | Superstructure - Steel | 1,726 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 3 | EA | 6 | \$866 |
| Roof System | | | | | |
| | Coping - Metal | 187 | LF | 6 | \$6,006 |
| | Downspouts - Exterior Downspouts | 2 | LF | 5 | \$162 |
| | Downspouts - Exterior Downspouts | 22 | LF | 6 | \$731 |
| | Roof - Metal | 1,960 | SF | 6 | \$26,262 |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 1,726 | SF | 7 | \$0 |
| Walls | | | | | |
| | Exterior Walls - Wood Siding | 2,057 | SF | 4 | \$43,005 |
| Windows | | | | | |
| | Guard - Guards perforated | 40 | SF | 6 | \$511 |
| | Windows - Casement Aluminum | 40 | SF | 6 | \$299 |
| Building Exterio | | | | | \$87,551 |

Building: Modular 3

Category: Electrical System



Edward Coles Elementary Language Academy

8441 S Yates Blvd Chicago, IL 60617

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|--|----------|------|------|---------|
| Emergency System | | | | | |
| | Emergency A/C Power - Auditoium and Aisle Lighting | 1,726 | SF | 6 | \$913 |
| | Emergency Battery Packs - Corridors and Stairs | 4 | EA | 6 | \$810 |
| | Exit Signs - Corridors and Stairs | 4 | EA | 6 | \$599 |
| | Security System - CCTV | 1,726 | SF | 6 | \$518 |
| | Security System - Intrusion Detection | 1,726 | SF | 6 | \$444 |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 6 | \$2,921 |
| | PA System | 1,726 | SF | 6 | \$568 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 2 | EA | 6 | \$598 |
| Electrical System | Subtotal: | | | | \$7,371 |

Building: Modular 3

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|----------------------|----------|------|------|----------|
| Fire Alarm | | | | | |
| | Fire Alarm Panel | 1 | EA | 6 | \$6,406 |
| | Fire Alarm_System | 1,726 | SF | 4 | \$3,431 |
| Sprinkler System | | | | | |
| | Sprinkler Heads | 1,726 | SF | 7 | \$0 |
| | Sprinkler Piping | 1,726 | SF | 6 | \$321 |
| | Wet Sprinkler System | 1,726 | SF | 6 | \$444 |
| Safty System Su | ubtotal: | | | | \$10,602 |

Safty System Subtotal:

Building: Modular 3

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|---|----------|------|------|----------|
| Temperature Control | | | | | |
| | Thermostats - DDC | 2 | EA | 6 | \$0 |
| Unit Ventilation | | | | | |
| | Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor | 2 | EA | 5 | \$19,762 |
| Ventilation | | | | | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 3 | EA | 4 | \$5,826 |



| Category: Me | chanical System | | | | |
|--------------|------------------|----------|------|--------|----------|
| Group | Item - Type | Quantity | / Un | it Ran | c Cost |
| Mechanical S | System Subtotal: | | | | \$25,588 |

Building: Modular 3

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------|---|----------|------|------|---------|
| Hot Water | | | | | |
| | Electric Heater - Less than 20 KW | 1 | EA | 5 | \$2,443 |
| Piping | | | | | |
| | Domestic Piping-Cold Water Horizontal Lines | 1,726 | SF | 6 | \$420 |
| | Domestic Piping-Hot Water Horizontal Lines | 1,726 | SF | 6 | \$321 |
| | Domestic Piping-Hot Water Return Lines | 1,726 | SF | 6 | \$247 |
| | Sanitary Piping | 1,726 | SF | 6 | \$1,580 |
| | Storm Piping | 1,726 | SF | 6 | \$1,506 |
| | Vent Piping | 1,726 | SF | 6 | \$1,160 |
| Plumbing Sys | tem Subtotal: | | | | \$7,675 |

Building: Modular 3

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-----------------------------------|----------|------|------|---------|
| Store Room (2 roo | oms) | | | | |
| | Ceiling - Lay-in | 1,536 | SF | 6 | \$4,613 |
| | Chalk Board | 24 | LF | 4 | \$2,203 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Carpet | 1,536 | SF | 6 | \$3,273 |
| | Lighting - Pendent/Surface | 40 | EA | 6 | \$4,956 |
| | Storage/ Closet | 72 | SF | 6 | \$522 |
| | Walls - Vinyl Coated Gypsum Panel | 1,598 | SF | 6 | \$4,410 |

Classrooms Subtotal:

Building: Modular 3

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|-------------|----------|------|------|-------|
| Restroom | | | | | |
| | Accessories | 96 | SF | 6 | \$885 |

\$20,579



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------|-----------------------------------|----------|------|------|---------|
| Restroom | | | | | |
| | Ceiling - Lay-in | 96 | SF | 6 | \$288 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Tile | 96 | SF | 6 | \$210 |
| | Lavatory | 2 | EA | 6 | \$639 |
| | Lighting - Pendent/Surface | 2 | EA | 6 | \$248 |
| | Walls - Vinyl Coated Gypsum Panel | 476 | SF | 6 | \$1,314 |
| | Water Closet | 2 | EA | 6 | \$672 |
| Rooms (Other | r Than Classrooms) Subtotal: | | | | \$4,858 |

Rooms (Other Than Classrooms) Subtotal:

Building: Modular 3

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------|--------------------------------------|----------|------|------|---------|
| Corridor | | | | | |
| | Ceiling - Lay-in | 64 | SF | 6 | \$192 |
| | Doors - Wood Doors include hw | 1 | EA | 6 | \$301 |
| | Drinking Fountains - Single Fountain | 1 | EA | 6 | \$276 |
| | Floor - Tile/Sheet | 64 | SF | 6 | \$35 |
| | Lighting - Pendent/Surface | 2 | EA | 7 | \$0 |
| | Walls - Vinyl Coated Gypsum Panel | 289 | SF | 6 | \$798 |
| Building Inter | ior Subtotal: | | | | \$1,601 |

Total Building Cost

\$165,826

Building: Modular 4

Category: Building Exterior

| Item - Type | Quantity | Unit | Rank | Cost |
|---------------------------------------|--|--|--|--|
| | | | | |
| Exterior Doors - Exterior Steel Door | 1 | EA | 5 | \$1,341 |
| Exterior Doors - Exterior Steel Door | 2 | EA | 6 | \$961 |
| Exterior Stairs - Steel or Aluminum | 40 | LF | 6 | \$154 |
| Stair Handrail - Steel_Stair Handrail | 40 | LF | 6 | \$347 |
| | | | | |
| Superstructure - Steel | 1,726 | SF | 7 | \$0 |
| | Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Stairs - Steel or Aluminum Stair Handrail - Steel_Stair Handrail | Exterior Doors - Exterior Steel Door1Exterior Doors - Exterior Steel Door2Exterior Stairs - Steel or Aluminum40Stair Handrail - Steel_Stair Handrail40 | Exterior Doors - Exterior Steel Door1EAExterior Doors - Exterior Steel Door2EAExterior Stairs - Steel or Aluminum40LFStair Handrail - Steel_Stair Handrail40LF | Exterior Doors - Exterior Steel Door1EA5Exterior Doors - Exterior Steel Door2EA6Exterior Stairs - Steel or Aluminum40LF6Stair Handrail - Steel_Stair Handrail40LF6 |



| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|---|----------|------|------|----------|
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 3 | EA | 6 | \$866 |
| Roof System | | | | | |
| | Coping - Metal | 187 | LF | 6 | \$6,006 |
| | Downspouts - Exterior Downspouts | 11 | LF | 4 | \$1,490 |
| | Downspouts - Exterior Downspouts | 11 | LF | 6 | \$366 |
| | Roof - Metal | 1,960 | SF | 6 | \$26,262 |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 1,726 | SF | 7 | \$0 |
| Walls | | | | | |
| | Exterior Walls - Wood Siding | 2,057 | SF | 4 | \$43,005 |
| Windows | | | | | |
| | Guard - Guards perforated | 40 | SF | 6 | \$511 |
| | Windows - Casement Aluminum | 40 | SF | 6 | \$299 |
| Building Exteri | or Subtotal: | | | | \$81,607 |

Building: Modular 4

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost | | |
|--------------------|--|----------|------|------|---------|--|--|
| Emergency System | | | | | | | |
| | Emergency A/C Power - Corridors and Stairs | 64 | SF | 6 | \$19 | | |
| | Emergency Battery Packs - Corridors and Stairs | 4 | EA | 6 | \$810 | | |
| | Exit Signs - Corridors and Stairs | 4 | EA | 6 | \$599 | | |
| | Security System - CCTV | 1,726 | SF | 6 | \$518 | | |
| | Security System - Intrusion Detection | 1,726 | SF | 6 | \$444 | | |
| Main Service | | | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 6 | \$2,921 | | |
| | PA System | 1,726 | SF | 6 | \$568 | | |
| Power Distribution | | | | | | | |
| | Lighting and Power Panels - 100 A | 2 | EA | 6 | \$598 | | |
| Electrical System | Subtotal: | | | | \$6,477 | | |



Edward Coles Elementary Language Academy

8441 S Yates Blvd Chicago, IL 60617

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|----------------------|----------|------|------|----------|
| Fire Alarm | | | | | |
| | Fire Alarm Panel | 1 | EA | 6 | \$6,406 |
| | Fire Alarm_System | 1,726 | SF | 4 | \$3,431 |
| Sprinkler System | | | | | |
| | Sprinkler Heads | 1,726 | SF | 7 | \$0 |
| | Sprinkler Piping | 1,726 | SF | 6 | \$321 |
| | Wet Sprinkler System | 1,726 | SF | 6 | \$444 |
| Safty System | Subtotal: | | | | \$10,602 |

Safty System Subtotal:

Building: Modular 4

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|--|----------|------|------|----------|
| emperature Control | | | | | |
| | Thermostats - DDC | 2 | EA | 6 | \$0 |
| Init Ventilation | | | | | |
| | Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor | 2 | EA | 5 | \$19,762 |
| /entilation | | | | | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 3 | EA | 4 | \$5,826 |
| Mechanical System | a Subtotal: | | | | \$25,588 |

Building: Modular 4

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------|---|----------|------|------|---------|
| Hot Water | | | | | |
| | Electric Heater - Less than 20 KW | 1 | EA | 6 | \$682 |
| Piping | | | | | |
| | Domestic Piping-Cold Water Horizontal Lines | 1,726 | SF | 6 | \$420 |
| | Domestic Piping-Hot Water Horizontal Lines | 1,726 | SF | 6 | \$321 |
| | Domestic Piping-Hot Water Return Lines | 1,726 | SF | 6 | \$247 |
| | Sanitary Piping | 1,726 | SF | 6 | \$1,580 |
| | Storm Piping | 1,726 | SF | 6 | \$1,506 |
| | Vent Piping | 1,726 | SF | 6 | \$1,160 |
| | | | | | |

Plumbing System Subtotal:



Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|-----------------------------------|----------|------|------|----------|
| Store Room (2 ro | oms) | | | | |
| | Ceiling - Lay-in | 1,536 | SF | 6 | \$4,613 |
| | Chalk Board | 24 | LF | 4 | \$2,203 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Carpet | 1,536 | SF | 4 | \$14,123 |
| | Lighting - Pendent/Surface | 40 | EA | 6 | \$4,956 |
| | Storage/ Closet | 72 | SF | 6 | \$522 |
| | Walls - Vinyl Coated Gypsum Panel | 1,798 | SF | 6 | \$4,962 |
| Classrooms S | Subtotal: | | | | \$31,981 |

Classrooms Subtotal:

Building: Modular 4

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------|-----------------------------------|----------|------|------|---------|
| Restroom | | | | | |
| | Accessories | 96 | SF | 6 | \$885 |
| | Ceiling - Lay-in | 96 | SF | 6 | \$288 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Tile | 96 | SF | 6 | \$210 |
| | Lavatory | 2 | EA | 6 | \$639 |
| | Lighting - Pendent/Surface | 2 | EA | 6 | \$248 |
| | Walls - Vinyl Coated Gypsum Panel | 476 | SF | 6 | \$1,314 |
| | Water Closet | 2 | EA | 6 | \$672 |
| Rooms (Other | r Than Classrooms) Subtotal: | | | | \$4,858 |

Building: Modular 4

Category: Building Interior

| 0, | 5 | | | | |
|----------|--------------------------------------|----------|------|------|-------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Corridor | | | | | |
| | Ceiling - Lay-in | 64 | SF | 6 | \$192 |
| | Doors - Wood Doors include hw | 1 | EA | 6 | \$301 |
| | Drinking Fountains - Single Fountain | 1 | EA | 6 | \$276 |
| | Floor - Tile/Sheet | 64 | SF | 6 | \$35 |
| | Lighting - Pendent/Surface | 2 | EA | 7 | \$0 |
| | Walls - Vinyl Coated Gypsum Panel | 289 | SF | 6 | \$798 |
| | | | | | |



\$168,630

Building: Modular 4

| Category: Bu | ilding Interior | | | | |
|----------------|-----------------|----------|------|------|---------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Building Inter | rior Subtotal: | | | | \$1,601 |
| | | | | | |

Total Building Cost

SITE

| Category: | Site |
|-----------|------|
| outegory. | One |

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------|---------------------------------|----------|------|------|-----------|
| Civil/Drainage | | | | | |
| | Civil/ Drainage - Catch Basin | 9 | EA | 7 | \$0 |
| | Civil/ Drainage - Site Manhole | 12 | EA | 7 | \$0 |
| Fencing | | | | | |
| | Fencing - Chain Link | 35 | LF | 5 | \$915 |
| | Fencing - Chain Link | 2,035 | LF | 6 | \$38,209 |
| Landscape | | | | | |
| | Landscape - Grass | 15,220 | SF | 6 | \$12,623 |
| | Landscape - Hardscape- Concrete | 120 | SF | 4 | \$1,771 |
| | Parkway trees | 48 | EA | 7 | \$0 |
| | Planting Beds/ Area | 1,300 | SF | 6 | \$2,138 |
| | Play Area - Asphalt/ Hardscape | 4,526 | SF | 4 | \$47,959 |
| | Play Area - Asphalt/ Hardscape | 51,917 | SF | 5 | \$243,333 |
| | Retaining Wall - Concrete | 700 | SF | 6 | \$16,406 |
| | Trash Receptacles | 1 | EA | 5 | \$505 |
| | Trash Receptacles | 1 | EA | 6 | \$312 |
| Parking Lot | | | | | |
| | Surface - Asphalt | 800 | SF | 4 | \$8,477 |
| | Surface - Asphalt | 25,355 | SF | 5 | \$115,662 |
| Playground | | | | | |
| | Equipment - Pre K 3-5 | 1 | EA | 6 | \$3,546 |
| | Equipment - School Age 5-12 | 1 | EA | 6 | \$3,546 |
| | Surface - Poured Surface | 1,243 | SF | 5 | \$17,082 |
| | Surface - Poured Surface | 2,009 | SF | 6 | \$14,709 |
| Sidewalks | | | | | |
| | Sidewalks - Internal Walks | 257 | LF | 6 | \$3,087 |
| | Sidewalks - Perimeter Sidewalks | 350 | SF | 5 | \$3,343 |



....

SITE

| Category: Site | | | | | |
|-----------------|---|----------|------|------|-----------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Sidewalks | | | | | |
| | Sidewalks - Perimeter Sidewalks | 14,917 | SF | 6 | \$29,651 |
| Signage | | | | | |
| | Flag Pole - Flag Pole | 1 | EA | 6 | \$1,657 |
| | Marquee - Free Standing Back lighted w/ LED | 1 | EA | 6 | \$0 |
| Site Subtotal: | | | | | \$564,931 |
| | | | | | |
| Total Site Cost | | | | | \$564,931 |

Campus Total ^{2 3} \$6,947,912

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------|-------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | ļ | - | | | | ļ | 11 | | | | | ļ | 1 |
| Computer Lab | Regular Classroom | 2nd Floor | 210 | 210 | 712 | 1 | 1 | 34 | 108 | 65 | 40 | Ν | Y | Ν |
| Office | Regular Classroom | 1st Floor | 108 | 108 | 468 | 1 | 2 | 8 | 38 | 4 | 40 | Ν | Y | Ν |
| Office | Regular Classroom | 1st Floor | 116 | 114 | 1,015 | 1 | 1 | 11 | 121 | 79 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 110 | 110 | 712 | 1 | 1 | 6 | 108 | 65 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 112 | 112 | 712 | 1 | 1 | 6 | 108 | 65 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 118 | 118 | 712 | 1 | 1 | 6 | 108 | 65 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 119 | 119 | 712 | 1 | 1 | 8 | 108 | 65 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 121 | 121 | 712 | 1 | 1 | 14 | 120 | 68 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 211 | 211 | 712 | 1 | 1 | 16 | 120 | 68 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 212 | 212 | 712 | 1 | 1 | 14 | 120 | 68 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 213 | 213 | 712 | 1 | 1 | 18 | 120 | 68 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 214 | 214 | 712 | 1 | 1 | 14 | 120 | 68 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 215 | 215 | 712 | 1 | 1 | 16 | 120 | 68 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 216 | 216 | 712 | 1 | 1 | 14 | 120 | 68 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 217 | 217 | 712 | 1 | 1 | 8 | 120 | 68 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 218 | 218 | 712 | 1 | 1 | 14 | 120 | 68 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 219 | 219 | 712 | 1 | 1 | 8 | 120 | 68 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 220 | 220 | 712 | 1 | 1 | 8 | 120 | 68 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 222 | 222 | 712 | 1 | 1 | 8 | 120 | 68 | 40 | Ν | Y | Ν |
| Science Classroom | Regular Classroom | 1st Floor | 117 | 117 | 780 | 1 | 1 | 8 | 120 | 68 | 40 | Ν | Y | N |
| Special Education | Regular Classroom | 1st Floor | 123 | 123 | 694 | 1 | 2 | 10 | 108 | 65 | 40 | Ν | Y | Ν |
| Annex | | | | | | | | | | | | | | |
| Computer Lab | Regular Classroom | 2nd Floor | 235 | 235 | 720 | 1 | 1 | 6 | 114 | 45 | 40 | Ν | Y | Ν |
| Kindergarten | Kindergarten | 1st Floor | 131 | 131 | 992 | 1 | 1 | 6 | 114 | 44 | 40 | Ν | Y | Ν |
| Pre School | Pre School | 1st Floor | 108 | 108 | 1,448 | 1 | 1 | 10 | 152 | 60 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 130 | 130 | 756 | 1 | 2 | 6 | 114 | 45 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 132 | 132 | 756 | 1 | 2 | 6 | 114 | 45 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 230 | 230 | 720 | 1 | 1 | 6 | 114 | 45 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 231 | 231 | 720 | 1 | 1 | 6 | 114 | 45 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 233 | 233 | 720 | 1 | 1 | 6 | 114 | 45 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 234 | 234 | 794 | 1 | 1 | 6 | 114 | 45 | 40 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 236 | 236 | 794 | 1 | 1 | 6 | 114 | 45 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 237 | 237 | 720 | 1 | 1 | 6 | 114 | 45 | 40 | Ν | Y | Ν |
| Modular 1 | | | | | | | | | | | | | | |
| Regular Classroom | Regular Classroom | 1st Floor | 301 | NA | 768 | 1 | 2 | 6 | 12 | 6 | 40 | Ν | Y | Ν |

COLES



Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------|-------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Modular 1 | | | | * | | | | | | | - | | | |
| Regular Classroom | Regular Classroom | 1st Floor | 302 | NA | 768 | 1 | 2 | 6 | 12 | 6 | 40 | Ν | Y | Ν |
| Modular 2 | | | | | | | | | | | | | | |
| Regular Classroom | Regular Classroom | 1st Floor | 303 | NA | 768 | 1 | 1 | 6 | 12 | 6 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 304 | NA | 768 | 1 | 2 | 6 | 12 | 6 | 40 | Ν | Y | Ν |
| Modular 3 | | | | | | | | | | | | | | |
| Store Room | Regular Classroom | 1st Floor | 305 | NA | 768 | 1 | 2 | 6 | 12 | 6 | 40 | Ν | Y | Ν |
| Store Room | Regular Classroom | 1st Floor | 306 | NA | 768 | 1 | 2 | 6 | 12 | 6 | 40 | Ν | Y | Ν |
| Modular 4 | | | | | | | | | | | | | | |
| Store Room | Regular Classroom | 1st Floor | 307 | NA | 768 | 1 | 2 | 6 | 12 | 6 | 40 | Ν | Y | Ν |
| Store Room | Regular Classroom | 1st Floor | 308 | NA | 768 | 1 | 2 | 6 | 12 | 6 | 40 | Ν | Y | N |