

Facility Assessment Report

This report contains a summary of the results from the facility assessment completed on the date noted in the document footer below. This report will roll-up each assessed item with identical rank and total the quantity into a single line, regardless of item location (for location data, see the detailed report). Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|----------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1996 | 3 | 67,964 | \$2,551,104 |
| SITE | | | | \$216,089 |
| Campus Total | | | 67,964 | \$2,767,193 |

Building: Main

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|---|----------|------|------|----------|
| Entrance | | | | | |
| | Entrance Control - Audio and Video | 1 | EA | 6 | \$702 |
| | Exterior Doors - Exterior Steel Door | 2 | EA | 4 | \$7,645 |
| | Exterior Doors - Exterior Steel Door | 7 | EA | 6 | \$3,364 |
| | Exterior Doors - Side lite | 3 | EA | 6 | \$940 |
| | Exterior Doors - Store Front | 12 | EA | 6 | \$6,553 |
| | Exterior Doors - Transom Lite | 12 | EA | 6 | \$3,760 |
| | Exterior Stairs - Concrete | 12 | LF | 6 | \$981 |
| | Power Door Operator and Controls | 2 | EA | 6 | \$0 |
| | Stair Handrail - Steel_Stair Handrail | 10 | LF | 6 | \$87 |
| Foundation | | | | | |
| | Foundation - Concrete | 797 | LF | 7 | \$0 |
| | Superstructure - Metal Deck/ Concrete Topping | 67,964 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 12 | EA | 6 | \$3,465 |
| Roof System | | | | | |
| | Chimney - Metal Flue | 127 | LF | 6 | \$20,084 |
| | Coping - Stone | 962 | LF | 6 | \$30,897 |
| | Downspouts - Interior Downspouts | 300 | LF | 6 | \$9,970 |
| | | | | | |



Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|---|----------|------|------|-------------|
| Roof System | | | | | |
| | Parapet - 16" - 30" Height | 890 | LF | 6 | \$35,559 |
| | Parapet - Parapet > 30" | 72 | LF | 6 | \$4,602 |
| | Roof - Modified Bitumen | 24,509 | SF | 5 | \$515,554 |
| | Roof - Modified Bitumen | 1,278 | SF | 6 | \$12,025 |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 25,787 | SF | 7 | \$0 |
| Walls | | | | | |
| | Canopy - Concrete/ Stucco | 664 | SF | 6 | \$21,972 |
| | Exterior Walls - Brick | 677 | SF | 5 | \$16,119 |
| | Exterior Walls - Brick | 23,201 | SF | 6 | \$155,934 |
| | Exterior Walls - Stone-Cast | 4,397 | SF | 6 | \$29,552 |
| Windows | | | | | |
| | Guard - Guards perforated | 3,904 | SF | 6 | \$49,854 |
| | Lintels - Steel | 838 | LF | 6 | \$24,326 |
| | Windows - Decorative | 72 | SF | 6 | \$537 |
| | Windows - Sash Aluminum Double-pane | 1,312 | SF | 5 | \$70,675 |
| | Windows - Sash Aluminum Double-pane | 5,248 | SF | 6 | \$39,174 |
| Building Exteri | or Subtotal: | | | | \$1,064,332 |

Building Exterior Subtotal:

Building: Main

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|--|----------|------|------|----------|
| Emergency System | 1 | | | | |
| | Automatic Transfer Switch | 1 | EA | 6 | \$408 |
| | Emergency A/C Power - Corridors and Stairs | 10,940 | SF | 6 | \$3,285 |
| | Emergency A/C Power - Gym | 3,503 | SF | 6 | \$1,302 |
| | Emergency A/C Power - Lunchrooms | 2,761 | SF | 6 | \$1,027 |
| | Emergency Battery Packs - Corridors and Stairs | 6 | EA | 6 | \$1,215 |
| | Emergency Battery Packs - Gym | 2 | EA | 6 | \$405 |
| | Emergency Battery Packs - Lunchrooms | 2 | EA | 6 | \$405 |
| | Exit Signs - Corridors and Stairs | 24 | EA | 2 | \$13,092 |
| | Exit Signs - Corridors and Stairs | 2 | EA | 6 | \$299 |
| | Exit Signs - Gym | 2 | EA | 2 | \$1,157 |
| | Exit Signs - Lunchroom | 6 | EA | 2 | \$3,273 |
| | Security System - CCTV | 67,964 | SF | 6 | \$20,410 |
| | Security System - Intrusion Detection | 67,964 | SF | 6 | \$17,494 |



Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|--|----------|------|------|----------|
| Emergency System | n | | | | |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 7 | \$0 |
| | Main Electrical Service - 1600 A 277/480/3PH | 1 | EA | 6 | \$5,977 |
| | PA System | 67,964 | SF | 6 | \$22,353 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 2 | EA | 7 | \$0 |
| | Lighting and Power Panels - Above 100 A | 11 | EA | 7 | \$0 |
| | Main Distribution Panels - 400 - 600 amp | 1 | EA | 7 | \$0 |
| | Main Distribution Panels - Greater than 600 amp | 4 | EA | 7 | \$0 |
| | Main Distribution Panels - Less than 400 amp | 2 | EA | 7 | \$0 |
| | Transformers - 277/480 - 120/208 | 3 | EA | 7 | \$0 |
| Electrical Syste | em Subtotal: | | | | \$92,101 |

Building: Main

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|--------------------------|----------|------|------|----------|
| Fire Alarm | | | | | |
| | Fire Alarm Panel | 1 | EA | 6 | \$6,406 |
| | Fire Alarm Strobe Lights | 67,964 | SF | 6 | \$24,297 |
| | Fire Alarm_System | 67,964 | SF | 5 | \$75,807 |
| | Fire Pump Controller | 1 | EA | 6 | \$1,823 |
| Pump Room Asser | mbly | | | | |
| | Fire Pump - 25-50 hp | 1 | EA | 5 | \$8,163 |
| | Jockey Pump | 1 | EA | 6 | \$758 |
| Sprinkler System | | | | | |
| | Sprinkler Heads | 67,964 | SF | 7 | \$0 |
| | Sprinkler Piping | 67,964 | SF | 7 | \$0 |
| | Wet Sprinkler System | 67,964 | SF | 7 | \$0 |

Safty System Subtotal:

Building: Main

Category: Mechanical System

\$117,254



Agustin Lara Elementary Academy

4619 S Wolcott Ave Chicago, IL 60609

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------|--|----------|------|------|---------------------------|
| Air Conditioning | | | | | |
| | Chemical Pot Feeder | 1 | EA | 7 | \$0 |
| | Chiller-Air Cooled-Screw Type-Roof Mounted - 201 - 300 tons | 1 | EA | 7 | \$0 |
| | Glycol Feed | 1 | EA | 7 | \$0 |
| | Pipes - Chilled Water Pipe- Copper | 800 | LF | 7 | \$0 |
| | Pressure Fill System | 1 | EA | 7 | \$0 |
| Air Handling Systems | | | | | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001- 12000 cfm | 1 | EA | 6 | \$3,350 |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm | 1 | EA | 6 | \$3,350 |
| | Air Intake | 2 | EA | 6 | \$11,529 |
| | Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM | 1 | EA | 6 | \$1,857 |
| | Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM | 1 | EA | 6 | \$2,433 |
| | Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 11 - 20 tons | 1 | EA | 6 | \$2,792 |
| | Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons | 1 | EA | 5 | \$10,623 |
| | VAV Box | 51 | EA | 6 | \$14,237 |
| Boiler Systems | | | | | |
| | Boiler Auxiliary- Non Condensing Hot Water - 3001 - 4000 MBH | 2 | EA | 6 | \$4,093 |
| | Chemical Pot Feeder | 1 | EA | 6 | \$725 |
| | Combustion Dampers | 1 | EA | 6 | \$409 |
| | Glycol Feed System | 1 | EA | 6 | \$539 |
| | Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 3001 - 4000 MBH | 2 | EA | 6 | \$1,996 |
| | Water Fill System | 1 | EA | 6 | \$1,168 |
| Heating Devices | | | | | |
| | Cabinet Heaters - With Hot Water Coil | 4 | EA | 6 | \$1,417 |
| | Duct Heater - Hot Water | 51 | | 6 | \$24,607 |
| | Radiator Panels - Hot Water | 10 | EA | 6 | \$2,778 |
| | Unit Heater - Hot Water | 3 | EA | 6 | \$837 |
| Mechanical Plumbing | | | | | |
| | Chilled Water Pump - 10 - 20 HP | 2 | EA | 6 | \$2,485 |
| | Hot Water Pump - 10 - 20 HP | 2 | EA | 6 | \$2,485 |
| | Hot Water Pump - Less than 10 | 2 | EA | 6 | \$2,222 |
| | Hydronic Supply and Return - Copper | 200 | LF | 6 | \$10,493 |
| | Hydronic Supply and Return - Galvanized | 500 | LF | 6 | \$38,660 |
| Temperature Control | | | | | |
| | DDC System | 67,964 | SF | 5 | \$111,767 |
| | Dage 4 of 15 | | | | Assessment Date: 11/5/201 |



Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cos |
|---------------------|--|----------|------|------|---------|
| Temperature Control | | | | | |
| | Electric Thermostat | 3 | EA | 6 | \$0 |
| | Thermostats - DDC | 51 | EA | 6 | \$0 |
| Ventilation | | | | | |
| | Exhaust Fans- Indoor - Less than 500 CFM | 2 | EA | 6 | \$592 |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 2 | EA | 6 | \$1,185 |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 2 | EA | 6 | \$592 |
| | Type I Exhaust Hood- Kitchen | 1 | EA | 6 | \$1,248 |
| | Type II Exhaust Hood- Warming Kitchen | 2 | EA | 6 | \$1,840 |

Mechanical System Subtotal:

Building: Main

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------|--|----------|------|------|-----------|
| Hot Water | | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | 1 | EA | 7 | \$0 |
| | Gas Heater - 300001 - 600000 BTU/HR | 1 | EA | 6 | \$310 |
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 67,964 | SF | 6 | \$13,606 |
| | Domestic Piping-Cold Water Horizontal Lines | 67,964 | SF | 6 | \$16,522 |
| | Domestic Piping-Cold Water Risers | 67,964 | SF | 6 | \$12,635 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 67,964 | SF | 6 | \$10,691 |
| | Domestic Piping-Hot Water Horizontal Lines | 67,964 | SF | 6 | \$12,635 |
| | Domestic Piping-Hot Water Return Lines | 67,964 | SF | 6 | \$9,719 |
| | Domestic Piping-Hot Water Return Risers | 67,964 | SF | 6 | \$9,719 |
| | Sanitary Piping | 67,964 | SF | 6 | \$62,201 |
| | Storm Piping | 67,964 | SF | 6 | \$59,285 |
| | Vent Piping | 67,964 | SF | 6 | \$45,679 |
| Pumps | | | | | |
| | Pumps - Domestic Booster Pump-Duplex | 1 | EA | 6 | \$1,977 |
| | Pumps - Sump-Simplex | 1 | EA | 6 | \$745 |
| Plumbing Sys | tem Subtotal: | | | | \$255,722 |

Plumbing System Subtotal:

\$262,309

Building: Main



Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|-----------------------------|----------|------|------|---------|
| Art Room (1 room) | | | | | |
| | Casework | 24 | LF | 6 | \$606 |
| | Ceiling - Lay-in | 16 | SF | 5 | \$128 |
| | Ceiling - Lay-in | 916 | SF | 6 | \$2,751 |
| | Doors - Side-lite | 12 | SF | 6 | \$201 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile/Sheet | 932 | SF | 6 | \$933 |
| | Lighting - Lay-in | 9 | EA | 7 | \$C |
| | Walls - Concrete Block | 790 | SF | 6 | \$2,316 |
| | Walls - Plaster/Drywall | 528 | SF | 6 | \$1,457 |
| | Work Sink | 1 | EA | 6 | \$379 |
| Computer Lab (1 ro | om) | | | | |
| | Casework | 28 | LF | 6 | \$707 |
| | Ceiling - Lay-in | 8 | SF | 5 | \$64 |
| | Ceiling - Lay-in | 874 | SF | 6 | \$2,625 |
| | Doors - Side-lite | 12 | SF | 6 | \$201 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile | 882 | SF | 6 | \$1,930 |
| | Lighting - Pendent/Surface | 24 | EA | 7 | \$0 |
| | Marker Board | 10 | LF | 7 | \$C |
| | Walls - Concrete Block | 777 | SF | 6 | \$2,278 |
| | Walls - Plaster/Drywall | 240 | SF | 6 | \$662 |
| | Wireless System | 1 | EA | 7 | \$C |
| Faculty Lounge (1 r | oom) | | | | |
| | Casework | 28 | LF | 6 | \$707 |
| | Ceiling - Lay-in | 12 | SF | 5 | \$96 |
| | Ceiling - Lay-in | 870 | SF | 6 | \$2,613 |
| | Doors - Side-lite | 12 | SF | 6 | \$201 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile | 882 | SF | 6 | \$1,930 |
| | Lighting - Lay-in | 9 | EA | 7 | \$0 |
| | Walls - Concrete Block | 777 | SF | 6 | \$2,278 |
| | Walls - Plaster/Drywall | 240 | SF | 6 | \$662 |
| Kindergarten (2 roo | ms) | | | | |
| | Casework | 110 | LF | 6 | \$2,778 |
| | Ceiling - Lay-in | 12 | SF | 5 | \$96 |
| | Ceiling - Lay-in | 2,177 | SF | 6 | \$6,538 |
| | Doors - Side-lite | 24 | SF | 6 | \$401 |



Category: Classrooms

| Kindergarten (2 room | • | | | | Cost |
|----------------------|-----------------------------|--------|----|---|----------|
| | ns) | | | | |
| | Doors - Wood Doors inclu hw | 4 | EA | 6 | \$1,204 |
| | Floor - Tile | 2,189 | SF | 6 | \$4,789 |
| | Lighting - Lay-in | 21 | EA | 7 | \$0 |
| | Walls - Concrete Block | 1,418 | SF | 6 | \$4,157 |
| | Walls - Plaster/Drywall | 705 | SF | 6 | \$1,946 |
| | Work Sink | 4 | EA | 6 | \$1,516 |
| Pre School (2 rooms) |) | | | | |
| | Casework | 85 | LF | 6 | \$2,147 |
| | Ceiling - Lay-in | 40 | SF | 5 | \$319 |
| | Ceiling - Lay-in | 796 | SF | 6 | \$2,390 |
| | Ceiling - Lay-in | 970 | SF | 7 | \$0 |
| | Chalk Board | 4 | LF | 4 | \$367 |
| | Doors - Side-lite | 24 | SF | 6 | \$401 |
| | Doors - Wood Doors inclu hw | 6 | EA | 6 | \$1,806 |
| | Floor - Tile | 1,806 | SF | 6 | \$3,951 |
| | Lighting - Lay-in | 20 | EA | 7 | \$0 |
| | Storage/ Closet | 100 | SF | 6 | \$725 |
| | Walls - Concrete Block | 1,276 | SF | 6 | \$3,741 |
| | Walls - Plaster/Drywall | 721 | SF | 6 | \$1,990 |
| | Work Sink | 4 | EA | 6 | \$1,516 |
| Regular Classroom (| 17 rooms) | | | | |
| | Casework | 627 | LF | 6 | \$15,834 |
| | Ceiling - Lay-in | 36 | SF | 5 | \$287 |
| | Ceiling - Lay-in | 16,255 | SF | 6 | \$48,814 |
| | Chalk Board | 207 | LF | 4 | \$19,004 |
| | Doors - Side-lite | 216 | SF | 6 | \$3,611 |
| | Doors - Wood Doors inclu hw | 19 | EA | 6 | \$5,719 |
| | Floor - Tile | 5,694 | SF | 6 | \$12,458 |
| | Floor - Tile/Sheet | 10,597 | SF | 6 | \$10,608 |
| | Lighting - Lay-in | 164 | EA | 7 | \$0 |
| | Marker Board | 10 | LF | 5 | \$507 |
| | Marker Board | 10 | LF | 6 | \$214 |
| | Marker Board | 66 | LF | 7 | \$0 |
| | Storage/ Closet | 76 | SF | 6 | \$551 |
| | Walls - Concrete Block | 10 | SF | 5 | \$141 |
| | Walls - Concrete Block | 11,486 | SF | 6 | \$33,671 |



Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-----------------------------|----------|------|------|----------|
| Regular Classroo | om (17 rooms) | | | | |
| | Walls - Plaster/Drywall | 8,559 | SF | 6 | \$23,622 |
| | Wireless System | 1 | EA | 6 | \$372 |
| | Work Sink | 5 | EA | 6 | \$1,895 |
| Science (1 room) | | | | | |
| | Casework | 65 | LF | 6 | \$1,641 |
| | Ceiling - Lay-in | 1,132 | SF | 6 | \$3,399 |
| | Chalk Board | 8 | LF | 4 | \$734 |
| | Doors - Side-lite | 24 | SF | 6 | \$401 |
| | Doors - Wood Doors inclu hw | 3 | EA | 6 | \$903 |
| | Floor - Tile | 1,132 | SF | 6 | \$2,477 |
| | Lighting - Lay-in | 18 | EA | 7 | \$0 |
| | Walls - Concrete Block | 512 | SF | 6 | \$1,501 |
| | Walls - Plaster/Drywall | 480 | SF | 6 | \$1,325 |
| | Work Sink | 3 | EA | 6 | \$1,137 |
| Science Classroo | om (1 room) | | | | |
| | Casework | 52 | LF | 6 | \$1,313 |
| | Ceiling - Lay-in | 12 | SF | 5 | \$96 |
| | Ceiling - Lay-in | 920 | SF | 6 | \$2,763 |
| | Chalk Board | 8 | LF | 4 | \$734 |
| | Doors - Side-lite | 12 | SF | 6 | \$201 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile | 8 | SF | 5 | \$46 |
| | Floor - Tile | 927 | SF | 6 | \$2,028 |
| | Lighting - Lay-in | 10 | EA | 7 | \$0 |
| | Walls - Concrete Block | 224 | SF | 6 | \$657 |
| | Walls - Plaster/Drywall | 850 | SF | 6 | \$2,346 |
| Special Education | n (3 rooms) | | | | |
| | Casework | 99 | LF | 6 | \$2,500 |
| | Ceiling - Lay-in | 8 | SF | 5 | \$64 |
| | Ceiling - Lay-in | 1,714 | SF | 6 | \$5,147 |
| | Chalk Board | 56 | LF | 4 | \$5,141 |
| | Doors - Side-lite | 36 | SF | 6 | \$602 |
| | Doors - Wood Doors inclu hw | 3 | EA | 6 | \$903 |
| | Floor - Tile | 1,370 | SF | 6 | \$2,997 |
| | Floor - Tile/Sheet | 352 | SF | 6 | \$352 |
| | Lighting - Lay-in | 20 | EA | 7 | \$0 |



| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-------------------------|----------|------|------|---------|
| Special Education | on (3 rooms) | | | | |
| | Marker Board | 2 | LF | 7 | \$0 |
| | Walls - Concrete Block | 1,061 | SF | 6 | \$3,110 |
| | Walls - Plaster/Drywall | 1,667 | SF | 6 | \$4,601 |

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|-----------------------------|----------|------|------|----------|
| Administrative S | uites/Offices | | | | |
| | AC Unit | 1 | EA | 6 | \$496 |
| | Ceiling - Exposed | 48 | SF | 6 | \$71 |
| | Ceiling - Lay-in | 8 | SF | 5 | \$64 |
| | Ceiling - Lay-in | 2,221 | SF | 6 | \$6,670 |
| | Doors - Side-lite | 100 | SF | 6 | \$1,672 |
| | Doors - Steel Doors incl hw | 1 | EA | 5 | \$1,174 |
| | Doors - Steel Doors incl hw | 5 | EA | 6 | \$1,505 |
| | Doors - Transom Window | 69 | SF | 6 | \$1,168 |
| | Doors - Wood Doors inclu hw | 12 | EA | 6 | \$3,612 |
| | Floor - Carpet | 547 | SF | 5 | \$2,808 |
| | Floor - Carpet | 322 | SF | 6 | \$686 |
| | Floor - Epoxy/ Painted | 130 | SF | 6 | \$69 |
| | Floor - Tile | 1,054 | SF | 6 | \$2,306 |
| | Floor - Tile/Sheet | 224 | SF | 6 | \$224 |
| | Lighting - Lay-in | 30 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 1 | EA | 7 | \$0 |
| | Power Distribution | 93 | EA | 7 | \$0 |
| | Storage/ Closet | 50 | SF | 6 | \$363 |
| | Walls - Concrete Block | 3,579 | SF | 6 | \$10,492 |
| | Walls - Plaster/Drywall | 2,547 | SF | 6 | \$7,029 |
| | Work Slnk | 2 | EA | 6 | \$1,016 |
| Gymnasia | | | | | |
| | Ceiling - Exposed | 3,503 | SF | 6 | \$5,210 |
| | Doors - Steel Doors incl hw | 1 | EA | 5 | \$1,174 |
| | Doors - Steel Doors incl hw | 10 | EA | 6 | \$3,010 |
| | Floor - Tile | 3,503 | SF | 6 | \$7,664 |



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cos |
|------------------|--------------------------------------|----------|------|------|----------|
| Gymnasia | | | | | |
| | Lighting - Metal Halide/Sodium Vapor | 3 | EA | 6 | \$401 |
| | Lighting - Metal Halide/Sodium Vapor | 17 | EA | 7 | \$0 |
| | Walls - Concrete Block | 1 | SF | 5 | \$14 |
| | Walls - Concrete Block | 6,846 | SF | 6 | \$20,069 |
| Kitchen | | | | | |
| | Ceiling - Plaster/Drywall | 1,079 | SF | 6 | \$3,734 |
| | Doors - Steel Doors incl hw | 5 | EA | 6 | \$1,505 |
| | Floor - Concrete Epoxy/ Painted | 1,079 | SF | 6 | \$571 |
| | Lighting - Lay-in | 9 | EA | 7 | \$0 |
| | Storage/ Closet | 120 | SF | 6 | \$870 |
| | Walls - Concrete Block | 1,935 | SF | 6 | \$5,672 |
| Library | | | | | |
| | Ceiling - Lay-in | 4 | SF | 5 | \$32 |
| | Ceiling - Lay-in | 2,054 | SF | 6 | \$6,168 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Carpet | 2,058 | SF | 6 | \$4,385 |
| | Lighting - Lay-in | 6 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 17 | EA | 7 | \$0 |
| | Walls - Concrete Block | 1,568 | SF | 6 | \$4,597 |
| | Walls - Plaster/Drywall | 391 | SF | 6 | \$1,079 |
| Locker/Shower Ro | bom | | | | |
| | Accessories | 288 | SF | 6 | \$1,128 |
| | Ceiling - Plaster/ Drywall | 288 | SF | 6 | \$997 |
| | Doors - Steel Doors incl hw | 4 | EA | 6 | \$1,204 |
| | Floor - Concrete Epoxy/ Painted | 288 | SF | 6 | \$152 |
| | Floor Drain | 2 | EA | 6 | \$2,118 |
| | Lavatory | 2 | EA | 6 | \$639 |
| | Lighting - Lay-in | 4 | EA | 7 | \$0 |
| | Showers | 2 | EA | 6 | \$623 |
| | Student Lockers - One Tier | 10 | EA | 6 | \$928 |
| | Walls - Concrete Block | 690 | SF | 6 | \$2,023 |
| | Water Closet | 2 | EA | 6 | \$672 |
| Lunch & Multipur | pose Room | | | | |
| | Ceiling - Lay-in | 80 | SF | 5 | \$638 |
| | Ceiling - Lay-in | 5,351 | SF | 6 | \$16,069 |



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|---------------------------------|----------|------|------|----------|
| Lunch & Multipur | pose Room | | | | |
| | Doors - Side-lite | 48 | SF | 6 | \$802 |
| | Doors - Wood Doors inclu hw | 5 | EA | 6 | \$1,505 |
| | Floor - Tile | 5,431 | SF | 6 | \$11,882 |
| | Lighting - Lay-in | 66 | EA | 7 | \$0 |
| | Serving Line | 42 | LF | 7 | \$0 |
| | Walls - Concrete Block | 3,858 | SF | 6 | \$11,310 |
| | Walls - Plaster/Drywall | 2,164 | SF | 6 | \$5,972 |
| MDF_IDF | | | | | |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Finishes | 108 | SF | 6 | \$771 |
| | Ventilation and Cooling | 1 | EA | 6 | \$1,855 |
| Mechanical/ Serv | ice Rooms | | | | |
| | Boiler Room | 960 | SF | 5 | \$15,485 |
| | Janitor's Closet | 60 | SF | 6 | \$430 |
| | Loading Docks | 144 | SF | 6 | \$1,032 |
| | Mechanical/ Service Rooms | 2,400 | SF | 6 | \$17,194 |
| | Storage Room | 1,636 | SF | 6 | \$11,721 |
| Prep Room | | | | | |
| | Casework | 30 | LF | 6 | \$758 |
| | Ceiling - Lay-in | 240 | SF | 6 | \$721 |
| | Floor - Tile | 240 | SF | 6 | \$525 |
| | Lighting - Lay-in | 3 | EA | 7 | \$0 |
| | Walls - Plaster/Drywall | 640 | SF | 6 | \$1,766 |
| | Work Sink | 1 | EA | 6 | \$379 |
| Restroom | | | | | |
| | Accessories | 2,405 | SF | 6 | \$22,183 |
| | Ceiling - Plaster/Drywall | 16 | SF | 5 | \$200 |
| | Ceiling - Plaster/Drywall | 2,395 | SF | 6 | \$8,288 |
| | Doors - Wood Doors inclu hw | 12 | EA | 6 | \$3,612 |
| | Floor - Concrete Epoxy/ Painted | 2,361 | SF | 6 | \$1,249 |
| | Floor - Tile/Sheet | 46 | SF | 6 | \$46 |
| | Floor Drain | 18 | EA | 6 | \$19,065 |
| | Hand Dryer | 6 | EA | 6 | \$1,380 |
| | Lavatory | 26 | EA | 6 | \$8,310 |
| | Lighting - Lay-in | 78 | EA | 7 | \$0 |



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|--------------------------------|----------|------|------|----------|
| Restroom | | | | | |
| | Partitions | 1 | EA | 5 | \$751 |
| | Partitions | 27 | EA | 6 | \$8,017 |
| | Urinals | 16 | EA | 6 | \$5,376 |
| | Walls - Concrete Block | 6,370 | SF | 6 | \$18,674 |
| | Walls - Masonry | 279 | SF | 6 | \$878 |
| | Walls - Structural Glazed Tile | 1,221 | SF | 6 | \$3,841 |
| | Walls - Structural Glazed Tile | 80 | SF | 7 | \$0 |
| | Water Closet | 34 | EA | 6 | \$11,423 |
| | | | | | |

Rooms (Other Than Classrooms) Subtotal:

Building: Main

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost | |
|----------|--|----------|------|-------|----------|--|
| Corridor | | | | | | |
| | Ceiling - Lay-in | 104 | 5 | \$928 | | |
| | Ceiling - Lay-in | 8,082 | SF | 6 | \$24,270 | |
| | Ceiling - Plaster/Drywall | 1,389 | SF | 6 | \$8,601 | |
| | Doors - Side-lite | 30 | EA | 6 | \$502 | |
| | Doors - Steel Doors incl hw | 27 | EA | 6 | \$8,127 | |
| | Doors - Transom Window | 120 | EA | 6 | \$2,032 | |
| | Doors - Wood Doors include hw | 6 | EA | 6 | \$1,806 | |
| | Drinking Fountains - Double Water Cooler | 4 | EA | 6 | \$1,508 | |
| | Drinking Fountains - Single Fountain | 8 | EA | 6 | \$2,206 | |
| | Floor - Tile Ceramic/ Porcelain | 315 | SF | 6 | \$878 | |
| | Floor - Tile/Sheet | 10 | SF | 5 | \$58 | |
| | Floor - Tile/Sheet | 8,971 | SF | 6 | \$4,875 | |
| | Lighting - Lay-in | 95 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 6,983 | SF | 6 | \$20,471 | |
| | Walls - Structural Glazed Tile | 5,499 | SF | 6 | \$17,300 | |
| Stairs | | | | | | |
| | Ceiling - Exposed | 900 | SF | 6 | \$1,338 | |
| | Floor - Concrete | 6 | SF | 5 | \$13 | |
| | Floor - Concrete | 1,308 | SF | 6 | \$692 | |
| | Floor - Tile/Sheet | 330 | SF | 6 | \$179 | |
| | Handrails | 312 | LF | 6 | \$2,704 | |

\$333,075



Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|-------------------------------|----------|------|------|-----------|
| Stairs | | | | | |
| | Lighting - Pendent/Surface | 40 | EA | 7 | \$0 |
| | Stairs - Concrete | 156 | LF | 6 | \$1,294 |
| | Walls - Concrete Block | 4 | SF | 5 | \$56 |
| | Walls - Concrete Block | 3,788 | SF | 6 | \$11,105 |
| Vertical Conveyance | | | | | |
| | Elevator - Hydraulic Elevator | 1 | EA | 6 | \$19,238 |
| Building Interior | Subtotal: | | | | \$130,179 |
| | | | | | |

Total Building Cost

SITE

Category: Site

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------|---------------------------------------|----------|------|------|----------|
| Civil/Drainage | | | | | |
| | Civil/ Drainage - Catch Basin | 4 | EA | 6 | \$4,375 |
| | Civil/ Drainage - Site Manhole | 4 | EA | 6 | \$5,971 |
| Fencing | | | | | |
| | Fencing - Chain Link | 18 | LF | 6 | \$338 |
| | Fencing - New Standard Ornamental | 100 | LF | 4 | \$22,450 |
| | Fencing - New Standard Ornamental | 765 | LF | 6 | \$24,406 |
| Landscape | | | | | |
| | Benches | 6 | EA | 6 | \$2,580 |
| | Landscape - Grass | 15,538 | SF | 6 | \$12,887 |
| | Landscape - Hardscape- Concrete | 2,360 | SF | 6 | \$12,183 |
| | Parkway trees | 16 | EA | 6 | \$10,561 |
| | Planting Beds/ Area | 2,856 | SF | 6 | \$4,697 |
| | Play Area - Synthetic Turf Play Field | 6,280 | SF | 6 | \$27,390 |
| | Trash Receptacles | 4 | EA | 6 | \$1,249 |
| Parking Lot | | | | | |
| | Lighting - Pole Mounted | 2 | EA | 6 | \$2,905 |
| | Surface - Asphalt | 6,185 | SF | 6 | \$14,947 |
| | Vehicular Screening | 160 | LF | 6 | \$12,598 |

\$2,551,104



SITE

Category: Site

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|--|----------|------|------|-----------|
| Playground | | | | | |
| | Equipment - Pre K 3-5 | 1 | EA | 6 | \$3,546 |
| | Equipment - School Age 5-12 | 1 | EA | 6 | \$3,546 |
| | Surface - Poured Surface | 4,656 | SF | 6 | \$34,089 |
| Sidewalks | | | | | |
| | Sidewalks - Internal Walks | 313 | LF | 6 | \$3,760 |
| | Sidewalks - Perimeter Sidewalks | 5,008 | SF | 6 | \$9,954 |
| Signage | | | | | |
| | Flag Pole - Building Mounted Flag Pole | 2 | EA | 6 | \$1,657 |
| | Marquee - Building Mounted Back Lighted w/ LED | 1 | EA | 6 | \$0 |
| Site Subtotal: | | | | | \$216,089 |
| Total Site Cost | | | | | \$216,089 |

| Cam | ous Total ^{2 3} | \$2,767,193 |
|-----|--------------------------|-------------|

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------|-------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | | ł | | | | ł | | | | - | 1 | | + |
| Art Room | Art Room | 2nd Floor | 220 | 222 | 932 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Y |
| Computer Lab | Computer Lab | 3rd Floor | 302 | 302 | 882 | 2 | 50 | 96 | 108 | 12 | 40 | Y | Ν | Ν |
| Faculty Lounge | Regular Classroom | 3rd Floor | 303 | 303 | 882 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Ν |
| Kindergarten | Regular Classroom | 1st Floor | 106 | 119 | 1,147 | 1 | 5 | 20 | 144 | 48 | 40 | Ν | Ν | Ν |
| Kindergarten | Regular Classroom | 1st Floor | 108 | 123 | 1,042 | 1 | 4 | 22 | 144 | 48 | 40 | Ν | Ν | Ν |
| Pre School | Regular Classroom | 1st Floor | 102 | 113 | 1,010 | 1 | 4 | 20 | 108 | 36 | 40 | N | Ν | Ν |
| Pre School | Regular Classroom | 1st Floor | 103 | 118 | 796 | 1 | 3 | 20 | 108 | 36 | 40 | Ν | Ν | Ν |
| Regular Classroom | Computer Lab | 2nd Floor | 202 | 202 | 1,305 | 1 | 10 | 32 | 108 | 36 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 882 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 206 | 900 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 1,018 | 1 | 8 | 24 | 108 | 12 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 209 | 932 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 211 | 211 | 932 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 215 | 215 | 932 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Y |
| Regular Classroom | Regular Classroom | | 217 | 217 | 932 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 218 | 216 | 932 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 219 | 220 | 932 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 222 | 229 | 900 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 306 | 306 | 882 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 311 | 311 | 932 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 315 | 315 | 932 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 319 | 319 | 932 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 321 | 321 | 1,134 | 1 | 8 | 24 | 108 | 12 | 40 | Y | Ν | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 322 | 324 | 882 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Ν |
| Science | Science | 3rd Floor | 300 | 300 | 1,132 | 1 | 8 | 24 | 144 | 16 | 40 | Y | Ν | Y |
| Science Classroom | Regular Classroom | 3rd Floor | 309 | 309 | 932 | 1 | 7 | 18 | 108 | 12 | 40 | Y | Ν | Y |
| Special Education | Special Education | 2nd Floor | 207 | 207 | 352 | 5 | 11 | 18 | 36 | 4 | 40 | Ν | Ν | Ν |
| Special Education | Special Education | 3rd Floor | 307 | 307 | 352 | 5 | 11 | 18 | 36 | 4 | 40 | Y | Ν | Y |
| Special Education | Regular Classroom | 3rd Floor | 308 | 308 | 1,018 | 1 | 8 | 24 | 108 | 12 | 40 | Y | Ν | Y |