

Facility Assessment Report

This report contains a summary of the results from the facility assessment completed on the date noted in the document footer below. This report will roll-up each assessed item with identical rank and total the quantity into a single line, regardless of item location (for location data, see the detailed report). Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|----------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1943 | 2 | 38,534 | \$2,153,073 |
| Addition | 2015 | 1 | 37,942 | \$36,963 |
| SITE | | | | \$260,833 |
| Campus Total | | | 76,476 | \$2,450,869 |

Building: Main

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------|---|----------|------|------|----------|
| Entrance | | | | | |
| | Entrance Control - Audio and Video | 2 | EA | 6 | \$1,403 |
| | Exterior Doors - Exterior FRP Door | 1 | EA | 6 | \$631 |
| | Exterior Doors - Exterior Steel Door | 10 | EA | 6 | \$4,806 |
| | Exterior Doors - Exterior Wood Door | 2 | EA | 4 | \$7,645 |
| | Exterior Doors - Transom Lite | 7 | EA | 6 | \$2,193 |
| | Exterior Stairs - Concrete | 344 | LF | 6 | \$28,128 |
| | Exterior Stairs - Stone | 24 | LF | 6 | \$2,712 |
| | Ramp Handrail - Steel_Ramp Handrail | 17 | LF | 6 | \$147 |
| | Ramps - Concrete | 45 | LF | 5 | \$23,923 |
| | Stair Handrail - Steel_Stair Handrail | 152 | LF | 6 | \$1,317 |
| Foundation | | | | | |
| | Foundation - Concrete | 785 | LF | 7 | \$0 |
| | Superstructure - Steel with Clay Tile Arch | 38,534 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | 8 | EA | 6 | \$4,292 |
| | Exterior Lighting - Wall Mounted | 8 | EA | 6 | \$2,310 |



Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|---|----------|------|------|-----------|
| Roof System | | | | | |
| | Cell Tower | 1 | EA | 6 | \$736 |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | 15 | LF | 6 | \$14,320 |
| | Coping - Stone | 884 | LF | 6 | \$28,392 |
| | Downspouts - Interior Downspouts | 250 | LF | 6 | \$8,308 |
| | Parapet - 16" - 30" Height | 253 | LF | 6 | \$10,108 |
| | Parapet - Parapet < 16" Height | 631 | LF | 6 | \$13,445 |
| | Roof - Modified Bitumen | 18,592 | SF | 6 | \$174,940 |
| | Roof Structure - Steel with Clay Tile Arch | 18,592 | SF | 7 | \$0 |
| Walls | | | | | |
| | Cheek-Wall - Concrete | 216 | SF | 6 | \$2,215 |
| | Exterior Walls - Brick | 22,475 | SF | 6 | \$151,054 |
| | Exterior Walls - Stone-Cast | 3,140 | SF | 6 | \$21,104 |
| Windows | | | | | |
| | Curtain wall - Insulated Panel | 1,776 | SF | 6 | \$19,911 |
| | Curtain wall - Louver | 60 | SF | 6 | \$673 |
| | Guard - Guards wire guard | 200 | SF | 6 | \$2,554 |
| | Lintels - Steel | 350 | LF | 6 | \$10,160 |
| | Lintels - Stone | 285 | LF | 6 | \$0 |
| | Windows - Decorative | 252 | SF | 6 | \$1,881 |
| | Windows - Sash Aluminum Double-pane | 1,200 | SF | 5 | \$64,642 |
| | Windows - Sash Aluminum Double-pane | 720 | SF | 6 | \$5,375 |
| | Windows - Sash Lexan | 1,077 | SF | 5 | \$31,618 |
| Building Exterio | or Subtotal: | | | | \$640,944 |

Building Exterior Subtotal:

Building: Main

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|--|----------|------|------|---------|
| Emergency System | | | | | |
| | Automatic Transfer Switch | 1 | EA | 4 | \$8,200 |
| | Emergency A/C Power - Corridors and Stairs | 7,484 | SF | 6 | \$2,247 |
| | Emergency A/C Power - Gym | 3,787 | SF | 6 | \$1,408 |
| | Emergency Battery Packs - Corridors and Stairs | 11 | EA | 6 | \$2,228 |
| | Emergency Battery Packs - Gym | 2 | EA | 6 | \$405 |
| | Emergency Battery Packs - Students Toilets | 4 | EA | 6 | \$810 |
| | Exit Signs - Corridors and Stairs | 16 | EA | 2 | \$8,728 |



Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|--|----------|------|------|----------|
| Emergency System | | | | | |
| | Exit Signs - Gym | 3 | EA | 2 | \$1,735 |
| | Security System - CCTV | 38,534 | SF | 6 | \$11,572 |
| | Security System - Intrusion Detection | 38,534 | SF | 6 | \$9,919 |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 7 | \$0 |
| | Main Electrical Service - 800 A and 120/208/3PH | 1 | EA | 6 | \$3,570 |
| | PA System | 38,534 | SF | 6 | \$12,674 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 3 | EA | 7 | \$0 |
| | Lighting and Power Panels - Above 100 A | 4 | EA | 7 | \$0 |
| | Main Distribution Panels - 400 - 600 amp | 1 | EA | 7 | \$0 |
| Electrical Syste | m Subtotal: | | | | \$63,495 |

Building: Main

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------|--------------------------|----------|------|------|----------|
| Fire Alarm | | | | | |
| | Fire Alarm Panel | 1 | EA | 7 | \$0 |
| | Fire Alarm Strobe Lights | 38,534 | SF | 6 | \$13,776 |
| | Fire Alarm_System | 38,534 | SF | 6 | \$18,735 |
| Safty System Subtotal: | | | | | \$32,511 |

Building: Main

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|---|----------|------|------|---------|
| Air Conditioning | | | | | |
| | Chemical Pot Feeder | 1 | EA | 6 | \$725 |
| | Chiller-Air Cooled-Scroll Type-Roof Mounted - 50 - 100 tons | 1 | EA | 6 | \$3,659 |
| | Condensing Unit- Ground Mounted - Less than 5 tons | 2 | EA | 6 | \$6,667 |
| | Condensing Unit- Roof Mounted - Less than 5 tons | 1 | EA | 6 | \$3,334 |
| | Glycol Feed | 1 | EA | 6 | \$490 |
| | Pipes - Chilled Water Pipe- Steel | 300 | LF | 6 | \$566 |
| | Pressure Fill System | 1 | EA | 6 | \$1,405 |



Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------|---|----------|------|------|-----------|
| Air Handling Systems | | | | | |
| | Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm | 1 | EA | 5 | \$66,438 |
| | Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm | 1 | EA | 5 | \$50,003 |
| | Air Intake | 2 | EA | 7 | \$0 |
| | Auxiliaries - 15001 - 25000 cfm | 1 | EA | 5 | \$14,899 |
| | Auxiliaries - 8001 - 15000 cfm | 1 | EA | 5 | \$12,908 |
| | Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM | 1 | EA | 6 | \$1,857 |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | 350 | LF | 7 | \$0 |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating Coil - 11 - 20 tons | 1 | EA | 5 | \$14,565 |
| | Zone Dampers | 27 | EA | 6 | \$22,492 |
| Boiler Systems | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 50 - 75 HP | 2 | EA | 4 | \$23,013 |
| | Chemical Feeder | 1 | EA | 5 | \$3,075 |
| | Combustion Dampers | 2 | EA | 6 | \$818 |
| | Condensate Pump | 1 | EA | 5 | \$18,196 |
| | Feed Water Pumps and Tank | 1 | EA | 5 | \$36,450 |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP | 2 | EA | 4 | \$75,476 |
| | Piping - Condensate Pipe- Steel | 300 | LF | 6 | \$566 |
| | Piping - Steam Pipe- Steel | 300 | LF | 6 | \$566 |
| | Steam Traps | 30 | EA | 5 | \$39,447 |
| Heating Devices | | | | | |
| | Unit Heater - Electric | 3 | EA | 5 | \$3,023 |
| Mechanical Plumbing | | | | | |
| | Chilled Water Pump - Less than 10 | 2 | EA | 6 | \$2,222 |
| Temperature Control | | | | | |
| | Electric Thermostat | 3 | EA | 6 | \$0 |
| | Pneumatic System | 38,534 | SF | 5 | \$132,800 |
| | Thermostats - Pneumatic | 7 | EA | 4 | \$5,161 |
| | Thermostats - Pneumatic | 20 | EA | 6 | \$0 |
| Unit Ventilation | | | | | |
| | Unit Ventilators- Floor Mounted- Steam Heating & Chilled Water Coils | 21 | EA | 5 | \$227,681 |
| Ventilation | | | | | . |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 1 | EA | 4 | \$1,942 |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 2 | EA | 6 | \$592 |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 2 | EA | 6 | |



| Category: Mechanica | I System |
|---------------------|-----------|
| Group | Itom Type |

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-------------|----------|------|------|-----------|
| Mechanical System | Subtotal: | | | | \$771,036 |

Building: Main

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------|--|----------|------|------|-----------|
| Hot Water | | | | | |
| | Gas Heater - Less than 150000 BTU/HR | 1 | EA | 6 | \$310 |
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 38,534 | SF | 6 | \$7,715 |
| | Domestic Piping-Cold Water Horizontal Lines | 38,534 | SF | 6 | \$9,368 |
| | Domestic Piping-Cold Water Risers | 38,534 | SF | 6 | \$7,163 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 38,534 | SF | 6 | \$6,061 |
| | Domestic Piping-Hot Water Horizontal Lines | 38,534 | SF | 6 | \$7,163 |
| | Domestic Piping-Hot Water Return Lines | 38,534 | SF | 6 | \$5,510 |
| | Domestic Piping-Hot Water Return Risers | 38,534 | SF | 6 | \$5,510 |
| | Sanitary Piping | 38,534 | SF | 6 | \$35,266 |
| | Storm Piping | 38,534 | SF | 6 | \$33,613 |
| | Vent Piping | 38,534 | SF | 6 | \$25,899 |
| Pumps | | | | | |
| | Pumps - Sump-Duplex | 1 | EA | 6 | \$1,387 |
| | Pumps - Sump-Simplex | 1 | EA | 6 | \$745 |
| <u></u> | tom Outstatel | | | | ¢4.45.744 |

Plumbing System Subtotal:

\$145,711

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|---------------------------------|----------|------|-------|---------|
| | | Quality | Onit | Nalik | 6031 |
| Art Room (1 roon | n) | | | | |
| | Casework | 12 | LF | 6 | \$303 |
| | Doors - Transom Window | 18 | SF | 6 | \$305 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Tile Ceramic/ Porcelain | 1,227 | SF | 6 | \$2,597 |
| | Lighting - Pendent/Surface | 16 | EA | 7 | \$0 |
| | Marker Board | 12 | LF | 7 | \$0 |
| | Storage/ Closet | 104 | SF | 6 | \$754 |
| | Walls - Plaster/Drywall | 1,513 | SF | 6 | \$4,176 |
| | | | | | |



Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|-----------------------------|----------|------|------|----------|
| Art Room (1 room | n) | | | | |
| | Work Sink | 2 | EA | 6 | \$758 |
| Kindergarten (2 ro | poms) | | | | |
| | Casework | 20 | LF | 6 | \$505 |
| | Ceiling - Plaster/Drywall | 1,525 | SF | 6 | \$5,277 |
| | Doors - Transom Window | 27 | SF | 6 | \$457 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Tile/Sheet | 700 | SF | 6 | \$701 |
| | Floor - Wood | 825 | SF | 6 | \$5,816 |
| | Lighting - Pendent/Surface | 30 | EA | 7 | \$0 |
| | Marker Board | 29 | LF | 7 | \$0 |
| | Storage/ Closet | 54 | SF | 6 | \$392 |
| | Walls - Plaster/Drywall | 2,443 | SF | 6 | \$6,742 |
| Music Room (1 ro | pom) | | | | |
| | Casework | 8 | LF | 6 | \$202 |
| | Ceiling - Plaster/Drywall | 700 | SF | 6 | \$2,422 |
| | Doors - Transom Window | 9 | SF | 6 | \$152 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Wood | 700 | SF | 6 | \$4,935 |
| | Lighting - Pendent/Surface | 12 | EA | 7 | \$0 |
| | Walls - Plaster/Drywall | 1,166 | SF | 6 | \$3,218 |
| Regular Classroo | m (14 rooms) | | | | |
| | Casework | 159 | LF | 6 | \$4,015 |
| | Ceiling - Plaster/Drywall | 9,675 | SF | 6 | \$33,481 |
| | Chalk Board | 58 | LF | 4 | \$5,325 |
| | Doors - Transom Window | 9 | SF | 5 | \$381 |
| | Doors - Transom Window | 126 | SF | 6 | \$2,133 |
| | Doors - Wood Doors inclu hw | 15 | EA | 6 | \$4,515 |
| | Floor - Tile/Sheet | 8,275 | SF | 6 | \$8,283 |
| | Floor - Tile/Sheet | 700 | SF | 7 | \$0 |
| | Floor - Wood | 700 | SF | 6 | \$4,935 |
| | Lighting - Pendent/Surface | 14 | EA | 6 | \$1,735 |
| | Lighting - Pendent/Surface | 172 | EA | 7 | \$0 |
| | Marker Board | 263 | LF | 7 | \$0 |
| | Storage/ Closet | 60 | SF | 6 | \$435 |
| | Walls - Plaster/Drywall | 15 | SF | 5 | \$77 |
| | Walls - Plaster/Drywall | 15,938 | SF | 6 | \$43,987 |



| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-----------------------------|----------|------|------|-----------|
| Regular Classro | om (14 rooms) | | | | |
| Science Classro | om (1 room) | | | | |
| | Casework | 48 | LF | 6 | \$1,212 |
| | Ceiling - Plaster/Drywall | 700 | SF | 6 | \$2,422 |
| | Doors - Transom Window | 9 | SF | 6 | \$152 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile/Sheet | 700 | SF | 6 | \$701 |
| | Lighting - Pendent/Surface | 12 | EA | 7 | \$0 |
| | Marker Board | 14 | LF | 7 | \$0 |
| | Storage/ Closet | 10 | SF | 6 | \$73 |
| | Walls - Plaster/Drywall | 1,166 | SF | 6 | \$3,218 |
| | Work Sink | 2 | EA | 6 | \$758 |
| Special Education | on (1 room) | | | | |
| | Casework | 5 | LF | 6 | \$126 |
| | Ceiling - Plaster/Drywall | 340 | SF | 6 | \$1,177 |
| | Chalk Board | 20 | LF | 4 | \$1,836 |
| | Doors - Transom Window | 9 | SF | 6 | \$152 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile/Sheet | 340 | SF | 6 | \$340 |
| | Lighting - Pendent/Surface | 6 | EA | 7 | \$0 |
| | Marker Board | 6 | LF | 7 | \$0 |
| | Walls - Plaster/Drywall | 860 | SF | 6 | \$2,374 |
| Classrooms | Cubicital. | | | | \$165 663 |

Classrooms Subtotal:

\$165,663

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------------|-----------------------------|----------|------|------|---------|
| Administrative Suites/Offi | ces | | | | |
| | Ceiling - Exposed | 135 | SF | 6 | \$201 |
| | Ceiling - Plaster/Drywall | 758 | SF | 6 | \$2,623 |
| | Doors - Side-lite | 6 | SF | 5 | \$420 |
| | Doors - Wood Doors inclu hw | 5 | EA | 6 | \$1,505 |
| | Floor - Concrete | 226 | SF | 6 | \$120 |
| | Floor - Tile/Sheet | 527 | SF | 6 | \$528 |
| | Floor - Wood | 140 | SF | 6 | \$987 |
| | Lighting - Pendent/Surface | 3 | EA | 6 | \$372 |



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|--------------------------------------|----------|------|------|----------|
| Administrative Su | uites/Offices | | | | |
| | Lighting - Pendent/Surface | 9 | EA | 7 | \$0 |
| | Power Distribution | 28 | EA | 7 | \$0 |
| | Storage/ Closet | 52 | SF | 6 | \$377 |
| | Walls - Plaster/Drywall | 2,558 | SF | 6 | \$7,060 |
| | Walls - Structural Glazed Tile | 418 | SF | 6 | \$1,315 |
| Gymnasia | | | | | |
| | Bleacher Seating | 64 | EA | 6 | \$1,852 |
| | Ceiling - Lay-in | 2,400 | SF | 6 | \$7,207 |
| | Doors - Wood Doors inclu hw | 6 | EA | 6 | \$1,806 |
| | Floor - Sport Flooring | 2,400 | SF | 6 | \$5,182 |
| | Lighting - Metal Halide/Sodium Vapor | 20 | EA | 7 | \$0 |
| | Scoreboards | 1 | EA | 6 | \$2,244 |
| | Sound System | 1 | EA | 6 | \$41,654 |
| | Stage | 260 | SF | 6 | \$1,502 |
| | Stage Curtain | 8 | EA | 7 | \$0 |
| | Stage Lighting System | 1 | EA | 6 | \$12,369 |
| | Stage-Stairs - Tile | 6 | LF | 6 | \$56 |
| | Storage/ Closet | 20 | SF | 6 | \$145 |
| | Walls - Structural Glazed Tile | 4,000 | SF | 6 | \$12,584 |
| Mechanical/ Serv | ice Rooms | | | | |
| | Boiler Room | 1,368 | SF | 6 | \$9,801 |
| | Coal Room | 360 | SF | 6 | \$2,579 |
| | Janitor's Closet | 174 | SF | 6 | \$1,247 |
| | Storage Room | 32 | SF | 6 | \$229 |
| Restroom | | | | | |
| | Accessories | 1,243 | SF | 6 | \$11,465 |
| | Ceiling - Exposed | 61 | SF | 6 | \$91 |
| | Ceiling - Plaster/Drywall | 1,182 | SF | 6 | \$4,090 |
| | Doors - Transom Window | 144 | SF | 6 | \$2,438 |
| | Doors - Wood Doors inclu hw | 12 | EA | 6 | \$3,612 |
| | Floor - Concrete | 61 | SF | 6 | \$32 |
| | Floor - Tile Ceramic/ Porcelain | 10 | SF | 5 | \$209 |
| | Floor - Tile Ceramic/ Porcelain | 1,182 | SF | 6 | \$2,502 |
| | Floor Drain | 4 | EA | 6 | \$4,237 |
| | Hand Dryer | 9 | EA | 6 | \$2,070 |
| | Lavatory | 12 | EA | 6 | \$3,835 |



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|--------------------------------|----------|------|------|-----------|
| Restroom | | | | | |
| | Lighting - Pendent/Surface | 21 | EA | 7 | \$0 |
| | Partitions | 20 | EA | 6 | \$5,939 |
| | Urinals | 12 | EA | 6 | \$4,032 |
| | Walls - Concrete Block | 259 | SF | 6 | \$759 |
| | Walls - Plaster/Drywall | 1,148 | SF | 6 | \$3,168 |
| | Walls - Structural Glazed Tile | 6 | SF | 5 | \$383 |
| | Walls - Structural Glazed Tile | 2,849 | SF | 6 | \$8,963 |
| | Water Closet | 24 | EA | 6 | \$8,063 |
| Rooms (Othe | r Than Classrooms) Subtotal: | | | | \$181,852 |

Building: Main

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|--------------------------------------|----------|------|------|----------|
| Corridor | | | | | |
| | Ceiling - Plaster/Drywall | 5,650 | SF | 6 | \$34,984 |
| | Doors - Steel Doors incl hw | 6 | EA | 6 | \$1,806 |
| | Doors - Transom Window | 21 | EA | 6 | \$356 |
| | Doors - Wood Doors include hw | 9 | EA | 6 | \$2,709 |
| | Drinking Fountains - Double Fountain | 4 | EA | 6 | \$1,344 |
| | Floor - Tile/Sheet | 6,069 | SF | 6 | \$3,298 |
| | Lighting - Pendent/Surface | 68 | EA | 7 | \$0 |
| | Student Lockers - One Tier | 314 | EA | 6 | \$29,150 |
| | Walls - Plaster/Drywall | 3,160 | SF | 6 | \$14,008 |
| | Walls - Structural Glazed Tile | 3,160 | SF | 6 | \$9,941 |
| Stairs | | | | | |
| | Ceiling - Plaster/Drywall | 2,415 | SF | 6 | \$17,682 |
| | Floor - Terrazzo | 2,415 | SF | 6 | \$20,272 |
| | Handrails | 414 | LF | 6 | \$3,588 |
| | Lighting - Pendent/Surface | 24 | EA | 7 | \$0 |
| | Stairs - Terrazzo | 180 | LF | 6 | \$1,671 |
| | Walls - Plaster/Drywall | 1,871 | SF | 6 | \$5,164 |
| | Walls - Structural Glazed Tile | 1,872 | SF | 6 | \$5,889 |

Building Interior Subtotal:

\$151,861



\$2,153,073

| Building: Addit | tion | | | | |
|-----------------|---|----------|------|------|------|
| Category: Build | ding Exterior | | | | |
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Entrance | | | | | |
| | Entrance Control - Audio and Video | 3 | EA | 7 | \$0 |
| | Exterior Doors - Exterior FRP Door | 3 | EA | 7 | \$0 |
| | Exterior Doors - Store Front | 8 | EA | 7 | \$0 |
| | Exterior Doors - Transom Lite | 8 | EA | 7 | \$0 |
| | Power Door Operator and Controls | 2 | EA | 7 | \$0 |
| Foundation | | | | | |
| | Foundation - Concrete | 663 | LF | 7 | \$0 |
| | Superstructure - Metal Deck/ Concrete Topping | 37,942 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 18 | EA | 7 | \$0 |
| Roof System | | | | | |
| | Coping - Metal | 829 | LF | 7 | \$0 |
| | Coping - Stone | 75 | LF | 7 | \$0 |
| | Downspouts - Exterior Downspouts | 299 | LF | 7 | \$0 |
| | Downspouts - Interior Downspouts | 58 | LF | 7 | \$0 |
| | Parapet - 16" - 30" Height | 663 | LF | 7 | \$0 |
| | Parapet - Parapet < 16" Height | 166 | LF | 7 | \$0 |
| | Roof - Modified Bitumen | 21,705 | SF | 7 | \$0 |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 21,705 | SF | 7 | \$0 |
| Walls | | | | | |
| | Canopy - Concrete/ Stucco | 447 | SF | 7 | \$0 |
| | Canopy - Metal | 32 | SF | 7 | \$0 |
| | Exterior Walls - Brick | 18,092 | SF | 7 | \$0 |
| | Exterior Walls - Stone-Cast | 860 | SF | 7 | \$0 |
| Windows | | | | | |
| | Guard - Guards perforated | 2,379 | SF | 7 | \$0 |
| | Lintels - Steel | 580 | LF | 7 | \$0 |
| | Windows - Decorative | 906 | SF | 7 | \$0 |
| | Windows - Sash Aluminum Double-pane | 3,263 | SF | 7 | \$0 |

Building Exterior Subtotal:

\$0



Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|--|----------|------|------|------|
| Emergency System | | | | | |
| | Automatic Transfer Switch | 2 | EA | 7 | \$0 |
| | Emergency A/C Power - Corridors and Stairs | 4,350 | SF | 7 | \$0 |
| | Emergency A/C Power - Students Toilets | 1,150 | SF | 7 | \$0 |
| | Emergency Battery Packs - Corridors and Stairs | 22 | EA | 7 | \$0 |
| | Emergency Battery Packs - Lunchrooms | 7 | EA | 7 | \$0 |
| | Emergency Battery Packs - Multipurpose Room | 5 | EA | 7 | \$0 |
| | Exit Signs - Corridors and Stairs | 18 | EA | 7 | \$0 |
| | Exit Signs - Lunchroom | 6 | EA | 7 | \$0 |
| | Exit Signs - Multipurpose Room | 3 | EA | 7 | \$0 |
| | Security System - CCTV | 37,942 | SF | 7 | \$0 |
| | Security System - Intrusion Detection | 37,942 | SF | 7 | \$0 |
| | UPS - Less than 30 KW | 1 | EA | 7 | \$0 |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 7 | \$0 |
| | Main Electrical Service - 1200 A 277/480/3PH | 1 | EA | 7 | \$0 |
| | PA System | 37,942 | SF | 7 | \$0 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 1 | EA | 7 | \$0 |
| | Lighting and Power Panels - Above 100 A | 9 | EA | 7 | \$0 |
| | Main Distribution Panels - 400 - 600 amp | 2 | EA | 7 | \$0 |
| | Main Distribution Panels - Greater than 600 amp | 2 | EA | 7 | \$0 |
| | Transformers - 277/480 - 120/208 | 2 | EA | 7 | \$0 |
| Electrical System | n Subtotal: | | | | \$0 |

Building: Addition

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------|--------------------------|----------|------|------|------|
| Fire Alarm | | | | | |
| | Fire Alarm Panel | 1 | EA | 7 | \$0 |
| | Fire Alarm Strobe Lights | 37,942 | SF | 7 | \$0 |
| | Fire Alarm_System | 37,942 | SF | 7 | \$0 |
| | Fire Pump Controller | 1 | EA | 7 | \$0 |
| Pump Room Ass | embly | | | | |
| | Fire Pump - 25-50 hp | 1 | EA | 7 | \$0 |
| | | | | | |



\$0

Building: Addition

| Category: Safty Sys | stem | | | | |
|---------------------|-------------|----------|------|------|------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Pump Room Assembly | | | | | |
| | Jockey Pump | 1 | EA | 7 | \$0 |

Safty System Subtotal:

Building: Addition

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------|--|----------|------|------|------|
| Air Conditioning | | | | | |
| | Chemical Pot Feeder | 1 | EA | 7 | \$0 |
| | Chiller-Air Cooled-Scroll Type-Ground Mounted - 101 - 150 tons | 1 | EA | 7 | \$0 |
| | Condensing Unit- Roof Mounted - Less than 5 tons | 1 | EA | 7 | \$0 |
| | Glycol Feed | 1 | EA | 7 | \$0 |
| | Pipes - Chilled Water Pipe- Copper | 300 | LF | 7 | \$0 |
| | Pressure Fill System | 1 | EA | 7 | \$0 |
| Air Handling Systems | | | | | |
| | Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM | 1 | EA | 7 | \$0 |
| | Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM | 1 | EA | 7 | \$0 |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 10 - 20 tons | 2 | EA | 7 | \$0 |
| Boiler Systems | | | | | |
| | Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP | 2 | EA | 7 | \$0 |
| | Chemical Pot Feeder | 1 | EA | 7 | \$0 |
| | Condensing- Hot Water Boiler - 1001 - 2000 MBH | 2 | EA | 7 | \$0 |
| | Glycol Feed System | 1 | EA | 7 | \$0 |
| | Water Fill System | 1 | EA | 7 | \$0 |
| Gas Booster | | | | | |
| | Gas Booster | 2 | EA | 7 | \$0 |
| Heating Devices | | | | | |
| | Cabinet Heaters - With Hot Water Coil | 4 | EA | 7 | \$0 |
| | Unit Heater - Electric | 1 | EA | 7 | \$0 |
| | Unit Heater - Hot Water | 2 | EA | 7 | \$0 |
| | Wall Heater - Electric | 4 | EA | 7 | \$0 |
| Mechanical Plumbing | | | | | |
| | Chilled Water Pump - 10 - 20 HP | 2 | EA | 7 | \$0 |



Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|--|----------|------|------|------|
| Mechanical Plumb | bing | | | | |
| | Daul Temperature Pump - 10 - 20 HP | 2 | EA | 7 | \$0 |
| | Hot Water Pump - Less than 10 | 2 | EA | 7 | \$0 |
| | Hydronic Supply and Return - Copper | 600 | LF | 7 | \$0 |
| Temperature Cont | trol | | | | |
| | DDC System | 37,942 | SF | 7 | \$0 |
| | Electric Thermostat | 3 | EA | 7 | \$0 |
| | Thermostats - DDC | 28 | EA | 7 | \$0 |
| Ventilation | | | | | |
| | Exhaust Fans- Indoor - Less than 500 CFM | 2 | EA | 7 | \$0 |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 4 | EA | 7 | \$0 |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 2 | EA | 7 | \$0 |
| | Type II Exhaust Hood- Warming Kitchen | 1 | EA | 7 | \$0 |
| Mechanical Sv | ystem Subtotal: | | | | \$0 |

Mechanical System Subtotal:

Building: Addition

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------|--|----------|------|------|------|
| Hot Water | | | | | |
| | Gas Heater - Less than 150000 BTU/HR | 2 | EA | 7 | \$0 |
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 37,942 | SF | 7 | \$0 |
| | Domestic Piping-Cold Water Horizontal Lines | 37,942 | SF | 7 | \$0 |
| | Domestic Piping-Cold Water Risers | 37,942 | SF | 7 | \$0 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 37,942 | SF | 7 | \$0 |
| | Domestic Piping-Hot Water Horizontal Lines | 37,942 | SF | 7 | \$0 |
| | Domestic Piping-Hot Water Return Lines | 37,942 | SF | 7 | \$0 |
| | Domestic Piping-Hot Water Return Risers | 37,942 | SF | 7 | \$0 |
| | Sanitary Piping | 37,942 | SF | 7 | \$0 |
| | Storm Piping | 37,942 | SF | 7 | \$0 |
| | Vent Piping | 37,942 | SF | 7 | \$0 |
| Pumps | | | | | |
| | Pumps - Domestic Booster Pump-Duplex | 1 | EA | 7 | \$0 |
| | Pumps - Sump-Simplex | 1 | EA | 7 | \$0 |
| | | | | | |



| Category: P | lumbing System | | | | |
|-------------|-----------------|----------|------|------|------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Plumbing S | ystem Subtotal: | | | | \$0 |

Plumbing System Subtotal:

Building: Addition

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-----------------------------|----------|------|------|------|
| Computer Lab (1 | room) | | | | |
| | Ceiling - Lay-in | 900 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 1 | EA | 7 | \$0 |
| | Floor - Tile | 900 | SF | 7 | \$0 |
| | Lighting - Lay-in | 13 | EA | 7 | \$0 |
| | Marker Board | 10 | LF | 7 | \$0 |
| | Walls - Plaster/Drywall | 2,020 | SF | 7 | \$0 |
| | Wireless System | 1 | EA | 7 | \$0 |
| Faculty Lounge (| 1 room) | | | | |
| | Ceiling - Lay-in | 750 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 1 | EA | 7 | \$0 |
| | Floor - Tile | 750 | SF | 7 | \$0 |
| | Lighting - Lay-in | 8 | EA | 7 | \$0 |
| | Marker Board | 10 | LF | 7 | \$0 |
| | Walls - Plaster/Drywall | 1,050 | SF | 7 | \$0 |
| Kindergarten (3 r | ooms) | | | | |
| | Casework | 24 | LF | 7 | \$0 |
| | Ceiling - Lay-in | 3,030 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 6 | EA | 7 | \$0 |
| | Floor - Tile | 3,030 | SF | 7 | \$0 |
| | Lighting - Lay-in | 42 | EA | 7 | \$0 |
| | Marker Board | 30 | LF | 7 | \$0 |
| | Storage/ Closet | 210 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 3,552 | SF | 7 | \$0 |
| | Work Sink | 3 | EA | 7 | \$0 |
| Pre School (2 roo | ms) | | | | |
| | Casework | 16 | LF | 7 | \$0 |
| | Ceiling - Lay-in | 2,020 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 4 | EA | 7 | \$0 |
| | Floor - Tile | 2,020 | SF | 7 | \$0 |
| | Lighting - Lay-in | 28 | EA | 7 | \$0 |
| | | | | | |



Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|-----------------------------|----------|------|------|---------|
| Pre School (2 room | is) | | | | |
| | Marker Board | 20 | LF | 7 | \$0 |
| | Storage/ Closet | 140 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 2,368 | SF | 7 | \$0 |
| | Work Sink | 2 | EA | 7 | \$0 |
| Regular Classroom | n (9 rooms) | | | | |
| | Ceiling - Lay-in | 828 | SF | 6 | \$2,486 |
| | Ceiling - Lay-in | 6,169 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 9 | EA | 7 | \$0 |
| | Floor - Tile | 6,997 | SF | 7 | \$0 |
| | Lighting - Lay-in | 76 | EA | 7 | \$0 |
| | Marker Board | 90 | LF | 7 | \$0 |
| | Walls - Plaster/Drywall | 9,459 | SF | 7 | \$0 |
| Science (1 room) | | | | | |
| | Ceiling - Lay-in | 1,066 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 2 | EA | 7 | \$0 |
| | Eye Wash Station | 1 | EA | 7 | \$0 |
| | Floor - Tile | 1,066 | SF | 7 | \$0 |
| | Lighting - Lay-in | 14 | EA | 7 | \$0 |
| | Marker Board | 10 | LF | 7 | \$0 |
| | Storage/ Closet | 100 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 1,444 | SF | 7 | \$0 |
| | Work Sink | 2 | EA | 7 | \$0 |
| Classrooms Su | ubtotal: | | | | \$2,486 |

Classrooms Subtotal:

Building: Addition

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|-----------------------------|----------|------|------|------|
| Administrative S | uites/Offices | | | | |
| | Ceiling - Lay-in | 1,895 | SF | 7 | \$0 |
| | Doors - Side-lite | 164 | SF | 7 | \$O |
| | Doors - Steel Doors incl hw | 7 | EA | 7 | \$O |
| | Floor - Carpet | 169 | SF | 7 | \$O |
| | Floor - Tile | 1,504 | SF | 7 | \$O |
| | Lighting - Lay-in | 31 | EA | 7 | \$O |
| | Power Distribution | 22 | EA | 7 | \$0 |



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|-----------------------------------|----------|------|------|---------|
| Administrative S | uites/Offices | | | | |
| | Storage/ Closet | 44 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 3,960 | SF | 7 | \$0 |
| Kitchen | | | | | |
| | Ceiling - Lay-in | 2,231 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 8 | EA | 7 | \$0 |
| | Floor - Tile Ceramic/ Porcelain | 2,231 | SF | 7 | \$0 |
| | Lighting - Lay-in | 30 | EA | 7 | \$0 |
| | Serving Line | 25 | LF | 7 | \$0 |
| | Storage/ Closet | 302 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 2,119 | SF | 7 | \$0 |
| Library | | | | | |
| | Ceiling - Exposed | 1,714 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 4 | EA | 7 | \$0 |
| | Doors - Transom Window | 30 | SF | 7 | \$0 |
| | Floor - Carpet | 1,714 | SF | 7 | \$0 |
| | Lighting - Pendent/Surface | 12 | EA | 7 | \$0 |
| | Walls - Plaster/Drywall | 2,277 | SF | 7 | \$0 |
| Lunch & Multipu | rpose Room | | | | |
| | Ceiling - Exposed | 4,136 | SF | 7 | \$0 |
| | Doors - Side-lite | 144 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 10 | EA | 7 | \$0 |
| | Floor - Tile | 4,136 | SF | 6 | \$9,049 |
| | Lighting - Lay-in | 24 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 30 | EA | 7 | \$0 |
| | Walls - Plaster/Drywall | 1,300 | SF | 7 | \$0 |
| | Walls - Vinyl Coated Gypsum Panel | 1,240 | SF | 7 | \$0 |
| MDF_IDF | | | | | |
| | Doors - Steel Doors incl hw | 1 | EA | 7 | \$0 |
| | Finishes | 1,696 | SF | 7 | \$0 |
| | Ventilation and Cooling | 1 | EA | 6 | \$1,855 |
| Mechanical/ Serv | ice Rooms | | | | |
| | Janitor's Closet | 104 | SF | 6 | \$745 |
| | Mechanical/ Service Rooms | 496 | SF | 6 | \$3,553 |
| | Storage Room | 380 | SF | 7 | \$0 |
| | | | | | |



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|---------------------------------|----------|------|------|-----------------|
| Restroom | | | | | |
| | Accessories | 1,618 | SF | 7 | \$0 |
| | Ceiling - Lay-in | 574 | SF | 7 | \$0 |
| | Ceiling - Plaster/Drywall | 1,044 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 8 | EA | 7 | \$0 |
| | Floor - Tile Quarry | 1,618 | SF | 7 | \$0 |
| | Floor Drain | 12 | EA | 7 | \$0 |
| | Hand Dryer | 16 | EA | 7 | \$0 |
| | Lavatory | 20 | EA | 7 | \$0 |
| | Lighting - Lay-in | 44 | EA | 7 | \$0 |
| | Partitions | 16 | EA | 7 | \$0 |
| | Student Lockers - One Tier | 11 | EA | 7 | \$0 |
| | Urinals | 6 | EA | 7 | \$0 |
| | Walls - Plaster/Drywall | 2,829 | SF | 7 | \$0 |
| | Walls - Tile Ceramic/ Porcelain | 2,565 | SF | 7 | \$0 |
| | Water Closet | 22 | EA | 7 | \$0 |
| - / | | | | | * 45 000 |

Rooms (Other Than Classrooms) Subtotal:

Building: Addition

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|--|----------|------|------|------|
| Corridor | | | | | |
| | Ceiling - Lay-in | 4 | SF | 5 | \$36 |
| | Ceiling - Lay-in | 4,602 | SF | 7 | \$0 |
| | Ceiling - Plaster/Drywall | 924 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 22 | EA | 7 | \$0 |
| | Doors - Transom Window | 36 | EA | 7 | \$0 |
| | Drinking Fountains - Single Water Cooler | 6 | EA | 7 | \$0 |
| | Floor - Tile Quarry | 279 | SF | 7 | \$0 |
| | Floor - Tile/Sheet | 6,080 | SF | 7 | \$0 |
| | Lighting - Chandelier, Incandescent | 15 | EA | 7 | \$0 |
| | Lighting - Lay-in | 68 | EA | 7 | \$0 |
| | Stairs - Concrete Stairs | 6 | LF | 7 | \$0 |
| | Student Lockers - One Tier | 18 | EA | 7 | \$0 |
| | Student Lockers - Two Tiers | 302 | EA | 7 | \$0 |
| | Walls - Concrete Block | 504 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 11,398 | SF | 7 | \$0 |

\$15,203



Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|-----------------------------------|----------|------|------|----------|
| Corridor | | | | | |
| | Walls - Vinyl Coated Gypsum Panel | 1,697 | SF | 7 | \$0 |
| Stairs | | | | | |
| | Ceiling - Lay-in | 891 | SF | 7 | \$0 |
| | Floor - Tile | 697 | SF | 7 | \$0 |
| | Handrails | 362 | LF | 7 | \$0 |
| | Lighting - Lay-in | 3 | EA | 7 | \$0 |
| | Lighting - Wall Mounted | 10 | EA | 7 | \$0 |
| | Stairs - Asphalt | 80 | LF | 7 | \$0 |
| | Walls - Plaster/Drywall | 3,648 | SF | 7 | \$0 |
| Vertical Conveyance | | | | | |
| | Elevator - Hydraulic Elevator | 1 | EA | 6 | \$19,238 |
| Building Interior | Subtotal | | | | \$19,274 |

Total Building Cost

SITE

Category: Site

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------|---------------------------------------|----------|------|------|----------|
| Civil/Drainage | | | | | |
| | Civil/ Drainage - Catch Basin | 18 | EA | 6 | \$19,689 |
| | Civil/ Drainage - Site Drain | 1 | EA | 6 | \$310 |
| | Civil/ Drainage - Site Manhole | 10 | EA | 6 | \$14,927 |
| Fencing | | | | | |
| | Fencing - New Standard Ornamental | 1,583 | LF | 6 | \$50,503 |
| Landscape | | | | | |
| | Benches | 9 | EA | 6 | \$3,870 |
| | Landscape - Grass | 25,700 | SF | 5 | \$38,956 |
| | Landscape - Hardscape- Concrete | 1,116 | SF | 6 | \$7,916 |
| | Landscape - Hardscape- Concrete | 9,770 | SF | 7 | \$0 |
| | Landscape - Hardscape- Pavers | 368 | SF | 6 | \$2,084 |
| | Parkway trees | 6 | EA | 6 | \$3,960 |
| | Planting Beds/ Area | 6,577 | SF | 6 | \$10,816 |
| | Play Area - Synthetic Turf Play Field | 8,911 | SF | 7 | \$0 |

\$36,963



SITE

Category: Site

| Calegory. Sile | | | | <u> </u> | |
|-----------------|--|----------|------|----------|-----------|
| Group | Item - Type | Quantity | Unit | Rank | Cos |
| Landscape | | | | | |
| | Retaining Wall - Concrete | 140 | SF | 6 | \$3,281 |
| | Trash Receptacles | 8 | EA | 6 | \$2,498 |
| Parking Lot | | | | | |
| | Concrete Curbs | 784 | LF | 6 | \$10,068 |
| | Interior Plantings | 72 | LF | 6 | \$3,063 |
| | Surface - Asphalt | 18,514 | SF | 6 | \$44,743 |
| | Trash Compactor | 1 | EA | 7 | \$0 |
| | Trash Enclosure - Masonry | 337 | SF | 7 | \$0 |
| Playground | | | | | |
| | Equipment - Pre K 3-5 | 1 | EA | 6 | \$3,546 |
| | Equipment - School Age 5-12 | 1 | EA | 6 | \$3,546 |
| | Surface - Poured Surface | 1,194 | SF | 6 | \$8,742 |
| Sidewalks | | | | | |
| | Sidewalks - Internal Walks | 1,263 | LF | 6 | \$15,171 |
| | Sidewalks - Perimeter Sidewalks | 5,779 | SF | 6 | \$11,487 |
| Signage | | | | | |
| | Flag Pole - Building Mounted Flag Pole | 1 | EA | 7 | \$0 |
| | Flag Pole - Flag Pole | 1 | EA | 6 | \$1,657 |
| | Marquee - Free Standing Back Lighted | 1 | EA | 7 | \$0 |
| Site Subtotal: | | | | | \$260,833 |
| Total Site Cost | | | | | \$260,833 |

Campus Total ^{2 3}

\$2,450,869

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.



Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------|-------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | | | | <u> </u> | | | 1 | | | | | 1 | 4 |
| Art Room | Art Room | 2nd Floor | 201 | 201-203 | 1,227 | 1 | 6 | 20 | 216 | 54 | 50 | Ν | N | Ν |
| Kindergarten | Regular Classroom | 1st Floor | 103 | 103 | 700 | 1 | 6 | 6 | 108 | 54 | 50 | Ν | Y | Ν |
| Kindergarten | Kindergarten | 1st Floor | 104 | 104 | 825 | 1 | 0 | 6 | 126 | 63 | 50 | Ν | Y | Y |
| Music Room | Regular Classroom | 1st Floor | 101 | 101 | 700 | 1 | 6 | 6 | 108 | 54 | 50 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 102 | 102 | 690 | 1 | 6 | 10 | 108 | 54 | 50 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 105 | 105 | 700 | 1 | 6 | 6 | 108 | 54 | 50 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 106 | 106 | 720 | 1 | 6 | 6 | 108 | 54 | 50 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 108 | 108 | 825 | 1 | 6 | 12 | 126 | 63 | 50 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 109 | 109 | 700 | 1 | 6 | 6 | 108 | 54 | 50 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 110 | 110 | 700 | 1 | 6 | 6 | 108 | 54 | 50 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 200 | 200 | 700 | 1 | 6 | 10 | 108 | 54 | 50 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 700 | 1 | 13 | 44 | 108 | 54 | 50 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 700 | 1 | 6 | 6 | 108 | 54 | 50 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 206 | 720 | 1 | 6 | 6 | 108 | 54 | 50 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | 207 | 400 | 0 | 4 | 6 | 54 | 27 | 50 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 700 | 1 | 6 | 6 | 108 | 54 | 50 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 209 | 720 | 1 | 6 | 6 | 108 | 54 | 50 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 210 | 210 | 700 | 1 | 6 | 6 | 108 | 54 | 50 | Ν | Y | Ν |
| Science Classroom | Science Classroom | 2nd Floor | 204 | 204 | 700 | 1 | 6 | 32 | 108 | 54 | 50 | Ν | Y | Y |
| Special Education | Office | 1st Floor | 100 | 100 | 340 | 1 | 2 | 10 | 54 | 27 | 50 | Ν | Y | Ν |
| Addition | | | | | | | | | | | | | | |
| Computer Lab | Computer Lab | 2nd Floor | 256 | 256 | 900 | 1 | 16 | 20 | 136 | 12 | 40 | Ν | N | Ν |
| Faculty Lounge | Regular Classroom | 2nd Floor | 252 | 252 | 750 | 1 | 6 | 18 | 90 | 12 | 40 | N | N | Ν |
| Kindergarten | Kindergarten | 1st Floor | 153 | 153 | 1,010 | 1 | 6 | 18 | 136 | 12 | 40 | N | N | Ν |
| Kindergarten | Kindergarten | 1st Floor | 155 | 155 | 1,010 | 1 | 6 | 18 | 136 | 12 | 40 | Ν | N | Ν |
| Kindergarten | Kindergarten | 1st Floor | 157 | 157 | 1,010 | 1 | 6 | 18 | 136 | 12 | 40 | N | N | Ν |
| Pre School | Pre School | 1st Floor | 159 | 159 | 1,010 | 1 | 6 | 18 | 136 | 12 | 40 | N | N | Ν |
| Pre School | Pre School | 1st Floor | 161 | 161 | 1,010 | 1 | 6 | 18 | 136 | 12 | 40 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 253 | 253 | 737 | 1 | 6 | 20 | 113 | 12 | 40 | N | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 255 | 255 | 737 | 1 | 6 | 20 | 136 | 12 | 40 | N | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 257 | 257 | 737 | 1 | 6 | 20 | 136 | 12 | 40 | N | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 258 | 258 | 828 | 1 | 6 | 18 | 136 | 12 | 40 | N | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 259 | 259 | 737 | 1 | 6 | 20 | 136 | 12 | 40 | N | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 261 | 261 | 737 | 1 | 6 | 20 | 136 | 12 | 40 | N | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 262 | 262 | 828 | 1 | 6 | 18 | 136 | 12 | 40 | N | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 264 | 264 | 828 | 1 | 6 | 18 | 136 | 12 | 40 | N | N | Ν |



Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------|-------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Addition | | | | | | | | | | | | | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 268 | 268 | 828 | 1 | 6 | 20 | 136 | 12 | 40 | Ν | N | Ν |
| Science | Science | 2nd Floor | 254 | 254 | 1,066 | 1 | 6 | 16 | 136 | 12 | 40 | Ν | Ν | Ν |