

Chicago Public Schools

6 Month Asbestos Surveillance

2024 Fall Six Month Survey

School: Norman A Bridge Elementary School
Address: 7001 W Addison

Oracle Unit: 22321
Region: 01

Building ID: 2380
Mail Room: 30

☐ **CHECK HERE IF NO CHANGE TO ASBESTOS**

Asbestos Surveyor: Ferhatbegovic, Denis
Survey Date: 10/28/2024
Email Address: dferhatbegovic@cps.edu

A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

☐ Each child's backpack ☒ Notice printed in school's newsletter ☐ Notice printed in school's calendar ☐ Other |

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01	Hot Water Tank Lagging #1	100	SF	Boiler Room - 1926		TSI	Yes	Loc	20		☒ YES ☐ NO

2022 Fall Six Month Survey: Damaged
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2023 Spring Six Month Survey: Damaged
Comments:none
2024 Spring Six Month Survey: Damaged
Comments:Need Repair
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 22321

Page 1

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	Hot Water Tank Lagging #2	175	SF	Boiler Room - 1926		TSI	Yes	Loc	30		☒ YES ☐ NO

2022 Fall Six Month Survey: Damaged
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2023 Spring Six Month Survey: Damaged
Comments:none
2024 Spring Six Month Survey: Damaged
Comments:Need Repair
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	Boiler Lagging #1	500	SF	Boiler Room - 1926		TSI	Yes	Loc	50		☒ YES ☐ NO

2022 Fall Six Month Survey: Damaged
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2023 Spring Six Month Survey: Damaged
Comments:none
2024 Spring Six Month Survey: Damaged
Comments:Need Repair
2024 Fall Six Month Survey: Damaged
Comments:Bad

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	Boiler Lagging #2	500	SF	Boiler Room - 1926		TSI	Yes	Loc	50		☒ YES ☐ NO

2022 Fall Six Month Survey: Damaged
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2023 Spring Six Month Survey: Damaged
Comments:none
2024 Spring Six Month Survey: Damaged
Comments:Need Repair
2024 Fall Six Month Survey: Damaged
Comments:Bad

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Header Insulation and Pipe Insulation (Mag Block)	260	LF	Boiler Room - 1926		TSI	Yes	Loc	20		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2023 Spring Six Month Survey: Damaged
Comments:none
2024 Spring Six Month Survey: Damaged
Comments:Need Repair
2024 Fall Six Month Survey: Damaged
Comments:Bad

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	Cardboard Pipe Insulation	1200	LF	Boiler Room, Mechanical Area, Tunnel, Unfinished Pipe Space, Unexcavated Areas and Air Tunnels (North and South) - 1926		TSI	Yes	Loc	57		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	Gasket Material (Boiler #1 & #2)	4	LF	Boiler Room - 1926		TSI	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	Aircell Pipe Insulation	2000	LF	Boiler Room, Mechanical Area, Tunnel, Unfinished Pipe Space, Unexcavated Areas and Air Tunnels (North and South) - 1926		TSI	Yes	Loc	269		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: Damaged
Comments:Bad

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	MJP E/F/V on Aircell Pipe Insulation	600	LF	Boiler Room, Mechanical Area, Tunnel, Unfinished Pipe Space, & Unexcavated Areas, N & S Air tunnels - 1926		TSI	Yes	Loc	60		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	MJP E/F/V on Cardboard Pipe Insulation	240	LF	Boiler Room, Mechanical Area, Tunnel, Unfinished Pipe Space, Unexcavated Areas and Air Tunnels (North and South) - 1926		TSI	Yes	Loc	6		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Aircell Duct Wrap	2500	SF	Unexcavated Areas - 1926		TSI	Yes	Loc	104		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Debris on Dirt Floor	1200	SF	NW, NE, Center, SW Unexcavated Areas - 1926		TSI	Yes	Dist	1200		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Mag Block Pipe Insulation	60	LF	Air Tunnel & Tunnel To Building, Mechanical Room, NW Unexcavated Area- 1926		TSI	Yes	Loc	6		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	MJP E/F/V on Fiberglass Pipe Run	200	LF	Mechanical Rm, Electrical Rm, Boiler Rm, Boys and Girls Toilet Pipe Chases- 1926		TSI	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	MJP E/F/V on Mag Block Pipe Insulation	43	LF	Boiler Room & Tunnel To Building- 1926		TSI	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Brown w/ White Streaks VFT	1400	SF	1st Floor Cafeteria (Room 112) - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" Brown w/ White Streaks VFT Mastic	1400	SF	1st Floor Cafeteria (Room 112) - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12"x12" White w/ Brown Streaks VFT	800	SF	1st Floor Cafeteria (Room 112) - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" White w/ Brown Streaks VFT Mastic	800	SF	1st Floor Cafeteria (Room 112) - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	9"x 9" White w/ Red Streaks VFT	550	SF	Room 110 (under the carpet), MDF Room - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	9"x 9" White w/ Red Streaks VFT Mastic	550	SF	Room 110 (under the carpet), MDF Room - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	9"x9" Beige VFT	750	SF	Room 111 - 1926		Miscellaneous	No	Dist	10		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	9"x9" Beige VFT Mastic	750	SF	Room 111 - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" Brown w/ Dark Brown Streaks VFT	360	SF	Room 108 - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12"x12" Brown w/ Dark Brown Streaks VFT Mastic	360	SF	Room 108 - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" White w/ Tan Streaks VFT	360	SF	Room 108 - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12"x12" White w/ Tan Streaks VFT Mastic	360	SF	Room 108 - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12"x12" Off White VFT	750	SF	Room 107 & Storage - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12"x12" Off White VFT Mastic	750	SF	Room 107 & Storage - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12"x12" Light Purple VFT	750	SF	Room 107 & Storage - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12"x12" Light Purple VFT Mastic	750	SF	Room 107 & Storage - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12"x12" Tan w/ Brown Streaks VFT	750	SF	Room 106 - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12"x12" Tan w/ Brown Streaks VFT Mastic	750	SF	Room 106 - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12"x12" Sand VFT	120	SF	Room 104 - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12"x12' Sand VFT Mastic	120	SF	Room 104 - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	9"x9" White w/ Blue Streaks VFT	700	SF	Room 105 - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	9"x9" White w/ Blue Streaks VFT Mastic	700	SF	Room 105 - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Lab Table Tops	1200	SF	Room 106 - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	12" x 12" Cream with Brown Streaks VFT	1500	SF	First and Second Floor Corridors - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64 A	12" x 12" Cream with Brown Streaks VFT Mastic	1500	SF	First and Second Floor Corridors - 1926		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	12"x12" White w/ Tan Specks VFT	1500	SF	1st & 2nd Floor Corridors - 1929		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	12"x12" White w/ Tan Specks VFT Mastic	1500	SF	1st & 2nd Floor Corridors - 1929		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	12"x12" Tan w/ White Specks VFT	700	SF	Room 102 - 1929		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	12"x12" Tan w/ White Specks VFT Mastic	700	SF	Room 102 - 1929		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:No repair needed

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	12"x12" Off White w/ Tan Specks VFT	700	SF	Room 102 - 1929		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	12"x12" Off White w/ Tan Specks VFT Mastic	700	SF	Room 102 - 1929		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:No repair needed

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12"x12" Black VFT	1100	SF	Assembly Hall - 1929		Miscellaneous	No	Loc	15		☒ YES ☐ NO

2022 Fall Six Month Survey: Damaged
Comments:none
2023 Spring Six Month Survey: Damaged
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2024 Fall Six Month Survey: Damaged
Comments:Bad
2024 Spring Six Month Survey: Damaged
Comments:Need Repair

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	12"x12" Black VFT Mastic	1100	SF	Assembly Hall - 1929		Miscellaneous	No	Loc	15		☒ YES ☐ NO

2022 Fall Six Month Survey: Damaged
Comments:none
2023 Spring Six Month Survey: Damaged
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2024 Spring Six Month Survey: Damaged
Comments:Need Repair
2024 Fall Six Month Survey: Damaged
Comments:Bad

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12"x12" Dark Red VFT	1100	SF	Assembly Hall - 1929		Miscellaneous	No	Loc	15		☒ YES ☐ NO

2022 Fall Six Month Survey: Damaged
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2023 Spring Six Month Survey: Damaged
Comments:none
2024 Spring Six Month Survey: Damaged
Comments:Need Repair
2024 Fall Six Month Survey: Damaged
Comments:Bad

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	12"x12" Dark Red VFT Mastic	1100	SF	Assembly Hall - 1929		Miscellaneous	No	Loc	15		☒ YES ☐ NO

2022 Fall Six Month Survey: Damaged
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2023 Spring Six Month Survey: Damaged
Comments:none
2024 Spring Six Month Survey: Damaged
Comments:Need Repair
2024 Fall Six Month Survey: Damaged
Comments:Bad

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	9"x18" Black VFT	350	SF	Assembly Hall - 1929		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Damaged
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2023 Spring Six Month Survey: Damaged
Comments:none
2024 Spring Six Month Survey: Damaged
Comments:Need Repair
2024 Fall Six Month Survey: Damaged
Comments:Bad

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	9"x18" Black VFT Mastic	350	SF	Assembly Hall - 1929		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Damaged
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2023 Spring Six Month Survey: Damaged
Comments:none
2024 Fall Six Month Survey: Damaged
Comments:Bad
2024 Spring Six Month Survey: Damaged
Comments:Need Repair

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	9"x9" Black w/ White Streaks VFT	400	SF	Assembly Hall - 1929		Miscellaneous	No	Loc	50		☒ YES ☐ NO

2022 Fall Six Month Survey: Damaged
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2023 Spring Six Month Survey: Damaged
Comments:none
2024 Fall Six Month Survey: Damaged
Comments:Bad
2024 Spring Six Month Survey: Damaged
Comments:Need Repair

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	9"x9" Black w/ White Streaks VFT Mastic	50	SF	Assembly Hall - 1929		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Damaged
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2023 Spring Six Month Survey: Damaged
Comments:none
2024 Fall Six Month Survey: Damaged
Comments:Bad
2024 Spring Six Month Survey: Damaged
Comments:Need Repair

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	9"x9" Dark Red w/ White Streaks VFT	50	SF	Assembly Hall - 1929		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Damaged
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2023 Spring Six Month Survey: Damaged
Comments:none
2024 Fall Six Month Survey: Damaged
Comments:Bad
2024 Spring Six Month Survey: Damaged
Comments:Need Repair

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	9"x9" Dark Red w/ White Streaks VFT Mastic	50	SF	Assembly Hall - 1929		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Damaged
Comments:none
2023 Fall Six Month Survey: Damaged
Comments:bad
2023 Spring Six Month Survey: Damaged
Comments:none
2024 Fall Six Month Survey: Damaged
Comments:Bad
2024 Spring Six Month Survey: Damaged
Comments:Need Repair

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	Carpet Mastic - REMOVED			Room 201 - 1929 - REMOVED							☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:No repair needed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	Hard Coat Plaster			Throughout - 1929							☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:No repair needed

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	Aircell Pipe Insulation	1250	LF	South: Air Tunnel, & Unex., Basement Store Rm, Elec. Rm, Assembly Hall Plenum, SE Unex. - 1929		TSI	Yes	Dist	60		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	MJP on Aircell Pipe Insulation	145	LF	South: Air Tunnel, & Unex., Basement Store Rm, Elec. Rm, Assembly Hall Plenum, SE Unexcavated. - 1929		TSI	Yes	Loc	21		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	Cardboard Pipe Insulation	535	LF	South: Air Tunnel, & Unex., Basement Store Rm, Elec. Rm, A.H. Plenum & W. Tol., SE Unex. - 1929		TSI	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	MJP on Cardboard Pipe Insulation	60	LF	South: Air Tunnel, & Unex., Basement Store Rm, Elec. Rm, A.H. Plenum & W. Tol., SE Unex. - 1929		TSI	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	MJP on Fiberglass Pipe Insulation	500	LF	Basement Electrical Room, 1st & 2nd Floor Boy's & Girl's Toilet Chases, Rm 300 Pipe Chase - 1929		TSI	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	Aircell Duct Insulation	500	SF	South & SouthEast Unexcavated - 1929		TSI	Yes	Dist	180		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	1 x 1 ft Grooved Ceiling Tiles	700	SF	Rooms 111 and 112		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:No repair needed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89 A	1 x 1 ft Grooved Ceiling Tile Mastic	700	SF	Rooms 111 and 112		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	Terrazo	4500	SF	1926 Building: Entryways, 1st and 2nd Floor Corridors, Gym Stairs, Stairwells, Room 300, 107 Wardrobe, Stage and Stairs		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91 A	Carpet Mastic	1600	SF	Rooms 110 and 213, Office and 2nd Floor Counselor's Office		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	12"x12" Blue VFT	700	SF	1st and 2nd Floor Corridors (Building 1926)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	12"x12" Blue Mastic	700	SF	1st and 2nd Floor Corridors (Building 1926)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:No repair needed
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
94	Blown-In Insulation on Duct Work	2500	SF	Attic		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	12"x12" White w/gray streaks VFT	3200	SF	Rooms 001-004 including the closets and the hallway in the MODULAR		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
96	12"x12" White w/gray streaks Mastic	3200	SF	Rooms 001-004 including the closets and the Hallway in the MODULAR		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	Beige w/brown streaks Linoleum Flooring	280	SF	Boy's and Girl's Bathrooms in the MODULAR		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
98	Beige w/brown streaks Linoleum Flooring Mastic	280	SF	Boy's and Girl's Washrooms in the MODULAR		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	Texture Drywall Ceiling	280	SF	Boy's and Girl's Washrooms in the MODULAR		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	2'x2' White w/holes Ceiling Tile	3200	SF	Rooms 001-004 including closets and the Hallway in the MODULAR		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	Drywall System	4500	SF	Throughout MODULAR		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	Vinyl Baseboard Mastic	600	LF	Throughout MODULAR		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	12"x12" Gray w/ Specks VFT	1200	SF	105, 107, and 112		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103A	12x12 Gray w/ Specks VFT Mastic	1200	SF	105, 107, 112		Miscellaneous	No	None			☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	12x12 Peach w/ Specks VFT	1200	SF	105, 107, 112		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104A	12x12 Peach w/ Specks VFT Mastic	1200	SF	105, 107, 112		Miscellaneous	No	None			☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	12x12 Blue w/ Specks VFT	1200	SF	105, 107, 112		Miscellaneous	No	None			☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105A	12x12 Blue w/ Specks VFT Mastic	1200	SF	105, 107, 112		Miscellaneous	No	None			☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	12x12 Blue w/ Light Blue and White Streaks VFT	400	SF	Room 105, 112		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	12x12 Blue w/ Light Blue and White Streaks VFT Mastic	400	SF	Room 105, 112		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	12x12 Gray w/ Blue and White Streaks VFT	400	SF	Room 105, 112		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
109	12x12 Gray w/ Blue and White Streaks VFT Mastic	400	SF	Room 105, 112		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2023 Spring Six Month Survey: No Change
Comments:none
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	12x12 Tan w/ Brown and Blue Streaks VFT	400	SF	Room 105, 112		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	12x12 Tan w/ Brown and Blue Streaks VFT Mastic	400	SF	Room 105, 112		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:none
2023 Spring Six Month Survey: No Change
Comments:none
2023 Fall Six Month Survey: No Change
Comments:good
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

A handwritten signature in black ink, appearing to read 'Richard J. Schleyer', written in a cursive style.

Richard J. Schleyer

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Norman A Bridge Elementary School

Date: 10/28/2024

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022.
Asbestos surveillances are conducted every six months.

CHECK ONE

- ☐ A copy of this notice was sent home in each child's backpack.
- ☒ A copy of this notice was printed in the school's newsletter and sent home with each child
- ☐ A copy of this notice was printed in the school's calendar and sent home with each child
- ☐ Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.