

Chicago Public Schools

6 Month Asbestos Surveillance

2024 Fall Six Month Survey

School: Everett McKinley Dirksen Elementary School
Address: 8601 W Foster Avenue

Oracle Unit: 22871
Region: 01

Building ID: 2950
Mail Room: 30

☐ **CHECK HERE IF NO CHANGE TO ASBESTOS**

Asbestos Surveyor: Flores, Genaro
Survey Date: 10/24/2024
Email Address:

A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

☐ *Each child's backpack* ☐ *Notice printed in school's newsletter* ☐ *Notice printed in school's calendar* ☐ *Other*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	Spray-on Fireproofing	4500	SF	1st Floor Kitchen and Throughout Building Above The Ceiling Tiles and Drywall - 1970 Bldg.		Surface	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 22871

Page 1

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12' Beige w/speckles VFT (not on-site)	7500	SF	Main Corridor - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Tan w/ Dark Brown Streaks VFT (ABATED)	0		Rooms 118, 112 , 120, 124, 126, 128 and 130 - 1971 Bldg.		Miscellaneous	No				☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Fall Six Month Survey: Abated
Comments:new tiles
2023 Spring Six Month Survey: Abated
Comments:new tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Beige w/ Specks VFT Mastic	7500	SF	Main Corridor - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Tan w/ Dark Brown Streaks VFT Mastic	2520	SF	Rooms 118, 120, 124, 126, 128 and 130 - 1971 Bldg.		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Fall Six Month Survey: Abated
Comments:new tiles
2023 Spring Six Month Survey: Abated
Comments:new tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	MJP E/F/V on Fiberglass Pipe Insulation	150	LF	Throughout - 1970 Bldg.		TSI	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	MJP E/F/V on Fiberglass Pipe Insulation	60	LF	1st Floor - Refuse Room - 1971 Bldg.		TSI	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Orange w/ Specks VFT	1200	SF	Main Corridor - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22A	12"x12" Orange w/ Specks VFT Mastic	1200	SF	Main Corridor - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Yellow w/ Specks VFT (Removed)			Room 104 - 1970 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Fall Six Month Survey: Abated
Comments:new tiles
2023 Spring Six Month Survey: Abated
Comments:new tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23A	12"x12" Yellow w/ Specks VFT Mastic (Removed)			Room 104 - 1970 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Spring Six Month Survey: Abated
Comments:new tiles
2023 Fall Six Month Survey: Abated
Comments:new tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Light Brown VFT	400	SF	Vault - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24A	12"x12" Light Brown VFT Mastic	400	SF	Vault - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Light Orange VFT	90	SF	102 & 104 Storage - 1970 Bldg.		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Spring Six Month Survey: Abated
Comments:new tiles
2023 Fall Six Month Survey: Abated
Comments:new tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25A	12"x12" Light Orange VFT Mastic	90	SF	102 & 104 Storage - 1970 Bldg.		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Fall Six Month Survey: Abated
Comments:new tiles
2023 Spring Six Month Survey: Abated
Comments:new tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Beige w/ Light Green VFT	1400	SF	Lunchroom and Room 102 - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:room 102 abated
2023 Spring Six Month Survey: Abated
Comments:new tiles in 102
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Abated
Comments:102 New tiles

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26A	12"x12" Beige w/ Light Green VFT Mastic	1400	SF	Lunchroom and Room 102 - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:room 102 abated
2023 Fall Six Month Survey: Abated
Comments:new tiles
2023 Spring Six Month Survey: Abated
Comments:new tiles in 102
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Abated
Comments:102 New tiles

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Green w/ White VFT	2000	SF	Lunchroom, Rooms 102 and 107 and the Engineers Office - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:room 102 abated
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27A	12"x12" Green w/ White VFT Mastic	2000	SF	Lunchroom, Rooms 102 and 107 and the Engineers Office - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:room 102 abated
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Grey w/ Specks VFT	220	SF	Lunchroom/Workroom and Teacher's Lounge - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28A	12"x12" Grey w/ Specks VFT Mastic	220	SF	Lunchroom/Workroom and Teacher's Lounge - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Beige (Marble) VFT	3500	SF	Gym (under new rubber flooring), Assistant Principal's Office, Room 201 and 201 Washroom, Room 204, Engineer's Storage Room and the SW Corner of the Library - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29A	12"x12" Beige (Marble) VFT Mastic	3500	SF	Gym (under new rubber flooring), Assistant Principal's Office, Room 201 and 201 Washroom, Room 204, Engineer's Storage Room and the SW Corner of the Library - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12" White VFT	1600	SF	Room 202 (Library), Engineer's Corridor and the Gym Stairwells - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30A	12"x12" White VFT Mastic	1600	SF	Room 202 (Library), Engineer's Corridor and the Gym Stairwells - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Tan w/ Small Specks VFT	7500	SF	Rooms 101, 103, 105, 109, 110, 111, 112, 113, 114, 115 and 201, the Principal's Office and the Main Office - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31A	12"x12" Tan w/ Small Specks VFT Mastic	7500	SF	Rooms 101, 103, 105, 109, 110, 111, 112, 113, 114 and 115, the Principal's Office and the Main Office - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" White w/ Tan Streaks VFT Mastic	2520	SF	Corridor and Rooms 118, 120, 124, 126, 128 and 130 - 1971 Bldg.		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Fall Six Month Survey: Abated
Comments:new tiles
2023 Spring Six Month Survey: Abated
Comments:new tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12"x12" White w/ Beige Speckles VFT	1440	SF	Rooms 119, 121, 122, 123 and 125 - 1971 Bldg.		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Spring Six Month Survey: Abated
Comments:new tiles
2023 Fall Six Month Survey: Abated
Comments:new tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33A	12"x12" White w/ Beige Streaks VFT Mastic	1440	SF	Rooms 119, 121, 122, 123 and 125 - 1971 Bldg.		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Spring Six Month Survey: Abated
Comments:new tiles
2023 Fall Six Month Survey: Abated
Comments:new tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" Light Tan w/ Black & White Speckles VFT	1440	SF	Rooms 119, 121, 122, 123 and 125 - 1971 Bldg.		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Fall Six Month Survey: Abated
Comments:new tiles
2023 Spring Six Month Survey: Abated
Comments:new tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34A	12"x12" Light Tan w/ Black & White Speckles VFT Mastic	1440	SF	Rooms 119, 121, 122, 123 and 125 - 1971 Bldg.		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Fall Six Month Survey: Abated
Comments:new tiles
2023 Spring Six Month Survey: Abated
Comments:new tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	2'x4' White w/ Grooved Ceiling Tile	9000	SF	Throughout - 1971 Bldg.		Miscellaneous	Yes	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Fall Six Month Survey: Abated
Comments:new tiles
2023 Spring Six Month Survey: Abated
Comments:new tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"x12" White w/ Tan Streaks VFT	2520	SF	Corridor and Rooms 118, 120, 124, 126, 128 and 130 - 1971 Bldg.		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Spring Six Month Survey: Abated
Comments:new tiles
2023 Fall Six Month Survey: Abated
Comments:new tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	2"x4' Ceiling Tile	7000	SF	Throughout - 1970 Bldg.		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	2"x2' Ceiling Tile	3250	SF	Throughout - 1970 Bldg.		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Fire Doors	16	EA	1st Floor Electrical Room, 1st Floor MDF Room and the Custodial Locker Room		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Fire Doors (no longer on-site)	10	EA	Mobile Unit		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longre exist
2024 Fall Six Month Survey: Other
Comments:No longer exist
2024 Spring Six Month Survey: Other
Comments:No longer exist

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Textured Plaster	270	SF	Men's and Women's Washroom Ceilings - Mobile Unit		Surface	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longer exist
2024 Spring Six Month Survey: Other
Comments:No longer exist
2024 Fall Six Month Survey: Other
Comments:No longer exist

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	12"x12" Crème w/ Brown Specks VFT (not on-site)	2500	SF	Throughout 99 Mobile Unit (Mobile Unit no longer on site)		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2024 Spring Six Month Survey: Other
Comments:No longer exist
2024 Fall Six Month Survey: Other
Comments:No longer exist

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100A	12"x12" Crème w/ Brown Specks VFT Mastic (not on-site)	2500	SF	Throughout 99 Mobile		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longer exist
2024 Fall Six Month Survey: Other
Comments:No longer exist
2024 Spring Six Month Survey: Other
Comments:no longer exist

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	2'x2' Ceiling Tile w/ Grooves (not on-site)			Throughout Mobile 99 (Except Washrooms and the Janitor's Closet)							☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2024 Spring Six Month Survey: Other
Comments:No longer exist
2024 Fall Six Month Survey: Other
Comments:No longer exist

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	Vinyl Baseboard (not on-site)			Throughout 99 Mobile							☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2024 Spring Six Month Survey: Other
Comments:No longer exist
2024 Fall Six Month Survey: Other
Comments:No longer exist

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102A	Vinyl Baseboard Mastic (not on-site)			Throughout 99 Mobile							☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longer exist
2024 Fall Six Month Survey: Other
Comments:No longer exist
2024 Spring Six Month Survey: Other
Comments:No longer exist

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	12"x12" Cream w/Brown Specks VFT	120	SF	E Corridor-Class Doorways		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2024 Spring Six Month Survey: Other
Comments:No longer exist
2024 Fall Six Month Survey: Other
Comments:No longer exist

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103 A	12"x12" Cream w/Brown Specks VFT Mastic	120	SF	E-Corridor-Class Doorways		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longer exist
2024 Fall Six Month Survey: Other
Comments:No longer exist
2024 Spring Six Month Survey: Other
Comments:No longer exist

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	Not Used										☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	Terrazzo Flooring	400	SF	Both Stairwells leading to the 2nd Floor Library - 1970 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	Drywall joint compound with tape	5000	SF	Throughout the Ceiling Tiles in Building 1970 Bldg.		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	Drywall Joint Compound with Tape	2000	SF	Above Ceiling Tiles Throughout - 1971 Bldg.		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:same
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	12X12 Off-white with tan specks VFT (not on-site)	4500	SF	2013 Mobile Unit: Rooms 401 & Storage; 402; Janitor Closet; 403 & Storage; 404; Electrical Room; Hallway; and N & S Entry Vestibules		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longer exist
2024 Spring Six Month Survey: Other
Comments:No longer exist
2024 Fall Six Month Survey: Other
Comments:No longer exist

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108A	12X12 Off-white with tan specks VFT Mastic (not on-site)	4500	SF	2013 Mobile Unit: Rooms 401 & Storage; 402; Janitor Closet; 403 & Storage; 404; Electrical Room; Hallway; and N & S Entry Vestibules		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2024 Spring Six Month Survey: Other
Comments:No longer exist
2024 Fall Six Month Survey: Other
Comments:No longer exist

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
109	2'X 2' Ceiling Tile (not on-site)	4900	SF	2013 Mobile Unit; Hallway N and S Entries; Rooms 401 & Storage; 402; 403 & Storage; 404; Boys, Girls and Unisex Toilets		Miscellaneous	Yes	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2024 Spring Six Month Survey: Other
Comments:No longer exist
2024 Fall Six Month Survey: Other
Comments:No longer exist

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	Drywall Systems (not on-site)	10000	SF	Throughout 2013 Mobile Unit		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2024 Spring Six Month Survey: Other
Comments:No longer exist
2024 Fall Six Month Survey: Other
Comments:No longer exist

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	Vinyl Baseboard Mastic (not on-site)	1000	LF	Rooms 401 and storage, 402, JC, 403 and storage, 404, Electrical Closet, Hallway - 2013 Mobile Unit		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2024 Spring Six Month Survey: Other
Comments:No longer exist
2024 Fall Six Month Survey: Other
Comments:No longer exist

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	Vinyl Flooring Mastic (not on-site)	400	SF	Boys and Girls toilet and Unisex toilet - 2013 Mobile Unit		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: Other
Comments:no longer exist
2024 Spring Six Month Survey: Other
Comments:No longer exist
2024 Fall Six Month Survey: Other
Comments:No longer exist

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	12"x12" Mustard w/White & Tan Speckles VFT	600	SF	Rm 104 - 1970 bldg.		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Fall Six Month Survey: Abated
Comments:new tiles
2023 Spring Six Month Survey: Abated
Comments:new tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113A	12"x12" Mustard w/White & Tan Speckles VFT Mastic	600	SF	Rm 104 - 1970 bldg.		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Spring Six Month Survey: Abated
Comments:new tiles
2023 Fall Six Month Survey: Abated
Comments:new tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114	12"x12" Off White w/ Tan Streaks VFT	420	SF	Rm 104 - 1970 bldg.		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Spring Six Month Survey: Abated
Comments:new tiles
2023 Fall Six Month Survey: Abated
Comments:new tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114A	12"x12" Off White w/ Tan Streaks VFT Mastic	420	SF	Rm 104 - 1970 bldg.		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:new
2023 Fall Six Month Survey: Abated
Comments:new tiles
2023 Spring Six Month Survey: Abated
Comments:new tiles
2024 Spring Six Month Survey: Abated
Comments:New tiles
2024 Fall Six Month Survey: Abated
Comments:New tiles

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
115	2'x2' Off White VFT	10000	SF			Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Other
Comments:no longer exist
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Abated
Comments:new tiles
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

A handwritten signature in black ink, appearing to read 'Richard J. Schleyer', written in a cursive style.

Richard J. Schleyer

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Everett McKinley Dirksen Elementary School

Date: 10/24/2024

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022.
Asbestos surveillances are conducted every six months.

CHECK ONE

- ☐ A copy of this notice was sent home in each child's backpack.
- ☐ A copy of this notice was printed in the school's newsletter and sent home with each child
- ☐ A copy of this notice was printed in the school's calendar and sent home with each child
- ☐ Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.