

Chicago Public Schools

6 Month Asbestos Surveillance

2024 Fall Six Month Survey

School: Joshua D Kershaw Elementary School
Address: 6450 S. Lowe

Oracle Unit: 23991
Region: 05

Building ID: 4270
Mail Room: 45

☒ **CHECK HERE IF NO CHANGE TO ASBESTOS**

Asbestos Surveyor: Abraham, Anthony
Survey Date: 11/19/2024
Email Address: _____

A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

☐ *Each child's backpack* ☐ *Notice printed in school's newsletter* ☐ *Notice printed in school's calendar* ☐ *Other* |

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	12X12 CELING TILE PINDOT (REGULAR PATTERN) ABATED			2ND FLOOR CORRIDOR		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 23991

Page 1

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02A	12X12 CELING TILE FISSURED PINDOT	1000	SF	THROUGHOUT - PATCHES		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02B	12X12 CELING TILE IRREGULAR PINDOT	50000	SF	THROUGHOUT BUILDING		Miscellaneous	Yes	Dist	100		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	WHITE HARDCOAT PLASTER	2000	SF	KITCHEN STORAGE AND STAGE		Surface	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12x12 Beige Speckle Floor Tile	790	SF	1st Floor Corridor		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07A	12X12 BEIGE FLOOR TILE	1200	SF	KITCHEN OFFICE, ROOM 212		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07B	12X12 BROWN W/BEIGE FLOOR TILE	200	SF	ROOM 212		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07C	12X12 BEIGE BROWN FLOOR TILE	150	SF	2ND FLOOR CORRIDOR (PATCHING NEAR RESTROOMS)		Miscellaneous	No	Loc	10		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	9x9 BROWN SPECKLED FLOOR TILE	200	SF	Auditorium, Teachers' Lounge, Room 200 Closet		Miscellaneous	No	Loc	6		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08A	9"x9" DARK BROWN W/WHITE FLOOR TILE (PART OF CHECKERBOARD PATTERN)	850	SF	LUNCHROOM, 105, 107, 108, 109, 110, 111, 112, 208, 210		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08B	9"x9" TAN W/ BROWN FLOOR TILE	88	SF	LUNCHROOM (CHECKERBOARD), OFFICE AND STORAGE		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08C	9"X9" LIGHT BLUE W/ GRAY AND WHITE FLOOR TILE	400	SF	KITCHEN		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08D	9X9 GRAY W/WHITE SPECKS FLOOR TILE	3500	SF	1ST & 2ND FLOOR CORRIDORS		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08E	9X9 GRAY w/WHITE SWIRL FLOOR TILE	17350	SF	ROOMS: 100, 102, 105, 107, 109, 110, 111, 108, 112, 208, 210		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09A	12x12 BEIGE FLOOR TILE MASTIC	1000	SF	KITCHEN OFFICE		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09B	12"X12" BROWN w/BEIGE FLOOR TILE MASTIC	200	SF	ROOM 212		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09C	12X12 BEIGE BROWN FLOOR TILE MASTIC	150	SF	2ND FLOOR CORRIDOR (PATCHING NEAR RESTROOM)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	9X9 BROWN SPECKLED FLOOR TILE MASTIC	500	SF	TEACHERS LOUNGE, AUDITORIUM		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10A	9X9 DARK BROWN w/WHITE MASTIC	850	SF	LUNCHROOM, 105, 107, 108, 109, 110, 111, 112, 201-211		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10B	9X9 TAN W/ BROWN MASTIC	1000	SF	LUNCHROOM (CHECKERBOARD)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10C	9X9 LIGHT BLUE w/GRAY AND WHITE SPECKS MASTIC	400	SF	KITCHEN		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10D	9X9 GRAY w/WHITE SPECKS MASTIC	3500	SF	1ST & 2ND FLOOR CORRIDORS		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10E	9X9 GRAY w/WHITE SWIRL FLOOR TILE MASTIC	19000	SF	ROOMS: 100, 102, 105, 107, 109, 110, 111, 108, 112, 200-211		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	VIBRATION CONNECTORS	80	LF	FAN ROOM 2ND FLOOR		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	FLUE PATCHING (ABATED)			BOILER ROOM		TSI					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Brown Carpet Mastic ABATED			Assistant Principal's Office		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12x12 Cream w/Specks Floor Tile	1500	SF	1st Floor Corridor		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12x12 Cream w/Specks Floor Tile Mastic	1500	SF	1st Floor Corridor		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12x12 Salmon Floor Tile ABATED			Book Storage		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12x12 Salmon Floor Tile Mastic ABATED			Book Storage		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12x12 Brown w/White Specks	250	SF	Faculty Lounge		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12x12 Brown w/White Specks Floor Tile Mastic	250	SF	Faculty Lounge		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Blue Carpet Mastic ABATED			Main Office, Room 103		Miscellaneous		None			☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12x12 Cream w/Tan Specks Floor Tile ABATED			Modular Building		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12x12 Cream w/Tan Specks Floor Tile Mastic ABATED			Modular Building		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	2" Cream Baseboard ABATED			Classrooms and Hallway in Modular Building		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	2" Cream Baseboard Mastic ABATED			Classrooms and Hallway in Modular Building		Miscellaneous		None			☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	2x2 Ceiling Tile	200	SF	2nd Floor Corridor		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	4" Cream Baseboard ABATED			Bathrooms in Modular Building		Miscellaneous		None			☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	24x24 White Acoustical Ceiling Tile	4000	SF	1st & 2nd Floor Corridors		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Purple Multicolor Carpet (NOT SUSPECT)			Main Office, Assistant Principal's Office		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Purple Multicolor Carpet Mastic	600	SF	Main Office, Assistant Principal's Office		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Purple Carpet NOT SUSPECT MATERIAL			Principal's Office		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Purple Carpet Mastic	600	SF	Principal's Office		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Blue Carpet-NOT SUSPECT MATERIAL			Library (Room 106)		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: Abated
Comments:New carpet installed
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Blue Carpet Mastic	1512	SF	Library (Room 106)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: Abated
Comments:New carpet installed
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Purple/Green Multicolor Carpet Mastic	500	SF	Room 106		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Blue Mix Carpet Mastic	500	SF	Rooms 103 & 106, Counselor's Office		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: Abated
Comments:New tile been installed
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Ductwork Insulation ABATED			Fan Room		TSI					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Blue Carpet-NOT SUSPECT			Room 103		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: Abated
Comments:New carpet installed
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Blue Carpet Mastic	330	SF	Room 103		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: Abated
Comments:New carpet installed
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12"x12" Orange w/Specks Vinyl Floor Tile	200	SF	Principal's Office		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39A	12"x12" Orange w/Specks Vinyl Floor Tile Mastic	200	SF	Principal's Office		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12"x12" Creme w/Specks Vinyl Floor Tile	700	SF	Rooms 209 & 211		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Fall Six Month Survey: No Change
Comments:Good
2024 Spring Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40A	12"x12" Creme w/Specks Vinyl Floor Tile Mastic	1500	SF	Rooms 209 & 212		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" Light Blue w/Specks Floor Tile	950	SF	Room 200		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12"x12" Light Blue w/Specks Floor Tile Mastic	950	SF	Room 200		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Burgundy Carpet Mastic	223	SF	Assistant Principal's Office		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12"x12" Grey White & Blue Floor Tile	2088	SF	Rooms 100 & 102		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Mastic associated with 12" x12" Grey White & Blue Floor Tile	2088	SF	Rooms 100 & 102		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Terrazzo Tile	500	SF	Stairs & Landings		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Joint Insulation of Fiberglass Insulated Pipes ABATED			Throughout Facility, Including Classroom Ceiling Soffitts in North Wing, First Floor Classrooms, Pipe Chases		TSI					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Spring Six Month Survey: No Change
Comments:ok
2023 Fall Six Month Survey: No Change
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations		Miscellaneous		Unknown			☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:GOOD
2023 Fall Six Month Survey: No Change
Comments:ok
2023 Spring Six Month Survey: Abated
Comments:ok
2024 Spring Six Month Survey: No Change
Comments:Good
2024 Fall Six Month Survey: No Change
Comments:Good

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

A handwritten signature in black ink, appearing to read "Richard J. Schleyer", written in a cursive style.

Richard J. Schleyer

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Joshua D Kershaw Elementary School

Date: 11/19/2024

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.

CHECK ONE

- ☐ A copy of this notice was sent home in each child's backpack.
- ☐ A copy of this notice was printed in the school's newsletter and sent home with each child
- ☐ A copy of this notice was printed in the school's calendar and sent home with each child
- ☐ Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.