

Chicago Public Schools

6 Month Asbestos Surveillance

2024 Fall Six Month Survey

School: Willa Cather Elementary School
Address: 2908 W. Washington

Oracle Unit: 26021
Region: 03

Building ID: 6730
Mail Room: 38

☐ **CHECK HERE IF NO CHANGE TO ASBESTOS**

Asbestos Surveyor: Suggs, Marshaun
Survey Date: 11/26/2024
Email Address: msuggs2@cps.k12.il.us

A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

☐ *Each child's backpack* ☐ *Notice printed in school's newsletter* ☐ *Notice printed in school's calendar* ☒ *Other* | *email*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	9" x 9" Brown/Gray Floor Tile	900	SF	Faculty Lunchroom, Gym Stage, Room 109, and Stairs.		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments: no change
2023 Fall Six Month Survey: No Change
Comments: n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments: no change
2024 Fall Six Month Survey: No Change
Comments: n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 26021

Page 1

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2	12" x 12" Brown Floor Tile	1800	SF	Rooms 115, 116 & 117,		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	Transite ceiling panel	100	SF	1st and 2nd floor washrooms, and 1st floor old phone booth		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	1' x 1' Random Dot Ceiling Tile (12" x 12")	100	SF	Partial in Hallway, Closet Annex		Miscellaneous	Yes	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	9" x 9" Brown/Gray Floor Tile Mastic	900	SF	Faculty Lunch Room		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	12" x 12" Brown Floor Tile Mastic	2400	SF	Rooms 115, 116 & 117		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	9" x 9" Gray Floor Tile			Annex Outside of Room 210, 213		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	9" x 9" Gray Floor Tile Mastic	18000	SF	Throughout Rooms on The 1st & 2nd Floors Rooms 114,110,107,109,112,113 , 213		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12" x 12" Tan Floor Tile			Room 111 & Engineer's Office, 112 (patch)		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12" x 12" Tan Floor Tile Mastic			Room 111 & Engineer's Office, 211 (patch)		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Baseboard			Throughout Building		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Baseboard mastic			Throughout Building		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Curtain wall insulation			Rooms 105, 106, 116, 117, 205, 207, 216 &217		TSI					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
016	White fiberglass pipe insulation			Throughout Building as Replacement Insulation		TSI					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Window glaze (interior)			Throughout Building		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Interior of Boilers	800	SF	Boiler Room		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: Other
Comments:new
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: Abated
Comments:New Boilers installed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Roof material - non ahera			Exterior		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: Other
Comments:new
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: Abated
Comments:new roof

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Vault door (insulation)	30	SF	Main Office		TSI	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Vibration collar (cloth)	60	LF	Mechanical Areas and Boiler Room		Miscellaneous	No	None	0	LF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12" x 12" White Floor Tile			Room 111		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12" x 12" White Floor Tile Mastic			Room 111		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Gray baseboard			Room 111		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Gray baseboard mastic			Room 111		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Plaster ceiling			Room 111		Surface					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	1' x 1' White Ceiling Tile (pinhole)	1000	SF	Throughout classrooms on soffits, Closets, Resource Center, Faculty Lounge,		Miscellaneous	Yes	Loc	10	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Carpet mastic			Room 111		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Interior window caulk			Throughout Interior of Building		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Exterior window caulk - non ahera			Exterior of Building		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Acoustical spray-on fireproofing	62000	SF	Throughout Building above ceilings in classrooms and hallways		Surface	Yes	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12" x 12" Brown w/Speckles Floor Tile	2400	SF	Hallway, Basement Entrance, Lunchroom, rooms 115,116,117		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" x 12" Brown w/Speckles Floor Tile Mastic			Room 111, 109		Miscellaneous			4		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Blue carpet adhesive			Library, Engineer's Office		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no chane
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Terrazo	1600	SF	Stairs in Gym, Stairwell & Auditorium		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Red carpet mastic	500	SF	Main Office,Principal Office, and Room 238		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12" x 12" Gray Floor Tile	17000	SF	Top of Stage in Gym, Throughout 1, 2 Hallways, Rooms 118,201-203, 206,207,212, 109, 108		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36M	12" x 12" Gray Floor Tile Mastic	17000	SF	Top of Stage in Gym, Throughout 1, 2, Floor Hallways, Rooms 118,201- 203,206,207,212, 109, 108		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Tan baseboard	100	SF	Room 111, 109		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37M	Tan baseboard mastic	100	SF	Room 111, 109		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12" x 12" Aqua & White Floor Tile	150	SF	Room 111, 109		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38M	12" x 12" Aqua White Floor Tile Mastic	150	SF	Room 111		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Ceramic tile & grout	500	SF	Bathrooms Walls		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39M	Ceramic tile mastic	500	SF	Bathroom Walls		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	6 x 6 White Floor Tile			Bathroom in Room 111, 109		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40 M	6 x 6 White Floor Tile Mastic			Bathrooms in Room 111 & 109		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	2' x 2' Ceiling Tiles	1700	SF	Main Office, Rooms 109,111,105,118, Partial 1st and 2nd Floor		Miscellaneous	Yes	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" Red Floor Tile			Room 210		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42M	12" x 12" Red Floor Tile Mastic			Room 210		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12" x 12" Green and Blue Floor Tile	150	SF	Room 111		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43M	12" x 12" Green and Blue Floor Tile Mastic	150	SF	Room 111		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	9" x 9" Floor Tile	18000	SF	Throughout Rooms on 1st and 2nd Floor		Miscellaneous	No	Dist	40	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Abated
Comments:new floors
2024 Spring Six Month Survey: No Change
Comments:no change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	1' x 1' White ceiling tile	5000	SF	Hallways		Miscellaneous	Yes	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Tongue and groove wooden floor	7500	SF	Gymnasium		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no chage
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	9" x 9" Black w/ White Specks Floor Tile	4	SF	Rooms 205, 204, 216, 213 (patches)		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Fall Six Month Survey: Abated
Comments:new floors
2024 Spring Six Month Survey: No Change
Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Mastic for 9" x 9" Black w/ White Specks Floor Tile	4	SF	Rooms 205, 204, 216, 213 (Patches)		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Abated
Comments:new floors
2024 Spring Six Month Survey: No Change
Comments:no change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12" x 12" Beige w/ White Specks Floor Tile	4	SF	Rooms 205, 204 , 216, 213, 209 , 114 (patches)		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Abated
Comments:new floors
2024 Spring Six Month Survey: No Change
Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Mastic for 12" x 12" Beige w/ White Specks Floor Tile	4	SF	Rooms 205, 204, 216, 213, 209, 114 (patches)		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Abated
Comments:new floor
2024 Spring Six Month Survey: No Change
Comments:no change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12" x 12" Light Gray w/ White Specks Floor Tile	20	SF	Rooms 204, 114 , 101 (patches)		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Fall Six Month Survey: Abated
Comments:new floor
2024 Spring Six Month Survey: No Change
Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Mastic for 12" x 12" Light Gray w/ White Specks Floor Tile	20	SF	Rooms 204, 114, 101 (patches)		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: Abated
Comments:new floor

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12" x 12" Purple w/ Light purple Specks Floor Tile	2000	SF	Room 215		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Mastic for 12" x 12" Purple w/ Light purple Specks Floor Tile	2000	SF	Room 215		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	12" x 12" White w/ gray Specks Floor Tile	2000	SF	Rooms 214, 210, 106, 107, 113, 114 (patches), 102, 103, 104		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	Mastic for 12" x 12" White w/ gray Specks Floor Tile	2000	SF	Rooms 214, 210, 106, 107, 113, 114 (patches), 102, 103, 104		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	9" x 9" Gray w/ Black Specks Floor Tile	20	SF	Rooms 211 , 209 (patches), main Office storage		Miscellaneous	No	Loc	6	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: Abated
Comments:new floors

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Mastic for 9" x 9" Gray w/ Black Specks Floor Tile	20	SF	Rooms 211, 209 (patches), main Office storage		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: Abated
Comments:new floors

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	9" x 9" Rose Gold w/ Brown Specks Floor Tile	5	SF	Rooms 211, 209 (patches)		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: Abated
Comments:new floor

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Mastic for 9" x 9" Rose Gold w/ Brown Specks Floor Tile	5	SF	Rooms 211, 209 (patches)		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: Abated
Comments:new floor

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	9" x 9" Beige w/ Brown & White Specks Floor Tile	5	SF	Rooms 211, 209 (patches)		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Fall Six Month Survey: Abated
Comments:new floor
2024 Spring Six Month Survey: No Change
Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Mastic for 9" x 9" Beige w/ Brown & White Specks Floor Tile	5	SF	Rooms 211, 209 (patches)		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Abated
Comments:new floor
2024 Spring Six Month Survey: No Change
Comments:no change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	9" x 9" Dark Brown & Beige Specks Floor Tile	50	SF	Room 210 Hallway		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	Mastic for 9" x 9" Beige w/ Brown & White Specks Floor Tile	50	SF	Room 210 Hallway		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	12" x 12" Dark Grays Floor Tile	2500	SF	Rooms 109, 108		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Abated
Comments:new floor
2024 Spring Six Month Survey: No Change
Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	Mastic for 12" x 12" Dark Grays Floor Tile	2500	SF	Rooms 109, 108		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: Abated
Comments:new floor

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	12" x 12" Light Grays Floor Tile	2500	SF	Rooms 109, 108		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: Abated
Comments:new floor

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	Mastic for 12" x 12" Light Gray Floor Tile	2500	SF	Rooms 109, 108		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: Abated
Comments:new floor

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	12" x 12" Rose Gold w/ Brown Specks Floor Tile	8	SF	Room 112 (patches)		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	Mastic for 12" x 12" Rose Gold w/ Brown Specks Floor Tile	8	SF	Room 112 (patches)		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Fall Six Month Survey: Abated
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
201	Light Gray w/ White & Black Specks Linoleum	2000	SF	Room 201		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
202	Light Gray w/ White & Black Specks Linoleum Adhesive	2000	SF	Room 201		Miscellaneous	No	None	0	SF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Fiberglass pipe fittings		LF	Pipe Chases, Add Gym		TSI				LF	☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:n/a
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

A handwritten signature in black ink, appearing to read "Richard J. Schleyer", written in a cursive style.

Richard J. Schleyer

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Willa Cather Elementary School

Date: 11/26/2024

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.

CHECK ONE

- ☐ A copy of this notice was sent home in each child's backpack.
- ☐ A copy of this notice was printed in the school's newsletter and sent home with each child
- ☐ A copy of this notice was printed in the school's calendar and sent home with each child
- ☒ Other. email

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.