

Chicago Public Schools

6 Month Asbestos Surveillance

2024 Fall Six Month Survey

School: Nicholas Senn High School
Address: 5900 N. Glenwood

Oracle Unit: 47061
Region: 01

Building ID: 1540
Mail Room: 32

☐ **CHECK HERE IF NO CHANGE TO ASBESTOS**

Asbestos Surveyor: Ceja, Juan
Survey Date: 11/20/2024
Email Address: jceja4@cps.edu

A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

☐ Each child's backpack ☐ Notice printed in school's newsletter ☐ Notice printed in school's calendar ☒ Other | **WEBSITE**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01	Boiler Lagging (ABATED 2010)			Boiler # 1 - 1931 Bldg.		TSI					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Spring Six Month Survey: Abated
Comments:N/A
2023 Fall Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 47061

Page 1

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	Boiler Lagging (ABATED 2010)			Boiler # 2 - 1931 Bldg.		TSI					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Spring Six Month Survey: Abated
Comments:N/A
2023 Fall Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	Boiler Lagging (ABATED 2010)			Boiler # 3 - 1931 Bldg.		TSI					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Spring Six Month Survey: Abated
Comments:N/a
2023 Fall Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	Boiler Lagging (ABATED 2010)			Boiler # 4 - 1931 Bldg.		TSI					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Spring Six Month Survey: Abated
Comments:N/A
2023 Fall Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Boiler Gasket (ABATED 2010)			Boiler # 1 - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Spring Six Month Survey: Abated
Comments:N/A
2023 Fall Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	Boiler Gasket (ABATED 2010)			Boiler # 2 - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Spring Six Month Survey: Abated
Comments:N/A
2023 Fall Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	MJP on Fiberglass Pipe Insulation	600	FITTING	Throughout (See Hatching Maps) - 1912 Bldg.		TSI	Yes	Loc	2		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	MJP on Fiberglass Pipe Insulation	425	FITTING	ROTC Room, Boiler & Pump Rooms, Main Tunnel, 2nd & 3rd Floor South Janitors Closet Chase, 2nd Floor Boys Toilet (N), 3rd Floor Unisex Toilet; 1st Floor Janitor's Closet; Under Sinks in Rooms 310, 352, and 366; BookRoom Between Room 315 and 317; Mens Room Next to Room 322 - 1931 Bldg.		TSI	Yes	Loc	1		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	MJP on Paperwrap Pipe Insulation	370	FITTING	1st Floor South JC, 2nd Floor Janitor's Closet, 238 Chase, 188, Autoshop - 1931 Bldg.		TSI	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Paperwrap Pipe Insulation	300	LF	ROTC Room, 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 Bldg.		TSI	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Mudded Joint Packing on Aircell Pipe Insulation	603	FITTING	Mixing Room, 219, 319, Auditorium Crawlspace, Room 120A - 1912 Bldg.		TSI	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Insulation in Vault Door	28	SF	Office - 1912 Bldg.		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Mudded Joint Packing on Aircell Insulation	300	FITTING	Room 238 Chase, Autoshop, Autoshop Tool Room - 1931 Bldg.		TSI	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Aircell Pipe Insulation	1000	LF	Corridor by Main Corridor (N), Room 238 Chase, Room 140, Autoshop & Autoshop Tool Room, Kitchen Storage - 1931 Bldg.		TSI	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Aircell Pipe Insulation	2600	LF	Rooms 219, 319, 356, & Auditorium Crawlspce - 1912 Bldg.		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Paperwrap Pipe Insulation	400	LF	Auditorium Crawlspce - 1912 Bldg.		TSI	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	MJP E/F/V on Paperwrap Pipe Insulation	50	FITTING	Auditorium Crawlspce - 1912 Bldg.		TSI	Yes	Dist	7		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N./A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Hard Coat Plaster			Throughout - 1912 Bldg.							☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Hard Coat Plaster			Throughout - 1931 Bldg.							☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12" x 12" Tan w/Speckles VFT	5000	SF	3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.		Miscellaneous	No	Dist	50		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	9" x 9" Brown w/Streaks VFT Mastic	500	SF	Room 356		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12" x 12" Tan w/Speckles VFT Mastic	5000	SF	3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	9" x 9" Maroon VFT (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Fall Six Month Survey: Abated
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	9" x 9" Maroon VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Fall Six Month Survey: Abated
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	9" x 9" Brown w/Streaks VFT NOT OBSERVED	500	SF	Room 356 - NOT OBSERVED		Miscellaneous	No	None	0		☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	12" x 12" Light Brown w/ White Streaks VFT (Not Observed)	200	SF	Rooms 100, 106, & 106 Office - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	12" x 12" Light Brown w/ White Streaks VFT Mastic (Not Observed)	200	SF	Rooms 100, 106, & 106 Office - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	9" x 9" Black VFT (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Fall Six Month Survey: Abated
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	9" x 9" Black VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Fall Six Month Survey: Abated
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	9" x 9" Black w/Large White Streaks VFT (Abated)			3rd Floor Hall (S&N) - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Fall Six Month Survey: Abated
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	9" x 9" Black w/Large White Streaks VFT Mastic (Abated)			3rd Floor Hall (S&N) - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Fall Six Month Survey: Abated
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	9" x 9" Brown w/Large White Streaks VFT (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Fall Six Month Survey: Abated
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	9" x 9" Brown w/Large White Streaks VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Fall Six Month Survey: Abated
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	9" x 9" Orange w/White VFT Streaks (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Fall Six Month Survey: Abated
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	9" x 9" Orange w/White Streaks VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Fall Six Month Survey: Abated
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	9" x 9" Maroon w/ White Streaks VFT (Abated)			2nd Floor Hall (S) - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Spring Six Month Survey: Abated
Comments:N/A
2023 Fall Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	9" x 9" Maroon w/ White Streaks VFT Mastic (Abated)			2nd Floor Hall (S) - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Fall Six Month Survey: Abated
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	9" x 9" Black w/ Faint White Streaks VFT (Abated)			2nd & 3rd Floor Halls (N&S) - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Spring Six Month Survey: Abated
Comments:N/A
2023 Fall Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	9" x 9" Black w/ Faint White Streaks VFT Mastic (Abated)			2nd & 3rd Floor Halls (N&S) - 1931 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Spring Six Month Survey: Abated
Comments:N/A
2023 Fall Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	12" x 12" White w/ Brown Speckles VFT (Not Observed)	1200	SF	Room 341 & 213 - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	12" x 12" White w/ Brown Speckles VFT Mastic	1200	SF	Room 341 & 213 - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	12" x 12" Brown w/ Light Brown Speckles VFT (Not observed)	600	SF	Room 239 - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	12" x 12" Brown w/ Light Brown Speckles VFT Mastic (Not Observed)	600	SF	Room 239 - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	Brown Linoleum	250	SF	238 North Storage - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	Green Linoleum (Not Observed)	5500	SF	Main Gym, Office & Locker - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	12" x 12" Peach w/ Speckles VFT- NOT OBSERVED	700	SF	Rooms 352, 379, 350 Storage - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	12" x 12" Peach w/ Speckles VFT Mastic - NOT OBSERVED	700	SF	Rooms 352, 379, 350 Storage - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	12" x 12" Light Brown w/ Dark Speckles VFT	700	SF	Room 355, 373, 375 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	12" x 12" Light Brown w/ Dark Speckles VFT Mastic	700	SF	Room 355, 373, 375 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
94	12" x 12" Beige w/ Dark Speckles VFT (Not Observed)	2000	SF	3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	12" x 12" Beige w/ Dark Speckles VFT Mastic (Not Observed)	2000	SF	3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
96	12" x 12" Dark Brown w/White & Dark Streaks VFT- NOT OBSERVED	1900	SF	3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	12" x 12" Dark Brown w/White & Dark Streaks VFT Mastic- NOT OBSERVED	1900	SF	3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
98	12" x 12" Black w/ White Speckles VFT- NOT OBSERVED	250	SF	3rd Floor Corridor (N) - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	12" x 12" Black w/ White Speckles VFT Mastic- NOT OBSERVED	250	SF	3rd Floor Corridor (N) - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	9" x 9" Red w/ White Streaks VFT- NOT OBSERVED	300	SF	115 Kitchen - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	9" x 9" Red w/ White Streaks VFT Mastic- NOT OBSERVED	300	SF	115 Kitchen - 1912 Bldg.		Miscellaneous	No	Dist	16		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	9" x 9" Gray w/ White Streaks VFT (Not Observed)	800	SF	Rooms 117A - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	9" x 9" Gray w/ White Streaks VFT Mastic (Not Observed)	800	SF	Rooms 117A - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	12" x 12" Light Green w/ White Streaks VFT (Not Observed)	350	SF	Room 123A - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	12" x 12" Light Green w/ White Streaks VFT Mastic (Not Observed)	350	SF	Room 123A - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	12" x 12" Beige w/ Dark & White Streaks VFT	6100	SF	Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	12" x 12" Beige w/ Dark & White Streaks VFT Mastic	6100	SF	Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	9" x 9" Lt. Brown w/ Dark Red Streaks VFT	455	SF	Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.		Miscellaneous	No	Dist	48		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: Abated
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
109	9" x 9" Lt. Brown w/ Dark Red Streaks VFT Mastic	455	SF	Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: Abated
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	9" x 9" Green w/ White Streaks VFT	300	SF	Teacher Lunchroom/Lounge - 1912 Bldg.		Miscellaneous	No	Loc	3		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: Abated
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	9" x 9" Green w/ White Streaks VFT Mastic	300	SF	Teacher Lunchroom/Lounge - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: Abated
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	12" x 12" Lt. Brown w/ Gray Speckles VFT (Not Observed)	80	SF	153 Vest., 120 Vest. - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	12" x 12" Lt. Brown w/ Gray Speckles VFT Mastic (Not Observed)	80	SF	153 Vest., 120 Vest. - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114	12" x 12" Beige w/ Brown Streaks VFT- NOT OBSERVED	1400	SF	Rooms 166, & 162 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
115	12" x 12" Beige w/ Brown Streaks VFT Mastic - NOT OBSERVED	1400	SF	Rooms 166, & 162 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116	12" x 12" Blue-Gray w/ White Streaks VFT	500	SF	Room 373, 375 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
117	12" x 12" Blue-Gray w/ White Streaks VFT Mastic	500	SF	Room 373, 375 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
118	12" x 12" Dk Gray w/ Beige Streaks VFT- NOT OBSERVED	2000	SF	Rooms 176, 174, 180 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
119	12" x 12" Dk Gray w/ Beige Streaks VFT Mastic- NOT OBSERVED	2000	SF	Rooms 176, 174, 180 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
120	12" x 12" Lt Gray w/ White Speckles VFT- NOT OBSERVED	2000	SF	Rooms 176, 174, 180 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
121	12" x 12" Lt Gray w/ White Speckles VFT Mastic- NOT OBSERVED	2000	SF	Rooms 176, 174, 180 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
122	12" x 12" Brown VFT- NOT OBSERVED		SF	Stage - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N.A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
123	12" x 12" Brown VFT Mastic- NOT OBSERVED	0	SF	Stage - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
124	2' x 2' Black Border VFT (Abated)			115 Kitchen - 1912 Bldg.		Miscellaneous					☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: Abated
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
125	2' x 2' Black Border VFT Mastic- Abated			115 Kitchen - 1912 Bldg.		Miscellaneous					☒ YES ☐ NO

2022 Fall Six Month Survey: Abated
Comments:None
2023 Fall Six Month Survey: Abated
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:N/A
2024 Fall Six Month Survey: Abated
Comments:N/A
2024 Spring Six Month Survey: Abated
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
126	2' x 2' Ceiling Tile- NOT OBSERVED	1700	SF	Room 425, & 326 - 1912 Bldg.		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
127	12" x 12" White w/Beige Streaks VFT - Not Observed	1000	SF	Room 377A, 178, 180		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
127 A	12" x 12" White w/Beige Streaks VFT Mastic	1000	SF	Room 377A		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
128	12" x 12" White w/Blue Streaks VFT	880	SF	Room 351		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
128 A	12" x 12" White w/Blue Streaks VFT Mastic	880	SF	Room 351		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
133	Lt Blue Speckled Linoleum- NOT OBSERVED	800	SF	Rooms 356, 326 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
134	Lt Blue Speckled Linoleum Mastic- NOT OBSERVED	800	SF	Rooms 356, 326 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
135	12" x 12" White w/ Gold Specks VFT (Not Observed)	1000	SF	Rooms 174, 176, & 180 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
136	12" x 12" White w/ Gold Specks VFT Mastic (Not Observed)	1000	SF	Rooms 174, 176, & 180 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
137	2' x 4' White Pin-Hole Ceiling Tile	1000	SF	Room 356 - 1912 Bldg.		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
138	12" x 12" White w/ Beige VFT	2000	SF	310 & Office, 302, 108, 110 - 1931 Bldg.		Miscellaneous	No	Loc	100		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
139	12" x 12" White w/ Beige VFT Mastic	2000	SF	310 & Office, 302, 108, 110 - 1931 Bldg.		Miscellaneous	No	Loc	100		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
140	12" x 12" Light Gray VFT	800	SF	Room 210, & Engineer's Office - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
141	12" x 12" Light Gray VFT Mastic	800	SF	210, & Engineer's Office - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
142	12" x 12" Light Blue VFT	900	SF	Room 210, 195A & Engineer's Office - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
143	12" x 12" Light Blue VFT Mastic	900	SF	Room 210, 195A & Engineer's Office - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
144	12" x 12" Green VFT (Not Observed)	300	SF	1st Floor Hall (N&S) - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
145	12" x 12" Green VFT Mastic (Not Observed)	300	SF	1st Floor Hall (N&S) - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:n/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
146	12" x 12" White VFT (Not Observed)	1000	SF	1st Floor Hall (N&S) - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
147	12" x 12" White VFT Mastic (Not Observed)	1000	SF	1st Floor Hall (N&S) - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
148	Linoleum, Gray w/Gray Streaks	4500	SF	Rooms 350, 352, 356 Vault, 306 and 310		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
148M	Linoleum, Gray w/Gray Streaks Mastic	4500	SF	Rooms 350, 352, 356 Vault, 306 and 310		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
149	Linoleum, Blue Solid	2000	SF	Rooms 100, 106, and 106 Office		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
149M	Linoleum, Blue Solid Mastic	2000	SF	Rooms 100, 106, and 106 Office		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
150	12" x 12" VFT- NOT OBSERVED	200	SF	3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
150M	12" x 12" VFT Mastic - NOT OBSERVED	200	SF	3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
151	12" x 12" Solid Gray VFT	800	SF	3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
151M	12" x 12" Solid Gray VFT Mastic	800	SF	3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
152	12" x 12" Tan w/Brown Speckles VFT (Not Observed)	800	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
152M	12" x 12" Tan w/Brown Speckles VFT Mastic (Not Observed)	800	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
153	12" x 12" White w/ Tan Speckles VFT (Not Observed)	200	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
153M	12" x 12" White w/ Tan Speckles VFT Mastic (Not Observed)	200	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
154M	Gold, Blue Carpet Mastic	1000	SF	Rooms 379, 375, 326, 315, and 272 (not observed), Room 225		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: Abated
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
155	Linoleum, White w/Gray Streaks	750	SF	Room 352		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
155M	Linoleum, White w/Gray Streaks Mastic	750	SF	Room 352		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
156	12" x 12" Light Gray w/ Gray and White Specks VFT	600	SF	Room 377, 377B		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
156A	12" x 12" Light Gray w/ Gray and White Specks VFT MASTIC	600	SF	Room 377, 377B		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
157	2' x 4' Smooth Ceiling Tile	700	SF	Room 351		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
158	1' x 1' Ceiling Tile w/ Grooves	2600	SF	Room 320, 425 - 1911 Bldg.		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
159	1' x 1' Ceiling Tile w/ Grooves above HA 161	1000	SF	Rooms 108, 148, 149, 146		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
160	2' x 4' Ceiling Tile w/ Grooves	22000	SF	South wing except women's toilet and 213-2nd fl. 2nd fl. north wing except boys toilet. 1st fl. south wing except for girls' toilet and engineer room. 1st fl. south wing hallway and rm 145. 3rd fl all south wing except for 306, 313, 315 and women's toilet. 3rd fl all north wing except for room 341, 335, 333 and men's toilet - 1930 Bldg.		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
161	2' x 4' Ceiling Tile w/ Grooves	45000	SF	Hallway from 319-335 and rooms 350, 353, 322, 326, 328, 330, 332, 334, 335, 325, 319, 358, 363, 367, 369, 373, 375, 379, 372, 374, 378, 380, 376, 258, 260, 261, 262, 264, 234, 266, 272, 276, 278, 273, 275, 277, 281, 222, 219, 221, 227, 231, 233, 230, 236. 2nd fl. hallway from room 319-335. 134, 132, 123A, 123, 121, 172, 174, 176, main office. 1st floor from 119-conference room and rooms 158, 160, 162, 166 - 1911 Bldg.		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
162	2' x 4' Ceiling Tile - pinhole	13000	SF	1st Floor Hallway from room 158-180 and from heat chamber 3- heat chamber 8. 2nd fl hallway from room 258-280 and hallway along side of auditorium. 3rd fl hallway from room 350-361-380 and from room 369-328 and classrooms 352, 364, 366 - 1911 Bldg.		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
163	2' x 4' Ceiling Tile - pinholes	4500	SF	Corridor from pump room- room 184, kitchen, cafeteria - 1930 Bldg.		Miscellaneous	Yes	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
164	12" x 12" Tan w/ light brown specks VFT	1600	SF	Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
164A	12" x 12" Tan w/ light brown specks VFT MASTIC	1600	SF	Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
165	9" x 9" Brown w/ yellow design VFT (Not Observed)	100	SF	Room 123 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
165A	9" x 9" Brown w/ yellow design VFT MASTIC (Not Observed)	100	SF	Room 123 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
166	12" x 12" Light Blue w/ blue specks VFT (Not Observed)	500	SF	2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
166A	12" x 12" Light Blue w/ blue specks VFT MASTIC (Not Observed)	500	SF	2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
167	12" x 12" White w/light blue, gray and yellow specks VFT (Not Observed)	7000	SF	2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
167A	12" x 12" White w/ light blue, gray and yellow specks VFT MASTIC (Not Observed)	7000	SF	2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
168	Black Lab Table Tops	700	SF	Rooms 358, 364, 367		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
169	Black Lab Counter Tops	300	SF	Rooms 358, 364, 367		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
170	Blue Linoleum with MASTIC	2300	SF	Rooms 358, 364, 366		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
171	12" x 12" Gray w/ tan streaks VFT w/ MASTIC	400	SF	Room 170		Miscellaneous	No	None			☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
172	Decorative Plaster	1200	SF	Assembly hall, vestibule leading to assembly hall		Surface	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
173	Terrazzo	2000	SF	Stairwells, 1st fl. corridor west of pump room - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
174	Terrazzo	1000	SF	1st Floor Corridors - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
175	12" x 12" Blue Speckled VFT (Not Observed)	1000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
176	12" x 12" Blue Speckled VFT Mastic (Not Observed)	1000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
177	12" x 12" Light Blue w/ Specks VFT (Not Observed)	8000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
178	12" x 12" Light Blue w/ Specks VFT Mastic (Not Observed)	8000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
179	12" x 12" Gray w/ Streaks VFT (Not Observed)	900	SF	Room 221		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
180	12" x 12" Gray w/ Streaks VFT Mastic (Not Observed)	900	SF	Room 221		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
181	Gray Linoleum w/ Granite Pattern	1200	SF	Room 100, 108, 106		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
182	Gray Linoleum w/ Granite Pattern Mastic	1200	SF	Room 100, 108, 106		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
183	Gray Linoleum	2400	SF	Rooms 105, 105A, 110		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
184	Gray Linoleum Mastic	2400	SF	Rooms 105, 105A, 110		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
185	12" x 12" Red w/ Streaks VFT	400	SF	Health Center (144)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
186	12" x 12" Red w/ Streaks VFT Mastic	400	SF	Health Center (144)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
187	12" x 12" Yellow w/Streaks VFT	400	SF	Health Center (144)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
188	12" x 12" Yellow w/Streaks VFT Mastic	400	SF	Health Center (144)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
189	12" x 12" Green w/ Streaks VFT	200	SF	Health Center (144)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
190	12" x 12" Green w/ Streaks VFT Mastic	200	SF	Health Center (144)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
191	12" x 12" Dark Gray Linoleum w/ Granite Pattern (Not Observed)	2000	SF	Main Office (131-134)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
192	12" x 12" Dark Gray Linoleum w/ Granite Pattern Mastic (Not Observed)	2000	SF	Main Office (131-134)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
193	12" x 12" Pink w/ Maroon Specks VFT	1200	SF	Room 115		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
194	12" x 12" Pink w/ Maroon Specks VFT Mastic	1200	SF	Room 115		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
195	12" x 12" Maroon w/ Pink Specks VFT	200	SF	Room 115		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
196	12" x 12" Maroon w/ Pink Specks VFT Mastic	200	SF	Room 115		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
197	12" x 12" Beige w/ Beige Specs VFT	2500	SF	Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
198	12" x 12" Beige w/ Beige Specs VFT Mastic	2500	SF	Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
199	20" x 20" Off White w/ Specks VFT	3335	SF	Rooms 339, 326, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117, 352 Vault, 3rd Floor West Toilets		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
200	20" x 20" Off White w/ Specks VFT Mastic	2800	SF	Rooms 339, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
201	20" x 20" Beige w/ Specks VFT	5000	SF	Room 225A, Library, 276, 278, 280, 326, 123A thru 117		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
202	20" x 20" Beige w/ Specks VFT Mastic	5000	SF	Room 225A, Library, 276, 278, 280, 326, 123A thru 117		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
203	20" x 20" Brown w/ Specks VFT	5000	SF	Room 225A, Library, 276, 278, 280, 123A thru 117, 326		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
204	20" x 20" Brown w/ Specks VFT Mastic	5000	SF	Room 225A, Library, 276, 278, 280, 123A thru 117		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
205	Linoleum Gray w/ Granite Pattern	2500	SF	Main Office and Associated Offices (131-134)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
206	Linoleum Gray w/ Granite Pattern Mastic	2500	SF	Main Office and Associated Offices (131-134)		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
207	Linoleum Gray w/ Black Spots	2300	SF	Rooms 151, 155		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
208	Linoleum Gray w/ Black Spots Mastic	2500	SF	Rooms 151, 155		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
209	12" x 12" Light Gray w/ Specks VFT	20000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
210	12" x 12" Light Gray w/ Specks VFT Mastic	2500	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
211	12" x 12" Dark Gray w/ Specks VFT	5000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
212	12" x 12" Dark Gray w/ Specks VFT Mastic	5000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
213	12" x 12" White w/ Red, Blue & Yellow Specks VFT	2500	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
214	12" x 12" White w/ Red, Blue & Yellow Specks VFT Mastic	2500	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
215	12" x 12" Light Gray w/ Specks VFT	10000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
216	12" x 12" Light Gray w/ Specks VFT Mastic	10000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
217	12" x 12" Dark Gray w/ Specks VFT	5000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
218	12" x 12" Dark Gray w/ Specks VFT Mastic	5000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1000	12" x 12" Orange/Brown VFT- NOT OBSERVED	24	SF	Room 180 wooden stage		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1001	12" x 12" Orange/Brown VFT Black Mastic - NOT OBSERVED	24	SF	Room 180 wooden stage		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AA	12" x 12" Green Floor Tile - NOT OBSERVED		SF	3rd floor, side corridor, East to West navy areas		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BB	Mastic associated with HA AA - NOT OBSERVED		SF	3rd floor, side corridor, East to West navy areas - NOT OBSERVED		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CC	Lab Counter Tops	3500	SF	Classrooms 100, 106, 108, 110, 302, 310, 350		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
DD	Lab Tables	2600	SF	Classrooms 110, 302, 310, 350		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Spring Six Month Survey: No Change
Comments:N/A
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
EE	Lab Fume Hoods	750	SF	Classrooms 100, 106, 350		Miscellaneous	No	None	0		☐ YES ☒ NO

2022 Fall Six Month Survey: No Change
Comments:None
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:N/A

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

A handwritten signature in black ink, appearing to read "Richard J. Schleyer", written in a cursive style.

Richard J.Schleyer

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Nicholas Senn High School

Date: 11/20/2024

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022.
Asbestos surveillances are conducted every six months.

CHECK ONE

- ☐ A copy of this notice was sent home in each child's backpack.
- ☐ A copy of this notice was printed in the school's newsletter and sent home with each child
- ☐ A copy of this notice was printed in the school's calendar and sent home with each child
- ☒ Other. WEBSITE

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.