

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2025 Fall Six Month Survey

**School:** Clara Barton Elementary School  
**Address:** 7650 S. Wolcott

**Oracle Unit:** 22151  
**Region:** 05

**Building ID:** 2170  
**Mail Room:** 43

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Panozzo, Michael  
**Survey Date:** 12/26/2025  
**Email Address:** \_\_\_\_\_

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

Each child's backpack    
 Notice printed in school's newsletter    
 Notice printed in school's calendar    
 Other | CPS website

| HA No | Material Description         | Material Quantity | Material Units | Material Location                             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04A   | 12"x12" Light Tan Floor Tile | 8120              | SF             | 1927 Building- 1st, 2nd & 3rd Floor Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description               | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 05A-1 | 12"x12" Burgundy Floor Tile ABATED |                   |                | 1927 Building- Assembly Hall |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description             | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 05B   | 12x12 Black Floor Tile<br>ABATED |                   |                | 1927 Building- Assembly Hall |               |                   |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 07A   | 9x9 Dark Green Floor Tile<br>ABATED |                   |                | 1927 Building- 2nd Floor Teachers' Lounge |               |                   |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                 | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 07B   | 9x9 Light Green Floor Tile<br>ABATED |                   |                | 1927 Building- 2nd Floor Teachers' Lounge |               |                   |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description            | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 08A   | 9 x 9 Brown w/Specks Floor Tile | 720               | SF             | 1927 Building- Room 110 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description            | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 09A   | 12 x 12 Tan Speckled Floor Tile | 7200              | SF             | 1973 Building- Lunchroom, 1st and 2nd Floor Corridors, Kitchen Storage Room, Off & Locker Room, Serving Area Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description              | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10A-2 | 12 x 12 White Speckled Floor Tile | 1450              | SF             | 1927 Building- Library |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11A-1 | 12x12 Off-White Speckled Floor Tile | 12000             | SF             | 1973 Building- Throughout All Classrooms |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                      | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16A   | 9"x9" Dark Green Floor Tile Mastic ABATED |                   |                | 1927 Building- 2nd Floor Teachers' Lounge |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No  | Material Description       | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|--------|----------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16A(2) | 9x9 Pink Floor Tile Mastic | 720               | SF             | 1927 Building- Room 110 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                  | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16A-1 | 9x9 Brown Floor Tile w/Streaks Mastic | 1100              | SF             | 1927 Building- Room 101 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                       | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16B   | 9 x 9 Light Green Floor Tile Mastic ABATED |                   |                | 1927 Building- 2nd Floor Teachers' Lounge |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description              | Material Quantity | Material Units | Material Location                             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17A   | 12x12 Light Tan Floor Tile Mastic | 8120              | SF             | 1927 Building- 1st, 2nd & 3rd Floor Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                    | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17A-1 | 12x12 Burgundy Floor Tile Mastic ABATED |                   |                | 1927 Building- Assembly Hall |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                   | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17A-2 | 12x12 White Speckled Floor Tile Mastic | 1450              | SF             | 1927 Building- Library |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                 | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17B   | 12x12 Black Floor Tile Mastic ABATED |                   |                | 1927 Building- Assembly Hall |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                 | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18A   | 12x12 Tan Speckled Floor Tile Mastic | 7200              | SF             | 1973 Building- 1st, 2nd & 3rd Floor Corridor, Lunchroom, Kitchen Storage Room and Office, Locker Room, Serving Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description          | Material Quantity | Material Units | Material Location                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18A-1 | Off-White Speckled Floor Tile | 12000             | SF             | 1973 Building-Throughout All Classrooms |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description           | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19A-1 | 9x9 Brown Floor Tile w/Streaks | 1100              | SF             | 1927 Building- Room 101 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                            | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20    | 12x12 Gray w/Blue Spots Floor Tile NOT OBSERVED | 750               | SF             | Room 202          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                                   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21    | 12x12 Gray w/Blue Spots Floor Tile Mastic NOT OBSERVED | 750               | SF             | Room 202          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22A   | 9x9 Beige & Orange Combination Floor tile | 500               | SF             | Engineer's Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                             | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22B   | 9x9 Beige & Orange Combination Floor Tile Mastic | 500               | SF             | Engineer's Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23    | Maroon Terrazzo      | 8000              | SF             | Stairways, Corridor Perimeters |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description            | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24    | Red Sheet Flooring NOT OBSERVED | 200               | SF             | Engineer's Office & Custodial Storage Room (Under Carpet) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                      | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24A   | Red Sheet Flooring Mastic<br>NOT OBSERVED | 200               | SF             | Engineer's Office &<br>Custodial Storage Room<br>(Under Carpet) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description     | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| A     | Boiler Insulation ABATED |                   |                | 1927 Building- Boiler<br>Room |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| AA    | 2'x4' Ceiling Tile   | 19000             | SF             | Throughout 1973 Building |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description    | Material Quantity | Material Units | Material Location                              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B     | Aircell Pipe Insulation | 250               | LF             | Tunnels, Boiler Room,<br>and Unexcavated Areas |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| BB-1  | Gray Baseboard       | 62                | LF             | 1927 Building- Room 208 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| BB-2  | Black Baseboard      | 1750              | LF             | 1973 Building- Throughout School |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description  | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| BBM-1 | Gray Baseboard Mastic | 62                | LF             | 1927 Building- Room 208 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description   | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| BBM-2 | Black Baseboard Mastic | 1750              | LF             | 1973 Building- Throughout School |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C     | Aircell Duct Wrap ABATED |                   |                | Unexcavated Area  |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| CM-1  | Rose Carpet Mastic   | 2000              | SF             | 1927 Building- Room 102, Adjustment Office, Principal's Office, and Main Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description             | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| CM-2  | Green Carpet Mastic NOT OBSERVED | 810               | SF             | 1927 Building- Assembly Hall |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description              | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| CM-3  | Purple Carpet Mastic NOT OBSERVED | 720               | SF             | 1927 Building- Room 208 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description            | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| CM-4  | Rose Carpet Mastic NOT OBSERVED | 285               | SF             | 1973 Building- Teachers' Lounge |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description      | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D     | Cardboard Pipe Insulation | 250               | LF             | Boiler Room and Engineering Rooms |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| H     | Aircell Fittings     | 50                | LF             | Engineering Rooms |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| I     | Cardboard Fittings   | 50                | FITTING        | Engineering Rooms |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description             | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| J     | 12"x12" Brown Ceramic Tile Grout | 200               | SF             | 2nd Floor Boys' Washroom |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description     | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| K     | Walls & Floor Tile Grout | 400               | SF             | 1st Floor Boys' Washroom |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description     | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| L     | Walls & Floor Tile Grout | 400               | SF             | 1st Floor Girls' Washroom |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description        | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| NEW   | Newly Installed Suspect ACM |                   |                | Installed After Implementation of Management Plan and After Renovations |               | Miscellaneous     |         | Unknown     | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

*Richard J. Schleyer*

---

Richard J.Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Clara Barton Elementary School

Date: 12/26/2025

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other. CPS website
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**