

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2025 Fall Six Month Survey

**School:** Christian Ebinger Elementary School  
**Address:** 7350 W Pratt Avenue

**Oracle Unit:** 23051  
**Region:** 01

**Building ID:** 3150  
**Mail Room:** 30

**Asbestos Surveyor:** Gorder, Erik  
**Survey Date:** 12/26/2025  
**Email Address:** egorder@cps.edu

**CHECK HERE IF NO CHANGE TO ASBESTOS**

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

Each child's backpack    
 Notice printed in school's newsletter    
 Notice printed in school's calendar    
 Other | Posted on CPS website

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2A	12"x12" White w/ Beige Streaks VFT			Kitchen Under Existing VFT (Room 100), Lunchroom (Room 101 & 103)		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments: Abated 2019

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2B	12"x12" Gray w/ Beige Streaks VFT			Kitchen Under Existing VFT (Room 100), Lunchroom (Room 101 & 103)		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments: Abated 2019

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2C	12"x12" White VFT	600	SF	Faculty Lounge (1st floor)		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2D	12"x12" Tan w/ White Spots VFT			Kitchen (Room 100)		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments: Abated 2019

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2E	12"x12" White w/ Gray Streaks VFT	7500	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3A	12"x12" White w/ Beige Streaks VFT Mastic			Kitchen Under Existing VFT (Room 100), Lunchroom (Room 101 & 103)		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments: Abated 2019

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3B	12"x12" Gray w/ Beige Streaks VFT Mastic			Kitchen Under Existing VFT (Room 100), Lunchroom (Room 101 & 103)		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments: Abated 2019

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3C	12"x12" White VFT Mastic	600	SF	Faculty Lounge		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3D	12"x12" Tan w/ White Spots VFT Mastic			Kitchen (Room 100)		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments: Abated 2019

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3E	12"x12" White w/ Gray Streaks VFT Mastic	7500	SF	1st & 2nd Floor Corridors		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	Exterior Caulk			Exterior Windows							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Interior Caulk			Interior Windows							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	Terrazzo Flooring	5000	SF	All Stairwells, 2nd Floor Corridors Around Boarders, 1st Floor Corridors Around Boarders, Stage Stairs, Assembly Hall Stairs and Vestibule, Room 200		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	Textured Plaster	2000	SF	Stage Walls		Surface	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	Carpet Mastic - Removed 12/2010			Assembly Hall - Removed 12/2010		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	12"X12" White w/Specks VFT (not on-site)	5000	SF	Throughout Mobile Units A and B, Except Boys and Girls Toilets		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Mobiles removed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9A	12"X12" White w/Specks VFT Mastic (not on-site)	5000	SF	Throughout Mobile Units A and B, Except Boys and Girls Toilets		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Mobiles removed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	2'X2' White Ceiling Tiles	5000	SF	Throughout Mobile Units A and B (no longer on site)		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Mobiles removed

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Linoleum Flooring	400	SF	Boys and Girls Toilets, Mobile Unit B (no longer on site)		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Mobiles removed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11A	Linoleum Flooring Mastic	400	SF	Boys and Girls Toilets, Mobile Unit B (no longer on site)		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Mobiles removed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Pink Linoleum Flooring	200	SF	Womens Toilet, Mobile Unit A (no longer on site)		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Mobiles removed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12A	Pink Linoleum Flooring Mastic	200	SF	Womens Toilet, Mobile Unit A (no longer on site)		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Mobiles removed

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Blue Linoleum Flooring	200	SF	Men's Toilet, Mobile Unit A (no longer on site)		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Mobiles removed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13A	Blue Linoleum Flooring Mastic	200	SF	Men's Toilet, Mobile Unit A (no longer on site)		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Mobiles removed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Drywall and Joint Compound	5000	SF	Throughout Mobile Units A and B (no longer on site)		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Mobiles removed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Dark Blue VFT	600	SF	Assembly Hall		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Dark Blue VFT Mastic	600	SF	Assembly Hall		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Light blue w/white, red and blue speckles VFT	600	SF	Assembly Hall		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Light blue w/white, red and blue speckles Mastic	600	SF	Assembly Hall		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Blue w/black and white speckles VFT	24	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12"x12" Blue w/black and white speckles Mastic	24	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" Sand VFT	24	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Sand Mastic	24	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Tan VFT	25	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Tan Mastic	25	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" White w/ gray speckles VFT	24	SF	Engineer's Office Toilet		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" White w/gray speckles Mastic	24	SF	Engineer's Office Toilet		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Gray w/black and white streaks VFT	12	SF	Engineer's Office Toilet		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Gray w/black and white streaks Mastic	12	SF	Engineer's Office Toilet		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Blown-In Insulation on Duct Work	2500	SF	Attic		Surface	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12 x 12 white w/ gray specks vft	1	SF	2nd floor corridor near 204		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12 x 12 white w/ gray specks vft Mastic	1	SF	2nd floor corridor near 204		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Mag Block Tank Insulation (Two)	250	SF	Boiler Room - Abated in 2015		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	Mag Block Condensation Tank Insulation	125	SF	Boiler Room - Abated in 2015		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Aircell Pipe Insulation (Abated 2018)			Unex. Spaces, Boiler Rm, & Boiler Tunnel, Basement NE and NW Corner Spaces, Basement S. Center Hall		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Abated 2018

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Aircell Pipe Insulation (Abated 2018)			Unex. Spaces, Boiler Rm, & Boiler Tunnel, Basement NE and NW Corner Spaces, Basement S. Center Hall		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Abated 2018

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Aircell Duct Wrap Insulation	600	SF	East and Main Unexcavated Crawl Space		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
H	Cardboard Pipe Insulation (Abated 2018)			Boiler Rm. & Boiler Tunnel, Basement NE and NW Corner Spaces, Basement S. Center Hall		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Abated 2018

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	MJP E/F/V on Cardboard Pipe Insulation (Abated 2018)			Boiler Rm. & Boiler Tunnel, Basement NE and NW Corner Spaces, Basement S. Center Hall		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Abated 2018

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Mag Pipe Insulation (Abated 2018)			Basement S. Center Hall, Boiler Room & Tunnel, NE & NW Corners Of Basement		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:Abated 2018

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	MJP E/F/V on Mag Pipe Insulation (Abated 2018)			Basement S. Center Hall, Boiler Room & Tunnel, NE & NW Corners Of Basement		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments: Abated 2018

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	MJP E/F/V on Fiberglass Pipe Insulation			Throughout		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

*Richard J. Schleyer*

---

Richard J.Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Christian Ebinger Elementary School  
Date: 12/26/2025

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other. Posted on CPS website
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.