

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2025 Fall Six Month Survey

**School:** Richard Edwards Elementary School  
**Address:** 4950 LaPorte

**Oracle Unit:** 23081  
**Region:** 04

**Building ID:** 6221  
**Mail Room:** 44

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Pacewic, James  
**Survey Date:** 12/26/2025  
**Email Address:** jepacewic@cps.edu

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

Each child's backpack    
 Notice printed in school's newsletter    
 Notice printed in school's calendar    
 Other | CPS Website

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03A	9" x 9" Tan Floor Tile	10400	SF	Gym, Main Office, Principal Office, Teachers' Bathroom, Rooms 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 501, Teacher's Lounge, 503, Unisex Bathroom, Janitor's Closet, 504, 505, 506, 507, 509, 508		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03B	9" x 9" Brown Floor Tile	409	SF	Hallway		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03C	9" x 9" Light Brown Floor Tile	1000	SF	Hallway, Main Office, Gymnasium		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	4' x 8' Transite Board					Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05A	9" x 9" Tan Floor Tile Mastic	10400	SF	Gym, Main Office, Principal Office, Teachers' Bathroom, Rooms 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 501, Teacher's Lounge, 503, Unisex Bathroom, Janitor's Closet, 504, 505, 506, 507, 509, 508		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05B	9" x 9" Brown Floor Tile Mastic	409	SF	Hallway		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05C	9" x 9" Light Brown Floor Tile Mastic	1000	SF	Hallway, Main Office, Gymnasium		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	Black Vinyl Baseboard Mastic			Office, Room 606, 601, 602, 605, 610		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	Black Vinyl Baseboard			Office, Room 606, 601, 607, 608, 610		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	1' x 1' Ceiling Tile Mastic			Throughout Building		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Interior Window Glazing			Throughout Building		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Interior Window Caulk			ABATED		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	2' x 4' Ceiling Tile w/ Fake 2' x 2' Pattern			Corridor, Classrooms, Offices		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Fire Proofing - Installed 2005	170	SF	Breezeway & Electrical Switchgear Rooms		Miscellaneous	Yes	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12" x 12" Blue Mottle Floor Tile			Engineer's Office and Bathroom		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12" x 12" Blue Mottle Floor Tile Mastic			Engineer's Office & Bathroom		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Sink Insulation			Rooms 601, 604, 605, 606, 607, 608, 609 Room 128, 130,		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Insulated Firedoors			Boiler Room, Gym		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Vault Door			Office		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12" x 12" Gray w/ Black Specks Vinyl Floor Tile			Throughout Annex - No Longer Cps Owned		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18A	12" x 12" Gray w/ Black Specks Vinyl Floor Tile Mastic			Throughout Annex - No Longer Cps Owned		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12" x 12" Blue w/ Black Specks Vinyl Floor Tile			Throughout Annex - No Longer Cps Owned		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19A	12" x 12" Blue w/ Black Specks Vinyl Floor Tile Mastic			Throughout Annex - No Longer Cps Owned		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12" x 12" Peach w/ Black Specks Vinyl Floor Tile			Throughout Annex - No Longer Cps Owned		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20A	12" x 12" Peach w/ Black Specks Vinyl Floor Tile Mastic			Throughout Annex - No Longer Cps Owned		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12" x 12" Beige w/ Black Specks Floor Tile			Throughout Annex - No Longer Cps Owned		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21A	12" x 12" Beige w/ Black Specks Floor Tile Mastic			Throughout Annex - No Longer Cps Owned		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12" x 12" Green w/ Black Specks Vinyl Floor Tile			Throughout Annex - No Longer Cps Owned		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22A	12" x 12" Green w/ Black Specks Vinyl Floor Tile Mastic			Throughout Annex - No Longer Cps Owned		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Gray Vinyl Baseboard	10000	SF	2nd Floor Hallway, 225 Storage, 226, 228, Storage 127, 128, 130, 230, 232, 234, 236, 237, 239, 241, 243, 245, 247, 249, 3rd Floor Hallway, 319, 325, 326, 328, 330, 332, 334, 336, 337, 339, 341, 338, 343, 345, Lunchroom		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23A	Gray Vinyl Baseboard Mastic	10000	SF	2nd Floor Hallway, 225 Storage, 226, 228, Storage 127, 128, 130, 230, 232, 234, 236, 237, 239, 241, 243, 245, 247, 249, 3rd Floor Hallway, 319, 325, 326, 328, 330, 332, 334, 336, 337, 339, 341, 338, 343, 345, Lunchroom		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	2' x 4' Ceiling Tile			DUPLICATE HA		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12" x 12" Beige Mottled Vinyl Floor Tile	50	SF	Rooms 505, 506, 507		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12" x 12" Beige Mottled Vinyl Floor Tile Mastic	50	SF	Rooms 505, 506, 507		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Drywall	2000	SF	Main Office, Rooms 501, 503, 504, 505, 506, 507, 508, 509		Miscellaneous	Yes	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Joint Compound	2000	SF	Main Office, Rooms 501, 503, 504, 505, 506, 507, 508, 509		Surface	Yes	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	4" Beige Vinyl Baseboard	30	LF	Room 507		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	4" Beige Vinyl Baseboard Adhesive	30	SF	Room 507		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Gray Sink Undercoating	2	SF	Teacher's Lounge		Surface	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	1' x 1' Fissured Ceiling Tile	100	SF	Principal's Office		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	2' x 4' Tectum Ceiling Tile	1500	SF	Gymnasium		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Red Fireproofing Caulk	5	LF	South Kitchen, Gymnasium		Surface	Yes	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Aircell Pipe Insulation			ABATED		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	Aircell Pipe Joints			ABATED		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Fiberglass Pipe Joints			ABATED		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Water Meter Packing			ABATED		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

*Richard J. Schleyer*

---

Richard J.Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Richard Edwards Elementary School  
Date: 8/1/2025

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other. CPS Website
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.