

Chicago Public Schools

6 Month Asbestos Surveillance

2025 Fall Six Month Survey

School: Donald Morrill Math & Science Elementary School
Address: 6011 Rockwell

Oracle Unit: 24571
Region: 05

Building ID: 4880
Mail Room: 43

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: Quinn, Kevin
Survey Date: 2/12/2026
Email Address: _____

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:
 Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 02 | 12"x12" Peach and Cream Floor Tile | 2400 | SF | 3rd Floor Corridor | | Miscellaneous | No | Dist | 30 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 03 | Dark Green Linoleum ABATED | | | Room 106, Old Library | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 06 | Decorative Plaster | 5000 | SF | Auditorium | | Surface | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 7 | Packing Material Around Pumps | 25 | SF | Tunnels | | TSI | Yes | None | 0 | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

2025 Fall Six Month Survey: Other
Comments:more specific

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10 | Aircell Debris | 200 | LF | Unexcavated Tunnel Area | | TSI | Yes | Loc | 1 | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

2025 Fall Six Month Survey: Other
Comments:more specific

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11 | 9x9 Brown & Tan Floor Tile Mastic ABATED | | | 1st & 2nd Floor Corridors | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12 | 12"x12" Peach & Cream Floor Tile Mastic | 2400 | SF | 3rd Floor Corridor | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13 | Linoleum Mastic ABATED | | | Room 106- Old Library | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14 | 2'x4' Acoustic Ceiling Tile | 40000 | SF | 1st, 2nd & 3rd Floor Classrooms and Corridors | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15 | Wall Accents Acoustic Tile | 500 | SF | Auditorium | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16 | 12"x12" Tan/Cream Vinyl Floor Tile | 1500 | SF | Rooms 106, 111, and 201 | | Miscellaneous | No | Dist | 20 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17 | 12"x12" Tan/Cream Vinyl Floor Tile Mastic | 1500 | SF | Rooms 101, 106, 201 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18 | White Boiler Gasket | 50 | SF | Boiler Room (On Boiler) | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19 | Foilwrap Over Duct Insulation | 500 | LF | Boiler Room - Boiler Duct Work | | TSI | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20 | Purple Carpet Mastic NOT OBSERVED | 1500 | SF | Main Office, Storage, Room 107 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21 | 12"x12" Blue on Blue Floor Tile | 1900 | SF | Cafeteria Lunchroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21M | 12x12 Blue on Blue Floor Tile Mastic | 1900 | SF | Cafeteria, Lunchroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22 | 12x12 Off-White w/Specks Floor Tile | 320 | SF | Kitchen Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22M | 12x12 Off-White w/Specks Floor Tile Mastic | 320 | SF | Kitchen Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23 | 12x12 Red w/Red Streaks Floor Tile | 450 | SF | Room 117 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23M | 12x12 Red w/Red Streaks Floor Tile Mastic | 450 | SF | Room 117 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24 | 12"x12" Green w/Green Specks Floor Tile | 450 | SF | Room 116 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24M | 12"x12" Green w/Green Specks Floor Tile Mastic | 450 | SF | Room 116 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25 | 12"x12" White w/Blue and Gray Floor Tile | 5050 | SF | 1st Floor Hall, Room 119, 2nd Floor Hall & Room 220 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25M | 12"x12" White w/Blue and Gray Floor Tile Mastic | 5050 | SF | 1st Floor Hall, Room 119, 2nd Floor Hall & Room 220 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26 | Carpet Mastic NOT OBSERVED | 1500 | SF | Library | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27 | Baseboard Mastic | 980 | SF | Rooms 116, 117, 119, 2nd Floor, Kitchen, Lunchroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28 | 2'x4' Pinhole Ceiling Tile | 2100 | SF | Floor Room and 1st & 2nd | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29 | Drywall | 12500 | SF | Annex- 1st & 2nd Floor | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30 | 2'x4' Textured Ceiling Tile | 4000 | SF | Annex (S)- 1st & 2nd Floor | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31 | 12"x12" Black Floor Tile | 40 | SF | Elevator | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31A | 12"x12" Black Floor Tile Mastic | 40 | SF | Elevator | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32 | 12"x12" White w/Blue, Pink & Yellow Specks Floor Tile | 1800 | SF | Rooms 103, 216 & 219 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32A | 12"x12" White w/Blue, Pink & Yellow Specks Floor Tile Mastic | 1800 | SF | Rooms 103, 216 & 219 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33 | 12"x12" Grey w/Specks Floor Tile | 1800 | SF | Main Office, Principal's Office & Room 217 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33A | 12"x12" Grey w/Specks Floor Tile Mastic | 1800 | SF | Main Office, Principal's Office & Room 217 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34 | 12"x12" Purple w/Specks Floor Tile | 1200 | SF | Rooms 214 & 214B | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34A | 12"x12" Purple w/Specks Floor Tile Mastic | 1200 | SF | Rooms 214 & 214B | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35 | 2'x4' Smooth Ceiling Tile | 1500 | SF | Server Line 118A, Servery 118B, Office 118C, Toilet 118D | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36 | 2"x2" Ceramic Tile Grout | 600 | SF | 3rd Floor Boys' & Girls' Washrooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37 | 12"x12" White & 9"x9" Ceramic Tile Grout | 3800 | SF | Open Area near Door 11 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38 | Blackboards | 1200 | SF | Throughout Main Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39 | Blue Stage Curtains | 2000 | SF | Assembly Hall Stage & Windows | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| AA | 12"x12" White w/Tan Floor Tile | 6000 | SF | 1st and 2nd Floor Corridors and Room 103 | | TSI | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| AA1 | 12"x12" White w/Tan Floor Tile Mastic | 6000 | SF | 1st and 2nd Floor Corridors and Room 103 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C | Air Cell ABATED | | | Tunnel | | TSI | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D | Aircell Pipe Joint Insulation ABATED | | | Tunnels | | TSI | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E | Cardboard Insulation | 500 | LF | Boiler Room | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| F | Cardboard Joint Compound | 40 | SF | Boiler Room, Unexcavated Tunnel | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FT-1 | 12"x12" White w/Blue Pink & Yellow Flecks Floor Tile | 1900 | SF | Rooms 101, 214, 214B | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FT-2 | 12"x12" White w/Blue, Pink & Yellow Specks Floor Tile | 750 | SF | Room 103 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FT-3 | 12"x12" Black w/White Flecks Floor Tile NOT OBSERVED | | | 1st Floor Hall- Patch | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FT-4 | 9"x9" Green & Cream Floor Tile (Covered with Carpet) NOT OBSERVED | 300 | SF | Principal's Office and Storage | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FT-5 | 9"x20" Black Terrazzo | 1000 | SF | 1st & 2nd Floor Halls Border | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FT-6 | 12"x12" Cream w/Tan Floor Tile | 750 | SF | Room 106, 111 & 201 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FT-7 | 12"x12" Grey w/Specks Floor Tile | 300 | SF | Gym Office | | Miscellaneous | No | | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FT-8 | 12"x12" White w/Dark Streaks Floor Tile | 2000 | SF | Library | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTM-1 | 12x12 White w/Blue, Pink & Yellow Flecks Floor Tile Mastic | 1900 | SF | Rooms 101, 214, 214B | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTM-2 | 12"x12" White w/Blue, Pink & Yellow Specks Floor Tile Mastic | 750 | SF | Room 103, Main Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTM-3 | 12"x12" Black w/White Flecks Floor Tile Mastic NOT OBSERVED | | | 1st Floor Hall- Patch | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTM-4 | 9x9 Green & Cream Floor Tile Mastic (Covered with Carpet) | 300 | SF | Principal's Office, Storage | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTM-5 | 9"x20" Black Flooring Mastic | 1000 | SF | 1st & 2nd Floor Halls | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTM-6 | 12"x12" Cream w/Tan Floor Tile Mastic | 1800 | SF | Room 106, 111 & 201 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTM-7 | 12"x12" Grey w/Specks Floor Tile Mastic | 300 | SF | Gym Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTM-8 | 12"x12" White w/Dark Streaks Floor Mastic | 2000 | SF | Library | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G | Mag Block-Boiler ABATED | | | Boiler Room | | TSI | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| I | 9"x9" Brown & Tan Floor Tile ABATED | | | 1st & 2nd floor corridors | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| J | Cementious Mud on Valves | 10 | LF | (N) Base Fan Room | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| K | Aircell Pipe Insulation | 350 | LF | (W) Tunnel Unexcavated | | TSI | Yes | Dist | 10 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| NEW | Newly Installed Suspect ACM | | | Installed After Implementation of Management Plan and After Renovations | | Miscellaneous | | Unknown | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

Richard J. Schleyer

Richard J.Schleyer

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Donald Morrill Math & Science Elementary School
Date: 2/12/2026

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.