

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2025 Fall Six Month Survey

**School:** Spencer Technology Academy  
**Address:** 214 N. Lavergne

**Oracle Unit:** 25441  
**Region:** 03

**Building ID:** 6000  
**Mail Room:** 36

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Valdez, Ontonio  
**Survey Date:** 2/11/2026  
**Email Address:** ovaldez11@cps.edu

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 Each child's backpack   
 Notice printed in school's newsletter   
 Notice printed in school's calendar   
 Other

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Hard Coat Plaster			1903 BUILDING - MAIN Throughout 1970 BUILDING - ANNEX 1970 Building - Room 415		Surface					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2	1' x 1' Ceiling Tile			1967 BUILDING - ADDITION Lunchroom		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	Acoustical Sprayed on Plaster	8000	SF	1903 BUILDING - MAIN 1st, 2nd, and 3rd Floor Corridors  1926 NORTH AND SOUTH BUILDINGS - ADDITION 1st, 2nd, and 3rd Floor Corridors  1967 BUILDING - ADDITION 1st (Basement Level), 2nd, and 3rd Floor Corridors, Rooms 010 and 012		Surface	Yes	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	2' x 4' Ceiling Tile			1970 BUILDING - ANNEX Throughout		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	2' x 4' Fissured Ceiling Tile			1926 NORTH AND SOUTH BUILDINGS - ADDITION Kindergarten		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6A	12" x 12" Tan Floor Tile	15000	SF	1903 BUILDING - MAIN Classrooms, Stairwells 1926 NORTH AND SOUTH BUILDINGS - ADDITION Classrooms, Stairwells		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7A	12" x 12" Beige Floor Tile			1970 BUILDING - ANNEX Room 415		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
 Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7B	12" x 12" Tan Floor Tile			1970 BUILDING - ANNEX Rooms 412, 413, 415		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
 Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7C	12" x 12" Brown Floor Tile	1000	SF	1970 BUILDING - ANNEX Lunchroom 1967 BUILDING - ADDITION 209A Univent Area		Miscellaneous	No	None			<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
 Comments:demolished

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7D	12" x 12" Cream Floor Tile			1970 BUILDING - ANNEX Rooms 401 and 403		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7E	12" x 12" White Floor Tile	3000	SF	1970 BUILDING - ANNEX Corridors, Rooms 418, 419		Miscellaneous	No	Dist	200	SF	<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8A	9" x 9" Dark Green Floor Tile			ABATED		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8B	9" x 9" Light Green Floor Tile			ABATED		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8C	9" x 9" Tan Floor Tile	1500	SF	1903 BUILDING - MAIN Room 99, 1st Floor Rest Area, 3rd Floor Areas, 108B Janitors Closet, 1st Floor Classrooms		Miscellaneous	No	Loc	60	SF	<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9A	12" x 12" Tan Floor Tile Mastic	15000	SF	1903 BUILDING - MAIN Classrooms, Stairwells 1926 NORTH AND SOUTH BUILDINGS - ADDITION Classrooms, Stairwells		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10A	9" x 9" Dark Green Floor Tile Mastic			ABATED		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10B	9" x 9" Light Green Floor Tile Mastic			ABATED		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10C	9" x 9" Tan Floor Tile Mastic	1200	SF	1903 BUILDING - MAIN Room 99, 1st Floor Rest Area, 3rd Floor Areas, 1st Floor Classrooms		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Hardcoat Plaster			1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout		Surface					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13A	12" x 12" Beige Floor Tile Mastic	1100	SF	1970 BUILDING - ANNEX Room 415		Miscellaneous	No	None			<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13B	12" x 12" Tan Floor Tile Mastic			1970 BUILDING - ANNEX Rooms 412, 413, 415		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
Comments:demolished

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13C	12" x 12" Brown Floor Tile Mastic			1970 BUILDING - ANNEX Room 405		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13D	12" x 12" Cream Floor Tile Mastic			1970 BUILDING - ANNEX Rooms 401 and 403		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13E	12" x 12" White Floor Tile Mastic	3000	SF	1970 BUILDING - ANNEX Corridors, Rooms 418, 419		Miscellaneous	No	None			<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14A	9" x 9" Black and Red Floor Tile & Mastic	150	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Corridors		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15A	9" x 9" Olive Floor Tile Mastic	1200	SF	1967 BUILDING - ADDITION Room 210, Office Corridor, Various Rooms		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15B	9" x 9" Black Floor Tile Mastic	5000	SF	1967 BUILDING - ADDITION Corridors		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15D	9" x 9" Tan Floor Tile Mastic	7000	SF	1967 BUILDING - ADDITION Room 209		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15E	9" x 9" Gray Floor Tile Mastic			ABATED		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15F	9" x 9" Peach Floor Tile Mastic	5000	SF	1967 BUILDING - ADDITION Room 212		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15G	9" x 9" Cream Floor Tile	1000	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout 1967 BUILDING - ADDITION Various Rooms, 209A		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16A	9" x 9" Black Floor Tile	200	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION 3rd Floor Corridor		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16B	9" x 9" Brown Floor Tile	200	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION 3rd Floor Corridor		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17A	9" x 9" Olive Floor Tile	1200	SF	1967 BUILDING - ADDITION Room 210, Office Corridor, Various Rooms		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17B	9" x 9" Black Floor Tile	5000	SF	1967 BUILDING - ADDITION Corridors		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17C	12" x 12" White Floor Tile	10000	SF	1967 BUILDING - ADDITION Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17D	9" x 9" Tan Floor Tile	7000	SF	1967 BUILDING - ADDITION Room 209		Miscellaneous	No	Loc	8	SF	<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17E	9" x 9" Gray Floor Tile			ABATED		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17F	9" x 9" Peach Floor Tile	5000	SF	1967 BUILDING - ADDITION Room 212		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17G	9" x 9" Cream Floor Tile Mastic	1200	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout 1967 BUILDING - ADDITION Various Rooms, 209A		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Hardcoat Plaster			1967 BUILDING - ADDITION Throughout		Surface					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Drywall			1926 NORTH AND SOUTH BUILDINGS - ADDITION 3rd Floor Classroom		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Drywall			1970 BUILDING - ANNEX Throughout		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Drywall Tape and Joint Compound			1926 NORTH AND SOUTH BUILDINGS - ADDITION 3rd Floor		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9" x 9" Black Asphalt Tile	3000	SF	1903 BUILDING - MAIN 1st Floor Corridor		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	9" x 9" Black Asphaltight Tile Mastic	3000	SF	1903 BUILDING - MAIN 1st Floor Corridor		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	9" x 9" Brown Asphaltight Floor Tile	3300	SF	1967 BUILDING - ADDITION Corridors		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	9" x 9" Red Asphaltight Floor Tile	3600	SF	1967 BUILDING - ADDITION Corridors		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	9" x 9" Red & Brown Asphaltight Floor Tile Mastic	6900	SF	1967 BUILDING - ADDITION Corridors		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Carpet Adhesive			1970 BUILDING - ANNEX Throughout		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
 Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Cove Base			1970 BUILDING - ANNEX Throughout		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
 Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Cove Base Mastic			1970 BUILDING - ANNEX Throughout		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
 Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Interior Window Caulk			1967 BUILDING - ADDITION Interior Windows		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Exterior Window Glazing - Non-AHERA			1967 BUILDING - ADDITION Exterior Windows		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Exterior Window Glazing - Non-AHERA			1926 NORTH AND SOUTH BUILDINGS - ADDITION Exterior Windows		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Canvas Wall Paper	20	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Exterior Window Caulk - Non-AHERA			1967 BUILDING - ADDITION Exterior Windows		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Exterior Window Caulk - Non-AHERA			1926 NORTH AND SOUTH BUILDINGS - ADDITION Exterior Windows		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Exterior Window Caulk - Non-AHERA			1903 BUILDING - MAIN Exterior Windows		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Exterior Window Glazing - Non-AHERA			1903 BUILDING - MAIN Exterior Windows		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44A	Interior Window Glazing	10	LF	1903 BUILDING - MAIN Engineer's Office		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Interior Window Glazing	500	LF	1967 BUILDING - ADDITION Interior Windows		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Interior Window Glazing	500	LF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Interior Windows		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Interior Window Glazing			1970 BUILDING - ANNEX Interior Windows		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Exterior Window Glazing - Non-AHERA			1970 BUILDING - ANNEX Exterior Windows		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
Comments:demolished

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Cove Base			1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Cove Base Mastic			1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Ceramic Tile			1970 BUILDING - ANNEX Throughout		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other
Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Ceramic Tile Mastic			1970 BUILDING - ANNEX Throughout		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other
Comments:demolished

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Grout			1970 BUILDING - ANNEX Throughout		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Cinderblock			1903 BUILDING - MAIN Throughout		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Cinderblock Mortar			1903 BUILDING - MAIN Throughout		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	Cinderblock			1967 BUILDING - ADDITION Throughout		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	Cinderblock Mortar			1967 BUILDING - ADDITION Throughout		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	White Glazed Ceramic Block	5000	SF	1967 BUILDING - ADDITION Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Ceramic Block Mortar	5000	SF	1967 BUILDING - ADDITION Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	Blue Glazed Ceramic Block	5000	SF	1967 BUILDING - ADDITION Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Ceramic Block Mortar	5000	SF	1967 BUILDING - ADDITION Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Green Glazed Ceramic Block	500	SF	1903 BUILDING - MAIN Bathrooms		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Ceramic Block Mortar	500	SF	1903 BUILDING - MAIN Bathrooms		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	Interior Glazed Brick	2000	SF	1903 BUILDING - MAIN Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	Interior Glazed Brick Mortar	2000	SF	1903 BUILDING - MAIN Throughout		Surface	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	Interior Glazed Brick	200	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Gym		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	Interior Brick Mortar	200	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Gym		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	Acoustical Ceiling Tile Glue Patches			MATERIAL REMOVED		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	Brown Ceramic Floor Tile Mastic	1000	SF	1967 BUILDING - ADDITION Kitchen		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	Brown Ceramic Tile Grout	1000	SF	1967 BUILDING - ADDITION Kitchen		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	Brown Ceramic Tile	1000	SF	1967 BUILDING - ADDITION Kitchen		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
94	Yellow and Brown Ceramic Tile Mastic	400	SF	1903 BUILDING - MAIN Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	Yellow & Brown Ceramic Floor Tile Grout	400	SF	1903 BUILDING - MAIN Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
96	Yellow and Brown Ceramic Floor Tile	400	SF	1903 BUILDING - MAIN Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	Blue Ceramic Floor Tile	3000	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Bathrooms		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
98	Blue Ceramic Floor Tile Grout	3000	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Bathrooms		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	Blue Ceramic Floor Tile Mastic	3000	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Bathrooms		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	White Ceramic Floor Tile	1000	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	White Ceramic Floor Tile Mastic	1000	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	White Ceramic Tile Grout	1000	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Various Rooms		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	Glue Pads	1500	SF	1967 BUILDING - ADDITION Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	Fire Doors	10		1903 BUILDING - MAIN Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	Fire Doors	15		1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	Fire Doors	15		1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	Fire Doors			1970 BUILDING - ANNEX Throughout		Miscellaneous					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	9" x 9" White Floor Tile & Mastic	7600	SF	1967 BUILDING - ADDITION Room 212		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	12" x 12" White Floor Tile	5000	SF	1903 BUILDING - MAIN Room 104 (Main Office) 1970 BUILDING - ANNEX Corridors, Room 409 1967 BUILDING - ADDITION Room 010		Miscellaneous	No	Dist	10	SF	<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	12" x 12" White Floor Tile Mastic	5000	SF	1903 BUILDING - MAIN Room 104 (Main Office) 1970 BUILDING - ANNEX Corridors, Room 409 1967 BUILDING - ADDITION Room 010		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	6" x 6" Black and White Check Linoleum	40	SF	1903 BUILDING - MAIN Engineer's Office		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114	6" x 6" Black and White Check Linoleum Mastic	40	SF	1903 BUILDING - MAIN Engineer's Office		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
115	12" x 12" White w/ Brown & Gray Floor Tile	700	SF	1903 BUILDING - MAIN Room 104, 101, 104A, 104 (Main Office), Ground Floor Pre-K Classroom		Miscellaneous	No	Loc	20	SF	<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116	12" x 12" White w/ Brown & Gray Floor Tile Mastic	700	SF	1903 BUILDING - MAIN Room 104, 101, 104A, 104 (Main Office), Ground Floor Pre-K Classroom		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
117	Black & White Terrazzo Flooring	4000	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout 1967 BUILDING - ADDITION Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
118	12" x 12" Gray w/ White Specks Floor Tile	2500	SF	1903 BUILDING - MAIN 1st Floor Corridor 1926 NORTH AND SOUTH BUILDINGS - ADDITION 1st Floor Corridor, Room 206 1967 BUILDING - ADDITION 1st Floor (Basement Level) Corridor, Room 009		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
118M	12" x 12" Gray w/ White Specks Floor Tile Mastic	2500	SF	1903 BUILDING - MAIN 1st Floor Corridor  1926 NORTH AND SOUTH BUILDINGS - ADDITION 1st Floor Corridor, Room 206  1967 BUILDING - ADDITION 1st Floor (Basement Level) Corridor, Room 009		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
119	12" x 12" Blue w/ Light Blue Specks Floor Tile	3000	SF	1967 BUILDING - ADDITION Room 010, Lunchroom 012-013		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
119M	12" x 12" Blue w/ Light Blue Specks Floor Tile Mastic	3000	SF	1967 BUILDING - ADDITION Room 010, Lunchroom 012-013		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
120	Brown Ceramic Grout	2800	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Boy's/Girl's and Teacher's Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
121	Brown Ceramic Grout Adhesive	2800	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Boy's/Girl's and Teacher's Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
122	12" x 12" Black w/ White Streaks Floor Tile	1500	SF	1903 BUILDING - MAIN 2nd & 3rd Floor Stair Landings  1926 NORTH AND SOUTH BUILDINGS - ADDITION 2nd & 3rd Floor Stair Landings		Miscellaneous	No	Loc	18	SF	<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
123	12" x 12" Black w/ White Streaks Floor Tile Mastic	1500	SF	1903 BUILDING - MAIN 2nd & 3rd Floor Stair Landings  1926 NORTH AND SOUTH BUILDINGS - ADDITION 2nd & 3rd Floor Stair Landings		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
124	2' x 4' Ceiling Tile w/ Gouges and Holes	10000	SF	1970 BUILDING - ANNEX Throughout		Miscellaneous	Yes	Dist	8000	SF	<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
125	Fire Proofing	60	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Groundfloor pre-K classroom, Lunchroom		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
126	12" x 12" White w/ Brown/Blue Specks Floor Tile	600	SF	1903 BUILDING - MAIN Rooms 301, 302, 303, 304, 102, 101 1967 BUILDING - ADDITION Room 210 (replacement tiles),		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
127	12" x 12" White w/ Brown/Blue Specks Floor Tile Mastic	600	SF	1903 BUILDING - MAIN Rooms 301, 302, 303, 304, 102, 101 1967 BUILDING - ADDITION Room 210 (replacement tiles),		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
128	Tongue and Groove Wooden Floor	200	SF	1903 BUILDING - MAIN 3rd Floor Storage Room, 204, 103 1926 NORTH AND SOUTH BUILDINGS - ADDITION Rooms 208, 108, 107A, 106		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
129	12" x 12" Beige w/ Brown/Gray Specks Floor Tile	600	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Rooms 305, 306 (replacement tiles), 307  1967 BUILDING - ADDITION Rooms 209A, 209B		Miscellaneous	No	Loc	3	SF	<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
130	12" x 12" Beige w/ Brown/Gray Specks Floor Tile Mastic	600	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Rooms 305, 306 (replacement tiles), 307  1967 BUILDING - ADDITION Rooms 209A, 209B		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
131	12" x 12" Peach w/ Brown & White Specks Floor Tile	600	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Rooms 306, 308		Miscellaneous	No	Dist	500	SF	<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
132	12" x 12" Peach w/ Brown/White Specks Floor Tile Mastic	600	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Rooms 306, 308		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
133	9" x 9" Black Floor Tile	1000	SF	1903 BUILDING - MAIN 3rd Floor Corridor, Boiler Room Bathroom  1926 NORTH AND SOUTH BUILDINGS - ADDITION 3rd Floor Corridor  1967 BUILDING - ADDITION 3rd Floor Corridor		Miscellaneous	No	Loc	3	SF	<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
134	9" x 9" Black w/ White Specks Floor Tile	1000	SF	1903 BUILDING - MAIN 3rd floor corridor  1926 NORTH AND SOUTH BUILDINGS - ADDITION 3rd floor corridor  1967 BUILDING - ADDITION 3rd floor corridor		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
135	9" x 9" Brown Floor Tile	1000	SF	1903 BUILDING - MAIN 3rd floor corridor  1926 NORTH AND SOUTH BUILDINGS - ADDITION 3rd Floor Corridor  1967 BUILDING - ADDITION 3rd Floor Corridor, Room 210		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
136	9" x 9" Brown w/ White Specks Floor Tile	1000	SF	1903 BUILDING - MAIN 3rd Floor Corridor  1926 NORTH AND SOUTH BUILDINGS - ADDITION 3rd Floor Corridor, 208B Janitor's Closet  1967 BUILDING - ADDITION 3rd Floor Corridor		Miscellaneous	No	Loc	25	SF	<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
137	9" x 9" White w/ Black Specks Floor Tile	1000	SF	1903 BUILDING - MAIN 3rd floor corridor  1926 NORTH AND SOUTH BUILDINGS - ADDITION 3rd floor corridor  1967 BUILDING - ADDITION 3rd floor corridor, Room 112		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
138	9" x 9" HAs 133-137 Mastic	5000	SF	1903 BUILDING - MAIN 3rd floor corridor  1926 NORTH AND SOUTH BUILDINGS - ADDITION 3rd floor corridor  1967 BUILDING - ADDITION 3rd floor corridor, Rooms 210, 112		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
139	Carpet Adhesive	1200	SF	1903 BUILDING - MAIN Rooms 203, 104  1926 NORTH AND SOUTH BUILDINGS - ADDITION Rooms 207, 107		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
140	9" x 9" Light Brown w/ White/Black Specks Floor Tile	600	SF	1967 BUILDING - ADDITION Room 005		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
141	9" x 9" Light Brown w/ White/Black Specks Floor Tile Mastic	600	SF	1967 BUILDING - ADDITION Room 005		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
142	9" x 9" Beige w/ Brown Specks Floor Tile	600	SF	1967 BUILDING - ADDITION Rooms 211, 213, 113, 114, 011, 009A		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
143	9" x 9" Beige w/ Brown Specks Floor Tile Mastic	600	SF	1967 BUILDING - ADDITION Rooms 211, 213, 113, 114, 011, 009A		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
144	12" x 12" Black White and Blue w/ Light Blue Specks Floor Tile			1967 BUILDING - ADDITION Room 010		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
145	12" x 12" Black, White and Blue w/ Light Blue Specks Floor Tile Mastic			1967 BUILDING - ADDITION Room 010		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
146	Concrete Leveling	25	SF	1903 BUILDING - MAIN Room 102 Janitor's Closet		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
147	Transite	250	SF	1903 BUILDING - MAIN Boiler Room Storage		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
148	12" x 12" Mauve Vinyl Floor Tile	650	SF	1970 BUILDING - ANNEX Room 413		Miscellaneous	No	None			<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
 Comments: Demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
149	12" x 12" Mauve Vinyl Floor Tile Mastic	650	SF	1970 BUILDING - ANNEX Room 413		Miscellaneous	No	None			<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
 Comments: demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Aircell Pipe Insulation	100	LF	1903 BUILDING - MAIN Throughout		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	Elbows on Aircell Pipe Insulation	200	FITTING	1903 BUILDING - MAIN Throughout		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C	Mag Pipe Insulation	100	LF	1903 BUILDING - MAIN Throughout		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Elbows on Mag Pipe Insulation	10	FITTING	1903 BUILDING - MAIN Throughout		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Cardboard Pipe Insulation	100	LF	1903 BUILDING - MAIN Throughout		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Elbows on Cardboard Pipe Insulation	25	FITTING	1903 BUILDING - MAIN Throughout		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Elbows on Fiberglass Pipe Insulation	50	FITTING	1903 BUILDING - MAIN Throughout		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
H	Tank Insulation			ABATED		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Boiler Rope			ABATED		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Aircell Pipe Insulation	500	SF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Elbows on Aircell Pipe Insulation	25	FITTING	1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Cardboard Pipe Insulation	250	LF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
O	Elbows on Cardboard Pipe Insulation			1926 NORTH AND SOUTH BUILDINGS - ADDITION Abated but Possibly Remaining Within Walls or Chases		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
P	Joints on Fiberglass Pipe Insulation	50	LF	1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	Joints on Fiberglass Pipe Insulation	100	LF	1967 BUILDING - ADDITION Throughout		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	Joints on Fiberglass Pipe Insulation	100	LF	1970 BUILDING - ANNEX Throughout		TSI					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2025 Fall Six Month Survey: Other  
Comments:demolished

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	Brick Mortar			1903 BUILDING - MAIN Throughout		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T	Brick			1903 BUILDING - MAIN Throughout		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
U	Brick Mortar			1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
V	Brick			1926 NORTH AND SOUTH BUILDINGS - ADDITION Throughout		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
W	Brick Mortar			1967 BUILDING - ADDITION Throughout		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
X	Brick			1967 BUILDING - ADDITION Throughout		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

*Richard J. Schleyer*

---

Richard J.Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Spencer Technology Academy

Date: 2/11/2026

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***