

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2025 Fall Six Month Survey

**School:** Jackie Robinson Elementary School  
**Address:** 4225 S. Lake Park Ave

**Oracle Unit:** 26061  
**Region:** 04

**Building ID:** 6780  
**Mail Room:** 46

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Mayo, Jack  
**Survey Date:** 2/12/2026  
**Email Address:** \_\_\_\_\_

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 Each child's backpack   
 Notice printed in school's newsletter   
 Notice printed in school's calendar   
 Other | Posted to the CPS W

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	2' x 4' Lay-in Ceiling Panels	40200	SF	3rd Floor Hallway, 2nd Floor Hallway, 201, 203, 202, 204, 206, 208, 205, 207a, 207, 210, 212, 1st Floor Hallway, Gymnasium, 110c, 111, 111a, Vestibules, 117, 109a, 107, 107a, Teachers' Lounge (106), 105, 103a, 103, 103b		Miscellaneous	Yes				<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2	Ceiling Plaster	40000	SF	Throughout Facility		Miscellaneous	Yes	Loc	10	SF	<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	12" x 12" White Floor Tile	18200	SF	Corridors, Lunchroom, Storages, 101, 102,		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 A	12" x 12" Brown Gray Floor Tile	1400	SF	Gym, 110a, 110c, 110d		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	12" x 12" White Floor Tile Mastic	20000	SF	Corridors, Offices, Lunchroom, Storages, 101, 102		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4 A	12" x 12" Brown Floor Tile Mastic	1400	SF	Gym, 110a, 110c, 110d		Miscellaneous	No				<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	Incinerator Fire Brick			Material Not Observed		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	Insulation Inside Of Firedoors			Material Not Present		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	Blue/Brown Mix Carpet Mastic	21350	SF	Rooms 207, 205 (Library), Assistant Principal's Office (105)		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	Window Glazing	10000	LF	Throughout Facility		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	Gasket Material			Material Not Present		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Drywall	800	SF	Stage		Miscellaneous	Yes	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Vinyl Baseboard Mastic	130	LF	Library		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Vinyl Baseboard	130	LF	Library		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Transite Table Tops			Material Not Present		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Coating on Bottoms Of Sinks	6	SF	Rooms 102 & 104		Miscellaneous	Yes	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Duct Vibration Absorbers	40	LF	2nd Floor Fan Room		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Window Caulk	2000	LF	Throughout Facility		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Insulation Inside Of Vault Door	32	SF	Office		TSI	Yes	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Chalk Board and Bulletin Board Adhesive	2000	SF	Throughout Classrooms		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Cloth Wiring Insulation on Unit Ventilators			Material Not Present		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Cinderblock	40000	SF	Throughout Facility		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Cinderblock Mortar	20000	SF	Throughout Facility		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Steel Door Insulation	28	SF	Incinerator Room		Miscellaneous	Yes	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12" x 12" White Floor Tile	1800	SF	Offices		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12" x 12" White Floor Tile Mastic	1800	SF	Offices		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Laminate Table Tops			Material Not Present		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Laminate Table Top Adhesive			Material Not Present		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Drywall Joint Compound	200	SF	Stage		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Drywall Joint Tape	200	LF	Stage		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Linoleum	600	SF	Principal's Office		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Linoleum Mastic	600	SF	Principal's Office		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Carpet Mastic			Room 309		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" x 12" Blue Vinyl Floor Tile	3600	SF	Rooms 201, 307		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12" x 12" Blue Vinyl Floor Tile Mastic	3600	SF	Rooms 201, 307		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12" x 12" Beige w/ Brown Streaks Floor Tile	25000	SF	Rooms 3rd Floor Hallway, 312, 2nd Floor Hallway, 202, 204, 207a, 210, 210a, 211, 1st Floor Hallway, 111, 111a, Lunchroom (107), 137		Miscellaneous	No				<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12" x 12" Beige w/ Brown Streaks Floor Tile Mastic	25000	SF	Rooms 3rd Floor Hallway, 312, 2nd Floor Hallway, 202, 204, 207a, 210, 210a, 211 1st Floor Hallway, 111, 111a, Lunchroom (107), 137		Miscellaneous	No				<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12" x 12" White w/ Gray Streaks Floor Tile	7000	SF	Rooms 309, 310, 305, 308, 306, 304, 302, 302a, 303, 301, 203, 206, 208		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12" x 12" White w/ Gray Streaks Floor Tile Mastic	7000	SF	Rooms 309, 310, 305, 308, 306, 304, 302, 302a, 303, 301, 203, 206, 208		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Chalkboard/Whiteboard Adhesive	1100	SF	Rooms 309, 310, 307, 305, 308, 306, 304, 302, 303, 301, 201, 203, 202, 204, 208, 210		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12" x 12" Light Blue W/ Blue Streaks Floor Tile	1000	SF	Rooms 307, 201		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12" x 12" Light Blue W/ Blue Streaks Floor Tile Mastic	1000	SF	Rooms 307, 201		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	2' x 4' Smooth Lay-in Ceiling Panel	6000	SF	Rooms 309, 310, 307, 305, 308, 306, 304, 302, 303, 301, 104, 102		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Dark Blue/Orange Multicolored Carpet Mastic	1300	SF	Rooms 205, 207, 107a, 105		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12" x 12" Off-White w/ White/Tan Streaks Floor Tile	1000	SF	Rooms 104, 104b, 102, 102b, 101, 103a, 103		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12" x 12" Off-White w/ White/Tan Streaks Floor Tile Mastic	1000	SF	Rooms 104, 104b, 102, 102b, 101, 103a, 103		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12" x 12" Dark Blue w/ Blue Streaks Floor Tile	300	SF	Rooms 104, 102		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12" x 12" Dark Blue w/ Blue Streaks Floor Tile Mastic	300	SF	Rooms 104, 102		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12" x 12" Light Grayish Blue w/ White Streak Floor Tile	200	SF	Rooms 104, 102		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12" x 12" Light Grayish Blue w/ White Streak Floor Tile Mastic	200	SF	Rooms 104, 102		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Mudded Joints	500	LF	Room 136		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	0.5" x 0.5" Brown Ceramic Floor Tile w/ Grout	3000	SF	All bathrooms, Vestibules and 1st Floor Storage Room		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Terrazzo	5000	SF	All Staircases		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	4" x 4" Beige Ceramic Floor Tile w/ Grout	1000	SF	Kitchen		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Wood Floor	400	SF	Room 106		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12" x 12" Light Brown Mottled Floor Tile	7	SF	Patches in Gym		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12" x 12" Light Brown Mottled Floor Tile Mastic	7	SF	Patches in Gym		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	12" x 12" Baby Blue Mottled Floor Tile	3	SF	Patches in Gym		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12" x 12" Baby Blue Mottled Floor Tile Mastic	3	SF	Patches in Gym		Miscellaneous	No	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	Mag Block Pipe Insulation	10	LF	Closet by Principal's Office		TSI	Yes	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C	Cementitious Joint Insulation -Fiberglass Lagging	6	JOINTS	2nd Floor Fan Room		TSI	Yes	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

*Richard J. Schleyer*

---

Richard J.Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Jackie Robinson Elementary School  
Date: 8/1/2025

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other. Posted to the CPS Website
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.