

Chicago Public Schools

6 Month Asbestos Surveillance

2025 Fall Six Month Survey

School: Thomas J Higgins Elementary Community Academy
Address: 11710 S Morgan

Oracle Unit: 31251
Region: 06

Building ID: 7210
Mail Room: 49

Asbestos Surveyor: Zavala, Jason
Survey Date: 1/20/2026
Email Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 03A | 9x9 Light Brown w/Specks Floor Tile | 3340 | SF | 1964 Building- 1st and 2nd Floor Corridors | | Miscellaneous | No | Loc | 5 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 03B | 9x9 Off White w/Dark Brown Specks Floor Tile | 150 | SF | Main Office Waiting Area | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 03C | 9x9 Tan w/White Streaks Floor Tile | 150 | SF | 1st Floor Women's Restroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 03D | 9x9 Light Green w/Streaks Floor Tile- Under 12x12 Blue Floor Tile (NOT OBSERVED) | 2600 | SF | Room 100, 1/2 Reading Recov. 206, 205, 106 | | Miscellaneous | No | | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 03E | 9x9 Tan w/ Dark Streaks Floor Tile | 850 | SF | Room 103 | | Miscellaneous | No | | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04A | 12x12 Tan w/White Specks Floor Tile | 2220 | SF | Lunchroom, 2nd Floor Storage Room/Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04B | 12x12 Blue w/Specks Floor Tile | 5200 | SF | 1972 Addition- 1st and 2nd Floor Corridors, Rooms 100, 102, 103, 104, 106, 111, 112, 113, 202, 203, 204, 205, 206, 207, Teacher's Lounge, Kitchen Storage & Janitor 126A | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04C | 12x12 Off White Floor Tile | 200 | SF | 1964 Building- Center North Staircase & Landing | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04D | 12x12 Beige w/Streaks Floor Tile | 1500 | SF | 1964 Building- Rooms 98, 99, 1/2 of 105, 110, 210, 211, 212, 213, 214, Engineer's Office, Main Office & Principal's Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04E | 12x12 Cream w/Streaks Floor Tile | 425 | SF | 1964 Building- 1/2 Room 105 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10A | 9x9 Light Brown w/Specks Floor Tile Mastic | 3340 | SF | 1964 Building- 1st & 2nd Floor Corridors | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10B | 9x9 Off White w/Dark Brown Specks Floor Tile Mastic | 150 | SF | Main Office Waiting Area | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10C | 9x9 Tan w/White Streaks Floor Tile Mastic | 150 | SF | 1st Floor Women's Restroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10D | 9x9 Light Green w/Streaks Floor Tile Mastic- Under 12x12 Blue Floor Tile | 2600 | SF | 1/2 Reading Recov., and Rooms 100, 106, 205, 206 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10E | 9x9 Tan w/ Dark Streaks Floor Tile Mastic | 850 | SF | Room 103 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11A | 12x12 Tan w/White Specks Floor tile Mastic | 2220 | SF | Lunchroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11B | 12x12 Blue w/Specks Floor Tile Mastic | 5000 | SF | 1972 Addition- 1st and 2nd Floor Corridors, Rooms 100, 102, 103, 104, 106, 111, 112, 113, 202, 203, 204, 205, 206, 207, Teacher's Lounge and Kitchen Storage | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11C | 12x12 Off White Floor Tile Mastic | 200 | SF | 1964 Building- Center North Staircase & Landing | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11D | 12x12 Beige w/Streaks Floor Tile Mastic | 1500 | SF | 1964 Building- Rooms 98, 99, 1/2 of 105, 110, 210, 211, 212, 213, 214, Engineer's Office, Main Office & Principal's Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11E | 12x12 Cream w/Streaks Floor Tile Mastic | 425 | SF | 1964 Building- 1/2 Room 105 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12A | Black Baseboard | 1665 | LF | 1964 Building- Throughout | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12B | Black Baseboard | 385 | LF | 1972 Addition- 3rd Floor Corridor | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13A | Black Baseboard Mastic | 1665 | LF | 1964 Building-Throughout | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13B | Black Baseboard Mastic | 385 | LF | 1972 Addition- 2nd Floor Corridor | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14 | Insulation in Fire Rated Door | 1 | EA | Engineer's Office | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15 | 2'x4' Ceiling Tile | 40000 | SF | 1964 Building-Throughout | | Miscellaneous | Yes | Dist | 30 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16 | 2'x4' Ceiling Tile | 15000 | SF | 1971 Building-Throughout | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17 | Tan Terrazzo Flooring | 1600 | SF | 1964 Building- Kitchen | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18 | Tan Terrazzo Flooring | 300 | SF | 1972 Building- Stairways | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19 | Yellow Mosaic Ceramic Tile Grout | 470 | SF | 1964 Building- Girls' Washrooms and Engineer's Washroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20 | Yellow Mosaic Ceramic Tile Adhesive | 470 | SF | 1964 Building- Girls' Washrooms and Engineer's Washroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21 | Blue Mosaic Ceramic Tile Grout | 510 | SF | 1964 Building- Boys Washrooms and Mens Washrooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22 | Blue Mosaic Ceramic Tile Adhesive | 510 | SF | 1964 Building- Boys Washrooms and Mens Washrooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23 | Tan Ceramic Tile Grout | 740 | SF | 1972 Building- Boys and Girls Washrooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24 | Tan Ceramic Tile Adhesive | 740 | SF | 1972 Building- Boys and Girls Washrooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25 | Clay Ceramic Tile Grout | 60 | SF | 1972 Building- West Vestibule | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26 | Clay Ceramic Tile Adhesive | 60 | SF | 1972 Building- West Vestibule | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27 | Blue Crpet Adhesive | 3640 | SF | 1972 Building- 114, 209 and Library | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28 | 12x12 Beige w/Streaks Floor Tile | 4930 | SF | 1972 Building- Rooms 110, 210, 211, 212, 213, and 214 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28M | 12x12 Beige w/Streaks Floor Tile Mastic | 4930 | SF | 1972 Building- Rooms 110, 210, 211, 212, 213, and 214 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29 | 12x12 Cream w/Streaks Floor Tile | 450 | SF | 1972 Building- Room 214 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29M | 12x12 Cream w/Streaks Floor Tile Mastic | 450 | SF | 1972 Building- Room 214 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30 | MJP on Fiberglass Pipe | 300 | SF | 1964 Building-Throughout | | Miscellaneous | Yes | Loc | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31 | 12x12 Brown-Streaked Vinyl Floor Tile | 740 | SF | Lobby Near Vestibule Near the Main Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31A | 12x12 Brown-Streaked Vinyl Floor Tile Mastic | 740 | SF | Lobby Near Vestibule Near the Main Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32 | Plaster Ceilings | 1500 | SF | 1st and 2nd Floor Restrooms and Janitor Closets | | Surface | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33 | 12x12 Gray-Streaked Vinyl Floor Tile | 100 | SF | Gym Storage Room | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33A | 12x12 Gray-Streaked Vinyl Floor Tile Mastic | 100 | SF | Gym Storage Room | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34 | Acoustical Ceiling Tiles | 300 | SF | Gym | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34A | Acoustical Ceiling Tiles Mastic | 3000 | SF | Gym | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35 | 12x12 Cream w/Beige Specks Vinyl Floor Tile | 1500 | SF | 1964 Building- Room 101, Assistant Principal's Office (Room 108), 1st Floor Corridor near Kindergarten Rooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36 | 12x12 Cream w/Beige Specks Mastic | 1500 | SF | 1964 Building- Room 101, Assistant Principal's Office (Room 108), 1st Floor Corridor near Kindergarten Rooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37 | 12x12 Dark Blue Floor Tile | 4800 | SF | Rooms 102, 103, 104, 106, 111, 112, 113, 203, 204, 205, 206 & 207 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37A | Mastic associated with 12x12 Dark Blue Floor Tile | 4800 | SF | Rooms 102, 103, 104, 106, 111, 112, 113, 203, 204, 205, 206 & 207 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38 | 12x12 Green Floor Tile | 600 | SF | Rooms 100 & 101 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38A | Mastic associated with 12x12 Green Floor Tile | 600 | SF | Rooms 100 & 101 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39 | 12x12 Teal Floor Tile | 600 | SF | Rooms 100 & 101 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39A | Mastic associated with 12x12 Teal Floor Tile | 600 | SF | Rooms 100 & 101 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40 | 12x12 Off-White Floor Tile | 600 | SF | Rooms 100 & 101 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40A | Mastic associated with 12x12 Off-White Floor Tile | 600 | SF | Rooms 100 & 101 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B | Magblock Breaching Boiler Insulation NOT OBSERVED | 80 | SF | Boiler Room | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C | Boiler Gaskets NOT OBSERVED | 5 | LF | Boiler Room | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| CM | Brown Carpet Mastic | 11595 | SF | 1st Floor Corridor, Teachers' Lounge, 113, 111, 110, 210, 211, 213, 209, 214, 114, & Library | | Miscellaneous | No | | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| NEW | Newly Installed Suspect ACM | | | Installed After Implementation of Management Plan and After Renovations | | Miscellaneous | | Unknown | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

Richard J. Schleyer

Richard J.Schleyer

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Thomas J Higgins Elementary Community Academy
Date: 11/20/2025

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.