

Chicago Public Schools

6 Month Asbestos Surveillance

2025 Fall Six Month Survey

School: Bronzeville Scholastic Academy High School
Address: 4934 S. Wabash

Oracle Unit: 55191
Region: 04

Building ID: 1280
Mail Room: 45

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: SYSTEM
Survey Date: 2/12/2026
Email Address: system@cps.edu

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:
 Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other onsite

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Insulation on Boiler #1	360	SF	Boiler Room		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Boiler #1 Gasket	16	LF	Boiler Room Boiler #1		Miscellaneous	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Pipe Insulation	40	LF	Boiler Room Behind Red Tank		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Red Tank Insulation	96	SF	Boiler Room		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Insulation on Tank #2	96	SF	Boiler Room		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Cementitious Incinerator Insulation	40	SF	Boiler Room		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
 Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Gasket on Boiler #2	18	LF	Boiler Room		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Insulation on Boiler #2	268	SF	Boiler Room		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Pipe Insulation	20	LF	Boiler Room#2, Kitchen Room 230		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Insulation on Tank #1	288	SF	Boiler Room		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Pipe Insulation	20	LF	Boiler Room		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Air Duct Insulation	200	SF	Circuit Breaker Room, 1st Floor Kitchen, 2nd Floor Kitchen		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Mag Block Pipe Insulation	150	LF	2nd Level of Boiler Room by Outer Wall		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Terrazzo Wall & Stall	216	SF	Bathrooms Throughout Facility		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Black Board	24	SF	Boiler Room Wall by Stairs		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	White Marble	200	SF	Bathrooms Throughout Facility		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Black Marble	200	SF	Bathrooms Throughout Facility		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Cinderblock	580000	SF	Throughout Facility		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Cinderblock Mortar	580000	SF	Throughout Original Building		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Pipe Insulation	18	LF	Next To Plenum #2		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Plaster Walls	475200	SF	Basement		Surface	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Cementitious Pipe Joints	48	LF	Wind Tunnel #6		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
 Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Spray-on Cementitious Material	50	SF	Wall by Fan Room 7		Surface	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Fiberglass Pipe Insulation	80	SF	Next To Fan Room # 8		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Fittings on Fiberglass Pipe Insulation	570	LF	Under New Addition, Air Tunnel # 8		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Cementitious Pipe Joint Insulation	16	LF	Engine Room West Side Next WomensFan Room # 7		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Fiberglass Pipe Insulation	120	LF	Fan Room #2		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Interior Brick	1632	SF	Boiler Room		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Interior Brick Mortar	1632	SF	Boiler Room		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12" x 12" White w/ Blue Specks Floor Tile	2646	SF	1962 Addition 2nd & 3rd Floor Corridor, 368, 366, 365, 264, 366, 109, 113, 120		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" White w/ Blue Specks Floor Tile Mastic	2646	SF	1962 Addition 2nd & 3rd Floor Corridor, 368, 366, 365, 264, 109, 113, 120		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	9" x 9" Tan w/ White Streaks Floor Tile	34800	SF	1st and 2nd Floor Southeast Corridor, 101, 104, 105, 106, 108, 154, 201, 203, 205, 207, 261, 264, 265, 266, 267, 269, 270, 301-305, 364, 366, 368, 369, 370, 272, 106, 104, 160, 365, 268, 206, 204		Miscellaneous	No	Loc	3	SF	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	9" x 9" Tan w/ White Streaks Floor Tile Mastic	34800	SF	1st and 2nd Floor Southeast Corridor, 101, 104, 105, 106, 108, 154, 201, 203, 205, 207, 261, 264, 265, 266, 267, 269, 270, 301-305, 364, 366, 368, 369, 370, 272, 106, 104, 160, 365, 268, 206, 204		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12" x 12" Brown w/ White Streaks Floor Tile	8012	SF	Rooms 365, 364, 367, 366, 369, 370, 303, 368		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12" x 12" Brown w/ White Streaks Floor Tile Mastic	8012	SF	Rooms 365, 364, 367, 366, 369, 370, 303, 305, 368		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Cinderblock	580000	SF	Throughout 1962 Building		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Cinderblock Mortar	580000	SF	Throughout 1962 Building		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Sound Proofing	80	SF	Room 206 Storage		Miscellaneous	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Finished Block Mortar	26000	SF	Throughout 1934 Building		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	9" x 9" Brown w/ White Streaks Floor Tile	12000	SF	1st and 2nd Floor Southeast Corridor, 105, 106, 154		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	9" x 9" Brown w/ White Streaks Floor Tile Mastic	12000	SF	1st and 2nd Floor Southeast Corridor, 105, 106, 154		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Dark Brown & White Ceramic Tile Grout	544	SF	3rd floor, 2nd Floor Mens Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	9" x 9" Dark Brown w/ White Streaks Floor Tile	50	SF	Room 208		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	9" x 9" Dark Brown w/ White Streaks Floor Tile Mastic	50	SF	Room 208		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	2' x 4' Ceiling Panels	200000	SF	1st floor and second floor		Miscellaneous	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	Drywall	400000	SF	Throughout Facility		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	1' x 1' Acoustical Ceiling Tile	3000	SF	Throughout Facility		Miscellaneous	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Plaster	130000	SF	Throughout Building		Surface	Yes	Dist	75	SF	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	Corkboard	100000	SF	Throughout Classrooms		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Pipe Chase Brick	96	SF	3rd Floor Next WomensMens Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Pipe Chase Brick Mortar	96	SF	3rd Floor Next WomensMens Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Terrazzo Stall Panels	8	SF	3rd Floor Mens Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	Terrazzo Sinks	4	SF	3rd Floor Mens Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	Light Brown & Tan Ceramic Tile Grout	1000	SF	Womens and men's 3rd Floor Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	Red Carpet Mastic	3000	SF	Auditorium		Miscellaneous	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	Blue Carpet Mastic	700	SF	Music Room		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	Cement Flooring	596	SF	Room 335		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	12" x 12" White w/ Black Specks Floor Tile			Rooms 113		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	12" x 12" White w/ Black Specks Floor Tile Mastic			Rooms 113		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12" x 12" Off-White w/ Beige Specks Floor Tile	18000	SF	1st, 2nd & 3rd Floor Corridors, 217, 216, 220, 121, 164, 167, gym 102 closet, 115, 120, 122, 117, 121		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	12" x 12" Off-White w/ Beige Specks Floor Tile Mastic	18000	SF	1st, 2nd & 3rd Floor Corridors, 217, 216, 220, 121, 164, 167, gym 102 closet, 115, 120, 122, 117, 121		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12" x 12" Tan w/ Light Brown Streaks Floor Tile	5000	SF	3rd Floor Safe Room, 3rd Floor Corridor		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	12" x 12" Tan w/ Light Brown Streaks Floor Tile Mastic	5000	SF	3rd Floor Safe Room, 3rd Floor Corridor		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	Carpet Mastic on Planter			Greenhouse		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	Terrazzo Flooring	300000	SF	1st, 2nd, 3rd Floor Corridors, 2nd floor Kitchen room 230		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	Finished Brick Mortar	580000	SF	Throughout Facility		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	Locker Caulk			Throughout Facility		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	12" x 12" Off-White w/ Gray Streaks Floor Tile	5000	SF	2nd Floor Lunchroom, Room 230, 3rd Floor Corridor		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	12" x 12" Off-White w/ Gray Streaks Floor Tile Mastic	5000	SF	2nd Floor Lunchroom, Room 230, 3rd Floor Corridor		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
 Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	12" x 12" Cream w/ White Streaks Floor Tile			Room 235		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	12" x 12" Cream w/ White Streaks Floor Tile Mastic			Room 235		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	Gray Carpet Mastic	1200	SF	Room 258, Gym, 119		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	9" x 9" Red Floor Tile	1200	SF	Rooms 360, 260, 109, 113, 214, 256, Gym Office 269(257), 214 MDF		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	9" x 9" Red Floor Tile Mastic	1200	SF	Rooms 360, 260, 109, 113, 214, 256, Gym Office 269(257), 214 MDF		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	9" x 9" Black Floor Tile	1600	SF	Rooms 360, 260, 113, 214		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	9" x 9" Black Floor Tile Mastic	1600	SF	Rooms 360, 260, 113, 214		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	9" x 9" Burnt Orange Floor Tile	1000	SF	Gym Office, Rooms 110 and 112		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	9" x 9" Burnt Orange Floor Tile Mastic	1000	SF	Gym Office, Rooms 110 and 112		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	9" x 9" Chocolate Brown Floor Tile	350	SF	Gym Office, Rooms 110 and 112, Vault		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	9" x 9" Chocolate Brown Floor Tile Mastic	350	SF	Gym Office, Rooms 110 and 112, Vault		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	Black Border Floor Tile			ABATED		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	Black Border Floor Tile Mastic			ABATED		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
94	9" x 9" Black Floor Tile	900	SF	Gym Closet 256, Gym Office 269 (257), 214 MDF		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	9" x 9" Black Floor Tile Mastic	900	SF	Gym Closet 256, Gym Office 269 (257), 214 MDF		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
96	12" x 12" Red Floor Tile			MATERIAL REMOVED		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	12" x 12" Red Floor Tile Mastic			ABATED		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
98	9" x 9" Carmel Colored Floor Tile Mastic			Gym Bathroom		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	Brown Linoleum			Room 109		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	Multi-Brown Ceramic Tile Grout	1500	SF	Gym Office Bathroom, 161 bathrooms		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	Spray-on Ceiling Material	80000	SF	1st and 2nd Floor Classrooms and south east corridor (1962 Addition),		Surface	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	Cream Colored Ceramic Tile Mastic	400	SF	1st Floor Girls Locker Room		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	Light Blue Ceramic Tile & Mastic	45000	SF	Swimming Pool Room, Boys and Girls Locker Rooms		Miscellaneous	No	Loc	20	SF	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	Swimming Pool Edge Mortar	120	LF	Swimming Pool		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	Blue and Yellow Ceramic Tile Grout	45000	SF	Swimming Pool, Girls Locker Room, Boys Locker Room		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	Yellow Linoleum on Counter Top and Wall			Room 113		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	Yellow Linoleum Mastic on Counter Top and Wall			Room 113		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	Brown Baseboard	100000	SF	Throughout facility		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
109	Brown Baseboard Mastic	100000	SF	Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	12" x 12" Brown w/ White Streaks Floor Tile	2400	SF	1st Floor Lunchroom, Rooms 217, 216, 220, 121,164, 167, 115, 117, 121		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	12" x 12" Brown w/ White Streaks Floor Tile Mastic	2400	SF	1st Floor Lunchroom, Rooms 217, 216, 220, 121,164, 167, 115, 117, 121		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	Green Marble	2000	SF	Auditorium		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	Light Brown Terrazzo	500	SF	Outside Auditorium		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114	Light Gray Terrazzo Flooring	500	SF	Outside Auditorium		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
115	Exterior Brick - Non-AHERA			Exterior of 1934 Building		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116	Exterior Brick Mortar - Non-AHERA			Exterior of 1934 Building		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
117	Exterior Brick - Non-AHERA			Exterior of 1962 Addition		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
118	Exterior Brick Mortar - Non-AHERA			Exterior of 1962 Addition		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
119	Exterior Window Caulk - Non-AHERA			1934 Building		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
120	Exterior Window Caulk - Non-AHERA			1962 Addition		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
121	Exterior Door Caulk - Non-AHERA			1934 Building		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
122	Exterior Door Caulk - Non-AHERA			1962 Addition		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
123	Roofing Material - Non-AHERA			Roof		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
124	Roof Flashing - Non-AHERA			Roof		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
126	Greenish Brown Carpet Mastic	60	SF	Room 209		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
127	1' x 1' Ceiling Tile Adhesive	10000	SF	Throughout 1962 Building		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
128	Lab Counter Tops	1008	SF	Rooms 129, 135, 233, 235, 266, 327, and 335, 268, 231		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
129	Liner in Vault Door	32	SF	Room 327		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
130	Green Carpet Mastic	1450	SF	Room 220, 103		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
131	Purple Carpet Mastic			Room 217		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
132	Brown Carpet Mastic	750	SF	Room 165, 216, 170		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
133	Blue Carpet Mastic	1250	SF	Room 167, 168		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
134	Reddish Purple Carpet Mastic			Rooms 121, 123, and 125		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
135	Free Standing Lab Tables	769	SF	Rooms 129, 135, 233, 235, 327, and 329, 335, 327, 233, 231		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
136	12" x 12" Tan Floor Tile w/ Brown Streaks			Room 348		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
137	12" x 12" Tan Floor Tile w/ Brown Streaks Mastic			Room 348		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
138	Cementitious Joint Insulation on Fiberglass Piping	400	LF	Basement/Tunnel		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
139	Transite Table Top	2		Room 113		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
140	Brown Linoleum	400	SF	Room 217 closet		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
141	Brown Linoleum Mastic			ABATED		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
142	12" x 12" Tan w/ White Streaks Vinyl Floor Tile			Room 235		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
143	12" x 12" Tan w/ White Streaks Vinyl Floor Tile Mastic			Room 235		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
144	12" x 12" Blue w/ White Streaks Vinyl Floor Tile			Room 165 Health Center		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
145	12" x 12" Blue w/ White Streaks Vinyl Floor Tile Mastic			Room 165 Health Center		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
146	12" x 12" Gray w/ Beige & White Spots Floor Tile	4200	SF	3rd Floor Corridor, 117		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
147	12" x 12" Gray w/ Beige & White Spots Floor Tile Mastic	4200	SF	3rd Floor Corridor, 117		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
148	Black and White Dots Linoleum	120	SF	Gym Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
149	Black and White Dots Linoleum Mastic	120	SF	Gym Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
150	Aircell Pipe Insulation & Possibly in Inaccessible Areas	200	LF	2nd Floor Girls Bathroom by Library & 227, 2nd Floor Boys Bathroom by 235, 1st Floor Womens Faculty Bathroom		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
151	Joint Insulation Assoc. w/ HA 150 & Inaccessible Areas	50	LF	2nd Floor Girls Bathroom by Library & 227, 2nd Floor Boys Bathroom by 235, 1st Floor Womens Faculty Bathroom		TSI	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
152	Chalk Board/ Poster Board Adhesive	15200	SF	Throughout All Classrooms		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
153	12" x 12" Off-White w/ Blue Swirls Floor Tile	1850	SF	Room 113		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
154	12" x 12" Off-White w/ Blue Swirls Floor Tile Mastic (Yellow)	1850	SF	Room 113		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
155	Brown Linoleum			Room 121		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
156	Brown Linoleum Mastic			Room 121		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
157	12" x 12" Off-White Tan Mottle Floor Tile	2000	SF	Room 302, 229, 250, 350		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
158	12" x 12" Off-White Tan Mottle Floor Tile Mastic	2000	SF	Room 302, 229, 250, 350		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
159	12" x 12" Tan Mottle Floor Tile	1800	SF	Room 166, 174		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
160	12" x 12" Tan Mottle Floor Tile Mastic	1800	SF	Room 166, 174		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
161	Tan Linoleum	3700	SF	Science Rooms. Room329, 335, 346, 327 back room,		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
162	Tan Linoleum Mastic	3700	SF	Science Room Room 329, 335, 346, 135		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
163	12" x 12" Off-White Gray Mottle Floor Tile	1500	SF	Room 113, 2nd & 3rd Floor Corridor, Gym Office (257)		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
164	12" x 12" Off-White Gray Mottle Floor Tile Mastic	1500	SF	Room 113, 2nd & 3rd Floor Corridor, Gym Office (257)		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
165	Sink Insulation	4	SF	Room 121		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
166	1' x 1' White Ceiling Tile	17500	SF	Gyms 256, 257, and 258		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
167	1' x 1' White Ceiling Tile Adhesive	17500	SF	Gyms 256, 257, and 258		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
168	Tan Laminate Flooring	3400	SF	Rooms 231, 233, 235		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
169	12" x 12" Brown/Tan/White Mottled Floor Tile	4500	SF	Rooms 370, 368, 364, 1st Floor Lunchroom Office, 164		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
170	12" x 12" Brown/Tan/White Mottled Floor Tile Mastic	4500	SF	Rooms 370, 368, 364, 1st Floor Lunchroom Office, 164		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
171	12" x 12" Light Gray/White Mottled Floor Tile	100000	SF	Room 348, 342, 372, 3rd Floor South Corridor , 217, 216, 220, 121, Lunchroom Office, 164, 167, 115, 117, 121		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
172	12" x 12" Gray/Dark Gray/White Mottled Floor Tile			Room 348		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
173	12" x 12" Light Gray/White Mottled Floor Tile Mastic	100000	SF	Room 348, 342, 372, 3rd Floor South Corridor , 217, 216, 220, 121, Lunchroom Office, 164, 167, 115, 117, 121		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
174	Light Blue Linoleum	500	SF	Rooms 327, 129, 135		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
175	Blue Linoleum	500	SF	Rooms 327, 129, 135		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
176	Light Gray Linoleum	500	SF	Rooms 327, 129, 135		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
177	Light Gray, Light Blue, & Blue Linoleum Mastic	500	SF	Rooms 327, 129, 135		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
178	12" x 12" Yellow Floor Tile	1000	SF	Rooms 107a, 107b, 107, 103		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
179	12" x 12" Yellow Floor Tile Mastic	1000	SF	Rooms 107a, 107b, 107, 103		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
180	12" x 12" Gray w/ Dark Gray & Blue Specks Floor Tile			Room 122		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
181	12" x 12" Gray w/ Dark Gray & Blue Specks Floor Tile Mastic			Room 122		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
182	Tongue and Groove	200000	SF	Throughout 1st and 2nd Floors Classrooms		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
183	2' x 2' Ceiling Tile	150000	SF	Room 324, 3rd Floor Reception Area, 325, 327, 321, 317, 320, 313, 310, 307, 308, 305, 303, 302, 135		Miscellaneous	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
184	2" x 8" Glazed Off-White and Beige Brick	350000	SF	Throughout School		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
185	2" x 8" Glazed Off-White and Beige Brick Grout	350000	SF	Throughout School		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
186	White Counter Top With Brown Speckles	100	SF	Rooms 324, 372		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
187	White Counter Top With Brown Speckles Adhesive	100	SF	Rooms 324, 372		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
188	12" x 12" Beige With Speckles Floor Tile	150	SF	3rd Floor Reception Area		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
189	12" x 12" Beige With Speckles Floor Tile Mastic	150	SF	3rd Floor Reception Area		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
190	5' x 12' Granite Acoustical Panels On Ceilings	1500	SF	3rd Floor Ceiling Corridor, 342		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
191	Multi-Color Carpet	12000	SF	Room 325 , 321, 317, 320, 313, 310, 307, 308, 305, 303, 302, 116-118		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
192	Multi-Color Carpet Mastic	12000	SF	Room 325 , 321, 317, 320, 313, 310, 307, 308, 305, 303, 302		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
193	6" x 12" White Glaze Ceramic Wall Tile	350000	SF	Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
194	6" x 12" White Glaze Ceramic Wall Tile Grout	350000	SF	Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
195	Fume Hood	1	EA	Room 335		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
196	6" x 18" White Ceramic Wall Tile	150	SF	3rd Floor All Genders Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
197	6" x 18" White Ceramic Wall Tile Adhesive	150	SF	3rd Floor All Genders Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
198	2" x 2" Dark Gray Ceramic Floor Tile	150	SF	3rd Floor All Genders Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
199	2" x 2" Dark Gray Ceramic Floor Tile Grout	150	SF	3rd Floor All Genders Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
200	2" x 2" Dark Gray Ceramic Floor Tile Mortar	150	SF	3rd Floor All Genders Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
201	2" x 2" Light Gray Ceramic Floor Tile	150	SF	3rd Floor All Genders Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
202	2" x 2" Light Gray Ceramic Floor Tile Grout	150	SF	3rd Floor All Genders Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
203	2" x 2" Light Gray Ceramic Floor Tile Mortar	150	SF	3rd Floor All Genders Bathroom		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
204	2" x 2" White Ceramic Floor Tile	150	SF	3rd Floor All Genders Bathroom, All Genders Bathroom Next To 272		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
205	2" x 2" White Ceramic Floor Tile Grout	150	SF	3rd Floor All Genders Bathroom, All Genders Bathroom Next To 272		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
206	2" x 2" White Ceramic Floor Tile Mortar	150	SF	3rd Floor All Genders Bathroom, All Genders Bathroom Next To 272		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
207	Black and White Octagon Ceramic Floor Tile	3000	SF	Room 226, 2nd Floor North End Women's Bathroom Outside Kitchen 230, Gym 256, Gym Office 269(257), 260, 126, Auditorium Bathrooms, 156 Female Lockers, 1st Floor Girls Bathroom By 160, Room 160		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
208	Black and White Octagon Ceramic Floor Tile Grout	3000	SF	Room 226, 2nd Floor North End Women's Bathroom Outside Kitchen 230, Gym 256, Gym Office 269(257), 260, 126, Auditorium Bathrooms, 156 Female Lockers, 1st Floor Girls Bathroom By 160, Room 160		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
209	Black and White Octagon Ceramic Floor Tile Mortar	3000	SF	Room 226, 2nd Floor North End Women's Bathroom Outside Kitchen 230, Gym 256, Gym Office 269(257), 260, 126, Auditorium Bathrooms, 156 Female Lockers, 1st Floor Girls Bathroom By 160, Room 160		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
210	9" x 18" White Glazed Ceramic Wall Tile	1500	SF	Kitchen Room 230		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
211	9" x 18" White Glazed Ceramic Wall Tile Grout	1500	SF	Kitchen Room 230		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
212	Vinyl Backsplash	1300	SF	Kitchen Walls Room 230 and 130		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
213	Vinyl Backsplash Adhesive	1300	SF	Kitchen Walls Room 230 and 130		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
214	6" x 6" Ceramic Baseboard	100	LF	Kitchen Room 230 and 130		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
215	6" x 6" Ceramic Baseboard Adhesive	100	LF	Kitchen Room 230 and 130		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
216	Vibration Collar	5	SF	Storage Room 2nd Floor Across 256, Ahu 5		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
217	Fire Caulk	300000	SF	Throughout		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
218	Sink Undercoat	10	SF	Room 154, 106		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
219	4" x 4" Ceramic Wall Tile	45000	SF	156 Female and Male Lockers		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
220	4" x 4" Ceramic Wall Tile Grout	45000	SF	156 Female and Male Lockers		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-001	9" x 9" Carmel Colored Floor Tile			Gym Bathroom		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

Richard J. Schleyer

Richard J.Schleyer

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Bronzeville Scholastic Academy High School

Date: 2/12/2026

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other. onsite
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.