

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2823
SCHOOL NAME: Ninos Heroes
ADDRESS OF SCHOOL: 8344 S Commercial
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 8/10/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/20/2025 ENROLLMENT 285
IDPH INSPECTOR LICENSE NUMBER: 100-21040
IDPH LICENSED INSPECTOR NAME (Please Print): Josh Herman
IDPH MP LICENSE NUMBER: 100-00349
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): James Tuinenga

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 6/17/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Ninos Heroes

8344 S Commercial
Chicago, IL, 60617

Unit: 31101
Building ID: 3720

IDPH ID Number: 14-016-2990-2823

REPORT DATE:
Tuesday, June 17, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
TEM Environmental, Inc.

174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone 630-790-0880
Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

06/16/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 31101 Region: 06 IDPH ID: 14-016-2990-2823

School: Ninos Heroes Building ID: 3720

Address: 8344 S Commercial

Chicago, IL, 60617

Building Contact: Borger, Matthew Contact Phone: 7737079256

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/20/2025

Review Date: 06/16/2025

Inspector: Josh Herman

Inspector IDPH License: 100-21040

Management Planner: James Tuinenga

Management Planner IDPH License: 100-00349

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



James Tuinenga
100-00349

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: June 17, 2025

RE: Ninos Heroes, Unit 31101
8344 S Commercial
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Ninos Heroes , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Ninos Heroes, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Ninos Heroes Unit: 31101 Region: 06
Address: 8344 S Commercial Chicago, IL, 60617
IDPH ID: 14-016-2990-2823 Building ID: 3720
Contact: Borger, Matthew Phone: 7737079256

2. Description of Facility

Original Construction: 1981 Additional Construction:
Total Square Footage: 73518 No of Floors: 3
Current Occupancy: 285

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880 Fax: 630-790-0882

5. Inspector

Inspector Name: Josh Herman

Signature: _____
Date: 5/20/2025

6. Management Planner

Management Planner Name: James Tuinenqa

Signature:
Date: 06/16/2025

7 Review Date: 06/16/2025

8 IFA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: Richard J. Schleyer

Signature:

Date: 6/17/2025

Name: Richard J. Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Ninos Heroes. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3720:

40	12"x12" Green, Cream & Navy Floor Tile
40M	Mastic associated w/12"x12" Green Cream & Navy Floor Tile
41	2'x2' Smooth Ceiling Tile
42	Sink Undercoating
43	Stage Curtains
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 3720:

40	12"x12" Green, Cream & Navy Floor Tile
40M	Mastic associated w/12"x12" Green Cream & Navy Floor Tile
41	2'x2' Smooth Ceiling Tile
42	Sink Undercoating
43	Stage Curtains

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01A	12x12 Off-White Speckled Floor Tile
01B	12x12 Taupe Floor Tile
05A	Brown Vinyl Baseboard
05B	Black Vinyl Baseboard
06A	12x12 Off-White Speckled Floor Tile Mastic
07A	Brown Vinyl Baseboard Mastic
07B	Black Vinyl Baseboard
08	Drywall
09	Drywall Compound
10	Hardcoat Plaster
11	Interior Window Glazing
12	Interior Window Caulking
13	Building Expansion Joint Compound
14	12x12 White w/Pink Speckles Floor Tile NOT OBSERVED
14A	12x12 White w/Pink Speckles Floor Tile Mastic NOT OBSERVED
15	12x12 White w/Blue Speckles Floor Tile NOT OBSERVED
15A	12x12 White w/Blue Speckles Floor Tile Mastic NOT OBSERVED
16	2'x4' White Fissured Lay-In Ceiling Tile
17	Spray-On Fireproofing on Beams
18	Tan Carpet Adhesive
19	Gray Carpet Adhesive
20	Blue Carpet Adhesive
21	Purple Carpet Adhesive
22	Gray Ceramic Tile Grout
23	Gray Ceramic Tile Adhesive
24	Brown Ceramic Tile Grout
25	Brown Ceramic Tile Adhesive
26	Blue Carpet Mastic
27	12x12 White w/Multicolor Speckles Vinyl Floor Tile NOT OBSERVED
28	12x12 White w/Multicolor Speckles Vinyl Floor Tile Mastic NOT OBSERVED
29	12x12 Brown Floor Tile
30	12x12 Brown Floor Tile Mastic
31	12x12 Cream Floor Tile
32	12x12 Cream Floor Mastic
33	12x12 Blue Speckled Floor Tile
34	12x12 Blue Speckled Floor Tile Mastic

35	12x12 Off-White w/Tan Speckles Floor Tile
36	12x12 Off-White w/Tan Speckles Floor Tile Mastic
39	Brown Tan Specks Carpet Mastic
40	12"x12" Green, Cream & Navy Floor Tile
40M	Mastic associated w/12"x12" Green Cream & Navy Floor Tile
41	2'x2' Smooth Ceiling Tile
42	Sink Undercoating
43	Stage Curtains
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

19	Gray Carpet Adhesive
25	Brown Ceramic Tile Adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Josh Herman, IDPH License # 100-21040. The Management Plan was updated by James Tuinenga, IDPH License # 100-00349. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 4/21/2022
6/9/2023

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Ninos Heroes Building 3720 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Ninos Heroes **Unit** 31101 **Building ID** 3720
Address 8344 S Commercial **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01A	12x12 Off-White Speckled Floor Tile	25,000	SF	On 1sr Floor- Gym, Cafeteria, Vault, Corridors, Workroom, Science Lab/L Throughout- 2nd & 3rd Floor Corridors, Science Lab, Rooms 124, 130, 325, PE Office and Apparatus Room	ASSUMED	MISC	N				No	ACBM with the potential for damage	3	MODERATE
01B	12x12 Taupe Floor Tile	670	SF	Gymnasium, Rooms 103, 206, 208, 305, 306, 308 and the Kindergarten Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	Vinyl Duct Sleeves NOT OBSERVED			Heat Pumps in the Ceiling		MISC								
05A	Brown Vinyl Baseboard	3,940	LF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05B	Black Vinyl Baseboard	1,700	LF	1st Floor- Kindergarten and Offices, 2nd Floor- Rooms 206 and 208, 3rd Floor- Rooms 300-308	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06A	12x12 Off-White Speckled Floor Tile Mastic	25,000	SF	1st Floor- Gym, Cafeteria, Vault, Corridors, Workroom, Science Lab/ Throughout - 2nd and 3rd Floor Corridors, Science Lab, Rooms 124, 130 and 325, PE Office and the Apparatus Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06B	12x12 Taupe Floor Tile Mastic	750	SF	Gymnasium, Rooms 103, 206, 208, 305, 306, 308 and All Kindergarten Rooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07A	Brown Vinyl Baseboard Mastic	3,940	LF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07B	Black Vinyl Baseboard	1,700	LF	1st Floor-	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Ninos Heroes **Unit** 31101 **Building ID** 3720
Address 8344 S Commercial **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Kindergarten and Offices, 2nd Floor-Rooms 206 and 208, 3rd Floor- Rooms 300-308								potential for damage		
08	Drywall	0	SF	Cafeteria, Stairwells, Library, Room 216 & the 3rd Floor Central Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	Drywall Compound	250	SF	Cafeteria, Stairwells, Library, Room 216 & the 3rd Floor Central Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	Hardcoat Plaster	550	SF	Cafeteria Pillars	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
11	Interior Window Glazing	3,460	LF	Rooms with Exterior Windows	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Interior Window Caulking	2,754	LF	Rooms with Exterior Windows	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	Building Expansion Joint Compound	100	LF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	12x12 White w/Pink Speckles Floor Tile NOT OBSERVED	70	SF	2nd and 3rd Floor Women's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
14A	12x12 White w/Pink Speckles Floor Tile Mastic NOT OBSERVED	70	SF	2nd & 3rd Floor Women's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12x12 White w/Blue Speckles Floor Tile NOT OBSERVED	70	SF	2nd & 3rd Floor Men's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15A	12x12 White w/Blue Speckles Floor Tile Mastic NOT OBSERVED	70	SF	2nd & 3rd Floor Men's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	2'x4' White Fissured Lay-In Ceiling Tile	65,000	SF	Throughout School (excluding the Gym)	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
17	Spray-On Fireproofing on Beams	30,000	LF	Throughout School	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
18	Tan Carpet Adhesive	7,000	SF	1st Floor Storage, Faculty Room, Rooms 202, 314, 315, 316 and 330, MDF Room and the Resource Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Gray Carpet Adhesive	4,172	SF	3rd Floor Hall Patch, Student Services Office, Business	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Ninos Heroes **Unit** 31101 **Building ID** 3720
Address 8344 S Commercial **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Office, Rooms 225, 302, 312 and 313										
20	Blue Carpet Adhesive	28	SF	Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Purple Carpet Adhesive	13,812	SF	Principal's Office, Conference Room, Rooms 101, 201, 205, 207, 211, 212, 326, 329, 200, 232, 223, 226, 300, Business Office & Student Services	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Gray Ceramic Tile Grout	1,482	SF	1st, 2nd & 3rd Floor Girls and Boys' Washrooms and 1st Floor Men's and Women's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Gray Ceramic Tile Adhesive	1,482	SF	1st, 2nd & 3rd Floor Girls' and Boys' Washrooms and 1st Floor Men's and Women's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Brown Ceramic Tile Grout	1,295	SF	Vestibules and Kitchen Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Brown Ceramic Tile Adhesive	1,295	SF	Vestibules and Kitchen Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Blue Carpet Mastic	1,800	SF	Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12x12 White w/Multicolor Speckles Vinyl Floor Tile NOT OBSERVED	200	SF	Main Office and the Men's and Women's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
28	12x12 White w/Multicolor Speckles Vinyl Floor Tile Mastic NOT OBSERVED	200	SF	Main Office and Men's and Women's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12x12 Brown Floor Tile	1,000	SF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12x12 Brown Floor Tile Mastic	1,000	SF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12x12 Cream Floor Tile	300	SF	Library Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	12x12 Cream Floor Mastic	300	SF	Library Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Ninos Heroes **Unit** 31101 **Building ID** 3720
Address 8344 S Commercial **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
33	12x12 Blue Speckled Floor Tile	16	SF	Library Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	12x12 Blue Speckled Floor Tile Mastic	16	SF	Library Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	12x12 Off-White w/Tan Speckles Floor Tile	1,200	SF	Gym Office and Apparatus Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12x12 Off-White w/Tan Speckles Floor Tile Mastic	1,200	SF	PE Office and Apparatus Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	12x12 Beige W/Brown Specks Vinyl Floor Tile ABATED 2014			Room 101, 201, 200, 205, 211, 207, 212, 222, 223, 226, 300, 301, 307, 326, 329, 330, 325	ABATED	MISC								
38	12x12 Beige W/Brown Specks Vinyl Floor Tile Mastic ABATED 2014			Rooms 101, 201, 200, 205, 211, 207, 212, 222, 223, 226, 300, 301, 307, 326, 329, 330, 325	ABATED	MISC								
39	Brown Tan Specks Carpet Mastic	2,000	SF	Principal Office, Conference RM, Business Office, Student Services	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	12"x12" Green, Cream & Navy Floor Tile	750	SF	Main Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
40M	Mastic associated w/12"x12" Green Cream & Navy Floor Tile	750	SF	Main Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
41	2'x2' Smooth Ceiling Tile	1,800	SF	Lunchroom & Kitchen	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
42	Sink Undercoating	5	EA	Rooms 105, 202, 205, 302 & 305	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
43	Stage Curtains	300	SF	Lunchroom Stage	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN	0		Yes	ACBM with the potential for damage		

Chicago Public Schools

School Ninos Heroes Unit 31101 Building ID 3720
Address 8344 S Commercial Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>5/20/2025</u>
Inspector Name <u>Josh Herman</u>
<u>100-21040</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01A	
01B	
04	
05A	
05B	
06A	
06B	
07A	
07B	
08	
09	
10	
11	
12	
13	
14	Not Observed 2025
14A	Not Observed 2025
15	Not Observed 2025
15A	Not Observed 2025
16	
17	
18	
19	
20	

Chicago Public Schools

School Ninos Heroes **Unit** 31101 **Building ID** 3720
Address 8344 S Commercial **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
21	
22	
23	
24	
25	
26	
27	Not Observed 2025
28	Not Observed 2025
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
40M	
41	
42	
43	
NEW	

Chicago Public Schools

School Ninos Heroes **Unit** 31101 **Building ID** 3720
Address 8344 S Commercial **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive
Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Table II
Management Planner's Review

Chicago Public Schools

School Ninos Heroes

Unit 31101

Building ID 3720

Address 8344 S Commercial

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01A	12x12 Off-White Speckled Floor Tile	25,000	SF	On 1sr Floor- Gym, Cafeteria, Vault, Corridors, Workroom, Science Lab;L Throughout- 2nd & 3rd Floor Corridors, Science Lab, Rooms 124, 130, 325, PE Office and Apparatus Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
01B	12x12 Taupe Floor Tile	670	SF	Gymnasium, Rooms 103, 206, 208, 305, 306, 308 and the Kindergarten Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	Vinyl Duct Sleeves NOT OBSERVED			Heat Pumps in the Ceiling		MISC					
05A	Brown Vinyl Baseboard	3,940	LF	Throughout	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
05B	Black Vinyl Baseboard	1,700	LF	1st Floor- Kindergarten and Offices, 2nd Floor- Rooms 206 and 208, 3rd Floor- Rooms 300-308	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
06A	12x12 Off-White Speckled Floor Tile Mastic	25,000	SF	1st Floor- Gym, Cafeteria, Vault, Corridors, Workroom, Science Lab/ Throughout - 2nd and 3rd Floor Corridors, Science Lab, Rooms 124, 130 and 325, PE Office and the Apparatus Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06B	12x12 Taupe Floor Tile Mastic	750	SF	Gymnasium, Rooms 103, 206, 208, 305, 306, 308 and All Kindergarten Rooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07A	Brown Vinyl Baseboard Mastic	3,940	LF	Throughout	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
07B	Black Vinyl Baseboard	1,700	LF	1st Floor- Kindergarten and Offices, 2nd Floor- Rooms 206 and 208, 3rd Floor- Rooms 300-308	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
08	Drywall	0	SF	Cafeteria, Stairwells, Library, Room 216 & the 3rd Floor Central Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	Drywall Compound	250	SF	Cafeteria, Stairwells, Library, Room 216 & the 3rd Floor Central Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	Hardcoat Plaster	550	SF	Cafeteria Pillars	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Interior Window Glazing	3,460	LF	Rooms with Exterior Windows	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
12	Interior Window Caulking	2,754	LF	Rooms with Exterior Windows	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
13	Building Expansion Joint Compound	100	LF	Throughout	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
14	12x12 White w/Pink Speckles Floor Tile NOT OBSERVED	70	SF	2nd and 3rd Floor Women's Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Ninos Heroes

Unit 31101

Building ID 3720

Address 8344 S Commercial

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
14A	12x12 White w/Pink Speckles Floor Tile Mastic NOT OBSERVED	70	SF	2nd & 3rd Floor Women's Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12x12 White w/Blue Speckles Floor Tile NOT OBSERVED	70	SF	2nd & 3rd Floor Men's Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	12x12 White w/Blue Speckles Floor Tile Mastic NOT OBSERVED	70	SF	2nd & 3rd Floor Men's Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	2'x4' White Fissured Lay-In Ceiling Tile	65,000	SF	Throughout School (excluding the Gym)	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Spray-On Fireproofing on Beams	30,000	LF	Throughout School	Assumed	SURFACE	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
18	Tan Carpet Adhesive	7,000	SF	1st Floor Storage, Faculty Room, Rooms 202, 314, 315, 316 and 330, MDF Room and the Resource Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Gray Carpet Adhesive	4,172	SF	3rd Floor Hall Patch, Student Services Office, Business Office, Rooms 225, 302, 312 and 313	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Blue Carpet Adhesive	28	SF	Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Purple Carpet Adhesive	13,812	SF	Principal's Office, Conference Room, Rooms 101, 201, 205, 207, 211, 212, 326, 329, 200, 232, 223, 226, 300, Business Office & Student Services	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Gray Ceramic Tile Grout	1,482	SF	1st, 2nd & 3rd Floor Girls' and Boys' Washrooms and 1st Floor Men's and Women's Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Gray Ceramic Tile Adhesive	1,482	SF	1st, 2nd & 3rd Floor Girls' and Boys' Washrooms and 1st Floor Men's and Women's Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Brown Ceramic Tile Grout	1,295	SF	Vestibules and Kitchen Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Brown Ceramic Tile Adhesive	1,295	SF	Vestibules and Kitchen Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Blue Carpet Mastic	1,800	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12x12 White w/Multicolor Speckles Vinyl Floor Tile NOT OBSERVED	200	SF	Main Office and the Men's and Women's Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12x12 White w/Multicolor Speckles Vinyl Floor Tile Mastic NOT OBSERVED	200	SF	Main Office and Men's and Women's Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12x12 Brown Floor Tile	1,000	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12x12 Brown Floor Tile Mastic	1,000	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12x12 Cream Floor Tile	300	SF	Library Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Ninos Heroes

Unit 31101

Building ID 3720

Address 8344 S Commercial

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
32	12x12 Cream Floor Mastic	300	SF	Library Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12x12 Blue Speckled Floor Tile	16	SF	Library Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12x12 Blue Speckled Floor Tile Mastic	16	SF	Library Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12x12 Off-White w/Tan Speckles Floor Tile	1,200	SF	Gym Office and Apparatus Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12x12 Off-White w/Tan Speckles Floor Tile Mastic	1,200	SF	PE Office and Apparatus Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12x12 Beige W/Brown Specks Vinyl Floor Tile ABATED 2014			Room 101, 201, 200, 205, 211, 207, 212, 222, 223, 226, 300, 301, 307, 326, 329, 330, 325	Abated	MISC					
38	12x12 Beige W/Brown Specks Vinyl Floor Tile Mastic ABATED 2014			Rooms 101, 201, 200, 205, 211, 207, 212, 222, 223, 226, 300, 301, 307, 326, 329, 330, 325	Abated	MISC					
39	Brown Tan Specks Carpet Mastic	2,000	SF	Principal Office, Conference RM, Business Office, Student Services	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12"x12" Green, Cream & Navy Floor Tile	750	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40M	Mastic associated w/12"x12" Green Cream & Navy Floor Tile	750	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	2'x2' Smooth Ceiling Tile	1,800	SF	Lunchroom & Kitchen	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Sink Undercoating	5	EA	Rooms 105, 202, 205, 302 & 305	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
43	Stage Curtains	300	SF	Lunchroom Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC		0		6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Ninos Heroes

Unit 31101

Building ID 3720

Address 8344 S Commercial

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	6/16/2025
Manager Planner Name	James Tuinenga
100-00349	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
01A	
01B	
04	
05A	
05B	
06A	
06B	
07A	
07B	
08	
09	
10	
11	
12	
13	
14	
14A	
15	

Chicago Public Schools

School Ninos Heroes

Unit 31101

Building ID 3720

Address 8344 S Commercial

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
15A	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
40M	

Chicago Public Schools

School Ninos Heroes

Unit 31101

Building ID 3720

Address 8344 S Commercial

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
41	
42	
43	
NEW	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01A		
MATERIAL DESCRIPTION:	12x12 Off-White Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Deterioration		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	On 1sr Floor- Gym, Cafeteria, Vault, Corridors, Workroom, Science Lab;L Throughout- 2nd & 3rd Floor Corridors, Science Lab, Rooms 124, 130, 325, PE Office and Apparatus Room		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA:	01A				
MATERIAL DESCRIPTION:	12x12 Off-White Speckled Floor Tile				
MATERIAL LOCATION:	On 1sr Floor- Gym, Cafeteria, Vault, Corridors, Workroom, Science Lab;L Throughout- 2nd & 3rd Floor Corridors, Science Lab, Rooms 124, 130, 325, PE Office and Apparatus Room				
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:		DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01B		
MATERIAL DESCRIPTION:	12x12 Taupe Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gymnasium, Rooms 103, 206, 208, 305, 306, 308 and the Kindergarten Rooms		
MATERIAL QUANTITY:	670	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	DAMAGE UNITS: SF		
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **01B**

MATERIAL DESCRIPTION: **12x12 Taupe Floor Tile**

MATERIAL LOCATION: **Gymnasium, Rooms 103, 206, 208, 305, 306, 308 and the Kindergarten Rooms**

MATERIAL QUANTITY: **670** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **Vinyl Duct Sleeves NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **FRIABLE**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Heat Pumps in the Ceiling**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/20/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **Vinyl Duct Sleeves NOT OBSERVED**

MATERIAL LOCATION: **Heat Pumps in the Ceiling**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05A		
MATERIAL DESCRIPTION:	Brown Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	3940	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **05A**

MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **3940** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05B		
MATERIAL DESCRIPTION:	Black Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor- Kindergarten and Offices, 2nd Floor- Rooms 206 and 208, 3rd Floor- Rooms 300-308**

MATERIAL QUANTITY: **1700** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/20/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA:	05B				
MATERIAL DESCRIPTION:	Black Vinyl Baseboard				
MATERIAL LOCATION:	1st Floor- Kindergarten and Offices, 2nd Floor- Rooms 206 and 208, 3rd Floor- Rooms 300-308				
MATERIAL QUANTITY:	1700	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06A		
MATERIAL DESCRIPTION:	12x12 Off-White Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor- Gym, Cafeteria, Vault, Corridors, Workroom, Science Lab/ Throughout - 2nd and 3rd Floor Corridors, Science Lab, Rooms 124, 130 and 325, PE Office and the Apparatus Room**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/20/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA:	06A				
MATERIAL DESCRIPTION:	12x12 Off-White Speckled Floor Tile Mastic				
MATERIAL LOCATION:	1st Floor- Gym, Cafeteria, Vault, Corridors, Workroom, Science Lab/ Throughout - 2nd and 3rd Floor Corridors, Science Lab, Rooms 124, 130 and 325, PE Office and the Apparatus Room				
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06B		
MATERIAL DESCRIPTION:	12x12 Taupe Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gymnasium, Rooms 103, 206, 208, 305, 306, 308 and All Kindergarten Rooms		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **06B**

MATERIAL DESCRIPTION: **12x12 Taupe Floor Tile Mastic**

MATERIAL LOCATION: **Gymnasium, Rooms 103, 206, 208, 305, 306, 308 and All Kindergarten Rooms**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07A		
MATERIAL DESCRIPTION:	Brown Vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	3940	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **07A**

MATERIAL DESCRIPTION: **Brown Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **3940** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07B		
MATERIAL DESCRIPTION:	Black Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor- Kindergarten and Offices, 2nd Floor- Rooms 206 and 208, 3rd Floor- Rooms 300-308		
MATERIAL QUANTITY:	1700	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA:	07B				
MATERIAL DESCRIPTION:	Black Vinyl Baseboard				
MATERIAL LOCATION:	1st Floor- Kindergarten and Offices, 2nd Floor- Rooms 206 and 208, 3rd Floor- Rooms 300-308				
MATERIAL QUANTITY:	1700	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria, Stairwells, Library, Room 216 & the 3rd Floor Central Corridor		
MATERIAL QUANTITY:	0	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Cafeteria, Stairwells, Library, Room 216 & the 3rd Floor Central Corridor**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	Drywall Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria, Stairwells, Library, Room 216 & the 3rd Floor Central Corridor		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **Drywall Compound**

MATERIAL LOCATION: **Cafeteria, Stairwells, Library, Room 216 & the 3rd Floor Central Corridor**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	Hardcoat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria Pillars		
MATERIAL QUANTITY:	550	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Hardcoat Plaster**

MATERIAL LOCATION: **Cafeteria Pillars**

MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Interior Window Glazing		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms with Exterior Windows		
MATERIAL QUANTITY:	3460	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Interior Window Glazing**

MATERIAL LOCATION: **Rooms with Exterior Windows**

MATERIAL QUANTITY: **3460** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	Interior Window Caulking		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms with Exterior Windows		
MATERIAL QUANTITY:	2754	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Interior Window Caulking**

MATERIAL LOCATION: **Rooms with Exterior Windows**

MATERIAL QUANTITY: **2754** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	Building Expansion Joint Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Building Expansion Joint Compound**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12x12 White w/Pink Speckles Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	2nd and 3rd Floor Women's Washrooms		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: **05/20/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12x12 White w/Pink Speckles Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **2nd and 3rd Floor Women's Washrooms**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14A		
MATERIAL DESCRIPTION:	12x12 White w/Pink Speckles Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd & 3rd Floor Women's Washrooms		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **14A**

MATERIAL DESCRIPTION: **12x12 White w/Pink Speckles Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **2nd & 3rd Floor Women's Washrooms**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	12x12 White w/Blue Speckles Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd & 3rd Floor Men's Washrooms		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12x12 White w/Blue Speckles Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **2nd & 3rd Floor Men's Washrooms**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15A		
MATERIAL DESCRIPTION:	12x12 White w/Blue Speckles Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd & 3rd Floor Men's Washrooms		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **15A**

MATERIAL DESCRIPTION: **12x12 White w/Blue Speckles Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **2nd & 3rd Floor Men's Washrooms**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	2'x4' White Fissured Lay-In Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout School (excluding the Gym)		
MATERIAL QUANTITY:	65000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **2'x4' White Fissured Lay-In Ceiling Tile**

MATERIAL LOCATION: **Throughout School (excluding the Gym)**

MATERIAL QUANTITY: **65000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	Spray-On Fireproofing on Beams		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout School		
MATERIAL QUANTITY:	30000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Spray-On Fireproofing on Beams**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: **30000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	Tan Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Storage, Faculty Room, Rooms 202, 314, 315, 316 and 330, MDF Room and the Resource Room**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/20/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Tan Carpet Adhesive**

MATERIAL LOCATION: **1st Floor Storage, Faculty Room, Rooms 202, 314, 315, 316 and 330, MDF Room and the Resource Room**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	Gray Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Hall Patch, Student Services Office, Business Office, Rooms 225, 302, 312 and 313**

MATERIAL QUANTITY: **4172** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/20/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Gray Carpet Adhesive**

MATERIAL LOCATION: **3rd Floor Hall Patch, Student Services Office, Business Office, Rooms 225, 302, 312 and 313**

MATERIAL QUANTITY: **4172** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Blue Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Elevator		
MATERIAL QUANTITY:	28	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

MATERIAL LOCATION: **Elevator**

MATERIAL QUANTITY: **28** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	Purple Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Principal's Office, Conference Room, Rooms 101, 201, 205, 207, 211, 212, 326, 329, 200, 232, 223, 226, 300, Business Office & Student Services**

MATERIAL QUANTITY: **13812** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/20/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Purple Carpet Adhesive**

MATERIAL LOCATION: **Principal's Office, Conference Room, Rooms 101, 201, 205, 207, 211, 212, 326, 329, 200, 232, 223, 226, 300, Business Office & Student Services**

MATERIAL QUANTITY: **13812** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	Gray Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd & 3rd Floor Girls' and Boys' Washrooms and 1st Floor Men's and Women's Washrooms		
MATERIAL QUANTITY:	1482	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Gray Ceramic Tile Grout**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Girls' and Boys' Washrooms and 1st Floor Men's and Women's Washrooms**

MATERIAL QUANTITY: **1482** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Gray Ceramic Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd & 3rd Floor Girls' and Boys' Washrooms and 1st Floor Men's and Women's Washrooms		
MATERIAL QUANTITY:	1482	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Gray Ceramic Tile Adhesive**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Girls' and Boys' Washrooms and 1st Floor Men's and Women's Washrooms**

MATERIAL QUANTITY: **1482** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	Brown Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Vestibules and Kitchen Area		
MATERIAL QUANTITY:	1295	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout**

MATERIAL LOCATION: **Vestibules and Kitchen Area**

MATERIAL QUANTITY: **1295** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Brown Ceramic Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Vestibules and Kitchen Area		
MATERIAL QUANTITY:	1295	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Brown Ceramic Tile Adhesive**

MATERIAL LOCATION: **Vestibules and Kitchen Area**

MATERIAL QUANTITY: **1295** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	Blue Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	12x12 White w/Multicolor Speckles Vinyl Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Main Office and the Men's and Women's Washrooms		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: **05/20/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12x12 White w/Multicolor Speckles Vinyl Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Main Office and the Men's and Women's Washrooms**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12x12 White w/Multicolor Speckles Vinyl Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office and Men's and Women's Washrooms		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12x12 White w/Multicolor Speckles Vinyl Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **Main Office and Men's and Women's Washrooms**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	12x12 Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12x12 Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	12x12 Cream Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library Office		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12x12 Cream Floor Tile**

MATERIAL LOCATION: **Library Office**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	12x12 Cream Floor Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library Office		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUILDING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12x12 Cream Floor Mastic**

MATERIAL LOCATION: **Library Office**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	12x12 Blue Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library Office		
MATERIAL QUANTITY:	16	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12x12 Blue Speckled Floor Tile**

MATERIAL LOCATION: **Library Office**

MATERIAL QUANTITY: **16** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	12x12 Blue Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library Office		
MATERIAL QUANTITY:	16	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12x12 Blue Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Library Office**

MATERIAL QUANTITY: **16** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12x12 Off-White w/Tan Speckles Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Office and Apparatus Room		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12x12 Off-White w/Tan Speckles Floor Tile**

MATERIAL LOCATION: **Gym Office and Apparatus Room**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12x12 Off-White w/Tan Speckles Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	PE Office and Apparatus Room		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12x12 Off-White w/Tan Speckles Floor Tile Mastic**

MATERIAL LOCATION: **PE Office and Apparatus Room**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 37

MATERIAL DESCRIPTION: 12x12 Beige W/Brown Specks Vinyl Floor Tile ABATED 2014

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 101, 201, 200, 205, 211, 207, 212, 222, 223, 226, 300, 301, 307, 326, 329, 330, 325

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12x12 Beige W/Brown Specks Vinyl Floor Tile ABATED 2014**

MATERIAL LOCATION: **Room 101, 201, 200, 205, 211, 207, 212, 222, 223, 226, 300, 301, 307, 326, 329, 330, 325**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38	
MATERIAL DESCRIPTION:	12x12 Beige W/Brown Specks Vinyl Floor Tile Mastic ABATED 2014	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 101, 201, 200, 205, 211, 207, 212, 222, 223, 226, 300, 301, 307, 326, 329, 330, 325

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12x12 Beige W/Brown Specks Vinyl Floor Tile Mastic ABATED 2014**

MATERIAL LOCATION: **Rooms 101, 201, 200, 205, 211, 207, 212, 222, 223, 226, 300, 301, 307, 326, 329, 330, 325**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	Brown Tan Specks Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Principal Office, Conference RM, Business Office, Student Services		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:	6/16/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Brown Tan Specks Carpet Mastic**

MATERIAL LOCATION: **Principal Office, Conference RM, Business Office, Student Services**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	NEW		
MATERIAL DESCRIPTION:	Newly Installed Suspect ACM		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/20/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:		James Tuinenga	
SCHOOL NAME:	Ninos Heroes	REVIEW DATE:			6/16/2025
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:			100-21040

HOMOGENEOUS AREA: **NEW**

MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**

MATERIAL LOCATION: Installed After Implementation of Management Plan and After Renovations

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: 0

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:

Jan Semigin

Date: 06/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	2'x2' Smooth Ceiling Tile		
MATERIAL LOCATION:	Lunchroom & Kitchen		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31101** BUIDLING ID: **3720**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Ninos Heroes** REVIEW DATE: **6/16/2025**

ADDRESS: **8344 S Commercial** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **2'x2' Smooth Ceiling Tile**

MATERIAL LOCATION: **Lunchroom & Kitchen**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	Stage Curtains		
MATERIAL LOCATION:	Lunchroom Stage		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31101** BUIDLING ID: **3720**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Ninos Heroes** REVIEW DATE: **6/16/2025**

ADDRESS: **8344 S Commercial** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Stage Curtains**

MATERIAL LOCATION: **Lunchroom Stage**


MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	12"x12" Green, Cream & Navy Floor Tile		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31101** BUIDLING ID: **3720**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Ninos Heroes** REVIEW DATE: **6/16/2025**

ADDRESS: **8344 S Commercial** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12"x12" Green, Cream & Navy Floor Tile**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **06/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	42				
MATERIAL DESCRIPTION:	Sink Undercoating				
MATERIAL LOCATION:	Rooms 105, 202, 205, 302 & 305				
MATERIAL QUANTITY:	5	MATERIAL UNITS:	EA		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	EA		

COMMENTS:

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31101** BUIDLING ID: **3720**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Ninos Heroes** REVIEW DATE: **6/16/2025**

ADDRESS: **8344 S Commercial** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Sink Undercoating**

MATERIAL LOCATION: **Rooms 105, 202, 205, 302 & 305**


MATERIAL QUANTITY: **5** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31101	BUIDLING ID:	3720
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Ninos Heroes	INSPECTION DATE:	5/20/2025		
ADDRESS:	8344 S Commercial	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	40M				
MATERIAL DESCRIPTION:	Mastic associated w/12"x12" Green Cream & Navy Floor Tile				
MATERIAL LOCATION:	Main Office				
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 05/20/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31101** BUIDLING ID: **3720**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Ninos Heroes** REVIEW DATE: **6/16/2025**

ADDRESS: **8344 S Commercial** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **40M**

MATERIAL DESCRIPTION: **Mastic associated w/12"x12" Green Cream & Navy Floor Tile**

MATERIAL LOCATION: **Main Office**


MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/16/2025

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JOSH R HERMAN
5121 N MONITOR AVE
CHICAGO, IL 60630

5/23/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 21040

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



**ASBESTOS
PROFESSIONAL
LICENSE**

ENDORSEMENTS

TC EXPIRES

INSPECTOR

7/19/2025

ID NUMBER
100 - 21040

ISSUED
5/23/2025

EXPIRES
05/15/2026

JOSH R HERMAN
5121 N MONITOR AVE
CHICAGO, IL 60630
Environmental Health



Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

Reliable
Environmental
Solutions, Inc. **R | E | S**

This is to certify that

James Tuinenga

*has on 2/2/22, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Building Inspector Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher.*

Course Date: February 2, 2022

COURSE LENGTH: 4 HOURS

Examination Date: February 2, 2022

Expiration Date: February 2, 2023

Certificate Number: BIR/1013

William S. Williams


Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois 217.787.9800 217.787.9801 FAX www.ReliableEnv.com



TEM ENVIRONMENTAL, INC.

ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



ENDORSEMENTS

INSPECTOR	2/2/2023
PROJECT DESIGNER	2/3/2023
MANAGEMENT PLANNER	2/2/2023
PROJECT MANAGER	2/1/2023
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

Reliable
Environmental
Solutions, Inc. **R E S**

This is to certify that

James Tuinenga

*has on 2/02/22, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: February 2, 2022

COURSE LENGTH: 4 HOURS

Examination Date: February 2, 2022

Expiration Date: February 2, 2023

William S. Williams


Certificate Number: MPR/0458

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois 217.787.9800 217.787.9801 FAX www.ReliableEnv.com



TEM ENVIRONMENTAL, INC.
ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



ENDORSEMENTS

INSPECTOR
PROJECT DESIGNER
MANAGEMENT PLANNER
PROJECT MANAGER
AIR SAMPLING PROFESSIONAL

TC EXPIRES

1/31/2025
2/1/2025
1/31/2025
1/30/2025

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

**Reliable
Environmental
Solutions, Inc. R E S**

This is to certify that

James Tuinenga

*has on 2/5/25, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Building Inspector Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher.*

Course Date: February 5, 2025

COURSE LENGTH: 4 HOURS

Examination Date: February 5, 2025

Expiration Date: February 5, 2026

Certificate Number: BIR/1227




Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois 217.787.9800 www.ReliableEnv.com



TEM ENVIRONMENTAL, INC.

ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



ENDORSEMENTS

INSPECTOR
PROJECT DESIGNER
MANAGEMENT PLANNER
PROJECT MANAGER
AIR SAMPLING PROFESSIONAL

TC EXPIRES

2/5/2026
2/6/2025
2/5/2026
2/4/2026

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**Reliable
Environmental
Solutions, Inc.** **R E S**

This is to certify that

James Tuinenga

*has on 2/5/25, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: February 5, 2025

COURSE LENGTH: 4 HOURS

Examination Date: February 5, 2025

Expiration Date: February 5, 2026

Certificate Number: MPR/0546



Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois 217.787.9800 www.ReliableEnv.com

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed