

## Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition<sup>1</sup>. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at [http://www.cps.edu/About\\_CPS/Policies\\_and\\_guidelines/Pages/facilitystandards.aspx](http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx). Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1913	4	219,500	\$9,225,834
Addition 1	1930	3	33,906	\$3,012,780
Addition 2	1930	3	37,798	\$2,983,560
SITE				\$304,677
<b>Campus Total</b>			<b>291,204</b>	<b>\$15,526,851</b>

### Building: Main

#### Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Entrance</b>							
	Entrance Control - Audio and Video	10 - Main	2	EA	6	\$1,403	
	Exterior Doors - Exterior AMP Door	10 - Main	4	EA	6	\$2,696	
	Exterior Doors - Exterior Steel Door	4	10	EA	6	\$4,806	
	Exterior Doors - Transom Lite	10 - Main	2	EA	6	\$627	
	Exterior Doors - Transom Lite	4	10	EA	6	\$3,133	
	Exterior Stairs - Concrete	4	300	LF	5	\$32,874	cracking, spalling
<b>Foundation</b>							
	Foundation - Concrete	Entire Building	1,314	LF	7	\$0	
	Superstructure - Steel with Clay Tile Arch	Entire Building	1,032	SF	6	\$0	sinking floor
	Superstructure - Steel with Clay Tile Arch	Entire Building	558	SF	6	\$0	sinking floor
	Superstructure - Steel with Clay Tile Arch	Entire Building	282	SF	5	\$0	sinking floor/walls
	Superstructure - Steel with Clay Tile Arch	Entire Building	218,186	SF	7	\$0	
<b>Lighting</b>							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	6	\$2,146	
	Exterior Lighting - Wall Mounted	Entire Building	20	EA	6	\$5,775	

## Building: Main

### Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Roof System</b>							
	Coping - Clay Tile	E	196	LF	6	\$6,295	
	Coping - Clay Tile	J	88	LF	6	\$2,826	
	Coping - Clay Tile	K	24	LF	6	\$771	
	Coping - Metal	E	100	LF	5	\$7,090	corroded
	Coping - Metal	E	927	LF	6	\$29,773	
	Coping - Metal	G	200	LF	6	\$6,424	
	Coping - Metal	J	217	LF	6	\$6,970	
	Coping - Stone	H	94	LF	6	\$3,019	
	Coping - Stone	L	94	LF	6	\$3,019	
	Coping - Terra Cotta	E	269	LF	6	\$8,640	
	Coping - Terra Cotta	G	138	LF	6	\$4,432	
	Coping - Terra Cotta	I	286	LF	6	\$9,186	
	Coping - Terra Cotta	J	24	LF	6	\$771	
	Downspouts - Exterior Downspouts	E	236	LF	6	\$7,843	
	Downspouts - Exterior Downspouts	F	50	LF	6	\$1,662	
	Downspouts - Exterior Downspouts	H	35	LF	6	\$1,163	
	Downspouts - Exterior Downspouts	L	35	LF	6	\$1,163	
	Downspouts - Interior Downspouts	E	480	LF	6	\$15,952	debris
	Parapet - 16" - 30" Height	E	1,392	LF	6	\$55,616	
	Parapet - 16" - 30" Height	G	338	LF	6	\$13,505	
	Parapet - 16" - 30" Height	I	158	LF	6	\$6,313	
	Parapet - 16" - 30" Height	I	40	LF	5	\$8,149	bulging
	Parapet - 16" - 30" Height	J	329	LF	6	\$13,145	
	Parapet - 16" - 30" Height	K	24	LF	6	\$959	
	Parapet - Parapet > 30"	H	94	LF	6	\$6,009	
	Parapet - Parapet > 30"	I	128	LF	6	\$8,182	
	Parapet - Parapet > 30"	L	94	LF	6	\$6,009	
	Roof Structure - Steel with Clay Tile Arch	E	39,719	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	F	17,368	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	G	7,372	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	H	2,914	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	I	6,504	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	J	9,564	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	K	8,376	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	L	2,914	SF	7	\$0	
	Roof - Asphalt Shingle	I	5,184	SF	6	\$23,796	
	Roof - Metal	K	300	SF	5	\$8,267	

## Building: Main

### Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Roof System</b>							
	Roof - Modified Bitumen	E	39,719	SF	5	\$835,501	peeling, bubbling, cracking
	Roof - Modified Bitumen	F	17,368	SF	5	\$365,341	peeling, bubbling, cracking
	Roof - Modified Bitumen	G	7,372	SF	5	\$155,072	peeling, bubbling, cracking
	Roof - Modified Bitumen	H	2,914	SF	5	\$61,297	peeling, bubbling, cracking
	Roof - Modified Bitumen	I	1,320	SF	5	\$27,767	peeling, bubbling, cracking
	Roof - Modified Bitumen	J	9,564	SF	5	\$201,182	peeling, bubbling, cracking
	Roof - Modified Bitumen	K	8,076	SF	5	\$169,881	peeling, bubbling, cracking
	Roof - Modified Bitumen	L	2,914	SF	5	\$61,297	peeling, bubbling, cracking
<b>Walls</b>							
	Cheek-Wall	Entire Building	64	SF	5	\$0	spalling, chipping
	Cornice - Metal Projecting	Entire Building	1,330	LF	5	\$200,099	minor corroding throughout
	Exterior Walls - Brick	Entire Building	600	SF	6	\$5,448	efflorescence
	Exterior Walls - Brick	Entire Building	559	SF	5	\$13,310	ivy throughout
	Exterior Walls - Brick	Entire Building	30,096	SF	6	\$202,275	small nicks throughout from previous repointing work
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	768	SF	7	\$0	corrugated metal penthouse
	Exterior Walls - Stone-Cut	Entire Building	3,640	SF	6	\$24,464	some staining (atmospheric)
	Exterior Walls - Terra Cotta	Entire Building	6,851	SF	6	\$46,046	some staining (atmospheric)
	Exterior Walls - Terra Cotta	Entire Building	1,075	SF	5	\$15,588	ivy throughout
<b>Windows</b>							
	Guard - Guards perforated	Entire Building	963	SF	5	\$14,762	ivy throughout
	Guard - Guards perforated	Entire Building	9,499	SF	6	\$121,301	
	Lintels - Brick	Entire Building	22	LF	7	\$0	
	Lintels - Steel	Entire Building	2,778	LF	6	\$80,643	
	Lintels - Stone	Entire Building	40	LF	7	\$0	
	Windows - Sash Aluminum Double-pane	Entire Building	1,445	SF	5	\$77,839	ivy throughout
	Windows - Sash Aluminum Double-pane	Entire Building	24,915	SF	6	\$185,981	

### Building Exterior Subtotal:

**\$3,185,500**

## Building: Main

### Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Emergency System</b>							
	Emergency A/C Power - Auditorium and Aisle Lighting	Entire Building	13,061	SF	6	\$6,911	
	Emergency A/C Power - Corridors and Stairs	Entire Building	41,541	SF	6	\$12,475	

## Building: Main

### Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Emergency System</b>							
	Emergency A/C Power - Gym	Entire Building	8,466	SF	6	\$3,148	
	Emergency A/C Power - Lunchrooms	Entire Building	11,500	SF	6	\$4,276	
	Emergency A/C Power - Multipurpose Room	Entire Building	1,344	SF	6	\$500	
	Emergency A/C Power - Pool	Entire Building	3,160	SF	6	\$1,175	
	Emergency A/C Power - Students Toilets	Entire Building	3,144	SF	6	\$1,169	
	Emergency Battery Packs - Lunchrooms	Entire Building	4	EA	6	\$810	
	Emergency Battery Packs - Pool	Entire Building	1	EA	6	\$203	
	Exit Signs - Auditorium	Entire Building	10	EA	6	\$1,497	
	Exit Signs - Corridors and Stairs	Entire Building	37	EA	6	\$5,541	
	Exit Signs - Gym	Entire Building	2	EA	6	\$315	
	Exit Signs - Lunchroom	Entire Building	9	EA	6	\$1,348	
	Exit Signs - Pool	Entire Building	3	EA	6	\$465	
	Security System - CCTV	Entire Building	290,922	SF	6	\$87,364	Serve entire school
	Security System - Intrusion Detection	Entire Building	290,922	SF	6	\$74,883	Serve entire school
<b>Main Service</b>							
	Main Electrical Service - Greater than 3000 A 120/208/3PH	Mechanical Room / Electrical Room	1	EA	6	\$16,381	Serves entire school
	PA System	Entire Building	290,922	SF	6	\$95,684	Serves entire school
<b>Power Distribution</b>							
	Lighting and Power Panels - 100 A	Entire Building	5	EA	7	\$0	
	Lighting and Power Panels - 100 A	Entire Building	40	EA	6	\$11,965	
	Main Distribution Panels - Greater than 600 amp	Entire Building	2	EA	7	\$0	
	Main Distribution Panels - Less than 400 amp	Entire Building	3	EA	7	\$0	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	\$0	
	Transformers - 120/240 - 120/208	Entire Building / Mechanical Room	1	EA	6	\$3,021	

**Electrical System Subtotal:** **\$329,129**

## Building: Main

### Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Fire Alarm</b>							
	Fire Alarm Strobe Lights	Entire Building	219,500	SF	6	\$78,471	Served from panel in addition 1

**Safty System Subtotal:** **\$78,471**

## Building: Main

## Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Air Conditioning</b>							
	Condensing Unit- Roof Mounted - 11-20 tons	Roof	1	EA	6	\$3,727	Serves pool AHU
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	2	EA	6	\$6,667	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	\$3,334	
<b>Air Handling Systems</b>							
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	7	\$0	AHU-5
	Air Handling Unit- Built Up-Multi Zone-Double Delivery-Dual Temperature Coils - 30001 - 45000 cfm	Mechanical Room / Entire Building	4	EA	7	\$0	The units are in good condition. The controls operate well, the doors are sealed, and dampers are in good condition.
	Air Handling Unit-Package Single Zone- Outdoor Roof Mounted- Hot Water and DX Cooling Coils - 4000-8000 cfm	Roof	1	EA	5	\$29,391	Unit is cooling only due to an internal control problem.
	Air Intake	Mechanical Room / Roof	4	EA	7	\$0	Each unit is served by a roof mounted return fan
	Air Intake	Mechanical Room / Roof	1	EA	7	\$0	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	7	\$0	
	Auxiliaries - 30001 - 45000 cfm	Mechanical Room / Entire Building	4	EA	7	\$0	
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	2	EA	7	\$0	
	Make Up Air Unit- Roof Mounted- Electric Coils - Less than 6000 cfm	Roof	1	EA	4	\$41,492	Retired in place
	Outdoor Return Fans- Air Handling Unit Type - Greater than 20000 CFM	Roof	5	EA	6	\$10,385	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Entire Building	100	LF	7	\$0	Served by return fan on roof
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Entire Building	100	LF	7	\$0	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Entire Building	100	LF	7	\$0	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Entire Building	100	LF	7	\$0	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Entire Building	100	LF	7	\$0	
	Zone Dampers	Mechanical Room / Entire Building	112	EA	6	\$93,300	New actuators for the hot deck/cold deck configuration
	Zone Dampers	Mechanical Room	9	EA	6	\$7,497	
<b>Heating Devices</b>							
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	\$1,417	
	Fin Tube - Hot Water	Entire Building	94	LF	6	\$887	
<b>Mechanical Plumbing</b>							
	Daul Temperature Pump - Greater than 50 HP	Boiler Room	2	EA	7	\$0	
	Daul Temperature Pump - Less than 10	Entire Building	5	EA	7	\$0	
	Hydronic Supply and Return - Steel	Entire Building	1,800	LF	6	\$138,198	
<b>Temperature Control</b>							
	DDC System	Entire Building	290,922	SF	6	\$166,407	Serves entire school
	Thermostats - DDC	Entire Building	125	EA	7	\$0	

## Building: Main

### Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Ventilation</b>							
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	2	EA	6	\$1,185	
	Exhaust Fans- Indoor - Greater than 8000 CFM	Entire Building	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	5	EA	6	\$2,962	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	3	EA	6	\$1,777	
	Lab Exhaust Hood	Entire Building	2	EA	6	\$2,495	
	Roof Mounted Duct Work	Entire Building / Roof	714	LF	7	\$0	
	Type I Exhaust Hood- Kitchen	Entire Building / 1st Floor	1	EA	2	\$28,265	

### Mechanical System Subtotal:

**\$539,980**

## Building: Main

### Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Piping</b>							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	219,500	SF	7	\$0	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	219,500	SF	7	\$0	
	Domestic Piping-Cold Water Risers	Entire Building	219,500	SF	6	\$40,805	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	219,500	SF	7	\$0	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	219,500	SF	7	\$0	
	Domestic Piping-Hot Water Return Lines	Entire Building	219,500	SF	7	\$0	
	Domestic Piping-Hot Water Return Risers	Entire Building	219,500	SF	6	\$31,389	
	Sanitary Piping	Entire Building	219,500	SF	6	\$200,886	
	Storm Piping	Entire Building	219,500	SF	6	\$191,470	
	Vent Piping	Entire Building	219,500	SF	6	\$147,526	

### Pool Systems

	Pool Drain Piping	Mechanical Room / 1st Floor	30	LF	6	\$859	
	Pool Filtration System including Pump	Mechanical Room / 1st Floor	1	EA	6	\$12,330	Filtration system needs to be reprogrammed
	Pool Hot Water Heater - Gas Fired	Mechanical Room / 1st Floor	1	EA	6	\$310	System uses a water to water plate and frame HX to heat pool water
	Pool Supply and Return Piping	Mechanical Room / 1st Floor	80	LF	6	\$3,844	

### Plumbing System Subtotal:

**\$629,419**

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-------	-------------	----------	----------	------	------	------	----------

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #158/160 (Weight)</b>							
	Ceiling - Lay-in		1,822	SF	6	\$5,471	needs tile some adjustment.
	Chalk Board		30	LF	4	\$2,754	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Floor - Weight/ Fitness Room Floor Matting		1,822	SF	6	\$9,536	
	Lighting - Lay-in		55	EA	6	\$6,544	
	Wall Mirrors		132	SF	6	\$0	
	Walls - Plaster/Drywall		1,120	SF	5	\$8,488	Peeling paint/material, cracks, water damage,
<b>Classroom #162 (Regular Classroom)</b>							
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Chalk Board		40	LF	4	\$3,672	Obsolete Material.
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Tile		730	SF	6	\$1,597	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Marker Board		24	LF	6	\$514	
	Walls - Plaster/Drywall		10	SF	3	\$147	Wall needs to be patched, currently patched with a plastic bag.
	Walls - Plaster/Drywall		500	SF	6	\$1,637	
	Walls - Plaster/Drywall		610	SF	5	\$4,623	
<b>Classroom #166 (Dance Room)</b>							
	Ceiling - Lay-in		1,488	SF	6	\$4,468	
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Floor - Tile		100	SF	6	\$219	
	Floor - Wood		1,388	SF	7	\$0	
	Lighting - Lay-in		42	EA	6	\$4,997	
	Marker Board		20	LF	6	\$428	
	Walls - Plaster/Drywall		1,804	SF	7	\$0	
<b>Classroom #172 (Regular Classroom)</b>							
	Ceiling - Lay-in		528	SF	6	\$1,586	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Tile		528	SF	6	\$1,155	
	Lighting - Lay-in		12	EA	6	\$1,428	
	Storage/ Closet		150	SF	6	\$1,088	
	Walls - Plaster/Drywall		1,025	SF	6	\$2,829	

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #174 (Regular Classroom)</b>							
	Ceiling - Lay-in		528	SF	6	\$1,586	
	Doors - Transom Window		12	SF	6	\$203	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		528	SF	6	\$1,155	
	Lighting - Lay-in		12	EA	6	\$1,428	
	Walls - Plaster/Drywall		945	SF	6	\$2,608	
<b>Classroom #176 (Regular Classroom)</b>							
	Casework		7	LF	5	\$1,464	
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Chalk Board		68	LF	4	\$6,243	Obsolete Material.
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Tile		730	SF	6	\$1,597	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Walls - Plaster/Drywall		1,120	SF	6	\$3,091	
<b>Classroom #219 (Regular Classroom)</b>							
	Casework		7	LF	5	\$1,464	missing and damaged hardware; damaged finish
	Ceiling - Lay-in		18	SF	4	\$253	water damage.
	Ceiling - Lay-in		1,012	SF	6	\$3,039	
	Chalk Board		53	LF	4	\$4,866	obsolete material
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		1,030	SF	6	\$7,261	sand and refinish
	Lighting - Lay-in		27	EA	6	\$3,212	replace damaged lense
	Walls - Plaster/Drywall		1,441	SF	7	\$0	
<b>Classroom #221 (Computer Lab)</b>							
	AC Units		2	EA	6	\$991	
	Casework		14	LF	6	\$354	damaged finishes
	Ceiling - Lay-in		1,500	SF	7	\$0	
	Chalk Board		40	LF	4	\$3,672	obsolete material
	Doors - Transom Window		48	SF	6	\$813	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Floor - Tile		1,500	SF	6	\$3,282	
	Lighting - Lay-in		24	EA	7	\$0	
	Marker Board		10	LF	6	\$214	
	Walls - Plaster/Drywall		1,490	SF	6	\$4,112	fresh paint over cracked plaster walls
	Wireless System		1	EA	6	\$372	



## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #221 (Computer Lab)</b>							
<b>Classroom #222 (Faculty Lounge)</b>							
	AC Units		2	EA	6	\$991	
	Casework		10	LF	6	\$253	
	Ceiling - Lay-in		705	SF	6	\$2,117	
	Doors - Transom Window		15	SF	6	\$254	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		705	SF	6	\$4,970	sand and refinish
	Lighting - Lay-in		21	EA	6	\$2,498	replace damaged lense
	Walls - Plaster/Drywall		1,140	SF	6	\$3,146	
	Work Sink		1	EA	6	\$379	damaged finish at faucet
<b>Classroom #230 (Regular Classroom)</b>							
	Casework		15	LF	6	\$379	
	Casework		10	LF	5	\$2,091	broken locks and drawers
	Ceiling - Lay-in		1,145	SF	7	\$0	
	Chalk Board		26	LF	4	\$2,387	obsolete material; partially covered.
	Doors - Transom Window		21	SF	5	\$889	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		1,145	SF	6	\$8,072	
	Lighting - Lay-in		32	EA	7	\$0	
	Walls - Plaster/Drywall		1,293	SF	6	\$3,569	
<b>Classroom #231-North (Office)</b>							
	AC Units		1	EA	4	\$6,086	damaged.
	Ceiling - Lay-in		580	SF	6	\$1,742	
	Chalk Board		30	LF	4	\$2,754	obsolete material
	Doors - Transom Window		21	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		580	SF	5	\$8,485	damaged - sand and refinish
	Lighting - Lay-in		15	EA	7	\$0	
	Walls - Plaster/Drywall		1,092	SF	6	\$3,014	cracked/flaking plaster
<b>Classroom #231-South (Health)</b>							
	AC Units		1	EA	6	\$496	
	Casework		7	LF	5	\$1,464	damaged hardware and finish
	Ceiling - Lay-in		580	SF	6	\$1,742	
	Chalk Board		30	LF	4	\$2,754	obsolete material
	Doors - Transom Window		21	SF	7	\$0	

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #231-South (Health)</b>							
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		580	SF	5	\$8,485	creaking and warped floorboards; damaged finish
	Lighting - Lay-in		10	EA	7	\$0	
	Walls - Plaster/Drywall		1,448	SF	6	\$3,996	
	Work Sink		1	EA	6	\$379	
<b>Classroom #233 (Regular Classroom)</b>							
	AC Units		1	EA	4	\$6,086	
	AC Units		1	EA	6	\$496	
	Casework		10	LF	6	\$253	damaged finish
	Ceiling - Lay-in		1,130	SF	6	\$3,393	
	Chalk Board		20	LF	4	\$1,836	obsolete material
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Tile		1,130	SF	5	\$5,074	
	Lighting - Lay-in		34	EA	7	\$0	
	Marker Board		10	LF	6	\$214	
	Walls - Plaster/Drywall		1,441	SF	6	\$3,977	
<b>Classroom #234 (Computer Lab)</b>							
	AC Units		2	EA	7	\$0	
	Ceiling - Lay-in		1,030	SF	7	\$0	
	Charging Station		1	EA	7	\$0	
	Doors - Transom Window		42	SF	6	\$711	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Floor - Wood		1,030	SF	6	\$7,261	
	Lighting - Lay-in		27	EA	7	\$0	
	Marker Board		36	LF	7	\$0	
	Walls - Plaster/Drywall		1,440	SF	6	\$3,974	cracked plaster below fresh coat of paint
	Wireless System		1	EA	6	\$372	
<b>Classroom #236 (Regular Classroom)</b>							
	Casework		7	LF	5	\$1,464	damaged doors, hardware, doors & finish
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Chalk Board		28	LF	4	\$2,571	obsolete material
	Doors - Transom Window		21	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	6	\$5,146	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Walls - Plaster/Drywall		200	SF	5	\$1,021	cracked and damaged plaster

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #236 (Regular Classroom)</b>							
	Walls - Plaster/Drywall		1,960	SF	6	\$5,409	
<b>Classroom #260 (Regular Classroom)</b>							
	AC Units		2	EA	5	\$3,652	
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		730	SF	6	\$2,192	Water Damage.
	Doors - Transom Window		15	SF	6	\$254	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	6	\$5,146	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Marker Board		24	LF	6	\$514	
	Walls - Plaster/Drywall		1,120	SF	6	\$3,091	
<b>Classroom #261 (Regular Classroom)</b>							
	AC Units		1	EA	5	\$1,826	
	Casework		16	LF	5	\$3,345	Missing glass and hardware.
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Doors - Transom Window		15	SF	6	\$254	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	6	\$5,146	
	Lighting - Lay-in		18	EA	6	\$2,142	
	Marker Board		24	LF	6	\$514	
	Walls - Plaster/Drywall		1,120	SF	6	\$3,091	
<b>Classroom #262 (Regular Classroom)</b>							
	AC Units		2	EA	6	\$991	
	Casework		7	LF	6	\$177	missing hardware
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Doors - Transom Window		15	SF	6	\$254	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	6	\$5,146	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Marker Board		24	LF	6	\$514	
	Walls - Plaster/Drywall		1,120	SF	6	\$3,091	
<b>Classroom #264 (Regular Classroom)</b>							
	AC Units		2	EA	5	\$3,652	
	Casework		7	LF	5	\$1,464	
	Ceiling - Lay-in		730	SF	5	\$4,343	Water damage throughout.

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #264 (Regular Classroom)</b>							
	Doors - Transom Window		15	SF	6	\$254	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	6	\$5,146	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Marker Board		24	LF	6	\$514	
	Walls - Plaster/Drywall		1,120	SF	6	\$3,091	
<b>Classroom #266 (Regular Classroom)</b>							
	AC Units		2	EA	5	\$3,652	
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Doors - Transom Window		15	SF	6	\$254	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	6	\$5,146	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Marker Board		30	LF	6	\$643	
	Walls - Plaster/Drywall		1,120	SF	6	\$3,091	
<b>Classroom #272 (Band Room)</b>							
	AC Units		1	EA	5	\$1,826	
	Ceiling - Lay-in		1,424	SF	6	\$4,276	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Wood		1,424	SF	6	\$10,039	
	Lighting - Lay-in		45	EA	6	\$5,354	
	Marker Board		32	LF	6	\$685	
	Storage/ Closet		168	SF	6	\$1,218	
	Walls - Plaster/Drywall		1,672	SF	6	\$4,615	
<b>Classroom #273 (Regular Classroom)</b>							
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		730	SF	6	\$2,192	Some Water Damage.
	Doors - Transom Window		15	SF	6	\$254	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	6	\$5,146	
	Lighting - Lay-in		18	EA	6	\$2,142	
	Marker Board		40	LF	6	\$857	
	Walls - Plaster/Drywall		1,120	SF	6	\$3,091	

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #275 (Regular Classroom)							
	Casework		7	LF	5	\$1,464	
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	6	\$5,146	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Marker Board		44	LF	6	\$943	
	Walls - Plaster/Drywall		1,120	SF	6	\$3,091	
Classroom #276 (Computer Lab)							
	AC Units		2	EA	5	\$3,652	
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		730	SF	6	\$2,192	water stains throughout
	Doors - Transom Window		15	SF	6	\$254	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	6	\$5,146	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Marker Board		38	LF	7	\$0	
	Walls - Plaster/Drywall		1,120	SF	6	\$3,091	
Classroom #277 (Regular Classroom)							
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Doors - Transom Window		15	SF	6	\$254	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	6	\$5,146	
	Lighting - Lay-in		18	EA	6	\$2,142	
	Marker Board		36	LF	6	\$771	
	Walls - Plaster/Drywall		1,120	SF	6	\$3,091	
Classroom #278 (Regular Classroom)							
	AC Units		1	EA	5	\$1,826	
	Casework		7	LF	5	\$1,464	
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Doors - Transom Window		15	SF	6	\$254	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Floor - Wood		730	SF	6	\$5,146	
	Lighting - Lay-in		18	EA	6	\$2,142	
	Marker Board		28	LF	7	\$0	
	Walls - Plaster/Drywall		1,120	SF	6	\$3,091	

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #278 (Regular Classroom)</b>							
<b>Classroom #280 (Regular Classroom)</b>							
	AC Units		2	EA	5	\$3,652	
	Casework		7	LF	6	\$177	Missing Hardware.
	Ceiling - Lay-in		930	SF	6	\$2,793	
	Doors - Transom Window		21	SF	6	\$356	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		930	SF	6	\$6,556	
	Lighting - Lay-in		32	EA	6	\$3,807	
	Marker Board		32	LF	7	\$0	
	Walls - Plaster/Drywall		1,120	SF	6	\$3,091	
<b>Classroom #281 (Regular Classroom)</b>							
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	6	\$5,146	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Marker Board		24	LF	6	\$514	
	Walls - Plaster/Drywall		1,120	SF	6	\$3,091	
<b>Classroom #319 (Regular Classroom)</b>							
	Casework		33	LF	6	\$833	missing hardware
	Ceiling - Lay-in		1,130	SF	5	\$6,722	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		1,130	SF	6	\$7,966	
	Lighting - Lay-in		30	EA	6	\$3,569	
	Marker Board		16	LF	6	\$343	
	Walls - Plaster/Drywall		700	SF	6	\$2,292	
	Walls - Plaster/Drywall		739	SF	5	\$5,601	
	Work Sink		1	EA	5	\$1,508	not functioning properly
<b>Classroom #320 (Regular Classroom)</b>							
	Casework		50	LF	6	\$1,263	
	Casework		70	LF	5	\$14,636	missing doors and damaged hardware
	Ceiling - Splined		1,050	SF	6	\$856	missing and dirty tiles
	Chalk Board		20	LF	4	\$1,836	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		1,050	SF	5	\$15,360	creaking and warped floor boards; damaged finish

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #320 (Regular Classroom)</b>							
	Lighting - Pendent/Surface		30	EA	6	\$3,717	
	Marker Board		20	LF	6	\$428	replace temporary markerboard with standard installation
	Walls - Plaster/Drywall		1,484	SF	6	\$4,096	
	Work Sink		1	EA	6	\$379	obsolete function and fixture
<b>Classroom #322 (Regular Classroom)</b>							
	Casework		16	LF	5	\$3,345	damaged and missing hardware; damaged drawers and doors; damaged finish
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Chalk Board		28	LF	4	\$2,571	obsolete and damaged material
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	5	\$10,679	warped floor boards & damaged finish
	Lighting - Lay-in		23	EA	6	\$2,736	
	Walls - Plaster/Drywall		600	SF	6	\$1,656	
	Walls - Plaster/Drywall		540	SF	5	\$2,386	peeling paint; damaged plaster; damaged window sills
<b>Classroom #325 (Music Room)</b>							
	Casework		80	LF	6	\$2,020	
	Ceiling - Lay-in		2,395	SF	6	\$7,192	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Floor - Wood		2,395	SF	5	\$35,036	warped and deteriorating finish.
	Lighting - Lay-in		43	EA	6	\$5,116	
	Walls - Plaster/Drywall		3,213	SF	6	\$8,868	
<b>Classroom #326 (Computer Lab)</b>							
	Ceiling - Lay-in		150	SF	5	\$1,197	water damage
	Ceiling - Lay-in		1,345	SF	6	\$4,039	
	Doors - Steel Doors incl hw		2	EA	7	\$0	
	Floor - Carpet		1,495	SF	5	\$7,675	replace damaged and missing carpet tiles
	Lighting - Lay-in		42	EA	6	\$4,997	
	Marker Board		32	LF	7	\$0	
	Walls - Plaster/Drywall		1,093	SF	7	\$0	
	Wireless System		1	EA	6	\$372	
<b>Classroom #328 (Regular Classroom)</b>							
	Casework		7	LF	5	\$1,464	broken hardware, damaged finish
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Chalk Board		60	LF	4	\$5,508	obsolete material

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #328 (Regular Classroom)</b>							
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		730	SF	6	\$5,146	
	Lighting - Lay-in		20	EA	7	\$0	
	Walls - Plaster/Drywall		1,140	SF	6	\$3,146	
<b>Classroom #330 (Regular Classroom)</b>							
	Casework		7	LF	6	\$177	damaged finish
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Chalk Board		32	LF	4	\$2,938	obsolete material
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	5	\$10,679	
	Lighting - Lay-in		21	EA	6	\$2,498	drooping lenses
	Marker Board		14	LF	6	\$300	
	Walls - Plaster/Drywall		700	SF	6	\$1,932	
	Walls - Plaster/Drywall		440	SF	5	\$1,944	cracked plaster; peeling paint
<b>Classroom #332 (Regular Classroom)</b>							
	AC Units		2	EA	6	\$991	
	Casework		8	LF	6	\$202	
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Chalk Board		18	LF	4	\$1,653	Obsolete Material;partially covered.
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	5	\$10,679	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Marker Board		30	LF	6	\$643	
	Walls - Plaster/Drywall		1,140	SF	7	\$0	
<b>Classroom #334 (Regular Classroom)</b>							
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		730	SF	5	\$4,343	
	Chalk Board		37	LF	4	\$3,397	obsolete material
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		730	SF	5	\$10,679	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Walls - Plaster/Drywall		1,140	SF	5	\$8,640	water damage to plaster; peeling paint; damaged window sills
<b>Classroom #335 (Computer Lab)</b>							
	AC Units		1	EA	6	\$496	



## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #335 (Computer Lab)</b>							
	Casework		7	LF	5	\$1,464	damaged hardware, door and finish
	Ceiling - Lay-in		1,130	SF	6	\$3,393	
	Chalk Board		14	LF	4	\$1,285	obsolete material
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		1,130	SF	6	\$7,966	
	Lighting - Lay-in		27	EA	6	\$3,212	
	Marker Board		22	LF	6	\$471	
	Walls - Plaster/Drywall		800	SF	6	\$2,208	
	Walls - Plaster/Drywall		539	SF	5	\$2,382	
	Wireless System		1	EA	6	\$372	
<b>Classroom #350 (Science Lab Level 1)</b>							
	Casework		111	LF	7	\$0	
	Ceiling - Lay-in		1,300	SF	7	\$0	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Eye Wash Station		1	EA	6	\$336	
	Floor - Tile		1,300	SF	6	\$2,844	
	Fume Hood		1	EA	7	\$0	
	Gas Line		16	EA	6	\$8,146	
	Lighting - Lay-in		17	EA	7	\$0	
	Marker Board		16	LF	7	\$0	
	Science Lab Shower		1	EA	6	\$379	
	Walls - Plaster/Drywall		1,313	SF	7	\$0	
	Work Sink		8	EA	6	\$3,032	
<b>Classroom #351 (Regular Classroom)</b>							
	Casework		19	LF	6	\$480	
	Ceiling - Lay-in		920	SF	7	\$0	
	Chalk Board		8	LF	4	\$734	obsolete material
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Tile		920	SF	6	\$2,013	cracked VCT throughout the room
	Lighting - Lay-in		21	EA	7	\$0	
	Marker Board		16	LF	7	\$0	
	Walls - Plaster/Drywall		1,133	SF	7	\$0	
	Work Sink		1	EA	6	\$379	
<b>Classroom #352 (Science Lab Level 3)</b>							
	Casework		52	LF	7	\$0	
	Ceiling - Lay-in		990	SF	7	\$0	

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #352 (Science Lab Level 3)</b>							
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Eye Wash Station		1	EA	6	\$336	
	Floor - Tile/Sheet		990	SF	6	\$991	
	Gas Line		2	EA	6	\$1,018	
	Lighting - Lay-in		29	EA	7	\$0	
	Marker Board		36	LF	7	\$0	
	Walls - Plaster/Drywall		1,001	SF	6	\$2,763	
	Work Sink		3	EA	6	\$1,137	
<b>Classroom #353 (Art Room)</b>							
	Casework		27	LF	6	\$682	
	Ceiling - Lay-in		920	SF	6	\$2,763	
	Chalk Board		8	LF	4	\$734	obsolete material
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		920	SF	6	\$6,486	sand and refinish
	Lighting - Lay-in		24	EA	7	\$0	
	Marker Board		7	LF	6	\$150	
	Walls - Plaster/Drywall		1,133	SF	6	\$3,127	
	Work Sink		1	EA	6	\$379	Double Sink.
<b>Classroom #355 (Art Room)</b>							
	Casework		19	LF	5	\$3,973	
	Ceiling - Lay-in		920	SF	5	\$5,473	rusted grid; water damaged tiles
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		920	SF	6	\$2,013	
	Kiln		1	EA	6	\$2,321	
	Lighting - Lay-in		24	EA	6	\$2,855	
	Walls - Metal Panel		1,133	SF	6	\$8,457	
	Work Sink		1	EA	6	\$379	
<b>Classroom #356 (Science Lab Level 1)</b>							
	Casework		209	LF	7	\$0	
	Ceiling - Lay-in		937	SF	7	\$0	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Eye Wash Station		1	EA	6	\$336	
	Floor - Tile		937	SF	6	\$2,050	
	Fume Hood		1	EA	6	\$816	
	Gas Line		16	EA	6	\$8,146	
	Lighting - Lay-in		16	EA	7	\$0	

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #356 (Science Lab Level 1)</b>							
	Marker Board		36	LF	6	\$771	
	Science Lab Shower		1	EA	6	\$379	
	Walls - Plaster/Drywall		1,157	SF	6	\$3,193	
	Work Sink		10	EA	6	\$3,790	
<b>Classroom #358 (Science Lab Level 3)</b>							
	AC Units		2	EA	6	\$991	
	Casework		37	LF	6	\$934	hardware broken
	Ceiling - Lay-in		1,216	SF	6	\$3,652	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Eye Wash Station		1	EA	6	\$336	
	Floor - Tile/Sheet		1,216	SF	6	\$1,217	
	Gas Line		1	EA	6	\$509	
	Lighting - Lay-in		24	EA	6	\$2,855	
	Marker Board		12	LF	6	\$257	
	Walls - Plaster/Drywall		1,000	SF	6	\$2,760	
	Walls - Plaster/Drywall		309	SF	5	\$1,365	
	Work Sink		1	EA	6	\$379	
<b>Classroom #361 (Art Room)</b>							
	AC Units		1	EA	5	\$1,826	
	Casework		60	LF	5	\$12,545	hardware and glass missing.
	Ceiling - Lay-in		1,584	SF	6	\$4,757	
	Chalk Board		22	LF	4	\$2,020	Obsolete Material.
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		1,584	SF	6	\$11,167	
	Instructional Surface		7	LF	5	\$433	
	Kiln		1	EA	6	\$2,321	
	Lighting - Lay-in		30	EA	6	\$3,569	
	Marker Board		22	LF	6	\$471	
	Walls - Plaster/Drywall		600	SF	6	\$1,965	
	Walls - Plaster/Drywall		855	SF	4	\$8,607	Water infiltration, crumbling plaster on the floor.
	Work Sink		1	EA	6	\$379	
<b>Classroom #363 (Regular Classroom)</b>							
	Casework		6	LF	5	\$1,254	
	Ceiling - Lay-in		816	SF	6	\$2,450	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		816	SF	6	\$5,753	

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #363 (Regular Classroom)</b>							
	Lighting - Lay-in		24	EA	6	\$2,855	
	Marker Board		15	LF	6	\$321	
	Walls - Plaster/Drywall		1,051	SF	6	\$2,901	
<b>Classroom #364 (Science Lab Level 3)</b>							
	AC Units		1	EA	7	\$0	
	Casework		60	LF	7	\$0	
	Ceiling - Lay-in		1,032	SF	6	\$3,099	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Eye Wash Station		1	EA	6	\$336	
	Floor - Tile/Sheet		1,032	SF	6	\$1,033	
	Fume Hood		1	EA	6	\$816	
	Gas Line		1	EA	6	\$509	
	Lighting - Lay-in		21	EA	7	\$0	
	Marker Board		41	LF	7	\$0	
	Science Lab Shower		1	EA	6	\$379	
	Walls - Plaster/Drywall		1,183	SF	6	\$3,265	
	Work Sink		3	EA	7	\$0	
<b>Classroom #366 (Science Lab Level 3)</b>							
	AC Units		1	EA	6	\$496	
	Casework		84	LF	7	\$0	
	Ceiling - Lay-in		1,050	SF	7	\$0	
	Ceiling - Plaster/Drywall		204	SF	6	\$706	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Eye Wash Station		1	EA	6	\$336	
	Floor - Tile/Sheet		1,050	SF	6	\$1,051	
	Gas Line		1	EA	6	\$509	
	Lighting - Lay-in		30	EA	7	\$0	
	Marker Board		12	LF	7	\$0	
	Walls - Plaster/Drywall		1,228	SF	6	\$3,389	
	Work Sink		3	EA	7	\$0	
<b>Classroom #367 (Regular Classroom)</b>							
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		725	SF	6	\$2,177	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		725	SF	6	\$5,111	
	Lighting - Lay-in		21	EA	6	\$2,498	

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #367 (Regular Classroom)</b>							
	Marker Board		17	LF	6	\$364	
	Walls - Plaster/Drywall		100	SF	5	\$442	
	Walls - Plaster/Drywall		797	SF	6	\$2,200	
<b>Classroom #372 (Regular Classroom)</b>							
	AC Units		2	EA	6	\$991	
	Ceiling - Lay-in		750	SF	6	\$2,252	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		750	SF	5	\$10,972	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Marker Board		25	LF	6	\$536	
	Walls - Plaster/Drywall		105	SF	5	\$536	
	Walls - Plaster/Drywall		956	SF	6	\$2,638	
<b>Classroom #374 (Regular Classroom)</b>							
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		50	SF	4	\$703	Water damage.
	Ceiling - Lay-in		700	SF	6	\$2,102	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Floor - Wood		750	SF	5	\$10,972	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Marker Board		24	LF	6	\$514	
	Walls - Plaster/Drywall		1,063	SF	6	\$2,934	
<b>Classroom #376 (Regular Classroom)</b>							
	Casework		7	LF	5	\$1,464	
	Ceiling - Lay-in		750	SF	5	\$4,462	ceiling cracks, water damage
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		750	SF	6	\$5,287	
	Lighting - Pendent/Surface		21	EA	6	\$2,602	
	Marker Board		22	LF	6	\$471	
	Walls - Plaster/Drywall		1,063	SF	6	\$2,934	
<b>Classroom #378 (Regular Classroom)</b>							
	Casework		7	LF	6	\$177	
	Ceiling - Lay-in		750	SF	6	\$2,252	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		750	SF	6	\$5,287	
	Lighting - Lay-in		20	EA	6	\$2,380	

## Building: Main

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #378 (Regular Classroom)</b>							
	Marker Board		24	LF	6	\$514	
	Walls - Plaster/Drywall		1,063	SF	6	\$2,934	
<b>Classroom #380 (Regular Classroom)</b>							
	Casework		7	LF	5	\$1,464	Missing glass and hardware.
	Ceiling - Lay-in		200	SF	4	\$2,265	water damage, cracked tiles throughout
	Ceiling - Lay-in		730	SF	6	\$2,192	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		930	SF	6	\$6,556	
	Lighting - Lay-in		32	EA	6	\$3,807	
	Marker Board		40	LF	6	\$857	
	Walls - Plaster/Drywall		1,120	SF	6	\$3,091	
<b>Classroom #425 (Band Room)</b>							
	Casework		10	LF	5	\$2,091	
	Ceiling - Splined		300	SF	4	\$3,398	water damage, missing tiles
	Ceiling - Splined		1,832	SF	6	\$1,493	
	Doors - Wood Doors inclu hw		2	EA	5	\$2,348	
	Floor - Wood		2,132	SF	6	\$15,030	
	Instrument Storage Casework		63	LF	5	\$4,184	damaged hardware and finish at casework.
	Lighting - Pendent/Surface		63	EA	6	\$7,805	
	Storage/ Closet		315	SF	5	\$5,081	plaster wall damage at storage room adjacent to room entry
	Walls - Plaster/Drywall		1,595	SF	6	\$4,402	
<b>Classrooms Subtotal:</b>						<b>\$1,100,068</b>	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	AC Unit	117A Counselor Office	1	EA	5	\$1,826	
	Ceiling - Lay-in	117A Counselor Office	767	SF	7	\$0	
	Doors - Transom Window	117A Counselor Office	11	SF	6	\$186	
	Doors - Wood Doors inclu hw	117A Counselor Office	1	EA	5	\$1,174	
	Doors - Wood Doors inclu hw	117A Counselor Office	3	EA	6	\$903	
	Doors - Wood Doors inclu hw	117A Counselor Office	1	EA	7	\$0	
	Floor - Tile	117A Counselor Office	67	SF	5	\$386	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Floor - Tile	117A Counselor Office	700	SF	6	\$1,532	
	Lighting - Lay-in	117A Counselor Office	24	EA	7	\$0	
	Power Distribution	117A Counselor Office	26	EA	7	\$0	Note: 12 computers plugged into one outlet w/extension cords.
	Storage/ Closet	117A Counselor Office	76	SF	6	\$551	
	Walls - Plaster/Drywall	117A Counselor Office	1,020	SF	7	\$0	
	Ceiling - Lay-in	117B Counselor Office	182	SF	7	\$0	
	Doors - Transom Window	117B Counselor Office	11	SF	6	\$186	
	Doors - Wood Doors inclu hw	117B Counselor Office	1	EA	7	\$0	
	Floor - Tile	117B Counselor Office	182	SF	6	\$398	
	Lighting - Lay-in	117B Counselor Office	4	EA	7	\$0	
	Power Distribution	117B Counselor Office	6	EA	7	\$0	
	Walls - Plaster/Drywall	117B Counselor Office	535	SF	7	\$0	
	Ceiling - Lay-in	117C Kitchenette	90	SF	7	\$0	
	Floor - Tile	117C Kitchenette	90	SF	4	\$773	tile is loose/damaged and should be replaced.
	Lighting - Lay-in	117C Kitchenette	2	EA	7	\$0	
	Power Distribution	117C Kitchenette	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	117C Kitchenette	300	SF	7	\$0	
	Work Sink	117C Kitchenette	1	EA	6	\$508	
	Ceiling - Plaster/Drywall	118A Pool Office	65	SF	5	\$596	peeling paint; apparent damage to substrate
	Doors - Steel Doors incl hw	118A Pool Office	1	EA	6	\$301	FRP facing
	Floor - Tile Ceramic/ Porcelain	118A Pool Office	65	SF	6	\$138	
	Lighting - Pendent/Surface	118A Pool Office	1	EA	6	\$124	
	Power Distribution	118A Pool Office	4	EA	5	\$15,407	provide cover; verify complies with electrical code
	Walls - Plaster/Drywall	118A Pool Office	485	SF	5	\$3,676	peeling paint; damaged wall finish throughout
	AC Unit	123A Counselor Office	1	EA	7	\$0	
	Ceiling - Lay-in	123A Counselor Office	280	SF	7	\$0	
	Doors - Transom Window	123A Counselor Office	11	SF	6	\$186	
	Doors - Wood Doors inclu hw	123A Counselor Office	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	123A Counselor Office	1	EA	7	\$0	
	Floor - Tile	123A Counselor Office	280	SF	6	\$613	
	Lighting - Lay-in	123A Counselor Office	6	EA	7	\$0	
	Power Distribution	123A Counselor Office	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	123A Counselor Office	630	SF	7	\$0	
	AC Unit	123B Counselor Office	1	EA	7	\$0	
	Ceiling - Lay-in	123B Counselor Office	558	SF	7	\$0	
	Doors - Transom Window	123B Counselor Office	11	SF	6	\$186	
	Doors - Wood Doors inclu hw	123B Counselor Office	1	EA	7	\$0	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Floor - Tile	123B Counselor Office	558	SF	4	\$4,796	Note: floor is sinking in center of room. structural framing and sub-floor should be examined. tile is loose and cracking.
	Lighting - Lay-in	123B Counselor Office	15	EA	7	\$0	
	Power Distribution	123B Counselor Office	14	EA	6	\$29,748	
	Walls - Plaster/Drywall	123B Counselor Office	870	SF	7	\$0	
	Ceiling - Lay-in	125 - Dean's Office	210	SF	6	\$631	
	Doors - Side-lite	125 - Dean's Office	42	SF	6	\$702	
	Doors - Store Front	125 - Dean's Office	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	125 - Dean's Office	2	EA	7	\$0	
	Floor - Tile	125 - Dean's Office	210	SF	5	\$943	warped, worn and damaged
	Lighting - Lay-in	125 - Dean's Office	12	EA	6	\$1,428	
	Power Distribution	125 - Dean's Office	11	EA	6	\$23,374	
	Walls - Plaster/Drywall	125 - Dean's Office	225	SF	6	\$737	
	Walls - Plaster/Drywall	125 - Dean's Office	232	SF	4	\$2,336	exposed pipes, protruding wires through conduit, cut-through and unfinished picture rail, exposed construction at windows, etc. Walls should be refinished.
	AC Unit	129 discipline office	1	EA	6	\$496	
	Ceiling - Lay-in	129 discipline office	291	SF	5	\$1,731	yellowed grid and mismatched and dirty tile - repaint grid and replace tile
	Doors - Wood Doors inclu hw	129 discipline office	2	EA	7	\$0	
	Floor - Tile/Sheet	129 discipline office	291	SF	7	\$0	
	Lighting - Lay-in	129 discipline office	6	EA	7	\$0	
	Power Distribution	129 discipline office	8	EA	7	\$0	
	Storage/ Closet	129 discipline office	81	SF	6	\$587	
	Walls - Plaster/Drywall	129 discipline office	595	SF	5	\$4,510	damaged plaster and paint; doors do not match adjacent woodwork; damaged window sill
	Ceiling - Lay-in	130 South Office in Main Office	75	SF	6	\$225	lighting included in Corridor in Main Office 135
	Doors - Side-lite	130 South Office in Main Office	20	SF	7	\$0	
	Doors - Wood Doors inclu hw	130 South Office in Main Office	1	EA	6	\$301	
	Floor - Tile/Sheet	130 South Office in Main Office	75	SF	7	\$0	
	Power Distribution	130 South Office in Main Office	2	EA	7	\$0	
	Walls - Metal Panel	130 South Office in Main Office	103	SF	7	\$0	partial height wood panels
	Walls - Plaster/Drywall	130 South Office in Main Office	198	SF	7	\$0	
	AC Unit	131 South Office in Main Office	1	EA	7	\$0	
	Ceiling - Lay-in	131 South Office in Main Office	117	SF	7	\$0	
	Doors - Side-lite	131 South Office in Main Office	25	SF	7	\$0	
	Doors - Wood Doors inclu hw	131 South Office in Main Office	2	EA	6	\$602	



## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Floor - Tile/Sheet	131 South Office in Main Office	117	SF	7	\$0	
	Lighting - Lay-in	131 South Office in Main Office	4	EA	7	\$0	
	Power Distribution	131 South Office in Main Office	4	EA	7	\$0	
	Walls - Plaster/Drywall	131 South Office in Main Office	377	SF	7	\$0	
	AC Unit	131B South Office in Main Office	1	EA	7	\$0	
	Ceiling - Lay-in	131B South Office in Main Office	196	SF	7	\$0	
	Doors - Side-lite	131B South Office in Main Office	50	SF	7	\$0	
	Doors - Wood Doors inclu hw	131B South Office in Main Office	1	EA	7	\$0	
	Floor - Tile/Sheet	131B South Office in Main Office	196	SF	7	\$0	
	Lighting - Lay-in	131B South Office in Main Office	6	EA	6	\$714	One light is out
	Power Distribution	131B South Office in Main Office	5	EA	7	\$0	
	Walls - Plaster/Drywall	131B South Office in Main Office	467	SF	6	\$1,289	
	AC Unit	132 Office in Main Office	1	EA	6	\$496	
	Ceiling - Lay-in	132 Office in Main Office	80	SF	6	\$240	lighting included in Corridor in Main Office 135
	Doors - Side-lite	132 Office in Main Office	10	SF	7	\$0	
	Doors - Wood Doors inclu hw	132 Office in Main Office	1	EA	7	\$0	
	Floor - Tile/Sheet	132 Office in Main Office	80	SF	7	\$0	
	Power Distribution	132 Office in Main Office	3	EA	7	\$0	
	Walls - Metal Panel	132 Office in Main Office	80	SF	7	\$0	partial height wood panel
	Walls - Plaster/Drywall	132 Office in Main Office	165	SF	7	\$0	
	Ceiling - Lay-in	133 Office in Main Office	75	SF	6	\$225	lighting included in Corridor in Main Office 135
	Doors - Side-lite	133 Office in Main Office	50	SF	7	\$0	
	Doors - Wood Doors inclu hw	133 Office in Main Office	1	EA	7	\$0	
	Floor - Tile/Sheet	133 Office in Main Office	75	SF	7	\$0	
	Power Distribution	133 Office in Main Office	3	EA	7	\$0	
	Walls - Metal Panel	133 Office in Main Office	77	SF	7	\$0	partial height wood panel
	Walls - Plaster/Drywall	133 Office in Main Office	161	SF	7	\$0	
	AC Unit	134 Office in Main Office	1	EA	6	\$496	
	Ceiling - Lay-in	134 Office in Main Office	125	SF	7	\$0	
	Doors - Side-lite	134 Office in Main Office	20	SF	7	\$0	
	Doors - Wood Doors inclu hw	134 Office in Main Office	1	EA	7	\$0	
	Floor - Tile/Sheet	134 Office in Main Office	125	SF	7	\$0	
	Lighting - Lay-in	134 Office in Main Office	4	EA	7	\$0	
	Power Distribution	134 Office in Main Office	6	EA	7	\$0	
	Walls - Metal Panel	134 Office in Main Office	120	SF	7	\$0	Wall is wood panel not metal
	Walls - Plaster/Drywall	134 Office in Main Office	297	SF	6	\$820	
	AC Unit	135 Main Office	3	EA	6	\$1,487	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Ceiling - Lay-in	135 Main Office	940	SF	7	\$0	
	Doors - Transom Window	135 Main Office	22	SF	7	\$0	
	Doors - Wood Doors inclu hw	135 Main Office	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	135 Main Office	2	EA	6	\$602	
	Floor - Tile/Sheet	135 Main Office	940	SF	7	\$0	
	Lighting - Lay-in	135 Main Office	26	EA	7	\$0	
	Power Distribution	135 Main Office	10	EA	7	\$0	
	Storage/ Closet	135 Main Office	55	SF	7	\$0	
	Walls - Plaster/Drywall	135 Main Office	1,221	SF	6	\$3,370	
	AC Unit	135A North Office in Main Office	1	EA	7	\$0	
	Ceiling - Lay-in	135A North Office in Main Office	174	SF	7	\$0	
	Doors - Wood Doors inclu hw	135A North Office in Main Office	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	135A North Office in Main Office	1	EA	7	\$0	
	Floor - Carpet	135A North Office in Main Office	174	SF	6	\$371	
	Lighting - Lay-in	135A North Office in Main Office	6	EA	7	\$0	
	Power Distribution	135A North Office in Main Office	4	EA	6	\$8,500	
	Storage/ Closet	135A North Office in Main Office	15	SF	7	\$0	
	Walls - Plaster/Drywall	135A North Office in Main Office	500	SF	7	\$0	
	Work Slnk	135A North Office in Main Office	1	EA	6	\$508	
	AC Unit	137 Principal's Office	1	EA	6	\$496	
	Ceiling - Lay-in	137 Principal's Office	338	SF	7	\$0	
	Doors - Transom Window	137 Principal's Office	11	SF	7	\$0	
	Doors - Wood Doors inclu hw	137 Principal's Office	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	137 Principal's Office	1	EA	7	\$0	
	Floor - Tile/Sheet	137 Principal's Office	338	SF	7	\$0	
	Lighting - Lay-in	137 Principal's Office	12	EA	7	\$0	
	Power Distribution	137 Principal's Office	8	EA	7	\$0	
	Storage/ Closet	137 Principal's Office	15	SF	7	\$0	
	Walls - Plaster/Drywall	137 Principal's Office	782	SF	7	\$0	
	AC Unit	139 conference room	1	EA	7	\$0	
	Ceiling - Lay-in	139 conference room	465	SF	7	\$0	
	Doors - Transom Window	139 conference room	11	SF	7	\$0	
	Doors - Wood Doors inclu hw	139 conference room	1	EA	7	\$0	
	Floor - Tile/Sheet	139 conference room	465	SF	7	\$0	
	Lighting - Lay-in	139 conference room	8	EA	7	\$0	
	Power Distribution	139 conference room	8	EA	7	\$0	
	Walls - Plaster/Drywall	139 conference room	676	SF	7	\$0	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Ceiling - Plaster/Drywall	156B Gym Office	258	SF	6	\$893	peeling paint
	Doors - Wood Doors inclu hw	156B Gym Office	1	EA	7	\$0	
	Floor - Wood	156B Gym Office	258	SF	6	\$1,819	
	Lighting - Pendent/Surface	156B Gym Office	5	EA	6	\$619	
	Power Distribution	156B Gym Office	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	156B Gym Office	862	SF	6	\$2,379	peeling paint
	Ceiling - Plaster/Drywall	190G Kitchen Office	155	SF	6	\$536	
	Doors - Wood Doors inclu hw	190G Kitchen Office	1	EA	6	\$301	
	Floor - Tile/Sheet	190G Kitchen Office	155	SF	7	\$0	
	Lighting - Pendent/Surface	190G Kitchen Office	3	EA	7	\$0	
	Power Distribution	190G Kitchen Office	8	EA	7	\$0	
	Walls - Plaster/Drywall	190G Kitchen Office	583	SF	6	\$1,609	
	AC Unit	196 teacher's lounge	1	EA	5	\$1,826	
	Ceiling - Lay-in	196 teacher's lounge	1,268	SF	6	\$3,808	
	Doors - Wood Doors inclu hw	196 teacher's lounge	3	EA	5	\$3,522	
	Floor - Terrazzo	196 teacher's lounge	236	SF	6	\$516	
	Floor - Tile	196 teacher's lounge	1,032	SF	3	\$8,869	Note: floor is sinking in center of room. structural framing and sub-floor should be examined. tile @ stair is loose and cracking.
	Lighting - Lay-in	196 teacher's lounge	30	EA	7	\$0	
	Power Distribution	196 teacher's lounge	2	EA	6	\$4,250	
	Storage/ Closet	196 teacher's lounge	210	SF	5	\$3,387	
	Walls - Plaster/Drywall	196 teacher's lounge	1,600	SF	7	\$0	
	Ceiling - Plaster/Drywall	196A office in teacher's lounge	76	SF	6	\$263	
	Doors - Store Front	196A office in teacher's lounge	1	EA	6	\$1,208	
	Doors - Wood Doors inclu hw	196A office in teacher's lounge	1	EA	5	\$1,174	
	Floor - Terrazzo	196A office in teacher's lounge	76	SF	6	\$166	
	Lighting - Lay-in	196A office in teacher's lounge	2	EA	7	\$0	
	Power Distribution	196A office in teacher's lounge	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	196A office in teacher's lounge	300	SF	6	\$828	
	Ceiling - Lay-in	227A Library Office	227	SF	5	\$1,350	discolored ceiling tile, water damage
	Doors - Wood Doors inclu hw	227A Library Office	1	EA	7	\$0	
	Floor - Wood	227A Library Office	227	SF	5	\$3,321	patched, warped and bowed floor boards; toilet room in the middle of the room
	Lighting - Lay-in	227A Library Office	4	EA	7	\$0	
	Power Distribution	227A Library Office	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	227A Library Office	600	SF	6	\$1,656	
	Walls - Plaster/Drywall	227A Library Office	136	SF	5	\$601	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	AC Unit	231 Health Office	1	EA	6	\$496	
	Ceiling - Lay-in	231 Health Office	265	SF	6	\$796	
	Doors - Transom Window	231 Health Office	9	SF	7	\$0	
	Doors - Wood Doors inclu hw	231 Health Office	1	EA	7	\$0	
	Floor - Wood	231 Health Office	265	SF	5	\$3,877	
	Lighting - Lay-in	231 Health Office	6	EA	7	\$0	
	Power Distribution	231 Health Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	231 Health Office	768	SF	5	\$5,821	
	Work Sink	231 Health Office	1	EA	6	\$508	
	Ceiling - Lay-in	231A Exam Room in Health Office	132	SF	6	\$396	
	Doors - Wood Doors inclu hw	231A Exam Room in Health Office	1	EA	7	\$0	
	Floor - Wood	231A Exam Room in Health Office	132	SF	5	\$1,931	warped, damaged & creaking
	Lighting - Lay-in	231A Exam Room in Health Office	2	EA	6	\$238	
	Power Distribution	231A Exam Room in Health Office	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	231A Exam Room in Health Office	544	SF	6	\$1,501	
	Ceiling - Lay-in	231B Office in Health Office	132	SF	6	\$396	
	Doors - Wood Doors inclu hw	231B Office in Health Office	1	EA	7	\$0	
	Floor - Wood	231B Office in Health Office	132	SF	5	\$1,931	warped, damaged & creaking floor
	Lighting - Lay-in	231B Office in Health Office	2	EA	6	\$238	
	Power Distribution	231B Office in Health Office	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	231B Office in Health Office	484	SF	5	\$3,668	
	AC Unit	258 Office	2	EA	6	\$991	
	Ceiling - Lay-in	258 Office	900	SF	6	\$2,703	Water damage and cracked ceiling tiles
	Doors - Wood Doors inclu hw	258 Office	1	EA	6	\$301	
	Floor - Wood	258 Office	900	SF	6	\$6,345	
	Lighting - Lay-in	258 Office	15	EA	6	\$1,785	
	Power Distribution	258 Office	10	EA	6	\$21,249	
	Walls - Plaster/Drywall	258 Office	968	SF	6	\$2,672	
	AC Unit	258A Office	1	EA	6	\$496	
	Ceiling - Lay-in	258A Office	100	SF	6	\$300	
	Doors - Wood Doors inclu hw	258A Office	1	EA	6	\$301	
	Floor - Wood	258A Office	100	SF	6	\$705	
	Lighting - Lay-in	258A Office	4	EA	6	\$476	
	Power Distribution	258A Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	258A Office	968	SF	6	\$2,672	
	Ceiling - Lay-in	258B Office	60	SF	6	\$180	
	Doors - Wood Doors inclu hw	258B Office	1	EA	7	\$0	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Floor - Wood	258B Office	60	SF	6	\$423	
	Lighting - Lay-in	258B Office	2	EA	6	\$238	
	Power Distribution	258B Office	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	258B Office	278	SF	6	\$767	
	Ceiling - Lay-in	2nd Floor A/V Room	72	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor A/V Room	1	EA	7	\$0	
	Floor - Tile	2nd Floor A/V Room	72	SF	7	\$0	
	Lighting - Pendent/Surface	2nd Floor A/V Room	9	EA	7	\$0	
	Power Distribution	2nd Floor A/V Room	6	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor A/V Room	236	SF	6	\$651	
	Ceiling - Lay-in	2nd Floor Control Room	72	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor Control Room	1	EA	7	\$0	
	Floor - Tile	2nd Floor Control Room	72	SF	7	\$0	
	Lighting - Lay-in	2nd Floor Control Room	1	EA	7	\$0	
	Power Distribution	2nd Floor Control Room	6	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor Control Room	236	SF	6	\$651	
	Ceiling - Plaster/Drywall	325A - Practice Room	85	SF	6	\$294	
	Doors - Wood Doors inclu hw	325A - Practice Room	1	EA	5	\$1,174	
	Floor - Wood	325A - Practice Room	85	SF	5	\$1,243	
	Lighting - Pendent/Surface	325A - Practice Room	1	EA	5	\$183	
	Walls - Plaster/Drywall	325A - Practice Room	135	SF	6	\$373	
	Ceiling - Splined	325B - Practice Room	85	SF	6	\$69	
	Doors - Wood Doors inclu hw	325B - Practice Room	1	EA	6	\$301	
	Floor - Wood	325B - Practice Room	85	SF	6	\$599	
	Lighting - Pendent/Surface	325B - Practice Room	2	EA	6	\$248	
	Power Distribution	325B - Practice Room	2	EA	7	\$0	
	Walls - Plaster/Drywall	325B - Practice Room	135	SF	6	\$373	
	Ceiling - Splined	325C - Practice Room	85	SF	6	\$69	
	Doors - Wood Doors inclu hw	325C - Practice Room	1	EA	6	\$301	
	Floor - Wood	325C - Practice Room	85	SF	6	\$599	
	Lighting - Pendent/Surface	325C - Practice Room	1	EA	6	\$124	
	Power Distribution	325C - Practice Room	1	EA	7	\$0	
	Walls - Plaster/Drywall	325C - Practice Room	135	SF	6	\$373	
	Ceiling - Splined	325D - Practice Room	85	SF	6	\$69	
	Doors - Wood Doors inclu hw	325D - Practice Room	1	EA	6	\$301	
	Floor - Wood	325D - Practice Room	85	SF	6	\$599	
	Lighting - Pendent/Surface	325D - Practice Room	1	EA	6	\$124	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Power Distribution	325D - Practice Room	2	EA	7	\$0	
	Walls - Plaster/Drywall	325D - Practice Room	135	SF	6	\$373	
	AC Unit	369 - Naval Academy Office	1	EA	6	\$496	
	Ceiling - Lay-in	369 - Naval Academy Office	725	SF	6	\$2,177	
	Doors - Wood Doors inclu hw	369 - Naval Academy Office	1	EA	7	\$0	
	Floor - Wood	369 - Naval Academy Office	725	SF	6	\$5,111	
	Lighting - Lay-in	369 - Naval Academy Office	21	EA	6	\$2,498	
	Power Distribution	369 - Naval Academy Office	16	EA	6	\$33,998	
	Walls - Plaster/Drywall	369 - Naval Academy Office	897	SF	6	\$2,476	
	AC Unit	373 - Principal's Office	1	EA	5	\$1,826	
	Ceiling - Lay-in	373 - Principal's Office	225	SF	6	\$676	
	Doors - Wood Doors inclu hw	373 - Principal's Office	1	EA	7	\$0	
	Floor - Tile	373 - Principal's Office	225	SF	6	\$492	
	Lighting - Lay-in	373 - Principal's Office	3	EA	6	\$357	
	Power Distribution	373 - Principal's Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	373 - Principal's Office	711	SF	6	\$1,962	
	AC Unit	375 - Conference Room	1	EA	6	\$496	
	Ceiling - Lay-in	375 - Conference Room	225	SF	6	\$676	
	Doors - Wood Doors inclu hw	375 - Conference Room	1	EA	7	\$0	
	Floor - Carpet	375 - Conference Room	225	SF	6	\$479	
	Lighting - Lay-in	375 - Conference Room	6	EA	6	\$714	
	Power Distribution	375 - Conference Room	14	EA	6	\$29,748	
	Walls - Plaster/Drywall	375 - Conference Room	711	SF	6	\$1,962	
	AC Unit	377A - Asst Principal's Office	1	EA	6	\$496	
	Ceiling - Lay-in	377A - Asst Principal's Office	550	SF	6	\$1,652	
	Ceiling - Lay-in	377A - Asst Principal's Office	100	SF	5	\$694	yellow edge, water damage
	Doors - Wood Doors inclu hw	377A - Asst Principal's Office	1	EA	7	\$0	
	Floor - Tile	377A - Asst Principal's Office	650	SF	6	\$1,422	
	Lighting - Lay-in	377A - Asst Principal's Office	14	EA	6	\$1,666	
	Power Distribution	377A - Asst Principal's Office	18	EA	6	\$38,248	
	Walls - Plaster/Drywall	377A - Asst Principal's Office	467	SF	6	\$1,289	
	AC Unit	377B - Office	1	EA	6	\$496	
	Ceiling - Lay-in	377B - Office	180	SF	6	\$541	
	Doors - Wood Doors inclu hw	377B - Office	1	EA	7	\$0	
	Floor - Carpet	377B - Office	180	SF	7	\$0	
	Lighting - Pendent/Surface	377B - Office	6	EA	6	\$743	
	Power Distribution	377B - Office	20	EA	6	\$42,498	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Walls - Plaster/Drywall	377B - Office	489	SF	6	\$1,350	
	AC Unit	379 Office	1	EA	6	\$496	
	Ceiling - Lay-in	379 Office	576	SF	6	\$1,730	
	Doors - Wood Doors inclu hw	379 Office	2	EA	7	\$0	
	Floor - Carpet	379 Office	576	SF	6	\$1,227	
	Lighting - Lay-in	379 Office	15	EA	6	\$1,785	
	Power Distribution	379 Office	17	EA	6	\$36,123	
	Storage/ Closet	379 Office	22	SF	6	\$160	
	Walls - Plaster/Drywall	379 Office	1,217	SF	6	\$3,359	
	Ceiling - Lay-in	379A - Office	176	SF	6	\$529	
	Doors - Wood Doors inclu hw	379A - Office	1	EA	7	\$0	
	Floor - Carpet	379A - Office	176	SF	6	\$375	
	Lighting - Lay-in	379A - Office	4	EA	6	\$476	
	Power Distribution	379A - Office	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	379A - Office	531	SF	6	\$1,466	
	Ceiling - Lay-in	379B - Office	180	SF	6	\$541	
	Doors - Wood Doors inclu hw	379B - Office	1	EA	6	\$301	
	Floor - Carpet	379B - Office	180	SF	6	\$384	
	Lighting - Lay-in	379B - Office	4	EA	6	\$476	
	Power Distribution	379B - Office	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	379B - Office	489	SF	6	\$1,350	
<b>Auditorium &amp; Theater</b>							
	Ceiling - Splined	180 Harold Ramis Theatre	1,311	SF	6	\$1,069	
	Doors - Transom Window	180 Harold Ramis Theatre	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	180 Harold Ramis Theatre	2	EA	7	\$0	
	Floor - Tile	180 Harold Ramis Theatre	1,311	SF	6	\$2,868	
	Lighting - Pendent/Surface	180 Harold Ramis Theatre	26	EA	6	\$3,221	a few lights were not able to be turned on.
	Stage	180 Harold Ramis Theatre	334	SF	6	\$1,930	
	Stage Curtain	180 Harold Ramis Theatre	2	EA	6	\$0	
	Stage Lighting System	180 Harold Ramis Theatre	1	EA	7	\$0	
	Stage-Stairs - Wood	180 Harold Ramis Theatre	18	LF	6	\$211	
	Storage/ Closet	180 Harold Ramis Theatre	207	SF	6	\$1,501	
	Walls - Plaster/Drywall	180 Harold Ramis Theatre	2,802	SF	6	\$13,343	
	Balcony Seating	1st Floor	218	EA	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	13,161	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	22	EA	7	\$0	
	Floor - Carpet	1st Floor	3,630	SF	7	\$0	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Auditorium &amp; Theater</b>							
	Floor - Concrete Epoxy/ Painted	1st Floor	7,631	SF	7	\$0	
	Floor - Terrazzo	1st Floor	1,900	SF	7	\$0	lobby
	Lighting - Lay-in	1st Floor	51	EA	6	\$6,068	lamps out
	Lighting - Pendent/Surface	1st Floor	79	EA	6	\$9,788	lamps out
	Lighting - Wall Mounted	1st Floor	36	EA	7	\$0	
	Main Floor Seating	1st Floor	557	EA	7	\$0	
	Sound System	1st Floor	1	EA	7	\$0	
	Stage	1st Floor	1,963	SF	7	\$0	
	Stage Curtain	1st Floor	9	EA	7	\$0	
	Stage Lighting System	1st Floor	1	EA	7	\$0	
	Stage-Stairs - Wood	1st Floor	70	LF	7	\$0	carpet
	Walls - Plaster/Drywall	1st Floor	10,572	SF	7	\$0	
<b>Gymnasias</b>							
	Ceiling - Plaster/Drywall	156 Gym	4,627	SF	5	\$66,629	
	Doors - Wood Doors inclu hw	156 Gym	5	EA	6	\$1,505	
	Floor - Wood	156 Gym	4,627	SF	6	\$32,620	
	Lighting - Pendent/Surface	156 Gym	48	EA	7	\$0	
	Scoreboards	156 Gym	1	EA	6	\$2,244	
	Sound System	156 Gym	1	EA	6	\$41,654	
	Storage/ Closet	156 Gym	169	SF	6	\$1,225	
	Walls - Plaster/Drywall	156 Gym	16,052	SF	5	\$121,658	
	Ceiling - Plaster/Drywall	1st West	3,839	SF	5	\$55,282	water damage, peeling paint
	Doors - Wood Doors inclu hw	1st West	3	EA	6	\$903	
	Floor - Wood	1st West	3	SF	6	\$21	
	Lighting - Pendent/Surface	1st West	21	EA	7	\$0	
	Walls - Plaster/Drywall	1st West	3,825	SF	5	\$16,902	peeling paint, cracked walls
	Walls - Plaster/Drywall	1st West	3,825	SF	6	\$12,526	
<b>Kitchen</b>							
	Ceiling - Lay-in	189 - Servery (on plan)	2,400	SF	7	\$0	
	Ceiling - Plaster/Drywall	189 - Servery (on plan)	86	SF	5	\$788	
	Doors - Wood Doors inclu hw	189 - Servery (on plan)	9	EA	6	\$2,709	
	Doors - Wood Doors inclu hw	189 - Servery (on plan)	3	EA	5	\$3,522	
	Doors - Wood Doors inclu hw	189 - Servery (on plan)	1	EA	4	\$3,413	missing
	Floor - Tile Quarry	189 - Servery (on plan)	2,486	SF	6	\$5,261	
	Lighting - Lay-in	189 - Servery (on plan)	56	EA	6	\$6,663	
	Walls - Concrete Block	189 - Servery (on plan)	430	SF	7	\$0	



## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Kitchen</b>							
	Walls - Masonry	189 - Servery (on plan)	900	SF	6	\$2,831	glazed
	Walls - Plaster/Drywall	189 - Servery (on plan)	620	SF	7	\$0	
	Walls - Tile Ceramic/ Porcelain	189 - Servery (on plan)	200	SF	6	\$452	
	Walls - Tile Ceramic/ Porcelain	189 - Servery (on plan)	30	SF	5	\$557	
	Ceiling - Lay-in	189A - Kitchen (on plan)	1,240	SF	7	\$0	
	Ceiling - Plaster/Drywall	189A - Kitchen (on plan)	85	SF	5	\$914	@ west windows - water damage
	Ceiling - Plaster/Drywall	189A - Kitchen (on plan)	500	SF	7	\$0	
	Doors - Steel Doors incl hw	189A - Kitchen (on plan)	1	EA	6	\$301	
	Doors - Steel Doors incl hw	189A - Kitchen (on plan)	1	EA	4	\$3,536	no cylinder in door. no access to storage room.
	Doors - Transom Window	189A - Kitchen (on plan)	11	SF	6	\$186	
	Doors - Wood Doors inclu hw	189A - Kitchen (on plan)	1	EA	4	\$3,413	damaged + does not lock.
	Floor - Terrazzo	189A - Kitchen (on plan)	500	SF	5	\$18,819	
	Floor - Tile Quarry	189A - Kitchen (on plan)	1,325	SF	7	\$0	
	Lighting - Pendent/Surface	189A - Kitchen (on plan)	31	EA	6	\$3,841	
	Lighting - Pendent/Surface	189A - Kitchen (on plan)	5	EA	5	\$913	
	Storage/ Closet	189A - Kitchen (on plan)	200	SF	6	\$1,450	
	Walls - Concrete Block	189A - Kitchen (on plan)	430	SF	6	\$1,261	
	Walls - Masonry	189A - Kitchen (on plan)	1,740	SF	6	\$5,474	glazed
	Walls - Plaster/Drywall	189A - Kitchen (on plan)	228	SF	6	\$629	
	Ceiling - Splined	190H - Dishwashing	370	SF	6	\$302	
	Ceiling - Splined	190H - Dishwashing	30	SF	5	\$290	
	Floor - Terrazzo	190H - Dishwashing	400	SF	5	\$15,055	
	Lighting - Pendent/Surface	190H - Dishwashing	10	EA	7	\$0	
	Walls - Masonry	190H - Dishwashing	200	SF	4	\$16,096	stepped cracking in glazed masonry on east wall
	Walls - Masonry	190H - Dishwashing	500	SF	6	\$1,573	glazed
	Walls - Plaster/Drywall	190H - Dishwashing	175	SF	6	\$483	
	Ceiling - Lay-in	190J - Canteen	360	SF	6	\$1,081	
	Doors - Wood Doors inclu hw	190J - Canteen	4	EA	5	\$4,696	roll up type door
	Floor - Tile Quarry	190J - Canteen	360	SF	7	\$0	
	Lighting - Lay-in	190J - Canteen	9	EA	6	\$1,071	
	Serving Line	190J - Canteen	21	LF	6	\$1,250	
	Serving Line	190J - Canteen	7	LF	5	\$3,631	
	Walls - Plaster/Drywall	190J - Canteen	900	SF	5	\$6,821	
<b>Library</b>							
	AC Unit	225 Library	3	EA	6	\$1,487	
	Casework	225 Library	676	LF	6	\$17,072	deteriorated finishes
	Ceiling - Lay-in	225 Library	3,077	SF	5	\$18,304	bowed tiles and discolored grid

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Library</b>							
	Doors - Transom Window	225 Library	24	SF	6	\$406	
	Doors - Wood Doors inclu hw	225 Library	5	EA	7	\$0	
	Floor - Tile	225 Library	3,077	SF	5	\$13,816	worn, cracked, chipped throughout
	Lighting - Lay-in	225 Library	109	EA	6	\$12,968	
	Walls - Plaster/Drywall	225 Library	1,005	SF	5	\$4,441	
	Walls - Plaster/Drywall	225 Library	2,401	SF	6	\$6,627	
	Casework	227 Library	358	LF	6	\$9,041	deteriorated finish
	Ceiling - Lay-in	227 Library	845	SF	5	\$5,027	bowed tiles and discolored grid
	Doors - Wood Doors inclu hw	227 Library	1	EA	7	\$0	
	Floor - Tile	227 Library	845	SF	5	\$3,794	worn, cracks and chips throughout
	Lighting - Lay-in	227 Library	32	EA	7	\$0	
	Walls - Plaster/Drywall	227 Library	1,140	SF	5	\$8,640	water damage - cracked plaster & chipped paint; sill damage at windows
<b>Locker/Shower Room</b>							
	Accessories	1st Floor Mens Pool	694	SF	5	\$6,064	vandalized and heavily damaged
	Benches, ped mounted	1st Floor Mens Pool	36	LF	7	\$0	
	Ceiling - Plaster/ Drywall	1st Floor Mens Pool	964	SF	6	\$3,336	
	Doors - Steel Doors incl hw	1st Floor Mens Pool	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor Mens Pool	1	EA	5	\$1,174	
	Floor Drain	1st Floor Mens Pool	5	EA	5	\$10,470	
	Floor - Tile Ceramic/ Porcelain	1st Floor Mens Pool	694	SF	4	\$19,412	tile base has deteriorated beyond repair; floors do not slope to drains properly
	Lavatory	1st Floor Mens Pool	1	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor Mens Pool	17	EA	7	\$0	
	Partitions	1st Floor Mens Pool	1	EA	5	\$751	
	Showers	1st Floor Mens Pool	9	EA	5	\$24,430	showers dripping at several locations; replace shower heads
	Student Lockers - Two Tier	1st Floor Mens Pool	48	EA	7	\$0	
	Urinals	1st Floor Mens Pool	1	EA	7	\$0	
	Walls - Concrete Block	1st Floor Mens Pool	1,460	SF	6	\$4,280	
	Water Closet	1st Floor Mens Pool	1	EA	6	\$336	
	Accessories	1st Floor Pool Womens	1,967	SF	6	\$7,707	replace/refurbish at showers
	Benches, ped mounted	1st Floor Pool Womens	110	LF	5	\$30,222	worn, deteriorated
	Ceiling - Plaster/ Drywall	1st Floor Pool Womens	1,567	SF	6	\$5,423	
	Ceiling - Plaster/ Drywall	1st Floor Pool Womens	400	SF	5	\$4,490	water damage at exit to pool
	Doors - Steel Doors incl hw	1st Floor Pool Womens	2	EA	5	\$2,348	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Locker/Shower Room</b>							
	Doors - Wood Doors inclu hw	1st Floor Pool Womens	2	EA	4	\$6,826	doors to gym are original to building - hardware is damaged beyond repair, door is deteriorated beyond repair
	Floor Drain	1st Floor Pool Womens	1	EA	5	\$2,094	improper drainage at accessible shower - ponding water
	Floor Drain	1st Floor Pool Womens	5	EA	6	\$5,296	
	Floor - Tile Ceramic/ Porcelain	1st Floor Pool Womens	1,967	SF	6	\$4,163	
	Hand Dryer	1st Floor Pool Womens	10	EA	7	\$0	
	Lavatory	1st Floor Pool Womens	1	EA	6	\$320	old lavatory fixture
	Lavatory	1st Floor Pool Womens	1	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor Pool Womens	34	EA	7	\$0	
	Partitions	1st Floor Pool Womens	2	EA	7	\$0	
	Showers	1st Floor Pool Womens	16	EA	5	\$43,432	shower heads and add privacy panels worn, deteriorating
	Student Lockers - Two Tier	1st Floor Pool Womens	362	EA	4	\$94,949	heavily rusted; deteriorated hinges; damaged doors
	Walls - Concrete Block	1st Floor Pool Womens	1,404	SF	7	\$0	
	Walls - Structural Glazed Tile	1st Floor Pool Womens	810	SF	6	\$3,533	
	Walls - Structural Glazed Tile	1st Floor Pool Womens	810	SF	5	\$46,737	large cracks at gym wall
	Water Closet	1st Floor Pool Womens	2	EA	7	\$0	
<b>Lunch &amp; Multipurpose Room</b>							
	AC Unit	115 Social Center	2	EA	7	\$0	
	Ceiling - Lay-in	115 Social Center	1,344	SF	7	\$0	
	Doors - Transom Window	115 Social Center	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	115 Social Center	4	EA	6	\$1,204	
	Doors - Wood Doors inclu hw	115 Social Center	1	EA	7	\$0	
	Floor - Tile	115 Social Center	1,344	SF	7	\$0	
	Lighting - Lay-in	115 Social Center	24	EA	6	\$2,855	recessed compact fluorescent
	Lighting - Lay-in	115 Social Center	21	EA	6	\$2,498	
	Storage/ Closet	115 Social Center	8	SF	7	\$0	
	Walls - Plaster/Drywall	115 Social Center	1,410	SF	7	\$0	
	Ceiling - Lay-in	190 Cafeteria	11,500	SF	6	\$34,535	
	Doors - Wood Doors inclu hw	190 Cafeteria	1	EA	6	\$301	storage room - two deadbolt cylinders with different keys - not accessed
	Doors - Wood Doors inclu hw	190 Cafeteria	1	EA	4	\$3,413	padlocked storage room - not accessed
	Doors - Wood Doors inclu hw	190 Cafeteria	8	EA	7	\$0	
	Floor - Terrazzo	190 Cafeteria	200	SF	6	\$438	
	Floor - Tile Quarry	190 Cafeteria	11,300	SF	6	\$23,915	
	Lighting - Lay-in	190 Cafeteria	220	EA	6	\$26,175	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Lunch &amp; Multipurpose Room</b>							
	Walls - Plaster/Drywall	190 Cafeteria	4,800	SF	6	\$13,248	
	Walls - Plaster/Drywall	190 Cafeteria	200	SF	5	\$1,021	
<b>Mechanical/ Service Rooms</b>							
	Air Tunnel	118A - South	239	SF	6	\$1,480	
	Air Tunnel	118A Mech Room	419	SF	6	\$2,594	
	Storage Room	131A Vault in Main Office	176	SF	6	\$1,261	
	Janitor's Closet	1st Floor	38	SF	6	\$272	Janitors closet in main building next to 190G
	Janitor's Closet	1st Floor	14	SF	6	\$100	
	Mechanical/ Service Rooms	1st Floor	1,150	SF	6	\$8,239	west Fan Room
	Mechanical/ Service Rooms	1st Floor	1,150	SF	6	\$8,239	190K Fan Room (Motor Room 2)
	Storage Room	1st Floor	426	SF	6	\$3,052	Kitchen Dry Storage
	Storage Room	1st Floor	113	SF	6	\$810	190F
	Storage Room	1st Floor	253	SF	5	\$4,081	190 C - Storage (was men's locker room)
	Storage Room	1st Floor	250	SF	6	\$1,791	Storage room west wall of cafeteria adjacent to fan room. No access.
	Mechanical/ Service Rooms	1st Flr Pool Pump Room	385	SF	6	\$2,758	
	Mechanical/ Service Rooms	2nd Flr SE Electrical Room	96	SF	5	\$1,549	items being stored in this room
	Janitor's Closet	Janitor closet #2 West	32	SF	5	\$516	
	Janitor's Closet	Janitor Closet	15	SF	6	\$107	
	Storage Room	Second floor SW storage room	74	SF	6	\$530	
<b>Pool &amp; Natatorium</b>							
	Ceiling - Lay-In	118	1,647	SF	7	\$0	
	Ceiling - Plaster/ Drywall	118	1,513	SF	7	\$0	
	Doors - Steel Doors incl hw	118	4	EA	4	\$14,144	Exit paths and hardware from this space does not comply with current egress requirements - careful review and remediation is required; replace hardware on designated egress doors to comply with life safety standards
	Lighting - Metal Halide/ High Pressure Sodium	118	12	EA	7	\$0	
	Pool Basin	118	1,513	SF	6	\$51,191	
	Pool Deck	118	405	SF	5	\$10,239	cracks in tile at pool edge
	Pool Deck	118	1,242	SF	6	\$11,793	
	Pool Deck Drains	118	6	EA	6	\$2,532	
	Walls - Structural Glazed Tile	118	1,506	SF	5	\$76,517	mortar joints are missing or failing; glazed face is chipped in numerous locations
	Walls - Vinyl Coated Gypsum Panel	118	1,506	SF	7	\$0	FRP-faced wall is in good condition. Substrate at this material is unknown.

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Prep Room</b>							
	Casework	350A - Science Prep Room	25	LF	7	\$0	
	Ceiling - Lay-in	350A - Science Prep Room	292	SF	7	\$0	
	Doors - Wood Doors inclu hw	350A - Science Prep Room	1	EA	7	\$0	
	Floor - Tile	350A - Science Prep Room	292	SF	6	\$639	
	Lighting - Lay-in	350A - Science Prep Room	3	EA	7	\$0	
	Lighting - Pendent/Surface	350A - Science Prep Room	1	EA	7	\$0	
	Walls - Plaster/Drywall	350A - Science Prep Room	529	SF	7	\$0	
	Work Sink	350A - Science Prep Room	1	EA	7	\$0	
	Casework	352A Science Prep Room	27	LF	6	\$682	
	Ceiling - Plaster/Drywall	352A Science Prep Room	131	SF	7	\$0	
	Doors - Steel Doors incl hw	352A Science Prep Room	1	EA	6	\$301	
	Floor - Tile	352A Science Prep Room	131	SF	6	\$287	
	Lighting - Pendent/Surface	352A Science Prep Room	2	EA	7	\$0	
	Walls - Plaster/Drywall	352A Science Prep Room	459	SF	6	\$1,267	
	Work Sink	352A Science Prep Room	1	EA	6	\$379	
	Casework	356A	36	LF	6	\$909	
	Ceiling - Lay-in	356A	216	SF	7	\$0	
	Doors - Steel Doors incl hw	356A	1	EA	6	\$301	
	Floor - Tile	356A	216	SF	6	\$473	
	Lighting - Lay-in	356A	4	EA	7	\$0	
	Walls - Plaster/Drywall	356A	657	SF	6	\$1,813	
	Work Sink	356A	1	EA	6	\$379	
	Casework	364 A Science Room	50	LF	6	\$1,263	
	Ceiling - Plaster/Drywall	364 A Science Room	228	SF	6	\$789	
	Doors - Wood Doors inclu hw	364 A Science Room	1	EA	6	\$301	
	Floor - Tile	364 A Science Room	228	SF	5	\$1,024	warped floor, missing tiles,stained floor
	Lighting - Pendent/Surface	364 A Science Room	3	EA	6	\$372	
	Walls - Plaster/Drywall	364 A Science Room	639	SF	7	\$0	
	Work Sink	364 A Science Room	1	EA	5	\$1,508	
	Casework	366B	50	LF	6	\$1,263	
	Ceiling - Plaster/Drywall	366B	144	SF	6	\$498	
	Floor - Tile	366B	144	SF	6	\$315	
	Lighting - Pendent/Surface	366B	1	EA	7	\$0	
	Walls - Plaster/Drywall	366B	534	SF	6	\$1,474	
	Work Sink	366B	1	EA	6	\$379	
<b>Restroom</b>							
	Accessories	125A Unisex Toilet in Dean's Office	69	SF	6	\$636	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Ceiling - Plaster/Drywall	125A Unisex Toilet in Dean's Office	69	SF	6	\$239	
	Doors - Wood Doors inclu hw	125A Unisex Toilet in Dean's Office	1	EA	5	\$1,174	
	Floor - Tile Ceramic/ Porcelain	125A Unisex Toilet in Dean's Office	69	SF	6	\$146	
	Hand Dryer	125A Unisex Toilet in Dean's Office	1	EA	6	\$230	antique fixture
	Lavatory	125A Unisex Toilet in Dean's Office	1	EA	6	\$320	deteriorated faucets
	Lighting - Pendent/Surface	125A Unisex Toilet in Dean's Office	1	EA	6	\$124	
	Partitions	125A Unisex Toilet in Dean's Office	1	EA	5	\$751	
	Walls - Plaster/Drywall	125A Unisex Toilet in Dean's Office	316	SF	5	\$2,395	remove wall mounted shelf; cracked and damaged plaster and paint
	Water Closet	125A Unisex Toilet in Dean's Office	1	EA	6	\$336	
	Accessories	137A Principal's Toilet	45	SF	7	\$0	
	Ceiling - Plaster/Drywall	137A Principal's Toilet	45	SF	7	\$0	
	Doors - Wood Doors inclu hw	137A Principal's Toilet	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	137A Principal's Toilet	15	SF	7	\$0	
	Floor - Tile/Sheet	137A Principal's Toilet	30	SF	7	\$0	
	Lavatory	137A Principal's Toilet	1	EA	7	\$0	
	Lighting - Pendent/Surface	137A Principal's Toilet	1	EA	4	\$541	T-12
	Lighting - Wall Mounted	137A Principal's Toilet	1	EA	7	\$0	
	Partitions	137A Principal's Toilet	1	EA	7	\$0	
	Walls - Plaster/Drywall	137A Principal's Toilet	304	SF	7	\$0	
	Water Closet	137A Principal's Toilet	1	EA	7	\$0	
	Accessories	190E Womens Lockers off Kitchen	282	SF	7	\$0	
	Ceiling - Plaster/Drywall	190E Womens Lockers off Kitchen	282	SF	6	\$976	
	Doors - Wood Doors inclu hw	190E Womens Lockers off Kitchen	3	EA	6	\$903	
	Floor - Tile Quarry	190E Womens Lockers off Kitchen	282	SF	6	\$597	
	Lavatory	190E Womens Lockers off Kitchen	1	EA	7	\$0	
	Lighting - Pendent/Surface	190E Womens Lockers off Kitchen	3	EA	6	\$372	
	Lighting - Wall Mounted	190E Womens Lockers off Kitchen	1	EA	6	\$124	
	Student Lockers - One Tier	190E Womens Lockers off Kitchen	12	EA	7	\$0	
	Walls - Plaster/Drywall	190E Womens Lockers off Kitchen	1,301	SF	4	\$13,097	Major Structural Cracking in Toilet Room
	Water Closet	190E Womens Lockers off Kitchen	1	EA	6	\$336	
	Accessories	1st Floor Mens	558	SF	6	\$5,147	
	Ceiling - Plaster/Drywall	1st Floor Mens	558	SF	6	\$1,931	
	Doors - Wood Doors inclu hw	1st Floor Mens	1	EA	7	\$0	
	Floor Drain	1st Floor Mens	1	EA	6	\$1,059	
	Floor - Tile	1st Floor Mens	558	SF	7	\$0	
	Hand Dryer	1st Floor Mens	1	EA	6	\$230	
	Lavatory	1st Floor Mens	4	EA	6	\$1,278	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Lighting - Pendent/Surface	1st Floor Mens	8	EA	7	\$0	
	Partitions	1st Floor Mens	5	EA	7	\$0	
	Urinals	1st Floor Mens	9	EA	7	\$0	
	Walls - Masonry	1st Floor Mens	1,240	SF	6	\$3,901	
	Walls - Structural Glazed Tile	1st Floor Mens	413	SF	6	\$1,299	
	Water Closet	1st Floor Mens	5	EA	6	\$1,680	
	Accessories	1st Floor South - Single User Toilet Room in Girls Toilet Room	42	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor South - Single User Toilet Room in Girls Toilet Room	42	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor South - Single User Toilet Room in Girls Toilet Room	1	EA	5	\$1,174	
	Floor - Concrete	1st Floor South - Single User Toilet Room in Girls Toilet Room	42	SF	6	\$22	
	Lavatory	1st Floor South - Single User Toilet Room in Girls Toilet Room	1	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor South - Single User Toilet Room in Girls Toilet Room	1	EA	5	\$183	
	Partitions	1st Floor South - Single User Toilet Room in Girls Toilet Room	1	EA	5	\$751	
	Walls - Concrete Block	1st Floor South - Single User Toilet Room in Girls Toilet Room	151	SF	6	\$443	
	Walls - Structural Glazed Tile	1st Floor South - Single User Toilet Room in Girls Toilet Room	151	SF	6	\$475	
	Water Closet	1st Floor South - Single User Toilet Room in Girls Toilet Room	1	EA	6	\$336	
	Accessories	1st Floor South at Auditorium	450	SF	6	\$4,151	Mirror and soap dispenser.
	Ceiling - Plaster/Drywall	1st Floor South at Auditorium	450	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor South at Auditorium	2	EA	7	\$0	
	Floor Drain	1st Floor South at Auditorium	1	EA	6	\$1,059	
	Floor - Tile Quarry	1st Floor South at Auditorium	450	SF	6	\$952	
	Hand Dryer	1st Floor South at Auditorium	2	EA	6	\$460	
	Lavatory	1st Floor South at Auditorium	3	EA	6	\$959	
	Lighting - Pendent/Surface	1st Floor South at Auditorium	8	EA	6	\$991	
	Partitions	1st Floor South at Auditorium	6	EA	7	\$0	
	Walls - Concrete Block	1st Floor South at Auditorium	1,260	SF	6	\$3,694	
	Walls - Structural Glazed Tile	1st Floor South at Auditorium	1,260	SF	6	\$3,964	
	Water Closet	1st Floor South at Auditorium	6	EA	7	\$0	
	Accessories	1st Floor West	220	SF	6	\$2,029	
	Ceiling - Plaster/Drywall	1st Floor West	220	SF	6	\$761	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Doors - Steel Doors incl hw	1st Floor West	1	EA	7	\$0	
	Floor Drain	1st Floor West	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor West	132	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor West	88	SF	5	\$395	
	Hand Dryer	1st Floor West	1	EA	6	\$230	
	Lavatory	1st Floor West	3	EA	6	\$959	
	Lighting - Pendent/Surface	1st Floor West	5	EA	7	\$0	
	Partitions	1st Floor West	4	EA	7	\$0	
	Walls - Concrete Block	1st Floor West	418	SF	6	\$1,225	
	Walls - Plaster/Drywall	1st Floor West	139	SF	6	\$384	
	Water Closet	1st Floor West	4	EA	6	\$1,344	
	Accessories	227B - Library Office Toilet Room	20	SF	6	\$184	Paper towel dispenser, soap dispenser.
	Floor - Concrete Epoxy/ Painted	227B - Library Office Toilet Room	12	SF	6	\$6	
	Lavatory	227B - Library Office Toilet Room	1	EA	4	\$7,342	cracked fixture; faucet deteriorated
	Partitions	227B - Library Office Toilet Room	1	EA	6	\$297	
	Water Closet	227B - Library Office Toilet Room	1	EA	6	\$336	obsolete fixture type (tank)
	Accessories	2nd Floor East - Single User Toilet Room in Boys Toilet Room	30	SF	7	\$0	paper towel dispenser and soap dispenser.
	Ceiling - Plaster/Drywall	2nd Floor East - Single User Toilet Room in Boys Toilet Room	30	SF	6	\$104	
	Doors - Wood Doors inclu hw	2nd Floor East - Single User Toilet Room in Boys Toilet Room	1	EA	5	\$1,174	
	Floor - Tile Ceramic/ Porcelain	2nd Floor East - Single User Toilet Room in Boys Toilet Room	30	SF	7	\$0	
	Lavatory	2nd Floor East - Single User Toilet Room in Boys Toilet Room	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd Floor East - Single User Toilet Room in Boys Toilet Room	1	EA	5	\$183	
	Walls - Concrete Block	2nd Floor East - Single User Toilet Room in Boys Toilet Room	63	SF	5	\$647	
	Walls - Structural Glazed Tile	2nd Floor East - Single User Toilet Room in Boys Toilet Room	189	SF	5	\$9,603	
	Water Closet	2nd Floor East - Single User Toilet Room in Boys Toilet Room	1	EA	5	\$1,344	
	Accessories	2nd Floor East - Single User Toilet Room in Girls Toilet Room	42	SF	7	\$0	Soap dispenser and toilet paper.
	Ceiling - Plaster/Drywall	2nd Floor East - Single User Toilet Room in Girls Toilet Room	42	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor East - Single User Toilet Room in Girls Toilet Room	1	EA	5	\$1,174	



## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Floor - Concrete Epoxy/ Painted	2nd Floor East - Single User Toilet Room in Girls Toilet Room	42	SF	5	\$72	
	Lavatory	2nd Floor East - Single User Toilet Room in Girls Toilet Room	1	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor East - Single User Toilet Room in Girls Toilet Room	1	EA	5	\$183	
	Partitions	2nd Floor East - Single User Toilet Room in Girls Toilet Room	1	EA	6	\$297	
	Walls - Concrete Block	2nd Floor East - Single User Toilet Room in Girls Toilet Room	139	SF	6	\$407	
	Walls - Structural Glazed Tile	2nd Floor East - Single User Toilet Room in Girls Toilet Room	139	SF	6	\$437	
	Water Closet	2nd Floor East - Single User Toilet Room in Girls Toilet Room	1	EA	6	\$336	
	Accessories	2nd Floor East Single User Unisex in Teachers Work Room	56	SF	6	\$517	Mirror, soap, toilet paper, paper towel dispenser.
	Ceiling - Plaster/Drywall	2nd Floor East Single User Unisex in Teachers Work Room	56	SF	6	\$194	
	Doors - Wood Doors inclu hw	2nd Floor East Single User Unisex in Teachers Work Room	1	EA	7	\$0	
	Floor Drain	2nd Floor East Single User Unisex in Teachers Work Room	1	EA	6	\$1,059	
	Floor - Tile	2nd Floor East Single User Unisex in Teachers Work Room	56	SF	6	\$123	
	Lavatory	2nd Floor East Single User Unisex in Teachers Work Room	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd Floor East Single User Unisex in Teachers Work Room	1	EA	6	\$124	
	Walls - Concrete Block	2nd Floor East Single User Unisex in Teachers Work Room	420	SF	5	\$4,312	
	Water Closet	2nd Floor East Single User Unisex in Teachers Work Room	1	EA	6	\$336	
	Accessories	2nd Floor East Womens in Teachers Work Room	190	SF	6	\$1,752	Mirror, soap dispenser.
	Ceiling - Plaster/Drywall	2nd Floor East Womens in Teachers Work Room	414	SF	6	\$1,433	
	Doors - Wood Doors inclu hw	2nd Floor East Womens in Teachers Work Room	1	EA	6	\$301	
	Floor Drain	2nd Floor East Womens in Teachers Work Room	1	EA	6	\$1,059	
	Floor - Tile	2nd Floor East Womens in Teachers Work Room	190	SF	6	\$416	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Floor - Wood	2nd Floor East Womens in Teachers Work Room	224	SF	6	\$1,579	
	Lavatory	2nd Floor East Womens in Teachers Work Room	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd Floor East Womens in Teachers Work Room	1	EA	6	\$124	
	Partitions	2nd Floor East Womens in Teachers Work Room	2	EA	6	\$594	
	Walls - Concrete Block	2nd Floor East Womens in Teachers Work Room	288	SF	6	\$844	
	Walls - Masonry	2nd Floor East Womens in Teachers Work Room	288	SF	5	\$11,902	
	Water Closet	2nd Floor East Womens in Teachers Work Room	2	EA	6	\$672	
	Accessories	2nd Floor East	261	SF	6	\$2,407	Toilet paper, mirror, soap dispenser.
	Accessories	2nd Floor East	477	SF	7	\$0	Toilet paper and soap dispenser, mirror.
	Ceiling - Plaster/Drywall	2nd Floor East	477	SF	6	\$1,651	Peeling Paint.
	Ceiling - Plaster/Drywall	2nd Floor East	261	SF	7	\$0	
	Doors - Side-lite	2nd Floor East	10	SF	7	\$0	
	Doors - Transom Window	2nd Floor East	11	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor East	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor East	1	EA	7	\$0	
	Floor Drain	2nd Floor East	1	EA	5	\$2,094	
	Floor - Tile	2nd Floor East	261	SF	7	\$0	
	Floor - Tile Ceramic/ Porcelain	2nd Floor East	477	SF	6	\$1,010	
	Hand Dryer	2nd Floor East	1	EA	6	\$230	
	Hand Dryer	2nd Floor East	1	EA	6	\$230	
	Lavatory	2nd Floor East	3	EA	6	\$959	
	Lavatory	2nd Floor East	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd Floor East	9	EA	6	\$1,115	
	Lighting - Pendent/Surface	2nd Floor East	5	EA	6	\$619	2 of the lights were out.
	Partitions	2nd Floor East	4	EA	7	\$0	
	Partitions	2nd Floor East	5	EA	7	\$0	
	Urinals	2nd Floor East	8	EA	7	\$0	
	Walls - Concrete Block	2nd Floor East	351	SF	6	\$1,029	
	Walls - Concrete Block	2nd Floor East	606	SF	6	\$1,776	
	Walls - Masonry	2nd Floor East	202	SF	5	\$8,348	
	Walls - Masonry	2nd Floor East	351	SF	6	\$1,104	
	Water Closet	2nd Floor East	4	EA	7	\$0	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Water Closet	2nd Floor East	5	EA	7	\$0	
	Accessories	2nd Floor West - Multi User Toilet Room in Boys Toilet Room	121	SF	7	\$0	Mirror, soap dispenser, toilet paper.
	Ceiling - Plaster/Drywall	2nd Floor West - Multi User Toilet Room in Boys Toilet Room	121	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor West - Multi User Toilet Room in Boys Toilet Room	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	2nd Floor West - Multi User Toilet Room in Boys Toilet Room	121	SF	6	\$256	
	Lavatory	2nd Floor West - Multi User Toilet Room in Boys Toilet Room	1	EA	6	\$320	2 faucets
	Lighting - Pendent/Surface	2nd Floor West - Multi User Toilet Room in Boys Toilet Room	2	EA	6	\$248	
	Partitions	2nd Floor West - Multi User Toilet Room in Boys Toilet Room	2	EA	6	\$594	
	Walls - Masonry	2nd Floor West - Multi User Toilet Room in Boys Toilet Room	265	SF	5	\$10,952	
	Walls - Plaster/Drywall	2nd Floor West - Multi User Toilet Room in Boys Toilet Room	265	SF	5	\$2,008	
	Water Closet	2nd Floor West - Multi User Toilet Room in Boys Toilet Room	2	EA	6	\$672	
	Accessories	2nd Floor West - Single User Toilet Room in Girls Toilet Room	50	SF	6	\$461	Toilet Paper.
	Ceiling - Plaster/Drywall	2nd Floor West - Single User Toilet Room in Girls Toilet Room	50	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor West - Single User Toilet Room in Girls Toilet Room	1	EA	6	\$301	
	Floor - Concrete Epoxy/ Painted	2nd Floor West - Single User Toilet Room in Girls Toilet Room	50	SF	7	\$0	
	Lavatory	2nd Floor West - Single User Toilet Room in Girls Toilet Room	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd Floor West - Single User Toilet Room in Girls Toilet Room	1	EA	6	\$124	
	Partitions	2nd Floor West - Single User Toilet Room in Girls Toilet Room	1	EA	7	\$0	
	Walls - Concrete Block	2nd Floor West - Single User Toilet Room in Girls Toilet Room	124	SF	5	\$1,273	
	Walls - Structural Glazed Tile	2nd Floor West - Single User Toilet Room in Girls Toilet Room	124	SF	5	\$6,300	
	Water Closet	2nd Floor West - Single User Toilet Room in Girls Toilet Room	1	EA	7	\$0	
	Accessories	2nd Floor West	349	SF	6	\$3,219	Toilet paper, soap, mirror.
	Accessories	2nd Floor West	371	SF	6	\$3,422	Mirror, toilet paper, soap dispenser.

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Ceiling - Plaster/Drywall	2nd Floor West	371	SF	7	\$0	
	Ceiling - Plaster/Drywall	2nd Floor West	349	SF	7	\$0	
	Doors - Side-lite	2nd Floor West	11	SF	7	\$0	
	Doors - Side-lite	2nd Floor West	11	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor West	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	2nd Floor West	1	EA	7	\$0	
	Floor Drain	2nd Floor West	1	EA	6	\$1,059	
	Floor Drain	2nd Floor West	1	EA	6	\$1,059	
	Floor - Tile	2nd Floor West	349	SF	7	\$0	
	Floor - Tile Quarry	2nd Floor West	371	SF	7	\$0	
	Hand Dryer	2nd Floor West	1	EA	7	\$0	
	Hand Dryer	2nd Floor West	1	EA	7	\$0	
	Lavatory	2nd Floor West	2	EA	7	\$0	
	Lavatory	2nd Floor West	3	EA	6	\$959	
	Lighting - Pendent/Surface	2nd Floor West	6	EA	6	\$743	
	Lighting - Pendent/Surface	2nd Floor West	5	EA	6	\$619	
	Partitions	2nd Floor West	8	EA	7	\$0	
	Partitions	2nd Floor West	3	EA	7	\$0	
	Urinals	2nd Floor West	2	EA	7	\$0	
	Walls - Concrete Block	2nd Floor West	495	SF	6	\$1,451	
	Walls - Concrete Block	2nd Floor West	385	SF	6	\$1,129	
	Walls - Masonry	2nd Floor West	165	SF	5	\$6,819	
	Walls - Structural Glazed Tile	2nd Floor West	335	SF	6	\$1,054	
	Water Closet	2nd Floor West	3	EA	7	\$0	
	Water Closet	2nd Floor West	8	EA	7	\$0	
	Accessories	3rd Floor East - Single User Toilet Room in Boys Toilet Room	27	SF	6	\$249	
	Ceiling - Plaster/Drywall	3rd Floor East - Single User Toilet Room in Boys Toilet Room	27	SF	6	\$93	
	Doors - Wood Doors inclu hw	3rd Floor East - Single User Toilet Room in Boys Toilet Room	1	EA	5	\$1,174	
	Floor - Tile Ceramic/ Porcelain	3rd Floor East - Single User Toilet Room in Boys Toilet Room	27	SF	7	\$0	
	Lavatory	3rd Floor East - Single User Toilet Room in Boys Toilet Room	1	EA	6	\$320	
	Lighting - Pendent/Surface	3rd Floor East - Single User Toilet Room in Boys Toilet Room	1	EA	6	\$124	
	Walls - Concrete Block	3rd Floor East - Single User Toilet Room in Boys Toilet Room	80	SF	5	\$821	peeling paint

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Walls - Structural Glazed Tile	3rd Floor East - Single User Toilet Room in Boys Toilet Room	160	SF	5	\$8,129	damaged material
	Water Closet	3rd Floor East - Single User Toilet Room in Boys Toilet Room	1	EA	6	\$336	
	Accessories	3rd Floor East - Single User Toilet Room in Girls Toilet Room	24	SF	7	\$0	toilet paper, soap dispenser, paper towel dispenser.
	Ceiling - Plaster/Drywall	3rd Floor East - Single User Toilet Room in Girls Toilet Room	24	SF	7	\$0	
	Doors - Wood Doors inclu hw	3rd Floor East - Single User Toilet Room in Girls Toilet Room	1	EA	5	\$1,174	
	Floor - Concrete Epoxy/ Painted	3rd Floor East - Single User Toilet Room in Girls Toilet Room	24	SF	5	\$41	
	Lavatory	3rd Floor East - Single User Toilet Room in Girls Toilet Room	1	EA	6	\$320	Dual Faucet
	Lighting - Pendent/Surface	3rd Floor East - Single User Toilet Room in Girls Toilet Room	1	EA	6	\$124	
	Partitions	3rd Floor East - Single User Toilet Room in Girls Toilet Room	1	EA	5	\$751	
	Walls - Concrete Block	3rd Floor East - Single User Toilet Room in Girls Toilet Room	119	SF	6	\$349	
	Walls - Masonry	3rd Floor East - Single User Toilet Room in Girls Toilet Room	60	SF	6	\$189	
	Water Closet	3rd Floor East - Single User Toilet Room in Girls Toilet Room	1	EA	6	\$336	
	Accessories	3rd Floor East	245	SF	6	\$2,260	Vandalized restroom, soap dispenser.
	Accessories	3rd Floor East	231	SF	7	\$0	Mirror, soap dispenser, and toilet paper.
	Ceiling - Plaster/Drywall	3rd Floor East	245	SF	5	\$2,246	Water Damage.
	Ceiling - Plaster/Drywall	3rd Floor East	231	SF	7	\$0	
	Doors - Side-lite	3rd Floor East	11	SF	6	\$184	
	Doors - Wood Doors inclu hw	3rd Floor East	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	3rd Floor East	1	EA	7	\$0	
	Floor Drain	3rd Floor East	1	EA	6	\$1,059	
	Floor Drain	3rd Floor East	1	EA	5	\$2,094	
	Floor - Tile Ceramic/ Porcelain	3rd Floor East	231	SF	7	\$0	
	Floor - Tile Ceramic/ Porcelain	3rd Floor East	245	SF	6	\$519	
	Hand Dryer	3rd Floor East	1	EA	7	\$0	
	Lavatory	3rd Floor East	3	EA	6	\$959	
	Lavatory	3rd Floor East	2	EA	6	\$639	
	Lighting - Pendent/Surface	3rd Floor East	5	EA	6	\$619	
	Lighting - Pendent/Surface	3rd Floor East	7	EA	6	\$867	
	Partitions	3rd Floor East	3	EA	7	\$0	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Partitions	3rd Floor East	4	EA	7	\$0	
	Urinals	3rd Floor East	7	EA	7	\$0	
	Walls - Concrete Block	3rd Floor East	354	SF	7	\$0	
	Walls - Concrete Block	3rd Floor East	392	SF	6	\$1,149	
	Walls - Masonry	3rd Floor East	392	SF	5	\$16,200	Peeling paint and water damage.
	Walls - Masonry	3rd Floor East	354	SF	5	\$14,630	
	Water Closet	3rd Floor East	3	EA	7	\$0	
	Water Closet	3rd Floor East	4	EA	7	\$0	
	Accessories	3rd Floor West Unisex	24	SF	6	\$221	
	Ceiling - Plaster/Drywall	3rd Floor West Unisex	24	SF	6	\$83	
	Doors - Wood Doors inclu hw	3rd Floor West Unisex	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	3rd Floor West Unisex	24	SF	6	\$51	
	Lavatory	3rd Floor West Unisex	1	EA	6	\$320	obsolete design (double faucet)
	Lighting - Metal Halide/Sodium Vapor	3rd Floor West Unisex	1	EA	6	\$134	
	Walls - Concrete Block	3rd Floor West Unisex	112	SF	6	\$328	
	Water Closet	3rd Floor West Unisex	1	EA	6	\$336	
	Accessories	3rd Floor West	231	SF	6	\$2,131	
	Accessories	3rd Floor West	245	SF	6	\$2,260	
	Ceiling - Plaster/Drywall	3rd Floor West	231	SF	6	\$799	
	Ceiling - Plaster/Drywall	3rd Floor West	245	SF	6	\$848	
	Doors - Wood Doors inclu hw	3rd Floor West	1	EA	5	\$1,174	
	Doors - Wood Doors inclu hw	3rd Floor West	2	EA	5	\$2,348	
	Floor Drain	3rd Floor West	1	EA	6	\$1,059	
	Floor Drain	3rd Floor West	1	EA	6	\$1,059	
	Floor - Tile	3rd Floor West	245	SF	6	\$536	
	Floor - Tile Ceramic/ Porcelain	3rd Floor West	231	SF	6	\$489	
	Hand Dryer	3rd Floor West	1	EA	6	\$230	
	Lavatory	3rd Floor West	3	EA	6	\$959	
	Lavatory	3rd Floor West	2	EA	6	\$639	
	Lighting - Pendent/Surface	3rd Floor West	5	EA	5	\$913	
	Lighting - Pendent/Surface	3rd Floor West	7	EA	6	\$867	
	Partitions	3rd Floor West	4	EA	6	\$1,188	
	Partitions	3rd Floor West	3	EA	6	\$891	
	Urinals	3rd Floor West	7	EA	6	\$2,352	
	Walls - Concrete Block	3rd Floor West	354	SF	6	\$1,038	
	Walls - Concrete Block	3rd Floor West	392	SF	5	\$4,025	
	Walls - Structural Glazed Tile	3rd Floor West	354	SF	6	\$1,114	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Water Closet	3rd Floor West	4	EA	6	\$1,344	
	Water Closet	3rd Floor West	3	EA	6	\$1,008	
	Accessories	Unisex Shower/Toilet Room in 156B	109	SF	6	\$1,005	
	Ceiling - Plaster/Drywall	Unisex Shower/Toilet Room in 156B	109	SF	6	\$377	
	Doors - Steel Doors incl hw	Unisex Shower/Toilet Room in 156B	1	EA	6	\$301	
	Floor Drain	Unisex Shower/Toilet Room in 156B	2	EA	7	\$0	
	Floor - Tile	Unisex Shower/Toilet Room in 156B	109	SF	6	\$238	
	Lavatory	Unisex Shower/Toilet Room in 156B	1	EA	6	\$320	
	Lighting - Pendent/Surface	Unisex Shower/Toilet Room in 156B	2	EA	6	\$248	
	Partitions	Unisex Shower/Toilet Room in 156B	1	EA	6	\$297	
	Showers	Unisex Shower/Toilet Room in 156B	1	EA	6	\$311	
	Walls - Concrete Block	Unisex Shower/Toilet Room in 156B	170	SF	6	\$498	
	Walls - Plaster/Drywall	Unisex Shower/Toilet Room in 156B	487	SF	6	\$1,344	
	Water Closet	Unisex Shower/Toilet Room in 156B	1	EA	6	\$336	

**Rooms (Other Than Classrooms) Subtotal:**
**\$2,133,329**

## Building: Main

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Ceiling - Lay-in	129B Link from 129 to Main Office	96	SF	7	\$0	
	Doors - Transom Window	129B Link from 129 to Main Office	11	EA	7	\$0	
	Doors - Wood Doors include hw	129B Link from 129 to Main Office	1	EA	7	\$0	
	Doors - Wood Doors include hw	129B Link from 129 to Main Office	1	EA	6	\$301	
	Floor - Tile/Sheet	129B Link from 129 to Main Office	96	SF	7	\$0	
	Lighting - Lay-in	129B Link from 129 to Main Office	2	EA	7	\$0	
	Walls - Plaster/Drywall	129B Link from 129 to Main Office	409	SF	6	\$1,813	
	Ceiling - Lay-in	1st floor East corridor	6,064	SF	5	\$39,976	wa, crackster damage
	Doors - Steel Doors incl hw	1st floor East corridor	2	EA	7	\$0	
	Doors - Wood Doors include hw	1st floor East corridor	6	EA	6	\$1,806	
	Doors - Wood Doors include hw	1st floor East corridor	6	EA	5	\$7,044	
	Drinking Fountains - Single Water Cooler	1st floor East corridor	1	EA	6	\$317	
	Floor - Terrazzo	1st floor East corridor	6,064	SF	5	\$228,234	cracked floor
	Lighting - Lay-in	1st floor East corridor	17	EA	6	\$2,023	
	Lighting - Pendent/Surface	1st floor East corridor	6	EA	6	\$743	
	Stairs - Concrete Stairs	1st floor East corridor	18	LF	6	\$149	

## Building: Main

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Student Lockers - One Tier	1st floor East corridor	250	EA	6	\$23,209	
	Walls - Plaster/Drywall	1st floor East corridor	8,385	SF	6	\$37,171	cracks on walls
	Ceiling - Lay-in	1st Floor Vestibule	1,800	SF	6	\$5,405	
	Doors - Transom Window	1st Floor Vestibule	90	EA	6	\$1,524	
	Doors - Wood Doors include hw	1st Floor Vestibule	20	EA	6	\$6,020	
	Floor - Terrazzo	1st Floor Vestibule	1,800	SF	6	\$15,109	
	Lighting - Lay-in	1st Floor Vestibule	19	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor Vestibule	1,733	SF	6	\$7,682	
	Ceiling - Lay-in	1st South	1,951	SF	5	\$12,862	
	Ceiling - Plaster/Drywall	1st South	325	SF	6	\$2,012	
	Floor - Terrazzo	1st South	2,276	SF	6	\$19,105	
	Lighting - Lay-in	1st South	17	EA	6	\$2,023	
	Lighting - Pendent/Surface	1st South	6	EA	6	\$743	
	Stairs - Concrete Stairs	1st South	18	LF	6	\$149	
	Walls - Plaster/Drywall	1st South	3,570	SF	6	\$15,826	
	Ceiling - Lay-in	1st West	5,950	SF	5	\$39,224	water damage, cracked, rusted surface
	Drinking Fountains - Single Water Cooler	1st West	1	EA	6	\$317	
	Floor - Terrazzo	1st West	5,950	SF	6	\$49,945	
	Lighting - Lay-in	1st West	53	EA	6	\$6,306	
	Lighting - Pendent/Surface	1st West	9	EA	6	\$1,115	missing surface lens
	Student Lockers - One Tier	1st West	236	EA	6	\$21,909	
	Walls - Plaster/Drywall	1st West	7,468	SF	6	\$33,106	
	Ceiling - Lay-in	2nd East	6,069	SF	6	\$18,225	
	Drinking Fountains - Single Water Cooler	2nd East	2	EA	6	\$633	
	Floor - Tile/Sheet	2nd East	6,069	SF	6	\$3,298	
	Lighting - Lay-in	2nd East	79	EA	7	\$0	
	Student Lockers - One Tier	2nd East	360	EA	6	\$33,421	
	Walls - Plaster/Drywall	2nd East	9,984	SF	6	\$44,259	
	Ceiling - Plaster/Drywall	2nd South	2,276	SF	5	\$28,674	water damage
	Floor - Tile/Sheet	2nd South	2,276	SF	5	\$10,220	
	Lighting - Lay-in	2nd South	30	EA	6	\$3,569	
	Student Lockers - One Tier	2nd South	240	EA	6	\$22,281	
	Walls - Plaster/Drywall	2nd South	4,177	SF	6	\$18,517	
	Ceiling - Lay-in	2nd West	4,023	SF	5	\$26,521	cracks
	Drinking Fountains - Single Water Cooler	2nd West	1	EA	6	\$317	
	Floor - Tile/Sheet	2nd West	4,023	SF	6	\$2,186	vct, warped
	Lighting - Lay-in	2nd West	57	EA	6	\$6,782	



## Building: Main

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Student Lockers - One Tier	2nd West	205	EA	6	\$19,031	
	Walls - Plaster/Drywall	2nd West	6,517	SF	5	\$48,088	
	Ceiling - Lay-in	3rd East	4,023	SF	5	\$26,521	water damage, yellowed edge
	Drinking Fountains - Single Water Cooler	3rd East	2	EA	6	\$633	
	Floor - Tile/Sheet	3rd East	4,023	SF	6	\$2,186	vct
	Lighting - Lay-in	3rd East	67	EA	6	\$7,971	
	Student Lockers - One Tier	3rd East	360	EA	6	\$33,421	
	Walls - Plaster/Drywall	3rd East	4,367	SF	6	\$19,359	
	Ceiling - Plaster/Drywall	3rd North (small corridor)	1,320	SF	6	\$8,173	
	Floor - Tile/Sheet	3rd North (small corridor)	1,320	SF	6	\$717	vct
	Lighting - Lay-in	3rd North (small corridor)	17	EA	7	\$0	
	Student Lockers - One Tier	3rd North (small corridor)	102	EA	6	\$9,469	
	Walls - Plaster/Drywall	3rd North (small corridor)	2,640	SF	6	\$11,703	
	Ceiling - Lay-in	3rd South	1,952	SF	6	\$5,862	
	Floor - Tile/Sheet	3rd South	1,952	SF	6	\$1,061	
	Lighting - Lay-in	3rd South	30	EA	6	\$3,569	
	Student Lockers - One Tier	3rd South	242	EA	6	\$22,466	
	Walls - Plaster/Drywall	3rd South	2,946	SF	6	\$13,060	
	Ceiling - Lay-in	3rd West	4,297	SF	6	\$12,904	
	Drinking Fountains - Single Water Cooler	3rd West	2	EA	6	\$633	
	Floor - Tile/Sheet	3rd West	4,297	SF	6	\$2,335	vct
	Lighting - Lay-in	3rd West	55	EA	6	\$6,544	
	Student Lockers - One Tier	3rd West	212	EA	6	\$19,681	
	Walls - Plaster/Drywall	3rd West	4,288	SF	6	\$19,009	
	Ceiling - Lay-in	Corridor in Main Office 135	300	SF	7	\$0	
	Doors - Steel Doors incl hw	Corridor in Main Office 135	1	EA	7	\$0	
	Doors - Transom Window	Corridor in Main Office 135	11	EA	7	\$0	
	Doors - Wood Doors include hw	Corridor in Main Office 135	1	EA	7	\$0	
	Floor - Tile/Sheet	Corridor in Main Office 135	300	SF	7	\$0	
	Lighting - Lay-in	Corridor in Main Office 135	20	EA	7	\$0	Lights included here for offices 130, 132 and 133 which have partial height partitions
	Walls - Metal Panel	Corridor in Main Office 135	300	SF	7	\$0	Panels are wood not metal
	Walls - Plaster/Drywall	Corridor in Main Office 135	852	SF	6	\$3,777	
<b>Safety</b>							
	Camera Viewing Station		3	EA	7	\$0	per principal
	Security Cameras		55	EA	7	\$0	per principal
	Security Cameras		5	EA	7	\$0	per principal

## Building: Main

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Stairs</b>							
	Ceiling - Plaster/Drywall	North East	200	SF	6	\$1,464	
	Floor - Concrete Epoxy/ Painted	North East	234	SF	5	\$1,067	cracks throughout
	Floor - Tile/Sheet	North East	187	SF	5	\$840	
	Handrails	North East	218	LF	5	\$2,506	paint peeled, worn out, rusted,
	Lighting - Lay-in	North East	3	EA	6	\$357	
	Lighting - Wall Mounted	North East	12	EA	6	\$1,487	
	Stairs - Concrete	North East	341	LF	5	\$33,788	
	Walls - Plaster/Drywall	North East	2,098	SF	6	\$5,790	a few cracks
	Ceiling - Lay-in	North West	488	SF	6	\$1,465	
	Floor - Epoxy/ Painted	North West	306	SF	5	\$1,396	major cracks
	Floor - Tile/Sheet	North West	265	SF	6	\$144	
	Handrails	North West	165	LF	6	\$1,430	needs to be repainted
	Lighting - Pendent/Surface	North West	8	EA	6	\$991	
	Stairs - Concrete	North West	440	LF	6	\$3,649	
	Walls - Plaster/Drywall	North West	3,734	SF	6	\$10,305	
	Ceiling - Plaster/Drywall	South East	200	SF	6	\$1,464	
	Floor - Concrete Epoxy/ Painted	South East	234	SF	6	\$114	
	Floor - Tile/Sheet	South East	187	SF	6	\$102	
	Handrails	South East	218	LF	5	\$2,506	
	Lighting - Lay-in	South East	3	EA	6	\$357	
	Lighting - Wall Mounted	South East	12	EA	6	\$1,487	
	Stairs - Concrete	South East	341	LF	6	\$2,828	
	Walls - Plaster/Drywall	South East	2,098	SF	6	\$5,790	
	Ceiling - Lay-in	South West	297	SF	6	\$892	
	Floor - Epoxy/ Painted	South West	426	SF	5	\$1,943	
	Floor - Tile/Sheet	South West	346	SF	6	\$188	
	Handrails	South West	151	LF	6	\$1,309	
	Lighting - Pendent/Surface	South West	9	EA	7	\$0	
	Stairs - Concrete	South West	436	LF	6	\$3,616	
	Walls - Plaster/Drywall	South West	3,152	SF	6	\$8,699	
	Ceiling - Lay-in	West	910	SF	6	\$2,733	
	Floor - Epoxy/ Painted	West	487	SF	6	\$258	
	Floor - Terrazzo	West	306	SF	6	\$2,569	
	Floor - Tile/Sheet	West	646	SF	6	\$351	
	Handrails	West	306	LF	6	\$2,652	
	Lighting - Pendent/Surface	West	22	EA	7	\$0	
	Stairs	West	977	LF	6	\$0	

## Building: Main

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Stairs</b>							
	Walls - Concrete Block	West	170	SF	6	\$498	Step cracks in vestibule area
	Walls - Plaster/Drywall	West	3,740	SF	5	\$17,061	Large cracks in vestibule area
<b>Vertical Conveyance</b>							
	Wheelchair Lift - Chair Lift		1	EA	6	\$5,597	

**Building Interior Subtotal: \$1,229,938**

**Total Building Cost \$9,225,834**

## Building: Addition 1

### Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Entrance</b>							
	Entrance Control - Audio and Video	2	1	EA	6	\$702	
	Entrance Control - Audio and Video	North - Clinic Loading	1	EA	6	\$702	
	Exterior Doors - Exterior Steel Door	1	2	EA	5	\$2,683	peeling paint, graffiti
	Exterior Doors - Exterior Steel Door	11	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	12	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	2	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	3	3	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	North - Boiler Room	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	North - Electrical Outbuilding	4	EA	6	\$1,922	
	Exterior Doors - Exterior Steel Door	North - Storage	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	NW - Auto Storage	1	EA	6	\$481	
	Exterior Doors - Overhead Rolling/ Garage Door	North - Clinic Loading	1	EA	6	\$1,433	
	Exterior Doors - Overhead Rolling/ Garage Door	North - Mechanical Room	1	EA	6	\$1,433	
	Exterior Doors - Overhead Rolling/ Garage Door	North - Storage	1	EA	7	\$0	
	Exterior Doors - Overhead Rolling/ Garage Door	NW - AutoShop	1	EA	6	\$1,433	
	Exterior Doors - Side lite	North - Clinic Loading	2	EA	6	\$627	
	Exterior Doors - Transom Lite	1	2	EA	6	\$627	
	Exterior Doors - Transom Lite	2	3	EA	6	\$940	
	Exterior Doors - Transom Lite	3	3	EA	6	\$940	
	Exterior Doors - Transom Lite	North - Clinic Loading	1	EA	6	\$313	
	Exterior Stairs - Concrete	12	70	LF	6	\$5,724	
	Exterior Stairs - Concrete	2	80	LF	6	\$6,541	
	Exterior Stairs - Concrete	2	16	LF	4	\$2,617	chipped nosings, spalling concrete

## Building: Addition 1

### Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Entrance</b>							
	Exterior Stairs - Concrete	North - Boiler Room	25	LF	6	\$2,044	
	Exterior Stairs - Concrete	North - Clinic Loading	25	LF	6	\$2,044	
	Exterior Stairs - Stone	1	160	LF	5	\$43,387	chipped nosings, spalling patches, deteriorated mortar joints
	Exterior Stairs - Stone	12	8	LF	5	\$2,169	
	Exterior Stairs - Stone	3	40	LF	5	\$10,847	chipping nosings, deteriorated mortar joints
	Exterior Stairs - Stone	NW - Auto Storage	3	LF	5	\$814	chipped nosings, deteriorated mortar
	Power Door Operator and Controls	2	1	EA	6	\$0	
	Ramp Handrail - Steel_Ramp Handrail	2	88	LF	6	\$763	
	Ramp Handrail - Steel_Ramp Handrail	North - Mechanical Room	30	LF	6	\$260	
	Ramps - Concrete	2	44	LF	6	\$6,610	small areas of surface deterioration
	Ramps - Concrete	North - Mechanical Room	15	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	2	30	LF	5	\$345	corroded
	Stair Handrail - Steel_Stair Handrail	North - Boiler Room	35	LF	6	\$303	peeling paint
<b>Foundation</b>							
	Foundation - Concrete	Entire Building	915	LF	7	\$0	
	Superstructure - Concrete	Entire Building	33,906	SF	7	\$0	
<b>Lighting</b>							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	5	EA	6	\$2,683	
	Exterior Lighting - Wall Mounted	Entire Building	15	EA	6	\$4,331	
<b>Roof System</b>							
	Chimney - Brick Chimney- Concrete/ Mortar Liner	B	20	LF	5	\$57,031	step cracking, deteriorated mortar
	Chimney - Brick Chimney- Concrete/ Mortar Liner	B	70	LF	6	\$66,828	
	Coping - Metal	A	120	LF	5	\$5,072	
	Coping - Metal	D	140	LF	7	\$0	metal fascia
	Coping - Stone	A	484	LF	6	\$15,545	
	Coping - Stone	D	249	LF	6	\$7,997	
	Coping - Terra Cotta	A	147	LF	6	\$4,721	
	Coping - Terra Cotta	B	175	LF	6	\$5,621	
	Downspouts - Interior Downspouts	A	340	LF	6	\$11,299	
	Downspouts - Interior Downspouts	B	114	LF	6	\$3,789	
	Downspouts - Interior Downspouts	D	43	LF	6	\$1,429	
	Parapet - 16" - 30" Height	A	751	LF	6	\$30,006	
	Parapet - 16" - 30" Height	B	137	LF	6	\$5,474	
	Parapet - 16" - 30" Height	D	30	LF	5	\$6,112	bulge
	Parapet - 16" - 30" Height	D	55	LF	6	\$2,197	

## Building: Addition 1

### Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Roof System</b>							
	Parapet - Parapet < 16" Height	B	38	LF	6	\$810	
	Parapet - Parapet > 30"	B	194	LF	6	\$12,401	
	Parapet - Parapet > 30"	D	194	LF	6	\$12,401	
	Roof Structure - Steel with Clay Tile Arch	A	20,642	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	B	2,448	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	D	9,932	SF	7	\$0	
	Roof - Modified Bitumen	A	20,642	SF	5	\$434,211	bubbling, splitting, deterioration
	Roof - Modified Bitumen	B	2,448	SF	5	\$51,494	bubbling, splitting, deterioration
	Roof - Modified Bitumen	D	9,932	SF	5	\$208,923	bubbling, splitting, deterioration
<b>Walls</b>							
	Cheek-Wall - Stone	Entire Building	48	SF	5	\$1,142	chipped
	Cornice - Metal Projecting	Entire Building	790	LF	5	\$118,856	minor corrosion throughout
	Exterior Walls - Brick	Entire Building	40	SF	4	\$6,586	bulging
	Exterior Walls - Brick	Entire Building	30	SF	5	\$714	bulging
	Exterior Walls - Brick	Entire Building	22,616	SF	6	\$152,002	
	Exterior Walls - Brick	Entire Building	1,060	SF	5	\$25,238	ivy throughout
	Exterior Walls - Stone-Cut	Entire Building	200	SF	5	\$3,524	spalled stone
	Exterior Walls - Stone-Cut	Entire Building	3,622	SF	6	\$24,343	
	Exterior Walls - Stone-Cut	Entire Building	220	SF	5	\$3,876	ivy throughout
	Exterior Walls - Terra Cotta	Entire Building	3,348	SF	6	\$22,502	
	Exterior Walls - Terra Cotta	Entire Building	150	SF	5	\$2,338	ivy throughout
<b>Windows</b>							
	Guard - Guards perforated	Entire Building	210	SF	5	\$3,219	ivy throughout
	Guard - Guards perforated	Entire Building	4,594	SF	6	\$58,665	
	Lintels - Steel	Entire Building	1,016	LF	6	\$29,493	
	Lintels - Terra Cotta	Entire Building	140	LF	6	\$0	
	Windows - Sash Aluminum Double-pane	Entire Building	600	SF	5	\$32,321	ivy throughout
	Windows - Sash Aluminum Double-pane	Entire Building	12,861	SF	6	\$96,002	

### Building Exterior Subtotal:

**\$1,634,225**

## Building: Addition 1

### Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Emergency System</b>							
	Automatic Transfer Switch	1st Floor	3	EA	7	\$0	

## Building: Addition 1

### Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Emergency System</b>							
	Emergency A/C Power - Corridors and Stairs	Entire Building	14,997	SF	6	\$4,504	
	Emergency A/C Power - Students Toilets	Entire Building	748	SF	6	\$278	
	Emergency Generator- Outdoor- Diesel - 101 - 150 KW	North Courtyard	1	EA	6	\$11,529	Serves entire school
	Exit Signs - Corridors and Stairs	Entire Building	16	EA	6	\$2,396	
<b>Main Service</b>							
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Mechanical Room / 1st Floor	1	EA	6	\$10,867	Serves north addition
<b>Power Distribution</b>							
	Lighting and Power Panels - 100 A	Entire Building	11	EA	6	\$3,290	
	Lighting and Power Panels - 100 A	Entire Building	10	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	7	\$0	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	\$0	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	\$0	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	\$0	

### Electrical System Subtotal:

**\$32,864**

## Building: Addition 1

### Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Fire Alarm</b>							
	Fire Alarm Panel	Entire Building / 1st Floor	1	EA	6	\$6,406	Serves the entire school
	Fire Alarm Strobe Lights	Entire Building	33,906	SF	6	\$12,121	
	Fire Alarm_System	Entire Building	290,922	SF	6	\$141,446	Serves the entire school

### Safty System Subtotal:

**\$159,973**

## Building: Addition 1

### Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Air Conditioning</b>							
	Chiller-Water Cooled- Cetrifugal - 201-300 tons	Roof / Boiler Room	2	EA	7	\$0	Serves entire school
	Condensing Unit- Ground Mounted - Less than 5 tons	Site North	1	EA	7	\$0	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	\$3,334	
	Cooling Tower - Closed Cell	Roof	2	EA	7	\$0	Serves entire school
	Glycol Feed	Roof / Boiler Room	1	EA	7	\$0	

## Building: Addition 1

### Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Air Conditioning</b>							
	Pipes - Chilled Water Pipe- Steel	Roof / Entire Building	320	LF	7	\$0	
<b>Air Handling Systems</b>							
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 8001 - 15000 cfm	Entire Building	2	EA	5	\$100,007	
	Air Handling Unit- Built Up- Single Zone- Daul Temperature Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	6	\$5,788	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Daul Temperature Coils - Greater than 35000 cfm	Mechanical Room / 1st Floor	1	EA	7	\$0	
	Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils- - Less than 6000 cfm	3rd Floor	1	EA	7	\$0	Serves room 336 only. No other information available on unit.
	Air Handling Unit- Package Single Zone- Indoor- Electric and DX Cooling Coil - Less than 4000 cfm	Entire Building / 1st Floor	1	EA	7	\$0	Serves health care area (room 142 on plans). No other information available on unit.
	Air Intake	3rd Floor / Roof	1	EA	7	\$0	
	Air Intake	Entire Building / North Façade	1	EA	7	\$0	
	Air Intake	Entire Building / Roof	2	EA	6	\$11,529	Intakes for AHU-8 & AHU-10
	Air Intake	Mechanical Room / Roof	1	EA	7	\$0	
	Air Intake	Mechanical Room / Roof	1	EA	7	\$0	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	\$5,788	
	Auxiliaries - 8001 - 15000 cfm	Entire Building	2	EA	5	\$25,815	There is chipping paint on unit; Doors do not seal; Housing wall looks deteriorated
	Auxiliaries - Greater than 35000 cfm	Mechanical Room / 1st Floor	1	EA	7	\$0	
	Outdoor Return Fans- Air Handling Unit Type - Greater than 20000 CFM	Roof	1	EA	6	\$2,077	
	Reheat Boxes - Reheat Boxes with Hot Water Coil	Mechanical Room / Basement	8	EA	6	\$7,885	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Entire Building	100	LF	5	\$131,341	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Entire Building	100	LF	5	\$131,341	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Entire Building	100	LF	7	\$0	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Entire Building	100	LF	7	\$0	
	Zone Dampers	Entire Building	19	EA	7	\$0	New actuators
	Zone Dampers	Mechanical Room / Basement	36	EA	6	\$29,989	New actuators on units
<b>Boiler Systems</b>							
	Boiler Auxiliary- Condensing Hot Water - 3001 - 4000 HP	Boiler Room	5	EA	7	\$0	
	Chemical Pot Feeder	Boiler Room	1	EA	7	\$0	
	Condensing- Hot Water Boiler - 3001 - 4000 MBH	Boiler Room	5	EA	7	\$0	
	Dual Temperature Pump	Boiler Room	2	EA	7	\$0	Boilers serve entire school
	Glycol Feed System	Boiler Room	1	EA	7	\$0	
<b>Gas Booster</b>							
	Gas Booster	Site West / West Courtyard	1	EA	6	\$499	

## Building: Addition 1

### Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Gas Booster</b>							
<b>Heating Devices</b>							
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	\$1,417	
	Fin Tube - Hot Water	Entire Building	44	LF	6	\$415	
	Unit Heater - Hot Water	Entire Building	3	EA	7	\$0	
<b>Mechanical Plumbing</b>							
	Condenser Pump - 21 - 50 HP	Boiler Room	2	EA	7	\$0	
	Daul Temperature Pump - Less than 10	Entire Building	5	EA	7	\$0	< 5 HP
	Hydronic Supply and Return - Steel	Entire Building	600	LF	6	\$46,066	
<b>Temperature Control</b>							
	Thermostats - DDC	Entire Building	45	EA	7	\$0	DDC System located in main building
<b>Ventilation</b>							
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Roof / Entire Building	1	EA	6	\$592	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Roof / Entire Building	1	EA	6	\$592	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Roof / Entire Building	1	EA	7	\$0	
	Exhaust Fans- Indoor - Greater than 8000 CFM	Roof / Entire Building	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	6	EA	6	\$3,554	
	Roof Mounted Duct Work	Roof	328	LF	7	\$0	

### Mechanical System Subtotal:

**\$508,623**

## Building: Addition 1

### Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Hot Water</b>							
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	2	EA	7	\$0	Serves entire school
	Hot Water Storage Tank_Gas - 501 - 1000 Gallons	Boiler Room / 1st Floor	2	EA	7	\$0	Serves entire school
<b>Piping</b>							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	33,906	SF	7	\$0	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	33,906	SF	7	\$0	
	Domestic Piping-Cold Water Risers	Entire Building	33,906	SF	6	\$6,303	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	33,906	SF	7	\$0	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	33,906	SF	7	\$0	
	Domestic Piping-Hot Water Return Lines	Entire Building	33,906	SF	7	\$0	
	Domestic Piping-Hot Water Return Risers	Entire Building	33,906	SF	6	\$4,849	



## Building: Addition 1

### Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Piping</b>							
	Sanitary Piping	Entire Building	33,906	SF	6	\$31,031	
	Storm Piping	Entire Building	33,906	SF	6	\$29,576	
	Vent Piping	Entire Building	33,906	SF	6	\$22,788	
<b>Pumps</b>							
	Pumps - Domestic Booster Pump-Duplex	Entire Building / Mechanical Room	1	EA	7	\$0	
	Pumps - Sump-Duplex	Entire Building / Mechanical Room	2	EA	6	\$2,774	

### Plumbing System Subtotal:

**\$97,321**

## Building: Addition 1

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #146 (Store Room)</b>							
	Casework		9	LF	4	\$4,178	Casework is damaged
	Ceiling - Splined		596	SF	7	\$0	
	Chalk Board		12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Wood		596	SF	7	\$0	
	Lighting - Pendent/Surface		6	EA	7	\$0	
	Lighting - Pendent/Surface		3	EA	4	\$1,622	T-12
	Walls - Plaster/Drywall		1,218	SF	7	\$0	
<b>Classroom #149 (Store Room)</b>							
	Ceiling - Splined		1,180	SF	7	\$0	
	Chalk Board		11	LF	4	\$1,010	
	Doors - Transom Window		33	SF	7	\$0	
	Doors - Wood Doors inclu hw		3	EA	4	\$10,239	Very deteriorated door panels and hardware
	Floor - Concrete		1,180	SF	6	\$624	
	Lighting - Pendent/Surface		18	EA	7	\$0	
	Storage/ Closet		152	SF	5	\$2,452	
	Walls - Plaster/Drywall		60	SF	4	\$882	Wall damage in south west corner of room under windows
	Walls - Plaster/Drywall		1,718	SF	5	\$13,021	
	Work Sink		1	EA	4	\$8,619	Toilet room type fixture is non-functioning
<b>Classroom #186 ROTC (Special Program)</b>							
	Ceiling - Plaster/Drywall	1st Floor	497	SF	6	\$1,720	

## Building: Addition 1

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #186 ROTC (Special Program)</b>							
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Concrete Epoxy/ Painted	1st Floor	497	SF	6	\$263	Painted
	Lighting - Pendent/Surface	1st Floor	6	EA	7	\$0	
	Marker Board	1st Floor	5	LF	6	\$107	
	Walls - Masonry	1st Floor	1,193	SF	6	\$3,753	
	Walls - Plaster/Drywall	1st Floor	216	SF	7	\$0	
<b>Classroom #235 (Office)</b>							
	AC Units		1	EA	7	\$0	
	Ceiling - Lay-in		217	SF	7	\$0	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Doors - Wood Doors inclu hw		11	EA	7	\$0	
	Floor - Wood		217	SF	7	\$0	
	Lighting - Lay-in		4	EA	7	\$0	
	Storage/ Closet		7	SF	7	\$0	
	Walls - Plaster/Drywall		707	SF	5	\$5,358	
<b>Classroom #239 (Office)</b>							
	Ceiling - Plaster/Drywall		512	SF	5	\$4,693	
	Doors - Transom Window		44	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Floor - Tile/Sheet		512	SF	7	\$0	
	Lighting - Pendent/Surface		8	EA	7	\$0	
	Walls - Masonry		174	SF	7	\$0	Masonry is glazed brick.
	Walls - Plaster/Drywall		1,398	SF	7	\$0	
<b>Classroom #240 (Regular Classroom)</b>							
	Casework		9	LF	6	\$227	
	Ceiling - Lay-in		726	SF	7	\$0	
	Chalk Board		44	LF	4	\$4,039	
	Doors - Transom Window		22	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Wood		726	SF	7	\$0	
	Lighting - Lay-in		21	EA	7	\$0	
	Walls - Plaster/Drywall		1,090	SF	7	\$0	

## Building: Addition 1

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #241 (Regular Classroom)</b>							
	Casework		9	LF	6	\$227	
	Ceiling - Lay-in		726	SF	7	\$0	
	Chalk Board		44	LF	4	\$4,039	
	Doors - Transom Window		22	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		726	SF	7	\$0	
	Lighting - Lay-in		21	EA	7	\$0	
	Walls - Plaster/Drywall		1,090	SF	7	\$0	
<b>Classroom #242 (Regular Classroom)</b>							
	Casework		9	LF	6	\$227	
	Ceiling - Lay-in		671	SF	7	\$0	
	Chalk Board		33	LF	4	\$3,030	
	Doors - Transom Window		11	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Wood		671	SF	7	\$0	
	Lighting - Lay-in		19	EA	7	\$0	
	Walls - Plaster/Drywall		1,090	SF	6	\$3,008	
<b>Classroom #243 (Regular Classroom)</b>							
	Casework		9	LF	6	\$227	
	Ceiling - Lay-in		726	SF	6	\$2,180	
	Chalk Board		44	LF	4	\$4,039	
	Doors - Transom Window		22	SF	7	\$0	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Wood		726	SF	6	\$5,118	
	Lighting - Lay-in		21	EA	7	\$0	
	Walls - Plaster/Drywall		1,090	SF	6	\$3,008	
<b>Classroom #244 (Regular Classroom)</b>							
	Casework		9	LF	6	\$227	
	Ceiling - Lay-in		726	SF	6	\$2,180	
	Chalk Board		44	LF	4	\$4,039	
	Doors - Transom Window		22	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Wood		726	SF	7	\$0	
	Lighting - Lay-in		21	EA	7	\$0	

## Building: Addition 1

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #244 (Regular Classroom)</b>							
	Walls - Plaster/Drywall		1,090	SF	6	\$3,008	
<b>Classroom #245 (Special Program)</b>							
	Casework		18	LF	6	\$455	
	Ceiling - Lay-in		367	SF	7	\$0	
	Chalk Board		6	LF	4	\$551	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Wood		367	SF	7	\$0	
	Lighting - Lay-in		6	EA	7	\$0	
	Marker Board		6	LF	5	\$304	
	Walls - Plaster/Drywall		858	SF	5	\$6,503	
<b>Classroom #246 East (Special Program)</b>							
	Casework		11	LF	6	\$278	
	Ceiling - Lay-in		594	SF	7	\$0	
	Chalk Board		22	LF	4	\$2,020	
	Doors - Transom Window		11	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Wood		594	SF	7	\$0	
	Lighting - Lay-in		18	EA	7	\$0	
	Walls - Plaster/Drywall		1,028	SF	7	\$0	
<b>Classroom #246 West (Store Room)</b>							
	AC Units		2	EA	6	\$991	
	Ceiling - Lay-in		490	SF	6	\$1,471	
	Chalk Board		9	LF	4	\$826	
	Doors - Transom Window		11	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		490	SF	7	\$0	Floor has an outlet strip on it
	Lighting - Lay-in		12	EA	7	\$0	
	Walls - Plaster/Drywall		955	SF	6	\$2,636	
	Wireless System		1	EA	7	\$0	
<b>Classroom #247 (Regular Classroom)</b>							
	Casework		9	LF	6	\$227	
	Ceiling - Lay-in		726	SF	7	\$0	
	Chalk Board		44	LF	4	\$4,039	
	Doors - Transom Window		22	SF	7	\$0	

## Building: Addition 1

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #247 (Regular Classroom)</b>							
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Wood		726	SF	6	\$5,118	
	Lighting - Lay-in		21	EA	7	\$0	
	Walls - Plaster/Drywall		1,090	SF	7	\$0	
<b>Classroom #248 East (Regular Classroom)</b>							
	AC Units		1	EA	6	\$496	
	Casework		11	LF	6	\$278	
	Ceiling - Lay-in		658	SF	7	\$0	
	Chalk Board		19	LF	4	\$1,744	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		658	SF	6	\$4,639	
	Lighting - Lay-in		18	EA	7	\$0	
	Walls - Plaster/Drywall		1,147	SF	6	\$3,166	
<b>Classroom #248 West (Special Program)</b>							
	AC Units		1	EA	7	\$0	
	Ceiling - Lay-in		490	SF	7	\$0	
	Chalk Board		12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		490	SF	6	\$3,454	
	Lighting - Lay-in		12	EA	7	\$0	
	Walls - Plaster/Drywall		955	SF	7	\$0	
<b>Classroom #249 (Regular Classroom)</b>							
	Casework		9	LF	6	\$227	
	Ceiling - Lay-in		816	SF	7	\$0	
	Chalk Board		37	LF	4	\$3,397	
	Doors - Transom Window		11	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Wood		816	SF	6	\$5,753	
	Lighting - Lay-in		21	EA	6	\$2,498	One row of lights does not go on
	Walls - Plaster/Drywall		1,100	SF	6	\$3,036	
<b>Classroom #336 (Art Room)</b>							
	Casework		36	LF	6	\$909	
	Ceiling - Lay-in		1,630	SF	6	\$4,895	

## Building: Addition 1

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #336 (Art Room)</b>							
	Doors - Steel Doors incl hw		1	EA	7	\$0	
	Doors - Transom Window		11	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		1,630	SF	6	\$11,491	
	Lighting - Lay-in		36	EA	7	\$0	
	Marker Board		6	LF	7	\$0	
	Storage/ Closet		167	SF	7	\$0	
	Walls - Plaster/Drywall		1,554	SF	6	\$4,289	
	Work Sink		3	EA	6	\$1,137	
<b>Classroom #337 (Office)</b>							
	AC Units		1	EA	7	\$0	
	Ceiling - Lay-in		223	SF	6	\$670	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		223	SF	7	\$0	
	Lighting - Lay-in		4	EA	7	\$0	
	Walls - Plaster/Drywall		642	SF	7	\$0	
<b>Classroom #340 (Regular Classroom)</b>							
	AC Units		2	EA	7	\$0	
	Casework		28	LF	6	\$707	
	Ceiling - Lay-in		1,050	SF	7	\$0	
	Chalk Board		24	LF	4	\$2,203	Note that one wall has black cork board not chalkboard so it was not quantified
	Doors - Transom Window		11	SF	7	\$0	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Floor - Wood		1,050	SF	7	\$0	
	Lighting - Lay-in		29	EA	7	\$0	
	Marker Board		5	LF	6	\$107	
	Storage/ Closet		35	SF	7	\$0	No Access
	Walls - Plaster/Drywall		1,299	SF	6	\$3,585	
<b>Classroom #341 (Office)</b>							
	AC Units		1	EA	4	\$6,086	AC does not work properly, can not cool the room space.
	Ceiling - Plaster/Drywall		494	SF	6	\$1,710	
	Chalk Board		24	LF	4	\$2,203	
	Doors - Transom Window		44	SF	7	\$0	

## Building: Addition 1

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #341 (Office)</b>							
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Floor - Tile/Sheet		494	SF	7	\$0	
	Lighting - Pendent/Surface		8	EA	6	\$991	
	Walls - Masonry		174	SF	7	\$0	Masonry is glazed brick
	Walls - Plaster/Drywall		942	SF	6	\$2,600	
<b>Classroom #343 East (Computer Lab)</b>							
	Casework		9	LF	6	\$227	
	Ceiling - Lay-in		982	SF	7	\$0	
	Chalk Board		37	LF	4	\$3,397	
	Doors - Transom Window		22	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		982	SF	6	\$6,923	
	Lighting - Lay-in		15	EA	7	\$0	
	Marker Board		16	LF	7	\$0	
	Walls - Plaster/Drywall		1,178	SF	7	\$0	
<b>Classroom #343 West (Computer Lab)</b>							
	AC Units		2	EA	7	\$0	
	Casework		9	LF	7	\$0	
	Ceiling - Lay-in		508	SF	7	\$0	
	Chalk Board		8	LF	4	\$734	
	Doors - Transom Window		11	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Wood		508	SF	6	\$3,581	
	Lighting - Lay-in		12	EA	7	\$0	
	Marker Board		16	LF	7	\$0	
	Walls - Plaster/Drywall		882	SF	7	\$0	
	Wireless System		1	EA	7	\$0	
<b>Classroom #344 (Regular Classroom)</b>							
	Casework		33	LF	6	\$833	
	Ceiling - Lay-in		1,122	SF	7	\$0	
	Chalk Board		33	LF	4	\$3,030	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Wood		1,122	SF	6	\$7,910	
	Lighting - Lay-in		33	EA	7	\$0	

## Building: Addition 1

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #344 (Regular Classroom)</b>							
	Walls - Plaster/Drywall		1,295	SF	6	\$3,574	
	Work Sink		1	EA	6	\$379	
<b>Classroom #345 (Special Program)</b>							
	AC Units		1	EA	7	\$0	
	Casework		10	LF	7	\$0	
	Ceiling - Lay-in		367	SF	7	\$0	
	Chalk Board		24	LF	4	\$2,203	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Wood		367	SF	7	\$0	
	Lighting - Lay-in		6	EA	7	\$0	
	Walls - Plaster/Drywall		796	SF	6	\$2,197	
<b>Classroom #346 East (Regular Classroom)</b>							
	Casework		9	LF	5	\$1,882	
	Ceiling - Lay-in		718	SF	7	\$0	
	Chalk Board		22	LF	4	\$2,020	
	Doors - Transom Window		11	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Wood		718	SF	7	\$0	
	Lighting - Lay-in		15	EA	7	\$0	
	Walls - Plaster/Drywall		1,010	SF	6	\$2,787	
<b>Classroom #346 West (Store Room)</b>							
	Ceiling - Lay-in		470	SF	7	\$0	
	Chalk Board		24	LF	4	\$2,203	
	Doors - Transom Window		11	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Wood		470	SF	6	\$3,313	
	Lighting - Lay-in		9	EA	7	\$0	
	Walls - Plaster/Drywall		812	SF	7	\$0	
<b>Classroom #347 (Regular Classroom)</b>							
	Casework		9	LF	6	\$227	
	Ceiling - Lay-in		743	SF	7	\$0	
	Chalk Board		38	LF	4	\$3,489	
	Doors - Transom Window		22	SF	7	\$0	
	Doors - Wood Doors inclu hw		2	EA	5	\$2,348	
	Floor - Wood		743	SF	6	\$5,238	



## Building: Addition 1

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #347 (Regular Classroom)</b>							
	Lighting - Lay-in		18	EA	7	\$0	
	Walls - Plaster/Drywall		1,022	SF	7	\$0	
<b>Classroom #348 (Regular Classroom)</b>							
	Casework		11	LF	6	\$278	
	Ceiling - Lay-in		1,200	SF	7	\$0	
	Chalk Board		30	LF	4	\$2,754	
	Doors - Transom Window		22	SF	7	\$0	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Wood		1,200	SF	6	\$8,460	
	Lighting - Lay-in		33	EA	7	\$0	
	Walls - Plaster/Drywall		1,344	SF	7	\$0	
<b>Classroom #349 (Regular Classroom)</b>							
	Casework		9	LF	6	\$227	
	Ceiling - Lay-in		816	SF	7	\$0	
	Chalk Board		47	LF	4	\$4,315	
	Doors - Transom Window		11	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Wood		816	SF	6	\$5,753	
	Lighting - Lay-in		18	EA	7	\$0	
	Walls - Plaster/Drywall		1,100	SF	6	\$3,036	
<b>Classrooms Subtotal:</b>						<b>\$299,758</b>	

## Building: Addition 1

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Ceiling - Lay-in	144 Clinic Reception Room	148	SF	7	\$0	
	Doors - Wood Doors inclu hw	144 Clinic Reception Room	1	EA	7	\$0	
	Floor - Tile/Sheet	144 Clinic Reception Room	148	SF	7	\$0	
	Lighting - Lay-in	144 Clinic Reception Room	2	EA	7	\$0	
	Power Distribution	144 Clinic Reception Room	6	EA	7	\$0	
	Walls - Plaster/Drywall	144 Clinic Reception Room	573	SF	7	\$0	
	AC Unit	145 - Office	1	EA	6	\$496	
	Ceiling - Lay-in	145 - Office	683	SF	7	\$0	

## Building: Addition 1

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Doors - Transom Window	145 - Office	22	SF	7	\$0	
	Doors - Wood Doors inclu hw	145 - Office	4	EA	6	\$1,204	
	Floor - Wood	145 - Office	683	SF	7	\$0	
	Lighting - Lay-in	145 - Office	17	EA	7	\$0	
	Power Distribution	145 - Office	12	EA	7	\$0	
	Storage/ Closet	145 - Office	201	SF	7	\$0	
	Walls - Plaster/Drywall	145 - Office	1,572	SF	6	\$4,339	
	Ceiling - Lay-in	145A - Office	200	SF	7	\$0	
	Doors - Wood Doors inclu hw	145A - Office	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	145A - Office	1	EA	6	\$301	
	Floor - Wood	145A - Office	200	SF	7	\$0	
	Lighting - Lay-in	145A - Office	5	EA	7	\$0	
	Power Distribution	145A - Office	6	EA	7	\$0	
	Walls - Plaster/Drywall	145A - Office	575	SF	6	\$1,587	
	AC Unit	145B - Office	1	EA	7	\$0	
	Ceiling - Lay-in	145B - Office	216	SF	7	\$0	
	Doors - Wood Doors inclu hw	145B - Office	1	EA	7	\$0	
	Floor - Wood	145B - Office	216	SF	7	\$0	
	Lighting - Lay-in	145B - Office	6	EA	7	\$0	
	Power Distribution	145B - Office	8	EA	7	\$0	
	Walls - Plaster/Drywall	145B - Office	568	SF	7	\$0	
	Ceiling - Plaster/Drywall	145C - Office	117	SF	7	\$0	
	Doors - Transom Window	145C - Office	11	SF	7	\$0	
	Doors - Wood Doors inclu hw	145C - Office	1	EA	6	\$301	
	Floor - Wood	145C - Office	117	SF	7	\$0	
	Lighting - Pendent/Surface	145C - Office	1	EA	7	\$0	
	Power Distribution	145C - Office	4	EA	7	\$0	
	Walls - Plaster/Drywall	145C - Office	532	SF	7	\$0	
	Ceiling - Splined	148 Office	1,308	SF	7	\$0	Includes ceiling for offices 148A, 148B, 148C and 148D which have partial height walls
	Doors - Steel Doors incl hw	148 Office	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	148 Office	2	EA	6	\$602	
	Floor - Wood	148 Office	818	SF	7	\$0	
	Lighting - Pendent/Surface	148 Office	21	EA	7	\$0	Includes lighting for offices 148A, 148B, 148C and 148D which have partial height walls
	Power Distribution	148 Office	26	EA	7	\$0	
	Walls - Plaster/Drywall	148 Office	1,983	SF	7	\$0	
	Work Sink	148 Office	1	EA	7	\$0	

## Building: Addition 1

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Doors - Wood Doors inclu hw	148A Office	1	EA	7	\$0	
	Floor - Wood	148A Office	117	SF	7	\$0	
	Power Distribution	148A Office	6	EA	7	\$0	
	Walls - Plaster/Drywall	148A Office	346	SF	7	\$0	
	Doors - Wood Doors inclu hw	148B Office	1	EA	7	\$0	
	Floor - Wood	148B Office	185	SF	7	\$0	
	Power Distribution	148B Office	12	EA	7	\$0	
	Walls - Plaster/Drywall	148B Office	373	SF	7	\$0	
	Doors - Wood Doors inclu hw	148C Office	1	EA	7	\$0	
	Floor - Wood	148C Office	195	SF	6	\$1,375	
	Power Distribution	148C Office	16	EA	7	\$0	
	Storage/ Closet	148C Office	6	SF	7	\$0	
	Walls - Plaster/Drywall	148C Office	394	SF	7	\$0	
	Doors - Wood Doors inclu hw	148D - Office	1	EA	7	\$0	
	Floor - Wood	148D - Office	172	SF	7	\$0	
	Power Distribution	148D - Office	16	EA	7	\$0	
	Walls - Plaster/Drywall	148D - Office	357	SF	7	\$0	
	Ceiling - Exposed	186A ROTC Office	696	SF	5	\$1,911	Extensive peeling paint
	Doors - Steel Doors incl hw	186A ROTC Office	1	EA	6	\$301	
	Floor - Concrete Epoxy/ Painted	186A ROTC Office	696	SF	6	\$368	Floor is Asphalt
	Lighting - Pendent/Surface	186A ROTC Office	8	EA	7	\$0	
	Power Distribution	186A ROTC Office	12	EA	7	\$0	
	Storage/ Closet	186A ROTC Office	225	SF	6	\$1,631	Mezzanine
	Walls - Masonry	186A ROTC Office	1,716	SF	6	\$5,399	
	Ceiling - Exposed	193A Break Room in Boiler Room	216	SF	5	\$593	Extensive peeling paint
	Doors - Wood Doors inclu hw	193A Break Room in Boiler Room	1	EA	6	\$301	
	Floor - Tile/Sheet	193A Break Room in Boiler Room	216	SF	7	\$0	
	Lighting - Pendent/Surface	193A Break Room in Boiler Room	2	EA	7	\$0	
	Power Distribution	193A Break Room in Boiler Room	6	EA	7	\$0	
	Walls - Masonry	193A Break Room in Boiler Room	945	SF	6	\$2,973	
	Work Slnk	193A Break Room in Boiler Room	1	EA	7	\$0	
	AC Unit	195 - Engineers Office	1	EA	7	\$0	
	Ceiling - Plaster/Drywall	195 - Engineers Office	328	SF	6	\$1,135	
	Doors - Wood Doors inclu hw	195 - Engineers Office	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	195 - Engineers Office	328	SF	7	\$0	
	Lighting - Pendent/Surface	195 - Engineers Office	12	EA	7	\$0	
	Power Distribution	195 - Engineers Office	16	EA	7	\$0	

## Building: Addition 1

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Walls - Plaster/Drywall	195 - Engineers Office	638	SF	6	\$1,761	
	AC Unit	195A Engineer's Office	1	EA	5	\$1,826	
	Ceiling - Plaster/Drywall	195A Engineer's Office	194	SF	6	\$671	
	Doors - Wood Doors inclu hw	195A Engineer's Office	1	EA	7	\$0	
	Floor - Tile/Sheet	195A Engineer's Office	194	SF	7	\$0	
	Lighting - Pendant/Surface	195A Engineer's Office	6	EA	7	\$0	
	Power Distribution	195A Engineer's Office	8	EA	7	\$0	
	Walls - Plaster/Drywall	195A Engineer's Office	369	SF	6	\$1,018	
	AC Unit	1st Floor Office East (off 149)	1	EA	7	\$0	
	Ceiling - Lay-in	1st Floor Office East (off 149)	203	SF	6	\$610	
	Doors - Wood Doors inclu hw	1st Floor Office East (off 149)	1	EA	6	\$301	
	Floor - Wood	1st Floor Office East (off 149)	203	SF	7	\$0	
	Lighting - Lay-in	1st Floor Office East (off 149)	6	EA	6	\$714	One lens cover missing
	Power Distribution	1st Floor Office East (off 149)	10	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor Office East (off 149)	542	SF	7	\$0	
	AC Unit	238B IT Work Room	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	238B IT Work Room	684	SF	7	\$0	
	Doors - Wood Doors inclu hw	238B IT Work Room	2	EA	6	\$602	
	Floor - Tile/Sheet	238B IT Work Room	684	SF	5	\$3,071	
	Lighting - Pendant/Surface	238B IT Work Room	4	EA	7	\$0	
	Power Distribution	238B IT Work Room	34	EA	7	\$0	
	Storage/ Closet	238B IT Work Room	32	SF	7	\$0	
	Walls - Plaster/Drywall	238B IT Work Room	1,400	SF	7	\$0	
	Ceiling - Lay-in	Behavioral Health Office in Clinic	61	SF	7	\$0	
	Doors - Wood Doors inclu hw	Behavioral Health Office in Clinic	1	EA	7	\$0	
	Floor - Tile/Sheet	Behavioral Health Office in Clinic	61	SF	7	\$0	
	Lighting - Lay-in	Behavioral Health Office in Clinic	2	EA	7	\$0	
	Power Distribution	Behavioral Health Office in Clinic	4	EA	7	\$0	
	Walls - Plaster/Drywall	Behavioral Health Office in Clinic	320	SF	7	\$0	
	Ceiling - Plaster/Drywall	Copy Room	322	SF	6	\$1,114	
	Doors - Transom Window	Copy Room	18	SF	7	\$0	
	Doors - Wood Doors inclu hw	Copy Room	2	EA	6	\$602	
	Floor - Tile/Sheet	Copy Room	322	SF	6	\$322	
	Lighting - Pendant/Surface	Copy Room	2	EA	7	\$0	
	Power Distribution	Copy Room	8	EA	7	\$0	
	Walls - Plaster/Drywall	Copy Room	946	SF	6	\$2,611	
	Ceiling - Splined	Dental Clinic	458	SF	7	\$0	

## Building: Addition 1

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Doors - Wood Doors inclu hw	Dental Clinic	1	EA	7	\$0	
	Floor - Tile/Sheet	Dental Clinic	458	SF	7	\$0	
	Lighting - Pendent/Surface	Dental Clinic	9	EA	7	\$0	
	Power Distribution	Dental Clinic	20	EA	7	\$0	
	Walls - Plaster/Drywall	Dental Clinic	1,090	SF	7	\$0	
	Work Sink	Dental Clinic	4	EA	7	\$0	
	Ceiling - Plaster/Drywall	Exam Room 1 in Clinic	106	SF	7	\$0	
	Doors - Wood Doors inclu hw	Exam Room 1 in Clinic	1	EA	7	\$0	
	Floor - Tile/Sheet	Exam Room 1 in Clinic	106	SF	7	\$0	
	Lighting - Lay-in	Exam Room 1 in Clinic	2	EA	7	\$0	
	Power Distribution	Exam Room 1 in Clinic	6	EA	7	\$0	
	Walls - Plaster/Drywall	Exam Room 1 in Clinic	327	SF	7	\$0	
	Work Sink	Exam Room 1 in Clinic	1	EA	7	\$0	
	Ceiling - Lay-in	Exam Room 2 in Clinic	106	SF	7	\$0	
	Doors - Wood Doors inclu hw	Exam Room 2 in Clinic	1	EA	7	\$0	
	Floor - Tile/Sheet	Exam Room 2 in Clinic	106	SF	7	\$0	
	Lighting - Lay-in	Exam Room 2 in Clinic	2	EA	7	\$0	
	Power Distribution	Exam Room 2 in Clinic	6	EA	7	\$0	
	Walls - Plaster/Drywall	Exam Room 2 in Clinic	327	SF	7	\$0	
	Work Sink	Exam Room 2 in Clinic	1	EA	7	\$0	
	Ceiling - Lay-in	Laboratory in Clinic	125	SF	7	\$0	
	Doors - Wood Doors inclu hw	Laboratory in Clinic	2	EA	7	\$0	One is a pocket door
	Floor - Tile/Sheet	Laboratory in Clinic	125	SF	7	\$0	
	Lighting - Lay-in	Laboratory in Clinic	3	EA	7	\$0	
	Power Distribution	Laboratory in Clinic	8	EA	7	\$0	
	Walls - Plaster/Drywall	Laboratory in Clinic	505	SF	7	\$0	
	Work Sink	Laboratory in Clinic	1	EA	7	\$0	
	Ceiling - Lay-in	Staff Room in Clinic	74	SF	7	\$0	
	Doors - Wood Doors inclu hw	Staff Room in Clinic	1	EA	7	\$0	
	Floor - Tile/Sheet	Staff Room in Clinic	74	SF	7	\$0	
	Lighting - Lay-in	Staff Room in Clinic	2	EA	7	\$0	
	Power Distribution	Staff Room in Clinic	8	EA	7	\$0	
	Walls - Plaster/Drywall	Staff Room in Clinic	340	SF	7	\$0	
<b>MDF_IDF</b>							
	AC Unit	238A	2	EA	7	\$0	
	Doors - Steel Doors incl hw	238A	1	EA	7	\$0	
	Finishes	238A	155	SF	7	\$0	

## Building: Addition 1

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
MDF_IDF							
<b>Mechanical/ Service Rooms</b>							
	Boiler Room	1st Floor	3,834	SF	7	\$0	193 Boiler Room
	Loading Docks	1st Floor	242	SF	7	\$0	142 Dock
	Mechanical/ Service Rooms	1st Floor	3,175	SF	6	\$22,747	191 Shop
	Mechanical/ Service Rooms	1st Floor	2,073	SF	6	\$14,852	194 Pump Room
	Mechanical/ Service Rooms	1st Floor	102	SF	7	\$0	142A Elevator Machine Room
	Mechanical/ Service Rooms	1st Floor	559	SF	7	\$0	140 & 142B Electrical Rooms
	Storage Room	1st Floor	423	SF	7	\$0	194A Yard Storage
	Storage Room	1st Floor	343	SF	6	\$2,457	185
	Storage Room	1st Floor	2,307	SF	6	\$16,528	166 Book Storage (3 adjacent rooms); Ceiling has extensive peeling paint
	Janitor's Closet	2nd Floor	14	SF	6	\$100	
	Mechanical/ Service Rooms	2nd Floor	1,260	SF	6	\$9,027	Fan Room off Boiler Room catwalk
	Storage Room	2nd Floor	901	SF	6	\$6,455	238 Storage
	Storage Room	2nd Floor	166	SF	7	\$0	Storage Room off of corridor
	Janitor's Closet	3rd Floor	14	SF	6	\$100	
	Mechanical/ Service Rooms	3rd Floor	338	SF	6	\$2,422	336A Mechanical (access through room 336)
	Mechanical/ Service Rooms	3rd Floor	660	SF	6	\$4,728	Fan room off of Boiler Room catwalk
	Storage Room	3rd Floor	166	SF	7	\$0	Storage room off of corridor
	Air Tunnel	Basement	2,730	SF	5	\$36,345	No access since it's a confined space; area is an estimate based on Addition 2 tunnel; evidence of water infiltration & some standing water
	Storage Room	Storage in Clinic	64	SF	7	\$0	
<b>Restroom</b>							
	Accessories	1st Floor Unisex	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor Unisex	50	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor Unisex	1	EA	7	\$0	
	Floor Drain	1st Floor Unisex	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor Unisex	50	SF	7	\$0	
	Lavatory	1st Floor Unisex	1	EA	7	\$0	
	Lighting - Pendant/Surface	1st Floor Unisex	1	EA	7	\$0	
	Walls - Concrete Block	1st Floor Unisex	59	SF	7	\$0	
	Walls - Plaster/Drywall	1st Floor Unisex	233	SF	7	\$0	
	Water Closet	1st Floor Unisex	1	EA	7	\$0	
	Accessories	1st Floor	256	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	256	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	

## Building: Addition 1

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Floor Drain	1st Floor	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	1st Floor	256	SF	7	\$0	
	Hand Dryer	1st Floor	1	EA	7	\$0	
	Lavatory	1st Floor	2	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	\$0	
	Partitions	1st Floor	1	EA	7	\$0	
	Urinals	1st Floor	4	EA	7	\$0	
	Walls - Concrete Block	1st Floor	255	SF	7	\$0	
	Walls - Masonry	1st Floor	54	SF	7	\$0	Masonry is glazed brick
	Walls - Plaster/Drywall	1st Floor	415	SF	6	\$1,145	
	Water Closet	1st Floor	1	EA	7	\$0	
	Accessories	2nd Floor	256	SF	7	\$0	
	Ceiling - Plaster/Drywall	2nd Floor	256	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Floor Drain	2nd Floor	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	256	SF	7	\$0	
	Hand Dryer	2nd Floor	1	EA	7	\$0	
	Lavatory	2nd Floor	2	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	\$0	
	Partitions	2nd Floor	1	EA	7	\$0	
	Urinals	2nd Floor	4	EA	7	\$0	
	Walls - Concrete Block	2nd Floor	255	SF	7	\$0	
	Walls - Masonry	2nd Floor	54	SF	7	\$0	Masonry is glazed brick
	Walls - Plaster/Drywall	2nd Floor	415	SF	6	\$1,145	
	Water Closet	2nd Floor	1	EA	7	\$0	
	Accessories	3rd Floor	256	SF	7	\$0	
	Ceiling - Plaster/Drywall	3rd Floor	256	SF	7	\$0	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
	Floor Drain	3rd Floor	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	256	SF	7	\$0	
	Hand Dryer	3rd Floor	1	EA	7	\$0	
	Lavatory	3rd Floor	2	EA	7	\$0	
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	\$0	
	Partitions	3rd Floor	1	EA	7	\$0	
	Urinals	3rd Floor	4	EA	7	\$0	
	Walls - Concrete Block	3rd Floor	255	SF	7	\$0	
	Walls - Masonry	3rd Floor	54	SF	7	\$0	Masonry is glazed brick

## Building: Addition 1

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Walls - Plaster/Drywall	3rd Floor	415	SF	6	\$1,145	
	Water Closet	3rd Floor	1	EA	7	\$0	
	Accessories	Basement Unisex Toilet/Shower Room in Boiler Room (adjacent to auto shop)	320	SF	7	\$0	
	Ceiling - Exposed	Basement Unisex Toilet/Shower Room in Boiler Room (adjacent to auto shop)	320	SF	6	\$476	
	Doors - Wood Doors inclu hw	Basement Unisex Toilet/Shower Room in Boiler Room (adjacent to auto shop)	2	EA	6	\$602	
	Floor Drain	Basement Unisex Toilet/Shower Room in Boiler Room (adjacent to auto shop)	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Basement Unisex Toilet/Shower Room in Boiler Room (adjacent to auto shop)	320	SF	6	\$677	
	Lavatory	Basement Unisex Toilet/Shower Room in Boiler Room (adjacent to auto shop)	1	EA	6	\$320	
	Lighting - Pendant/Surface	Basement Unisex Toilet/Shower Room in Boiler Room (adjacent to auto shop)	2	EA	6	\$248	
	Showers	Basement Unisex Toilet/Shower Room in Boiler Room (adjacent to auto shop)	1	EA	6	\$311	
	Student Lockers - One Tier	Basement Unisex Toilet/Shower Room in Boiler Room (adjacent to auto shop)	6	EA	7	\$0	
	Urinals	Basement Unisex Toilet/Shower Room in Boiler Room (adjacent to auto shop)	1	EA	6	\$336	
	Walls - Masonry	Basement Unisex Toilet/Shower Room in Boiler Room (adjacent to auto shop)	1,345	SF	6	\$4,231	
	Walls - Plaster/Drywall	Basement Unisex Toilet/Shower Room in Boiler Room (adjacent to auto shop)	200	SF	6	\$552	
	Water Closet	Basement Unisex Toilet/Shower Room in Boiler Room (adjacent to auto shop)	1	EA	6	\$336	
	Accessories	Engineer's Toilet in 195A	48	SF	7	\$0	
	Accessories	Engineer's Toilet in 195	47	SF	7	\$0	
	Ceiling - Plaster/Drywall	Engineer's Toilet in 195A	48	SF	6	\$166	
	Doors - Wood Doors inclu hw	Engineer's Toilet in 195A	1	EA	6	\$301	
	Floor Drain	Engineer's Toilet in 195A	1	EA	6	\$1,059	
	Floor - Concrete Epoxy/ Painted	Engineer's Toilet in 195A	48	SF	6	\$25	
	Lavatory	Engineer's Toilet in 195A	1	EA	7	\$0	
	Lighting - Pendant/Surface	Engineer's Toilet in 195A	1	EA	7	\$0	CFL
	Lighting - Wall Mounted	Engineer's Toilet in 195A	1	EA	7	\$0	CFL
	Showers	Engineer's Toilet in 195A	1	EA	5	\$1,172	
	Walls - Plaster/Drywall	Engineer's Toilet in 195A	184	SF	6	\$508	
	Water Closet	Engineer's Toilet in 195A	1	EA	7	\$0	
	Ceiling - Plaster/Drywall	Engineer's Toilet in 195	47	SF	6	\$163	



## Building: Addition 1

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Doors - Wood Doors inclu hw	Engineer's Toilet in 195	1	EA	6	\$301	
	Floor Drain	Engineer's Toilet in 195	1	EA	5	\$2,094	
	Floor - Concrete Epoxy/ Painted	Engineer's Toilet in 195	47	SF	6	\$25	
	Lavatory	Engineer's Toilet in 195	1	EA	7	\$0	
	Lighting - Pendent/Surface	Engineer's Toilet in 195	1	EA	6	\$124	
	Showers	Engineer's Toilet in 195	1	EA	6	\$311	
	Walls - Plaster/Drywall	Engineer's Toilet in 195	181	SF	5	\$1,372	
	Water Closet	Engineer's Toilet in 195	1	EA	6	\$336	
	Accessories	Unisex Clinic Toilet	54	SF	7	\$0	
	Ceiling - Lay-in	Unisex Clinic Toilet	54	SF	7	\$0	
	Doors - Wood Doors inclu hw	Unisex Clinic Toilet	1	EA	7	\$0	
	Floor Drain	Unisex Clinic Toilet	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	Unisex Clinic Toilet	54	SF	7	\$0	
	Hand Dryer	Unisex Clinic Toilet	1	EA	7	\$0	
	Lavatory	Unisex Clinic Toilet	1	EA	7	\$0	
	Lighting - Lay-in	Unisex Clinic Toilet	2	EA	7	\$0	
	Walls - Plaster/Drywall	Unisex Clinic Toilet	148	SF	7	\$0	
	Walls - Tile Ceramic/ Porcelain	Unisex Clinic Toilet	148	SF	7	\$0	
	Water Closet	Unisex Clinic Toilet	1	EA	7	\$0	

**Rooms (Other Than Classrooms) Subtotal:**
**\$177,139**

## Building: Addition 1

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Ceiling - Lay-in	First Floor Corridors	5,633	SF	6	\$16,916	
	Drinking Fountains - Single Water Cooler	First Floor Corridors	2	EA	7	\$0	
	Floor - Terrazzo	First Floor Corridors	373	SF	6	\$3,702	
	Floor - Terrazzo	First Floor Corridors	2,130	SF	7	\$0	
	Floor - Tile/Sheet	First Floor Corridors	2,783	SF	7	\$0	
	Floor - Tile/Sheet	First Floor Corridors	347	SF	6	\$223	
	Lighting - Lay-in	First Floor Corridors	80	EA	7	\$0	
	Student Lockers - One Tier	First Floor Corridors	125	EA	7	\$0	
	Walls - Masonry	First Floor Corridors	2,023	SF	6	\$6,364	
	Walls - Plaster/Drywall	First Floor Corridors	6,349	SF	7	\$0	
	Ceiling - Plaster/Drywall	First Floor Vestibules	222	SF	6	\$1,635	

## Building: Addition 1

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Ceiling - Plaster/Drywall	First Floor Vestibules	282	SF	7	\$0	
	Doors - Wood Doors include hw	First Floor Vestibules	2	EA	6	\$602	
	Doors - Wood Doors include hw	First Floor Vestibules	1	EA	7	\$0	
	Floor - Terrazzo	First Floor Vestibules	172	SF	6	\$1,707	
	Floor - Terrazzo	First Floor Vestibules	332	SF	7	\$0	
	Lighting - Pendent/Surface	First Floor Vestibules	1	EA	7	\$0	
	Lighting - Pendent/Surface	First Floor Vestibules	7	EA	6	\$867	
	Walls - Masonry	First Floor Vestibules	643	SF	6	\$2,023	
	Walls - Plaster/Drywall	First Floor Vestibules	54	SF	6	\$336	
	Walls - Plaster/Drywall	First Floor Vestibules	916	SF	7	\$0	
	Ceiling - Lay-in	Health Clinic	148	SF	7	\$0	
	Doors - Wood Doors include hw	Health Clinic	2	EA	7	\$0	
	Floor - Tile/Sheet	Health Clinic	148	SF	7	\$0	
	Lighting - Lay-in	Health Clinic	3	EA	7	\$0	
	Walls - Plaster/Drywall	Health Clinic	650	SF	7	\$0	
	Doors - Steel Doors incl hw	Misc. Mech/Service Room Doors / 1st Floor	2	EA	7	\$0	
	Doors - Steel Doors incl hw	Misc. Mech/Service Room Doors / 1st Floor	18	EA	6	\$5,418	
	Doors - Wood Doors include hw	Misc. Mech/Service Room Doors / 1st Floor	6	EA	6	\$1,806	
	Doors - Wood Doors include hw	Misc. Mech/Service Room Doors / 1st Floor	2	EA	5	\$2,348	
	Doors - Steel Doors incl hw	Misc. Mech/Service Room Doors / 2nd Floor	2	EA	7	\$0	
	Doors - Wood Doors include hw	Misc. Mech/Service Room Doors / 2nd Floor	3	EA	6	\$903	
	Doors - Wood Doors include hw	Misc. Mech/Service Room Doors / 3rd Floor	1	EA	5	\$1,174	
	Doors - Wood Doors include hw	Misc. Mech/Service Room Doors / 3rd Floor	3	EA	6	\$903	
	Ceiling - Lay-in	Second Floor Corridors	439	SF	7	\$0	
	Ceiling - Lay-in	Second Floor Corridors	2,431	SF	6	\$7,300	
	Ceiling - Plaster/Drywall	Second Floor Corridors	26	SF	7	\$0	
	Drinking Fountains - Single Water Cooler	Second Floor Corridors	1	EA	5	\$3,007	
	Drinking Fountains - Single Water Cooler	Second Floor Corridors	1	EA	7	\$0	
	Floor - Terrazzo	Second Floor Corridors	334	SF	7	\$0	
	Floor - Tile/Sheet	Second Floor Corridors	2,532	SF	7	\$0	
	Floor - Tile/Sheet	Second Floor Corridors	50	SF	6	\$53	
	Lighting - Lay-in	Second Floor Corridors	36	EA	7	\$0	

## Building: Addition 1

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Lighting - Lay-in	Second Floor Corridors	1	EA	6	\$119	
	Student Lockers - One Tier	Second Floor Corridors	140	EA	7	\$0	
	Walls - Masonry	Second Floor Corridors	2,056	SF	6	\$6,468	
	Walls - Plaster/Drywall	Second Floor Corridors	2,166	SF	7	\$0	
	Ceiling - Lay-in	Third Floor Corridor	2,870	SF	6	\$8,619	
	Ceiling - Plaster/Drywall	Third Floor Corridor	26	SF	7	\$0	
	Drinking Fountains - Single Water Cooler	Third Floor Corridor	2	EA	7	\$0	
	Floor - Terrazzo	Third Floor Corridor	334	SF	7	\$0	
	Floor - Tile/Sheet	Third Floor Corridor	371	SF	6	\$239	
	Floor - Tile/Sheet	Third Floor Corridor	2,201	SF	7	\$0	
	Lighting - Lay-in	Third Floor Corridor	42	EA	7	\$0	
	Student Lockers - One Tier	Third Floor Corridor	147	EA	7	\$0	
	Walls - Masonry	Third Floor Corridor	2,056	SF	6	\$6,468	
	Walls - Plaster/Drywall	Third Floor Corridor	1,657	SF	7	\$0	
<b>Safety</b>							
	Camera Viewing Station	Office 145A	1	EA	7	\$0	Large monitor w/views of 16 cameras at a time
<b>Stairs</b>							
	Ceiling - Lay-in	Northeast Staircase	136	SF	6	\$408	
	Ceiling - Plaster/Drywall	Northeast Staircase	162	SF	7	\$0	
	Floor - Terrazzo	Northeast Staircase	260	SF	7	\$0	
	Handrails	Northeast Staircase	123	LF	6	\$1,066	
	Lighting - Lay-in	Northeast Staircase	2	EA	7	\$0	
	Lighting - Pendent/Surface	Northeast Staircase	4	EA	7	\$0	
	Stairs - Terrazzo	Northeast Staircase	352	LF	7	\$0	
	Walls - Masonry	Northeast Staircase	1,004	SF	6	\$3,159	
	Walls - Plaster/Drywall	Northeast Staircase	1,507	SF	7	\$0	
	Ceiling - Lay-in	Northwest Staircase	182	SF	7	\$0	
	Ceiling - Plaster/Drywall	Northwest Staircase	505	SF	7	\$0	
	Floor - Terrazzo	Northwest Staircase	418	SF	7	\$0	
	Handrails	Northwest Staircase	128	LF	6	\$1,109	
	Lighting - Lay-in	Northwest Staircase	7	EA	7	\$0	
	Lighting - Pendent/Surface	Northwest Staircase	6	EA	7	\$0	
	Stairs - Terrazzo	Northwest Staircase	499	LF	7	\$0	
	Walls - Masonry	Northwest Staircase	1,085	SF	6	\$3,413	
	Walls - Plaster/Drywall	Northwest Staircase	1,327	SF	7	\$0	
	Ceiling - Plaster/Drywall	Service Stair from rm 194 to rm 336	136	SF	5	\$1,999	Ceiling has extensive peeling paing

## Building: Addition 1

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Stairs</b>							
	Floor - Concrete	Service Stair from rm 194 to rm 336	10	SF	6	\$5	
	Floor - Exposed	Service Stair from rm 194 to rm 336	255	SF	6	\$135	Floor is diamond plate metal
	Handrails	Service Stair from rm 194 to rm 336	92	LF	6	\$797	
	Lighting - Pendant/Surface	Service Stair from rm 194 to rm 336	1	EA	5	\$183	
	Stairs - Asphalt	Service Stair from rm 194 to rm 336	193	LF	6	\$1,791	Stair is diamond plate metal
	Walls - Plaster/Drywall	Service Stair from rm 194 to rm 336	2,107	SF	5	\$9,612	Walls have extensive peeling paint

### Vertical Conveyance

	Elevator - Elevator- Roped Holeless Hydraulic		1	EA	7	\$0	
--	---	--	---	----	---	-----	--

### Building Interior Subtotal:

**\$102,878**

### Total Building Cost

**\$3,012,780**

## Building: Addition 2

### Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Entrance</b>							
	Exterior Doors - Exterior Steel Door	5	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	6	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	7	2	EA	5	\$2,683	loose glazing
	Exterior Doors - Exterior Steel Door	8	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	9	6	EA	5	\$8,048	
	Exterior Doors - Transom Lite	5	3	EA	6	\$940	
	Exterior Doors - Transom Lite	6	3	EA	6	\$940	
	Exterior Doors - Transom Lite	7	2	EA	6	\$627	
	Exterior Doors - Transom Lite	8	2	EA	6	\$627	
	Exterior Doors - Transom Lite	9	4	EA	6	\$1,253	
	Exterior Stairs - Stone	5	40	LF	5	\$10,847	chipped nosings, open and deteriorated mortar joint
	Exterior Stairs - Stone	6	14	LF	4	\$4,442	severely spalled
	Exterior Stairs - Stone	6	67	LF	5	\$18,168	chipped nosings, pockmarks, deteriorated mortar joints
	Exterior Stairs - Stone	7	8	LF	4	\$2,538	severe spall, holes from former railing
	Exterior Stairs - Stone	7	152	LF	5	\$41,218	deteriorated mortar joints, severely worn patterns
	Exterior Stairs - Stone	8	20	LF	5	\$5,423	chipped nosings, deteriorated mortar joints

## Building: Addition 2

### Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Foundation							
	Foundation - Concrete	Entire Building	822	LF	7	\$0	seepage and standing water present in east mechanical room and east and west tunnels
	Superstructure - Concrete	Entire Building	37,798	SF	7	\$0	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	9	EA	6	\$4,829	
	Exterior Lighting - Wall Mounted	Entire Building	13	EA	6	\$3,754	
Roof System							
	Coping - Metal	N	216	LF	6	\$6,937	
	Coping - Metal	O	87	LF	6	\$2,794	
	Coping - Metal	P	377	LF	6	\$12,108	
	Coping - Stone	M	47	LF	6	\$1,510	
	Coping - Terra Cotta	N	20	LF	6	\$642	
	Coping - Terra Cotta	P	88	LF	6	\$2,826	
	Downspouts - Exterior Downspouts	M	70	LF	6	\$2,326	
	Downspouts - Exterior Downspouts	N	96	LF	6	\$3,190	
	Downspouts - Exterior Downspouts	P	288	LF	6	\$9,571	
	Downspouts - Interior Downspouts	N	100	LF	6	\$3,323	
	Parapet - 16" - 30" Height	O	87	LF	6	\$3,476	
	Parapet - 16" - 30" Height	P	465	LF	6	\$18,579	
	Parapet - Parapet < 16" Height	M	60	LF	4	\$29,386	bulging, step cracking
	Parapet - Parapet < 16" Height	N	20	LF	6	\$426	
	Parapet - Parapet > 30"	M	47	LF	6	\$3,004	
	Parapet - Parapet > 30"	N	216	LF	6	\$13,807	
	Roof Structure - Steel with Clay Tile Arch	M	8,128	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	N	10,880	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	O	3,706	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	P	15,030	SF	7	\$0	
	Roof - Modified Bitumen	M	8,128	SF	5	\$170,975	ponding, general deterioration, cracking, bubbling
	Roof - Modified Bitumen	N	10,880	SF	5	\$228,864	ponding, general deterioration, cracking, bubbling
	Roof - Modified Bitumen	O	3,706	SF	5	\$77,957	ponding, general deterioration, cracking, bubbling
	Roof - Modified Bitumen	P	15,030	SF	5	\$316,161	ponding, general deterioration, cracking, bubbling
Walls							
	Cheek-Wall - Stone	Entire Building	95	SF	5	\$2,261	chipping, some spalling
	Cornice - Metal Projecting	Entire Building	852	LF	5	\$128,184	corrosion throughout
	Exterior Walls - Brick	Entire Building	411	SF	5	\$9,786	ivy throughout
	Exterior Walls - Brick	Entire Building	19,002	SF	6	\$127,712	

## Building: Addition 2

### Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Walls</b>							
	Exterior Walls - Brick	Entire Building / North West	50	SF	5	\$1,190	crack evident in gymnasium office
	Exterior Walls - Stone-Cut	Entire Building	3,759	SF	6	\$25,264	
	Exterior Walls - Stone-Cut	Entire Building	97	SF	5	\$1,709	ivy throughout
	Exterior Walls - Stone-Cut	Entire Building / Site West	20	SF	5	\$352	cracking
	Exterior Walls - Terra Cotta	Entire Building	8,212	SF	6	\$55,193	
	Exterior Walls - Terra Cotta	Entire Building	231	SF	5	\$3,601	ivy throughout
<b>Windows</b>							
	Guard - Guards perforated	Entire Building	181	SF	5	\$2,775	ivy throughout
	Guard - Guards perforated	Entire Building	5,016	SF	6	\$64,054	
	Lintels - Steel	Entire Building	1,249	LF	6	\$36,257	
	Windows - Sash Aluminum Double-pane	Entire Building	477	SF	5	\$25,695	ivy throughout
	Windows - Sash Aluminum Double-pane	Entire Building	13,194	SF	6	\$98,488	

### Building Exterior Subtotal:

**\$1,600,565**

## Building: Addition 2

### Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Emergency System</b>							
	Emergency A/C Power - Corridors and Stairs	Entire Building	11,294	SF	6	\$3,392	
	Emergency A/C Power - Gym	Entire Building	13,380	SF	6	\$4,975	
	Emergency A/C Power - Students Toilets	Entire Building	1,205	SF	6	\$448	
	Exit Signs - Corridors and Stairs	Entire Building	22	EA	6	\$3,294	
	Exit Signs - Gym	Entire Building	2	EA	2	\$1,157	Exit sign is greater than 20 yrs old and not working
	Exit Signs - Gym	Entire Building	5	EA	6	\$787	
<b>Power Distribution</b>							
	Lighting and Power Panels - 100 A	Entire Building	13	EA	6	\$3,888	
	Lighting and Power Panels - 100 A	Entire Building	4	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	\$0	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	\$0	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	4	\$29,047	Transformer in poor condition

### Electrical System Subtotal:

**\$46,988**

## Building: Addition 2



## Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Fire Alarm</b>							
	Fire Alarm Strobe Lights	Entire Building	37,798	SF	6	\$13,513	Served from panel in addition 1
<b>Safty System Subtotal:</b>						<b>\$13,513</b>	

## Building: Addition 2

### Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Air Handling Systems</b>							
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Daul Temperature Coils - Greater than 35000 cfm	Mechanical Room / 1st Floor	1	EA	7	\$0	
	Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	
	Auxiliaries - Greater than 35000 cfm	Mechanical Room / 1st Floor	1	EA	7	\$0	
	Outdoor Return Fans- Air Handling Unit Type - Greater than 20000 CFM	Roof	2	EA	6	\$4,154	
	Reheat Boxes - Reheat Boxes with Hot Water Coil	Mechanical Room / Basement	10	EA	6	\$9,856	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers	Mechanical Room / Roof	100	LF	7	\$0	
		Mechanical Room / Basement	39	EA	7	\$0	
<b>Heating Devices</b>							
	Cabinet Heaters - With Hot Water Coil	Entire Building	6	EA	6	\$2,126	
	Fin Tube - Hot Water	Entire Building	40	LF	6	\$378	
<b>Mechanical Plumbing</b>							
	Daul Temperature Pump - Less than 10	Entire Building	1	EA	7	\$0	HP not available on pump
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	\$30,711	
<b>Temperature Control</b>							
	Thermostats - DDC	Entire Building	39	EA	7	\$0	DDC System located in main building
<b>Ventilation</b>							
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	2	EA	6	\$1,185	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	2	EA	6	\$1,185	
	Lab Exhaust Hood	Entire Building	2	EA	6	\$2,495	
	Roof Mounted Duct Work	Entire Building / Roof	20	LF	7	\$0	
<b>Mechanical System Subtotal:</b>						<b>\$57,854</b>	

## Building: Addition 2

### Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-------	-------------	----------	----------	------	------	------	----------

## Building: Addition 2

### Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Piping</b>							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	37,798	SF	7	\$0	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	37,798	SF	7	\$0	
	Domestic Piping-Cold Water Risers	Entire Building	37,798	SF	6	\$7,027	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	37,798	SF	7	\$0	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	37,798	SF	7	\$0	
	Domestic Piping-Hot Water Return Lines	Entire Building	37,798	SF	7	\$0	
	Domestic Piping-Hot Water Return Risers	Entire Building	37,798	SF	6	\$5,405	
	Sanitary Piping	Entire Building	37,798	SF	6	\$34,593	
	Storm Piping	Entire Building	37,798	SF	6	\$32,971	
	Vent Piping	Entire Building	37,798	SF	6	\$25,404	
<b>Pumps</b>							
	Pumps - Sump-Duplex	Basement	1	EA	6	\$1,387	
<b>Plumbing System Subtotal:</b>						<b>\$106,787</b>	

## Building: Addition 2

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #100 (Science Lab Level 1)</b>							
	Casework	1st Floor	83	LF	7	\$0	
	Ceiling - Lay-in	1st Floor	1,314	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	\$0	
	Eye Wash Station	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	1,314	SF	7	\$0	
	Fume Hood	1st Floor	1	EA	7	\$0	
	Gas Line	1st Floor	8	EA	7	\$0	
	Lighting - Lay-in	1st Floor	36	EA	7	\$0	
	Marker Board	1st Floor	10	LF	7	\$0	
	Science Lab Shower	1st Floor	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,500	SF	7	\$0	
	Work Sink	1st Floor	8	EA	7	\$0	
<b>Classroom #101 (Regular Classroom)</b>							
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Lay-in	1st Floor	796	SF	7	\$0	
	Chalk Board	1st Floor	48	LF	4	\$4,407	
	Doors - Transom Window	1st Floor	11	SF	6	\$186	



## Building: Addition 2

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #101 (Regular Classroom)</b>							
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	796	SF	6	\$5,612	
	Lighting - Lay-in	1st Floor	21	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,065	SF	7	\$0	
<b>Classroom #103 (Regular Classroom)</b>							
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Lay-in	1st Floor	750	SF	7	\$0	
	Chalk Board	1st Floor	44	LF	4	\$4,039	
	Doors - Transom Window	1st Floor	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	5	\$2,348	
	Floor - Wood	1st Floor	750	SF	6	\$5,287	
	Lighting - Lay-in	1st Floor	21	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	964	SF	6	\$2,661	
<b>Classroom #105 (Science Lab Level 2)</b>							
	Casework	1st Floor	88	LF	7	\$0	
	Ceiling - Lay-in	1st Floor	1,124	SF	7	\$0	
	Doors - Transom Window	1st Floor	22	SF	6	\$372	
	Doors - Transom Window	1st Floor	11	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	5	\$1,174	
	Eye Wash Station	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	1,124	SF	6	\$1,125	
	Gas Line	1st Floor	8	EA	7	\$0	
	Lighting - Lay-in	1st Floor	18	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Science Lab Shower	1st Floor	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,174	SF	7	\$0	
	Work Sink	1st Floor	8	EA	7	\$0	
<b>Classroom #106 (Science Lab Level 2)</b>							
	Casework	1st Floor	90	LF	7	\$0	
	Ceiling - Lay-in	1st Floor	1,232	SF	7	\$0	
	Doors - Transom Window	1st Floor	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	5	\$1,174	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Eye Wash Station	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	1,232	SF	7	\$0	

## Building: Addition 2

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #106 (Science Lab Level 2)</b>							
	Gas Line	1st Floor	8	EA	7	\$0	
	Lighting - Lay-in	1st Floor	35	EA	7	\$0	
	Marker Board	1st Floor	10	LF	7	\$0	
	Science Lab Shower	1st Floor	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,387	SF	7	\$0	
	Work Sink	1st Floor	8	EA	7	\$0	
<b>Classroom #110 (Science Lab Level 2)</b>							
	AC Units	1st Floor	1	EA	5	\$1,826	
	Casework	1st Floor	90	LF	7	\$0	
	Ceiling - Lay-in	1st Floor	1,472	SF	7	\$0	
	Doors - Transom Window	1st Floor	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	\$0	
	Eye Wash Station	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	1,472	SF	7	\$0	
	Gas Line	1st Floor	8	EA	7	\$0	
	Lighting - Lay-in	1st Floor	21	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Science Lab Shower	1st Floor	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,434	SF	7	\$0	
	Work Sink	1st Floor	8	EA	7	\$0	
<b>Classroom #200 (Regular Classroom)</b>							
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	796	SF	7	\$0	
	Chalk Board	2nd Floor	40	LF	4	\$3,672	
	Doors - Transom Window	2nd Floor	11	SF	6	\$186	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	796	SF	6	\$5,612	
	Lighting - Lay-in	2nd Floor	22	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,237	SF	7	\$0	
<b>Classroom #201 (Regular Classroom)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	AC Units	2nd Floor	1	EA	5	\$1,826	
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	796	SF	7	\$0	
	Chalk Board	2nd Floor	38	LF	4	\$3,489	
	Doors - Transom Window	2nd Floor	11	SF	6	\$186	

## Building: Addition 2

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #201 (Regular Classroom)</b>							
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	796	SF	6	\$5,612	
	Lighting - Lay-in	2nd Floor	22	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	6	\$343	
	Walls - Plaster/Drywall	2nd Floor	1,237	SF	7	\$0	
<b>Classroom #202 (Regular Classroom)</b>							
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	726	SF	6	\$2,180	
	Chalk Board	2nd Floor	44	LF	4	\$4,039	
	Doors - Transom Window	2nd Floor	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	726	SF	6	\$5,118	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	\$3,008	
<b>Classroom #203 (Regular Classroom)</b>							
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	726	SF	7	\$0	
	Chalk Board	2nd Floor	36	LF	4	\$3,305	
	Doors - Transom Window	2nd Floor	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	\$903	
	Floor - Wood	2nd Floor	726	SF	6	\$5,118	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	7	\$0	
<b>Classroom #204 (Regular Classroom)</b>							
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	726	SF	7	\$0	
	Chalk Board	2nd Floor	44	LF	4	\$4,039	
	Doors - Transom Window	2nd Floor	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	726	SF	6	\$5,118	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	\$3,008	

## Building: Addition 2

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #205 (Other Instructional Use)</b>							
	Casework	2nd Floor	11	LF	6	\$278	
	Ceiling - Lay-in	2nd Floor	358	SF	7	\$0	
	Chalk Board	2nd Floor	5	LF	4	\$459	
	Doors - Transom Window	2nd Floor	11	SF	6	\$186	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	358	SF	6	\$2,524	
	Lighting - Lay-in	2nd Floor	6	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	832	SF	6	\$2,296	
<b>Classroom #206 (Regular Classroom)</b>							
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	726	SF	7	\$0	
	Chalk Board	2nd Floor	44	LF	4	\$4,039	
	Doors - Transom Window	2nd Floor	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	726	SF	6	\$5,118	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	\$3,008	
<b>Classroom #207 (Regular Classroom)</b>							
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	726	SF	7	\$0	
	Chalk Board	2nd Floor	44	LF	4	\$4,039	
	Doors - Transom Window	2nd Floor	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Floor - Wood	2nd Floor	726	SF	6	\$5,118	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	90	SF	5	\$459	
	Walls - Plaster/Drywall	2nd Floor	1,000	SF	6	\$2,760	
<b>Classroom #208 (Regular Classroom)</b>							
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	726	SF	7	\$0	
	Chalk Board	2nd Floor	44	LF	4	\$4,039	
	Doors - Transom Window	2nd Floor	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	726	SF	6	\$5,118	

## Building: Addition 2

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #208 (Regular Classroom)</b>							
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	\$3,008	
<b>Classroom #209 (Regular Classroom)</b>							
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	726	SF	6	\$2,180	
	Chalk Board	2nd Floor	44	LF	4	\$4,039	
	Doors - Transom Window	2nd Floor	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	726	SF	6	\$5,118	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Marker Board	2nd Floor	44	LF	5	\$2,230	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	\$3,008	
<b>Classroom #210 (Regular Classroom)</b>							
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	726	SF	7	\$0	
	Chalk Board	2nd Floor	44	LF	4	\$4,039	
	Doors - Transom Window	2nd Floor	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	726	SF	6	\$1,588	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	\$3,008	
<b>Classroom #213 (Special Education)</b>							
	AC Units	2nd Floor	1	EA	6	\$496	Intended Usage - Men's Restroom (not a pull down menu option)
	Ceiling - Plaster/Drywall	2nd Floor	510	SF	7	\$0	
	Chalk Board	2nd Floor	10	LF	4	\$918	
	Doors - Transom Window	2nd Floor	44	SF	6	\$745	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	\$0	
	Floor - Tile	2nd Floor	10	SF	5	\$58	
	Floor - Tile	2nd Floor	500	SF	6	\$1,094	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	\$0	
	Walls - Masonry	2nd Floor	190	SF	6	\$598	glazed
	Walls - Plaster/Drywall	2nd Floor	100	SF	5	\$511	

## Building: Addition 2

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #213 (Special Education)</b>							
	Walls - Plaster/Drywall	2nd Floor	1,050	SF	6	\$2,898	
<b>Classroom #217 (Other Instructional Use)</b>							
	Ceiling - Lay-in	2nd Floor	152	SF	7	\$0	
	Chalk Board	2nd Floor	4	LF	4	\$367	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Floor - Wood	2nd Floor	152	SF	6	\$1,072	
	Lighting - Lay-in	2nd Floor	4	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	100	SF	5	\$442	
	Walls - Plaster/Drywall	2nd Floor	477	SF	7	\$0	
<b>Classroom #300 (Regular Classroom)</b>							
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	3rd Floor	825	SF	6	\$2,477	
	Chalk Board	3rd Floor	51	LF	4	\$4,682	
	Doors - Transom Window	3rd Floor	11	SF	6	\$186	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	825	SF	6	\$5,816	
	Lighting - Lay-in	3rd Floor	22	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,114	SF	6	\$3,075	
<b>Classroom #301 (Regular Classroom)</b>							
	AC Units	3rd Floor	1	EA	7	\$0	
	AC Units	3rd Floor	1	EA	4	\$6,086	
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	3rd Floor	825	SF	7	\$0	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	\$92	
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	11	SF	6	\$186	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	\$1,174	
	Floor - Wood	3rd Floor	825	SF	6	\$5,816	
	Lighting - Lay-in	3rd Floor	22	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,000	SF	6	\$2,760	
	Walls - Plaster/Drywall	3rd Floor	114	SF	5	\$582	
<b>Classroom #302 (Science Lab Level 3)</b>							
	Casework	3rd Floor	25	LF	6	\$631	
	Casework	3rd Floor	9	LF	4	\$4,178	damaged/worn surfaces in need of replacement
	Ceiling - Lay-in	3rd Floor	778	SF	7	\$0	

## Building: Addition 2

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #302 (Science Lab Level 3)</b>							
	Ceiling - Lay-in	3rd Floor	8	SF	5	\$64	
	Chalk Board	3rd Floor	12	LF	4	\$1,102	
	Doors - Transom Window	3rd Floor	11	SF	6	\$186	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	786	SF	5	\$3,529	
	Gas Line	3rd Floor	1	EA	6	\$509	
	Lighting - Lay-in	3rd Floor	21	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	900	SF	6	\$2,484	
	Walls - Plaster/Drywall	3rd Floor	148	SF	5	\$654	
	Work Sink	3rd Floor	1	EA	4	\$8,619	damaged/worn surfaces in need of replacement
<b>Classroom #303 (Regular Classroom)</b>							
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	3rd Floor	750	SF	7	\$0	
	Chalk Board	3rd Floor	40	LF	4	\$3,672	
	Doors - Transom Window	3rd Floor	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	5	\$2,348	
	Floor - Wood	3rd Floor	750	SF	6	\$5,287	
	Lighting - Lay-in	3rd Floor	21	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	\$2,705	
<b>Classroom #305 (Other Instructional Use)</b>							
	Casework	3rd Floor	11	LF	6	\$278	
	Ceiling - Lay-in	3rd Floor	368	SF	7	\$0	
	Chalk Board	3rd Floor	10	LF	4	\$918	
	Doors - Transom Window	3rd Floor	11	SF	6	\$186	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	368	SF	6	\$2,594	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	6	LF	6	\$129	
	Walls - Plaster/Drywall	3rd Floor	755	SF	6	\$2,084	
<b>Classroom #306 (Science Lab Level 2)</b>							
	Casework	3rd Floor	85	LF	7	\$0	
	Casework	3rd Floor	7	LF	5	\$1,464	
	Ceiling - Lay-in	3rd Floor	28	SF	5	\$223	
	Ceiling - Lay-in	3rd Floor	1,200	SF	7	\$0	
	Doors - Transom Window	3rd Floor	22	SF	6	\$372	

## Building: Addition 2

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #306 (Science Lab Level 2)</b>							
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	\$1,174	
	Eye Wash Station	3rd Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	3rd Floor	1,228	SF	6	\$1,229	
	Gas Line	3rd Floor	8	EA	7	\$0	
	Lighting - Lay-in	3rd Floor	36	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	6	\$214	
	Walls - Plaster/Drywall	3rd Floor	70	SF	5	\$357	
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	6	\$3,312	
	Work Sink	3rd Floor	8	EA	6	\$3,032	
<b>Classroom #307 (Regular Classroom)</b>							
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	3rd Floor	750	SF	7	\$0	
	Chalk Board	3rd Floor	49	LF	4	\$4,498	
	Doors - Transom Window	3rd Floor	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	750	SF	6	\$5,287	
	Lighting - Lay-in	3rd Floor	21	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	800	SF	6	\$2,208	
	Walls - Plaster/Drywall	3rd Floor	180	SF	4	\$2,188	damaged plaster on north exterior wall. possibly vandalism
<b>Classroom #309 (Regular Classroom)</b>							
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	3rd Floor	750	SF	7	\$0	
	Chalk Board	3rd Floor	49	LF	4	\$4,498	
	Doors - Transom Window	3rd Floor	22	SF	6	\$372	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	\$1,174	
	Floor - Wood	3rd Floor	750	SF	6	\$5,287	
	Lighting - Lay-in	3rd Floor	21	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	\$2,705	
<b>Classroom #310 (Science Lab Level 2)</b>							
	Casework	3rd Floor	60	LF	6	\$1,515	
	Casework	3rd Floor	14	LF	5	\$2,927	
	Ceiling - Lay-in	3rd Floor	1,136	SF	6	\$3,411	
	Chalk Board	3rd Floor	12	LF	4	\$1,102	



## Building: Addition 2

### Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #310 (Science Lab Level 2)</b>							
	Doors - Transom Window	3rd Floor	11	SF	6	\$186	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	3rd Floor	1,136	SF	6	\$1,137	
	Gas Line	3rd Floor	4	EA	6	\$2,036	
	Lighting - Lay-in	3rd Floor	32	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	8	SF	5	\$41	
	Walls - Plaster/Drywall	3rd Floor	1,330	SF	6	\$3,671	
	Work Sink	3rd Floor	1	EA	6	\$379	
	Work Sink	3rd Floor	1	EA	5	\$1,508	
	Work Sink	3rd Floor	1	EA	4	\$8,619	sink finish deteriorated/damaged, unusable.
<b>Classroom #315 (Special Education)</b>							
	Ceiling - Plaster/Drywall	3rd Floor	290	SF	5	\$2,658	Intended Usage - Men's Restroom (not a pull down menu option)
	Ceiling - Plaster/Drywall	3rd Floor	200	SF	6	\$818	
	Chalk Board	3rd Floor	16	LF	4	\$1,469	
	Doors - Transom Window	3rd Floor	44	SF	6	\$745	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	\$0	
	Floor - Carpet	3rd Floor	490	SF	5	\$2,516	
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	\$0	
	Walls - Masonry	3rd Floor	190	SF	7	\$0	glazed
	Walls - Plaster/Drywall	3rd Floor	838	SF	6	\$2,313	
<b>Classroom #317 (Other Instructional Use)</b>							
	Ceiling - Lay-in	3rd Floor	148	SF	7	\$0	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
	Floor - Wood	3rd Floor	148	SF	6	\$1,043	
	Lighting - Lay-in	3rd Floor	3	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	496	SF	7	\$0	

### Classrooms Subtotal:

**\$333,074**

## Building: Addition 2

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	AC Unit	150 Coach's Office in Gym 1	1	EA	5	\$1,826	
	Ceiling - Plaster/Drywall	150 Coach's Office in Gym 1	292	SF	5	\$2,677	

## Building: Addition 2

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Doors - Wood Doors inclu hw	150 Coach's Office in Gym 1	2	EA	5	\$2,348	
	Floor - Tile/Sheet	150 Coach's Office in Gym 1	292	SF	4	\$2,823	floor is worn, brittle, cracked and in need of replacement, including sub-floor.
	Lighting - Pendant/Surface	150 Coach's Office in Gym 1	4	EA	6	\$496	
	Power Distribution	150 Coach's Office in Gym 1	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	150 Coach's Office in Gym 1	520	SF	6	\$1,435	
<b>Gymnasias</b>							
	Ceiling - Plaster/Drywall	151 Gym	3,350	SF	7	\$0	
	Doors - Wood Doors inclu hw	151 Gym	2	EA	5	\$2,348	
	Doors - Wood Doors inclu hw	151 Gym	3	EA	6	\$903	
	Doors - Wood Doors inclu hw	151 Gym	4	EA	7	\$0	
	Floor - Wood	151 Gym	3,350	SF	6	\$23,617	
	Lighting - Metal Halide/Sodium Vapor	151 Gym	12	EA	7	\$0	
	Walls - Masonry	151 Gym	1,680	SF	6	\$5,285	glazed
	Walls - Plaster/Drywall	151 Gym	3,670	SF	7	\$0	
	Bleacher Seating	Gymnasium 1	190	EA	6	\$5,499	
	Ceiling - Plaster/Drywall	Gymnasium 1	9,700	SF	7	\$0	
	Doors - Steel Doors incl hw	Gymnasium 1	1	EA	6	\$301	steel vault door with combination to under bleacher storage room was non-accessible
	Doors - Wood Doors inclu hw	Gymnasium 1	2	EA	4	\$6,826	under bleacher storage doors
	Doors - Wood Doors inclu hw	Gymnasium 1	4	EA	7	\$0	
	Floor - Epoxy/ Painted	Gymnasium 1	2,200	SF	6	\$1,164	@ balcony
	Floor - Tile Ceramic/ Porcelain	Gymnasium 1	100	SF	4	\$2,797	tile at boys locker room entrance is missing a large section and broken in other areas.
	Floor - Wood	Gymnasium 1	7,400	SF	7	\$0	
	Lighting - Metal Halide/Sodium Vapor	Gymnasium 1	33	EA	7	\$0	
	Lighting - Metal Halide/Sodium Vapor	Gymnasium 1	1	EA	5	\$227	bldg engineer stated 1 flickers
	Scoreboards	Gymnasium 1	1	EA	5	\$10,580	per bldg engineer. if can't be fixed, should be replaced.
	Sound System	Gymnasium 1	1	EA	7	\$0	per bldg engineer
	Stage-Stairs - Terrazzo	Gymnasium 1	85	LF	6	\$650	NW balcony stair
	Stage-Stairs - Terrazzo	Gymnasium 1	32	LF	6	\$245	NE balcony stair
	Stage-Stairs - Terrazzo	Gymnasium 1	68	LF	6	\$520	SW balcony stair
	Storage/ Closet	Gymnasium 1	120	SF	4	\$3,344	non-accessible due to combination steel vault door. area estimated from plan.
	Storage/ Closet	Gymnasium 1	340	SF	5	\$5,484	151A storage below bleachers. shared with gym 151.
	Walls - Masonry	Gymnasium 1	8,400	SF	6	\$26,426	glazed

## Building: Addition 2

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Locker/Shower Room</b>							
	Accessories	1st Floor	98	SF	6	\$384	
	Accessories	1st Floor	100	SF	6	\$392	
	Benches, ped mounted	1st Floor	96	LF	5	\$26,376	
	Benches, ped mounted	1st Floor	13	LF	5	\$3,572	not secured to floor - tipping hazard
	Ceiling - Exposed	1st Floor	20	SF	5	\$78	toilet room skylight - broken glazing
	Ceiling - Exposed	1st Floor	250	SF	4	\$1,140	locker room skylight broken glazing + damaged framing. should either be removed or repaired.
	Ceiling - Exposed	1st Floor	400	SF	4	\$1,825	skylight: broken glass, damaged wood framing and in need of removal or replacement.
	Ceiling - Plaster/ Drywall	1st Floor	2,123	SF	5	\$20,280	
	Ceiling - Plaster/ Drywall	1st Floor	100	SF	6	\$479	
	Ceiling - Plaster/ Drywall	1st Floor	644	SF	7	\$0	
	Ceiling - Plaster/ Drywall	1st Floor	500	SF	4	\$8,787	substantial water damage to plaster ceilings.
	Ceiling - Plaster/ Drywall	1st Floor	840	SF	6	\$2,907	
	Ceiling - Plaster/ Drywall	1st Floor	98	SF	7	\$0	
	Doors - Transom Window	1st Floor	22	SF	7	\$0	
	Doors - Transom Window	1st Floor	11	SF	6	\$186	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	5	\$4,696	storage room doors
	Doors - Wood Doors inclu hw	1st Floor	1	EA	4	\$3,413	exit door to gymnasium is padlocked, exit signage is missing.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	4	\$3,413	no exit signage at only door used for exiting. exits through gymnasium and not directly to corridor.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	5	\$1,174	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	storage room door
	Doors - Wood Doors inclu hw	1st Floor	2	EA	4	\$6,826	one full and one 3/4 leaf door. Full door only opens 70 degrees (hits floor) and is currently the sole exit for the locker room due to other padlocked doors. exit signage is missing. exits into gymnasium and not directly to corridor.
	Doors - Wood Doors inclu hw	1st Floor	2	EA	4	\$6,826	pair of exit doors to corridor are locked, exit signage is missing, corridor outside doors is used as storage blocking exiting.
	Doors - Wood Doors inclu hw	1st Floor	2	EA	4	\$6,826	pair of exit doors to corridor are padlocked, exit signage is missing, corridor outside doors is used as storage blocking exiting.
	Floor Drain	1st Floor	2	EA	5	\$4,188	
	Floor Drain	1st Floor	7	EA	6	\$7,414	
	Floor Drain	1st Floor	1	EA	5	\$2,094	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor - Concrete	1st Floor	172	SF	6	\$91	

## Building: Addition 2

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Locker/Shower Room</b>							
	Floor - Tile Ceramic/ Porcelain	1st Floor	98	SF	7	\$0	toilet area
	Floor - Tile Ceramic/ Porcelain	1st Floor	744	SF	6	\$2,075	
	Floor - Tile Ceramic/ Porcelain	1st Floor	1,448	SF	6	\$3,065	
	Floor - Tile Ceramic/ Porcelain	1st Floor	2,523	SF	5	\$40,300	
	Hand Dryer	1st Floor	1	EA	7	\$0	
	Lavatory	1st Floor	1	EA	5	\$3,763	non-operable
	Lavatory	1st Floor	1	EA	6	\$320	
	Lavatory	1st Floor	1	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	25	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	66	EA	7	\$0	
	Partitions	1st Floor	2	EA	7	\$0	
	Partitions	1st Floor	1	EA	6	\$297	
	Showers	1st Floor	13	EA	6	\$4,048	
	Showers	1st Floor	1	EA	4	\$4,720	shower head missing @ ADA shower
	Storage/ Closet	1st Floor	70	SF	6	\$508	154B
	Storage/ Closet	1st Floor	275	SF	6	\$1,994	151A
	Storage/ Closet	1st Floor	80	SF	6	\$580	151B
	Student Lockers - One Tier	1st Floor	193	EA	6	\$17,917	
	Student Lockers - Two Tier	1st Floor	114	EA	6	\$5,292	
	Student Lockers - Two Tier	1st Floor	638	EA	4	\$167,341	damaged, dented, bent, rusted, poorly repainted and much older than the men's lockers. In need of replacement.
	Urinals	1st Floor	1	EA	7	\$0	
	Walls - Concrete Block	1st Floor	3,000	SF	6	\$8,795	
	Walls - Masonry	1st Floor	1,750	SF	6	\$5,506	glazed
	Walls - Masonry	1st Floor	1,730	SF	6	\$5,443	glazed
	Walls - Masonry	1st Floor	40	SF	4	\$3,996	glazed. missing/damaged masonry.
	Walls - Plaster/Drywall	1st Floor	660	SF	6	\$1,822	
	Walls - Plaster/Drywall	1st Floor	220	SF	4	\$2,674	water damage at low area of walls in pep room and behind toilets in restroom area
	Walls - Plaster/Drywall	1st Floor	100	SF	5	\$442	
	Walls - Plaster/Drywall	1st Floor	450	SF	4	\$4,530	columns damaged due to vandalism. replace with more durable material.
	Water Closet	1st Floor	2	EA	7	\$0	
	Water Closet	1st Floor	1	EA	7	\$0	
<b>Mechanical/ Service Rooms</b>							
	Interior Stairs	1st Floor	50	LF	6	\$451	steel stair - access to east tunnel
	Interior Stairs	1st Floor	50	LF	6	\$451	concrete stair - access to west tunnel

## Building: Addition 2

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Mechanical/ Service Rooms</b>							
	Janitor's Closet	1st Floor	90	SF	4	\$2,508	adjacent to Gym 1 - access to tunnel. water damage to walls.
	Janitor's Closet	1st Floor	50	SF	5	\$807	1E-J.
	Mechanical/ Service Rooms	1st Floor	60	SF	6	\$430	electrical (across from 110)
	Mechanical/ Service Rooms	1st Floor	712	SF	5	\$11,485	fan room + access stair to SW tunnel (across from 110)
	Mechanical/ Service Rooms	1st Floor	950	SF	6	\$6,806	fan room (accessible from SW tunnel). located between women's locker room + men's locker room
	Storage Room	1st Floor	18	SF	6	\$129	2 closets off corridor
	Janitor's Closet	2nd Floor	25	SF	5	\$403	2C-J
	Mechanical/ Service Rooms	2nd Floor	150	SF	7	\$0	Electrical.
	Interior Stairs	3rd Floor	33	LF	6	\$298	steel access stair to roof from 3C-J
	Janitor's Closet	3rd Floor	62	SF	6	\$444	3C-J. access stair to roof.
	Storage Room	3rd Floor	390	SF	6	\$2,794	Crawl space storage where greenhouse used to be.
	Storage Room	3rd Floor	56	SF	6	\$401	3rd floor abandoned boiler room for old removed greenhouse.
	Storage Room	3rd Floor	178	SF	6	\$1,275	4 storage rooms off the corridor
	Air Tunnel	Basement	1,300	SF	5	\$17,307	west side - 12'-0" wide, but length not determined due to inaccessibility (low ductwork) and no plans. Area is an estimate. Evidence of water infiltration with wet concrete at stair area.
	Air Tunnel	Basement	2,730	SF	5	\$36,345	east side. Evidence of water infiltration with some standing water.
	Mechanical/ Service Rooms	Basement	350	SF	4	\$9,755	room with access stair to tunnel. Evidence of water infiltration with substantial standing water in entire room.
<b>Prep Room</b>							
	Casework	in Science Lab 100	40	LF	7	\$0	
	Ceiling - Plaster/Drywall	in Science Lab 100	230	SF	7	\$0	
	Doors - Wood Doors inclu hw	in Science Lab 100	1	EA	7	\$0	
	Floor - Tile/Sheet	in Science Lab 100	230	SF	7	\$0	
	Lighting - Pendent/Surface	in Science Lab 100	3	EA	7	\$0	
	Walls - Plaster/Drywall	in Science Lab 100	637	SF	7	\$0	
	Work Sink	in Science Lab 100	1	EA	6	\$379	
	Casework	in Science Lab 105	30	LF	7	\$0	
	Ceiling - Plaster/Drywall	in Science Lab 105	326	SF	7	\$0	
	Doors - Transom Window	in Science Lab 105	11	SF	6	\$186	
	Doors - Transom Window	in Science Lab 105	11	SF	7	\$0	
	Doors - Wood Doors inclu hw	in Science Lab 105	2	EA	7	\$0	

## Building: Addition 2

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Prep Room</b>							
	Floor - Tile/Sheet	in Science Lab 105	326	SF	7	\$0	
	Lighting - Pendent/Surface	in Science Lab 105	3	EA	7	\$0	
	Walls - Plaster/Drywall	in Science Lab 105	693	SF	7	\$0	
	Work Sink	in Science Lab 105	1	EA	7	\$0	
	Casework	in Science Lab 106	49	LF	7	\$0	
	Ceiling - Plaster/Drywall	in Science Lab 106	230	SF	7	\$0	
	Doors - Wood Doors inclu hw	in Science Lab 106	1	EA	5	\$1,174	
	Floor - Tile/Sheet	in Science Lab 106	230	SF	7	\$0	
	Lighting - Pendent/Surface	in Science Lab 106	3	EA	7	\$0	
	Walls - Plaster/Drywall	in Science Lab 106	566	SF	7	\$0	
	Work Sink	in Science Lab 106	1	EA	6	\$379	
	Casework	in Science Lab 306	40	LF	7	\$0	
	Ceiling - Plaster/Drywall	in Science Lab 306	230	SF	7	\$0	
	Doors - Side-lite	in Science Lab 306	20	SF	7	\$0	
	Doors - Wood Doors inclu hw	in Science Lab 306	1	EA	6	\$301	
	Floor - Tile/Sheet	in Science Lab 306	230	SF	6	\$230	
	Lighting - Pendent/Surface	in Science Lab 306	4	EA	6	\$496	
	Walls - Plaster/Drywall	in Science Lab 306	637	SF	7	\$0	
	Work Sink	in Science Lab 306	1	EA	6	\$379	
	Casework	in Science Lab 310 (east)	48	LF	7	\$0	
	Ceiling - Plaster/Drywall	in Science Lab 310 (east)	230	SF	6	\$796	
	Doors - Side-lite	in Science Lab 310 (east)	12	SF	6	\$201	
	Doors - Wood Doors inclu hw	in Science Lab 310 (east)	1	EA	6	\$301	
	Floor - Tile/Sheet	in Science Lab 310 (east)	230	SF	6	\$230	
	Lighting - Pendent/Surface	in Science Lab 310 (east)	2	EA	7	\$0	
	Lighting - Pendent/Surface	in Science Lab 310 (east)	2	EA	6	\$248	Missing lenses
	Walls - Plaster/Drywall	in Science Lab 310 (east)	543	SF	6	\$1,499	
	Work Sink	in Science Lab 310 (east)	1	EA	6	\$379	
	Casework	in Science Lab 310 (west)	21	LF	6	\$530	
	Ceiling - Plaster/Drywall	in Science Lab 310 (west)	130	SF	6	\$450	
	Doors - Wood Doors inclu hw	in Science Lab 310 (west)	1	EA	6	\$301	
	Floor - Tile/Sheet	in Science Lab 310 (west)	130	SF	6	\$130	
	Lighting - Pendent/Surface	in Science Lab 310 (west)	3	EA	7	\$0	
	Walls - Plaster/Drywall	in Science Lab 310 (west)	608	SF	6	\$1,678	
	Work Sink	in Science Lab 310 (west)	1	EA	4	\$8,619	non-operational. replace faucet.

## Building: Addition 2

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Accessories	150A Unisex Locker/Toilet Room in Coach's Office of Gym 1	128	SF	6	\$1,181	
	Ceiling - Plaster/Drywall	150A Unisex Locker/Toilet Room in Coach's Office of Gym 1	128	SF	6	\$443	
	Doors - Wood Doors inclu hw	150A Unisex Locker/Toilet Room in Coach's Office of Gym 1	3	EA	5	\$3,522	
	Floor - Tile Ceramic/ Porcelain	150A Unisex Locker/Toilet Room in Coach's Office of Gym 1	28	SF	6	\$59	
	Floor - Tile/Sheet	150A Unisex Locker/Toilet Room in Coach's Office of Gym 1	100	SF	4	\$967	damaged, brittle, cracked and in need of full replacement (subfloor as well)
	Lavatory	150A Unisex Locker/Toilet Room in Coach's Office of Gym 1	1	EA	6	\$320	
	Lighting - Pendant/Surface	150A Unisex Locker/Toilet Room in Coach's Office of Gym 1	2	EA	7	\$0	
	Lighting - Wall Mounted	150A Unisex Locker/Toilet Room in Coach's Office of Gym 1	1	EA	5	\$169	non-operable
	Student Lockers - One Tier	150A Unisex Locker/Toilet Room in Coach's Office of Gym 1	7	EA	5	\$981	
	Walls - Concrete Block	150A Unisex Locker/Toilet Room in Coach's Office of Gym 1	70	SF	4	\$2,510	large crack in exterior concrete wall.
	Walls - Plaster/Drywall	150A Unisex Locker/Toilet Room in Coach's Office of Gym 1	350	SF	6	\$966	
	Walls - Plaster/Drywall	150A Unisex Locker/Toilet Room in Coach's Office of Gym 1	100	SF	4	\$1,216	substantial water damage to toilet room walls
	Water Closet	150A Unisex Locker/Toilet Room in Coach's Office of Gym 1	1	EA	6	\$336	
	Accessories	1st Floor	325	SF	6	\$2,998	
	Accessories	1st Floor	182	SF	6	\$1,679	
	Ceiling - Exposed	1st Floor	40	SF	6	\$59	skylight
	Ceiling - Plaster/Drywall	1st Floor	142	SF	6	\$491	
	Ceiling - Plaster/Drywall	1st Floor	325	SF	6	\$1,125	
	Doors - Side-lite	1st Floor	16	SF	7	\$0	
	Doors - Side-lite	1st Floor	16	SF	5	\$1,120	
	Doors - Transom Window	1st Floor	44	SF	6	\$745	
	Doors - Transom Window	1st Floor	11	SF	6	\$186	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	5	\$1,174	
	Floor Drain	1st Floor	1	EA	5	\$2,094	
	Floor Drain	1st Floor	1	EA	4	\$3,354	broken
	Floor - Tile Ceramic/ Porcelain	1st Floor	325	SF	6	\$688	
	Floor - Tile Ceramic/ Porcelain	1st Floor	182	SF	6	\$385	

## Building: Addition 2

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Hand Dryer	1st Floor	1	EA	7	\$0	
	Lavatory	1st Floor	1	EA	7	\$0	
	Lavatory	1st Floor	1	EA	6	\$320	
	Lavatory	1st Floor	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st Floor	4	EA	6	\$496	
	Lighting - Pendent/Surface	1st Floor	4	EA	6	\$496	
	Partitions	1st Floor	5	EA	7	\$0	
	Partitions	1st Floor	2	EA	6	\$594	
	Urinals	1st Floor	4	EA	5	\$5,376	continually flushing
	Walls - Concrete Block	1st Floor	260	SF	6	\$762	
	Walls - Concrete Block	1st Floor	150	SF	7	\$0	
	Walls - Masonry	1st Floor	60	SF	6	\$189	glazed
	Walls - Plaster/Drywall	1st Floor	200	SF	6	\$552	
	Walls - Plaster/Drywall	1st Floor	56	SF	5	\$247	water damage
	Walls - Plaster/Drywall	1st Floor	430	SF	6	\$1,187	
	Water Closet	1st Floor	2	EA	7	\$0	
	Water Closet	1st Floor	3	EA	6	\$1,008	
	Water Closet	1st Floor	2	EA	6	\$672	
	Accessories	2nd Floor	244	SF	6	\$2,251	
	Ceiling - Plaster/Drywall	2nd Floor	244	SF	6	\$844	
	Doors - Side-lite	2nd Floor	16	SF	7	\$0	
	Doors - Side-lite	2nd Floor	16	SF	5	\$1,120	
	Doors - Transom Window	2nd Floor	44	SF	6	\$745	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Floor Drain	2nd Floor	1	EA	4	\$3,354	broken and appears clogged
	Floor - Tile Ceramic/ Porcelain	2nd Floor	244	SF	6	\$516	
	Hand Dryer	2nd Floor	1	EA	7	\$0	
	Lavatory	2nd Floor	1	EA	7	\$0	
	Lavatory	2nd Floor	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd Floor	4	EA	6	\$496	
	Partitions	2nd Floor	1	EA	5	\$751	
	Partitions	2nd Floor	5	EA	7	\$0	
	Walls - Concrete Block	2nd Floor	300	SF	6	\$879	
	Walls - Masonry	2nd Floor	60	SF	6	\$189	glazed
	Walls - Plaster/Drywall	2nd Floor	280	SF	6	\$773	
	Water Closet	2nd Floor	4	EA	7	\$0	
	Water Closet	2nd Floor	2	EA	6	\$672	



## Building: Addition 2

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Accessories	3rd Floor	244	SF	6	\$2,251	
	Ceiling - Plaster/Drywall	3rd Floor	244	SF	7	\$0	
	Doors - Side-lite	3rd Floor	16	SF	7	\$0	
	Doors - Side-lite	3rd Floor	16	SF	5	\$1,120	
	Doors - Transom Window	3rd Floor	44	SF	6	\$745	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
	Floor Drain	3rd Floor	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	244	SF	7	\$0	
	Hand Dryer	3rd Floor	1	EA	7	\$0	
	Lavatory	3rd Floor	2	EA	7	\$0	
	Lighting - Pendent/Surface	3rd Floor	4	EA	6	\$496	
	Partitions	3rd Floor	6	EA	7	\$0	
	Walls - Concrete Block	3rd Floor	300	SF	7	\$0	
	Walls - Masonry	3rd Floor	60	SF	6	\$189	glazed
	Walls - Plaster/Drywall	3rd Floor	280	SF	6	\$773	
	Water Closet	3rd Floor	1	EA	6	\$336	
	Water Closet	3rd Floor	5	EA	7	\$0	
	Accessories	Gym 1 Balcony Mens	90	SF	6	\$830	
	Ceiling - Plaster/Drywall	Gym 1 Balcony Mens	10	SF	5	\$108	
	Ceiling - Plaster/Drywall	Gym 1 Balcony Mens	80	SF	6	\$277	
	Doors - Wood Doors inclu hw	Gym 1 Balcony Mens	1	EA	7	\$0	
	Floor Drain	Gym 1 Balcony Mens	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Gym 1 Balcony Mens	90	SF	6	\$190	
	Lavatory	Gym 1 Balcony Mens	1	EA	7	\$0	
	Lighting - Pendent/Surface	Gym 1 Balcony Mens	1	EA	6	\$124	
	Partitions	Gym 1 Balcony Mens	1	EA	6	\$297	
	Urinals	Gym 1 Balcony Mens	1	EA	6	\$336	
	Walls - Concrete Block	Gym 1 Balcony Mens	100	SF	6	\$293	
	Walls - Plaster/Drywall	Gym 1 Balcony Mens	280	SF	5	\$2,122	
	Water Closet	Gym 1 Balcony Mens	1	EA	6	\$336	
	Accessories	Gym 1 Balcony Womens	120	SF	6	\$1,107	
	Ceiling - Plaster/Drywall	Gym 1 Balcony Womens	120	SF	6	\$415	
	Doors - Wood Doors inclu hw	Gym 1 Balcony Womens	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	Gym 1 Balcony Womens	120	SF	7	\$0	
	Lavatory	Gym 1 Balcony Womens	1	EA	7	\$0	
	Lighting - Pendent/Surface	Gym 1 Balcony Womens	2	EA	7	\$0	
	Partitions	Gym 1 Balcony Womens	2	EA	7	\$0	

## Building: Addition 2

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Walls - Plaster/Drywall	Gym 1 Balcony Womens	135	SF	4	\$1,641	water damage to NW corner
	Walls - Plaster/Drywall	Gym 1 Balcony Womens	600	SF	7	\$0	
	Water Closet	Gym 1 Balcony Womens	2	EA	6	\$672	

### Rooms (Other Than Classrooms) Subtotal:

**\$693,128**

## Building: Addition 2

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Doors - Steel Doors incl hw	Basement	1	EA	7	\$0	
	Ceiling - Plaster/Drywall	Corridor @ Mens Locker Room 154	142	SF	6	\$879	Note: this corridor is an exit for men's locker room, but is being used for storage.
	Doors - Transom Window	Corridor @ Mens Locker Room 154	22	EA	6	\$372	
	Doors - Wood Doors include hw	Corridor @ Mens Locker Room 154	2	EA	6	\$602	
	Floor - Tile Ceramic/ Porcelain	Corridor @ Mens Locker Room 154	142	SF	6	\$396	
	Lighting - Pendent/Surface	Corridor @ Mens Locker Room 154	4	EA	7	\$0	
	Walls - Masonry	Corridor @ Mens Locker Room 154	300	SF	6	\$944	
	Walls - Plaster/Drywall	Corridor @ Mens Locker Room 154	20	SF	5	\$173	
	Walls - Plaster/Drywall	Corridor @ Mens Locker Room 154	170	SF	6	\$754	
	Ceiling - Lay-in	First Floor Corridors	2,702	SF	6	\$8,114	
	Ceiling - Plaster/Drywall	First Floor Corridors	949	SF	6	\$5,876	
	Doors - Steel Doors incl hw	First Floor Corridors	6	EA	7	\$0	
	Doors - Transom Window	First Floor Corridors	22	EA	6	\$372	
	Doors - Wood Doors include hw	First Floor Corridors	3	EA	6	\$903	
	Doors - Wood Doors include hw	First Floor Corridors	5	EA	5	\$5,870	
	Drinking Fountains - Single Water Cooler	First Floor Corridors	2	EA	5	\$6,014	
	Floor - Terrazzo	First Floor Corridors	1,247	SF	7	\$0	
	Floor - Terrazzo	First Floor Corridors	10	SF	6	\$116	
	Floor - Tile/Sheet	First Floor Corridors	70	SF	6	\$74	
	Floor - Tile/Sheet	First Floor Corridors	2,666	SF	7	\$0	
	Lighting - Lay-in	First Floor Corridors	42	EA	7	\$0	
	Lighting - Pendent/Surface	First Floor Corridors	4	EA	7	\$0	
	Lighting - Pendent/Surface	First Floor Corridors	6	EA	6	\$743	
	Student Lockers - One Tier	First Floor Corridors	147	EA	7	\$0	
	Walls - Masonry	First Floor Corridors	2,915	SF	6	\$9,171	
	Walls - Plaster/Drywall	First Floor Corridors	972	SF	6	\$5,115	

## Building: Addition 2

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Walls - Plaster/Drywall	First Floor Corridors	2,247	SF	7	\$0	
	Ceiling - Plaster/Drywall	First Floor Vestibules	329	SF	7	\$0	
	Ceiling - Plaster/Drywall	First Floor Vestibules	86	SF	6	\$633	
	Doors - Wood Doors include hw	First Floor Vestibules	3	EA	6	\$903	
	Floor - Terrazzo	First Floor Vestibules	172	SF	6	\$1,707	
	Floor - Terrazzo	First Floor Vestibules	243	SF	7	\$0	
	Lighting - Pendent/Surface	First Floor Vestibules	4	EA	7	\$0	
	Lighting - Pendent/Surface	First Floor Vestibules	4	EA	6	\$496	
	Walls - Masonry	First Floor Vestibules	647	SF	6	\$2,035	
	Walls - Plaster/Drywall	First Floor Vestibules	384	SF	7	\$0	
	Walls - Plaster/Drywall	First Floor Vestibules	326	SF	6	\$1,716	
	Ceiling - Plaster/Drywall	Gym 1 Vestibule	208	SF	6	\$1,288	
	Doors - Steel Doors incl hw	Gym 1 Vestibule	2	EA	6	\$602	
	Floor - Terrazzo	Gym 1 Vestibule	208	SF	6	\$1,746	
	Lighting - Pendent/Surface	Gym 1 Vestibule	2	EA	6	\$248	
	Walls - Masonry	Gym 1 Vestibule	280	SF	6	\$881	
	Walls - Masonry	Gym 1 Vestibule	6	SF	4	\$599	
	Walls - Plaster/Drywall	Gym 1 Vestibule	250	SF	6	\$1,108	
	Ceiling - Lay-in	Second Floor Corridors	2,431	SF	6	\$7,300	
	Ceiling - Lay-in	Second Floor Corridors	439	SF	7	\$0	
	Ceiling - Plaster/Drywall	Second Floor Corridors	36	SF	7	\$0	
	Doors - Wood Doors include hw	Second Floor Corridors	1	EA	5	\$1,174	
	Doors - Wood Doors include hw	Second Floor Corridors	1	EA	6	\$301	
	Drinking Fountains - Single Water Cooler	Second Floor Corridors	2	EA	5	\$6,014	
	Floor - Terrazzo	Second Floor Corridors	334	SF	7	\$0	
	Floor - Tile/Sheet	Second Floor Corridors	1,834	SF	7	\$0	
	Floor - Tile/Sheet	Second Floor Corridors	738	SF	6	\$475	
	Lighting - Lay-in	Second Floor Corridors	41	EA	7	\$0	
	Student Lockers - One Tier	Second Floor Corridors	143	EA	7	\$0	
	Walls - Masonry	Second Floor Corridors	2,056	SF	6	\$6,468	
	Walls - Plaster/Drywall	Second Floor Corridors	2,166	SF	7	\$0	
	Ceiling - Lay-in	Third Floor Corridors	2,858	SF	6	\$8,583	
	Ceiling - Plaster/Drywall	Third Floor Corridors	48	SF	7	\$0	
	Doors - Wood Doors include hw	Third Floor Corridors	1	EA	7	\$0	
	Doors - Wood Doors include hw	Third Floor Corridors	4	EA	6	\$1,204	
	Doors - Wood Doors include hw	Third Floor Corridors	3	EA	5	\$3,522	
	Drinking Fountains - Single Water Cooler	Third Floor Corridors	2	EA	5	\$6,014	

## Building: Addition 2

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Floor - Terrazzo	Third Floor Corridors	332	SF	7	\$0	
	Floor - Tile/Sheet	Third Floor Corridors	2,207	SF	7	\$0	
	Floor - Tile/Sheet	Third Floor Corridors	365	SF	6	\$235	
	Lighting - Lay-in	Third Floor Corridors	40	EA	7	\$0	
	Student Lockers - One Tier	Third Floor Corridors	144	EA	7	\$0	
	Walls - Masonry	Third Floor Corridors	2,052	SF	6	\$6,456	
	Walls - Plaster/Drywall	Third Floor Corridors	1,657	SF	7	\$0	
	Ceiling - Plaster/Drywall	Vestibule @ Womens Locker Room	48	SF	6	\$297	Note: this is an exit for women's gym, but is being used as storage.
	Doors - Transom Window	Vestibule @ Womens Locker Room	22	EA	6	\$372	
	Doors - Wood Doors include hw	Vestibule @ Womens Locker Room	2	EA	6	\$602	
	Floor - Terrazzo	Vestibule @ Womens Locker Room	48	SF	6	\$403	
	Lighting - Pendent/Surface	Vestibule @ Womens Locker Room	1	EA	7	\$0	
	Walls - Masonry	Vestibule @ Womens Locker Room	110	SF	5	\$4,546	
	Walls - Plaster/Drywall	Vestibule @ Womens Locker Room	60	SF	6	\$266	
<b>Stairs</b>							
	Ceiling - Lay-in	Southeast Stairwell	136	SF	6	\$408	
	Ceiling - Plaster/Drywall	Southeast Stairwell	162	SF	6	\$1,186	
	Floor - Terrazzo	Southeast Stairwell	260	SF	7	\$0	
	Handrails	Southeast Stairwell	123	LF	6	\$1,066	
	Lighting - Lay-in	Southeast Stairwell	2	EA	7	\$0	
	Lighting - Pendent/Surface	Southeast Stairwell	4	EA	7	\$0	
	Stairs - Terrazzo	Southeast Stairwell	346	LF	7	\$0	
	Stairs - Terrazzo	Southeast Stairwell	6	LF	6	\$56	
	Walls - Masonry	Southeast Stairwell	1,004	SF	6	\$3,159	
	Walls - Plaster/Drywall	Southeast Stairwell	1,507	SF	6	\$4,159	
	Ceiling - Lay-in	Southwest Staircase	484	SF	6	\$1,453	
	Ceiling - Plaster/Drywall	Southwest Staircase	122	SF	6	\$893	
	Ceiling - Plaster/Drywall	Southwest Staircase	81	SF	7	\$0	
	Floor - Terrazzo	Southwest Staircase	418	SF	7	\$0	
	Handrails	Southwest Staircase	121	LF	6	\$1,049	
	Lighting - Lay-in	Southwest Staircase	6	EA	7	\$0	
	Lighting - Pendent/Surface	Southwest Staircase	1	EA	6	\$124	
	Lighting - Pendent/Surface	Southwest Staircase	5	EA	7	\$0	
	Stairs - Terrazzo	Southwest Staircase	499	LF	7	\$0	
	Walls - Masonry	Southwest Staircase	1,085	SF	6	\$3,413	
	Walls - Plaster/Drywall	Southwest Staircase	1,327	SF	7	\$0	



## Building: Addition 2

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-------	-------------	----------	----------	------	------	------	----------

**Building Interior Subtotal:** **\$131,651**

**Total Building Cost** **\$2,983,560**

## SITE

### Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-------	-------------	----------	----------	------	------	------	----------

#### Civil/Drainage

Civil/ Drainage - Catch Basin	Entire Site	2	EA	7	\$0	
Civil/ Drainage - Site Drain	Entire Site	3	EA	7	\$0	light well
Civil/ Drainage - Site Manhole	Entire Site	21	EA	7	\$0	

#### Fencing

Fencing - Chain Link	Entire Site	115	LF	6	\$2,159	
Fencing - New Standard Ornamental	Entire Site	85	LF	7	\$0	

#### Landscape

Benches	Entire Site	86	EA	7	\$0	
Landscape - Grass	Entire Site	132,792	SF	7	\$0	
Landscape - Hardscape- Concrete	Entire Site	32,747	SF	6	\$169,050	
Parkway trees	Entire Site	52	EA	7	\$0	
Planting Beds/ Area	Entire Site	6,311	SF	7	\$0	site east and west
Retaining Wall - Concrete	Entire Site / Site - East	640	SF	5	\$34,228	spalling, cracking
Trash Receptacles	Entire Site	2	EA	7	\$0	

#### Parking Lot

Concrete Curbs	Entire Site / Site West	715	LF	6	\$9,182	
Surface - Asphalt	Entire Site	13,674	SF	6	\$33,046	site west and north
Trash Compactor	Entire Site / Site North	1	EA	6	\$0	
Trash Enclosure - Masonry	Entire Site / Site North	486	SF	5	\$34,304	bulging

#### Sidewalks

Sidewalks - Perimeter Sidewalks	Entire Site	11,424	SF	6	\$22,707	
---------------------------------	-------------	--------	----	---	----------	--

#### Signage

Flag Pole - Building Mounted Flag Pole	Entire Site / Site - East	1	EA	7	\$0	
Flag Pole - Flag Pole	Entire Site	2	EA	7	\$0	site east and west
Marquee - Building Mounted Back Lighted w/ LED	Entire Site / Site West	1	EA	7	\$0	
Monument - Sign	Entire Site / Site - East	1	EA	7	\$0	

## SITE

### Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Site Subtotal:</b>						<b>\$304,677</b>	
<b>Total Site Cost</b>						<b>\$304,677</b>	
<b>Campus Total <sup>2 3</sup></b>						<b>\$15,526,851</b>	

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

<sup>2</sup> As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

<sup>3</sup> The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

## Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- **Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- **For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
- **Campus Total** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

## Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
<b>Main</b>														
Art Room	Art Room		353	353	920	0	7	17	210	105	40	Y	Y	N
Art Room	Art Room		355	355	920	0	2	14	210	105	40	Y	Y	N
Art Room	Art Room		361	361	1,584	0	1	10	108	54	40	N	Y	N
Band Room	Regular Classroom		272	272	1,592	1	10	25	414	207	40	Y	N	N
Band Room	Music Room		425	425	2,447	0	1	13	514	214	40	Y	Y	N
Computer Lab	Regular Classroom		221	221	1,500	1	42	88	350	175	40	Y	Y	N
Computer Lab	Regular Classroom		234	234	1,030	0	47	88	280	140	40	Y	Y	N
Computer Lab	Regular Classroom		276	276	730	0	31	45	207	103	40	Y	N	N
Computer Lab	Computer Lab		326	326	1,495	0	63	157	650	325	40	Y	Y	N
Computer Lab	Computer Lab		335	335	1,130	0	37	85	180	90	40	Y	Y	N
Dance Room	Regular Classroom		166	164/166	1,488	1	4	26	360	180	40	Y	N	N
Faculty Lounge	Regular Classroom		222	222	705	0	15	25	210	105	40	Y	Y	N
Health	Regular Classroom		231-South	231	580	2	0	7	160	80	40	Y	Y	N
Music Room	Music Room		325	325	2,395	0	1	19	550	150	40	Y	Y	N
Office	Regular Classroom		231-North	231	580	3	3	6	160	80	40	Y	Y	N
Regular Classroom	Regular Classroom		162	162	730	1	4	26	207	103	40	Y	N	N
Regular Classroom	Regular Classroom		172	172	678	1	0	11	120	60	40	Y	N	N
Regular Classroom	Regular Classroom		174	174	528	1	2	11	120	60	40	Y	N	N
Regular Classroom	Regular Classroom		176	176	730	1	1	8	207	103	40	Y	N	N
Regular Classroom	Regular Classroom		219	219	1,030	1	2	13	215	107	40	Y	Y	N
Regular Classroom	Regular Classroom		230	230	1,145	0	0	23	280	140	40	Y	Y	N
Regular Classroom	Regular Classroom		233	233	1,130	0	4	26	225	125	40	Y	Y	N
Regular Classroom	Regular Classroom		236	236	730	0	7	28	450	225	40	Y	Y	N
Regular Classroom	Regular Classroom		260	260	730	0	3	18	207	103	40	N	N	N
Regular Classroom	Regular Classroom		261	261	730	1	6	14	164	82	40	N	N	N
Regular Classroom	Regular Classroom		262	262	730	0	4	14	207	103	40	Y	N	N
Regular Classroom	Regular Classroom		264	264	730	0	4	12	207	103	40	N	N	N
Regular Classroom	Regular Classroom		266	266	730	1	2	12	201	103	40	Y	N	N
Regular Classroom	Regular Classroom		273	273	730	0	4	14	207	103	40	N	N	N
Regular Classroom	Regular Classroom		275	275	730	1	4	14	207	113	40	Y	N	N
Regular Classroom	Regular Classroom		277	277	730	1	4	15	207	103	40	Y	N	N
Regular Classroom	Regular Classroom		278	278	730	0	3	18	207	103	40	Y	N	N
Regular Classroom	Regular Classroom		280	280	930	0	34	88	390	195	40	N	N	N
Regular Classroom	Regular Classroom		281	281	730	1	3	14	207	103	40	Y	N	N
Regular Classroom	Regular Classroom		319	319	1,130	1	4	16	150	75	40	Y	Y	N
Regular Classroom	Regular Classroom		320	320	1,050	0	5	7	140	35	40	Y	Y	N
Regular Classroom	Regular Classroom		322	322	730	1	0	39	210	105	40	Y	Y	N

## Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
<b>Main</b>														
Regular Classroom	Regular Classroom		328	328	730	0	1	13	210	105	40	Y	Y	N
Regular Classroom	Regular Classroom		330	330	730	0	3	13	210	105	40	Y	Y	N
Regular Classroom	Regular Classroom		332	332	730	0	0	41	210	105	40	N	Y	N
Regular Classroom	Regular Classroom		334	334	730	0	4	16	300	150	40	Y	Y	N
Regular Classroom	Art Room		351	351	920	1	17	18	210	105	40	Y	Y	N
Regular Classroom	Regular Classroom		363	363	816	0	5	17	162	81	40	N	N	N
Regular Classroom	Regular Classroom		367	367	725	0	4	14	270	135	40	N	N	N
Regular Classroom	Regular Classroom		372	372	750	0	3	94	126	63	40	N	Y	N
Regular Classroom	Regular Classroom		374	374	750	1	4	10	126	63	40	Y	Y	N
Regular Classroom	Regular Classroom		376	376	750	1	3	10	126	63	40	N	N	N
Regular Classroom	Regular Classroom		378	378	750	0	3	10	126	63	40	N	N	N
Regular Classroom	Regular Classroom		380	380	930	0	4	14	390	195	40	N	N	N
Science Lab Level 1	Science Lab Level 1		350	350	1,300	1	14	44	260	130	40	Y	Y	N
Science Lab Level 1	Science Lab Level 1		356	356	937	0	15	48	210	105	40	Y	Y	N
Science Lab Level 3	Science Lab Level 3		352	352	990	0	1	26	280	140	40	Y	Y	N
Science Lab Level 3	Science Lab Level 3		358	358	1,216	0	3	50	231	115	40	N	N	N
Science Lab Level 3	Science Lab Level 3		364	364	1,032	0	2	34	168	84	40	N	N	N
Science Lab Level 3	Science Lab Level 3		366	366	1,050	0	4	39	240	120	40	N	N	N
Weight	Regular Classroom		158/160	158/160	1,822	0	0	32	640	320	40	N	N	N

## Addition 1

Art Room	Art Room		336	336	1,797	0	1	12	370	150	40	N	Y	N
Computer Lab	Regular Classroom		343 East	343	982	1	37	88	250	65	40	N	Y	N
Computer Lab	Regular Classroom		343 West	343	508	0	21	54	94	19	40	N	Y	N
Office	Special Program		235	235	224	1	1	6	54	11	40	N	Y	N
Office	Special Program		239	239	512	1	1	6	72	22	40	N	Y	N
Office	Special Program		337	337	223	2	0	6	47	9	40	N	Y	N
Office	Special Program		341	341	494	1	3	42	47	9	40	N	Y	N
Regular Classroom	Regular Classroom		240	240	726	1	3	13	216	66	40	N	N	N
Regular Classroom	Regular Classroom		241	241	726	1	3	13	216	66	40	N	N	N
Regular Classroom	Regular Classroom		242	242	671	1	3	13	216	66	40	N	Y	N
Regular Classroom	Regular Classroom		243	243	726	1	3	13	216	66	40	N	Y	N
Regular Classroom	Regular Classroom		244	244	726	1	3	13	216	66	40	N	N	N
Regular Classroom	Regular Classroom		247	247	726	1	3	13	216	66	40	N	Y	N
Regular Classroom	Regular Classroom		248 East	230 (partial)	658	0	10	20	162	44	40	N	N	N
Regular Classroom	Regular Classroom		249	249	816	1	3	11	216	66	40	N	N	N
Regular Classroom	Regular Classroom		340	340	1,085	1	3	18	250	65	40	N	N	N



## Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
<b>Addition 1</b>														
Regular Classroom	Regular Classroom		344	344	1,122	1	4	42	282	84	40	N	N	N
Regular Classroom	Regular Classroom		346 East	346 (Partial)	718	2	8	32	188	56	40	N	Y	N
Regular Classroom	Regular Classroom		347	347	743	1	4	30	188	56	40	N	Y	N
Regular Classroom	Regular Classroom		348	348	1,200	1	4	12	282	84	40	N	Y	N
Regular Classroom	Regular Classroom		349	349	816	1	3	10	188	56	40	N	Y	N
Special Program	Store Room	1st Floor	186 ROTC	186	497	1	1	18	0	0	40	N	N	N
Special Program	Special Program		245	245	367	1	0	5	108	33	40	N	N	N
Special Program	Regular Classroom		246 East	248	594	0	0	7	180	55	40	N	N	N
Special Program	Special Program		248 West	230 (partial)	490	1	13	28	126	33	40	N	N	N
Special Program	Special Program		345	345	367	3	5	32	78	19	40	N	Y	N
Store Room	Special Program		146	146	596	0	0	52	214	60	40	N	Y	N
Store Room	Special Program		149	149	1,332	1	4	36	384	108	40	N	N	N
Store Room	Computer Lab		246 West	246	490	1	56	114	108	22	40	N	N	N
Store Room	Special Program		346 West	346 (Partial)	470	0	7	22	94	28	40	N	N	N

<b>Addition 2</b>														
Other Instructional Use	Other Instructional Use	2nd Floor	205	205	358	1	2	13	108	33	40	N	Y	N
Other Instructional Use	Office	2nd Floor	217	217	152	0	0	3	72	22	40	N	Y	N
Other Instructional Use	Other Instructional Use	3rd Floor	305	305	368	1	2	15	94	28	40	N	N	N
Other Instructional Use	Office	3rd Floor	317	317	148	0	0	4	62	18	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	101	101	796	1	2	9	256	72	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	103	103	750	1	2	16	256	72	40	N	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	796	1	2	12	216	66	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	796	1	40	52	216	44	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	726	1	2	18	216	66	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	726	1	2	24	216	66	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	726	1	2	13	216	66		N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	726	1	2	13	216	66	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	726	1	2	13	216	66	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	726	1	2	13	216	66	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	726	0	0	7	216	55	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	726	1	2	13	216	66	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	300	300	825	1	2	18	188	56	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	825	1	24	50	188	37	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	750	1	2	4	188	56	40	N	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	750	1	2	11	188	56	40	N	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	750	1	2	11	188	56	40	N	N	N

## Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
<b>Addition 2</b>														
Science Lab Level 1	Regular Classroom	1st Floor	100	100	1,314	2	2	46	427	120	40	N	N	N
Science Lab Level 2	Regular Classroom	1st Floor	105	105	1,124	1	11	42	384	108	40	N	N	N
Science Lab Level 2	Regular Classroom	1st Floor	106	106	1,232	2	2	46	427	120	40	N	N	N
Science Lab Level 2	Regular Classroom	1st Floor	110	110 + 108	1,472	1	11	48	512	132	40	N	N	N
Science Lab Level 2	Regular Classroom	3rd Floor	306	306	1,228	0	4	42	312	93	40	N	N	N
Science Lab Level 2	Regular Classroom	3rd Floor	310	310	1,136	1	2	18	312	93	40	N	N	N
Science Lab Level 3	Regular Classroom	3rd Floor	302	302	786	1	2	6	188	56	40	N	N	N
Special Education		2nd Floor	213	213	510	0	0	28	72	22	40	N	Y	N
Special Education		3rd Floor	315	315	490	1	2	14	62	18		N	Y	N