

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1895	3	51,852
Campus Total			51,852

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	1						
	Exterior Doors - Exterior FRP Door	1	2	EA	6	10+ years	
	Exterior Doors - Side lite	1	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	1	2	EA	6	10+ years	
	Ramps - Concrete	1	16	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	1st Floor Fire Escape	1	EA	5	0-1 year	Frame deterioration w/rust and minor
		·				·	signs of corrosion
	Exterior Doors - Side lite	1st Floor Fire Escape	1	EA	5	0-1 year	Frame deterioration
	Exterior Doors - Transom Lite	1st Floor Fire Escape	1	EA	5	0-1 year	Frame Rusted/Corroded
	Exterior Doors - Exterior Steel Door	2	1	EA	5	2-5 years	Weather Exposed/Rotting frame.
						-	Caulking missing
	Exterior Doors - Transom Lite	2	1	EA	5	2-5 years	Weather Exposed/rotting and
							deteriorating frame
	Exterior Doors - Exterior Steel Door	2nd Floor Fire Escape	1	EA	5	2-5 years	Frame: rust/corrosion/rot
							deterioration. Door: Minor
							paint/Repair
	Exterior Doors - Transom Lite	2nd Floor Fire Escape	1	EA	5	0-1 year	Aged/outdated Wood window
	Exterior Doors - Exterior Steel Door	3	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	3rd Floor Fire Escape	1	EA	5	2-5 years	Frame: Rust/Corroded/Deterioration.
							Door: minor repair/Paint
	Exterior Doors - Transom Lite	3rd Floor Fire Escape	1	EA	4	0-1 year	Aged/outdated window
	Exterior Stairs - Concrete	3rd Floor Fire Escape	4	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	4 - Boiler Room	1	EA	4	0-1 year	Deteriorated
	Exterior Stairs - Concrete	4 - Boiler Room	3	LF	4	0-1 year	Cracked broken
	Exterior Doors - Exterior Steel Door	5	1	EA	6	10+ years	



gory	y : Exterior		В	uilding	: Main		
						Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	5	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	6	2	EA	6	10+ years	
	Exterior Doors - Side lite	6	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	6	2	EA	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	6	8	LF	6	2-5 years	
	Ramps - Steel or Aluminum	6	4	LF	6	10+ years	
	Entrance Control - Audio and Video	7 - Main	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	7 - Main	2	EA	6	10+ years	
	Exterior Doors - Side lite	7 - Main	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	7 - Main	2	EA	6	10+ years	
	Power Door Operator and Controls	7 - Main	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	7 - Main	32	LF	6	10+ years	
	Ramps - Concrete	7 - Main	20	LF	6	2-5 years	
	Ramps - Concrete	7 - Main	10	LF	4	1-2 years	Cracked
	Entrance Control - Audio and Video	8	1	EA	7	10+ years	Ordonod
	Exterior Doors - Exterior FRP Door	8	2	EA	6	10+ years	
	Exterior Doors - Side lite	8	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	8	2	EA	7	10+ years	
	Power Door Operator and Controls	8	1	EA	7	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	8	32	LF	5	2-5 years	Re-securing/Paint: loose/woobly
	Ramps - Concrete	8	16	LF	7	10+ years	Re-securing/Famil: 1005e/W00biy
Escap		Foot Foods	78	LF		2.5.42272	
	Fire Escape	East Façade	78	LF	5	2-5 years	
dation	n						
	Foundation - Masonry	Entire Building	646	LF	7	10+ years	
	Foundation - Masonry	Entire Building	30	LF	5	1-2 years	Cracking/chipping - epoxy/Seal
	Superstructure - Steel with Clay Tile Arch	Entire Building	51,852	SF	7	10+ years	отальный от трина
	Caperon dotare Close man clay the reserve	g	0.,002	<b>.</b>	•	.o. you.o	
ng							
	Exterior Lighting - Wall Mounted	Entire Building	12	EA	6	6-10 years	Quantity Adjusted
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	0-1 year	Fixture outdated/broken globe/broker
							lamp and weather exposed
Syste	em						
	Access Ladder - Metal	A	1	EA	7	10+ years	Ladder could be heavier gauge metal flimsy at top but all n all does well avertical circulation
	Access Ladder - Wood	A	1	EA	4	0-1 year	Lean-Too wood ladder - Ladder rung is uneven, with a splitting members. Nailed as opposed to screwed construction.
	Access Ladder - Wood	A	1	E	Α	A 4	A 4 0-1 year



Category : Exterior			В	Building : Main					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Coping - Terra Cotta	Α	337	LF	6	10+ years			
	Downspouts - Exterior Downspouts	Α	146	LF	6	10+ years			
	Parapet - 16" - 30" Height	Α	137	LF	7	10+ years			
	Parapet - 16" - 30" Height	Α	100	LF	5	2-5 years			
	Parapet - 16" - 30" Height	Α	100	LF	5	2-5 years			
	Roof - Modified Bitumen	Α	5,360	SF	6	6-10 years			
	Roof Hatch - Metal	Α	1	EA	7	10+ years	Hatch only accesses attic space		
	Roof Structure - Steel with Clay Tile Arch	Α	5,360	SF	7	10+ years	,		
	Access Ladder - Metal	В	1	EA	4	1-2 years	Loose		
	Coping - Clay Tile	В	42	LF	6	10+ years			
	Coping - Terra Cotta	В	174	LF	6	10+ years			
	Downspouts - Exterior Downspouts	В	178	LF	6	10+ years			
	Parapet - 16" - 30" Height	В	188	LF	6	10+ years			
	Parapet - Parapet < 16" Height	В	28	LF	6	10+ years			
	Roof - Modified Bitumen	В	3,267	SF	6	6-10 years			
	Roof Hatch - Metal	В	1	EA	7	10+ years			
	Roof Structure - Steel with Clay Tile Arch	В	3,267	SF	7	10+ years			
	Coping - Stone	C	61	LF	6	10+ years			
	Downspouts - Exterior Downspouts	C	19	LF	6	6-10 years			
	Parapet - Parapet < 16" Height	C	61	LF	6	10+ years			
	Roof - Modified Bitumen	C	434	SF	6	•			
		C	434	SF	7	6-10 years			
	Roof Structure - Steel with Clay Tile Arch	D				10+ years			
	Access Ladder - Metal		1	EΑ	7	10+ years			
	Access Ladder - Metal	D	1	EA	7	10+ years			
	Coping - Clay Tile	D	42	LF	6	10+ years			
	Coping - Terra Cotta	D	30	LF	6	10+ years			
	Coping - Terra Cotta	D	144	LF . –	6	10+ years			
	Downspouts - Exterior Downspouts	D	178	LF . –	6	10+ years			
	Parapet - 16" - 30" Height	D	188	LF	6	6-10 years	Joints receding/deteriorating		
	Parapet - Parapet < 16" Height	D	28	LF	6	10+ years			
	Roof - Modified Bitumen	D	3,267	SF	6	6-10 years			
	Roof Hatch - Metal	D	1	EA	7	10+ years			
	Roof Structure - Steel with Clay Tile Arch	D	3,267	SF	7	10+ years			
	Coping - Stone	E	61	LF	6	10+ years			
	Downspouts - Exterior Downspouts	E	19	LF	6	6-10 years			
	Parapet - 16" - 30" Height	E	61	LF	6	10+ years			
	Roof - Modified Bitumen	E	306	SF	6	6-10 years			
	Roof Structure - Steel with Clay Tile Arch	E	306	SF	7	10+ years			
	Coping - Clay Tile	F	28	LF	6	10+ years			
	Coping - Terra Cotta	F	51	LF	6	10+ years			
	Downspouts - Exterior Downspouts	F	16	LF	6	6-10 years			
	Parapet - Parapet < 16" Height	F	79	LF	6	10+ years			
	Roof - Modified Bitumen	F	760	SF	6	6-10 years			
	Roof Structure - Steel with Clay Tile Arch	F	760	SF	7	10+ years			
	The state of the s	-	700	٥.	•	,			



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Chimney - Brick Chimney- Concrete/ Mortar	G	50	LF	7	10+ years	
	Liner						
	Chimney - Brick Chimney- Concrete/ Mortar	G	20	LF	5	2-5 years	Brick failure/Cracking w/ Joint
	Liner Coping - Clay Tile	0	69	LF	6	10	deterioration and open joints
		G G	68	LF LF	6	10+ years	
	Coping - Terra Cotta		48		6	10+ years	
	Downspouts - Exterior Downspouts	G G	16	LF LF	6	10+ years	
	Parapet - Parapet < 16" Height		116		6	10+ years	
	Roof - Modified Bitumen	G	1,440	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	G	1,440	SF	7	10+ years	
	Coping - Clay Tile	H	46	LF	6	10+ years	
	Coping - Terra Cotta	H	86	LF	6	10+ years	
	Downspouts - Exterior Downspouts	H	16	LF	6	10+ years	
	Parapet - Parapet < 16" Height	H	132	LF	7	10+ years	
	Roof - Modified Bitumen	H	1,464	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Н	1,464	SF	7	10+ years	
Valls							
	Cornice - Metal Projecting	Entire Building	462	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	18,965	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	315	SF	5	2-5 years	
	Exterior Walls - Stone-Cut	Entire Building	2,539	SF	5	2-5 years	
Nindows	3						
	Guard - Guards wire guard	Entire Building	1,869	SF	6	2-5 years	
	Lintels - Brick	Entire Building	276	LF	6	10+ years	
	Lintels - Steel	Entire Building	358	LF	6	10+ years	
	Lintels - Stone	Entire Building	170	LF	6	10+ years	
	Skylite - Lexan	Entire Building	27	SF	6	10+ years	Per site engineer asset does not exi- - Removed
	Windows - Decorative	Entire Building	171	SF	6	10+ years	- Kellioved
	Windows - Decorative	Entire Building	9	SF	6	10+ years	
	Windows - Insulated Panel	Entire Building	160	SF	6	10+ years	
	Windows - Histolated Farier Windows - Louver	Entire Building	144	SF	6	10+ years	
	Windows - Louvei Windows - Sash Aluminum	Entire Building	494	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,936	SF	6	10+ years	
	•	Littiro Building				101 youro	
Catego	ry : Electrical		В	uilding	: Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
-	Emergency A/C Power - Corridors and Stairs	Entire Building	8,562	SF	6	10+ years	Building has EM panel



Catego	ry : Electrical		В	uilding	: Main		The Hoyne Avenue, Gilleago, ie 66616
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Gym	Entire Building	1,200	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,003	SF	6	10+ years	
	Emergency A/C Power - Multipurpose	Entire Building	4,570	SF	6	10+ years	
	Room Emergency Battery Packs - Corridors and	Entire Building	21	EA	6	6-10 years	
	Stairs	Little Ballanig	21	L/\	O	o ro years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	2	0-1 year	Older, more than 40 years old, batteries not replaced
	Emergency Battery Packs - Lunchrooms	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose	Entire Building	2	EA	6	6-10 years	
	Room	Ziiiii o Dallallig	_	_, .	Ŭ	o ro youro	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Security System - CCTV	Entire Building	51,582	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	51,582	SF	5	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	12	EA	5	6-10 years	Recently serviced
	Exit Signs - Corridors and Stairs	Entire Building	10	EA	2	0-1 year	No battery pack
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	Recently repaired
	Exit Signs - Gym	Entire Building	3	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	1	EΑ	6	6-10 years	With battery
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	with battory
	Automatic Transfer Switch	Mechanical Room	1	EA	4	2-5 years	Older, not reliable
_Main Ser	vice						
	PA System	Entire Building	51,582	SF	5	6-10 years	
	Independent Electrical Service for	Mechanical Room	1	EA	4	2-5 years	Not reliable, served by an older ATS,
	emergency power	Wechanical Room	ı	LA	7	2-5 years	2 electric meters
	Main Electrical Service - 1200 A	Mechanical Room	1	EA	4	2-5 years	More than 50 years old, not reliable,
	120/208/3PH						replacement parts difficult to find, corroded
Power D	istribution						
_ OWELD	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	Older, occasionally trip
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	7	10+ years	τ το , τ τ το , τ γ τ γ
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	6-10 years	Recently serviced
	Main Distribution Panels - Less than 400	Entire Building	1	EA	7	10+ years	
	amp						
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	4	2-5 years	Older, corroded, not reliable, occasionally trips
	Transformers - 120/240 - 120/208	Entire Building	1	EA	5	6-10 years	Next to switchgear, previously not



Group Item - Type Location  Fire Alarm  Fire Alarm Panel Mechanical Room Fire Alarm Strobe Lights Mechanical Room	Quantity	UOM		Recommend	
Fire Alarm Fire Alarm Panel Mechanical Room	Quantity			Danlagament	Comments
Fire Alarm Panel Mechanical Room		OOW	Rank	Replacement	Comments
	1	EA	6	6-10 years	More than 30 years old,not reliable
	51,582	SF	6	10+ years	More than 30 years old, not reliable
Fire Alarm_System Mechanical Room	51,582	SF	5	•	
				6-10 years	Older 40 years ald not reliable
Fire Pump Controller Mechanical Room	1	EA	4	2-5 years	Older, 40 years old, not reliable
Pump Room Assembly					
Fire Pump - Less than 25hp Fire Pump Room	1	EA	6	10+ years	For dry system
The Full Process	·	_, 、	Ü	101 youro	r or any oyotom
Sprinkler System					
Dry Sprinkler System Entire Building	51,582	SF	6	6-10 years	Served by air compressor
Sprinkler Heads Entire Building	51,582	SF	4	2-5 years	More than 70 years old, not reliable
·				·	Corroded. A few deteriorated
					sprinklers heads were recently
					replaced
Sprinkler Piping Entire Building	51,582	SF	5	6-10 years	Minor leaks occasionally repaired
				-	
Category : Mechanical	В	uilding	: Main	_	
Group Item - Type Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Conditioning	Quantity	OCIVI	Naiik	Replacement	Comments
Condensing Unit- Roof Mounted - 5-10 Roof	1	EA	5	6 10 years	Serves fan coil unit in MDF room.
<b>y</b>	1	EA	5	6-10 years	assessed by MEP, previously not
tons					assessed by MEP, previously not assessed. Data Aire Inc makes
					computer room air conditioners, CRACs
					CRACS
Air Handling Systems					
Air Handling Unit- Built Up-Multi Zone- Basement	1	EA	5	10+ years	Old and well maintained
Double Delivery- Steam Coils - 30001 -				•	
45000 cfm					
Air Intake Basement	2	EA	5	6-10 years	
Auxiliaries - 30001 - 45000 cfm Basement	1	EA	5	10+ years	Well maintained, old
Return Duct Work - Masonry and Ducts- Basement	100	LF	5	10+ years	Common return from corridor
Missing or Existing Shaft			-	<b>,</b>	
Zone Dampers Basement	34	EA	5	6-10 years	Some are manually adjusted.
·				,	Functional. BAS controls issue,
					located in south and north plenum
					rooms
Boiler Systems					
Boiler Auxiliary- Scotch Marine- Steam Low Boiler Room	2	EA	5	6-10 years	



Catego	Category : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Pressure Boiler - 101 - 150 HP						
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	2016 installation
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	4	2-5 years	Corroded tank, old, leaking steam, probably due to failed steam traps
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	10+ years	A few tubes replaced in 2021
	Piping - Condensate Pipe- Steel	Boiler Room	150	LF	5	10+ years	There are a few pipe clamps, functional, no leaks
	Piping - Steam Pipe- Steel	Boiler Room	150	LF	5	10+ years	There are a few pipe clamps
	Steam Traps	Boiler Room	150	EA	5	6-10 years	Occasionally serviced
	Steam Traps	Boiler Room	5	EA	3	0-1 year	Leak, causing feed water tank to leak steam
Heating	Devices						
	Cabinet Heaters - With Steam Coil	2nd Floor	2	EA	6	10+ years	
	Fin Tube - Electric	Basement	4	LF	6	10+ years	Previously not assessed, in office
	Unit Heater - Steam	Boiler Room	1	EΑ	4	2-5 years	Older, corroded, not reliable
	Radiators - Steam	Entire Building	5	EA	5	6-10 years	Older, functional, temperatures are difficult to control
	Wall Heater - Electric	Entire Building	1	EA	6	10+ years	amount to control
	Wall Heater - Electric	Entire Building	7	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	5	EA	4	2-5 years	Older, not reliable
_Tempera	ture Control						
·	Electric Thermostat	Entire Building	4	EA	5	6-10 years	Used for Remotely temperature controlled wall heaters
	Pneumatic System	Entire Building	51.582	SF	4	2-5 years	Mostly manually controlled, old
	Thermostats - Pneumatic	Entire Building	8	EA	6	10+ years	
	Thermostats - Pneumatic	Entire Building	24	EA	5	6-10 years	Not callibrated
	Thermostats - Pneumatic	Entire Building	4	EA	4	1-2 years	Leak, not calibrated, old
Ventilation							
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	3	EA	5	6-10 years	In elevator mechanical room, kitchen
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	6	EA	6	6-10 years	
	Lab Exhaust Hood	Entire Building	1	EA	6	10+ years	Science Room 208. See also interior assessment for science room 208
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	or .						



Catego	ry : Plumbing		В	uilding	: Main		
Group	Hom Type	Location	Quantity	UOM	Rank	Recommend	Comments
Group	Item - Type Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	Quantity 1	EA	5	Replacement 6-10 years	Comments
_Piping_							
- 1	Domestic Piping-Hot Water Return Lines	Entire Building	51,582	SF	6	10+ years	Occasional leaks repaired
	Domestic Piping-Hot Water Return Risers	Entire Building	51,582	SF	6	10+ years	There are a few pipe clamps
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	51,582	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	51,582	SF	6	10+ years	Pipes have internal calcification, up to 50% restriction of flow, compensated for by use of a pressure booster pump
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	51,582	SF	6	10+ years	r wit
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	51,582	SF	6	10+ years	There are a few pipe clamps
	Sanitary Piping	Entire Building	51,582	SF	5	10+ years	
	Storm Piping	Entire Building	51,582	SF	5	10+ years	
	Vent Piping	Entire Building	51,582	SF	5	10+ years	
_Pumps_							
	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	6	10+ years	Seals recently repacked
	Pumps - Sump-Simplex	Elevator Pit	1	EA	5	6-10 years	Under elevator
	Pumps - Sump-Simplex	Mechanical Room	1	EA	5	6-10 years	In pit next to feed water tank, collects condensate water from leaking feed water tank. On 5 % of the time. Used frequently, every hour, 24/7

Category : Room **Building: Main** 

	Name Tama	l di	0	LIOM	DI-	Recommend	0
up	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
minist	rative Suites/Offices						
	Ceiling - Lay-in	001 Engineers Office	99	SF	6	10+ years	
	Ceiling - Lay-in	001 Engineers Office	16	SF	5	1-2 years	Water damaged and missing tile
	Doors - Wood Doors inclu hw	001 Engineers Office	1	EA	6	10+ years	
	Floor - Tile	001 Engineers Office	115	SF	6	10+ years	
	Lighting - Lay-in	001 Engineers Office	2	EA	6	6-10 years	
	Power Distribution	001 Engineers Office	2	EA	6	10+ years	
	Walls - Plaster/Drywall	001 Engineers Office	405	SF	6	10+ years	
	Work SInk	001 Engineers Office	1	EA	7	10+ years	
	Ceiling - Lay-in	017 Kitchen Office	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	017 Kitchen Office	1	EΑ	6	10+ years	
	Floor - Tile	017 Kitchen Office	60	SF	6	10+ years	
	Lighting - Pendent/Surface	017 Kitchen Office	1	EΑ	6	6-10 years	

Campus Name: Alcott HS Page : 8 of 25 Assessment Date: 05/03/2022



Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Masonry	017 Kitchen Office	136	SF	6	10+ years	
	Walls - Plaster/Drywall	017 Kitchen Office	136	SF	6	10+ years	
	Ceiling - Plaster/Drywall	102B	177	SF	6	10+ years	
	Doors - Transom Window	102B	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	102B	2	EA	6	10+ years	
	Floor - Tile	102B	177	SF	6	10+ years	
	Lighting - Pendent/Surface	102B	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	102B	663	SF	6	10+ years	
	Ceiling - Plaster/Drywall	104B	165	SF	6	10+ years	
	Doors - Transom Window	104B	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	104B	1	ĒΑ	6	10+ years	
	Floor - Tile	104B	165	SF	6	10+ years	
	Lighting - Pendent/Surface	104B	1	EΑ	5	2-5 years	
	Storage/ Closet	104B	4	SF	7	10+ years	
	Walls - Plaster/Drywall	104B	663	SF	6	10+ years	
	AC Unit	105 - Main Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	105 - Main Office	552	SF	6	10+ years	
	Ceiling - Lay-in	105 - Main Office	6	SF	4	0-1 year	Water damage
	Doors - Transom Window	105 - Main Office	9	SF	6	10+ years	water damage
	Doors - Wood Doors inclu hw	105 - Main Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	105 - Main Office	543	SF	7	,	
			15	SF	4	10+ years	Ctained flooring
	Floor - Tile/Sheet	105 - Main Office				0-1 year	Stained flooring
	Lighting - Lay-in	105 - Main Office	6	EA	6	6-10 years	
	Storage/ Closet	105 - Main Office	188	SF	5	10+ years	
	Walls - Plaster/Drywall	105 - Main Office	756	SF	6	10+ years	
	Work SInk	105 - Main Office	1	EA	7	10+ years	
	AC Unit	105A - Principal's Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	105A - Principal's Office	212	SF	6	10+ years	
	Doors - Wood Doors inclu hw	105A - Principal's Office	1	EA	6	10+ years	
	Floor - Tile	105A - Principal's Office	212	SF	6	10+ years	
	Lighting - Lay-in	105A - Principal's Office	2	EA	6	6-10 years	
	Storage/ Closet	105A - Principal's Office	6	SF	7	10+ years	
	Walls - Plaster/Drywall	105A - Principal's Office	666	SF	6	10+ years	
	Ceiling - Plaster/Drywall	106B	166	SF	6	10+ years	
	Doors - Wood Doors inclu hw	106B	2	EA	6	10+ years	
	Floor - Tile	106B	166	SF	6	10+ years	
	Lighting - Pendent/Surface	106B	1	EA	6	6-10 years	
	Storage/ Closet	106B	4	SF	7	10+ years	
	Walls - Plaster/Drywall	106B	663	SF	6	10+ years	
	AC Unit	107-Counselor Office	2	EA	7	6-10 years	
	Ceiling - Splined	107-Counselor Office	759	SF	6	10+ years	
	Doors - Wood Doors inclu hw	107-Counselor Office	1	EA	6	10+ years	
	Floor - Tile	107-Counselor Office	759	SF	6	10+ years	
	Lighting - Pendent/Surface	107-Counselor Office	14	EA	6	6-10 years	
	0 0				-	,	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	107-Counselor Office	1,030	SF	6	10+ years	
	Ceiling - Plaster/Drywall	107B	177	SF	6	10+ years	
	Doors - Wood Doors inclu hw	107B	2	EA	7	10+ years	
	Floor - Tile	107B	177	SF	6	10+ years	
	Lighting - Pendent/Surface	107B	1	EA	6	6-10 years	
	Storage/ Closet	107B	4	SF	7	10+ years	
	Walls - Plaster/Drywall	107B	663	SF	6	10+ years	
	Ceiling - Plaster/Drywall	108B - Storage	177	SF	6	10+ years	
	Doors - Wood Doors inclu hw	108B - Storage	2	EA	6	10+ years	
	Floor - Tile	108B - Storage	177	SF	6	10+ years	
	Lighting - Pendent/Surface	108B - Storage	2	EA	6	6-10 years	
	Storage/ Closet	108B - Storage	4	SF	7	10+ years	
	Walls - Plaster/Drywall	108B - Storage	663	SF	6	10+ years	
	Ceiling - Plaster/Drywall	201B	180	SF	6	10+ years	
	Doors - Transom Window	201B	1	SF	7	10+ years	
	Doors - Transom Window	201B	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	201B	2	ĒΑ	6	10+ years	
	Floor - Tile	201B	180	SF	6	10+ years	
	Lighting - Pendent/Surface	201B	1	EA	6	6-10 years	
	Storage/ Closet	201B	4	SF	7	10+ years	
	Walls - Plaster/Drywall	201B	663	SF	6	10+ years	
	Ceiling - Plaster/Drywall	202B	180	SF	6	10+ years	peeling
	Doors - Transom Window	202B	9	SF	7	10+ years	p 3 5
	Doors - Wood Doors inclu hw	202B	2	ĒΑ	6	10+ years	
	Floor - Tile	202B	180	SF	6	10+ years	
	Lighting - Pendent/Surface	202B	1	EΑ	6	6-10 years	
	Storage/ Closet	202B	4	SF	7	10+ years	
	Walls - Plaster/Drywall	202B	663	SF	6	10+ years	
	Ceiling - Plaster/Drywall	204B	170	SF	6	10+ years	
	Doors - Steel Doors incl hw	204B	1	EA	6	10+ years	
	Doors - Transom Window	204B	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	204B	2	EA	6	10+ years	
	Floor - Tile	204B	170	SF	6	10+ years	
	Lighting - Pendent/Surface	204B	1	EA	6	6-10 years	
	Power Distribution	204B	4	EA	6	10+ years	
	Storage/ Closet	204B	4	SF	7	10+ years	
	Walls - Plaster/Drywall	204B	663	SF	6	10+ years	
	Ceiling - Plaster/Drywall	302B	180	SF	6	10+ years	
	Doors - Transom Window	302B	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	302B	2	EA	6	10+ years	
	Floor - Tile	302B 302B	180	SF	7	10+ years	
	Lighting - Pendent/Surface	302B 302B	100	EA	6	6-10 years	
	Power Distribution	302B	2	EA	7	10+ years	
	Storage/ Closet	302B 302B	4	SF	7	10+ years	
	Storage/ Gloset	3020	4	3F	,	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	302B	510	SF	7	10+ years	
	Ceiling - Plaster/Drywall	308B	170	SF	6	10+ years	
	Ceiling - Plaster/Drywall	308B	10	SF	5	10+ years	
	Doors - Transom Window	308B	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	308B	2	EA	6	10+ years	
	Floor - Tile	308B	180	SF	7	10+ years	
	Lighting - Pendent/Surface	308B	1	EA	6	6-10 years	
	Power Distribution	308B	4	EA	7	10+ years	
	Storage/ Closet	308B	4	SF	7	10+ years	
	Walls - Plaster/Drywall	308B	510	SF	6	10+ years	
Gvmnas	ia						
	Ceiling - Plaster/Drywall	303	4,570	SF	6	10+ years	
	Doors - Side-lite	303	40	SF	7	10+ years	
	Doors - Transom Window	303	54	SF	7	10+ years	
	Doors - Wood Doors inclu hw	303	9	EA	6	10+ years	
	Floor - Wood	303	4,570	SF	6	10+ years	
	Lighting - Pendent/Surface	303	17	EΑ	6	6-10 years	
	Sound System	303	1	EA	7	6-10 years	
	Stage	303	1,066	SF	7	10+ years	
	Stage Curtain	303	2	ĒΑ	7	6-10 years	
	Stage Lift	303	1	EΑ	7	10+ years	
	Stage Lighting System	303	1	ΕA	7	6-10 years	
	Stage-Stairs - Wood	303	24	LF	7	10+ years	
	Walls - Plaster/Drywall	303	4,410	SF	6	10+ years	
Kitchen							
	Ceiling - Exposed	017 - Basement	486	SF	6	10+ years	
	Doors - Wood Doors inclu hw	017 - Basement	1	EA	6	10+ years	
	Floor - Tile	017 - Basement	486	SF	6	10+ years	
	Lighting - Pendent/Surface	017 - Basement	9	EA	6	6-10 years	
	Serving Line	017 - Basement	9	LF	6	10+ years	
	Walls - Concrete Block	017 - Basement	210	SF	7	10+ years	
	Walls - Masonry	017 - Basement	419	SF	7	10+ years	
	Walls - Plaster/Drywall	017 - Basement	210	SF	6	10+ years	
Locker/S	Shower Room						
	Accessories	301A	267	SF	7	6-10 years	
	Benches, ped mounted	301A	28	LF	7	10+ years	
	Ceiling - Plaster/Drywall	301A 301A	267	SF	6	10+ years	
	Doors - Transom Window	301A 301A	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	301A 301A	1	EA	6	-	
		301A 301A		SF		10+ years	
	Floor - Tile Ceramic/ Porcelain	JUIA	267	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		-
J				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	301A	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	301A	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	301A	506	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	301A	170	SF	6	10+ years	
	AC Unit	301B	1	EA	7	6-10 years	
	Accessories	301B	356	SF	7	6-10 years	
	Benches, ped mounted	301B	14	LF	6	10+ years	
	Ceiling - Plaster/Drywall	301B	356	SF	6	10+ years	
	Doors - Transom Window	301B	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	301B	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	301B	356	SF	6	10+ years	
	Lighting - Lay-in	301B	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	301B	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	301B	740	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	301B	170	SF	6	10+ years	
Lunch &	Multipurpose Room						
LUITOITO	Ceiling - Lay-in	013 Lunch Room	1,003	SF	6	10+ years	
	Doors - Steel Doors incl hw	013 Lunch Room	2	EA	6	10+ years	
	Floor - Tile	013 Lunch Room	1,003	SF	6	10+ years	
	Lighting - Pendent/Surface	013 Lunch Room	15	EA	6	6-10 years	
	Walls - Plaster/Drywall	013 Lunch Room	748	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	013 Lunch Room	374	SF	6	10+ years	
	Ceiling - Lay-in	016 Servery	710	SF	6	10+ years	
	Floor - Tile	016 Servery	710	SF	6	10+ years	
	Lighting - Pendent/Surface	016 Servery	9	EA	6	6-10 years	
	Walls - Masonry	016 Servery	622	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	016 Servery	311	SF	6	10+ years	
	Ceiling - Splined	211- Teachers Room	213	SF	6	10+ years	
	Doors - Transom Window	211- Teachers Room	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	211- Teachers Room	1	EA	6	10+ years	
	Floor - Tile	211- Teachers Room	213	SF	6	10+ years	
	Lighting - Pendent/Surface	211- Teachers Room 211- Teachers Room		EA	6	,	
	Storage/ Closet		2 59	SF		6-10 years	
		211- Teachers Room		SF SF	7	10+ years	
	Walls - Plaster/Drywall	211- Teachers Room	759	SF	6	10+ years	
_MDF_ID							
	Doors - Transom Window	207 B	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	207 B	1	EA	6	10+ years	
	Finishes	207 B	180	SF	5	6-10 years	
	Other Cooling Unit	207 B	1	EA	7	6-10 years	Computer cooling system
	Window AC Unit	207 B	1	EΑ	7	6-10 years	

Campus Name: Alcott HS Page : 12 of 25 Assessment Date: 05/03/2022



Catego	ry : Room		В	uilding	: Main		
			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	8	SF	7	10+ years	
	Janitor's Closet	2nd Floor	30	SF	7	10+ years	
	Storage Room	3rd Floor	170	SF	7	10+ years	
	Storage Room	3rd Floor	174	SF	7	10+ years	
	Storage Room	3rd Floor	180	SF SF	7	10+ years	
	Boiler Room Janitor's Closet	Basement Basement	1,470 22	SF SF	7 7	10+ years	
	Mechanical/ Service Rooms	Basement	80	SF SF	7	10+ years 10+ years	
	Mechanical/ Service Rooms	Basement	583	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	510	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	821	SF	7	10+ years	
	Storage Room	Basement	94	SF	7	10+ years	
	Storage Room	Basement	95	SF	7	10+ years	
	Storage Room	Basement	85	SF	7	10+ years	
	Storage Room	Basement	186	SF	7	10+ years	
	Storage Hostin	2000	.00	О.	•	. o v y can c	
Prep Ro	om						
	Casework	206 B	13	LF	6	10+ years	
	Ceiling - Lay-in	206 B	210	SF	7	10+ years	
	Doors - Wood Doors inclu hw	206 B	1	EA	6	10+ years	
	Floor - Tile	206 B	210	SF	7	10+ years	
	Lighting - Pendent/Surface	206 B	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	206 B	703	SF	7	10+ years	
	Work Sink	206 B	1	EA	7	10+ years	
Restroor	n						
TYCSHOOL	Accessories	002	323	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	002	323	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	002	323	SF	6	10+ years	Missing cover
	Floor Drain	002	1	ĒΑ	7	10+ years	3 11 1
	Hand Dryer	002	1	EA	7	6-10 years	
	Lavatory	002	3	EA	7	10+ years	
	Lighting - Pendent/Surface	002	4	EA	5	6-10 years	
	Partitions	002	4	EA	7	10+ years	
	Urinals	002	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	002	640	SF	6	10+ years	
	Water Closet	002	4	EA	7	10+ years	
	Accessories	006 Unisex	77	SF	7	10+ years	
	Ceiling - Exposed	006 Unisex	77	SF	6	10+ years	
	Doors - Wood Doors inclu hw	006 Unisex	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	006 Unisex	77	SF	6	10+ years	
	Floor Drain	006 Unisex	1	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	006 Unisex	1	EA	6	10+ years	
	Lighting - Pendent/Surface	006 Unisex	1	EA	6	6-10 years	
	Showers	006 Unisex	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	006 Unisex	330	SF	6	10+ years	
	Water Closet	006 Unisex	1	EA	6	10+ years	
	Accessories	018	385	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	018	385	SF	6	10+ years	
	Doors - Wood Doors inclu hw	018	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	018	385	SF	7	10+ years	
	Floor Drain	018	1	EΑ	7	10+ years	
	Hand Dryer	018	2	EA	7	6-10 years	
	Lavatory	018	3	EA	7	10+ years	
	Lighting - Pendent/Surface	018	7	ΕA	6	6-10 years	
	Partitions	018	8	EA	7	10+ years	
	Walls - Structural Glazed Tile	018	654	SF	6	10+ years	
	Water Closet	018	8	EA	7	10+ years	
	Accessories	101/Storage	60	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	101/Storage	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	101/Storage	1	EA	6	10+ years	
	Floor - Tile	101/Storage	60	SF	6	10+ years	
	Lavatory	101/Storage	1	EA	6		
	•	101/Storage	1	EA	6	10+ years	Dathroom ourrently not in use
	Lighting - Pendent/Surface		1	EA	5	6-10 years	Bathroom currently not in use
	Partitions Walls - Plaster/Drywall	101/Storage	•	SF		10+ years	
	<u> </u>	101/Storage	281		6	10+ years	
	Accessories	105A	54	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	105A	54	SF	6	10+ years	
	Doors - Wood Doors inclu hw	105A	1	EA	6	10+ years	
	Floor - Tile	105A	54	SF	6	10+ years	
	Lavatory	105A	1	EA	6	10+ years	
	Lighting - Pendent/Surface	105A	1	EA	5	2-5 years	
	Walls - Plaster/Drywall	105A	271	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	105A	90	SF	6	10+ years	
	Water Closet	105A	1	EA	6	10+ years	
	Accessories	109	93	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	109	93	SF	5	0-1 year	Water damaged
	Doors - Transom Window	109	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	109	1	EA	6	10+ years	
	Floor - Tile	109	53	SF	7	6-10 years	
	Floor - Tile	109	40	SF	4	0-1 year	Damaged tiles
	Lavatory	109	1	EA	6	10+ years	
	Lighting - Pendent/Surface	109	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	109	433	SF	6	10+ years	
	Water Closet	109	1	EA	6	10+ years	
	Accessories	205	230	SF	7	6-10 years	
		<del></del>	200	٠.	•	2 . 2 , 000	



Floor - Tile

# Louisa May Alcott College Preparatory HS 2957 N Hoyne AVENUE, Chicago, IL 60618

Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Exposed	205	230	SF	6	10+ years	
	Doors - Wood Doors inclu hw	205	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	205	230	SF	6	10+ years	
	Floor Drain	205	1	EA	7	10+ years	
	Hand Dryer	205	2	EA	7	6-10 years	
	Lavatory	205	3	EA	7	10+ years	
	Lighting - Pendent/Surface	205	3	EA	6	6-10 years	
	Partitions	205	3	EA	7	10+ years	
	Urinals	205	6	EA	7	10+ years	
	Walls - Plaster/Drywall	205	192	SF	6	10+ years	
	Walls - Structural Glazed Tile	205	575	SF	6	10+ years	
	Water Closet	205	3	EΑ	7	10+ years	
	Accessories	209	73	SF	7	6-10 years	
	Ceiling - Exposed	209	73	SF	7	10+ years	
	Doors - Transom Window	209	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	209	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	209	73	SF	6	10+ years	
	Floor Drain	209	1	EΑ	7	10+ years	
	Lavatory	209	1	EA	6	10+ years	
	Lighting - Pendent/Surface	209	1	ĒΑ	6	6-10 years	
	Walls - Structural Glazed Tile	209	414	SF	7	10+ years	
	Water Closet	209	1	ĒΑ	6	10+ years	
	Accessories	212	208	SF	7	6-10 years	
	Ceiling - Exposed	212	208	SF	6	10+ years	
	Doors - Wood Doors inclu hw	212	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	212	208	SF	6	10+ years	
	Floor Drain	212	1	EA	7	10+ years	
	Hand Dryer	212	2	EA	7	6-10 years	
	Lavatory	212	3	EΑ	7	10+ years	
	Lighting - Pendent/Surface	212	2	EA	6	6-10 years	
	Lighting - Wall Mounted	212	3	EA	6	6-10 years	
	Partitions	212	5	EA	7	10+ years	
	Walls - Plaster/Drywall	212	182	SF	6	10+ years	
	Walls - Structural Glazed Tile	212	547	SF	6	10+ years	
	Water Closet	212	5	EA	6	10+ years	
		2.2	0	_, .	Ŭ	, 500.0	
Catego	ory : Classroom		В	uilding	: Main		
<b>J</b>	•			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #001 (Music Room)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Lay-in	Basement	1,161	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	5	ĒΑ	6	10+ years	
	Floor Tile	Doomont	4.404	C.E.	•	101 400	

Basement

1,161

10+ years



Company   Comp	Catego	ory : Classroom		В	uilding	: Main		The state of the s
Lighting - Pendent/Surface	_				_			
Marker Board   Basement   20	Group		Location	Quantity	UOM	Rank		Comments
Storage Closet   Basement   80   SF   7   10+ years		Lighting - Pendent/Surface	Basement	14	EA	6	6-10 years	
Storage / Closet   Basement   80   SF   7   10 + years   Walls - Masonry   Basement   1,198   SF   6   10 + years   Walls - Masonry   Work Sink   Basement   1   EA   7   10 + years   Work Sink   Basement   1   EA   7   10 + years   Work Sink   Basement   1   EA   7   6 - 10 years   Walls - Plaster/Dynal   Basement   1,003   SF   6   10 + years   Floor - Tile   Basement   1,003   SF   6   10 + years   Floor - Tile   Basement   1,003   SF   6   10 + years   Floor - Tile   Floor - Tile -		Marker Board	Basement	20	LF	6	6-10 years	
Walls   Masonry   Basement		Storage/ Closet	Basement	80	SF	7	10+ years	
Walls - Masonry		Storage/ Closet	Basement	80	SF	7		
Mork Sink   Basement   1 EA 7 10+ years		Walls - Masonry	Basement	1,198	SF	6	10+ years	
AC Units Celling - Splined Basement 1,003 SF 6 10+ years Floor - Tile Basement 1,003 SF 6 10+ years Lighting - Pendent/Surface Basement 1,003 SF 6 10+ years Lighting - Pendent/Surface Basement 1,003 SF 6 10+ years Lighting - Pendent/Surface Basement 1,105 SF 6 10+ years Lighting - Pendent/Surface Basement 1,155 SF 6 10+ years Walfs - Plaster/Dywall Basement 1,155 SF 6 10+ years Work Sink Basement 1,155 SF 6 10+ years Work Sink Basement 1,155 SF 6 10+ years  Classroom #101 (Art Room)  AC Units 1st Floor 1 EA 7 6-10 years Casework 1st Floor 1 BA 6 10+ years Casework 1st Floor 1 EA 7 6-10 years Casework 1 St Floor 1 EA 7 6-10 years Casework 1 St Floor 1 EA 7 6-10 years Casework 1 St Floor 1 EA 7 6-10 years Casework 1 St Floor 1 EA 7 6-10 years Casework 1 St Floor 1 EA 7 6-10 years Casework 1 St Floor 1 EA 7 6-10 years Casework 1 St Floor 1 St Floor 1 St Floor 1 St Fl		Work Sink	Basement	1	EA	7		
AC Units Celling - Splined Basement 1,003 SF 6 10+ years Floor - Tile Basement 1,003 SF 6 10+ years Lighting - Pendent/Surface Basement 1,003 SF 6 10+ years Lighting - Pendent/Surface Basement 1,003 SF 6 10+ years Lighting - Pendent/Surface Basement 1,105 SF 6 10+ years Lighting - Pendent/Surface Basement 1,155 SF 6 10+ years Walfs - Plaster/Dywall Basement 1,155 SF 6 10+ years Work Sink Basement 1,155 SF 6 10+ years Work Sink Basement 1,155 SF 6 10+ years  Classroom #101 (Art Room)  AC Units 1st Floor 1 EA 7 6-10 years Casework 1st Floor 1 BA 6 10+ years Casework 1st Floor 1 EA 7 6-10 years Casework 1 St Floor 1 EA 7 6-10 years Casework 1 St Floor 1 EA 7 6-10 years Casework 1 St Floor 1 EA 7 6-10 years Casework 1 St Floor 1 EA 7 6-10 years Casework 1 St Floor 1 EA 7 6-10 years Casework 1 St Floor 1 EA 7 6-10 years Casework 1 St Floor 1 St Floor 1 St Floor 1 St Fl	Classroo	om #007 (Science Lab Level 1)						
Calling - Splined   Basement   1,003   SF   6   10+ years   Floor - Tile   Basement   1,003   SF   6   10+ years   Floor - Tile   Floor - Tile   1   EA   7   6-10   years   Floor - Tile   1   EA   7   6-10   years   Floor - Tile   1   EA   7   10+ years   Floor - Tile   EA   7   10+ years   Floor   Tile   Floo			Basement	1	FA	7	6-10 years	
Floor - Tile   Basement   1,003   SF   6   10+ ýears								
Lighting - Pendent/Surface   Basement   8								
Lighting - Pendent/Surface   Basement   1				•		-		
Marker Board         Basement         10         LF         6         6-10 years           Walls - Plaster/Drywall         Basement         1,155         \$5         6         10 - years           Work Sink         Basement         3         EA         7         10 + years           Curis         1st Floor         1         EA         7         6 -10 years           Casework         1st Floor         18         LF         6         10 + years           Ceiling - Splined         1st Floor         753         SF         6         10 + years           Doors - Transom Window         1st Floor         9         SF         6         10 + years           Doors - Wood Doors inclu hw         1st Floor         1         EA         6         10 + years           Floor - Tile         1st Floor         753         SF         6         10 + years           Floor - Tile         1st Floor         753         SF         6         10 + years           Lighting - Pendent/Surface         1st Floor         14         EA         6         6-10 years           Storage/ Closet         1st Floor         15         LF         6         6-10 years           Storage/ Closet								
Walls - Plaster/Drywall   Basement   1,155   SF   6   10+ years				•		-		
Classroom #101 (Art Room)								
AC Units								
AC Units	01						, , , , , ,	
Casework Ceiling - Splined         1st Floor         18 1st Floor         LF 753 753 756 753 756 753 756 753 756 753 756 753 756 753 756 753 756 753 756 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 753 757 757	Classroc							
Ceiling - Splined								
Doors - Transom Window								
Doors - Wood Doors inclu hw							•	
Floor - Tile							•	
Kiln								
Lighting - Pendent/Surface       1st Floor       14 EA 6 6-10 years         Marker Board       1st Floor       15 LF 6 6-10 years         Storage/ Closet       1st Floor       128 SF 7 10+ years         Walls - Plaster/Drywall       1st Floor       976 SF 6 10+ years         Classroom#102 (Regular Classroom)         AC Units       1st Floor       1 EA 7 6-10 years         Casework       1st Floor       4 LF 6 10+ years         Ceiling - Splined       1st Floor       743 SF 6 10+ years         Ceiling - Splined       1st Floor       10 SF 5 1-2 years       Damaged tiles         Doors - Transom Window       1st Floor       18 SF 6 10+ years       Damaged tiles         Doors - Wood Doors inclu hw       1st Floor       2 EA 6 10+ years       10+ years         Floor - Tile       1st Floor       753 SF 6 10+ years         Lighting - Pendent/Surface       1st Floor       40 LF 6 6-10 years         Marker Board       1st Floor       967 SF 6 10+ years								
Marker Board   1st Floor   15						-		
Storage/ Closet   1st Floor   128   SF   7   10+ years   10+ yea		Lighting - Pendent/Surface				_		
Walls - Plaster/Drywall       1st Floor       976       SF       6       10+ years         Classroom #102 (Regular Classroom)       AC Units       1st Floor       1 EA 7 6-10 years         Casework       1st Floor       4 LF 6 10+ years         Ceiling - Splined       1st Floor       743 SF 6 10+ years         Ceiling - Splined       1st Floor       10 SF 5 1-2 years Damaged tiles         Doors - Transom Window       1st Floor       18 SF 6 10+ years         Doors - Wood Doors inclu hw       1st Floor       2 EA 6 10+ years         Floor - Tile       1st Floor       753 SF 6 10+ years         Lighting - Pendent/Surface       1st Floor       14 EA 7 6-10 years         Marker Board       1st Floor       40 LF 6 6-10 years         Walls - Plaster/Drywall       1st Floor       967 SF 6 10+ years				_		-		
AC Units			1st Floor			7		
AC Units       1st Floor       1 EA 7 6-10 years         Casework       1st Floor       4 LF 6 10+ years         Ceiling - Splined       1st Floor       743 SF 6 10+ years         Ceiling - Splined       1st Floor       10 SF 5 1-2 years Damaged tiles         Doors - Transom Window       1st Floor       18 SF 6 10+ years         Doors - Wood Doors inclu hw       1st Floor       2 EA 6 10+ years         Floor - Tile       1st Floor       753 SF 6 10+ years         Lighting - Pendent/Surface       1st Floor       14 EA 7 6-10 years         Marker Board       1st Floor       40 LF 6 6-10 years         Walls - Plaster/Drywall       1st Floor       967 SF 6 10+ years		Walls - Plaster/Drywall	1st Floor	976	SF	6	10+ years	
Casework Ceiling - Splined Spl	Classroo	om #102 (Regular Classroom)						
Casework Ceiling - Splined Spl		AC Units		1		7	6-10 years	
Ceiling - Splined1st Floor743SF610+ yearsCeiling - Splined1st Floor10SF51-2 yearsDamaged tilesDoors - Transom Window1st Floor18SF610+ yearsDoors - Wood Doors inclu hw1st Floor2EA610+ yearsFloor - Tile1st Floor753SF610+ yearsLighting - Pendent/Surface1st Floor14EA76-10 yearsMarker Board1st Floor40LF66-10 yearsWalls - Plaster/Drywall1st Floor967SF610+ years			1st Floor	4				
Ceiling - Splined1st Floor10SF51-2 yearsDamaged tilesDoors - Transom Window1st Floor18SF610+ yearsDoors - Wood Doors inclu hw1st Floor2EA610+ yearsFloor - Tile1st Floor753SF610+ yearsLighting - Pendent/Surface1st Floor14EA76-10 yearsMarker Board1st Floor40LF66-10 yearsWalls - Plaster/Drywall1st Floor967SF610+ years		Ceiling - Splined	1st Floor	743		6		
Doors - Transom Window1st Floor18SF610+ yearsDoors - Wood Doors inclu hw1st Floor2EA610+ yearsFloor - Tile1st Floor753SF610+ yearsLighting - Pendent/Surface1st Floor14EA76-10 yearsMarker Board1st Floor40LF66-10 yearsWalls - Plaster/Drywall1st Floor967SF610+ years			1st Floor	10			•	Damaged tiles
Doors - Wood Doors inclu hw1st Floor2EA610+ yearsFloor - Tile1st Floor753SF610+ yearsLighting - Pendent/Surface1st Floor14EA76-10 yearsMarker Board1st Floor40LF66-10 yearsWalls - Plaster/Drywall1st Floor967SF610+ years			1st Floor	18	SF	6	10+ years	-
Floor - Tile 1st Floor 753 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 14 EA 7 6-10 years Marker Board 1st Floor 40 LF 6 6-10 years Walls - Plaster/Drywall 1st Floor 967 SF 6 10+ years		Doors - Wood Doors inclu hw	1st Floor	2	EA	6	•	
Lighting - Pendent/Surface1st Floor14 EA 7 6-10 yearsMarker Board1st Floor40 LF 6 6-10 yearsWalls - Plaster/Drywall1st Floor967 SF 6 10+ years		Floor - Tile	1st Floor	753	SF	6		
Marker Board 1st Floor 40 LF 6 6-10 years Walls - Plaster/Drywall 1st Floor 967 SF 6 10+ years		Lighting - Pendent/Surface		14		7		
Walls - Plaster/Drywall 1st Floor 967 SF 6 10+ years					LF	6		
Classroom #103 (Regular Classroom)								
	Classroo	om #103 (Regular Classroom)						



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Splined	1st Floor	820	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	820	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EΑ	6	6-10 years	
	Marker Board	1st Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,068	SF	6	10+ years	
Classroo	om #104 (Computer Lab)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	42	LF	6	10+ years	
	Ceiling - Splined	1st Floor	820	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	820	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	937	SF	6	10+ years	
	Wallo T lastel/Bry Wall	1001	001	O.	Ū	101 youro	
Classroo	om #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Splined	1st Floor	820	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	820	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EΑ	6	6-10 years	
	Marker Board	1st Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,039	SF	6	10+ years	
Classroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	4	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	759	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	759	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	SF EA		-	
	Marker Board	1st Floor	20	LF	7 7	6-10 years 6-10 years	
	WALKEL BOSTO	ISLEIOOF	20	ı F	/	n= III VAAIS	



Catego	ory : Classroom		В	uilding	: Main		•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	892	SF	6	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	751	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	751	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	975	SF	6	10+ years	
_Classroo	om #202 (Computer Lab)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	769	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	769	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	6-10 years	
	Marker Board	2nd Floor	50	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	977	SF	6	10+ years	
	Wireless System	2nd Floor	1	ĒΑ	7	6-10 years	
_Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	834	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	834	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,072	SF	6	10+ years	
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	834	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	834	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	6	6-10 years	
	- <del>-</del>					•	



Catego	ry : Classroom		В	uilding	: Main		
<b>0</b>	Na T	Lagation	0		D I-	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,102	SF	6	10+ years	
Classroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	834	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	834	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,072	SF	6	10+ years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	759	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	759	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	926	SF	6	10+ years	
Classroo	om #208 (Science Lab Level 1)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	80	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	837	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	837	SF	6	10+ years	
	Gas Line	2nd Floor	8	ĒΑ	7	10+ years	
	Lighting - Lay-in	2nd Floor	2	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	6	6-10 years	
	Science Lab Elements	2nd Floor	837	SF	7	10+ years	
	Science Lab Fume Hood	2nd Floor	1	EA	7	10+ years	
	Science Lab Shower	2nd Floor	1	EΑ	7	10+ years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,264	SF	6	10+ years	
	Work Sink	2nd Floor	8	EA	7	10+ years	



y : Classroom		ь	uilding	. walli		
					Docommond	
Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
AC Units	3rd Floor	Quantity 1	EA	7	6-10 years	Comments
Casework	3rd Floor	4	LF	6	10+ years	
					•	
		_		-	•	
		_			•	
		•				
		_				
					-	
Walls - Plaster/Drywall	3rd Floor	1,298	SF	6	10+ years	
m #307 (Regular Classroom)						
AC Units	3rd Floor	1	EΑ	7	6-10 years	
Casework	3rd Floor	4	LF	6	10+ years	
		776				
		1			•	
		1			•	
		776			•	
					,	
Walls - Plaster/Drywall	3rd Floor	1,319	SF	6	10+ years	
m #308 (Regular Classroom)						
	3rd Floor	1	FΔ	7	6-10 years	
		· •				
					-	
					•	
		-			•	
					•	
					•	
				_		
walls - Plaster/Drywall	31a F1001	1,319	SF	б	10+ years	
y : Interior		В	uilding	: Main	D	
Item - Type	Location	Quantity	HOM	Rank		Comments
item - Type	Location	Quantity		IVALIA	Replacement	Comments
Ceiling - Plaster/Drywall	1st Floor	2,041	SF	6	10+ years	
		1			-	
Floor - Tile/Sheet		2.041			•	
					•	
					-	
	Ceiling - Splined Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall  m #307 (Regular Classroom)  AC Units Casework Ceiling - Splined Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall  m #308 (Regular Classroom)  AC Units Casework Ceiling - Splined Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall  y: Interior  Item - Type  Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain	Ceiling - Splined 3rd Floor Doors - Transom Window 3rd Floor Doors - Wood Doors inclu hw 3rd Floor Floor - Tile 3rd Floor Surface 3rd Floor Marker Board 3rd Floor Casework 3rd Floor Casework 3rd Floor Casework 3rd Floor Marker Board 3rd Floor Doors - Transom Window 3rd Floor Doors - Wood Doors inclu hw 3rd Floor Floor - Tile 3rd Floor Marker Board 3rd Floor Marker	Ceiling - Splined         3rd Floor         776           Doors - Transom Window         3rd Floor         9           Doors - Wood Doors inclu hw         3rd Floor         1           Floor - Tile         3rd Floor         776           Lighting - Pendent/Surface         3rd Floor         30           Walls - Plaster/Drywall         3rd Floor         30           Walls - Plaster/Drywall         3rd Floor         1,298           m #307 (Regular Classroom)         1         2           AC Units         3rd Floor         1           Casework         3rd Floor         4           Ceiling - Splined         3rd Floor         76           Doors - Transom Window         3rd Floor         1           Doors - Wood Doors inclu hw         3rd Floor         1           Floor - Tile         3rd Floor         7           Lighting - Pendent/Surface         3rd Floor         7           Marker Board         3rd Floor         30           Walls - Plaster/Drywall         3rd Floor         1           AC Units         3rd Floor         1           Casework         3rd Floor         7           AC Borts         3rd Floor         7           Ceil	Ceiling - Splined         3rd Floor         776         SF           Doors - Transom Window         3rd Floor         9         SF           Doors - Wood Doors inclu hw         3rd Floor         1         EA           Floor - Tile         3rd Floor         14         EA           Marker Board         3rd Floor         14         EA           Walls - Plaster/Drywall         3rd Floor         30         LF           Walls - Plaster/Drywall         3rd Floor         1         EA           AC Units         3rd Floor         4         LF           Celing - Splined         3rd Floor         4         LF           Celing - Splined         3rd Floor         776         SF           Doors - Transom Window         3rd Floor         1         EA           Doors - Wood Doors inclu hw         3rd Floor         1         EA           Floor - Tile         3rd Floor         776         SF           Lighting - Pendent/Surface         3rd Floor         776         SF           Walls - Plaster/Drywall         3rd Floor         1         EA           Walls - Plaster/Drywall         3rd Floor         1         EA           Ceiling - Splined         3rd Floor	Ceiling - Splined         3rd Floor         776         SF         6           Doors - Transom Window         3rd Floor         9         SF         7           Doors - Wood Doors inclu hw         3rd Floor         76         SF         6           Floor - Tile         3rd Floor         776         SF         6           Lighting - Pendent/Surface         3rd Floor         30         LF         7           Marker Board         3rd Floor         30         LF         7           Walls - Plaster/Drywall         3rd Floor         30         LF         7           Walls - Plaster/Drywall         3rd Floor         30         LF         7           Walls - Plaster/Drywall         3rd Floor         1         EA         7           Casework         3rd Floor         76         SF         6           Ceiling - Splined         3rd Floor         776         SF         6           Doors - Transom Window         3rd Floor         76         SF         7           Doors - Transom Window         3rd Floor         7         EA         7           Walls - Plaster/Drywall         3rd Floor         1         EA         7           Casework <td< td=""><td>Ceiling - Splined         3rd Floor         776         SF         6         10+ years           Doors - Transom Window         3rd Floor         1         EA         6         10+ years           Doors - Wood Doors inclu hw         3rd Floor         1         EA         6         10+ years           Floor - Tile         3rd Floor         14         EA         7         6-10 years           Marker Board         3rd Floor         3.0         LF         7         6-10 years           Malls - Plaster/Drywall         3rd Floor         1,298         SF         6         10+ years           Malls - Plaster/Drywall         3rd Floor         1         EA         7         6-10 years           AC Units         3rd Floor         4         LF         6         10+ years           Casework         3rd Floor         76         SF         6         10+ years           Ceiling - Splined         3rd Floor         776         SF         6         10+ years           Ceiling - Splined         3rd Floor         776         SF         6         10+ years           Leiling - Splined         3rd Floor         76         SF         6         10+ years           Lighting - Pe</td></td<>	Ceiling - Splined         3rd Floor         776         SF         6         10+ years           Doors - Transom Window         3rd Floor         1         EA         6         10+ years           Doors - Wood Doors inclu hw         3rd Floor         1         EA         6         10+ years           Floor - Tile         3rd Floor         14         EA         7         6-10 years           Marker Board         3rd Floor         3.0         LF         7         6-10 years           Malls - Plaster/Drywall         3rd Floor         1,298         SF         6         10+ years           Malls - Plaster/Drywall         3rd Floor         1         EA         7         6-10 years           AC Units         3rd Floor         4         LF         6         10+ years           Casework         3rd Floor         76         SF         6         10+ years           Ceiling - Splined         3rd Floor         776         SF         6         10+ years           Ceiling - Splined         3rd Floor         776         SF         6         10+ years           Leiling - Splined         3rd Floor         76         SF         6         10+ years           Lighting - Pe



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	1,926	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,922	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	4	SF	4	1-2 years	Broken tiles
	Lighting - Pendent/Surface	2nd Floor	27	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	9	EA	7	10+ years	
	Student Lockers - Two Tiers	2nd Floor	73	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,173	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor North Corridor	756	SF	6	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor North Corridor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor North Corridor	756	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor North Corridor	9	EA	6	6-10 years	
	Student Lockers - One Tier	3rd Floor North Corridor	14	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor North Corridor	771	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor South Corridor	602	SF	6	10+ years	
	Floor - Tile/Sheet	3rd Floor South Corridor	602	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor South Corridor	7	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor South Corridor	737	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	2,303	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	8	ĒΑ	6	10+ years	
	Doors - Transom Window	Basement	72	SF	6	10+ years	
	Drinking Fountains - Double Fountain	Basement	1	ĒΑ	7	10+ years	
	Floor - Tile/Sheet	Basement	2,143	SF	7	10+ years	
	Floor - Wood	Basement	160	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	18	ĒΑ	6	6-10 years	
	Student Lockers - One Tier	Basement	16	ΕA	7	10+ years	
	Walls - Masonry	Basement	1,544	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	1,899	SF	6	10+ years	
		2400	.,000	О.	· ·	.o. youro	
Safety							
Galety	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	14	EA	7	6-10 years	
	Security Cameras	13(1100)	17	LA	,	0-10 years	
Stairs							
Otalis	Ceiling - Plaster/Drywall	North	467	SF	6	10+ years	
	Floor - Tile	North	467	SF	6	10+ years	
	Handrails	North	170	LF	7	10+ years	
	Lighting - Pendent/Surface	North	4	EA	7	6-10 years	
	Stairs - Rubber	North	519	LF	6	10+ years	
	Walls - Plaster/Drywall	North	3,136	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	467	SF	6	10+ years	
	Floor - Tile	South	467	SF	6	10+ years	
	Handrails	South	170	LF	7	10+ years	
		South	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	Jouin	4	EA	U	o-10 years	



Catego	ry : Interior	В	uilding	: Main				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	Stairs - Rubber Walls - Plaster/Drywall	South South	519 3,136	LF SF	6 6	10+ years 10+ years		
Vertical	Conveyance							
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years		

Campus Name: Alcott HS Page : 22 of 25 Assessment Date: 05/03/2022



Category: Site **Building: Site** 

Category : Site			B	ullaing	. Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	4	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	9	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	1	ĒΑ	5	2-5 years	
					_	, , , , , ,	
Fencing							
- <del> </del>	Fencing - Chain Link	Entire Site	200	LF	6	10+ years	Quantity Adjusted
	Fencing - Chain Link	Entire Site	32	LF	5	2-5 years	Mangled/Bent/Leaning gate
	Fencing - Guard Rail	Entire Site	85	LF	6	10+ years	3 3 4 4 4 4 4 9 3 4 4 4
	Fencing - New Standard Ornamental	Entire Site	235	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	5	LF	5	2-5 years	Rust/Bent and mangled sections
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	98	LF	6	10+ years	
						, , , , , , , , , , , , , , , , , , , ,	
Landscar	oe						
	Benches	Entire Site	2	EA	6	10+ years	
	Landscape - Grass	Entire Site	1,573	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	600	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	3,055	SF	5	2-5 years	Broken/Cracked/Displacement -
	·		·			•	Heave and settlement
	Parkway trees	Entire Site	16	EA	6	10+ years	Rank suspect as tree's roots are
	·					•	causing damage to perimeter
							Sidewalks in various locations. Item
							addressed in "perimeter Sidewalks"
	Parkway trees	Entire Site	1	EA	4	1-2 years	Missing Tree
	Planting Beds/ Area	Entire Site	584	SF	6	6-10 years	· ·
	Trash Receptacles	Entire Site	2	EA	5	10+ years	W/3 additional garbage
	·					•	cans/containers
Parking L		•					
	Surface - Asphalt	South	14,500	SF	5	2-5 years	Quantity Adjusted
	Surface - Asphalt	South	9,551	SF	4	1-2 years	Potholes/Holes/Alligator
							cracking/material decomposition with
							remains from removed steel post
							and/or concrete postholes
	Trash Enclosure - Chain Links	South	1,512	SF	5	10+ years	Missing screening slats/gate leaning
Sidewalk		<b>-</b> •					
	Sidewalks - Perimeter Sidewalks	Entire Site	8,106	SF	6	10+ years	0 1:
	Sidewalks - Perimeter Sidewalks	Entire Site	500	SF	5	1-2 years	Cracking
Signage							




Category : Site			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter	Entire Site	1	EA	7	10+ years	
	Sign					•	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

Campus Name: Alcott HS Page: 24 of 25 Assessment Date: 05/03/2022

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





**Classroom Summary** 

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main			•				•		
Art Room	Kindergarten	1st Floor	101	101	753	120	60	Y	N
Computer Lab	Regular Classroom	1st Floor	104	104	820	85	45	Υ	N
Computer Lab	Regular Classroom	2nd Floor	202	202	769	100	50	Υ	N
Music Room	Play Room	Basement	001	Boys Play Room	1,161	40	20	Y	N
Regular Classroom	Regular Classroom	1st Floor	102	102	753	75	35	Υ	N
Regular Classroom	Regular Classroom	1st Floor	103	103	820	100	50	Υ	N
Regular Classroom	Regular Classroom	1st Floor	106	106	820	85	40	Υ	N
Regular Classroom	Regular Classroom	1st Floor	108	108	759	120	60	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	751	140	70	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	834	100	50	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	834	100	50	Υ	Ν
Regular Classroom	Regular Classroom	2nd Floor	206	206	834	100	50	Υ	Ν
Regular Classroom	Regular Classroom	2nd Floor	207	207	759	90	60	Υ	Ν
Regular Classroom	Regular Classroom	3rd Floor	302	302	776	100	50	Υ	Ν
Regular Classroom	Regular Classroom	3rd Floor	307	307	776	90	35	Υ	Ν
Regular Classroom	Regular Classroom	3rd Floor	308	308	776	10	50	Y	N
Science Lab Level 1	Library	Basement	007	Library	1,050	70	35	Y	N
Science Lab Level 1	Science Classroom	2nd Floor	208	208	837	140	70	Y	N