

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1927	2	64,300
Annex	1996	1	14,400
Campus Total			78,700

Catego	Category : Exterior Building :						
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Cell Equ	ipment						
	Cell Equipment - Antenna	Main Roof - Boiler Room	1	EA	7	10+ years	
	Cell Equipment - Cabinets	Main Roof - Boiler Room	1	EA	7	10+ years	
Entrance	2						
	Entrance Control - Audio and Video	#1	1	EA	7	6-10 years	Being installed
	Exterior Doors - Exterior Steel Door	#1	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#1	130	LF	6	10+ years	
	Power Door Operator and Controls	#1	2	EA	7	10+ years	
	Ramps - Concrete	#1	115	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1	41	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#10 (2nd FI Fire Escape)	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#10 (2nd Fl Fire Escape)	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	<pre>#11 (2nd Flr Fire Escape)</pre>	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	<pre>#11 (2nd Flr Fire Escape)</pre>	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#12	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	#12	1	EA	6	10+ years	Not previously assessed
	Exterior Doors - Exterior Wood Door	#13	1	EA	7	10+ years	Replaced
	Exterior Stairs - Stone	#13	1	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#2	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#2	20	LF	7	10+ years	Repaired
	Exterior Stairs - Concrete	#2	40	LF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Stairs - Stone	#2	80	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#3	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3	1	EA	6	10+ years	
	Exterior Stairs - Steel or Aluminum	#3	15	LF	5	10+ years	
	Stair Handrail - Steel_Stair Handrail	#3	12	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#4	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4	1	EA	6	10+ years	
	Exterior Stairs - Stone	#4	14	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5	1	EA	6	10+ years	
	Exterior Stairs - Stone	#5	14	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#6	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6	1	EA	6	10+ years	
	Ramp Handrail - Wood_Ramp Handrail	#6	65	LF	6	6-10 years	
	Ramps - Wood Ramp	#6	30	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#7	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7	- 1	EA	6	10+ years	
	Exterior Stairs - Concrete	#7	60	LF	6	10+ years	
	Exterior Stairs - Stone	#7	65	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#8	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#8	45	LF	6	10+ years	
	Exterior Stairs - Stone	#8	76	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#8	36	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#9	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#9 #9	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#9 #9	20	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail			LF	6	,	
		#9	12	LF	0	10+ years	
ire Esc	1						
	Fire Escape	Entire Building	40	LF	6	10+ years	
	Fire Escape	Entire Building	50	LF	6	10+ years	
oundati	on						
	Foundation - Concrete	Entire Building	1,153	LF	7	10+ years	
	Foundation - Concrete	Entire Building	250	LF	5	2-5 years	Seepage and spalling in tunnel
	Superstructure - Concrete	Entire Building	64,300	SF	6	10+ years	
		..	,		-	· · · · · ·	
ighting	Exterior Linkting Devenet on Development	Entire Duilding	47			C 40 years	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	17	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	6	6-10 years	



Category : Exterior Building : Main Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Access Ladder - Metal Roof #1 ΕA 10+ vears 4 7 Access Ladder - Wood ΕA 2-5 years Roof #1 4 5 Coping - Terra Cotta Roof #1 1.103 LF 6 10+ years Corrected material and rating LF 6 **Downspouts - Exterior Downspouts** Roof #1 65 6-10 years LF **Downspouts** - Interior Downspouts Roof #1 225 6 6-10 years LF Parapet - 16" - 30" Height Roof #1 903 6 10+ years Reassessed condition Parapet - Parapet > 30" Roof #1 200 LF 6 10+ years Reassessed condition SF Roof - Asphalt Shingle Roof #1 1.260 6 6-10 years Roof - Modified Bitumen Roof #1 27.510 SF 4 1-2 years Soft spots throughout, active leaks Roof Hatch - Metal Roof #1 ΕA 5 2-5 years 4 Roof Structure - Concrete Roof #1 27.510 SF 7 10+ vears Access Ladder - Metal Roof #2 EΑ 7 10+ years Corrected rating 1 Roof #2 ΕA Access Ladder - Metal 1 4 1-2 years Staple design, step ladder improve front LF Chimney - Brick Chimney- Concrete/ Mortar Roof #2 90 6 10+ years Liner LF Coping - Terra Cotta Roof #2 210 6 10+ years LF **Downspouts - Interior Downspouts** Roof #2 20 6 10+ years Parapet - 16" - 30" Height LF Roof #2 210 6 10+ vears Roof - Modified Bitumen Roof #2 2,766 SF 5 6-10 years Roof Hatch - Metal Roof #2 ΕA 5 6-10 years 1 SF Roof Structure - Steel / Metal Deck/ Roof #2 2,766 7 10+ years Concrete Topping Walls Cheek-Wall - Concrete 104 SF 6 Entire Building 10+ years LF Cornice - Terra Cotta Entire Building 1,118 6 10+ years SF Exterior Walls - Brick Entire Building 38,500 6 10+ years Windows 1,920 SF Guard - Guards wire guard Entire Building 6 10+ years LF Lintels - Steel Entire Building 30 6 10+ years Entire Building 370 LF 6 Lintels - Terra Cotta 10+ years Windows - Louver Entire Building 6 SF 6 10+ years Windows - Sash Aluminum Double-pane Entire Building 7.700 SF 6 10+ years **Category : Electrical Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Emergency System FΑ **Emergency Battery Packs - Auditoium and** 1st Floor 2 6 2-5 years Aisle Lighting **Emergency Battery Packs - Corridors and** 1st Floor 6 ΕA 6 2-5 years



2828 N Kilbourn AVENUE, Chicago, IL 60641 **Building : Main Category : Electrical** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Stairs Automatic Transfer Switch ΕA Electrical Room 6 6-10 vears 1 Serves main building Emergency A/C Power - Auditoium and Entire Building 2.800 SF 6 6-10 years Aisle Lighting Emergency A/C Power - Corridors and Entire Building 12,150 SF 6 6-10 years Stairs Emergency A/C Power - Gym SF 6 6-10 years Entire Building 1,150 SF Emergency A/C Power - Lunchrooms Entire Building 3.040 6 6-10 years Exit Signs - Auditoium Entire Building 6 ΕA 2 0-1 year No battery backup 2 Exit Signs - Corridors and Stairs Entire Building 20 ΕA 0-1 year No battery backup Exit Sians - Gvm Entire Building 2 ΕA 2 0-1 vear No battery backup Exit Signs - Lunchroom Entire Building 4 ΕA 2 0-1 year No battery backup Security System - CCTV Entire Building 64,300 SF 5 2-5 years A few cameras need repair SF 5 Security System - Intrusion Detection Entire Building 64,300 6-10 years Main Service ΕA Main Electrical Service - 1200 A Electrical Room 1 6 10+ years Serves main building 120/208/3PH Independent Electrical Service for Electrical Room 1 ΕA 6 6-10 years Serves main building emergency power PA System Entire Building 64.300 SF 5 1-2 years Serves main and annex building. Older system. Power Distribution Lighting and Power Panels - 100 A Entire Building 8 EΑ 6 6-10 years Lighting and Power Panels - 100 A 1 ΕA 2 0-1 vear Entire Building Live Lighting and Power Panels - Above 100 A Entire Building 3 ΕA 6 6-10 years ΕA 6 6-10 vears Lighting and Power Panels - Above 100 A Entire Building 1 Main Distribution Panels - 400 - 600 amp Entire Building 4 FΑ 6 6-10 years Missing smalll internal cover Main Distribution Panels - Greater than 600 Entire Building 1 FΑ 6 10+ years amp

Category : Fire Protection	egory : Fire Protection Building : Main					
Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alarm						
Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Serves main building
Fire Alarm Strobe Lights	Entire Building	64,300	SF	6	6-10 years	Ū.
Fire Alarm_System	Entire Building	64,300	SF	6	6-10 years	Serves main building



John Barry Elementary School 2828 N Kilbourn AVENUE, Chicago, IL 60641

Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	lling Systems						
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm	Mechanical Room	1	EA	4	1-2 years	Serves auditorium, noisy, near end of life
	Air Intake	Mechanical Room	1	EA	5	6-10 years	
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm	Mechanical Room	1	EA	4	1-2 years	Serves gym, noisy
	Air Intake	Mechanical Room	1	EA	4	0-1 year	Rusted.
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	2-5 years	
	Air Intake	Mechanical Room	1	EA	5	2-5 years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	7	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	6-10 years	
	Zone Dampers	Mechanical Room	18	EA	6	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	2-5 years	
	Air Intake	Mechanical Room	1	EA	5	2-5 years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	5	2-5 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	6	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	6-10 years	
	Zone Dampers	Mechanical Room	15	EA	5	10+ years	
Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	5	2-5 years	
	Chemical Feed System	Boiler Room	1	EA	5	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	Dual pump, 1 well
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	5	2-5 years	Serves main building
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	6	10+ years	•••
	Steam Traps	Boiler Room	70	EA	4	1-2 years	Many steam traps leak
Gas Boo	oster						
	Gas Booster	Boiler Room	2	EA	6	6-10 years	



John Barry Elementary School 2828 N Kilbourn AVENUE, Chicago, IL 60641

Catego	ry : Mechanical		В	: Main			
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
- leating	Devices					-	
	Unit Heater - Steam	Boiler Room	1	EA	5	6-10 years	
	Radiators - Steam	Entire Building	33	EA	5	2-5 years	
	Wall Heater - Electric	Entire Building	12	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	4	EA	5	6-10 years	
	Fin Tube - Steam	Entire Building	40	LF	6	6-10 years	
Temper:	ature Control						
<u> </u>	Electric Thermostat	Entire Building	2	EA	5	6-10 years	
	Pneumatic System	Entire Building	16	SF	5	2-5 years	Mostly manually controlled
	Thermostats - Pneumatic	Entire Building	15	ĒA	5	6-10 years	
	Thermostats - Pneumatic	Entire Building	16	EA	5	2-5 years	
Ventilati	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	3	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	5	2-5 years	
	CFM	3			-	· · · · ·	
		Fusting Duritations	1	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	L/	Ũ	2 0 youro	
Cotogo	CFM	Entire Building				2 0 90010	
Catego		Entire Building		uilding			
	CFM ry : Plumbing	J	В	uilding	: Main	Recommend	Comments
Group	CFM ry : Plumbing Item - Type	Location					Comments
Group	CFM ry : Plumbing Item - Type er	Location	B Quantity	uilding UOM	: Main Rank	Recommend Replacement	
Group	CFM ry : Plumbing Item - Type	J	В	uilding	: Main	Recommend	
Group Hot Wat	CFM ry : Plumbing Item - Type er Gas Heater - Less than 150000 BTU/HR	Location Boiler Room	B Quantity	uilding UOM EA	: Main Rank 4	Recommend Replacement	Serves main building. Unit is older
Group Hot Wat	CFM ry : Plumbing Item - Type er Gas Heater - Less than 150000 BTU/HR Domestic Piping-Hot Water Return Lines	Location Boiler Room Entire Building	B Quantity 1 64,300	uilding UOM EA SF	: Main Rank	Recommend Replacement 1-2 years 10+ years	Serves main building. Unit is older
Group Hot Wat	CFM ry : Plumbing Item - Type er Gas Heater - Less than 150000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers	Location Boiler Room	B Quantity 1	uilding UOM EA	: Main Rank 4	Recommend Replacement	Serves main building. Unit is older
Group Hot Wat	CFM ry : Plumbing Item - Type er Gas Heater - Less than 150000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to	Location Boiler Room Entire Building	B Quantity 1 64,300	uilding UOM EA SF	: Main Rank 4	Recommend Replacement 1-2 years 10+ years	Serves main building. Unit is older
Group Hot Wat	CFM ry : Plumbing Item - Type er Gas Heater - Less than 150000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply	Location Boiler Room Entire Building Entire Building	B Quantity 1 64,300 64,300	UOM EA SF SF	: Main Rank 4 6 6	Recommend Replacement 1-2 years 10+ years 10+ years	Serves main building. Unit is older
	CFM ry : Plumbing Item - Type er Gas Heater - Less than 150000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water Return Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply	Location Boiler Room Entire Building Entire Building Entire Building Entire Building	B Quantity 1 64,300 64,300 64,300	UOM EA SF SF SF	: Main Rank 4 6 6 6 6	Recommend Replacement 1-2 years 10+ years 10+ years 10+ years	Serves main building. Unit is older
Group Hot Wat	CFM ry : Plumbing Item - Type er Gas Heater - Less than 150000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply	Location Boiler Room Entire Building Entire Building Entire Building Entire Building Entire Building	B Quantity 1 64,300 64,300 64,300 64,300	UOM EA SF SF SF SF	: Main Rank 4 6 6 6 6	Recommend Replacement 1-2 years 10+ years 10+ years 10+ years 10+ years	Serves main building. Unit is older
Group Hot Wat	CFM ry : Plumbing Item - Type er Gas Heater - Less than 150000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers)	Location Boiler Room Entire Building	B Quantity 1 64,300 64,300 64,300 64,300 64,300	UOM EA SF SF SF SF SF SF	: Main Rank 4 6 6 6 6 6	Recommend Replacement 1-2 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Serves main building. Unit is older than 15 years old.
Group Hot Wat	CFM ry : Plumbing Item - Type er Gas Heater - Less than 150000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping	Location Boiler Room Entire Building Entire Building	B Quantity 1 64,300 64,300 64,300 64,300 64,300 64,300	UOM EA SF SF SF SF SF SF SF SF	: Main Rank 4 6 6 6 6 6 6 6	Recommend Replacement 1-2 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 0-1 year	Serves main building. Unit is older than 15 years old.
Group Hot Wat	CFM ry : Plumbing Item - Type er Gas Heater - Less than 150000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Location Boiler Room Entire Building Entire Building	B Quantity 1 64,300 64,300 64,300 64,300 64,300 64,300	UOM EA SF SF SF SF SF SF SF SF	: Main Rank 4 6 6 6 6 6 6 6	Recommend Replacement 1-2 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Serves main building. Unit is older than 15 years old.



John Barry Elementary School 2828 N Kilbourn AVENUE, Chicago, IL 60641

Catego	Category : Plumbing		Building : Main			2828 N KIIDOUTH AVENUE, Chicago, il 60641		
Juicgo	.,			anang	. man	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Pumps								
<u> </u>	Pumps - Ejector-Duplex	Basement	1	EA	5	2-5 years	Dual pump	
		Datement	·	_/ (Ũ	2 0 90010		
Catego	ry : Room		В	uilding	: Main			
Ŭ	•			Ŭ		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Administ	rative Suites/Offices							
	AC Unit	1st Floor inside boiler room	1	EA	7	6-10 years		
		engineers office						
	Ceiling - Plaster/Drywall	1st Floor inside boiler room	129	SF	7	10+ years		
		engineers office						
	Doors - Wood Doors inclu hw	1st Floor inside boiler room	1	EA	7	6-10 years		
		engineers office	100	05	0	40		
	Floor - Tile	1st Floor inside boiler room	129	SF	6	10+ years		
	Lighting Pondont/Surface	engineers office 1st Floor inside boiler room	2	EA	5	1.2 voors	Missing covor	
	Lighting - Pendent/Surface	engineers office	2	EA	5	1-2 years	Missing cover.	
	Power Distribution	1st Floor inside boiler room	6	EA	7	6-10 years		
		engineers office	0	L /\	,	o to youro		
	Walls - Plaster/Drywall	1st Floor inside boiler room	650	SF	5	2-5 years		
	ý	engineers office				,		
	AC Unit	2nd floor north end of corridor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd floor north end of corridor	433	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd floor north end of corridor	2	EA	7	6-10 years		
	Floor - Carpet	2nd floor north end of corridor	433	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd floor north end of corridor	3	EA	7	6-10 years		
	Power Distribution	2nd floor north end of corridor	12	EA	7	6-10 years		
	Walls - Masonry	2nd floor north end of corridor	643	SF SF	7	10+ years		
	Walls - Plaster/Drywall AC Unit	2nd floor north end of corridor Rm 102- main office	643 1	EA	7 7	10+ years 6-10 years		
	Ceiling - Lay-in	Rm 102- main office	325	SF	6	10+ years		
	Doors - Transom Window	Rm 102- main office	9	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	Rm 102- main office	1	EA	6	6-10 years		
	Floor - Tile	Rm 102- main office	325	SF	6	10+ years		
	Lighting - Lay-in	Rm 102- main office	6	EA	6	6-10 years		
	Power Distribution	Rm 102- main office	8	EA	6	6-10 years		
	Walls - Plaster/Drywall	Rm 102- main office	756	SF	6	10+ years		
	AC Unit	Rm 102A- Conference Rm in Main	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	Rm 102A- Conference Rm in Main	156	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Rm 102A- Conference Rm in Main	1	EA	6	6-10 years		
	Floor - Tile	Rm 102A- Conference Rm in Main	156	SF	6	10+ years		
	Lighting - Pendent/Surface	Rm 102A- Conference Rm in Main	1	EA	6	6-10 years		
	Power Distribution	Rm 102A- Conference Rm in Main	10	EA	6	6-10 years		
	Walls - Plaster/Drywall	Rm 102A- Conference Rm in Main	560	SF	6	10+ years		



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments AC Unit Rm 102B-Principal Office in Main ΕA 6-10 vears 7 1 Rm 102B-Principal Office in Main 121 SF 7 Ceiling - Lav-in 10+ vears Doors - Wood Doors inclu hw Rm 102B-Principal Office in Main FΑ 7 6-10 years 1 Floor - Tile Rm 102B-Principal Office in Main SF 121 6 6-10 years 7 Lighting - Lay-in Rm 102B-Principal Office in Main 2 EΑ 6-10 years Rm 102B-Principal Office in Main ΕA 7 **Power Distribution** 4 6-10 years Walls - Plaster/Drywall Rm 102B-Principal Office in Main SF 7 10+ years 490 SF Ceiling - Lay-in Rm 105A- English Learners Office 115 7 10+ years Under construction (in 105) Doors - Wood Doors inclu hw Rm 105A- English Learners Office FΑ 7 1 10+ years (in 105) Floor - Tile Rm 105A- English Learners Office 115 SF 7 10+ years Under construction (in 105) Lighting - Lay-in Rm 105A- English Learners Office 1 EΑ 7 6-10 years Under construction (in 105) Rm 105A- English Learners Office FΑ Power Distribution 4 7 10+ years (in 105) Walls - Plaster/Drywall Rm 105A- English Learners Office 430 SF 7 Under construction 10+ years (in 105) AC Unit Rm 113- PE Teacher's Office 1 EΑ 7 6-10 years Ceiling - Plaster/Drywall Rm 113- PE Teacher's Office 400 SF 6 10+ years Doors - Transom Window SF Rm 113- PE Teacher's Office 9 6 6-10 years 6 Doors - Wood Doors inclu hw Rm 113- PE Teacher's Office 1 EA 6-10 years SF Floor - Tile Ceramic/ Porcelain Rm 113- PE Teacher's Office 400 6 10+ years Lighting - Pendent/Surface 6 ΕA 6 6-10 years Rm 113- PE Teacher's Office Power Distribution Rm 113- PE Teacher's Office 8 ΕA 6 6-10 vears SF 7 Walls - Plaster/Drywall Rm 113- PE Teacher's Office 920 10+ years Auditorium & Theater Balconv Seating 1st Floor 90 ΕA 5 10+ years SF Ceiling - Plaster/Drywall 1st Floor 3.040 6 10+ years Doors - Wood Doors inclu hw ΕA 1st Floor 4 6 6-10 years Floor - Carpet 1st Floor 477 SF 6 6-10 years Floor - Concrete Epoxy/ Painted 2.563 SF 5 10+ years 1st Floor Lighting - Chandelier, Incandescent 8 ΕA 6 6-10 years 1st Floor Lighting - Pendent/Surface 3 ΕA 6 1st Floor 6-10 years Lighting - Wall Mounted 1st Floor 11 FΑ 6 6-10 years Main Floor Seating 288 FΑ 5 1st Floor 6-10 years Sound System 1st Floor 1 ΕA 5 6-10 vears SF 405 6 Stage 1st Floor 10+ years Stage Curtain ΕA 5 6-10 years 1st Floor 2 5 Stage Lighting System 1st Floor 1 ΕA 6-10 years Stage-Stairs - Wood 1st Floor 10 LF 6 6-10 years SF 5 Storage/ Closet 1st Floor 190 6-10 years



Category : Room

Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments SF Walls - Plaster/Drywall 1st Floor 6.042 6 10+ vears Gvmnasia Ceiling - Plaster/Drywall 1st Floor SF 2.800 6 10+ years Doors - Transom Window SF 7 6-10 years 1st Floor 16 Doors - Wood Doors inclu hw 2 FΑ 1st Floor 6 6-10 years Floor - Wood 1st Floor 2.800 SF 7 10+ years Lighting - Metal Halide/Sodium Vapor 1st Floor 8 ΕA 7 6-10 years Walls - Plaster/Drywall SF 1st Floor 2.000 6 10+ years Walls - Plaster/Drywall SF 1st Floor 1,000 5 0-1 year Water damage. Walls - Structural Glazed Tile SF 1st Floor 1.540 6 10+ years Kitchen Ceiling - Plaster/Drvwall 1st Floor 592 SF 6 10+ vears Doors - Wood Doors inclu hw 1st Floor 1 EΑ 6 6-10 years Floor - Tile Quarry 1st Floor 592 SF 6 10+ years Lighting - Pendent/Surface ΕA 7 6-10 years 1st Floor 4 Walls - Plaster/Drvwall SF 6 10+ years 1st Floor 750 Walls - Structural Glazed Tile SF 250 6 1st Floor 10+ years Library 7 AC Unit 213 2 EΑ 6-10 years Ceiling - Lay-in 213 1,175 SF 10+ years 6 Ceiling - Lay-in SF 213 96 4 1-2 years Water damaged SF Doors - Transom Window 213 18 6 6-10 years Doors - Wood Doors inclu hw 213 EΑ 6 6-10 years 4 SF Floor - Carpet 213 1.271 6 6-10 vears Lighting - Lay-in 213 22 ΕA 6 6-10 vears Walls - Plaster/Drywall 213 1,574 SF 6 10+ years AC Unit 7 6-10 years Rm 111- Teacher's Library 1 EA LF 6 6-10 years Casework Rm 111- Teacher's Library 60 Rm 111- Teacher's Library SF Ceiling - Lay-in 732 6 10+ years Doors - Side-lite Rm 111- Teacher's Library 60 SF 6 6-10 years SF Doors - Transom Window Rm 111- Teacher's Library 9 6 6-10 years Doors - Wood Doors inclu hw Rm 111- Teacher's Library 1 EΑ 6 6-10 years Floor - Tile Rm 111- Teacher's Library 732 SF 6 6-10 vears Lighting - Lay-in Rm 111- Teacher's Library 12 EΑ 6 6-10 years Walls - Plaster/Drywall Rm 111- Teacher's Library 1,154 SF 6 10+ years Lunch & Multipurpose Room AC LINH 4 - 4 -. **–** ^ -0 40

Building : Main

AC UNIL	151 F1001		1	0-10 years	
Ceiling - Lay-in	1st Floor	1,100 SF	7	10+ years	
Ceiling - Lay-in	1st Floor	51 SF	4	0-1 year	Water damage.



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Doors - Transom Window 1st Floor 18 SF 6-10 vears 7 Doors - Wood Doors inclu hw 1st Floor 2 ΕA 7 6-10 years Floor - Tile 1st Floor 1.151 SF 7 10+ years Gymnasium is also the lunch/ multi purpose room Lighting - Lay-in 1st Floor 22 EΑ 7 6-10 years LF Serving Line 1st Floor 14 7 6-10 years Storage/ Closet 1st Floor SF 7 6-10 years 7 SF Walls - Plaster/Drywall 1st Floor 1.537 7 10+ years AC Unit Teacher's Lounge (in 105) EΑ 7 6-10 years 1 Ceiling - Plaster/Drywall SF Teacher's Lounge (in 105) 280 6 10+ vears Doors - Wood Doors inclu hw Teacher's Lounge (in 105) 2 ΕA 7 6-10 vears Floor - Tile Teacher's Lounge (in 105) 280 SF 7 10+ years Lighting - Pendent/Surface Teacher's Lounge (in 105) 3 ΕA 7 6-10 years SF 7 Walls - Plaster/Drywall Teacher's Lounge (in 105) 580 10+ years Mechanical/ Service Rooms SF 5 Janitor's Closet 1st Floor 100 6-10 years 7 Janitor's Closet 2nd Floor 90 SF 6-10 years SF 5 Boiler Room **Basement** 2,544 10+ years Coal Room 1,100 SF 5 10+ years Basement SF Mechanical/ Service Rooms Basement 686 5 10+ years Storage Room Basement 9.100 SF 5 10+ vears Restroom Accessories 1st First Boiler in Engineer's Office 25 SF 5 6-10 years 1st First Boiler in Engineer's Office Ceiling - Plaster/Drywall 25 SF 6 10+ years Doors - Wood Doors inclu hw 1st First Boiler in Engineer's Office 1 ΕA 6 6-10 years Floor - Tile 25 SF 1st First Boiler in Engineer's Office 4 0-1 vear Separating. Lavatorv 1st First Boiler in Engineer's Office 1 FΑ 6 6-10 vears Lighting - Pendent/Surface 1st First Boiler in Engineer's Office 1 FΑ 5 0-1 year Missing cover. Walls - Plaster/Drywall 1st First Boiler in Engineer's Office 50 SF 5 1-2 years Cracking. Water Closet 1st First Boiler in Engineer's Office 1 EΑ 6 6-10 years 1st floor North boy's - Currently staff SF 5 Accessories 205 6-10 years only Ceiling - Plaster/Drywall 1st floor North boy's - Currently staff 205 SF 6 10+ vears only SF Doors - Transom Window 1st floor North boy's - Currently staff 18 6 6-10 years onlv 2 Doors - Wood Doors inclu hw 1st floor North boy's - Currently staff EΑ 6 6-10 years only Floor - Tile Ceramic/ Porcelain 1st floor North boy's - Currently staff 185 SF 6 10+ years only SF Floor - Tile Ceramic/ Porcelain 1st floor North boy's - Currently staff 20 4 0-1 year Missing under partition. only



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Floor Drain 1st floor North boy's - Currently staff EΑ 6-10 years 1 7 only Hand Dryer 1st floor North boy's - Currently staff 2 EΑ 5 2-5 years only Lavatory 1st floor North boy's - Currently staff 2 EΑ 6 2-5 years only ΕA Lighting - Pendent/Surface 1st floor North boy's - Currently staff 4 6 6-10 years only Partitions 1st floor North boy's - Currently staff 2 EΑ 5 6-10 years only Urinals 1st floor North boy's - Currently staff 5 ΕA 6 2-5 years only SF 6 Walls - Masonry 1st floor North boy's - Currently staff 302 10+ years only SF Walls - Plaster/Drywall 1st floor North boy's - Currently staff 370 6 10+ years only SF Walls - Structural Glazed Tile 1st floor North boy's - Currently staff 68 6 10+ years only Water Closet 2 ΕA 1st floor North boy's - Currently staff 6 6-10 years only 1st floor North girl's - Currently staff 294 SF 5 Accessories 6-10 years only Ceiling - Plaster/Drywall 1st floor North girl's - Currently staff 294 SF 6 10+ years only Doors - Transom Window SF 1st floor North girl's - Currently staff 18 6 6-10 years only Doors - Wood Doors inclu hw 1st floor North girl's - Currently staff 2 EΑ 6 6-10 years only Floor - Tile Ceramic/ Porcelain 1st floor North girl's - Currently staff 294 SF 6 10+ years only Floor Drain EΑ 1st floor North girl's - Currently staff 1 4 2-5 years only 2 FΑ Hand Dryer 1st floor North girl's - Currently staff 5 2-5 years onlv Lavatory 1st floor North girl's - Currently staff 1 EΑ 6 2-5 years only Lighting - Pendent/Surface 1st floor North girl's - Currently staff 4 EΑ 6 6-10 years only Partitions 1st floor North girl's - Currently staff 7 EΑ 5 6-10 years onlv Walls - Masonry 1st floor North girl's - Currently staff SF 6 346 10+ years onlv Walls - Plaster/Drywall 1st floor North girl's - Currently staff 406 SF 6 10+ years only



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments 1st floor North girl's - Currently staff 10+ years Walls - Structural Glazed Tile 60 SF 6 onlv Water Closet 1st floor North girl's - Currently staff 7 ΕA 6 2-5 years only Accessories 1st floor boys at south (under 205 SF 7 6-10 years Entire bathroom under construction renovation) Ceiling - Plaster/Drywall 1st floor boys at south (under SF 205 7 10+ years renovation) Doors - Transom Window 1st floor boys at south (under 18 SF 7 6-10 years renovation) Doors - Wood Doors inclu hw 1st floor boys at south (under 2 ΕA 7 6-10 vears renovation) 205 SF Floor - Tile Ceramic/ Porcelain 1st floor boys at south (under 7 10+ years renovation) Floor Drain 1st floor boys at south (under 1 EΑ 7 10+ years renovation) Hand Dryer 1st floor boys at south (under 2 ΕA 7 6-10 years renovation) 1st floor boys at south (under 2 ΕA 7 Lavatory 6-10 years renovation) Lighting - Pendent/Surface 1st floor boys at south (under EΑ 7 4 6-10 years renovation) Partitions 1st floor boys at south (under 2 EΑ 7 6-10 years renovation) 1st floor boys at south (under 5 ΕA Urinals 7 6-10 years renovation) Walls - Masonry 1st floor boys at south (under 302 SF 7 10+ years renovation) Walls - Plaster/Drywall 1st floor boys at south (under 370 SF 7 10+ years renovation) SF Walls - Structural Glazed Tile 1st floor boys at south (under 7 68 10+ years renovation) Water Closet 1st floor boys at south (under 2 FΑ 7 6-10 years renovation) Accessories 1st floor girls at south (under 294 SF 7 6-10 years Entire bathroom under construction renovation) Ceiling - Plaster/Drywall 1st floor girls at south (under 294 SF 7 10+ years Entire bathroom under construction renovation) Doors - Transom Window 1st floor girls at south (under 18 SF 7 6-10 years renovation) Doors - Wood Doors inclu hw 1st floor girls at south (under 2 ΕA 7 6-10 years renovation) Floor - Tile Ceramic/ Porcelain 1st floor girls at south (under 294 SF 7 10+ years renovation)



Catego	ry : Room		В	uilding	: Main		
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	1st floor girls at south (under renovation)	1	EA	7	10+ years	
	Hand Dryer	1st floor girls at south (under renovation)	2	EA	7	6-10 years	
	Lavatory	1st floor girls at south (under renovation)	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st floor girls at south (under renovation)	4	EA	7	6-10 years	
	Partitions	1st floor girls at south (under renovation)	7	EA	7	6-10 years	
	Walls - Masonry	1st floor girls at south (under renovation)	346	SF	7	10+ years	
	Walls - Plaster/Drywall	1st floor girls at south (under renovation)	406	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st floor girls at south (under renovation)	60	SF	7	10+ years	
	Water Closet	1st floor girls at south (under renovation)	7	EA	7	6-10 years	
	Accessories	1st floor inside principal office	27	SF	5	6-10 years	
	Ceiling - Lay-in	1st floor inside principal office	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor inside principal office	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st floor inside principal office	27	SF	6	10+ years	
	Lavatory	1st floor inside principal office	1	EA	6	2-5 years	
	Lighting - Wall Mounted	1st floor inside principal office	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st floor inside principal office	260	SF	6	10+ years	
	Water Closet	1st floor inside principal office	1	EA	6	6-10 years	
	Accessories	1st flr- In 113	84	SF	5	6-10 years	
	Ceiling - Lay-in	1st flr- In 113	84	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st flr- In 113	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st flr- In 113	84	SF	6	10+ years	
	Lavatory	1st flr- In 113	1	ĒA	6	10+ years	
	Lighting - Lay-in	1st flr- In 113	1	EA	6	6-10 years	
	Partitions	1st flr- In 113	2	EA	5	6-10 years	
	Walls - Plaster/Drywall	1st flr- In 113	388	SF	6	10+ years	
	Water Closet	1st flr- In 113	2	EA	6	10+ years	
	Accessories	2nd floor boys at north	205	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor boys at north	205	SF	6	10+ years	
	Doors - Transom Window	2nd floor boys at north	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd floor boys at north	2	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd floor boys at north	205	SF	6	10+ years	
	Floor Drain	2nd floor boys at north	203	EA	4	2-5 years	
	Hand Dryer	2nd floor boys at north	2	EA	5	2-5 years	
	Lavatory	2nd floor boys at north	2	EA	6	2-5 years	
	Lighting - Pendent/Surface	2nd floor boys at north	4	EA	6	6-10 years	



Catego	Category : Room		В	uilding	: Main			
				J		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Partitions	2nd floor boys at north	2	EA	5	6-10 years		
	Urinals	2nd floor boys at north	5	EA	6	2-5 years		
	Walls - Masonry	2nd floor boys at north	302	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd floor boys at north	370	SF	6	10+ years		
	Walls - Structural Glazed Tile	2nd floor boys at north	68	SF	6	10+ years		
	Water Closet	2nd floor boys at north	2	EA	6	2-5 years		
	Accessories	2nd floor boys at south	205	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	2nd floor boys at south	205	SF	6	10+ years		
	Doors - Transom Window	2nd floor boys at south	18	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd floor boys at south	2	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd floor boys at south	205	SF	5	10+ years		
	Floor Drain	2nd floor boys at south	1	EA	4	2-5 years		
	Hand Dryer	2nd floor boys at south	2	EA	5	2-5 years		
	Lavatory	2nd floor boys at south	2	EA	6	2-5 years		
	Lighting - Pendent/Surface	2nd floor boys at south	4	EA	6	6-10 years		
	Partitions	2nd floor boys at south	2	EA	5	6-10 years		
	Urinals	2nd floor boys at south	5	EA	6	2-5 years		
	Walls - Masonry	2nd floor boys at south	370	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd floor boys at south	302	SF	6	10+ years		
	Walls - Structural Glazed Tile	2nd floor boys at south	68	SF	6	10+ years		
	Water Closet	2nd floor boys at south	2	EA	6	6-10 years		
	Accessories	2nd floor girls at north	294	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	2nd floor girls at north	294	SF	6	10+ years		
	Doors - Transom Window	2nd floor girls at north	18	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd floor girls at north	2	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd floor girls at north	294	SF	6	10+ years		
	Floor Drain	2nd floor girls at north	1	EA	7	2-5 years		
	Hand Dryer	2nd floor girls at north	2	EA	5	2-5 years		
	Lavatory	2nd floor girls at north	1	EA	6	2-5 years		
	Lighting - Pendent/Surface	2nd floor girls at north	4	EA	6	6-10 years		
	Partitions	2nd floor girls at north	7	EA	5	6-10 years		
	Walls - Masonry	2nd floor girls at north	346	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd floor girls at north	406	SF	6	6-10 years		
	Walls - Structural Glazed Tile	2nd floor girls at north	60	SF	6	10+ years		
	Water Closet	2nd floor girls at north	7	EA	6	2-5 years		
	Accessories	2nd floor girls at south	294	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	2nd floor girls at south	294	SF	6	10+ years		
	Doors - Transom Window	2nd floor girls at south	18	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd floor girls at south	2	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd floor girls at south	294	SF	6	10+ years		
	Floor Drain	2nd floor girls at south	1	EA	7	2-5 years		
	Hand Dryer	2nd floor girls at south	2	EA	5	2-5 years		
	Lavatory	2nd floor girls at south	1	EA	6	2-5 years		
	Lighting - Pendent/Surface	2nd floor girls at south	4	EA	6	6-10 years		



Building : Main Category : Room Recommend Quantity Group Item - Type Location UOM Rank Replacement Comments 2nd floor girls at south Partitions 7 ΕA 5 6-10 years 2nd floor girls at south 346 SF 6 10+ years Walls - Masonry 2nd floor girls at south Walls - Plaster/Drywall 401 SF 6 10+ years 2nd floor girls at south Walls - Plaster/Drywall 5 SF 4 1-2 years Hole in wall. Walls - Structural Glazed Tile SF 6 2nd floor girls at south 60 10+ years Water Closet 2nd floor girls at south 7 ΕA 6 2-5 years Accessories 2nd floor south end of corridor 82 SF 5 6-10 years Ceiling - Plaster/Drywall SF 2nd floor south end of corridor 82 6 10+ years Doors - Wood Doors inclu hw 2nd floor south end of corridor 1 ΕA 6 6-10 years SF Floor - Tile Ceramic/ Porcelain 2nd floor south end of corridor 82 6 10+ years 2nd floor south end of corridor Lavatorv 2 ΕA 6 2-5 vears Lighting - Pendent/Surface 2nd floor south end of corridor 1 ΕA 7 6-10 years Lighting - Wall Mounted 2nd floor south end of corridor 1 ΕA 7 6-10 years 2 ΕA 5 Partitions 2nd floor south end of corridor 6-10 years Walls - Plaster/Drywall SF 6 10+ years 2nd floor south end of corridor 400 Water Closet 2 FΑ 6 2nd floor south end of corridor 6-10 years

Building : Main

Category : Classroom

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	m #100 (Special Education)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	471	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	471	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	918	SF	7	10+ years	
Classroc	m #101 (Kindergarten)						
Classroo	AC Units	1st Floor	1	EA	7	6-10 years	
Classroo	· · · · ·	1st Floor 1st Floor	1	LF	7 7	6-10 years 6-10 years	
Classroo	AC Units		1 9 667	LF SF	7 7 7	-	
Classroc	AC Units Casework	1st Floor		LF SF SF	7 7 7 4	6-10 years	Water damage.
Classroo	AC Units Casework Ceiling - Lay-in	1st Floor 1st Floor	667	LF SF SF SF	7 7 7 4 7	6-10 years 10+ years	Water damage.
Classroo	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in	1st Floor 1st Floor 1st Floor	667 48	LF SF SF	7 7 7 4 7 7	6-10 years 10+ years 0-1 year	Water damage.
Classroo	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Transom Window	1st Floor 1st Floor 1st Floor 1st Floor	667 48	LF SF SF SF	7 7 4 7 7 7	6-10 years 10+ years 0-1 year 6-10 years	Water damage.
Classroc	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	667 48 9 1	LF SF SF EA SF EA	7 7 4 7 7 7 7	6-10 years 10+ years 0-1 year 6-10 years 6-10 years	Water damage.
Classroc	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	667 48 9 1 715	LF SF SF EA SF	7 7 4 7 7 7 7 7	6-10 years 10+ years 0-1 year 6-10 years 6-10 years 10+ years	Water damage.
Classroc	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	667 48 9 1 715 12	LF SF SF EA SF EA	7 7 4 7 7 7 7 7 7	6-10 years 10+ years 0-1 year 6-10 years 6-10 years 10+ years 6-10 years	Water damage.



Catego	ory : Classroom		В	uilding	: Main		
_			-			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #103 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	685	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	32	SF	5	0-1 year	Water damage.
	Doors - Transom Window	1st Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	677	SF	7	10+ years	
	Floor - Tile	1st Floor	40	SF	4	1-2 years	Holes.
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	28	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	878	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	40	SF	4	1-2 years	Crack in wall.
Classroo	om #104 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	36	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	752	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Wood	1st Floor	752	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	954	SF	7	10+ years	
Classro	om #106 (Kindergarten)						
0103310	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	14	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	715	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	9 1	EA	7	6-10 years	
	Floor - Wood	1st Floor	715	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	28	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	20 918	SF	7	10+ years	
Classre	om #107 (Regular Classroom)					-	
UIA55100	AC Units	1st Floor	4	EA	7	6 10 years	
			1		7	6-10 years	
	Casework	1st Floor	10	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	722	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Wood	1st Floor	722	SF	7	10+ years	

Lighting - Lay-in

12

ΕA

7

6-10 years

1st Floor



Catego	ry : Classroom		В	uilding	: Main		· · · · · ·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	54	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	928	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Water damage.
Classroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	19	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	674	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Wood	1st Floor	674	SF	7	10+ vears	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	907	SF	7	10+ years	
Classroo	om #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	718	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	7	6-10 years	
	Floor - Wood	1st Floor	718	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	54	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	920	SF	7	10+ years	
Classroo	om #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	4	1-2 years	Missing cabinetry
	Ceiling - Lay-in	1st Floor	725	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Wood	1st Floor	725	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	48	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	922	SF	7	10+ years	
Classroo	om #200 (Kindergarten)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	288	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	49	SF	4	1-2 years	Cracks and water damage.
	Doors - Transom Window	2nd Floor	49	SF	4 7	6-10 years	oracio ana water damaye.
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years	
			2	LA	'	U- IU years	



Building : Main Category : Classroom Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments Floor - Terrazzo 2nd Floor 337 SF 10+ vears 7 2nd Floor 5 ΕA 7 6-10 vears Lighting - Lay-in Marker Board 2nd Floor 6 LF 7 6-10 years Storage/ Closet 2nd Floor SF 7 110 6-10 years SF Walls - Plaster/Drywall 2nd Floor 839 7 10+ years Classroom #201 (Art Room) AC Units 2nd Floor 7 1 ΕA 6-10 years 20 LF Casework 2nd Floor 6 6-10 years SF Ceiling - Lay-in 2nd Floor 652 6 10+ years Ceiling - Lay-in 2nd Floor SF 5 1-2 years 70 Water damage. Doors - Transom Window 2nd Floor 9 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor 2 ΕA 6 6-10 years SF Floor - Wood 2nd Floor 722 6 10+ years 2nd Floor ΕA 6 6-10 vears Lighting - Lay-in 12 Marker Board 2nd Floor 30 LF 6 6-10 years 928 SF Walls - Plaster/Drywall 2nd Floor 6 10+ years Classroom #202 (Regular Classroom) AC Units 2nd Floor 1 FΑ 7 6-10 years 10 LF Casework 2nd Floor 7 6-10 years SF Ceiling - Lav-in 2nd Floor 725 7 10+ years SF Doors - Transom Window 2nd Floor 9 7 6-10 years Doors - Wood Doors inclu hw 2nd Floor 1 ΕA 7 6-10 years Floor - Wood 2nd Floor 725 SF 7 10+ years 2nd Floor 12 ΕA 7 6-10 years Lighting - Lay-in LF Marker Board 2nd Floor 43 7 6-10 years 922 SF 7 Walls - Plaster/Drywall 2nd Floor 10+ years Classroom #203 (Computer Lab) AC Units 2nd Floor 2 7 EA 6-10 years 2nd Floor 20 LF 7 Casework 6-10 years Ceiling - Lay-in 2nd Floor 680 SF 7 10+ years SF Ceiling - Lay-in 2nd Floor 40 4 1-2 years Water damage. SF 7 Doors - Transom Window 2nd Floor 9 6-10 years Doors - Wood Doors inclu hw 2nd Floor 2 ΕA 7 6-10 vears Floor - Wood SF 2nd Floor 720 7 10+ years Lighting - Lay-in 2nd Floor 12 ΕA 7 6-10 years Marker Board 2nd Floor LF 7 6-10 years 60 Walls - Plaster/Drywall 2nd Floor 868 SF 6 10+ years 2nd Floor SF Walls - Plaster/Drywall 50 6 1-2 years Chipped and cracking paint on walls. Wireless System 2nd Floor FΑ 7 6-10 years 1



Category : Classroom Bu			Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	om #204 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	20	LF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	701	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	16	SF	4	1-2 years	Water damage.	
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years		
	Floor - Wood	2nd Floor	725	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	30	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	922	SF	6	10+ years		
Classroo	om #205 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	20	LF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	678	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	40	SF	4	1-2 years	Water damage.	
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒA	7	6-10 years		
	Floor - Wood	2nd Floor	718	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	Lighting cover not secure to fixture. Notify maintenance.	
	Marker Board	2nd Floor	43	LF	7	6-10 years	Notity maintenance.	
	Walls - Plaster/Drywall	2nd Floor	898	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	20	SF	6	1-2 years	Chipped paint	
			20	36	0	1-2 years		
Classroo	om #206 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	20	LF	6	6-10 years		
	Ceiling - Lay-in	2nd Floor	721	SF	6	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years		
	Floor - Wood	2nd Floor	721	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	30	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	889	SF	6	10+ years		
Classroo	om #207 (Kindergarten)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	20	LF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	639	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	80	SF	5	1-2 years	Water damage.	
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years		



Group

Category : Classroom

Item - Type Location Quantity UOM Rank Replacement Comments Doors - Wood Doors inclu hw 2nd Floor 2 ΕA 6-10 vears 7 Floor - Wood 2nd Floor SF 7 719 10+ years Lighting - Lay-in 2nd Floor 12 FΑ 7 6-10 years Marker Board 2nd Floor 43 LF 7 6-10 years SF Walls - Plaster/Drywall 2nd Floor 893 7 10+ years SF Walls - Plaster/Drywall 2nd Floor 25 6 1-2 years Crack pealing paint over window seal. Classroom #208 (Regular Classroom) AC Units 2nd Floor 1 EΑ 7 6-10 years LF Casework 2nd Floor 20 7 6-10 years Ceiling - Lay-in 2nd Floor 720 SF 7 10+ years Doors - Transom Window 2nd Floor 9 SF 7 6-10 years Doors - Wood Doors inclu hw 2nd Floor 2 ΕA 7 6-10 years SF Floor - Wood 2nd Floor 720 7 10+ years 2nd Floor ΕA 7 6-10 vears Lighting - Lay-in 12 Marker Board 2nd Floor 30 LF 7 6-10 years SF Walls - Plaster/Drywall 2nd Floor 918 7 10+ years Classroom #209 (Regular Classroom) AC Units 2nd Floor 1 FΑ 7 6-10 years 20 LF Casework 2nd Floor 7 6-10 years SF Ceiling - Lav-in 2nd Floor 720 7 10+ years SF Doors - Transom Window 2nd Floor 9 7 6-10 years Doors - Wood Doors inclu hw 2nd Floor 2 ΕA 7 6-10 years Floor - Wood 2nd Floor 720 SF 7 10+ years 2nd Floor 12 ΕA 7 6-10 years Lighting - Lay-in LF Marker Board 2nd Floor 43 7 6-10 years 909 SF 7 Walls - Plaster/Drywall 2nd Floor 10+ years Classroom #210 (Regular Classroom) AC Units 2nd Floor 7 1 EA 6-10 years 2nd Floor LF 7 Casework 20 6-10 years Ceiling - Lay-in 2nd Floor 730 SF 7 10+ years SF Doors - Transom Window 2nd Floor 9 7 6-10 years Doors - Wood Doors inclu hw 2nd Floor 2 EΑ 7 6-10 years Floor - Wood 2nd Floor 730 SF 7 10+ vears 2nd Floor 6-10 years Lighting - Lay-in 12 EΑ 7 Marker Board 2nd Floor 70 LF 7 6-10 years 928 SF Walls - Plaster/Drywall 2nd Floor 7 10+ years Classroom #211 (Regular Classroom) AC Units 2nd Floor 1 ΕA 7 6-10 years Casework 2nd Floor 20 LF 7 6-10 years

Building : Main

Recommend



Catego	ry : Classroom		В	uilding	: Main				
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	2nd Floor	718	SF	7	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years			
	Floor - Wood	2nd Floor	718	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	43	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	918	SF	7	10+ years			
Catego	ry : Interior		В	uilding	: Main				
						Recommend			

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor			-			•	
	Ceiling - Lay-in	1st Floor	3,884	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	554	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	9	EA	6	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	2-5 years	
	Floor - Terrazzo	1st Floor	738	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	3,700	SF	5	10+ years	
	Lighting - Lay-in	1st Floor	44	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	13	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor	4	EA	6	6-10 years	
	Stairs - Terrazzo	1st Floor	19	LF	6	10+ years	
	Student Lockers - One Tier	1st Floor	203	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	3,218	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,340	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	4,334	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	104	SF	5	1-2 years	Water damage.
	Doors - Wood Doors include hw	2nd Floor	2	EA	6	6-10 years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	5	2-5 years	
	Floor - Terrazzo	2nd Floor	668	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	3,770	SF	5	10+ years	
	Lighting - Lay-in	2nd Floor	60	EA	6	6-10 years	
	Stairs - Terrazzo	2nd Floor	19	LF	6	10+ years	
	Student Lockers - One Tier	2nd Floor	263	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	3,218	SF	6	10+ years	
afetv							
	Camera Viewing Station	1st Floor	2	EA	5	2-5 years	
	Security Cameras	1st Floor	5	EA	5	2-5 years	
tairs							
	Ceiling - Lay-in	North	40	SF	4	1-2 years	Water damage.
	Ceiling - Plaster/Drywall	North	118	SF	6	10+ years	Paint chipping and peeling.



Building : Main Category : Interior Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Floor - Terrazzo North 134 SF 10+ years 7 Handrails 62 LF 7 6-10 years North Lighting - Lay-in North 4 ΕA 7 6-10 years Stairs - Terrazzo 27 LF 7 North 10+ years SF Walls - Plaster/Drywall North 945 7 10+ years SF Ceiling - Plaster/Drywall 7 North West 103 10+ years Ceiling - Plaster/Drywall North West 15 SF 1-2 years Pealing paint 6 Floor - Terrazzo SF North West 134 7 10+ years LF Handrails North West 62 7 6-10 years LF 7 Stairs - Terrazzo North West 27 10+ years North West SF Walls - Plaster/Drvwall 990 7 10+ vears Ceiling - Lay-in South 40 SF 4 1-2 years Water damage. Ceiling - Plaster/Drywall South 78 SF 7 10+ years SF Floor - Terrazzo 7 South 122 10+ years SF Floor - Terrazzo 0-1 year South 12 4 Crack. Handrails 62 LF 7 South 6-10 years LF 27 7 Stairs - Terrazzo South 10+ years SF Walls - Plaster/Drywall South 990 7 10+ years Ceiling - Lay-in South West SF 7 103 10+ years Ceiling - Plaster/Drywall South West SF 1-2 years 15 6 Pealing paint Floor - Terrazzo South West 134 SF 7 10+ years LF Handrails South West 7 6-10 years 62 LF South West 27 7 Stairs - Terrazzo 10+ years South West SF 7 Walls - Plaster/Drywall 990 10+ years Walls - Plaster/Drywall South West 50 SF 6 1-2 years Pealing paint.



Category : Exterior Building : Annex Recommend Item - Type Location Quantity UOM Replacement **Comments** Group Rank Entrance FΑ 7 Entrance Control - Audio #1a W 1 6-10 years 2 FΑ Exterior Doors - Exterior Steel Door #1a W 6 6-10 years Power Door Operator and Controls #1a W 1 ΕA 7 6-10 years Exterior Doors - Exterior Steel Door #2a N 2 ΕA 6 6-10 years Exterior Doors - Exterior Steel Door #3a S 2 ΕA 6 6-10 years Foundation Foundation - Concrete Entire Building LF 7 10+ years 560 Superstructure - Metal Deck/ Concrete Entire Building 14,400 SF 7 10+ years Topping Liahtina 9 ΕA Exterior Lighting - Wall Mounted Entire Building 6 10+ years Roof System Chimney - Metal Flue Entire Building 5 LF 6 10+ vears Downspouts - Exterior Downspouts LF Entire Building 44 6 10+ years Roof - Metal SF 6 10+ years Entire Building 18.000 SF 7 Roof Structure - Steel / Metal Deck/ Entire Building 18.000 10+ years Concrete Topping Walls Canopy - Metal Entire Building 70 SF 7 10+ years SF Exterior Walls - Brick Entire Building 5.775 6 10+ years Windows Guard - Guards perforated Entire Building 1,470 SF 6 10+ years Entire Building LF Lintels - Steel 277 6 10+ years Windows - Casement Aluminum Double-Entire Building SF 6 10+ years 1.470 pane **Category : Electrical Building : Annex** Recommend Location UOM Rank **Replacement** Comments Group Item - Type Quantity Emergency System Emergency A/C Power - Corridors and 1st Floor 1,300 SF 6 6-10 years

Exit Signs - Corridors and Stairs

Security System - Intrusion Detection

Security System - CCTV

Stairs

6

14,400

14,400

EΑ

SF

SF

2

5

5

0-1 year

6-10 years

6-10 years

1st Floor

1st Floor

1st Floor

No battery backup



2828 N Kilbourn AVENUE, Chicago, IL 60641 **Category : Electrical Building : Annex** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments **Emergency Battery Packs - Corridors and** 1st Floor 2 FΑ 6 6-10 vears Stairs Automatic Transfer Switch Electrical Room 1 FΑ 6 6-10 years Serves annex Main Service 1st Floor 14,400 SF 5 PA System 6-10 vears Connected to main building Independent Electrical Service for 1st Floor FΑ 6 6-10 years Serves Annex 1 emergency power Main Electrical Service - 800 A and Less Electrical Room 1 EΑ 6 6-10 years Serves annex than 120/208/3PH Power Distribution Lighting and Power Panels - 100 A Entire Building 2 FΑ 6 6-10 years Lighting and Power Panels - Above 100 A Entire Building 1 ΕA 6 6-10 vears Main Distribution Panels - 400 - 600 amp Entire Building 1 ΕA 6 6-10 years **Category : Fire Protection Building : Annex** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Fire Alarm Fire Alarm Panel ΕA 6 Entire Building 1 2-5 years Serves annex, older but in good condition SF 6 Fire Alarm Strobe Lights Entire Building 14.400 2-5 vears SF Fire Alarm_System Entire Building 14,400 6 2-5 years Serves annex, original equipment Sprinkler System Sprinkler Heads 1st Floor 14,400 SF 7 6-10 years Sprinkler Piping 14,400 SF 7 6-10 years 1st Floor SF Wet Sprinkler System 1st Floor 14,400 7 6-10 years Serves annex, using city pressure Category : Mechanical **Building : Annex** Recommend Location Replacement Comments Item - Type Quantity UOM Rank Group Air Handling Systems Air Handling Unit-Package Single Zone-FΑ Mechanical Room 1 5 6-10 years Serves annex Indoor- Hot Water Coils - 4000-8000 cfm Air Intake Mechanical Room EΑ 6 6-10 years 1 Boiler Systems Boiler Auxiliary- Non Condensing Hot Water 2 ΕA Boiler Room 5 6-10 years - 2001 - 3000 MBH Chemical Pot Feeder Boiler Room ΕA 5 1 6-10 years



<u> </u>	Schools						28 N Kilbourn AVENUE, Chicago, IL 60641
Catego	ry : Mechanical		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Glycol Feed System	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump	Boiler Room	2	EA	6	6-10 years	
	Non Condensing- Water Tube- Flexible	Boiler Room	2	EA	5	2-5 years	Serves annex
	Tube- Force Draft- Hot Water Boiler - 2001						
	- 3000 MBH						
	Water Fill System	Boiler Room	1	EA	6	6-10 years	
Heating I							
	Cabinet Heaters - With Hot Water Coil	1st Floor	2	EA	6	6-10 years	Ceiling mounted
	Unit Heater - Hot Water	1st Floor	1	EA	5	6-10 years	
Mechanio	cal Plumbing						
	Hydronic Supply and Return - Steel	1st Floor	600	LF	6	6-10 years	
_							
Tempera	iture Control						•
	Electric Thermostat	Entire Building	13	EA	6	6-10 years	Serve univents and unit heater
Unit Ven	Unit Ventilators- Floor Mounted- Hot Water	1st Floor	10		5	0.5.40000	
		1st Floor	12	EA	5	2-5 years	Original equipment
	w/ DX Cooling Coil & w/ Self Contained						
	Compressors						
Ventilatio	~~						
venulauc	Exhaust Fans- Roof Mounted - 1501 - 8000	Main Roof	1	EA	6	6 10 vooro	
	CFM	Main Rool	I	EA	0	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Main Roof	3	EA	6	6 10 vooro	
	CFM		3	EA	0	6-10 years	
Catego	ry : Plumbing		В	uildina	: Annex		
Ŭ				Ū		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	e.						
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Serves annex
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	14,400	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	14,400	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	14,400	SF	6	10+ years	
	Fixtures						
				~ -	-		
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	14,400	SF	6	10+ years	



XP	Schools						28 N Kilbourn AVENUE, Chicago, IL 606
Catego	ry : Plumbing		В	uilding	: Annex	ſ	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	14,400	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	14,400	SF	6	10+ years	
	Sanitary Piping	Entire Building	14,400	SF	6	10+ years	Connected directly to underground piping
	Storm Piping	Entire Building	14,400	SF	6	10+ years	
	Vent Piping	Entire Building	14,400	SF	6	10+ years	
Catego	ory : Classroom		В	uilding	: Annex	[
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #1 (Regular Classroom)						
	Casework	1st Floor	25	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	867	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒA	7	6-10 years	
	Floor - Tile	1st Floor	867	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	776	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	254	SF	7	10+ years	
Classroo	om #10 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	25	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	7	10+ years	
	Doors - Transom Window	1st Floor	1	SF	6	6-10 years	
	Floor - Tile	1st Floor	871	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	40	LF	7	6-10 years	
	Walla Canarata Diaak	Act Eleen	770	05	7	10	

		IST FIDUI	071	SF .	0	0-10 years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	40	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	776	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	254	SF	5	10+ years	
Classro	oom #2 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	25	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	863	SF	5	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	0-1 year	Cracked.
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	871	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	1	EA	5	0-1 year	Does not work.
	Marker Board	1st Floor	30	LF	7	6-10 years	



Catego	ory : Classroom		В	uildina	: Annex		
•			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	776	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	254	SF	7	10+ years	
Cleanro	om #3 (Regular Classroom)						
01222100	AC Units	1st Floor	1	EA	7	6-10 years	
		1st Floor	25	LF	7		
	Casework		25 868	SF		6-10 years	
	Ceiling - Lay-in	1st Floor			7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	868	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	516	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	517	SF	7	10+ years	
Classroo	om #4 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	25	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	878	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒA	7	6-10 years	
	Floor - Tile	1st Floor	878	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	40	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	522	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	517	SF	7	10+ years	
Classro	om #5 (Regular Classroom)						
0123310	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	25	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	Door needs repainting. Minor dent at
		13111001	I	LA	0	0-10 years	the bottom of door from door stopper.
	Floor - Tile	1st Floor	871	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	516	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	517	SF	7	10+ years	
Classro	om #6 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	25	LA	7	6-10 years	
	Casework Ceiling - Lay-in	1st Floor	880	SF	7	,	
	Doors - Steel Doors incl hw	1st Floor	000 1	EA	7	10+ years 6-10 years	
	Floor - Tile	1st Floor	880	SF	7	•	
			000	SF	1	10+ years	



Category : Classroom

Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Lighting - Lay-in 1st Floor 9 ΕA 6-10 vears 7 Marker Board 1st Floor 24 LF 7 6-10 vears Walls - Concrete Block 1st Floor 522 SF 7 10+ years 517 SF Walls - Plaster/Drywall 1st Floor 7 10+ years Classroom #7 (Regular Classroom) AC Units 1st Floor 1 EΑ 7 6-10 years LF 25 Casework 1st Floor 6 2-5 years Minor cracking/chipping on front doors. SF Ceiling - Lay-in 1st Floor 871 7 10+ years Doors - Steel Doors incl hw ΕA 6-10 years 1st Floor 1 7 Floor - Tile 1st Floor 871 SF 7 10+ years Lighting - Lay-in 1st Floor 9 ΕA 7 6-10 years LF Marker Board 1st Floor 24 7 6-10 years SF 7 Walls - Concrete Block 1st Floor 516 10+ years Walls - Plaster/Drywall 1st Floor 517 SF 7 10+ years Classroom #8 (Regular Classroom) AC Units 1st Floor 1 FΑ 7 6-10 years Casework 1st Floor 25 LF 7 6-10 years SF Ceiling - Lay-in 1st Floor 880 7 10+ years Doors - Steel Doors incl hw ΕA 1st Floor 7 6-10 years 1 SF Floor - Tile 1st Floor 880 7 10+ years ΕA 7 6-10 years Lighting - Lay-in 1st Floor 9 Marker Board 1st Floor 40 LF 7 6-10 years 1st Floor SF 7 Walls - Concrete Block 522 10+ years SF Walls - Plaster/Drywall 1st Floor 517 7 10+ years Classroom #9 (Regular Classroom) AC Units 1st Floor 1 ΕA 7 6-10 years Casework 25 LF 7 6-10 years 1st Floor SF 8 7 Ceiling - Lay-in 1st Floor 10+ years Ceiling - Lay-in 859 SF 7 1st Floor 10+ years Doors - Steel Doors incl hw 1st Floor 1 EΑ 7 10+ years SF Floor - Tile 1st Floor 863 6 10+ years SF Floor - Tile 1st Floor 4 4 0-1 vear Chipped tiles. 9 7 6-10 years Lighting - Lay-in 1st Floor EΑ Marker Board 1st Floor 24 LF 7 6-10 years 776 SF 7 Walls - Concrete Block 1st Floor 10+ years 254 SF 7 Walls - Plaster/Drywall 1st Floor 10+ years Classroom #Resource room (Regular Classroom) AC Units 7 1st Floor 1 ΕA 6-10 years

Building : Annex



Catego	ory : Classroom		Building : Annex						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	1st Floor	367	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	6-10 years			
	Floor - Tile	1st Floor	367	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	6	EA	7	6-10 years			
	Marker Board	1st Floor	10	LF	7	6-10 years			
	Walls - Concrete Block	1st Floor	200	SF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	637	SF	7	10+ years			
Catego	ory : Room		Building : Annex						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Kitchen									

litchen					-	
Ceiling - Plaster/Drywall	1st Floor	44	SF	7	10+ years	
Floor - Tile	1st Floor	44 44	SF	7	10+ years	
Lighting - Lay-in	1st Floor		EA	7	10+ years	
Walls - Concrete Block	1st Floor	280	SF	7	10+ years	
	13(1100)	200	01	'	for years	
1DF_IDF						
Doors - Steel Doors incl hw	Rear of electrical room	1	EA	7	6-10 years	
Finishes	Rear of electrical room	60	SF	5	10+ years	
Other Cooling Unit	Rear of electrical room	1	EA	5	6-10 years	PTAC
lechanical/ Service Rooms						
Boiler Room	1st Floor	340	SF	5	10+ years	
Mechanical/ Service Rooms	1st Floor	350	SF	5	10+ years	
Janitor's Closet	Janitors Closet	25	SF	7	10+ years	
Restroom						
Accessories	1st Floor	44	SF	5	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	44	SF	6	10+ years	
Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
Floor - Tile	1st Floor	44	SF	6	6-10 years	
Floor Drain	1st Floor	1	EA	7	10+ years	
Lavatory	1st Floor	1	EA	6	2-5 years	
Lighting - Lay-in	1st Floor	1	EA	6	6-10 years	
Walls - Concrete Block	1st Floor	260	SF	6	10+ years	
Water Closet	1st Floor	1	EA	6	2-5 years	
Accessories	1st Floor	509	SF	5	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	509	SF	6	10+ years	
Floor - Concrete Epoxy/ Painted	1st Floor	509	SF	5	10+ years	
Floor Drain	1st Floor	1	EA	7	2-5 years	
Hand Dryer	1st Floor	2	EA	5	2-5 years	Older model
Lavatory	1st Floor	3	EA	6	2-5 years	



Category : Room **Building : Annex** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments 1st Floor ΕA 6-10 years Lighting - Lay-in 5 6 Partitions 1st Floor 9 ΕA 7 6-10 years Walls - Concrete Block 1,373 1st Floor SF 6 10+ years Water Closet 1st Floor 9 ΕA 6 2-5 years SF 5 509 Accessories 1st Floor 6-10 years SF Ceiling - Plaster/Drywall 1st Floor 509 6 10+ years SF Floor - Epoxy/ Painted 1st Floor 509 7 10+ years Floor Drain 2 ΕA 7 1st Floor 10+ years Hand Dryer 1st Floor 2 ΕA 5 2-5 years 1st Floor 3 ΕA 6 2-5 years Lavatory Lighting - Lay-in 5 1st Floor ΕA 6 6-10 years Partitions 3 6-10 years 1st Floor ΕA 5 2-5 years Urinals 1st Floor 6 ΕA 6 Walls - Concrete Block SF 1,373 6 1st Floor 10+ years Water Closet 1st Floor 3 ΕA 6 2-5 years

Category : Interior

Building : Annex

		•			Recommend	•
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Ceiling - Lay-in	1st Floor	1,564	SF	7	10+ years	
Ceiling - Plaster/Drywall	1st Floor	258	SF	7	10+ years	
Doors - Steel Doors incl hw	1st Floor	8	EA	7	6-10 years	
Drinking Fountains - Single Fountain	1st Floor	2	EA	7	6-10 years	
Floor - Tile Ceramic/ Porcelain	1st Floor	258	SF	7	10+ years	
Floor - Tile/Sheet	1st Floor	1,564	SF	7	10+ years	
Lighting - Lay-in	1st Floor	20	EA	7	6-10 years	
Walls - Concrete Block	1st Floor	4,577	SF	6	10+ years	
Security Cameras	1st Floor	2	EA	7	2-5 years	
	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Lighting - Lay-in Walls - Concrete Block	Ceiling - Lay-in1st FloorCeiling - Plaster/Drywall1st FloorDoors - Steel Doors incl hw1st FloorDrinking Fountains - Single Fountain1st FloorDrinking Fountains - Single Fountain1st FloorFloor - Tile Ceramic/ Porcelain1st FloorFloor - Tile/Sheet1st FloorLighting - Lay-in1st FloorWalls - Concrete Block1st Floor	Ceiling - Lay-in1st Floor1,564Ceiling - Plaster/Drywall1st Floor258Doors - Steel Doors incl hw1st Floor8Drinking Fountains - Single Fountain1st Floor2Floor - Tile Ceramic/ Porcelain1st Floor258Floor - Tile/Sheet1st Floor258Floor - Tile/Sheet1st Floor258Lighting - Lay-in1st Floor20Walls - Concrete Block1st Floor4,577	Ceiling - Lay-in1st Floor1,564SFCeiling - Plaster/Drywall1st Floor258SFDoors - Steel Doors incl hw1st Floor8EADrinking Fountains - Single Fountain1st Floor2EAFloor - Tile Ceramic/ Porcelain1st Floor258SFFloor - Tile/Sheet1st Floor258SFLighting - Lay-in1st Floor20EAWalls - Concrete Block1st Floor4,577SF	Ceiling - Lay-in1st Floor1,564SF7Ceiling - Plaster/Drywall1st Floor258SF7Doors - Steel Doors incl hw1st Floor8EA7Drinking Fountains - Single Fountain1st Floor2EA7Floor - Tile Ceramic/ Porcelain1st Floor258SF7Floor - Tile/Sheet1st Floor258SF7Lighting - Lay-in1st Floor20EA7Walls - Concrete Block1st Floor4,577SF6	Item - TypeLocationQuantityUOMRankReplacementCeiling - Lay-in1st Floor1,564SF710+ yearsCeiling - Plaster/Drywall1st Floor258SF710+ yearsDoors - Steel Doors incl hw1st Floor8EA76-10 yearsDrinking Fountains - Single Fountain1st Floor2EA76-10 yearsFloor - Tile Ceramic/ Porcelain1st Floor258SF710+ yearsFloor - Tile/Sheet1st Floor258SF710+ yearsLighting - Lay-in1st Floor20EA76-10 yearsWalls - Concrete Block1st Floor4,577SF610+ years



Category : Site Building : Site Recommend Location Replacement Item - Type Quantity UOM Comments Group Rank Athletic Surface - Asphalt SF 7 North 1.200 10+ years 20.250 SF 7 Surface - Synthetic North 10+ years Civil/Drainage Civil/ Drainage - Catch Basin ΕA Entire Site 10 6 10+ years Civil/ Drainage - Site Manhole Entire Site 10 FΑ 6 10+ years Fencina Fencing - Chain Link Entire Site 1,375 LF 6 10+ years Landscape Benches Entire Site 2 ΕA 7 10+ years ! SF Landscape - Grass Entire Site 14,471 6 10+ years I Landscape - Hardscape- Concrete Entire Site SF 6 10+ years 11,100 SF Landscape - Mulch Entire Site 2,500 6 6-10 years Parkway trees Entire Site 59 ΕA 6 10+ vears ! Parkway trees Entire Site 10 FΑ 6 2-5 years Play Area - Hardscape- Asphalt Entire Site 21.970 SF 6 6-10 years 1 Trash Receptacles Entire Site FΑ 6 6-10 years 1 2 Parking Lot Concrete Curbs Parking Lot- South LF 6 175 10+ years Parking Lot- South LF Interior Plantings 60 6 6-10 years Parking Lot- South SF 6-10 years Surface - Asphalt 13.000 6 Surface - Asphalt Parking Lot- South 650 SF 4 0-1 year Cracking. LF Vehicular Screening Parking Lot- South 175 6 10+ years Playground Equipment - School Age 5-12 South ΕA 7 10+ years 1 SF Surface - Poured Surface South 2.400 7 10+ years Sidewalks Sidewalks - Internal Walks Entire Site 250 LF 6 10+ years SF Sidewalks - Perimeter Sidewalks Entire Site 10.832 6 10+ years Signage Flag Pole - Flag Pole East side of property 1 ΕA 6 10+ years Marguee - Free Standing Back lighted w/ East side of property 1 EΑ 6 10+ years LED



¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	Intended Usage	Room Eocation	Number	Number		Alea	Alta	Stop	Duaru
Art Room	Regular Classroom	2nd Floor	201	201	722	131	132	Y	Y
Computer Lab	Regular Classroom	2nd Floor	203	201	720	117	106	Y	Y
Kindergarten	Faculty Lounge	2nd Floor	200	Teacher	337	0	0	Y	Y
Rinderganen	Taculty Lounge	211011001	200	lunch	557	Ū	0		1
Kindergarten	Kindergarten	1st Floor	103	103	717	131	132	Y	Y
Kindergarten	Regular Classroom	1st Floor	101	100	715	131	132	Ý	Y
Kindergarten	Regular Classroom	1st Floor	104	104	752	131	132	Ý	Y
Kindergarten	Regular Classroom	1st Floor	106	101	715	131	132	Ý	Y
Kindergarten	Science Classroom	2nd Floor	207	207	719	131	132	Ý	Ý
Regular Classroom	Regular Classroom	1st Floor	107	107	722	131	132	Ŷ	Ŷ
Regular Classroom	Regular Classroom	1st Floor	108	108	674	131	132	Ý	Ŷ
Regular Classroom	Regular Classroom	1st Floor	109	109	718	131	132	Ý	Ý
Regular Classroom	Regular Classroom	1st Floor	110	110	725	131	132	Ŷ	Ŷ
Regular Classroom	Regular Classroom	2nd Floor	202	202	725	131	132	Ý	Ý
Regular Classroom	Regular Classroom	2nd Floor	205	205	718	131	132	Ý	Ý
Regular Classroom	Regular Classroom	2nd Floor	206	206	721	131	132	Ý	Ý
Regular Classroom	Regular Classroom	2nd Floor	208	208	720	131	132	Ý	Y
Regular Classroom	Regular Classroom	2nd Floor	210	210	730	131	132	Ý	Ý
Regular Classroom	Regular Classroom	2nd Floor	211	211	718	131	132	Ý	Ý
Regular Classroom	Science Classroom	2nd Floor	204	204	725	131	132	Ŷ	Ý
Regular Classroom	Science Classroom	2nd Floor	209	209	720	131	132	Ý	Ý
Special Education	Health	1st Floor	100	100	471	78	79	Ý	Ý
								•	
Building : Annex									
Regular Classroom	Regular Classroom	1st Floor	1	1	867	102	104	Y	Y
Regular Classroom	Regular Classroom	1st Floor	10	10	871	102	104	Y	Y
Regular Classroom	Regular Classroom	1st Floor	2	2	871	102	104	Y	Y
Regular Classroom	Regular Classroom	1st Floor	3	3	868	102	104	Y	Y
Regular Classroom	Regular Classroom	1st Floor	4	4	878	102	104	Y	Y
Regular Classroom	Regular Classroom	1st Floor	5	5	871	102	104	Y	Y
Regular Classroom	Regular Classroom	1st Floor	6	6	880	102	104	Y	Y
Regular Classroom	Regular Classroom	1st Floor	7	7	871	102	104	Y	Y
Regular Classroom	Regular Classroom	1st Floor	8	8	880	102	104	Y	Y
Regular Classroom	Regular Classroom	1st Floor	9	9	867	102	104	Y	Y
Regular Classroom	Special Education	1st Floor	Resource	Special	367	50	25	N	Y
			room	educati					