

**Facility Assessment Report** 

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1945	1	16,847
Annex	2021	1	17,685
Linked Addition	1995	1	23,721
Campus Total			58,253

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	1						
	Exterior Doors - Store Front	#2 N	3	EA	7	10+ years	
	Exterior Doors - Transom Lite	#2 N	3	EA	7	10+ years	
	Exterior Doors - Store Front	#3 E	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	#3 E	2	EA	7	10+ years	
	Exterior Stairs - Concrete	#3 E	3	LF	7	10+ years	
	Entrance Control - Audio and Video	#4 E	1	EA	7	10+ years	
	Exterior Doors - Side lite	#4 E	1	EA	7	10+ years	
	Exterior Doors - Store Front	#4 E	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	#4 E	3	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#5 S	2	EA	7	10+ years	
	Exterior Stairs - Concrete	#5 S	7	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#6 S	1	EA	7	10+ years	
	Exterior Doors - Side lite	#6 S	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	#6 S	2	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#7 S	1	EA	7	10+ years	
	Exterior Doors - Side lite	#7 S	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	#7 S	2	EA	7	10+ years	
_Foundati	on						
	Foundation - Concrete	Entire Building	633	LF	7	10+ years	
	Superstructure - Steel	Entire Building	16,847	SF	7	10+ years	
		-				•	



Categor	ategory : Exterior		Building : Main				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	18	EA	7	10+ years	
Roof Sys							
	Coping - Metal	High Roof	177	LF	7	10+ years	
	Downspouts - Interior Downspouts	High Roof	20	LF	7	10+ years	
	Roof - Modified Bitumen	High Roof	1,881	SF	5	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	High Roof	1,881	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	35	LF	6	10+ years	
	Coping - Metal	Main Roof	566	LF	7	10+ years	Under construction, installation
	Downspouts - Interior Downspouts	Main Roof	85	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	14,966	SF	7	10+ years	
	Roof Hatch - Metal	Main Roof	, 1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	14,966	SF	7	10+ years	
Nalls							
	Canopy - Concrete/ Stucco	Entire Building	70	SF	6	10+ years	
	Canopy - Concrete/ Stucco	Entire Building	70	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	3,015	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,603	SF	6	10+ years	
Vindows							
	Curtain wall - Insulated Panel	Entire Building	1,008	SF	7	10+ years	
	Windows - Wood- Double-pane	Entire Building	2,433	SF	7	10+ years	
Categor	y : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emergen	cy System						
-	Emergency A/C Power - Corridors and Stairs	Entire Building	2,583	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	1,622	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	421	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	
			2	EA	6	6-10 years	

Campus Name: Beard Page : 2 of 41 Assessment Date: 10/25/2021



Catego	ry : Electrical		B	uilding	· Main		6445 W Strong STREET, Chicago, IL 60656
Calcgo	ry . Liceti icai			unung	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Security System - CCTV	Entire Building	16,847	SF	7	6-10 years	The security cameras are new and all
	Occurry Cystem GOTV	Entire Building	10,047	O1	,	o to years	work
	Security System - Intrusion Detection	Entire Building	16,847	SF	6	6-10 years	WOIK
	Exit Signs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	2	EΑ	6	6-10 years	
	Exit digital Manaparpood Room	Entire Ballating	_	_/\	O	o ro youro	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	6-10 years	
	amp	Entire Ballanig	'		O	o ro years	
	·						
Catego	ry : Fire Protection		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Newly installed
	Fire Alarm Strobe Lights	Entire Building	16,847	SF	7	6-10 years	Strobe lights are installed in all rooms
	Fire Alarm_System	Entire Building	16,847	SF	6	6-10 years	
Catago	ry : Mechanical		D	uilding	· Main		
Calego	ry . Mechanicai		<b>D</b>	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond			•			•	
	Heat Pump- Floor Mounted- Electric Heating	Roof	1	EA	7	10+ years	
	& DX Cooling- Remote Mounted		·	_, ,	•	.o. you.o	
	Compressor - Less than 3 tons						
	2000 tildii 2 tolio						
Boiler Sy	vstems						
•	Boiler Auxiliary- Condensing Hot Water -	Mechanical Room	2	EA	7	10+ years	
	1001 - 2000 HP					j	
	Chemical Pot Feeder	Mechanical Room	1	EA	7	6-10 years	
	Combustion Dampers	Mechanical Room	1	EA	6	10+ years	
	Condensing- Hot Water Boiler - 1001 - 2000	Mechanical Room	2	EA	7	10+ years	
	MBH					-	
	Glycol Feed System	Mechanical Room	1	EA	7	10+ years	
	Hot Water Pump	Mechanical Room	2	EA	7	6-10 years	
	Piping - Dual Temperature Pipes- Copper	Mechanical Room	300	LF	7	10+ years	
	Water Fill System	Mechanical Room	1	EA	7	6-10 years	
Heating	Devices						



Category : Mechanical

# Daniel C Beard Elementary School 6445 W Strong STREET, Chicago, IL 60656

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Unit Heater - Electric	1st Floor	3	EA	6	6-10 years	Comments
	Unit Heater - Gas	1st Floor	2	EA	7	10+ years	
	Fin Tube - Hot Water	Entire Building	72	LF	6	6-10 years	
	Wall Heater - Electric	Entire Building	3	EA	6	2-5 years	
	Cabinet Heaters - With Electric Coil	Entire Building	2	EA	7	10+ years	
_Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	200	LF	5	6-10 years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	2-5 years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	2-5 years	
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors	Entire Building	14	EA	6	6-10 years	
_Ventilatio							
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	7	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	7	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	7	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	4	EA	7	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Hot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	2	EA	7	10+ years	Installed in 2021
_Piping_							
. •	Domestic Piping-Hot Water Return Lines	Entire Building	16,847	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	16,847	SF	6	6-10 years	
	Sanitary Piping	Entire Building	16,847	SF	6	6-10 years	
	Storm Piping	Entire Building	16,847	SF	6	6-10 years	
	Vent Piping	Entire Building	16,847	SF	6	6-10 years	
Catego	ry : Room		В	uilding	: Main		
	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments

**Building: Main** 



					Replacement	
strative Suites/Offices					7	
Ceiling - Lay-in	1st Floor- Office 3	320	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor- Office 3	3	ĒΑ	7	10+ years	
Floor - Tile	1st Floor- Office 3	320	SF	6	10+ years	
Lighting - Lay-in	1st Floor- Office 3	2	EA	7	10+ years	
Power Distribution	1st Floor- Office 3	6	EΑ	6	10+ years	
Storage/ Closet	1st Floor- Office 3	25	SF	7	10+ years	
Storage/ Closet	1st Floor- Office 3	8	SF	5	10+ years	
Walls - Concrete Block	1st Floor- Office 3	720	SF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor-Engineer's Office	80	SF	6	6-10 years	
Doors - Steel Doors incl hw	1st Floor-Engineer's Office	1	EA	7	6-10 years	
Floor - Concrete	1st Floor-Engineer's Office	80	SF	7	6-10 years	
Lighting - Pendent/Surface	1st Floor-Engineer's Office	1	EA	7		
					6-10 years	
Power Distribution	1st Floor-Engineer's Office	8	EA	6	10+ years	
Walls - Concrete Block	1st Floor-Engineer's Office	395	SF	6	10+ years	
Ceiling - Lay-in	1st Floor-Nurse office	660	SF	7	6-10 years	
Doors - Wood Doors inclu hw	1st Floor-Nurse office	1	EA	7	6-10 years	
Floor - Tile	1st Floor-Nurse office	660	SF	7	10+ years	
Lighting - Pendent/Surface	1st Floor-Nurse office	10	EA	7	6-10 years	
Power Distribution	1st Floor-Nurse office	16	EA	7	10+ years	
Walls - Concrete Block	1st Floor-Nurse office	515	SF	7	10+ years	
Walls - Plaster/Drywall	1st Floor-Nurse office	275	SF	7	10+ years	
Ceiling - Lay-in	1st Floor-Teacher's Room	193	SF	7	6-10 years	
Doors - Wood Doors inclu hw	1st Floor-Teacher's Room	2	EA	7	6-10 years	
Floor - Tile	1st Floor-Teacher's Room	193	SF	7	10+ years	
Lighting - Pendent/Surface	1st Floor-Teacher's Room	2	EA	7	6-10 years	
Power Distribution	1st Floor-Teacher's Room	4	EΑ	7	10+ years	
Walls - Concrete Block	1st Floor-Teacher's Room	434	SF	6	10+ years	
Work SInk	1st Floor-Teacher's Room	1	EΑ	5	10+ years	
Ceiling - Lay-in	1st floor-102 art classroom (used to be Faculty Lounge)	660	SF	7	6-10 years	
Doors - Transom Window	1st floor-102 art classroom (used to	58	SF	7	6-10 years	
	be Faculty Lounge)					
Doors - Wood Doors inclu hw	1st floor-102 art classroom (used to be Faculty Lounge)	1	EA	7	10+ years	
Floor - Tile	1st floor-102 art classroom (used to be Faculty Lounge)	660	SF	7	10+ years	
Lighting - Pendent/Surface	1st floor-102 art classroom (used to	5	EA	7	6-10 years	
	be Faculty Lounge)	_		_		
Power Distribution	1st floor-102 art classroom (used to be Faculty Lounge)	6	EA	7	10+ years	
Storage/ Closet	1st floor-102 art classroom (used to be Faculty Lounge)	25	SF	7	6-10 years	
Walls - Concrete Block	1st floor-102 art classroom (used to be Faculty Lounge)	515	SF	7	10+ years	
Walls - Plaster/Drywall	1st floor-102 art classroom (used to	275	SF	7	10+ years	



					Replacement	
	be Faculty Lounge)					
nch & Multipurpose Room						
Ceiling - Lay-in	1st Floor	1,605	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
Floor - Tile	1st Floor	1,605	SF	7	6-10 years	
Lighting - Pendent/Surface	1st Floor	1,003	EA	7	6-10 years	
Storage/ Closet	1st Floor	110	SF	7	•	
Walls - Concrete Block	1st Floor	2,090	SF SF	7	10+ years 10+ years	
Walls - College Block	13111001	2,030	01	,	10+ years	
echanical/ Service Rooms						
Boiler Room	1st Floor	415	SF	7	6-10 years	
Janitor's Closet	1st Floor	20	SF	7	6-10 years	
Storage Room	1st Floor	35	SF	7	10+ years	
Storage Room	1st Floor	91	SF	7	10+ years	
Storage Room	1st Floor	35	SF	7	10+ years	
Storage Room	1st Floor	35	SF	7	10+ years	
Vaults	1st Floor	55	SF	7	6-10 years	
2442.2						
estroom Accessories	1st Floor-102 restroom	22	SF	5	2-5 years	
Ceiling - Lay-in	1st Floor-102 restroom	22	SF	7	6-10 years	
Doors - Wood Doors inclu hw	1st Floor-102 restroom	1	EA	7	6-10 years	
Floor - Tile	1st Floor-102 restroom	22	SF	6	6-10 years	
Lavatory	1st Floor-102 restroom	2	EA	5	2-5 years	
Lighting - Pendent/Surface	1st Floor-102 restroom	1	EA	7	6-10 years	
Walls - Concrete Block	1st Floor-102 restroom	145	SF	6	,	
Accessories		218	SF	7	10+ years	
	1st Floor Boys Restroom				6-10 years	
Ceiling - Lay-in	1st Floor-Boys Restroom	218	SF	7	6-10 years	
Doors - Wood Doors inclu hw	1st Floor-Boys Restroom	1	EA	7	6-10 years	
Floor - Tile	1st Floor-Boys Restroom	210	SF	6	10+ years	
Floor - Tile	1st Floor-Boys Restroom	8	SF	6	10+ years	
Floor Drain	1st Floor-Boys Restroom	1	EA	7	10+ years	
Hand Dryer	1st Floor-Boys Restroom	1	EA	5	2-5 years	
Lavatory	1st Floor-Boys Restroom	2	EA	6	10+ years	
Lighting - Pendent/Surface	1st Floor-Boys Restroom	2	EA	7	6-10 years	
Partitions	1st Floor-Boys Restroom	3	EA	7	6-10 years	
Urinals	1st Floor-Boys Restroom	3	EA	6	10+ years	
Walls - Concrete Block	1st Floor-Boys Restroom	280	SF	6	10+ years	
Walls - Structural Glazed Tile	1st Floor-Boys Restroom	295	SF	6	10+ years	
Water Closet	1st Floor-Boys Restroom	2	EA	6	10+ years	
Water Closet	1st Floor-Boys Restroom	1	EA	6	10+ years	
Accessories	1st Floor-Girls Restroom	218	SF	7	6-10 years	
Ceiling - Lay-in	1st Floor-Girls Restroom	218	SF	7	6-10 years	
	1st Floor-Girls Restroom	1	EΑ	7	6-10 years	
Doors - Wood Doors inclu hw	131 1001-0113 1(631100111	•			0-10 years	



					Replacement	
Floor Drain	1st Floor-Girls Restroom	1	EA	7	10+ years	
Hand Dryer	1st Floor-Girls Restroom	1	EA	7	6-10 years	
Lavatory	1st Floor-Girls Restroom	2	EA	6	6-10 years	
Lighting - Pendent/Surface	1st Floor-Girls Restroom	2	EA	7	6-10 years	
Partitions	1st Floor-Girls Restroom	6	EA	7	6-10 years	
Walls - Concrete Block	1st Floor-Girls Restroom	280	SF	6	10+ years	
Walls - Structural Glazed Tile	1st Floor-Girls Restroom	295	SF	6	10+ years	
Water Closet	1st Floor-Girls Restroom	6	EA	6	10+ years	
Accessories	1st Floor-Men's Restroom	20	SF	7	6-10 years	
Ceiling - Lay-in	1st Floor-Men's Restroom	20	SF	7	6-10 years	
Doors - Wood Doors inclu hw	1st Floor-Men's Restroom	1	EA	7	6-10 years	
Floor - Tile	1st Floor-Men's Restroom	20	SF	6	10+ years	
Lavatory	1st Floor-Men's Restroom	1	EA	6	10+ years	
Lighting - Pendent/Surface	1st Floor-Men's Restroom	1	EA	7	6-10 years	
Walls - Concrete Block	1st Floor-Men's Restroom	105	SF	6	10+ years	
Walls - Tile	1st Floor-Men's Restroom	90	SF	6	10+ years	
Water Closet	1st Floor-Men's Restroom	1	EA	6	10+ years	
Accessories	1st Floor-Office 3 Restroom	22	SF	5	2-5 years	
Ceiling - Plaster/Drywall	1st Floor-Office 3 Restroom	22	SF	7	6-10 years	
Doors - Wood Doors inclu hw	1st Floor-Office 3 Restroom	1	EA	5	6-10 years	
Floor - Tile	1st Floor-Office 3 Restroom	22	SF	6	10+ years	
Lavatory	1st Floor-Office 3 Restroom	1	EA	6	10+ years	
Lighting - Pendent/Surface	1st Floor-Office 3 Restroom	1	EA	7	6-10 years	
Walls - Concrete Block	1st Floor-Office 3 Restroom	32	SF	6	10+ years	
Walls - Plaster/Drywall	1st Floor-Office 3 Restroom	100	SF	6	10+ years	
Water Closet	1st Floor-Office 3 Restroom	1	EΑ	6	10+ years	
Accessories	1st Floor-Women's Restroom	95	SF	5	2-5 years	
Ceiling - Lay-in	1st Floor-Women's Restroom	95	SF	7	6-10 years	
Doors - Wood Doors inclu hw	1st Floor-Women's Restroom	1	EΑ	7	6-10 years	
Floor - Concrete	1st Floor-Women's Restroom	95	SF	7	10+ years	
Lavatory	1st Floor-Women's Restroom	1	EA	6	10+ years	
Lighting - Pendent/Surface	1st Floor-Women's Restroom	1	EA	7	6-10 years	
Walls - Concrete Block	1st Floor-Women's Restroom	202	SF	7	10+ years	
Walls - Tile	1st Floor-Women's Restroom	160	SF	7	10+ years	
Water Closet	1st Floor-Women's Restroom	1	EA	7	10+ years	
Accessories	1st floor-104 restroom	22	SF	7	6-10 years	
Ceiling - Lay-in	1st floor-104 restroom	22	SF	5	2-5 years	
Doors - Wood Doors inclu hw	1st floor-104 restroom	1	EA	7	6-10 years	
Floor - Tile	1st floor-104 restroom	22	SF	6	10+ years	
Lavatory	1st floor-104 restroom	1	EA	6	10+ years	
Lighting - Pendent/Surface	1st floor-104 restroom	1	EΑ	7	6-10 years	
Walls - Concrete Block	1st floor-104 restroom	145	SF	6	10+ years	
Water Closet	1st floor-104 restroom	1	EA	6	10+ years	
Accessories	Inside classroom 105	25	SF	7	6-10 years	
Ceiling - Plaster/Drywall	Inside classroom 105	25	SF	7	10+ years	
Doors - Wood Doors inclu hw						
Floor - Tile	Inside classroom 105 Inside classroom 105	1 25	EA SF	7 7	10+ years 10+ years	



Floor - Tile

## Daniel C Beard Elementary School 6445 W Strong STREET, Chicago, IL 60656

Replacement

						Replacement	
	Lavatory	Inside classroom 105	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Inside classroom 105	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Inside classroom 105	165	SF	7	10+ years	
	•					•	
	Water Closet	Inside classroom 105	1	EA	7	10+ years	
• •	•		_				
Catego	ory : Classroom		В	uilding	: Main		
		1	0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classro	om #104 (Regular Classroom)						
	Casework	1st Floor	73	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	1,321	SF	7	10+ years	
	Doors - Transom Window	1st Floor	130	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,321	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	15	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	25	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	721	SF	7	10+ years	
			121				
	Work Sink	1st Floor	1	EA	7	6-10 years	
01	#405 (D I. Ol )						
_Classro	om #105 (Regular Classroom)						
	Casework	1st Floor	45	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	812	SF	7	6-10 years	
	Doors - Transom Window	1st Floor	125	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	812	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	795	SF	6	10+ years	
						,	
Classro	om #106 (Regular Classroom)						
	Casework	1st Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	814	SF	7	10+ years	
	Doors - Transom Window	1st Floor	125	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	123	EA	7	6-10 years	
	Floor - Tile	1st Floor	814	SF	7	•	
						10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	795	SF	6	10+ years	
_Classro	om #107 (Regular Classroom)						
	Casework	1st Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	812	SF	7	10+ years	
	Doors - Transom Window	1st Floor	125	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	125	EA	7		
	Doors - wood Doors Inclu nw	1St Floor	040	EA	7	10+ years	

1st Floor

812 SF

7

10+ years



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	795	SF	6	10+ years	
_Classroo	om #108 (Regular Classroom)						
	Casework	1st Floor	45	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	814	SF	7	6-10 years	
	Doors - Transom Window	1st Floor	125	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	814	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	672	SF	6	10+ years	
Classroo	om #109 (Faculty Lounge)						
	Casework	1st Floor	45	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	812	SF	7	10+ years	
	Doors - Transom Window	1st Floor	125	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	6-10 years	
	Floor - Tile	1st Floor	812	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	8	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	672	SF	6	10+ years	
_Classroo	om #110 (Regular Classroom)						
	Casework	1st Floor	45	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	814	SF	7	10+ years	
	Doors - Transom Window	1st Floor	125	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	6-10 years	
	Floor - Tile	1st Floor	814	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	8	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	795	SF	6	10+ years	
_Classroo	om #111 (Regular Classroom)						
	Casework	1st Floor	45	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	812	SF	7	10+ years	
	Doors - Transom Window	1st Floor	58	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	812	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	795	SF	7	10+ years	



Catego	ry : Classroom		В	uilding		-		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroc	om #112 (Regular Classroom)							
	Casework	1st Floor	45	LF	6	6-10 years		
	Ceiling - Lay-in	1st Floor	814	SF	7	10+ years		
	Chalk Board	1st Floor	10	LF	4	2-5 years		
	Doors - Transom Window	1st Floor	58	SF	5	2-5 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	814	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	795	SF	6	10+ years		
Catego	ry : Interior		В	Building : Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor	•		•			•		
	Ceiling - Lay-in	1st Floor	3,250	SF	7	6-10 years		
	Doors - Steel Doors incl hw	1st Floor	14	EA	7	6-10 years		
	Drinking Fountains - Single Fountain	1st Floor	2	EA	5	6-10 years		
	Floor - Tile/Sheet	1st Floor	3,250	SF	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	24	EA	6	10+ years		
	Walls - Masonry	1st Floor	480	SF	6	10+ years		
	vvalis - iviasorii v	13(1100)						

Campus Name: Beard Page : 10 of 41 Assessment Date: 10/25/2021



Category : Exterior Building : Annex

Categoi	gory : Exterior		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	12 W	1	EA	7	10+ years	
	Exterior Doors - Store Front	12 W	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	12 W	1	EA	7	10+ years	
	Exterior Doors - Store Front	13 N	2	EA	7	10+ years	
	Power Door Operator and Controls	13 N	1	EA	7	10+ years	
	Entrance Control - Audio and Video	14 S	1	EA	7	10+ years	
	Exterior Doors - Store Front	14 S	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	14 S	1	EA	7	10+ years	
	Power Door Operator and Controls	14 S	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	15 Service Garage	2	EA	7	10+ years	
Foundation	on						
	Foundation - Concrete	Entire Building	664	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	13,660	SF	7	10+ years	
ighting							
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	7	10+ years	
Roof Sys	tem						
•	Access Ladder - Metal	Entire Building	1	EA	7	10+ years	
	Coping - Metal	Entire Building	664	LF	7	10+ years	
	Downspouts - Interior Downspouts	Entire Building	10	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Entire Building	664	LF	7	10+ years	
	Roof - Modified Bitumen	Entire Building	13,660	SF	7	10+ years	
	Roof Hatch - Metal	Entire Building	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Entire Building	13,660	SF	7	10+ years	
	Concrete Topping						
Walls							
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	9,040	SF	7	10+ years	
Windows							
	Storefront Windows	Entire Building	1,200	SF	7	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	1,350	SF	7	10+ years	
	pane	•	,			•	



Catego	ry : Electrical		В	uilding	: Annex		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	ncy System						
	Emergency Battery Packs - Corridors and Stairs	1st Floor	8	EA	7	6-10 years	
	Emergency Battery Packs - Multipurpose Room	1st Floor	1	EA	7	6-10 years	
	Emergency Battery Packs - Students Toilets	1st Floor	4	EA	7	6-10 years	
	Emergency A/C Power - Corridors and Stairs	1st Floor	6	SF	7	10+ years	
	Emergency A/C Power - Multipurpose Room	1st Floor	1	SF	7	10+ years	
	Emergency A/C Power - Students Toilets	1st Floor	5	SF	7	10+ years	
	Exit Signs - Corridors and Stairs	1st Floor	6	EA	7	6-10 years	
	Security System - CCTV	1st Floor	17,685	SF	7	6-10 years	
	Security System - Intrusion Detection	1st Floor	17,685	SF	7	6-10 years	
Main Se		=					
	Main Electrical Service - 800 A and 120/208/3PH	1st Floor	1	EA	7	10+ years	
Power D	Distribution						
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	1st Floor	5	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Annex		
<b>0</b>	Name Trans	Lasatian	0	11014	Danila	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alaı							
	Fire Alarm Panel	1st Floor	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	1st Floor	17,685	SF	7	10+ years	
	Fire Alarm_System	1st Floor	17,685	SF	7	10+ years	
Sprinkle	r System						
	Dry Sprinkler System	1st Floor	17,685	SF	7	10+ years	
	Sprinkler Heads	1st Floor	17,685	SF	7	10+ years	
	Sprinkler Piping	1st Floor	17,685	SF	7	10+ years	
Catego	ry : Mechanical		В	uilding	: Annex		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ditioning						
ALL COLL	Heat Pump- Ceiling Mounted- Electric	Roof	1	EA	7	10+ years	



Catego	ry : Mechanical		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Compressor - 4 - 5 tons						
Air Hand	ling Systems						
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	7	10+ years	
	Electric and DX Cooling w/ Self Contained						
	Compressor - 10 - 20 tons	5 (			_	4.0	
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	7	10+ years	
	Electric and DX Cooling w/ Self Contained						
	Compressor - 21 - 30 tons						
	Davida da						
Heating I	Unit Heater - Hot Water	1st Floor	1	EA	7	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	3	EA	7	•	
	Cabinet Heaters - Willi Mut Water Cull	Little building	3	EA	,	10+ years	
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	1st Floor	1,500	LF	7	10+ years	
						-	
Tempera	ture Control						
	DDC System	1st Floor	17,685	SF	7	10+ years	Work in progress
	Electric Thermostat	1st Floor	2	EΑ	7	10+ years	
	Thermostats - DDC	1st Floor	14	EA	7	10+ years	
Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Roof	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Roof	3	EA	7	10+ years	
	CFM					•	
	Exhaust Fans- Roof Mounted - Less than	Roof	1	EA	7	10+ years	
	500 CFM					•	
Catego	ry : Plumbing		R	uildina	: Annex		
- a.ogo	, ,			a.i.a.i.ig		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - Less than 150000 BTU/HR	1st Floor	2	EA	7	10+ years	
Piping							
	Domestic Piping-Hot Water Return Lines	1st Floor	17,685	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	1st Floor	17,685	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to	1st Floor	17,685	SF	7	10+ years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply	1st Floor	17,685	SF	7	10+ years	
	(Horizontal Lines)						



Catego	ry : Plumbing		В	uilding	: Annex		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply	1st Floor	17,685	SF	7	10+ years	
	(Risers)						
	Domestic Piping-Hot/Cold Water Supply	1st Floor	17,685	SF	7	10+ years	
	(from Risers to Fixtures)						
	Sanitary Piping	1st Floor	17,685	SF	7	10+ years	
	Storm Piping	1st Floor	17,685	SF	7	10+ years	
	Vent Piping	1st Floor	17,685	SF	7	10+ years	
	_		_		_		
atego	ry : Room		В	uilding	: Annex		
roup	Itom Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
roup	Item - Type	Location	Quantity	UOIVI	Kalik	Replacement	Comments
<u>taınımı</u>	rative Suites/Offices	222	005		7	40	
	Ceiling - Lay-in	220 workroom	325	SF	7	10+ years	
	Doors - Wood Doors inclu hw	220 workroom	1	EA	7	10+ years	
	Floor - Carpet	220 workroom	325	SF	6	2-5 years	
	Lighting - Lay-in	220 workroom	6	EA	7	10+ years	
	Power Distribution	220 workroom	6	EΑ	7	10+ years	
	Walls - Plaster/Drywall	220 workroom	550	SF	6	1-2 years	Deep scratches and dents from construction/moving
	Ceiling - Lay-in	221	165	SF	7	10+ years	S
	Doors - Wood Doors inclu hw	221	1	EA	7	10+ years	
	Floor - Carpet	221	165	SF	7	6-10 years	
	Lighting - Lay-in	221	4	EA	7	6-10 years	
	Power Distribution	221	6	EΑ	7	10+ years	
	Walls - Plaster/Drywall	221	320	SF	7	10+ years	
	Ceiling - Lay-in	225	145	SF	7	•	
						10+ years	
	Doors - Wood Doors inclu hw	225	1	EA	7	10+ years	
	Floor - Carpet	225	145	SF	7	6-10 years	
	Lighting - Lay-in	225	2	EA	7	6-10 years	
	Power Distribution	225	6	EA	7	10+ years	
	Walls - Plaster/Drywall	225	280	SF	7	10+ years	
itchen							
	Ceiling - Lay-in	1st Floor	410	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	410	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	6	ĒΑ	7	6-10 years	
	Storage/ Closet	1st Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	920	SF	7	10+ years	
unch &	Multipurpose Room						
<u></u>	Ceiling - Lay-in	222	790	SF	7	10+ years	
	Doors - Wood Doors inclu hw	222	1	EA	7	10+ years	

Campus Name: Beard Page : 14 of 41 Assessment Date: 10/25/2021



Catego	ry : Room		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	222	790	SF	7	10+ years	
	Lighting - Lay-in	222	9	EA	7	6-10 years	
	Market Board	222	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	222	1,320	SF	7	10+ years	
	Ceiling - Lay-in	223	850	SF	7	10+ years	
	Doors - Store Front	223	2	EA	7	10+ years	
	Floor - Tile	223	850	SF	7	10+ years	
	Lighting - Lay-in	223	9	ĒΑ	7	6-10 years	
	Market Board	223	16	LF	7	6-10 years	
	Storage/ Closet	223	195	SF	7	10+ years	
	Walls - Plaster/Drywall	223	1,380	SF	7	10+ years	
	,		•			,	
1DF_ID							
	Doors - Wood Doors inclu hw	230 IDF	1	EA	7	10+ years	
	Finishes	230 IDF	100	SF	7	10+ years	
	Other Cooling Unit	230 IDF	1	EA	7	10+ years	
1echani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	65	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	140	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	125	SF	7	10+ years	
	Storage Room	1st Floor	206	SF	7	10+ years	
	Storage Room	1st Floor	195	SF	7	10+ years	
) o o tro o n	_						
estroor	Accessories	All Gender East	25	SF	7	10+ years	
	Doors - Wood Doors inclu hw	All Gender East	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	All Gender East	95	SF	7		
				SF EA	7 7	10+ years	
	Floor Drain	All Gender East	1			10+ years	
	Hand Dryer	All Gender East	1	EΑ	7	10+ years	
	Lavatory	All Gender East	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	All Gender East	5	EA	7	10+ years	
	Walls - Tile	All Gender East	320	SF	7	10+ years	
	Water Closet	All Gender East	1	EA	7	10+ years	
	Accessories	All Gender West	25	SF	7	10+ years	
	Ceiling - Plaster/Drywall	All Gender West	110	SF	7	10+ years	
	Doors - Wood Doors inclu hw	All Gender West	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	All Gender West	110	SF	7	10+ years	
	Floor Drain	All Gender West	1	EA	7	10+ years	
	Hand Dryer	All Gender West	1	EA	7	10+ years	
	Lavatory	All Gender West	1	EA	7	10+ years	
	Lighting - Pendent/Surface	All Gender West	5	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	All Gender West	340	SF	7	10+ years	

Campus Name: Beard Page : 15 of 41 Assessment Date: 10/25/2021



Catego	ry : Room		В	uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	All Gender West	1	EA	7	10+ years	
	Accessories	Inside 201	55	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside 201	55	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Inside 201	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 201	55	SF	7	10+ years	
	Floor Drain	Inside 201	1	EA	7	10+ years	
	Hand Dryer	Inside 201	1	EA	7	10+ years	
	Lavatory	Inside 201	1	EA	7	10+ years	
	Lighting - Lay-in	Inside 201	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Inside 201	300	SF	7	10+ years	
	Water Closet	Inside 201	1	EA	7	10+ years	
	Accessories	Inside 202	55	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside 202	55	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Inside 202	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 202	55	SF	7	10+ years	
	Floor Drain	Inside 202	1	EA	7	10+ years	
	Hand Dryer	Inside 202	1	EA	7	10+ years	
	Lavatory	Inside 202	1	EA	7	10+ years	
	Lighting - Lay-in	Inside 202	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Inside 202	55	SF	7	10+ years	
	Water Closet	Inside 202	1	EA	7	10+ years	
	Accessories	Inside 203	55	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside 203	55	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Inside 203	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 203	55	SF	7	10+ years	
	Floor Drain	Inside 203	1	EA	7	10+ years	
	Hand Dryer	Inside 203	1	EA	7	10+ years	
	Lavatory	Inside 203	1	EA	7	10+ years	
	Lighting - Lay-in	Inside 203	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Inside 203	300	SF	7	10+ years	
	Water Closet	Inside 203	1	EA	7	10+ years	
	Accessories	Inside 204	55	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside 204	55	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Inside 204	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 204	55	SF	7	10+ years	
	Floor Drain	Inside 204	1	EA	7	10+ years	
	Hand Dryer	Inside 204	1	EA	7	10+ years	
	Lavatory	Inside 204	1	EΑ	7	10+ years	
	Lighting - Lay-in	Inside 204	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Inside 204	300	SF	7	10+ years	
	Water Closet	Inside 204	1	EA	7	10+ years	
	Accessories	Inside 205	55	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside 205	55	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Inside 205	1	EA	7	10+ years	

Campus Name: Beard Page : 16 of 41 Assessment Date: 10/25/2021



Catego	ry : Room		В	uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	Inside 205	55	SF	7	10+ years	
	Floor Drain	Inside 205	1	EA	7	10+ years	
	Hand Dryer	Inside 205	1	EA	7	10+ years	
	Lavatory	Inside 205	1	EA	7	10+ years	
	Lighting - Lay-in	Inside 205	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Inside 205	300	SF	7	10+ years	
	Water Closet	Inside 205	1	EA	7	10+ years	
	Accessories	Inside 206	55	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside 206	55	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Inside 206	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 206	55	SF	7	10+ years	
	Floor Drain	Inside 206	1	ĒΑ	7	10+ years	
	Hand Dryer	Inside 206	1	EA	7	10+ years	
	Lavatory	Inside 206	1	EΑ	7	10+ years	
	Lighting - Lay-in	Inside 206	1	EΑ	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Inside 206	300	SF	7	10+ years	
	Water Closet	Inside 206	1	EA	7	10+ years	
	Accessories	Inside 200	55	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside 207	55	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Inside 207	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 207	55	SF	7	10+ years	
	Floor Drain	Inside 207	1	EA	7	10+ years	
	Hand Dryer	Inside 207	1	EA	7	•	
	Lavatory	Inside 207	1	EA	7	10+ years 10+ years	
	Lighting - Lay-in	Inside 207	1	EA	7		
	Walls - Tile Ceramic/ Porcelain	Inside 207	300	SF	7	6-10 years	
	Water Closet	Inside 207	300	EA	7	10+ years 10+ years	
	Accessories	Inside 207 Inside 208	55	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside 208	55	SF	7	,	
	Doors - Wood Doors inclu hw		55 1	SF EA		10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 208	55	SF	7	10+ years	
		Inside 208	55 1	Sr EA	7	10+ years	
	Floor Drain	Inside 208	1 1		7	10+ years	
	Hand Dryer	Inside 208	1	EΑ	7	6-10 years	
	Lavatory	Inside 208	1	EΑ	7	10+ years	
	Lighting - Lay-in	Inside 208	1	EA SF	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Inside 208	300		7	10+ years	
	Water Closet	Inside 208	1	EA	7	10+ years	
	Accessories	Inside 209	55	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside 209	55	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Inside 209	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 209	55	SF	7	10+ years	
	Floor Drain	Inside 209	1	EΑ	7	10+ years	
	Hand Dryer	Inside 209	1	EA	7	10+ years	
	Lavatory	Inside 209	1	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Annex		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	Inside 209	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Inside 209	300	SF	7	10+ years	
	Water Closet	Inside 209	1	EA	7	10+ years	
	Accessories	Inside 210	55	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside 210	55	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Inside 210	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 210	55	SF	7	10+ years	
	Floor Drain	Inside 210	1	EA	7	10+ years	
	Hand Dryer	Inside 210	1	EA	7	10+ years	
	Lavatory	Inside 210	1	EA	7	10+ years	
	Lighting - Lay-in	Inside 210	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Inside 210	300	SF	7	10+ years	
	Water Closet	Inside 210	1	EA	7	10+ years	
	Accessories	Mens	50	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Mens	170	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Mens	170	SF	7	10+ years	
	Floor Drain	Mens	1	ĒΑ	7	10+ years	
	Hand Dryer	Mens	1	EA	7	10+ years	
	Lavatory	Mens	2	EΑ	7	10+ years	
	Lighting - Lay-in	Mens	6	EΑ	7	10+ years	
	Partitions	Mens	2	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Mens	110	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Mens	300	SF	7	10+ years	
	Water Closet	Mens	2	EA	7	10+ years	
	Accessories	Women's	50	SF	5	10+ years	Sanitary napkin dispenser isn't
	Accessories	Women's	30	OI.	J	10+ years	installed yet.
	Ceiling - Plaster/Drywall	Women's	170	SF	7	10+ years	installed yet.
	Floor - Tile Ceramic/ Porcelain	Women's	170	SF	7	10+ years	
	Floor Drain	Women's	170	EA	7	•	
			1 1	EA	7 7	10+ years	
	Hand Dryer	Women's	•			10+ years	
	Lavatory	Women's	2	EA EA	7	10+ years	
	Lighting - Lay-in	Women's	6		7	10+ years	
	Partitions	Women's	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Women's	110	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Women's	300	SF	7	10+ years	
	Water Closet	Women's	2	EA	7	10+ years	
atego	ry : Classroom		В	uilding	: Annex		
				11611		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
assroc	om #201 (Regular Classroom)	1st Floor	40	1.5	7	10	
	Casework		18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	800	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,280	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #202 (Regular Classroom)						
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	800	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,280	SF	7	10+ years	
	Work Sink	1st Floor	1,200	EA	7	10+ years	
						, , , , , , , , , , , , , , , , , , ,	
Classroo	om #203 (Regular Classroom)						
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	800	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,280	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #204 (Regular Classroom)						
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	800	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,280	SF	7	10+ years	
	Work Sink	1st Floor	1,200	EA	7	10+ years	
01	(1005 (Dl. a Ole						
_Uassroo	om #205 (Regular Classroom)	4 . 🗔				40	
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	800	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Annex		W Strong STREET, Officago, IE 00030
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	800	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,280	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #206 (Regular Classroom)						
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	800	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,280	SF	7	10+ years	
	Work Sink	1st Floor	1,200	EA	7	10+ years	
Classroo	om #207 (Regular Classroom)						
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	800	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,280	SF	7	10+ years	
	Work Sink	1st Floor	1,200	EA	7	10+ years	
Classroo	om #208 (Regular Classroom)						
	Casework	1st Floor	18	LF	7	10+ years	
	Casework Ceiling - Lay-in	1st Floor	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	800	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	,	
	Marker Board	1st Floor 1st Floor	10	LF	7	6-10 years	
		1st Floor	55	SF	7	6-10 years	
	Storage/ Closet Walls - Plaster/Drywall	1st Floor		SF SF	7 7	10+ years	
	Walls - Plaster/Drywall Work Sink	1st Floor 1st Floor	1,280 1	EA	7	10+ years 10+ years	
Classes	om #209 (Regular Classroom)						
Ciassio	, ,	4 at Ela	10	1 -	7	40	
	Casework	1st Floor	18	LF	7	10+ years	



ALL A	JCI 10013						5445 W Strong STREET, Chicago, IL 60656
Catego	ry : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Ceiling - Lay-in	1st Floor	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	800	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,280	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #210 (Regular Classroom)						
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	800	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	12	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Catego	ry : Interior		В	uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor						-	
	Ceiling - Lay-in	1st Floor	595	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,190	SF	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	3	ĒΑ	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,785	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	28	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,828	SF	7	10+ years	
			_,0_0		-	,	



Category : Exterior Building : Linked Addition

						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
trance	9						
	Entrance Control - Audio and Video	#1 N	1	EA	7	10+ years	
	Exterior Doors - Side lite	#1 N	6	EA	7	10+ years	
	Exterior Doors - Store Front	#1 N	2	ΕA	7	10+ years	
	Exterior Doors - Transom Lite	#1 N	_ 1	ΕA	7	10+ years	
	Entrance Control - Audio and Video	#10 S	1	EA	7	10+ years	
	Exterior Doors - Side lite	#10 S	2	EΑ	7	10+ years	
	Exterior Doors - Store Front	#10 S	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	#10 S	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#10 G #11 W	1	EA	6	6-10 years	
	Entrance Control - Audio and Video	#11 VV #8 S	1	EA	7	10+ years	
	Exterior Doors - Side lite	#8 S	6	EA	7	10+ years	
	Exterior Doors - Store Front	#8 S		EA	7		
			2			10+ years	
	Exterior Doors - Transom Lite	#8 S	1	EA	7	10+ years	<b>D</b> 1 (
	Exterior Doors - Exterior Steel Door	#9 E	1	EA	7	10+ years	Door bent
undat	ion						
	Foundation - Concrete	Entire Building	678	LF	7	10+ years	
	Superstructure - Steel	Entire Building	23,961	SF	7	10+ years	
	'	3	,			,	
htina							
ghting	Exterior Lighting - Wall Mounted	Entire Building	12	EA	7	10+ years	
	0 0	Entire Building	12	EA	7	10+ years	
	stem						
	stem Coping - Metal	Low Roof	60	LF	7	10+ years	
	stem  Coping - Metal  Downspouts - Interior Downspouts	Low Roof Low Roof	60 15	LF LF	7 7	10+ years 10+ years	
ghting oof Sy	stem  Coping - Metal  Downspouts - Interior Downspouts  Roof - Modified Bitumen	Low Roof Low Roof Low Roof	60 15 1,238	LF LF SF	7 7 7	10+ years 10+ years 10+ years	
	Stem  Coping - Metal  Downspouts - Interior Downspouts  Roof - Modified Bitumen  Roof Structure - Steel / Metal Deck/	Low Roof Low Roof	60 15	LF LF	7 7	10+ years 10+ years	
	Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Structure - Steel / Metal Deck/ Concrete Topping	Low Roof Low Roof Low Roof Low Roof	60 15 1,238 1,238	LF LF SF SF	7 7 7 7	10+ years 10+ years 10+ years 10+ years	
	Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Structure - Steel / Metal Deck/ Concrete Topping Access Ladder - Metal	Low Roof Low Roof Low Roof Low Roof Main Roof	60 15 1,238 1,238	LF LF SF SF	7 7 7 7	10+ years 10+ years 10+ years 10+ years	
	Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Structure - Steel / Metal Deck/ Concrete Topping Access Ladder - Metal Chimney - Metal Flue	Low Roof Low Roof Low Roof Low Roof Main Roof Main Roof	60 15 1,238 1,238 1	LF LF SF SF	7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 2-5 years	
	Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Structure - Steel / Metal Deck/ Concrete Topping Access Ladder - Metal Chimney - Metal Flue Coping - Metal	Low Roof Low Roof Low Roof Low Roof Main Roof Main Roof Main Roof	60 15 1,238 1,238 1 1 36 675	LF LF SF SF EA LF LF	7 7 7 7 7 6 5	10+ years 10+ years 10+ years 10+ years 2-5 years 2-5 years	
	Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Structure - Steel / Metal Deck/ Concrete Topping Access Ladder - Metal Chimney - Metal Flue Coping - Metal Downspouts - Interior Downspouts	Low Roof Low Roof Low Roof Low Roof Main Roof Main Roof Main Roof Main Roof Main Roof	60 15 1,238 1,238 1 36 675 52	LF LF SF SF EA LF LF	7 7 7 7 7 6 5 6	10+ years 10+ years 10+ years 10+ years 2-5 years 2-5 years 6-10 years	
	Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Structure - Steel / Metal Deck/ Concrete Topping Access Ladder - Metal Chimney - Metal Flue Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen	Low Roof Low Roof Low Roof Low Roof Main Roof	60 15 1,238 1,238 1 36 675 52 22,483	LF LF SF SF EA LF LF SF	7 7 7 7 7 6 5 6 7	10+ years 10+ years 10+ years 10+ years 2-5 years 2-5 years 6-10 years 10+ years	
	Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Structure - Steel / Metal Deck/ Concrete Topping Access Ladder - Metal Chimney - Metal Flue Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Hatch - Metal	Low Roof Low Roof Low Roof Low Roof Main Roof Main Roof Main Roof Main Roof Main Roof	60 15 1,238 1,238 1 36 675 52 22,483	LF LF SF EA LF LF SF EA	7 7 7 7 7 6 5 6 7	10+ years 10+ years 10+ years 10+ years 2-5 years 2-5 years 6-10 years 10+ years 10+ years	
	Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Structure - Steel / Metal Deck/ Concrete Topping Access Ladder - Metal Chimney - Metal Flue Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Hatch - Metal Roof Structure - Steel / Metal Deck/	Low Roof Low Roof Low Roof Low Roof Main Roof	60 15 1,238 1,238 1 36 675 52 22,483	LF LF SF SF EA LF LF SF	7 7 7 7 7 6 5 6 7	10+ years 10+ years 10+ years 10+ years 2-5 years 2-5 years 6-10 years 10+ years	
	Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Structure - Steel / Metal Deck/ Concrete Topping Access Ladder - Metal Chimney - Metal Flue Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Hatch - Metal	Low Roof Low Roof Low Roof Low Roof Main Roof	60 15 1,238 1,238 1 36 675 52 22,483	LF LF SF EA LF LF SF EA	7 7 7 7 7 6 5 6 7	10+ years 10+ years 10+ years 10+ years 2-5 years 2-5 years 6-10 years 10+ years 10+ years	
nof Sy	Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Structure - Steel / Metal Deck/ Concrete Topping Access Ladder - Metal Chimney - Metal Flue Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Hatch - Metal Roof Structure - Steel / Metal Deck/	Low Roof Low Roof Low Roof Low Roof Main Roof	60 15 1,238 1,238 1 36 675 52 22,483	LF LF SF EA LF LF SF EA	7 7 7 7 7 6 5 6 7	10+ years 10+ years 10+ years 10+ years 2-5 years 2-5 years 6-10 years 10+ years 10+ years	
	Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Structure - Steel / Metal Deck/ Concrete Topping Access Ladder - Metal Chimney - Metal Chimney - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Hatch - Metal Roof Structure - Steel / Metal Deck/ Concrete Topping  Canopy - Concrete/ Stucco	Low Roof Low Roof Low Roof Low Roof Main Roof	60 15 1,238 1,238 1,238 1 36 675 52 22,483 1 22,483	LF LF SF EA LF LF SF EA SF	7 7 7 7 6 5 6 7 7	10+ years 10+ years 10+ years 10+ years 2-5 years 2-5 years 6-10 years 10+ years 10+ years 10+ years	
oof Sy	Coping - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Structure - Steel / Metal Deck/ Concrete Topping Access Ladder - Metal Chimney - Metal Chimney - Metal Downspouts - Interior Downspouts Roof - Modified Bitumen Roof Hatch - Metal Roof Structure - Steel / Metal Deck/ Concrete Topping	Low Roof Low Roof Low Roof Low Roof Main Roof	60 15 1,238 1,238 1,238 1 36 675 52 22,483 1 22,483	LF SF SF EA LF LF SF EA SF	7 7 7 7 6 5 6 7 7	10+ years 10+ years 10+ years 10+ years 2-5 years 2-5 years 6-10 years 10+ years 10+ years	



Catego	y : Exterior		В	uilding	: Linked	l Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<b>Windows</b>							
	Lintels - Steel	Entire Building	356	LF	7	10+ years	
	Windows - Decorative	Entire Building	240	SF	7	10+ years	
	Windows - Wood- Double-pane	Entire Building	2,120	SF	7	10+ years	
:atenoi	ry : Electrical		R	uildina	·linked	l Addition	
Jaicgoi	y . Licotricai			unung	. Lilikee	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	cy System		<b>,</b>				
-mergen	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	
	Security System - CCTV	Entire Building	23,271	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	23,271	SF	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	3,445	SF	6	10+ years	
	Stairs	Entire building	3,443	31	J	TOT years	
	Exit Signs - Corridors and Stairs	Entire Building	8	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	4	EΑ	6	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	8	EA	7	6-10 years	
	Stairs						
Main Ser	vice						
	Independent Electrical Service for	Electrical Room	1	EA	7	10+ years	
	emergency power					,	
	PA System	Entire Building	23,721	SF	6	6-10 years	
	Main Electrical Service - 2000 A	Mechanical Room	1	EA	6	10+ years	
	120/208/3PH					•	
Power Di	stribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	6-10 years	
	amp	g	·		· ·	0 10 ,00.0	
Categoi	y : Fire Protection		В	uildina	: Linked	l Addition	
	<b>,</b>		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Aları							
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Connected with the main building
	Fire Alarm Strobe Lights	Entire Building	23,721	SF	7	6-10 years	

Campus Name: Beard Page : 23 of 41 Assessment Date: 10/25/2021



Catego	ry : Fire Protection	Building : Linked Addition					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm_System	Entire Building	23,721	SF	7	6-10 years	
Sprinkler	System						
	Sprinkler Heads	Entire Building	23,721	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	23,721	SF	6	6-10 years	
	Wet Sprinkler System	Entire Building	23,721	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Linked	l Addition	
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	litioning						
	Chiller-Air Cooled- Recipricating-Ground	Courtyard	1	EA	7	6-10 years	
	Mounted - 50 - 100 tons					0.40	
	Glycol Feed	Courtyard	1	EA	6	6-10 years	
	Pipes - Chilled Water Pipe- Galvanized	Courtyard	240	LF	6	6-10 years	
	Pressure Fill System	Courtyard	1	EA	5	2-5 years	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	7	10+ years	
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	6-10 years	
	than 5 tons					-	
Air Hand	lling Systems						
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	7	10+ years	
	Electric and Chilled Water Coils - 21 - 30					, , , , ,	
	tons						
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	7	10+ years	
	Electric and Chilled Water Coils - 21 - 30	Rooi		L/\	'	101 years	
	tons						
Boiler Sy		Machanical Dage		Γ^		2 E v:====	
	Boiler Auxiliary- Non Condensing Hot Water - 500 - 1000 MBH	Mechanical Room	2	EA	5	2-5 years	
	Combustion Dampers	Mechanical Room	1	EA	6	6-10 years	
	Glycol Feed System	Mechanical Room	1	EA	7	6-10 years	The new pot is being installed
	Non Condensing- Water Tube- Flexible	Mechanical Room	2	EA	5	6-10 years	5 F 22.12 22 9 1910 9
	Tube- Force Draft- Hot Water Boiler - 500 -		_		ŭ	2 . 2 , 5	
	1000 MBH						
	Water Fill System	Mechanical Room	1	EA	5	2-5 years	
-leating	Devices						
realing.	Fin Tube - Hot Water	Entire Building	96	LF	6	6-10 years	
	Unit Heater - Hot Water	Mechanical Room	1	EA	6	6-10 years	
	Other foctor flot viator	Modianiou Room	'	L/ \	U	o io years	

Page : 24 of 41 Campus Name: Beard Assessment Date: 10/25/2021



#### Daniel C Beard Elementary School

Froup	ry : Mechanical ltem - Type		_	3		I Addition Recommend	
-	Item - Type						
<u>lechanic</u>		Location	Quantity	UOM	Rank	Replacement	Comments
	cal Plumbing		·			<u> </u>	
	Hydronic Supply and Return - Steel	Entire Building	700	LF	6	6-10 years	
	Hot Water Pump - Less than 10	Mechanical Room	2	EA	4	6-10 years	One pump is leaking
	Chilled Water Pump - Less than 10	Mechanical Room	1	EA	4	2-5 years	Pump is working but leaking
	·					·	
Jnit Venti							
	Unit Ventilators- Floor Mounted- Dual	Entire Building	10	EA	5	6-10 years	
	Temperature Coils (Hot/Chilled) Water						
/entilatior	n						
CHIMATIO	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	7	6-10 years	
	CFM	3				, , , , , , ,	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	7	6-10 years	The unit is newly replaced
	CFM		_		_		
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	2	EA	7	6-10 years	
	CFM Exhaust Fans- Roof Mounted - Less than	Entire Building	1	EA	7	6-10 years	The unit has been replaced
	500 CFM	Little Ballaring	'	LA	,	0-10 years	The unit has been replaced
	Exhaust Fans- Roof Mounted - Less than	Entire Building	6	EA	7	6-10 years	
	500 CFM	3				,	
`otogor	av i Blumbina		ь	uildina	Linkoo	l Addition	
alegor	y : Plumbing		D	unung	. Linket	I Addition Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Water	-						
or water	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	6	2-5 years	
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EΑ	7	10+ years	Newly installed unit
						,	,
Piping							
. 0	Domestic Piping-Hot Water Return Lines	Entire Building	23,721	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	23,721	SF	6	6-10 years	
	(Horizontal Lines)						
	Sanitary Piping	Entire Building	23,721	SF	6	6-10 years	
	Storm Piping	Entire Building	23,721	SF	6	6-10 years	
	Vent Piping	Entire Building	23,721	SF	6	6-10 years	
`atogor	ry - Poom		D	uildina	·Linkoo	I Addition	
alegor	y : Room		D	unung	. Linket	I Addition Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	rative Suites/Offices					op ooinont	2 3
MINIMA	Ceiling - Lay-in	1st Floor-116 Office	125	SF	6	10+ years	Room was previously labeled as 11
	Doors - Wood Doors inclu hw	1st Floor-116 Office	125	EA	6	10+ years	Room was previously labeled as 11

Campus Name: Beard Page : 25 of 41 Assessment Date: 10/25/2021



	ry : Room	Building : Linked Addition							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Concrete	1st Floor-116 Office	125	SF	5	10+ years			
	Lighting - Lay-in	1st Floor-116 Office	2	EA	6	10+ years			
	Power Distribution	1st Floor-116 Office	6	EA	6	10+ years			
	Walls - Concrete Block	1st Floor-116 Office	415	SF	6	10+ years			
	Ceiling - Lay-in	1st Floor-Assistant Principal's Office	156	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor-Assistant Principal's Office	2	EA	6	6-10 years			
	Floor - Tile	1st Floor-Assistant Principal's Office	156	SF	6	6-10 years			
	Lighting - Lay-in	1st Floor-Assistant Principal's Office	4	EA	6	6-10 years			
	Power Distribution	1st Floor-Assistant Principal's Office	6	EA	6	6-10 years			
	Walls - Concrete Block	1st Floor-Assistant Principal's Office	220	SF	6	6-10 years			
	Walls - Plaster/Drywall	1st Floor-Assistant Principal's Office	220	SF	6	6-10 years			
	Ceiling - Lay-in	1st Floor-Conference Room	215	SF	6	10+ years	Quantity changed as total has been		
	Coming Lay in	13t 1 loor Somerence Room	210	O.	O	TOT years	aggregated/divided.		
	Doors - Wood Doors inclu hw	1st Floor-Conference Room	1	EA	6	10+ years	agg. ogatos, s. 11sos.		
	Floor - Tile	1st Floor-Conference Room	215	SF	6	10+ years			
	Lighting - Lay-in	1st Floor-Conference Room	4	ĒΑ	6	10+ years			
	Power Distribution	1st Floor-Conference Room	4	EA	6	10+ years			
	Walls - Concrete Block	1st Floor-Conference Room	266	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor-Conference Room	266	SF	6	10+ years			
	Ceiling - Lay-in	1st Floor-Conference/Storage Room	442	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor-Conference/Storage Room	1	EA	6	10+ years			
	Floor - Tile	1st Floor-Conference/Storage Room	442	SF	6	10+ years			
		1st Floor-Conference/Storage Room		EA	6	•			
	Lighting - Lay-in Power Distribution		6 8	EA	6	10+ years			
		1st Floor-Conference/Storage Room		SF		10+ years			
	Walls - Concrete Block	1st Floor-Conference/Storage Room	352		6	10+ years			
	Walls - Plaster/Drywall	1st Floor-Conference/Storage Room	432	SF	6	10+ years	D		
	Work SInk	1st Floor-Conference/Storage Room	1	EA	7	10+ years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations		
	Ceiling - Lay-in	1st Floor-Counselor's Office	115	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor-Counselor's Office	1	EA	6	10+ years			
	Floor - Tile	1st Floor-Counselor's Office	115	SF	6	10+ years	Quantity changed as total has been		
	11001 1110	Tot Floor Gournoller o Clindo		O.	ŭ	.o. youro	aggregated/divided.		
	Lighting - Lay-in	1st Floor-Counselor's Office	2	EA	6	10+ years			
	Power Distribution	1st Floor-Counselor's Office	6	EA	6	10+ years			
	Walls - Plaster/Drywall	1st Floor-Counselor's Office	375	SF	6	10+ years			
	Ceiling - Lay-in	1st Floor-Main Office	530	SF	6	10+ years	Quantity changed as total has been aggregated/divided.		
	Doors - Side-lite	1st Floor-Main Office	30	SF	6	10+ years	- 33 - 3		
	Doors - Wood Doors inclu hw	1st Floor-Main Office	2	ĒΑ	6	10+ years			
	Floor - Tile	1st Floor-Main Office	510	SF	6	10+ years			
	Floor - Tile	1st Floor-Main Office	20	SF	5	0-1 year	Staff commented that they frequently trip on the large cracks.		

Campus Name: Beard Page : 26 of 41 Assessment Date: 10/25/2021



Catego	Category : Room			uilding	: Linked	l Addition	<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor-Main Office	20	EA	6	10+ years	
	Power Distribution	1st Floor-Main Office	12	EΑ	6	10+ years	
	Walls - Concrete Block	1st Floor-Main Office	405	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-Main Office	775	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-Main Office	20	SF	5	0-1 year	Missing drywall, exposed wiring.
	Ceiling - Lay-in	1st Floor-N Testing Room	85	SF	6	10+ years	Quantity changed as total has been aggregated/divided.
	Doors - Side-lite	1st Floor-N Testing Room	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-N Testing Room	1	EA	6	10+ years	
	Floor - Tile	1st Floor-N Testing Room	85	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-N Testing Room	1	EΑ	6	10+ years	
	Power Distribution	1st Floor-N Testing Room	2	EΑ	6	10+ years	
	Walls - Concrete Block	1st Floor-N Testing Room	275	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-N Testing Room	95	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor-Principal's Office	207	SF	6	10+ years	Quantity changed as total has been aggregated/divided.
	Ceiling - Lay-in	1st Floor-Principal's Office	8	SF	4	1-2 years	Missing
	Doors - Wood Doors inclu hw	1st Floor-Principal's Office	2	ĒΑ	6	10+ years	3
	Floor - Tile	1st Floor-Principal's Office	215	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-Principal's Office	4	ĒΑ	6	10+ years	
	Power Distribution	1st Floor-Principal's Office	4	EΑ	6	10+ years	
	Walls - Concrete Block	1st Floor-Principal's Office	132	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-Principal's Office	395	SF	6	10+ years	
	AC Unit	1st Floor-Room 118	1	EA	5	0-1 year	Missing cover, appeared very warm in room.
	Ceiling - Lay-in	1st Floor-Room 118	246	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor-Room 118	24	SF	5	1-2 years	Stained
	Doors - Wood Doors inclu hw	1st Floor-Room 118	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor-Room 118	270	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-Room 118	4	ĒΑ	6	10+ years	
	Power Distribution	1st Floor-Room 118	4	EΑ	6	10+ years	
	Walls - Concrete Block	1st Floor-Room 118	650	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor-S Testing Room	85	SF	6	10+ years	
	Doors - Side-lite	1st Floor-S Testing Room	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-S Testing Room	1	EA	6	10+ years	
	Floor - Tile	1st Floor-S Testing Room	85	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-S Testing Room	1	EA	6	10+ years	
	Power Distribution	1st Floor-S Testing Room	2	EA	6	10+ years	
	Walls - Concrete Block	1st Floor-S Testing Room	275	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-S Testing Room	95	SF	6	10+ years	
	Ceiling - Lay-in	Sensory Room M09	180	SF	7	10+ years	New room, was not previously reported.
	Doors - Wood Doors inclu hw	Sensory Room M09	1	EA	7	10+ years	
	Floor - Tile/Sheet	Sensory Room M09	180	SF	7	10+ years	
	55. 1110/011000	Concern Noo	100	5.	•	.o. youro	

Campus Name: Beard Page : 27 of 41 Assessment Date: 10/25/2021



Category : Room		В	uilding	: Linked	d Addition		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	Sensory Room M09	3	EA	7	10+ years	
	Walls - Concrete Block	Sensory Room M09	560	SF	7	10+ years	
Kitchen							
	Ceiling - Lay-in	1st Floor	880	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Concrete	1st Floor	880	SF	5	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	6	10+ years	
	Storage/ Closet	1st Floor	92	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,018	SF	6	10+ years	
Library							
	Casework	1st Floor-Multimedia/Library	52	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor-Multimedia/Library	1,165	SF	6	10+ years	Quantity changed as total has been aggregated/divided.
	Doors - Wood Doors inclu hw	1st Floor-Multimedia/Library	2	EA	6	10+ years	
	Floor - Tile	1st Floor-Multimedia/Library	1,165	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-Multimedia/Library	12	EA	6	10+ years	
	Walls - Concrete Block	1st Floor-Multimedia/Library	705	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-Multimedia/Library	705	SF	6	10+ years	
unch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor-114 Dining Room	1,158	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-114 Dining Room	1,136	EA	6	10+ years	
	Floor - Tile	1st Floor-114 Dining Room	1,058	SF	6	10+ years	
	Floor - Tile	1st Floor-114 Dining Room	100	SF	4	1-2 years	Cracked
	Lighting - Lay-in	1st Floor-114 Dining Room		EA		•	Cracked
		1st Floor-114 Dining Room	16	LF	6	10+ years	
	Serving Line		10		6	10+ years	
	Storage/ Closet	1st Floor-114 Dining Room	85	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-114 Dining Room	1,330	SF	6	10+ years	
MDF_ID							
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Finishes	1st Floor	135	SF	7	10+ years	
	Window AC Unit	1st Floor	1	EA	4	0-1 year	Room was extremely warm even though unit seemed to be running.
Mechani	cal/ Service Rooms						
	Boiler Room	1st Floor	1,258	SF	7	10+ years	
	Janitor's Closet	1st Floor	32	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	156	SF	7	10+ years	
	Storage Room	1st Floor	60	SF	7	10+ years	

Campus Name: Beard Page : 28 of 41 Assessment Date: 10/25/2021



tegor	ry : Room		В	uilding	: Linked	l Addition	
				_		Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
stroon							
	Accessories	1st Floor-116 Office Restroom	45	SF	7	10+ years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations. Room was previous labeled as inside 118.
	Ceiling - Lay-in	1st Floor-116 Office Restroom	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-116 Office Restroom	1	EA	6	10+ years	
	Floor - Tile	1st Floor-116 Office Restroom	45	SF	6	10+ years	
	Floor Drain	1st Floor-116 Office Restroom	1	EA	7	10+ years	
	Lavatory	1st Floor-116 Office Restroom	1	EA	6	10+ years	
	Lighting - Lay-in	1st Floor-116 Office Restroom	1	EA	6	10+ years	
	Showers	1st Floor-116 Office Restroom	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor-116 Office Restroom	255	SF	6	10+ years	
	Accessories	1st Floor-Boiler Room Restroom	42	SF	5	1-2 years	Marred and scratched.
	Ceiling - Lay-in	1st Floor-Boiler Room Restroom	42	SF	6	10+ years	Marred and Scratched.
	Doors - Steel Doors incl hw	1st Floor-Boiler Room Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Boiler Room Restroom	42	SF	6	10+ years	
		1st Floor-Boiler Room Restroom		EA	7	,	
	Floor Drain	1st Floor-Boiler Room Restroom	1	EA	6	10+ years	
	Lavatory	1st Floor-Boiler Room Restroom			-	10+ years	
	Lighting - Lay-in		1	EA	6	10+ years	
	Walls - Concrete Block	1st Floor-Boiler Room Restroom	240	SF	6	10+ years	
	Water Closet	1st Floor-Boiler Room Restroom	1	EA	6	10+ years	
	Accessories	1st Floor-Boy's Restroom	195	SF	7	6-10 years	Rank and/or Priority Replacemen (AKA RUL) changed to update/correct to match current observations
	Ceiling - Lay-in	1st Floor-Boy's Restroom	195	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Boy's Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Boy's Restroom	195	SF	6	10+ years	
	Floor Drain	1st Floor-Boy's Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Boy's Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-Boy's Restroom	2	EA	6	10+ years	
	Lighting - Lay-in	1st Floor-Boy's Restroom	4	EA	6	10+ years	
	Partitions	1st Floor-Boy's Restroom	2	EA	7	10+ years	
	Urinals	1st Floor-Boy's Restroom	1	EA	6	10+ years	
	Walls - Concrete Block	1st Floor-Boy's Restroom	588	SF	6	10+ years	
	Water Closet	1st Floor-Boy's Restroom	2	EA	6	10+ years	
	Accessories	1st Floor-Girl's Restroom	150	SF	7	10+ years	Rank and/or Priority Replacemen (AKA RUL) changed to update/correct to match current
	0.33	4 / 51   01    5	. = -	<b>6</b> -	_	4.0	observations
	Ceiling - Lay-in	1st Floor-Girl's Restroom	150	SF	6	10+ years	

Campus Name: Beard Page : 29 of 41 Assessment Date: 10/25/2021



tegory : Room			В	uilding	: Linked	l Addition	
						Recommend	
up	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor-Girl's Restroom	1	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Girl's Restroom	150	SF	6	10+ years	
	Floor Drain	1st Floor-Girl's Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Girl's Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-Girl's Restroom	2	EA	6	10+ years	
	Lighting - Lay-in	1st Floor-Girl's Restroom	3	EA	6	10+ years	
	Partitions	1st Floor-Girl's Restroom	2	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Girl's Restroom	482	SF	6	10+ years	
	Water Closet	1st Floor-Girl's Restroom	2	EA	6	10+ years	
	Accessories	1st Floor-Staff Restroom	48	SF	7	10+ years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations
	Ceiling - Lay-in	1st Floor-Staff Restroom	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Staff Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Staff Restroom	48	SF	6	10+ years	
	Floor Drain	1st Floor-Staff Restroom	1	EA	7	10+ years	
	Lavatory	1st Floor-Staff Restroom	1	EA	6	10+ years	
	Lighting - Lay-in	1st Floor-Staff Restroom	1	EA	6	10+ years	
	Walls - Concrete Block	1st Floor-Staff Restroom	232	SF	6	10+ years	
	Water Closet	1st Floor-Staff Restroom	1	EA	6	10+ years	
	Accessories	1st Floor-Unisex Toilet near Boy's Restroom and Girl's Restroom	32	SF	5	1-2 years	Marred and scratched.
	Ceiling - Lay-in	1st Floor-Unisex Toilet near Boy's Restroom and Girl's Restroom	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Unisex Toilet near Boy's Restroom and Girl's Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Unisex Toilet near Boy's Restroom and Girl's Restroom	32	SF	6	10+ years	
	Floor Drain	1st Floor-Unisex Toilet near Boy's Restroom and Girl's Restroom	1	EA	7	10+ years	
	Lavatory	1st Floor-Unisex Toilet near Boy's Restroom and Girl's Restroom	1	EA	6	10+ years	
	Lighting - Lay-in	1st Floor-Unisex Toilet near Boy's Restroom and Girl's Restroom	1	EA	6	10+ years	
	Walls - Concrete Block	1st Floor-Unisex Toilet near Boy's Restroom and Girl's Restroom	210	SF	6	10+ years	Quantity changed as total has been aggregated/divided.
	Water Closet	1st Floor-Unisex Toilet near Boy's Restroom and Girl's Restroom	1	EA	6	10+ years	
	Accessories	1st Floor-Women's Staff Restroom	48	SF	7	10+ years	Rank and/or Priority Replacement (AKA RUL) changed as Asset has been replaced/refurbished.
	Ceiling - Lay-in	1st Floor-Women's Staff Restroom	48	SF	6	10+ years	•
	Doors - Wood Doors inclu hw	1st Floor-Women's Staff Restroom	1	ĒΑ	6	10+ years	

Campus Name: Beard Page : 30 of 41 Assessment Date: 10/25/2021



Catego	ry : Room		Building : Linked Addition							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor - Tile Ceramic/ Porcelain	1st Floor-Women's Staff Restroom	48	SF	6	10+ years				
	Floor Drain	1st Floor-Women's Staff Restroom	1	EA	7	10+ years				
	Lavatory	1st Floor-Women's Staff Restroom	1	EA	6	10+ years				
	Lighting - Lay-in	1st Floor-Women's Staff Restroom	1	EA	6	10+ years				
	Walls - Concrete Block	1st Floor-Women's Staff Restroom	232	SF	6	10+ years				
	Water Closet	1st Floor-Women's Staff Restroom	1	EA	6	10+ years				
	Accessories	Classroom 113 Restroom - First Floor	25	SF	7	6-10 years				
	Ceiling - Lay-in	Classroom 113 Restroom - First Floor	25	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	Classroom 113 Restroom - First Floor	1	EA	6	6-10 years				
	Floor - Tile Ceramic/ Porcelain	Classroom 113 Restroom - First Floor	25	SF	6	6-10 years				
	Floor Drain	Classroom 113 Restroom - First Floor	1	EA	7	6-10 years				
	Lavatory	Classroom 113 Restroom - First Floor	1	EA	6	6-10 years				
	Lighting - Lay-in	Classroom 113 Restroom - First Floor	1	EA	6	6-10 years				
	Walls - Concrete Block	Classroom 113 Restroom - First Floor	185	SF	6	6-10 years				
	Water Closet	Classroom 113 Restroom - First Floor	1	EA	6	6-10 years				
	Accessories	Classroom 115 Restroom - First Floor	25	SF	7	6-10 years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations			
	Ceiling - Lay-in	Classroom 115 Restroom - First Floor	25	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Classroom 115 Restroom - First Floor	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Classroom 115 Restroom - First Floor	25	SF	6	10+ years				
	Floor Drain	Classroom 115 Restroom - First Floor	1	EA	7	10+ years				
	Lavatory	Classroom 115 Restroom - First Floor	1	EA	6	10+ years				
	Lighting - Lay-in	Classroom 115 Restroom - First Floor	1	EA	6	10+ years				
	Walls - Concrete Block	Classroom 115 Restroom - First Floor	185	SF	6	10+ years				
	Water Closet	Classroom 115 Restroom - First Floor	1	EA	6	10+ years				



Catego	Category : Room			uilding	: Linked	Addition	
				11614		Recommend	0
Group	Item - Type	Location Final	Quantity	UOM	Rank	Replacement	Comments
	Accessories	Classroom 117 Restroom - First Floor	25	SF	7	6-10 years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations
	Ceiling - Lay-in	Classroom 117 Restroom - First Floor	25	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Classroom 117 Restroom - First Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Classroom 117 Restroom - First Floor	25	SF	6	10+ years	
	Floor Drain	Classroom 117 Restroom - First Floor	1	EA	7	10+ years	
	Lavatory	Classroom 117 Restroom - First Floor	1	EA	6	10+ years	
	Lighting - Lay-in	Classroom 117 Restroom - First Floor	1	EA	6	10+ years	
	Walls - Concrete Block	Classroom 117 Restroom - First Floor	185	SF	6	10+ years	
	Water Closet	Classroom 117 Restroom - First Floor	1	EA	6	10+ years	
	Accessories	Classroom 119 Restroom - First Floor	25	SF	7	6-10 years	
	Ceiling - Lay-in	Classroom 119 Restroom - First Floor	25	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Classroom 119 Restroom - First Floor	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Classroom 119 Restroom - First Floor	25	SF	6	6-10 years	
	Floor Drain	Classroom 119 Restroom - First Floor	1	EA	7	6-10 years	
	Lavatory	Classroom 119 Restroom - First Floor	1	EA	6	6-10 years	
	Lighting - Lay-in	Classroom 119 Restroom - First Floor	1	EA	6	6-10 years	
	Walls - Concrete Block	Classroom 119 Restroom - First Floor	185	SF	6	6-10 years	
	Water Closet	Classroom 119 Restroom - First Floor	1	EA	6	6-10 years	
	Accessories	Classroom 120 Restroom - First Floor	32	SF	7	6-10 years	
	Ceiling - Lay-in	Classroom 120 Restroom - First Floor	32	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Classroom 120 Restroom - First Floor	1	EA	6	6-10 years	



Catego	Category : Room		В	uilding	: Linked	l Addition	· · · · · · · · · · · · · · · · · · ·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	Classroom 120 Restroom - First Floor	32	SF	6	6-10 years	
	Floor Drain	Classroom 120 Restroom - First Floor	1	EA	7	6-10 years	
	Lavatory	Classroom 120 Restroom - First Floor	1	EA	6	6-10 years	
	Lighting - Lay-in	Classroom 120 Restroom - First Floor	1	EA	6	6-10 years	
	Walls - Concrete Block	Classroom 120 Restroom - First Floor	205	SF	6	6-10 years	
	Water Closet	Classroom 120 Restroom - First Floor	1	EA	6	6-10 years	
	Accessories	Classroom 121 Restroom - First Floor	32	SF	7	10+ years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations
	Ceiling - Lay-in	Classroom 121 Restroom - First Floor	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Classroom 121 Restroom - First Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Classroom 121 Restroom - First Floor	32	SF	6	10+ years	
	Floor Drain	Classroom 121 Restroom - First Floor	1	EA	7	10+ years	
	Lavatory	Classroom 121 Restroom - First Floor	1	EA	6	10+ years	
	Lighting - Lay-in	Classroom 121 Restroom - First Floor	1	EA	6	10+ years	
	Walls - Concrete Block	Classroom 121 Restroom - First Floor	205	SF	6	10+ years	
	Water Closet	Classroom 121 Restroom - First Floor	1	EA	6	10+ years	
	Accessories	Classroom 122 Restroom - First Floor	32	SF	7	6-10 years	
	Ceiling - Lay-in	Classroom 122 Restroom - First Floor	32	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Classroom 122 Restroom - First Floor	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Classroom 122 Restroom - First Floor	32	SF	6	6-10 years	
	Floor Drain	Classroom 122 Restroom - First Floor	1	EA	7	6-10 years	
	Lavatory	Classroom 122 Restroom - First Floor	1	EA	6	6-10 years	

Campus Name: Beard Page : 33 of 41 Assessment Date: 10/25/2021



Catego	Category : Room			uilding	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	Classroom 122 Restroom - First Floor	1	EA	6	6-10 years	
	Walls - Concrete Block	Classroom 122 Restroom - First Floor	205	SF	6	6-10 years	Quantity changed as total has been aggregated/divided.
	Water Closet	Classroom 122 Restroom - First Floor	1	EA	6	6-10 years	
	Accessories	Classroom 123 Restroom - First Floor	32	SF	7	6-10 years	
	Ceiling - Lay-in	Classroom 123 Restroom - First Floor	32	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Classroom 123 Restroom - First Floor	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Classroom 123 Restroom - First Floor	32	SF	6	6-10 years	
	Floor Drain	Classroom 123 Restroom - First Floor	1	EA	7	6-10 years	
	Lavatory	Classroom 123 Restroom - First Floor	1	EA	6	6-10 years	
	Lighting - Lay-in	Classroom 123 Restroom - First Floor	1	EA	6	6-10 years	
	Walls - Concrete Block	Classroom 123 Restroom - First Floor	205	SF	6	6-10 years	
	Water Closet	Classroom 123 Restroom - First Floor	1	EA	6	6-10 years	
	Accessories	Classroom 125 Restroom - First Floor	32	SF	7	6-10 years	
	Ceiling - Lay-in	Classroom 125 Restroom - First Floor	32	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Classroom 125 Restroom - First Floor	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Classroom 125 Restroom - First Floor	32	SF	6	6-10 years	
	Floor Drain	Classroom 125 Restroom - First Floor	1	EA	7	6-10 years	
	Lavatory	Classroom 125 Restroom - First Floor	1	EA	6	6-10 years	
	Lighting - Lay-in	Classroom 125 Restroom - First Floor	1	EA	6	6-10 years	
	Walls - Concrete Block	Classroom 125 Restroom - First Floor	205	SF	6	6-10 years	Quantity changed as total has been aggregated/divided.
	Water Closet	Classroom 125 Restroom - First Floor	1	EA	6	6-10 years	aggi ogalow aividod.

Campus Name: Beard Page : 34 of 41 Assessment Date: 10/25/2021



Catego	ry : Classroom		В	uilding	: Linked	d Addition	
			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #113 (Regular Classroom)						
	Casework	1st Floor	45	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	880	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	875	SF	6	10+ years	
	Floor - Tile	1st Floor	5	SF	4	1-2 years	Chipped and cracked tiles.
	Lighting - Lay-in	1st Floor	12	EA	6	10+ years	
	Marker Board	1st Floor	5	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	590	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	530	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	5	10+ years	
Classroc	om #115 (Regular Classroom)						
	Casework	1st Floor	45	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	880	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	880	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	530	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	5	0-1 year	Leaking, held together with caulking
_Classroo	om #117 (Regular Classroom)						
	Casework	1st Floor	45	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,185	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	, -1	ĒA	6	10+ years	
	Floor - Tile	1st Floor	1,165	SF	6	6-10 years	Quantity changed as total has been
		100.1	.,	•	· ·	0 10 700.0	aggregated/divided. Rank and/or Priority Replacement (AKA RUL)
							changed to update/correct to match
	Floor - Tile	1st Floor	22	C.E.	4	1.2 voors	current observations
			20 13	SF	4	1-2 years	Chipped tiles
	Lighting - Lay-in	1st Floor	13 25	EA SF	6	10+ years	
	Storage/ Closet	1st Floor			7	10+ years	
	Walls - Concrete Block	1st Floor	585	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	705	SF	6	10+ years	Davida and/an Drianita Davida and
	Work Sink	1st Floor	1	EA	7	10+ years	Rank and/or Priority Replacement (AKA RUL) changed to
							update/correct to match current observations
Classroc	om #119 (Regular Classroom)						
	Casework	1st Floor	45	LF	6	10+ years	



Catego	Category : Classroom			Building : Linked Addition						
				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Ceiling - Lay-in	1st Floor	904	SF	6	10+ years	Quantity changed as total has been aggregated/divided.			
	Ceiling - Lay-in	1st Floor	16	SF	5	1-2 years	Water stained tiles. Quantity changed as total has been aggregated/divided.			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	55 5			
	Floor - Tile	1st Floor	920	SF	6	10+ years	Quantity changed as total has been aggregated/divided.			
	Lighting - Lay-in	1st Floor	12	EA	6	10+ years				
	Storage/ Closet	1st Floor	105	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	586	SF	7	6-10 years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations			
	Walls - Plaster/Drywall	1st Floor	620	SF	6	10+ years				
	Work Sink	1st Floor	1	EA	7	10+ years				
Classroo	om #120 (Kindergarten)									
	Casework	1st Floor	45	LF	6	10+ years				
	Ceiling - Lay-in	1st Floor	920	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years				
	Floor - Tile	1st Floor	910	SF	6	10+ years				
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Cracked tiles			
	Lighting - Lay-in	1st Floor	12	EA	6	10+ years				
	Marker Board	1st Floor	5	LF	6	6-10 years				
	Storage/ Closet	1st Floor	105	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	586	SF	6	10+ years				
	Walls - Plaster/Drywall	1st Floor	620	SF	6	10+ years				
	Work Sink	1st Floor	1	EA	7	10+ years				
_Classroo	om #121 (Kindergarten)									
	Casework	1st Floor	45	LF	6	10+ years				
	Ceiling - Lay-in	1st Floor	920	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years				
	Floor - Tile	1st Floor	920	SF	6	10+ years	Quantity changed as total has been aggregated/divided.			
	Lighting - Lay-in	1st Floor	12	EA	6	10+ years				
	Storage/ Closet	1st Floor	105	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	586	SF	6	10+ years				
	Walls - Plaster/Drywall	1st Floor	620	SF	6	6-10 years				
	Work Sink	1st Floor	1	EA	5	0-1 year	Leaking.			
_Classroo	om #122 (Kindergarten)									
	Casework	1st Floor	45	LF	6	10+ years				

Campus Name: Beard Page : 36 of 41 Assessment Date: 10/25/2021



Catego	ry : Classroom		Building : Linked Addition							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Ceiling - Lay-in	1st Floor	920	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years				
	Floor - Tile	1st Floor	895	SF	6	10+ years				
	Floor - Tile	1st Floor	25	SF	4	1-2 years	Chipped tiles			
	Lighting - Lay-in	1st Floor	12	EA	6	10+ years				
	Storage/ Closet	1st Floor	105	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	8	SF	6	10+ years				
	Walls - Concrete Block	1st Floor	578	SF	6	10+ years				
	Walls - Plaster/Drywall	1st Floor	620	SF	7	10+ years				
	Work Sink	1st Floor	1	EA	7	10+ years				
Classroc	om #123 (Pre School)									
Olassioo	Casework	1st Floor	45	LF	6	10+ years				
	Ceiling - Lay-in	1st Floor	920	SF	6	10+ years	Quantity changed as total has been			
	Ç ,					·	aggregated/divided. Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match			
					_		current observations			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years				
	Floor - Tile	1st Floor	920	SF	6	10+ years	Quantity changed as total has been aggregated/divided.			
	Lighting - Lay-in	1st Floor	12	EA	6	10+ years	33 - 3			
	Storage/ Closet	1st Floor	105	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	586	SF	6	10+ years				
	Walls - Plaster/Drywall	1st Floor	620	SF	6	10+ years				
	Work Sink	1st Floor	1	EA	7	10+ years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations			
Classroc	om #125 (Regular Classroom)									
	Casework	1st Floor	45	LF	6	10+ years				
	Ceiling - Lay-in	1st Floor	920	SF	6	10+ years	Quantity changed as total has been aggregated/divided.			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	aggiogatod/aivided.			
	Floor - Tile	1st Floor	920	SF	6	10+ years	Quantity changed as total has been			
		151 11001		SF		·	aggregated/divided.			
	Lighting - Lay-in	1st Floor	12	EA	6	10+ years				
	Storage/ Closet	1st Floor	105	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	586	SF	7	10+ years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations			
	Walls - Plaster/Drywall	1st Floor	620	SF	6	10+ years				

Campus Name: Beard Page : 37 of 41 Assessment Date: 10/25/2021



Catego	Category : Classroom				Building : Linked Addition						
						Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
	Work Sink	1st Floor	1	EA	7	10+ years	Quantity changed as total has been aggregated/divided. Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations				

**Building: Linked Addition** Category : Interior

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	3,445	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	15	SF	6	10+ years	
	Doors - Store Front	1st Floor	4	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	6-10 years	
	Drinking Fountains - Triple Fountain	1st Floor	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	1,080	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	20	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,352	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	15	SF	5	1-2 years	
	Lighting - Lay-in	1st Floor	44	EA	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	5,562	SF	6	10+ years	
Safety							
•	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	1	EA	7	6-10 years	

Campus Name: Beard Page : 38 of 41 Assessment Date: 10/25/2021



Catego	ry : Site	Building : Site								
			Recommend							
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
ivil/Dra	inage									
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years				
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years				
	Civil/ Drainage - Site Manhole	Entire Site	7	EA	6	10+ years				
encina										
	Fencing - Chain Link	Entire Site	885	LF	6	6-10 years				
	Fencing - Guard Rail	Entire Site	100	LF	6	6-10 years				
	Fencing - New Standard Ornamental	Entire Site	611	LF	6	6-10 years				
andsca	na									
iiuoua	Benches	Entire Site	6	EA	7	6-10 years				
	Benches	Entire Site	14	EA	6	2-5 years				
	Landscape - Grass	Entire Site	32,836	SF	6	10+ years				
	Landscape - Grass  Landscape - Hardscape- Concrete	Entire Site	1,578	SF	6	6-10 years				
	Landscape - Hardscape- Pavers	Entire Site	2,300	SF	7	10+ years				
	Parkway trees	Entire Site	29	EA	6	10+ years				
	Planting Beds/ Area	Entire Site	12,702	SF	6	6-10 years				
	Play Area - Hardscape- Asphalt	Entire Site	7,745	SF	6	2-5 years				
	Play Area - Synthetic Turf	Entire Site	3,000	SF	7	10+ years				
	Trash Receptacles	Entire Site	3,000	EA	6	6-10 years				
arking	ot									
arking	Lighting - Pole Mounted	South Courtyard	4	EA	7	10+ years				
	Surface - Concrete	South Courtyard	42,954	SF	7	10+ years				
	Surface - Concrete	South Courtyalu	42,934	SF	,	10+ years				
laygrou										
	Equipment - Combo 3-12	West Courtyard	1	EA	6	6-10 years				
	Equipment - Swingset	West Courtyard	1	EA	6	6-10 years				
	Surface - Poured Surface	West Courtyard	4,291	SF	7	10+ years				
	Equipment - Pre K 3-5	West Courtyard	1	EA	7	10+ years				
	Equipment - Swingset	West Courtyard	1	EA	7	10+ years				
	Surface - Poured Surface	West Courtyard	1	SF	7	10+ years				
ervice (	Garage									
	Service Garage - Free-Standing	South	640	SF	7	10+ years				
dewalk	as									
	Sidewalks - Internal Walks	Entire Site	733	LF	6	10+ years				
	Sidewalks - Perimeter Sidewalks	Entire Site	8,876	SF	6	10+ years				
			-,		-	· ,				

Campus Name: Beard Page : 39 of 41 Assessment Date: 10/25/2021



#### **Daniel C Beard Elementary School**

6445 W Strong STREET, Chicago, IL 60656

Category : Site			В	Building : Site						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments			
Signage										
- 5 5	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years				
	Monument - Building Mounted Cut Letter	Entire Site	1	EA	6	6-10 years				
	Sign					•				

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Beard Page : 40 of 41 Assessment Date: 10/25/2021

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary			•	•	1	•	T		
Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	intended Usage	Room Location	Number	Number	(37)	Alea	Alea	Зюр	Doaru
Faculty Lounge	Regular Classroom	1st Floor	109	109	812	140	70	N	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	1,321	225	90	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	812	140	70	N	Y
Regular Classroom	Regular Classroom	1st Floor	106	106	814	150	60	N	Y
Regular Classroom	Regular Classroom	1st Floor	107	107	812	140	70	N	Y
Regular Classroom	Regular Classroom	1st Floor	107	108	814	150	60	N	Y
Regular Classroom	Regular Classroom	1st Floor	110	110	814	150	60	N	Y
		1st Floor			812	140	70		Y
Regular Classroom	Regular Classroom		111	111				N	Y
Regular Classroom	Regular Classroom	1st Floor	112	112	814	150	60	N	Y
Building : Linked Addition									
Kindergarten	Special Education	1st Floor	120	131	920	160	80	Y	Υ
Kindergarten	Special Education	1st Floor	121	146	920	160	80	Y	Υ
Kindergarten	Special Education	1st Floor	122	133	920	160	80	Y	Υ
Pre School	Special Education	1st Floor	123	143	920	160	80	Y	Υ
Regular Classroom	Kindergarten	1st Floor	117	152	1,185	160	80	Y	Υ
Regular Classroom	Pre School	1st Floor	113	158	880	160	80	N	Υ
Regular Classroom	Pre School	1st Floor	115	154	880	160	80	Y	Υ
Regular Classroom	Special Education	1st Floor	119	149	920	160	80	Y	Υ
Regular Classroom	Special Education	1st Floor	125	140	920	160	80	N	Υ
Building : Annex		T . =					T ====================================		
Regular Classroom	Regular Classroom	1st Floor	201	201	800	96	36		Υ
Regular Classroom	Regular Classroom	1st Floor	202	202	800	96	36		Υ
Regular Classroom	Regular Classroom	1st Floor	203	203	800	96	36		Υ
Regular Classroom	Regular Classroom	1st Floor	204	204	800	96	36		Υ
Regular Classroom	Regular Classroom	1st Floor	205	205	800	96	36		Υ
Regular Classroom	Regular Classroom	1st Floor	206	206	800	96	36		Υ
Regular Classroom	Regular Classroom	1st Floor	207	207	800	96	36		Υ
Regular Classroom	Regular Classroom	1st Floor	208	208	800	96	36		Υ
Regular Classroom	Regular Classroom	1st Floor	209	209	800	96	36		Υ
Regular Classroom	Regular Classroom	1st Floor	210	210	800	96	36		Υ