

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1961	1	14,788
Addition	1995	1	23,160
Campus Total			37,948

Category: Exterior **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Entrance Exterior Doors - Exterior Steel Door 10 1 EΑ 6 10+ years Exterior Doors - Exterior Steel Door 7 1 EΑ 6 10+ years Ramp Handrail - Steel Ramp Handrail 7 10 LF 5 2-5 years LF Ramps - Concrete 7 12 5 0-1 year Large cracks Exterior Doors - Exterior Steel Door 8 EΑ 6 10+ years 1 Entrance Control - Audio and Video 9 EΑ 6 10+ years 9 Exterior Doors - Exterior Steel Door 2 EΑ 6 10+ years Exterior Doors - Transom Lite FΑ 6 10+ years Exterior Doors - Exterior Steel Door Mechanical Room FΑ 10+ years 1 Exterior Doors - Transom Lite Mechanical Room 1 FΑ 6 10+ years Exterior Doors - Exterior Steel Door Storage Room 1 EΑ 6 10+ years ΙF Ramps - Concrete Storage Room 10+ years Foundation LF Foundation - Concrete **Entire Building** 634 7 10+ years Superstructure - Metal Deck/ Concrete Entire Building 14,788 SF 10+ years 7 Topping _Liahtina Exterior Lighting - Wall Mounted **Entire Building** EΑ 5 5 2-5 years Dim lighting Roof System





Catego	ry : Exterior		В	uilding	: Main		6767 W 65fd F EAGE, Officago, IE 6666
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Access Ladder - Metal	Roof A	2	EΑ	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof A	14	LF	5	6-10 years	
	Chimney - Brick Chimney- Stainless Steel Liner	Roof A	13	LF	6	10+ years	
	Coping - Metal	Roof A	478	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof A	60	LF	6	10+ years	
	Roof - Modified Bitumen	Roof A	12,812	SF	4	1-2 years	Cracking, ponding, patches throughout
	Roof Hatch - Metal	Roof A	1	EA	5	2-5 years	Rusted
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof A	12,812	SF	7	10+ years	
	Coping - Stone	Roof B	180	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof B	20	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof B	180	LF	6	10+ years	
	Roof - Modified Bitumen	Roof B	1,976	SF	4	1-2 years	Cracking, bubbling
	Roof Structure - Steel / Metal Deck/	Roof B	1,976	SF	7	10+ years	G. a.c
	Concrete Topping	Noor B	1,070	O.	,	101 youro	
alls							
	Canopy - Concrete/ Stucco	Entire Building	635	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	4,869	SF	6	10+ years	
'indows							
	Guard - Guards perforated	Entire Building	681	SF	7	10+ years	
	Lintels - Steel	Entire Building	452	LF	6	10+ years	
	Windows - Insulated Panel	Entire Building	375	SF	6	10+ years	
	Windows - Louver	Entire Building	120	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,908	SF	6	10+ years	
atego	ry : Electrical		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System						
mer de r	Exit Signs - Corridors and Stairs	Entire Building	2	EA	2	0-1 year	No backup generator nor backup batteries
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	2	0-1 year	No backup generator nor batteries
	Security System - CCTV	Entire Building	14,788	SF	6	6-10 years	-
	Security System - Intrusion Detection	Entire Building	14,788	SF	6	6-10 years	
	rvice						
ain Se		Entire Building	14,788	SF			

Campus Name: Blair Page : 2 of 25 Assessment Date: 10/14/2021



Catego	ry : Electrical			uilding	· Main		6731 W 63Id PLACE, Chicago, IL 60636
Catego	iy . Electricai			unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	istribution						
1 OWEL D	Lighting and Power Panels - 100 A	Entire Building	4	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	6-10 years	
	amp	Entire Building		LA	O	0-10 years	
	amp						
Catego	ry : Fire Protection		В	uilding	· Main		
Outego			_	unung	· Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
_ I lie Alai	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	The fire alarm panel is new
	Fire Alarm Strobe Lights	Entire Building	14,788	SF	7	6-10 years	The life alaim patier is new
	Fire Alarm_System	Entire Building	14,788	SF	6	6-10 years	
	File Alaini_System	Entire Building	14,700	SF	O	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler Sy	vstems						
,	Boiler Auxiliary- Condensing Hot Water -	Boiler Room	2	EA	7	10+ years	
	Less than 500 HP					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	Chemical Pot Feeder	Boiler Room	1	EA	6	2-5 years	The chemical pot is functional
	Combustion Dampers	Boiler Room	1	EA	6	6-10 years	F
	Condensing- Hot Water Boiler - Less than	Boiler Room	2	EA	7	10+ years	
	500 MBH					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	Water Fill System	Boiler Room	1	EA	6	10+ years	
	•					·	
Heating	Devices						
	Fin Tube - Hot Water	Entire Building	20	LF	5	6-10 years	
	Wall Heater - Electric	Entire Building	8	EA	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	3	EA	6	10+ years	
_Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Entire Building	2	EA	5	2-5 years	
	Hydronic Supply and Return - Steel	Entire Building	300	LF	6	10+ years	
Tompore	tura Cantral						
rempera	ture Control DDC System	Entire Building	44.700	SF	5	1 2 1/22/2	Incompatibility with the unit ventileties
	DDC System	Entire Building	14,788	SF	Э	1-2 years	Incompatibility with the unit ventilation
	Thermostats - DDC	Entire Building	13	EA	4	1-2 years	systems
	momodato DDO	Little Dallaling	13	L/\	7	i Z youis	
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	13	EA	6	6-10 years	
		-				-	

Campus Name: Blair Page : 3 of 25 Assessment Date: 10/14/2021





'atono	ry : Mechanical		D	uilding	· Main		6751 W 63Id PLACE, Chicago, iL 6063
alegoi	y . Wechanical		D	unung	. IVIAIII	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ТОПР	w/ DX Cooling Coil & w/ Self Contained				1101111		
	Compressors						
entilatio							
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	1	EA	5	2-5 years	
ategoi	ry : Plumbing		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ot Wate		D.1. D.				40	
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	7	10+ years	
iping							
	Domestic Piping-Hot Water Return Lines	Entire Building	14,788	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	14,788	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	14,788	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	14,788	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	14,788	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	14,788	SF	6	6-10 years	
	(from Risers to Fixtures) Sanitary Piping	Entiro Building	14,788	SF	6	6 10 years	
	Storm Piping	Entire Building Entire Building	14,788	SF	6	6-10 years 6-10 years	
	Vent Piping	Entire Building Entire Building	14,788	SF	6 6	6-10 years	
		Entire Dalianing				o ro youro	
atego	ry : Room		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Pank	Recommend Replacement	Commonts
iroup	rative Suites/Offices	Location	Quantity	UUIVI	Rank	Replacement	Comments
ummst		102 C Topohor's Louises	207	SE.	6	6 10 vooro	
	Ceiling - Splined	102 C - Teacher's Lounge	327	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	102 C - Teacher's Lounge	1	EA	6	6-10 years	
	Floor - Carpet	102 C - Teacher's Lounge	285	SF	6	6-10 years	
	Floor - Tile	102 C - Teacher's Lounge	42	SF	7	6-10 years	
	Lighting - Pendent/Surface	102 C - Teacher's Lounge	5	EA	6	6-10 years	
	Power Distribution	102 C - Teacher's Lounge	6	EA	6	6-10 years	
	Walls - Concrete Block	102 C - Teacher's Lounge	756	SF	6	6-10 years	
	lame: Blair	2	: 4 of 25				Assessment Date: 10/14/2





Catego	ry : Room		В	uilding	: Main		, , , , , , , , , , , , , , , , , , , ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Splined	Kitchen Office (Principal)	195	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Kitchen Office (Principal)	1	EA	6	6-10 years	
	Floor - Tile	Kitchen Office (Principal)	195	SF	7	6-10 years	
	Lighting - Pendent/Surface	Kitchen Office (Principal)	2	EA	7	6-10 years	
	Walls - Concrete Block	Kitchen Office (Principal)	560	SF	7	6-10 years	
	Ceiling - Splined	Main Office - Vault (Nurse)	60	SF	6	6-10 years	
	Doors - Steel Doors incl hw	Main Office - Vault (Nurse)	1	EA	6	6-10 years	
	Floor - Tile	Main Office - Vault (Nurse)	60	SF	7	6-10 years	
	Lighting - Pendent/Surface	Main Office - Vault (Nurse)	1	EA	6	6-10 years	
	Walls - Concrete Block	Main Office - Vault (Nurse)	265	SF	6	10+ years	
	Ceiling - Splined	Nurse's Office Room 102A	494	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Nurse's Office Room 102A	2	EA	6	6-10 years	
	Floor - Tile	Nurse's Office Room 102A	494	SF	6	6-10 years	
	Lighting - Pendent/Surface	Nurse's Office Room 102A	9	EA	6	6-10 years	
	Power Distribution	Nurse's Office Room 102A	8	EA	6	6-10 years	
	Storage/ Closet	Nurse's Office Room 102A	72	SF	7	6-10 years	
	Walls - Concrete Block	Nurse's Office Room 102A	1,000	SF	6	6-10 years	
	Ceiling - Splined	Nurse's Station Room 102B	56	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Nurse's Station Room 102B	1	ĒΑ	6	6-10 years	
	Floor - Tile	Nurse's Station Room 102B	56	SF	7	6-10 years	
	Lighting - Pendent/Surface	Nurse's Station Room 102B	1	ĒΑ	6	6-10 years	
	Storage/ Closet	Nurse's Station Room 102B	20	SF	7	10+ years	Quantity changed to update/correct to
	Walls - Concrete Block	Nurse's Station Room 102B	288	SF	6	6-10 years	match current observations.
Lunch &	Multipurpose Room						
	Ceiling - Splined	Therapy Room 99	1,780	SF	6	6-10 years	
	Doors - Steel Doors incl hw	Therapy Room 99	4	EA	6	6-10 years	
	Doors - Wood Doors inclu hw	Therapy Room 99	2	EA	6	6-10 years	Quantity changed to update/correct to
	Boold Wood Boold Hold HW	morapy Room oo	_		Ū	o to youro	match current observations.
	Doors - Wood Doors inclu hw	Therapy Room 99	4	EA	4	1-2 years	Doors missing. Quantity changed to
							update/correct to match current observations.
	Floor - Tile	Therapy Room 99	1,780	SF	6	6-10 years	
	Lighting - Pendent/Surface	Therapy Room 99	24	EΑ	6	6-10 years	
	Storage/ Closet	Therapy Room 99	88	SF	7	6-10 years	
	Walls - Concrete Block	Therapy Room 99	1,245	SF	7	10+ years	
	Walls - Structural Glazed Tile	Therapy Room 99	1,245	SF	7	10+ years	
			, -			, , , , ,	
_MDF_ID	F						
	Doors - Wood Doors inclu hw	Janitor's Closet	1	EA	7	10+ years	
	Finishes	Janitor's Closet	25	SF	7	10+ years	
	Doors - Steel Doors incl hw	Mechanical Room	1	EA	7	10+ years	
	Finishes	Mechanical Room	600	SF	7	10+ years	

Campus Name: Blair Page : 5 of 25 Assessment Date: 10/14/2021



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Finishes	Outside Storage	90	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Storage (by Boiler Room)	1	EA	7	6-10 years	
	Finishes	Storage (by Boiler Room)	90	SF	7	10+ years	
Restroo	m						
	Accessories	100	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	100	30	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	100	1	EA	6	6-10 years	
	Floor - Tile	100	30	SF	6	6-10 years	
	Lavatory	100	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	100	1	EA	6	6-10 years	
	Walls - Concrete Block	100	176	SF	6		
			_		_	10+ years	
	Water Closet	100	1	EA	6	6-10 years	
	Accessories	102 B	56	SF	7	10+ years	
	Ceiling - Plaster/Drywall	102 B	56	SF	6	10+ years	
	Doors - Wood Doors inclu hw	102 B	1	EA	6	10+ years	
	Floor - Tile	102 B	56	SF	6	10+ years	
	Lavatory	102 B	1	EA	6	10+ years	
	Lighting - Pendent/Surface	102 B	1	EA	6	10+ years	
	Partitions	102 B	1	EA	7	10+ years	
	Walls - Concrete Block	102 B	240	SF	6	10+ years	
	Water Closet	102 B	1	EA	6	10+ years	
	Accessories	102 C	56	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	102 C	56	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	102 C	1	EA	6	6-10 years	
	Floor - Tile	102 C	56	SF	7	6-10 years	
	Lavatory	102 C	1	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	102 C	1	EA	6	6-10 years	
	Walls - Concrete Block	102 C	270	SF	6	6-10 years	
	Water Closet	102 C	1	EA	6	6-10 years	
	Accessories	Boys	410	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys	410	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Boys	1	ĒΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Boys	410	SF	6	6-10 years	
	Floor Drain	Boys	1	EA	7	6-10 years	
	Lavatory	Boys	2	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	Boys	2	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	Boys	1	EΑ	6	6-10 years	
	Partitions	Boys	2	EA	7	6-10 years	
	Urinals	Boys	1	EA	6	6-10 years	
	Walls - Concrete Block	•	240	SF	6	10+ years	
	Walls - Concrete Block Walls - Structural Glazed Tile	Boys	630	SF SF	6		
		Boys			_	10+ years	
	Water Closet	Boys	2	EA	6	6-10 years	
	Accessories	Girls	410	SF	7	6-10 years	





Catego	ry : Room		В	uilding	: Main		
_						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Girls	410	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Girls	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Girls	410	SF	7	6-10 years	
	Floor Drain	Girls	1	EΑ	7	6-10 years	
	Lavatory	Girls	2	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	Girls	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Girls	1	EΑ	6	6-10 years	
	Partitions	Girls	3	EΑ	7	6-10 years	
	Walls - Concrete Block	Girls	240	SF	6	6-10 years	
	Walls - Structural Glazed Tile	Girls	630	SF	6	6-10 years	
						•	
	Water Closet	Girls	3	EA	6	10+ years	
	Accessories	Mechanical Room (Engineer's Restroom)	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Mechanical Room (Engineer's Restroom)	35	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Mechanical Room (Engineer's Restroom)	1	EA	6	6-10 years	
	Floor - Tile	Mechanical Room (Engineer's Restroom)	35	SF	7	6-10 years	
	Lavatory	Mechanical Room (Engineer's Restroom)	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Mechanical Room (Engineer's Restroom)	1	EA	6	6-10 years	
	Walls - Concrete Block	Mechanical Room (Engineer's Restroom)	240	SF	6	6-10 years	
	Water Closet	Mechanical Room (Engineer's Restroom)	1	EA	6	6-10 years	
	Accessories	Women's	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women's	30	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Women's	1	EA	6	6-10 years	
	Floor - Tile	Women's	30	SF	6	6-10 years	
	Lavatory	Women's	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Women's	1	EA	6	6-10 years	
	Partitions	Women's	=	EA			
			2 176	SF	7	6-10 years	
	Walls - Concrete Block	Women's	176		7	6-10 years	
	Water Closet	Women's	2	EA	6	6-10 years	
tego	ry : Classroom		В	uilding	: Main	Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ssroo	om #100 (Kindergarten)						
	Casework	1st Floor	35	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	1,100	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	6	6-10 years	





	ry : Classroom		В	uilding	: Main		6731 W 63IU PLACE, CHICAGO, IL 60636
Juliogo	.,		_	u		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Tile	1st Floor	1,100	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	19	EA	6	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,385	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #102D (Other Instructional Use)						
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	404	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Carpet	1st Floor	404	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	8	EA	6	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	640	SF	7	6-10 years	
Classroo	om #103 (Regular Classroom)						
_ OIGOOI OX	Casework	1st Floor	25	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	848	SF	6	6-10 years	
	Ceiling - Splined	1st Floor	10	SF	5	1-2 years	Water stained
	Chalk Board	1st Floor	40	LF	4	2-5 years	Water stamod
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	858	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	910	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #104 (Regular Classroom)						
Oldoorox	Casework	1st Floor	25	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	858	SF	6	6-10 years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	858	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	974	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #105 (Regular Classroom)						
UIGSSIU(Casework	1st Floor	25	LF	6	6-10 years	
	Casework Ceiling - Splined	1st Floor	858	SF	6	•	
	Chalk Board	1st Floor	20	LF	4	6-10 years 2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
						•	



Catego	ry : Classroom		В	uilding	: Main		
2 3 0						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Tile	1st Floor	858	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	974	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #106 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	858	SF	6	6-10 years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	758	SF	6	6-10 years	
	Floor - Tile	1st Floor	100	SF	5	1-2 years	Disjointed, chipped, and stained.
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	974	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #107 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	858	SF	6	6-10 years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	858	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	974	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #108 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	858	SF	6	6-10 years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	858	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	974	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	



Catego	ry : Interior		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Splined	1st Floor	1,728	SF	6	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,728	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	15	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	3,264	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Vestibule #109	35	SF	6	6-10 years	
	Doors - Steel Doors incl hw	Vestibule #109	2	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Vestibule #109	35	SF	7	10+ years	
	Lighting - Pendent/Surface	Vestibule #109	1	EA	6	6-10 years	
	Walls - Masonry	Vestibule #109	9	SF	7	10+ years	
_Safetv							
	Security Cameras	engineers office	2	EA	7	6-10 years	at the doors



Category : Exterior Building : Addition

Catego	y . Exterior			ununig	. Additi	Recommend	
0	Itam Tuna	Lagation	Overtity	LIOM	Dank		Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1	1	EA	6	10+ years	
	Exterior Doors - Store Front	1	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	1	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	2	1	EA	6	10+ years	
	Entrance Control - Audio and Video	3	1	EA	6	10+ years	
	Exterior Doors - Side lite	3	2	EA	6	10+ years	
	Exterior Doors - Store Front	3	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	3	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	4	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	5 - Mechanical	1	EA	6	6-10 years	
	Exterior Doors - Store Front	6	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	6	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Yard Storage	2	EA	6	6-10 years	
Foundati	on						
	Foundation - Concrete	Entire Building	650	LF	7	10+ years	
	Foundation - Concrete	Entire Building	70	LF	5	1-2 years	Settlement at north side of addition,
		g			•	,	interior cracks throughout
	Superstructure - Metal Deck/ Concrete	Entire Building	23,160	SF	7	10+ years	and a great
	Topping	3	.,			, , , , ,	
	-11 3						
Lighting							
_ gg _	Exterior Lighting - Wall Mounted	Entire Building	9	EA	5	2-5 years	Dim lighting
	Extendi Lighting Wall Modified	Entire Ballating	Ü		O	2 0 youro	Dini ngriting
Roof Sys	stem						
	Coping - Metal	Roof C	101	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof C	13	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof C	43	LF	6	10+ years	
	Roof - Modified Bitumen	Roof C	1,247	SF	4	1-2 years	Cracking, patches throughout
	Roof Structure - Steel / Metal Deck/	Roof C	1,247	SF	7	10+ years	Oracking, pateries unoughout
	Concrete Topping	11001 0	1,241	Oi	,	10+ years	
	Access Ladder - Metal	Roof D	1	EA	7	10+ years	
	Chimney - Metal Flue	Roof D	5	LF	6	10+ years	
	Coping - Metal	Roof D	666	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof D	72	LF	6	10+ years	
	Roof - Modified Bitumen	Roof D	21,853	SF	4	0-1 year	Bubbling, cracks throughout
	Roof Hatch - Metal	Roof D	21,003	EA	7	10+ years	Dubbing, cracks initugnout
			· · · · · · · · · · · · · · · · · · ·	SF			
		KUUI D	∠1,653	SF	′	10+ years	
		Doof C	60	1.5	6	10	
				ᄕ			
	Downspouts - Exterior Downspouts	KOOT E	2	LF	ь	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping Coping - Metal Downspouts - Exterior Downspouts	Roof D Roof E Roof E	21,853 60 2	SF LF LF	7 6 6	10+ years 10+ years 10+ years	

Campus Name: Blair Page : 11 of 25 Assessment Date: 10/14/2021



Catogo	ry : Exterior			uildina	: Additi	on	6731 W 63Id FLACE, Chicago, IL 60636
Calego	I y . Exterior		D	unung	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
Group	Roof - Modified Bitumen	Roof E	60	SF	4	0-1 year	Ponding, cracks
	Roof Structure - Steel / Metal Deck/	Roof E	60	SF	7	10+ years	1 Orlaing, Gracics
	Concrete Topping	11001 2	00	O.	•	101 youro	
	Concrete repping						
Walls							
	Canopy - Concrete/ Stucco	Entire Building	109	SF	7	10+ years	
	Canopy - Fabric	Entire Building	200	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	7,567	SF	6	10+ years	
	Exterior Walls - Concrete Block	Entire Building	720	SF	6	10+ years	
_Windows		E 4 B 4 F				4.0	
	Guard - Guards perforated	Entire Building	930	SF	7	10+ years	
	Lintels - Steel	Entire Building	410	LF	6	10+ years	
	Storefront Windows	Entire Building	280	SF	6	10+ years	
	Windows - Louver	Entire Building	30	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,247	SF	5	6-10 years	
Catego	ry : Electrical		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	2-5 years	
	Exit Signs - Corridors and Stairs	Entire Building	11	EA	2	0-1 year	No power back up
	Exit Signs - Lunchroom	Entire Building	2	EA	2	0-1 year	No power back up
	Exit Signs - Multipurpose Room	Entire Building	1	EA	2	0-1 year	No power back up
	Security System - CCTV	Entire Building	23,160	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	23,160	SF	6	6-10 years	
_Main Se	nde						
<u>ıvıallı Se</u>	Main Electrical Service - 2000 A	Electrical Room	1	EA	6	10+ years	
	120/208/3PH	Licotrical Noom	'	LA	U	TOT years	
	Independent Electrical Service for	Electrical Room	1	EA	7	10+ years	
	emergency power		•	_, .	•	, Jours	
	PA System	Entire Building	23,160	SF	6	6-10 years	
		-				-	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years	

Campus Name: Blair Page : 12 of 25 Assessment Date: 10/14/2021



Catego	ry : Fire Protection		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Fire Alar									
	Fire Alarm Strobe Lights	Entire Building	23,160	SF	7	6-10 years	All classrooms are fitted with strobe		
	Fire Alarm_System	Entire Building	23,160	SF	6	6-10 years			
0	0.1								
Sprinkler	System		20.400						
	Sprinkler Heads	Entire Building	23,160	SF	7	10+ years			
	Sprinkler Piping	Entire Building	23,160	SF	7	10+ years			
	Wet Sprinkler System	Entire Building	23,160	SF	7	10+ years			
Catego	ry : Mechanical		В	uilding	: Additi	on			
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Air Cond									
	Chiller-Air Cooled- Recipricating-Roof	Roof	1	EA	4	2-5 years			
	Mounted - 50 - 100 tons	Roof	1	EA	6	6 10 vooro	Functional		
	Condensing Unit- Roof Mounted - Less than 5 tons	ROOI	ı	EA	О	6-10 years	Functional		
	than 5 tons								
Air Hand	ling Systems								
	Air Handling Unit-Package Single Zone-	Office Plenum Space	1	EA	6	6-10 years			
	Indoor- Hot Water and Chilled Water Coils -								
	Less than 4000 cfm								
	Air Intake	Office Plenum Space	1	EA	6	6-10 years			
	Zone Dampers	Office Plenum Space	6	EA	6	6-10 years			
Boiler Sy	rstems								
<u> </u>	Boiler Auxiliary- Non Condensing Hot Water	Boiler Room	2	EA	6	6-10 years			
	- 500 - 1000 MBH	200. 1 (00	_	_, ,	· ·	0 .0 ,00.0			
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years			
	Combustion Dampers	Boiler Room	1	EA	6	6-10 years			
	Glycol Feed System	Boiler Room	1	EA	6	6-10 years			
	Non Condensing- Water Tube- Flexible	Boiler Room	2	EA	5	6-10 years			
	Tube- Force Draft- Hot Water Boiler - 500 -		_		•	,			
	1000 MBH								
Heating I	Dovisos								
пеашц	Unit Heater - Hot Water	Boiler Room	1	EA	6	6-10 years			
	Fin Tube - Hot Water	Entire Building	156	LF	6	6-10 years			
	i iii i abe - i iot vvatei	Litale building	130	LI	U	U-10 years			
Mechani	cal Plumbing								
	Chilled Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years			
	Hot Water Pump - Less than 10	Boiler Room	2	EΑ	6	6-10 years			

Campus Name: Blair Page : 13 of 25 Assessment Date: 10/14/2021



Catego	ry : Mechanical	В					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	6-10 years	
_Tempera	ture Control						
·	Electric Controls	Entire Building	23,160	SF	5	6-10 years	
	Electric Thermostat - DDC	Entire Building	6	EA	6	6-10 years	
Unit Ven	tilation						
	Unit Ventilators- Ceiling Mounted- Hot Water & Chilled Water Coils	1st Floor	1	EA	4	1-2 years	The building engineer says that the unit is non functional. Not accessible
	Unit Ventilators- Floor Mounted- Hot Water & Chilled Water Coils	Entire Building	11	EA	6	6-10 years	11 units have the admission valves for cooling and heating not working
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	4	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	3	EA	6	6-10 years	

Category · Plumbing **Building** · Addition

Category : Plumbing			Building : Addition					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Hot Wate	er		Í			·		
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	4	1-2 years	The shell is rusted due to leaking	
Piping								
	Domestic Piping-Hot Water Return Lines	Entire Building	23,160	SF	6	6-10 years		
	Domestic Piping-Hot Water Return Risers	Entire Building	23,160	SF	6	6-10 years		
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	23,160	SF	6	6-10 years		
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	23,160	SF	6	6-10 years		
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	23,160	SF	6	6-10 years		
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	23,160	SF	6	6-10 years		
	Sanitary Piping	Entire Building	23,160	SF	6	6-10 years		
	Storm Piping	Entire Building	23,160	SF	6	6-10 years		
	Vent Piping	Entire Building	23,160	SF	6	6-10 years		

Campus Name: Blair Page : 14 of 25 Assessment Date: 10/14/2021





Category : Room		R	uildina	: Additi	on	0701 W 03rd 1 EAGE, Officago, 1E 00000	
Jalogo				uiig	. , taaiti	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	trative Suites/Offices		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
	Ceiling - Lay-in	104 - Main Office	507	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	104 - Main Office	1	EA	6	6-10 years	
	Floor - Tile	104 - Main Office	507	SF	6	6-10 years	
	Lighting - Lay-in	104 - Main Office	8	EA	6	6-10 years	
	Power Distribution	104 - Main Office	10	EA	6	6-10 years	
	Walls - Concrete Block	104 - Main Office	60	SF	6	10+ years	
	Walls - Concrete Block	104 - Main Office	468	SF	6	10+ years	
	Ceiling - Lay-in	Assistant Principal - 110	180	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Assistant Principal - 110 Assistant Principal - 110	100	EA	6	10+ years	
	Floor - Carpet	Assistant Principal - 110 Assistant Principal - 110	180	SF	6	6-10 years	
	Lighting - Lay-in	Assistant Principal - 110 Assistant Principal - 110				,	
			2	EΑ	6	10+ years	
	Power Distribution	Assistant Principal - 110	· · · · · · · · · · · · · · · · · · ·	EA SF	6	10+ years	
	Walls - Concrete Block	Assistant Principal - 110	432		6	10+ years	
	Ceiling - Lay-in	Counsel 113	84	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Counsel 113	1	EA	6	6-10 years	
	Floor - Tile	Counsel 113	84	SF	7	6-10 years	
	Lighting - Lay-in	Counsel 113	1	EΑ	6	10+ years	
	Power Distribution	Counsel 113	2	EA	7	6-10 years	
	Walls - Concrete Block	Counsel 113	342	SF	7	6-10 years	
	Ceiling - Lay-in	Faculty Lounge - Room 107	450	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Faculty Lounge - Room 107	1	EA	6	6-10 years	
	Floor - Tile	Faculty Lounge - Room 107	450	SF	7	6-10 years	
	Lighting - Lay-in	Faculty Lounge - Room 107	6	EA	6	6-10 years	
	Power Distribution	Faculty Lounge - Room 107	6	EA	6	6-10 years	
	Walls - Concrete Block	Faculty Lounge - Room 107	630	SF	6	6-10 years	
	Work SInk	Faculty Lounge - Room 107	1	EA	7	6-10 years	
	Ceiling - Lay-in	Principal's Office Room 106	210	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office Room 106	1	EA	6	10+ years	
	Floor - Carpet	Principal's Office Room 106	210	SF	6	6-10 years	
	Lighting - Lay-in	Principal's Office Room 106	4	EA	6	10+ years	
	Power Distribution	Principal's Office Room 106	6	EA	7	10+ years	
	Walls - Concrete Block	Principal's Office Room 106	450	SF	7	10+ years	
	Ceiling - Lay-in	Vault/Storage - 109	180	SF	6	10+ years	
	Doors - Steel Doors incl hw	Vault/Storage - 109	1	ĒΑ	6	10+ years	
	Floor - Tile	Vault/Storage - 109	180	SF	7	10+ years	
	Lighting - Lay-in	Vault/Storage - 109	4	ĒΑ	6	10+ years	
	Power Distribution	Vault/Storage - 109	2	EA	6	10+ years	
	Walls - Concrete Block	Vault/Storage - 109	432	SF	6	10+ years	
			.02		-	,	
_Kitchen							
	Ceiling - Lay-in	1st Floor	795	SF	7	6-10 years	
	Floor - Tile	1st Floor	795	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	10+ years	
	3 ···· 3 —, ···				•	,	





Category : Room		В	uilding	: Additi			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	900	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen office (147) (storage)	98	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen office (147) (storage)	1	EA	7	6-10 years	
	Floor - Tile	Kitchen office (147) (storage)	98	SF	7	10+ years	
	Lighting - Lay-in	Kitchen office (147) (storage)	1	EA	7	10+ years	
	Walls - Concrete Block	Kitchen office (147) (storage)	336	SF	7	10+ years	
ocker/S	hower Room						
	Ceiling - Plaster/Drywall	144	50	SF	7	10+ years	
	Doors - Wood Doors inclu hw	144	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	144	50	SF	7	6-10 years	
	Floor Drain	144	1	EA	7	10+ years	
	Lavatory	144	1	EA	6	6-10 years	
	Lavatory Lighting - Pendent/Surface	144	1	EA	7		
			1			10+ years	
	Showers	144	1	EA	7	10+ years	
	Walls - Concrete Block	144	174	SF	7	10+ years	
	Walls - Tile	144	66	SF	7	10+ years	
	Accessories	Shower / 132	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Shower / 132	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Shower / 132	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Shower / 132	35	SF	6	10+ years	
	Floor Drain	Shower / 132	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	Shower / 132	1	EA	7	10+ years	
	Showers	Shower / 132	1	EA	7	10+ years	
	Walls - Concrete Block	Shower / 132	153	SF	6	10+ years	
	Walls - Tile	Shower / 132	63	SF	7	10+ years	
unch &	Multipurpose Room						
	Ceiling - Lay-in	110 A / 150	1,050	SF	7	10+ years	
	Doors - Wood Doors inclu hw	110 A / 150	2	ĒΑ	7	6-10 years	
	Floor - Tile	110 A / 150	1,050	SF	6	10+ years	
	Lighting - Lay-in	110 A / 150	15	EΑ	7	10+ years	
	Walls - Concrete Block	110 A / 150	890	SF	7	10+ years	
	Ceiling - Lay-in	110 B / 149	1,123	SF	7	10+ years	
	Doors - Transom Window	110 B / 149	30	SF	7	6-10 years	
	Doors - Wood Doors inclu hw		4	EA			
		110 B / 149	-	SF	7	6-10 years	
	Floor - Tile	110 B / 149	1,123		7	10+ years	
	Lighting - Lay-in	110 B / 149	15	EA	7	10+ years	
	Serving Line	110 B / 149	10	LF	7	6-10 years	
	Storage/ Closet	110 B / 149	63	SF	7	6-10 years	
	Walls - Concrete Block	110 B / 149	810	SF	7	10+ years	

Campus Name: Blair Page : 16 of 25 Assessment Date: 10/14/2021



Catego	ry : Room		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	Mechanical Room	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	Mechanical Room	1	EA	7	10+ years	
	Finishes	Mechanical Room	120	SF	7	10+ years	
	Window AC Unit	Mechanical Room	1	EA	7	6-10 years	
_Mechani	cal/ Service Rooms						
	Mechanical/ Service Rooms	1st Floor	768	SF	7	10+ years	
	Mechanical/ Service Rooms	Elect. Room	180	SF	7	10+ years	
	Janitor's Closet	Janitor's Closet	35	SF	7	10+ years	
	Storage Room	Outside Store Room	120	SF	7	10+ years	
	Storage Room	Storage 119	126	SF	7	10+ years	
	Storage Room	Storage 124	126	SF	7	10+ years	
Restroo	m						
	Accessories	114 / 128	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	114 / 128	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	114 / 128	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	114 / 128	40	SF	7	10+ years	
	Floor Drain	114 / 128	1	EA	7	10+ years	
	Lavatory	114 / 128	1	EA	7	10+ years	
	Lighting - Pendent/Surface	114 / 128	1	EA	7	10+ years	
	Walls - Concrete Block	114 / 128	208	SF	7	10+ years	
	Water Closet	114 / 128	1	EA	7	10+ years	
	Accessories	117 / 121	40	SF	7	6-10 years	
	Ceiling - Lay-in	117 / 121	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	117 / 121	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	117 / 121	40	SF	7	10+ years	
	Floor Drain	117 / 121	1	EA	7	10+ years	
	Lavatory	117 / 121	1	EA	7	10+ years	
	Lighting - Lay-in	117 / 121	1	EA	7	10+ years	
	Walls - Concrete Block	117 / 121	208	SF	7	10+ years	
	Water Closet	117 / 121	1	ĒΑ	7	10+ years	
	Accessories	119 / 120	40	SF	7	6-10 years	
	Ceiling - Lay-in	119 / 120	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	119 / 120	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	119 / 120	40	SF	7	10+ years	
	Floor Drain	119 / 120	1	EA	7	6-10 years	
	Lavatory	119 / 120	1	EA	7	6-10 years	
	Lighting - Lay-in	119 / 120	1	EA	7	10+ years	
	Walls - Concrete Block	119 / 120	208	SF	7	10+ years	
	Water Closet	119 / 120	200	EA	7	6-10 years	
	Accessories	Boys (134)	192	SF	7	6-10 years	
			192	SF SF	6	10+ years	
	Ceiling - Lay-in Doors - Wood Doors inclu hw	Boys (134)		Sr EA	6	-	
	Pools - Mood Pools little lik	Boys (134)	1	⊏A	Ö	6-10 years	

Campus Name: Blair Page : 17 of 25 Assessment Date: 10/14/2021





Catego	ry : Room		В	uilding	: Additi	on	, , , , , , , , , , , , , , , , , , , ,
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	Boys (134)	192	SF	7	10+ years	
	Floor Drain	Boys (134)	1	EA	7	6-10 years	
	Lavatory	Boys (134)	2	EA	7	6-10 years	
	Lighting - Lay-in	Boys (134)	3	EA	7	10+ years	
	Partitions	Boys (134)	3	EA	7	6-10 years	
	Urinals	Boys (134)	1	EΑ	7	6-10 years	
	Walls - Concrete Block	Boys (134)	576	SF	7	10+ years	
	Water Closet	Boys (134)	3	EA	7	6-10 years	
	Accessories	Girls (135)	192	SF	7	6-10 years	
	Ceiling - Lay-in	Girls (135)	192	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Girls (135)	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Girls (135)	192	SF	7	10+ years	
	Floor Drain	Girls (135)	1	EA	7	6-10 years	
	Lavatory	Girls (135)	2	EA	7	6-10 years	
	Lighting - Lay-in	Girls (135)	3	EA	7	10+ years	
	Partitions	Girls (135)	3	EA	7	6-10 years	
	Walls - Concrete Block	Girls (135)	576	SF	7	10+ years	
	Water Closet	Girls (135)	3	EA	6	6-10 years	
	Ceiling - Lay-in	Laundry Room	130	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Laundry Room	1	ĒΑ	7	6-10 years	
	Floor - Tile	Laundry Room	130	SF	7	10+ years	
	Floor Drain	Laundry Room	1	EA	7	6-10 years	
	Lighting - Lay-in	Laundry Room	2	EA	7	10+ years	
	Walls - Concrete Block	Laundry Room	416	SF	7	10+ years	
	Accessories	Mechanical Room (Eng)	35	SF	7	6-10 years	
	Ceiling - Lay-in	Mechanical Room (Eng)	35	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Mechanical Room (Eng)	1	ĒΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Mechanical Room (Eng)	35	SF	7	10+ years	
	Floor Drain	Mechanical Room (Eng)	1	ĒΑ	7	6-10 years	
	Lavatory	Mechanical Room (Eng)	1	EA	7	6-10 years	
	Lighting - Lay-in	Mechanical Room (Eng)	1	EΑ	7	10+ years	
	Walls - Concrete Block	Mechanical Room (Eng)	192	SF	7	10+ years	
	Water Closet	Mechanical Room (Eng)	1	ĒΑ	7	10+ years	
	Accessories	Men's (111)	48	SF	7	6-10 years	
	Ceiling - Lay-in	Men's (111)	48	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Men's (111)	1	EA	6	10+ years	
	Floor - Tile	Men's (111)	48	SF	7	10+ years	
	Floor Drain	Men's (111)	1	EA	7	10+ years	
	Lavatory	Men's (111)	1	EΑ	7	6-10 years	
	Lighting - Lay-in	Men's (111)	1	EΑ	7	10+ years	
	Walls - Concrete Block	Men's (111)	224	SF	7	10+ years	
	Water Closet	Men's (111)	1	EA	7	6-10 years	
	Accessories	Women's (112)	48	SF	7	6-10 years	
	Ceiling - Lay-in	Women's (112)	48	SF	7	6-10 years	
	Coming Lay III	(112)	70	Oi.	'	o to yours	

Campus Name: Blair Page : 18 of 25 Assessment Date: 10/14/2021



Catego	ry : Room		Building : Addition						
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	Women's (112)	1	SF	4	0-1 year	Water damage stain		
	Doors - Wood Doors inclu hw	Women's (112)	1	EA	6	6-10 years			
	Floor - Tile	Women's (112)	48	SF	6	10+ years			
	Floor Drain	Women's (112)	1	EA	7	6-10 years			
	Lavatory	Women's (112)	1	EA	7	6-10 years			
	Lighting - Lay-in	Women's (112)	1	EA	7	10+ years			
	Walls - Concrete Block	Women's (112)	224	SF	7	10+ years			
	Water Closet	Women's (112)	1	EA	7	6-10 years			
	Accessories	Women's by 110C	107	SF	7	6-10 years			
	Ceiling - Lay-in	Women's by 110C	107	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Women's by 110C	2	EA	7	10+ years			
	Floor - Tile	Women's by 110C	72	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Women's by 110C	35	SF	6	10+ years			
	Floor Drain	Women's by 110C	1	EA	7	10+ years			
	Lavatory	Women's by 110C	1	EA	7	6-10 years			
	Lighting - Lay-in	Women's by 110C	2	EA	7	10+ years			
	Walls - Concrete Block	Women's by 110C	480	SF	7	10+ years			
	Water Closet	Women's by 110C	1	EA	7	6-10 years			

Category : Classroom **Building: Addition**

July	ory : Glacoroom			ananig	. ,	0	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #109 (Regular Classroom)						
	Casework	1st Floor	41	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,050	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	6-10 years	
	Floor - Tile	1st Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,012	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	4	SF	6	2-5 years	Repaired but needs paint.
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classro	om #110C (Regular Classroom)						
	Casework	1st Floor	41	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,050	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,016	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classro	om #111 (Regular Classroom)						
CIGOSIO	Casework	1st Floor	41	LF	7	6-10 years	
				_	•	3 .0 ,00.0	

Campus Name: Blair Page : 19 of 25 Assessment Date: 10/14/2021





Category : Classroom		В	uilding	: Addition			
J						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Ceiling - Lay-in	1st Floor	1,050	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	10+ years	
	Walls - Concrete Block	1st Floor	1,016	SF	7	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	6-10 years	
Classroo	m #112 (Kindergarten)						
	Casework	1st Floor	41	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,050	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,016	SF	7	10+ years	
	Work Sink	1st Floor	1,010	EA	7	10+ years	
	WOLK SILIK	IST FIOOI	1	EA	,	10+ years	
Classroo	m #113 (Regular Classroom)						
	Casework	1st Floor	41	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,050	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,016	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	108	SF	6	2-5 years	Spotted with what appears to be rust
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #114 (Special Education)						
	Casework	1st Floor	30	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,020	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	1,020	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EΑ	7	10+ years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,010	SF	7	10+ years	
Classroo	m #115 (Regular Classroom)						
	Casework	1st Floor	41	LF	7	6-10 years	
	Casework Ceiling - Lay-in	1st Floor	1,050	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1,030	EA	7	10+ years	
	Floor - Tile	1st Floor		SF	7		
			1,050			10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,016	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	





Lighting - Lay-in Walls - Concrete Block

Ceiling - Lay-in

Ceiling - Lay-in

Doors - Side-lite

Doors - Store Front

	30110010						6751 W 6310 PLACE, Chicago, IL 606
Catego	ry : Classroom		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #117 (Pre School)						
	Casework	1st Floor	33	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	810	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	810	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EΑ	7	10+ years	
	Walls - Concrete Block	1st Floor	1,061	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	10	SF	6	10+ years	Repaired but needs paint.
	Work Sink	1st Floor	1	EA	7	10+ years	·
Classroo	om #119 (Pre School)						
	Casework	1st Floor	33	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	810	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	810	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,001	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	60	SF	6	1-2 years	Previously repaired but needs pair
	Work Sink	1st Floor	1	EA	7	6-10 years	reviewely repaired but neede pair
- atomo	ry : Interior		D	uilding	· Additi	on	
Salego	ry . interior		ь	unung	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	пеш турс	Location	Quantity	COM	Italik	Replacement	Comments
JOHIGOL	Ceiling - Lay-in	1st Floor	3,810	SF	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	3,610	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,810	SF	7		
		1st Floor	,	EA	7	10+ years	
	Lighting - Lay-in	1st Floor 1st Floor	23	SF	7 7	10+ years	
	Walls - Concrete Block		5,130	SF SF		10+ years	
	Ceiling - Lay-in	Lobby (103)	720		6	10+ years	
	Floor - Tile Quarry	Lobby (103)	720	SF	7	10+ years	
	Lighting - Lay-in	Lobby (103)	9	EA	7	10+ years	
	Walls - Concrete Block	Lobby (103)	270	SF	7	10+ years	
	Ceiling - Lay-in	Main office 108 Corridor passage	200	SF	7	6-10 years	
	Doors - Wood Doors include hw	Main office 108 Corridor passage	2	EA	7	6-10 years	
	Floor - Tile/Sheet	Main office 108 Corridor passage	200	SF	7	6-10 years	

2

810

255

15

6

2

EΑ

SF

SF

SF

SF

EΑ

7

7

7

7

6-10 years

6-10 years

6-10 years

0-1 year

6-10 years

6-10 years

Water damage stain

Main office 108 Corridor passage

Main office 108 Corridor passage

Vestibule #1 (102)

Vestibule #1 (102)

Vestibule #1 (102)

Vestibule #1 (102)



Catego	ry : Interior		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	Vestibule #1 (102)	1	SF	7	6-10 years	
	Floor - Tile Quarry	Vestibule #1 (102)	270	SF	7	10+ years	
	Lighting - Lay-in	Vestibule #1 (102)	3	EA	7	10+ years	
	Walls - Concrete Block	Vestibule #1 (102)	162	SF	7	10+ years	
	Ceiling - Lay-in	Vestibule #2 (122)	81	SF	7	10+ years	
	Doors - Wood Doors include hw	Vestibule #2 (122)	2	EΑ	7	10+ years	
	Floor - Tile/Sheet	Vestibule #2 (122)	64	SF	7	10+ years	
	Lighting - Lay-in	Vestibule #2 (122)	1	EΑ	7	10+ years	
	Walls - Concrete Block	Vestibule #2 (122)	288	SF	7	10+ years	
	Ceiling - Lay-in	Vestibule #3 (125)	120	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Vestibule #3 (125)	120	SF	7	10+ years	
	Lighting - Lay-in	Vestibule #3 (125)	1	EΑ	7	10+ years	
	Walls - Concrete Block	Vestibule #3 (125)	180	SF	7	10+ years	
Safety							
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	4	EA	7	6-10 years	



Category : Site Building : Site

Quantity UOM	Recommend Rank Replacement	Comments
Quantity UOM	Rank Replacement	Comments
4 EA	6 10+ years	
7 EA	6 10+ years	
	o ioi yeare	
25 I.F.	6 6-10 years	
29 Li	o to+ years	
5 EA	6 10+ years	
11,519 SF	6 10+ years	
•		
23 EA		
1,550 SF		
	•	
154 LF	6 10+ years	
7,968 SF		Uneven, holes, cracking
5,400 SF	6 10+ years	
	-	
4,080 SF	6 10+ years	
265 1 5	6 10± years	
30 SF	5 0-10 years	
1 EA	6 10+ years	
1 EA	7 10+ years	
	,	
2 EA	6 10+ years	
	•	
	11,519 SF 3,259 SF 50 SF 23 EA 1,550 SF 154 LF 7,968 SF 5,400 SF 1 EA 4,600 SF 1 EA 4,080 SF 265 LF 4,950 SF 50 SF	460 LF 6 10+ years 29 LF 6 10+ years 11,519 SF 6 10+ years 3,259 SF 6 10+ years 50 SF 6 10+ years 23 EA 6 10+ years 1,550 SF 6 10+ years 1,5400 SF 6 10+ years 1,5400 SF 6 10+ years 1,550 SF 7 10+ years

Campus Name: Blair Page : 23 of 25 Assessment Date: 10/14/2021





1 It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Blair Page: 24 of 25 Assessment Date: 10/14/2021



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window	Operable Window Area	Window	Smart- Board
Building : Main	intended Usage	Room Location	Number	Number	(SF)	Area	Alea	Stop	Doaru
Kindergarten	Kindergarten	1st Floor	100	100	1,100	251	68	Υ	Υ
Other Instructional Use	Regular Classroom	1st Floor	102D	102	404	74	18	Y	N
Regular Classroom	Regular Classroom	1st Floor	103	103	858	150	38	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	858	150	38	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	105	105	858	150	38	Y	N
Regular Classroom	Regular Classroom	1st Floor	106	106	858	150	38	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	107	107	858	150	38	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	108	108	858	150	38	Υ	Υ
Building : Addition			-	+			t		+
Kindergarten	Kindergarten	1st Floor	112	129	1.050	160	53	Υ	Y

Building : Addition								÷.	
Kindergarten	Kindergarten	1st Floor	112	129	1,050	160	53	Y	Υ
Pre School	Pre School	1st Floor	117	118	810	140	46	Y	Υ
Pre School	Pre School	1st Floor	119	123	810	140	46	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	109	114	1,050	160	53	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	110C	130	1,050	160	53	Y	N
Regular Classroom	Regular Classroom	1st Floor	111	115	1,050	160	53	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	113	116	1,050	160	53	Y	N
Regular Classroom	Regular Classroom	1st Floor	115	117	1,050	160	53	Y	Y
Special Education	Kindergarten	1st Floor	114	128/126	1,020	140	46	Y	N

Campus Name: Blair Page : 25 of 25 Assessment Date: 10/14/2021