

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1976	3	102,060
Linked Addition-Fine Arts & Tech Building	1974	1	66,155
Linked Addition-Physical Education Building	1974	1	37,803
Campus Total			206,018

Category : Exterior Building : Main

			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance	1						
	Exterior Doors - Overhead Rolling/ Garage	#20	1	EA	6	10+ years	
	Door						
	Entrance Control - Audio and Video	#21	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#21	1	EA	4	0-1 year	Corroded door and frame
	Entrance Control - Audio and Video	1-Main	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	1-Main	6	EA	6	10+ years	
	Exterior Doors - Side lite	1-Main	12	EA	6	10+ years	
	Exterior Doors - Transom Lite	1-Main	3	EA	6	10+ years	
	Exterior Doors - Side lite	16	4	EA	7	10+ years	
	Exterior Doors - Store Front	16	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	16	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	6	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	6	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	7	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	7	4	EA	6	10+ years	
	Exterior Stairs - Concrete	7	30	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	8	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	8	4	EA	6	10+ years	
_Foundati	on						
	Foundation - Concrete	Entire Building	740	LF	7	10+ years	
	Superstructure - Metal Deck/ Concrete	Entire Building	102,060	SF	7	10+ years	
	•	<u> </u>				•	

Campus Name: Collins HS Page: 1 of 68 Assessment Date: 06/22/2022



Categor	y : Exterior		В	uilding	: Main		
Group	Itom Tuno	Location	Quantity	UOM	Donk	Recommend Replacement	Comments
Group	Item - Type Topping	Location	Quantity	UOW	Rank	Replacement	Comments
	Topping						
Lighting							
	Exterior Lighting - Lighting	Entire Building	6	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	23	EA	7	10+ years	New LEDs
Roof Sys							
	Access Ladder - Metal	F	1	EA	7	10+ years	
	Chimney - Metal Flue	F -	10	LF 	6	10+ years	
	Coping - Metal	<u>F</u>	726	LF 	6	10+ years	
	Downspouts - Interior Downspouts	F	356	LF 	6	10+ years	
	Parapet - Parapet < 16" Height	F	726	LF	6	10+ years	
	Roof - Modified Bitumen	F	28,650	SF	6	10+ years	
	Roof - Modified Bitumen	F	400	SF	5	0-1 year	Worn out surfaces
	Roof - Modified Bitumen	F	110	SF	4	0-1 year	Open seams , blistering , soft spots.
	Roof Hatch - Metal	F	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	F	29,160	SF	7	10+ years	
	Concrete Topping						
Walls							
	Canopy - Concrete/ Stucco	Entire Building	384	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	400	SF	7	10+ years	
	Exterior Walls - Prefabricated Metal Panel	Entire Building	15,141	SF	5	10+ years	Peeling paint, some corrosion.
	Wall	3	-,	-	-	,	Galvanized steel walls/spandrels and column covers, painted.
Windows							
	Curtain wall - Glazed Double Pane	Entire Building	10,372	SF	6	10+ years	
	Curtain wall - Windows	Entire Building	5,186	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	8,652	SF	6	10+ years	
Categor	ry : Electrical		В	uilding	: Main		
0	Ham Time	Laastian	0	11014	Devil	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emergen	cy System						
	Automatic Transfer Switch	Basement	1	EA	6	6-10 years	
	Automatic Transfer Switch	Basement	1	EA	6	6-10 years	
	Automatic Transfer Switch	Basement	4	EA	6	6-10 years	
	Security System - CCTV	Entire Building	206,018	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	206,018	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	45	EA	6	6-10 years	Light bulbs need to be changed.
	Exit Signs - Lunchroom Exit Signs - Lunchroom	Entire Building	2 2	EA EA	6	6-10 years	Light bulbs need to be changed.

Campus Name: Collins HS Page : 2 of 68 Assessment Date: 06/22/2022





Catego	ry : Electrical		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Corridors and Stairs	Entire Building	19,965	SF	7	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,666	SF	7	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,090	SF	7	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	1,353	SF	7	10+ years	
	Emergency Generator- Outdoor- Natural Gas - 201 - 250 KW	Outside Northeast Corner of Building	1	EA	6	6-10 years	
Main Se							
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	2-5 years	New item added per current observation
	Main Electrical Service - 2001 to 3000 A 277/480/3PH	Electrical Room	1	EA	6	2-5 years	
	Independent Electrical Service for emergency power	Electrical Room	2	EA	7	6-10 years	
	PA System	Entire Building	206,018	SF	6	6-10 years	Serves Physical and Fine Arts building also
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	12	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	4	0-1 year	Fuse panel Original to building
	Lighting and Power Panels - 100 A	Entire Building	2	EA	3	0-1 year	Missing breakers
	Lighting and Power Panels - Above 100 A	Entire Building	27	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	3	EA	6	10+ years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	2-5 years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	2	0-1 year	Abandoned per building enginee
	Transformers - 277/480 - 120/208	Entire Building	3	EA	6	10+ years	
	Transformers - 277/480 - 120/240	Entire Building	1	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar		20041011	Quantity		- Karik	Topiaoomont	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Serves physical and Fine Arts buildings also
	Fire Alarm Strobe Lights	Entire Building	102,060	SF	6	10+ years	
	Fire Alarm_System	Entire Building	206,018	SF	6	10+ years	Serves physical and Fine Arts buildings also.
	Fire Pump Controller	Entire Building	1	EA	6	10+ years	<u> </u>

Campus Name: Collins HS Page : 3 of 68 Assessment Date: 06/22/2022



Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Pump Ro	oom Assembly						
	Fire Pump - 51-75hp	Mechanical Room	1	EA	6	2-5 years	
	Jockey Pump	Mechanical Room	1	EA	4	1-2 years	Corroded and aged
Sprinkle	r System						
	Dry Sprinkler System	Entire Building	5,166	SF	6	6-10 years	Serves loading dock.
	Sprinkler Heads	Entire Building	102,060	SF	7	10+ years	
	Sprinkler Piping	Entire Building	102,060	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	102,060	SF	7	6-10 years	Serves main building only.
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	Iling Systems						D
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-2
	Gas Heating and DX Cooling w/ Self						
	Contained Compressor - 31 - 45 tons	D (•	0.40	D.T.I. O
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-3
	Gas Heating and DX Cooling w/ Self						
	Contained Compressor - 31 - 45 tons	Deet	4	_^	0	0.40	DTU 0
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-8
	Gas Heating and DX Cooling w/ Self Contained Compressor - 31 - 45 tons						
	Roof Top Unit-Multi Zone-Roof Mounted-	Doof	1	ΓΛ	6	6 10 veers	DTUE
		Roof	I	EA	О	6-10 years	RTU-5
	Gas Heating and DX Cooling w/ Self Contained Compressor - 31 - 45 tons						
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6 10 years	RTU-6
	Gas Heating and DX Cooling w/ Self	ROOI	ı	EA	O	6-10 years	K10-6
	Contained Compressor - 31 - 45 tons						
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-1
	Gas Heating and DX Cooling w/ Self	KOOI	Į.	LA	O	0-10 years	K10-1
	Contained Compressor - 31 - 45 tons						
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-4
	Gas Heating and DX Cooling w/ Self	1001	1	LA	U	0-10 years	1110-4
	Contained Compressor - 31 - 45 tons						
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	5	6-10 years	RTU-7 Only one compressor working
	Gas Heating and DX Cooling w/ Self	11001	'	LA	3	0-10 years	Per building engineer
	Contained Compressor - 31 - 45 tons						i or building engineer
	Zone Dampers	Roof - Zone Dampers	86	EA	6	2-5 years	Integral to the RTUs.
	·	·				•	,
<u>leating</u>	Devices						
	Cabinet Heaters - With Electric Coil	Entire Building	10	EA	5	6-10 years	





Catego	ry : Mechanical		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Fin Tube - Electric	Entire Building	1,434	LF	6	6-10 years			
	Wall Heater - Electric	Entire Building	2	EA	6	6-10 years			
	Wall Heater - Electric	Entire Building	1	EA	6	2-5 years			
_Tempera	ature Control								
	DDC System	Entire Building	102,060	SF	6	6-10 years	Serves main building.		
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	MDF room		
	Thermostats - DDC	Entire Building	66	EA	6	6-10 years			
_Ventilati	on								
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years			
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years			
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	5	0-1 year	Damage and not working per building engineer		
	Exhaust Fans- Indoor - Greater than 8000 CFM	Entire Building	1	EA	7	10+ years	ong.iiooi		
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	7	10+ years			
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years			
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Quantity change per current observation		
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	5	EA	7	10+ years	Quantity change per current observation		
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	4	EA	6	6-10 years			
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	5	0-1 year	Badly dented.		
	Roof Mounted Duct Work	Entire Building	150	LF	7	10+ years			
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	6-10 years	New item added per current observation With fire suppression system		
	Type II Exhaust Hood- Warming Kitchen	Entire Building	2	EA	6	10+ years	Quantity change per current observation Location change per current observation Dishwasher remove from place		
			_						

Category: Plumbing Building: Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Hot Wate	Gas Heater - 300001 - 600000 BTU/HR	Mechanical Room	2	EA	4	1-2 years	Corroded and deteriorated. Serves main and Fine Arts building.

Campus Name: Collins HS Page : 5 of 68 Assessment Date: 06/22/2022





Catego	ry : Plumbing	В	uilding				
_	<u>-</u>					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hot Water Storage Tank_Gas - 501 - 1000 Gallons	Mechanical Room	1	EA	7	10+ years	
Piping							
. •	Domestic Piping-Hot Water Return Lines	Entire Building	102,060	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	102,060	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	102,060	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	102,060	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	102,060	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	102,060	SF	6	10+ years	
	Sanitary Piping	Entire Building	102,060	SF	7	10+ years	
	Storm Piping	Entire Building	102,060	SF	7	10+ years	
	Vent Piping	Entire Building	102,060	SF	7	10+ years	
Pumps							
•	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Ejector-Simplex	Entire Building	1	EA	6	6-10 years	New item added per current observation In the elevator pit Not accessible
	Pumps - Sump-Duplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Sump-Duplex	Entire Building	1	EA	6	6-10 years	New item added per current observation

Category: Room **Building: Main**


					Recommend	
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administrative Suites/Offices						
Ceiling - Lay-in	029 Engineer's Office (033 on plan)	176	SF	6	10+ years	
Doors - Steel Doors incl hw	029 Engineer's Office (033 on plan)	3	EA	7	10+ years	
Floor - Tile	029 Engineer's Office (033 on plan)	176	SF	6	10+ years	
Lighting - Lay-in	029 Engineer's Office (033 on plan)	4	EA	6	6-10 years	
Power Distribution	029 Engineer's Office (033 on plan)	6	EA	7	10+ years	
Storage/ Closet	029 Engineer's Office (033 on plan)	100	SF	7	10+ years	
Walls - Concrete Block	029 Engineer's Office (033 on plan)	436	SF	7	10+ years	
Ceiling - Lay-in	100 - Waiting Room	250	SF	6	10+ years	
Doors - Side-lite	100 - Waiting Room	37	SF	7	10+ years	
Doors - Wood Doors inclu hy	v 100 - Waiting Room	1	EA	7	10+ years	
Floor - Carpet	100 - Waiting Room	250	SF	6	6-10 years	
Lighting - Lay-in	100 - Waiting Room	2	EA	6	6-10 years	

Campus Name: Collins HS Page : 6 of 68 Assessment Date: 06/22/2022





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	100 - Waiting Room	2	EA	7	10+ years	
	Walls - Plaster/Drywall	100 - Waiting Room	305	SF	6	10+ years	
	Ceiling - Lay-in	102 - Conference room (In Main Office Lawndale)	283	SF	6	10+ years	
	Doors - Wood Doors inclu hw	102 - Conference room (In Main Office Lawndale)	1	EA	7	10+ years	
	Floor - Carpet	102 - Conference room (In Main Office Lawndale)	283	SF	6	6-10 years	
	Lighting - Lay-in	102 - Conference room (In Main Office Lawndale)	4	EA	6	6-10 years	
	Power Distribution	102 - Conference room (In Main Office Lawndale)	8	EA	7	10+ years	
	Walls - Concrete Block	102 - Conference room (In Main Office Lawndale)	144	SF	7	10+ years	
	Walls - Plaster/Drywall	102 - Conference room (In Main Office Lawndale)	314	SF	6	10+ years	
	Ceiling - Lay-in	103A - Vice Principal's Office (Main Office Lawndale)	140	SF	6	10+ years	
	Doors - Wood Doors inclu hw	103A - Vice Principal's Office (Main Office Lawndale)	1	EA	7	10+ years	
	Floor - Carpet	103A - Vice Principal's Office (Main Office Lawndale)	140	SF	6	6-10 years	
	Lighting - Lay-in	103A - Vice Principal's Office (Main Office Lawndale)	2	EA	6	6-10 years	
	Power Distribution	103A - Vice Principal's Office (Main Office Lawndale)	10	EA	7	10+ years	
	Walls - Plaster/Drywall	103A - Vice Principal's Office (Main Office Lawndale)	363	SF	6	10+ years	
	Ceiling - Lay-in	103B - Principal's Office (Lawndale)	140	SF	6	10+ years	
	Doors - Wood Doors inclu hw	103B - Principal's Office (Lawndale)	1	EA	7	10+ years	
	Floor - Carpet	103B - Principal's Office (Lawndale)	140	SF	6	6-10 years	
	Lighting - Lay-in	103B - Principal's Office (Lawndale)	2	ĒΑ	6	6-10 years	
	Power Distribution	103B - Principal's Office (Lawndale)	6	EA	7	10+ years	
	Walls - Plaster/Drywall	103B - Principal's Office (Lawndale)	363	SF	6	10+ years	
	Ceiling - Lay-in	104 - Principal Office (In Main Office)	280	SF	6	10+ years	
	Doors - Wood Doors inclu hw	104 - Principal Office (In Main Office)	1	EA	7	10+ years	
	Floor - Carpet	104 - Principal Office (In Main Office)	280	SF	6	6-10 years	
	Lighting - Lay-in	104 - Principal Office (In Main Office)	4	EA	6	6-10 years	
	Power Distribution	104 - Principal Office (In Main Office)	12	EA	7	10+ years	







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Walls - Plaster/Drywall 104 - Principal Office (In Main 316 SF 6 10+ years Office) Ceiling - Lav-in 107 - Office in Library 140 SF 6 10+ years Doors - Wood Doors inclu hw EΑ 7 107 - Office in Library 1 10+ years SF Floor - Carpet 107 - Office in Library 140 6 6-10 years EΑ Lighting - Lay-in 107 - Office in Library 2 6 6-10 years Power Distribution EΑ 7 10+ years 107 - Office in Library 10 SF Walls - Plaster/Drywall 107 - Office in Library 318 6 6-10 years SF Ceiling - Lay-in 108 - Office in Library 187 6 10+ years SF Ceiling - Lay-in 8 4 0-1 vear Cracked tile 108 - Office in Library Doors - Wood Doors inclu hw 108 - Office in Library 1 EΑ 7 10+ years Floor - Carpet 108 - Office in Library 195 SF 6 6-10 years Lighting - Lay-in 2 EΑ 6 6-10 years 108 - Office in Library 7 Power Distribution 108 - Office in Library 12 EΑ 10+ years SF 7 Walls - Masonry 108 - Office in Library 184 10+ years SF Walls - Plaster/Drywall 108 - Office in Library 258 6 10+ years SF Ceiling - Lay-in 109 - Office in Library 95 6 10+ years Doors - Store Front 109 - Office in Library 1 EΑ 7 10+ years Doors - Wood Doors inclu hw 109 - Office in Library 1 EΑ 7 10+ vears Floor - Carpet 109 - Office in Library 95 SF 6 6-10 years Lighting - Lay-in 109 - Office in Library 1 EΑ 6 6-10 years 7 Power Distribution 109 - Office in Library 6 EΑ 10+ years 76 SF 7 Walls - Masonry 109 - Office in Library 10+ years SF Walls - Plaster/Drywall 109 - Office in Library 118 6 10+ years Ceiling - Lay-in 120 - Office 280 SF 6 10+ years Doors - Wood Doors inclu hw 120 - Office 2 EΑ 7 10+ years SF Floor - Carpet 120 - Office 280 6 6-10 years Lighting - Lay-in 120 - Office EΑ 6 6-10 years 3 Power Distribution 7 120 - Office 12 EΑ 10+ years Walls - Concrete Block 120 - Office 128 SF 7 10+ years SF Walls - Plaster/Drywall 120 - Office 338 6 10+ years SF Ceiling - Lav-in 121 - Office 148 6 10+ years Doors - Wood Doors inclu hw FΑ 7 121 - Office 10+ years 1 Floor - Carpet 121 - Office 148 SF 6 6-10 years Lighting - Lay-in 121 - Office 2 EΑ 6 6-10 years EΑ 7 Power Distribution 121 - Office 18 10+ years SF Walls - Concrete Block 121 - Office 174 7 10+ years Walls - Plaster/Drywall 121 - Office SF 174 6 10+ years SF Ceiling - Lay-in 124 - Lounge 574 6 10+ years Ceiling - Lav-in SF 124 - Lounge 6 4 0-1 vear Missina. Doors - Wood Doors inclu hw 124 - Lounge 1 EΑ 7 10+ years SF Floor - Tile 124 - Lounge 580 6 10+ years Lighting - Lay-in 124 - Lounge EΑ 6 6-10 years 4 7 Power Distribution 124 - Lounge 16 EΑ 10+ years







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Walls - Plaster/Drywall 124 - Lounge 855 SF 10+ vears 6 Ceiling - Lav-in 125 - Copy Room SF 6 153 10+ years Doors - Store Front 125 - Copy Room FΑ 7 10+ years 1 Doors - Wood Doors inclu hw 125 - Copy Room 7 1 EΑ 10+ years SF Floor - Tile 125 - Copy Room 153 6 10+ years 125 - Copy Room Lighting - Lay-in 2 EΑ 6 6-10 years Power Distribution 125 - Copy Room 2 EΑ 7 10+ years SF Walls - Plaster/Drywall 125 - Copy Room 290 6 10+ years SF Ceiling - Lay-in 126 - Front Desk Reception 505 6 10+ years SF Floor - Carpet 126 - Front Desk Reception 505 6 6-10 years Lighting - Lay-in 126 - Front Desk Reception 5 EΑ 6 6-10 years Power Distribution 126 - Front Desk Reception 32 EΑ 7 10+ years Walls - Plaster/Drywall 126 - Front Desk Reception 738 SF 6 10+ years SF 6 Ceiling - Lay-in 127 - Waiting Room Main Office 238 10+ years Doors - Wood Doors inclu hw 127 - Waiting Room Main Office EΑ 7 1 10+ years Floor - Carpet 127 - Waiting Room Main Office 238 SF 6 6-10 years EΑ Lighting - Lay-in 127 - Waiting Room Main Office 2 6 6-10 years Power Distribution 127 - Waiting Room Main Office 2 EΑ 7 10+ years 55 SF Walls - Concrete Block 127 - Waiting Room Main Office 7 10+ years SF Walls - Plaster/Drywall 127 - Waiting Room Main Office 282 6 10+ years Ceiling - Lay-in 128 - Principal's Office 262 SF 6 10+ years SF Ceiling - Lay-in 128 - Principal's Office 16 4 0-1 year Water damage Doors - Wood Doors inclu hw 7 128 - Principal's Office 1 EΑ 10+ years SF Floor - Carpet 128 - Principal's Office 278 6 6-10 years Lighting - Lay-in 128 - Principal's Office EΑ 6 6-10 years 4 Power Distribution 128 - Principal's Office 16 EΑ 7 10+ years SF Walls - Plaster/Drywall 128 - Principal's Office 312 6 10+ years Ceiling - Lay-in 129 - Assistant Principal 288 SF 6 10+ years Ceiling - Lay-in SF 129 - Assistant Principal 8 4 0-1 year Water damage Doors - Wood Doors inclu hw 129 - Assistant Principal 1 EΑ 7 10+ years Floor - Carpet 129 - Assistant Principal 296 SF 6 6-10 years Lighting - Lav-in 129 - Assistant Principal 4 EΑ 6 6-10 years 7 Power Distribution 12 FΑ 10+ years 129 - Assistant Principal Walls - Plaster/Drywall 129 - Assistant Principal 479 SF 6 10+ years SF Ceiling - Lay-in 130 - Conference Room 291 6 10+ years Doors - Wood Doors inclu hw 7 130 - Conference Room EΑ 10+ years 1 130 - Conference Room SF Floor - Carpet 291 6 6-10 years Lighting - Lay-in 130 - Conference Room EΑ 6 6-10 years 4 Power Distribution 130 - Conference Room 12 EΑ 7 10+ years SF Walls - Masonry 130 - Conference Room 7 10+ years 145 SF Walls - Plaster/Drywall 130 - Conference Room 319 6 10+ years SF 7 Ceiling - Lav-in 132 - Athletic Director's Office 110 10+ years Doors - Wood Doors inclu hw 132 - Athletic Director's Office EΑ 7 10+ years 1 SF Floor - Carpet 132 - Athletic Director's Office 107 7 6-10 years







Catego	Category : Room		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Carpet	132 - Athletic Director's Office	3	SF	4	0-1 year	Edge loose	
	Lighting - Lay-in	132 - Athletic Director's Office	2	EA	7	6-10 years		
	Power Distribution	132 - Athletic Director's Office	10	EΑ	7	10+ years		
	Walls - Concrete Block	132 - Athletic Director's Office	60	SF	7	10+ years		
	Walls - Plaster/Drywall	132 - Athletic Director's Office	274	SF	7	10+ years		
	Ceiling - Lay-in	134 - Counselor's Office	154	SF	6	10+ years		
	Doors - Wood Doors inclu hw	134 - Counselor's Office	1	EA	7	10+ years		
	Floor - Carpet	134 - Counselor's Office	154	SF	6	6-10 years		
	Lighting - Lay-in	134 - Counselor's Office	2	EA	6	6-10 years		
	Power Distribution	134 - Counselor's Office	12	EA	7	10+ years		
	Walls - Concrete Block	134 - Counselor's Office	249	SF	7	10+ years		
	Walls - Plaster/Drywall	134 - Counselor's Office	225	SF	6	10+ years		
	Ceiling - Lay-in	135 - Counselors Office	152	SF	6	10+ years		
	Doors - Wood Doors inclu hw	135 - Counselors Office	1	EA	7	10+ years		
	Floor - Carpet	135 - Counselors Office	152	SF	6	6-10 years		
	Lighting - Lay-in	135 - Counselors Office	2	EA	6	6-10 years		
	Power Distribution	135 - Counselors Office	12	EA	7	10+ years		
	Walls - Plaster/Drywall	135 - Counselors Office	388	SF	6	10+ years		
	Ceiling - Lay-in	136 - Counselor's Office	123	SF	6	10+ years		
	Doors - Wood Doors inclu hw	136 - Counselor's Office	123	EA	7	10+ years		
	Floor - Carpet	136 - Counselor's Office	123	SF	6	6-10 years		
	Lighting - Lay-in	136 - Counselor's Office	2	EA	6	6-10 years		
	Power Distribution	136 - Counselor's Office	12	EA	7	10+ years		
	Walls - Plaster/Drywall	136 - Counselor's Office	332	SF	6	10+ years		
	Ceiling - Lay-in	140 - Counselor's Office	120	SF	6	10+ years		
	Doors - Wood Doors inclu hw	140 - Counselor's Office	120	EA	7	,		
	Floor - Carpet	140 - Counselor's Office	120	SF	6	10+ years 6-10 years		
	•			EA				
	Lighting - Lay-in	140 - Counselor's Office	2 8	EA EA	6 7	6-10 years		
	Power Distribution	140 - Counselor's Office		SF	6	10+ years		
	Walls - Plaster/Drywall	140 - Counselor's Office 141 - Counselors Office	328 145	SF SF	6	10+ years		
	Ceiling - Lay-in		_	SF SF	-	10+ years	\Materials demonstrate	
	Ceiling - Lay-in	141 - Counselors Office	8	SF EA	4	0-1 year	Water damage	
	Doors - Wood Doors inclu hw	141 - Counselors Office	1		7	10+ years		
	Floor - Carpet	141 - Counselors Office	153	SF	6	6-10 years		
	Lighting - Lay-in	141 - Counselors Office	2	EΑ	6	6-10 years		
	Power Distribution	141 - Counselors Office	8	EA	7	10+ years		
	Walls - Plaster/Drywall	141 - Counselors Office	326	SF	6	10+ years		
	Ceiling - Lay-in	142 - Counselor's Office	110	SF	6	10+ years		
	Doors - Wood Doors inclu hw	142 - Counselor's Office	1	EA	7	10+ years		
	Floor - Carpet	142 - Counselor's Office	110	SF	6	6-10 years		
	Lighting - Lay-in	142 - Counselor's Office	2	EA	6	6-10 years		
	Power Distribution	142 - Counselor's Office	8	EA	7	10+ years		
	Walls - Concrete Block	142 - Counselor's Office	60	SF	7	10+ years		
	Walls - Plaster/Drywall	142 - Counselor's Office	272	SF	6	10+ years		
	-					-		

Campus Name: Collins HS Page : 10 of 68 Assessment Date: 06/22/2022





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	145 - Counselor's Office	155	SF	6	10+ years	
	Doors - Wood Doors inclu hw	145 - Counselor's Office	1	EA	7	10+ years	
	Floor - Carpet	145 - Counselor's Office	155	SF	6	6-10 years	
	Lighting - Lay-in	145 - Counselor's Office	2	EA	6	6-10 years	
	Power Distribution	145 - Counselor's Office	8	EA	7	10+ years	
	Walls - Concrete Block	145 - Counselor's Office	202	SF	6	10+ years	
	Walls - Plaster/Drywall	145 - Counselor's Office	178	SF	6	10+ years	
	Ceiling - Lay-in	154 - Office	162	SF	6	10+ years	
	Doors - Wood Doors inclu hw	154 - Office	2	EA	7	10+ years	
	Floor - Tile	154 - Office	162	SF	7	10+ years	
	Lighting - Lay-in	154 - Office	2	EA	7	6-10 years	
	Power Distribution	154 - Office	8	EA	7	10+ years	
	Walls - Plaster/Drywall	154 - Office	114	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	154 - Office	310	SF	6	10+ years	
	Ceiling - Lay-in	155 - Technology Office	278	SF	6	10+ years	
	Ceiling - Lay-in	155 - Technology Office	6	SF	4	0-1 year	Missing
	Doors - Wood Doors inclu hw	155 - Technology Office	1	ĒΑ	7	10+ years	3
	Doors - Wood Doors inclu hw	155 - Technology Office	1	EA	7	10+ years	
	Floor - Tile	155 - Technology Office	284	SF	6	10+ years	
	Lighting - Lay-in	155 - Technology Office	4	ĒΑ	6	6-10 years	
	Power Distribution	155 - Technology Office	16	EA	7	10+ years	
	Walls - Plaster/Drywall	155 - Technology Office	114	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	155 - Technology Office	478	SF	7	10+ years	
	Ceiling - Lay-in	207 - Faculty Work Room	527	SF	6	10+ years	
	Doors - Wood Doors inclu hw	207 - Faculty Work Room	2	ĒΑ	7	10+ years	
	Floor - Tile	207 - Faculty Work Room	527	SF	6	10+ years	
	Lighting - Lay-in	207 - Faculty Work Room	6	ĒΑ	6	6-10 years	
	Power Distribution	207 - Faculty Work Room	19	EA	7	10+ years	
	Walls - Masonry	207 - Faculty Work Room	182	SF	7	10+ years	
	Walls - Plaster/Drywall	207 - Faculty Work Room	564	SF	6	10+ years	
	Ceiling - Lay-in	208 - Book Room	234	SF	7	10+ years	
	Doors - Wood Doors inclu hw	208 - Book Room	1	EA	7	10+ years	
	Floor - Carpet	208 - Book Room	234	SF	6	6-10 years	
	Lighting - Lay-in	208 - Book Room	3	EA	7	6-10 years	
	Power Distribution	208 - Book Room	4	ĒΑ	7	10+ years	
	Walls - Masonry	208 - Book Room	65	SF	7	10+ years	
	Walls - Plaster/Drywall	208 - Book Room	373	SF	6	10+ years	
	Ceiling - Lay-in	241 - Faculty Work Room	506	SF	6	10+ years	
	Doors - Wood Doors inclu hw	241 - Faculty Work Room	2	EA	7	10+ years	
	Floor - Tile	241 - Faculty Work Room	506	SF	6	10+ years	
	Lighting - Lay-in	241 - Faculty Work Room	5	EA	6	6-10 years	
	Power Distribution	241 - Faculty Work Room	26	EA	7	10+ years	
	Walls - Masonry	241 - Faculty Work Room	170	SF	7	10+ years	
	Walls - Plaster/Drywall	241 - Faculty Work Room	579	SF	6	10+ years	
	Trans Tractor, Dry Wall	ZII I douby Work Room	575	J1	J	ioi youis	

Campus Name: Collins HS Page : 11 of 68 Assessment Date: 06/22/2022







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Ceiling - Lav-in 242 - Office 190 SF 6 10+ vears Doors - Wood Doors inclu hw EΑ 7 242 - Office 1 10+ years Floor - Carpet 242 - Office 190 SF 6 6-10 years 242 - Office 3 EΑ Lighting - Lay-in 6 6-10 years 7 Power Distribution 242 - Office 12 EΑ 10+ years SF 7 Walls - Masonry 242 - Office 51 10+ years Walls - Plaster/Drywall 242 - Office 531 SF 6 10+ years SF Ceiling - Lav-in 329 - Office 187 6 10+ years Doors - Wood Doors inclu hw 329 - Office 1 EΑ 7 10+ years SF Floor - Carpet 329 - Office 187 6 6-10 years Lighting - Lay-in 329 - Office 4 EΑ 6 6-10 years Power Distribution 329 - Office 12 EΑ 7 10+ years Walls - Masonry 329 - Office 50 SF 7 10+ years SF Walls - Plaster/Drywall 329 - Office 537 6 10+ years 330A - Office SF Ceiling - Lay-in 345 6 10+ years Doors - Wood Doors inclu hw 330A - Office FΑ 7 1 10+ years SF Floor - Carpet 330A - Office 345 6 6-10 years Lighting - Lay-in 330A - Office 5 EΑ 6 6-10 years Power Distribution 330A - Office 30 EΑ 7 10+ vears Walls - Masonry 330A - Office 211 SF 7 10+ years Walls - Plaster/Drywall 330A - Office 774 SF 6 10+ years 330B - Office SF Ceiling - Lay-in 148 6 10+ years Ceiling - Lav-in SF Water damage 330B - Office 8 0-1 year Doors - Wood Doors inclu hw 7 330B - Office 1 FΑ 10+ years Floor - Carpet 330B - Office 156 SF 6 6-10 years Lighting - Lay-in 330B - Office 2 EΑ 6 6-10 years 7 Power Distribution 330B - Office 12 EΑ 10+ years Walls - Plaster/Drywall 330B - Office 505 SF 6 10+ years SF Ceiling - Lay-in 348 - Office 177 6 10+ years Doors - Side-lite 348 - Office 6 SF 7 10+ years Doors - Wood Doors inclu hw 348 - Office 1 EΑ 7 10+ years Floor - Tile 348 - Office 177 SF 6 10+ years 7 348 - Office 2 FΑ 6-10 years Lighting - Lay-in Power Distribution 348 - Office 14 FΑ 7 10+ years SF 7 Walls - Masonry 348 - Office 52 10+ years Walls - Plaster/Drywall 348 - Office SF 420 6 10+ years SF Ceiling - Lay-in 349 - Faculty Work Room 504 6 10+ years Ceiling - Lay-in 349 - Faculty Work Room SF 8 4 0-1 year Water damage SF Doors - Side-lite 349 - Faculty Work Room 12 7 10+ years 349 - Faculty Work Room Doors - Wood Doors inclu hw 2 EΑ 7 10+ years Floor - Tile 349 - Faculty Work Room 512 SF 6 10+ years Lighting - Lay-in 349 - Faculty Work Room FΑ 6 6 6-10 years Power Distribution 349 - Faculty Work Room 41 EΑ 7 10+ years 349 - Faculty Work Room SF Walls - Masonry 255 7 10+ years

Campus Name: Collins HS Page: 12 of 68 Assessment Date: 06/22/2022





Category : Room		R	uilding	: Main	131	•	
, maga. j						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Walls - Plaster/Drywall	349 - Faculty Work Room	583	SF	6	10+ years	Comments
	Ceiling - Lay-in	Main Office - Lawndale	590	SF	6	10+ years	
	Floor - Carpet	Main Office - Lawndale	590	SF	6	6-10 years	
	Lighting - Lay-in	Main Office - Lawndale	5	EA	6	6-10 years	
	Power Distribution	Main Office - Lawndale	25	EA	7	10+ years	
	Walls - Plaster/Drywall	Main Office - Lawndale	568	SF	6	10+ years	
Kitchen							
	Ceiling - Lay-in	216	453	SF	6	10+ years	
	Doors - Steel Doors incl hw	216	3	ĒΑ	7	10+ years	
	Floor - Tile Quarry	216	453	SF	7	10+ years	
	Lighting - Lay-in	216	8	ĒΑ	6	6-10 years	
	Serving Line	216	32	LF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	216	824	SF	6	10+ years	
	Ceiling - Lay-in	217 Canteen (in 216)	137	SF	6	10+ years	
	Doors - Steel Doors incl hw	217 Canteen (in 216)	1	EA	7	10+ years	
	Floor - Tile Quarry	217 Canteen (in 216)	137	SF	6	10+ years	
	Lighting - Lay-in	217 Canteen (in 216)	2	EA	6	6-10 years	
	Serving Line	217 Canteen (in 216)	6	LF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	217 Canteen (in 216)	274	SF	6	10+ years	
	Ceiling - Lay-in	337 Canteen (in 338)	129	SF	6	10+ years	
	Ceiling - Lay-in	, ,	8	SF	5	0-1 year	Missing tiles
	Doors - Wood Doors inclu hw	337 Canteen (in 338)	0	EA	7		Missing tiles
		337 Canteen (in 338)				10+ years	
	Floor - Tile Quarry	337 Canteen (in 338)	137	SF	7	10+ years	
	Lighting - Lay-in	337 Canteen (in 338)	2	EA	6	6-10 years	
	Serving Line	337 Canteen (in 338)	6	LF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	337 Canteen (in 338)	420	SF	6	10+ years	
	Ceiling - Lay-in	338	453	SF	6	10+ years	
	Doors - Wood Doors inclu hw	338	3	EA	7	10+ years	
	Floor - Tile Quarry	338	453	SF	7	10+ years	
	Lighting - Pendent/Surface	338	8	EA	7	6-10 years	
	Serving Line	338	32	LF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	338	824	SF	6	10+ years	
ibrary							
	Ceiling - Lay-in	105	3,666	SF	6	10+ years	
	Doors - Side-lite	105	39	SF	7	10+ years	
	Doors - Wood Doors inclu hw	105	3	EA	6	10+ years	
	Floor - Carpet	105	3,661	SF	6	6-10 years	
	Floor - Carpet	105	5	SF	4	0-1 year	Torn carpet
	Lighting - Lay-in	105	51	EA	6	6-10 years	
	Lighting - Lay-in	105	4	EA	6	6-10 years	
	Walls - Concrete Block	105	312	SF	7	10+ years	
		105	160	SF	7	10+ years	



Category : Room			В	uilding	: Main		
Ī						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Walls - Plaster/Drywall	105	1,220	SF	6	10+ years	
_ocker/S	hower Room						
	Accessories	014 Janitor Mens	386	SF	7	10+ years	
	Benches, ped mounted	014 Janitor Mens	15	LF	6	10+ years	
	Ceiling - Lay-in	014 Janitor Mens	240	SF	6	10+ years	
	Ceiling - Lay-in	014 Janitor Mens	40	SF	4	0-1 year	Water damage.
	Ceiling - Plaster/Drywall	014 Janitor Mens	106	SF	6	10+ years	3
	Doors - Steel Doors incl hw	014 Janitor Mens	1	EΑ	7	10+ years	
	Doors - Steel Doors incl hw	014 Janitor Mens	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	014 Janitor Mens	106	SF	6	10+ years	
	Floor - Tile/Sheet	014 Janitor Mens	280	SF	7	10+ years	
	Floor Drain	014 Janitor Mens	1	EA	7	10+ years	
	Hand Dryer	014 Janitor Mens	1	EΑ	7	10+ years	
	Lavatory	014 Janitor Mens	2	EΑ	7	10+ years	
	Lighting - Lay-in	014 Janitor Mens	7	EA	6	6-10 years	
	Partitions	014 Janitor Mens	1	EA	7	10+ years	
	Student Lockers - One Tier	014 Janitor Mens	25	EA	7	10+ years	
	Urinals	014 Janitor Mens	1	EA	7	10+ years	
	Walls - Concrete Block	014 Janitor Mens	530	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	014 Janitor Mens	216	SF	7	10+ years	
	Water Closet	014 Janitor Mens	1	EA	7	10+ years	
	Accessories	020 Kitchen Womens	290	SF	7	10+ years	
		020 Kitchen Womens	10	LF	7	•	
	Benches, ped mounted Ceiling - Lay-in	020 Kitchen Womens	185	SF	6	10+ years	
	Ceiling - Lay-iii Ceiling - Plaster/Drywall	020 Kitchen Womens	105	SF	6	10+ years 10+ years	
	Doors - Steel Doors incl hw		2	EA	7	•	
		020 Kitchen Womens		SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet	020 Kitchen Womens	105 185	SF SF	7	10+ years	
	Floor Drain	020 Kitchen Womens	100	EA	7	10+ years	
		020 Kitchen Womens	1	EA		10+ years	
	Hand Dryer	020 Kitchen Womens	·		7	10+ years	
	Lavatory	020 Kitchen Womens	2	EΑ	7	10+ years	
	Lighting - Lay-in	020 Kitchen Womens	5	EΑ	6	6-10 years	
	Partitions	020 Kitchen Womens	2	EΑ	7	10+ years	
	Student Lockers - One Tier	020 Kitchen Womens	19	EA	7	10+ years	
	Walls - Concrete Block	020 Kitchen Womens	332	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	020 Kitchen Womens	214	SF	6	10+ years	
	Water Closet	020 Kitchen Womens	2	EA	7	10+ years	
unch &	Multipurpose Room						
	Ceiling - Lay-in	227	1,906	SF	6	10+ years	
	Ceiling - Plaster/Drywall	227	184	SF	6	10+ years	
	Doors - Side-lite	227	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	227	2	EA	7	10+ years	
	_ 55.5 11664 B 6676 III 614 III		_	_, 、	•	.c. youro	



	ry : Room		ь	uilding	: wain		
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	227	2,015	SF	6	10+ years	
	Floor - Tile	227	75	SF	4	0-1 year	Cracking tiles
	Lighting - Lay-in	227	34	EA	6	6-10 years	
	Walls - Plaster/Drywall	227	1,340	SF	6	10+ years	
	Ceiling - Lay-in	303	1,546	SF	6	10+ years	
	Ceiling - Plaster/Drywall	303	120	SF	6	10+ years	
	Doors - Side-lite	303	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	303	2	EA	7	10+ years	
	Floor - Tile	303	1,666	SF	6	10+ years	
	Lighting - Lay-in	303	25	EΑ	6	6-10 years	
	Lighting - Lay-in	303	1	EA	5	1-2 years	Cover loose
	Walls - Plaster/Drywall	303	1,136	SF	6	10+ years	
MDF_ID	F						
	Doors - Wood Doors inclu hw	156 (in 155)	1	EA	7	10+ years	
	Finishes	156 (in 155)	136	SF	5	10+ years	Water damage ceiling.
	Other Cooling Unit	156 (in 155)	1	EA	7	6-10 years	Ductless split system.
Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	60	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	34	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	39	SF	7	10+ years	
	Storage Room	1st Floor	420	SF	7	10+ years	
	Janitor's Closet	2nd Floor	30	SF	5	6-10 years	Light out
	Mechanical/ Service Rooms	3rd Floor	30	SF	7	10+ years	g out
	Mechanical/ Service Rooms	3rd Floor	12	SF	5	10+ years	Hole in ceiling
	Janitor's Closet	Basement	76	SF	7	10+ years	riolo in coming
	Janitor's Closet	Basement	50	SF	7	10+ years	
	Loading Docks	Basement	2,500	SF	7	10+ years	Not previously assessed
	Mechanical/ Service Rooms	Basement	400	SF	7	10+ years	rect providuoly addoceda
	Mechanical/ Service Rooms	Basement	63	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	324	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	650	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	600	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	38	SF	5	10+ years	Water damage at ceiling
	Storage Room	Basement	568	SF	7	10+ years	
	Storage Room	Basement	860	SF	7	10+ years	
	Storage Room	Basement	1,000	SF	7	10+ years	
	Storage Room	Basement	300	SF	7	10+ years	
	Vaults	Basement	582	SF	7	10+ years	
	Vaults	Basement	168	SF	7	10+ years	
Prep Ro	om						

Campus Name: Collins HS Page : 15 of 68 Assessment Date: 06/22/2022







or	y : Room		В	uilding	: wain	_	
	Name Time	Landin	0	11014	Danis	Recommend	0
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	201 - Science Prep Room (in 202)	16	LF	7	10+ years	
	Ceiling - Lay-in	201 - Science Prep Room (in 202)	126	SF	6	10+ years	
	Ceiling - Plaster/Drywall	201 - Science Prep Room (in 202)	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	201 - Science Prep Room (in 202)	1	EA	7	10+ years	
	Floor - Tile	201 - Science Prep Room (in 202)	138	SF	6	10+ years	
	Lighting - Lay-in	201 - Science Prep Room (in 202)	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	201 - Science Prep Room (in 202)	216	SF	6	10+ years	
	Casework	202 - Science Prep Room	13	LF	7	10+ years	
	Ceiling - Lay-in	202 - Science Prep Room	182	SF	6	10+ years	
	Ceiling - Plaster/Drywall	202 - Science Prep Room	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	202 - Science Prep Room	2	EA	7	10+ years	
	Floor - Tile	202 - Science Prep Room	218	SF	6	10+ years	
	Lighting - Lay-in	202 - Science Prep Room	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	202 - Science Prep Room	370	SF	6	10+ years	
	Work Sink	202 - Science Prep Room	1	ĒA	7	10+ years	
	Casework	204 - Science Prep Room	40	LF	7	10+ years	
	Ceiling - Lay-in	204 - Science Prep Room	300	SF	6	10+ years	
	Ceiling - Lay-in	204 - Science Prep Room	30	SF	4	1-2 years	Water damage.
	Ceiling - Plaster/Drywall	204 - Science Prep Room	58	SF	6	10+ years	Water damage.
	Doors - Wood Doors inclu hw	204 - Science Prep Room	2	EA	7	10+ years	
	Floor - Tile	204 - Science Prep Room	388	SF	6	10+ years	
	Lighting - Lay-in	204 - Science Prep Room	3	EA	6	6-10 years	
	Walls - Plaster/Drywall	204 - Science Prep Room	540	SF	6		
	Work Sink	204 - Science Prep Room		SF EA	7	10+ years	
			1 21	LF	7	10+ years	
	Casework	309 - Science Prep Room			=	10+ years	
	Ceiling - Lay-in	309 - Science Prep Room	380	SF	6	10+ years	NA
	Ceiling - Lay-in	309 - Science Prep Room	10	SF	4	0-1 year	Water damage.
	Doors - Steel Doors incl hw	309 - Science Prep Room	1	EA	6	10+ years	Missing door knob
	Floor - Tile	309 - Science Prep Room	390	SF	6	10+ years	
	Lighting - Lay-in	309 - Science Prep Room	6	EA	6	6-10 years	
	Walls - Concrete Block	309 - Science Prep Room	176	SF	7	10+ years	
	Walls - Plaster/Drywall	309 - Science Prep Room	370	SF	6	10+ years	
	Work Sink	309 - Science Prep Room	2	EA	7	10+ years	
	Casework	312 - Science Prep Room	11	LF	7	10+ years	
	Ceiling - Lay-in	312 - Science Prep Room	290	SF	6	10+ years	
	Ceiling - Lay-in	312 - Science Prep Room	10	SF	4	1-2 years	Water damage.
	Doors - Steel Doors incl hw	312 - Science Prep Room	2	EA	7	10+ years	
	Floor - Tile	312 - Science Prep Room	300	SF	6	10+ years	
	Lighting - Lay-in	312 - Science Prep Room	3	ĒΑ	6	6-10 years	
	Walls - Plaster/Drywall	312 - Science Prep Room	10	SF	6	10+ years	
	Walls - Plaster/Drywall	312 - Science Prep Room	400	SF	6	10+ years	
	Work Sink	312 - Science Prep Room	1	EA	7	10+ years	
		5.2 Goldfiod (Top (Colif)	•	_, .	•	10. 304.0	

Campus Name: Collins HS Page : 16 of 68 Assessment Date: 06/22/2022





Catego	ry : Room		Building : Main							
				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Accessories	019 - Women's	200	SF	7	6-10 years				
	Ceiling - Lay-in	019 - Women's	125	SF	6	10+ years				
	Ceiling - Plaster/Drywall	019 - Women's	75	SF	6	10+ years				
	Doors - Steel Doors incl hw	019 - Women's	2	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	019 - Women's	200	SF	6	10+ years				
	Floor Drain	019 - Women's	1	EA	7	10+ years				
	Lavatory	019 - Women's	1	EΑ	7	10+ years				
	Lighting - Lay-in	019 - Women's	4	EA	6	6-10 years				
	Partitions	019 - Women's	1	EΑ	7	10+ years				
	Showers	019 - Women's	1	EA	7	10+ years				
	Showers	019 - Women's	1	EA	5	6-10 years				
	Student Lockers - One Tier	019 - Women's	3	EA	7	10+ years				
	Walls - Masonry	019 - Women's	320	SF	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	019 - Women's	190	SF	6	10+ years				
	Water Closet	019 - Women's	1	EΑ	7	10+ years				
	Accessories	162 on plan	229	SF	7	10+ years				
	Ceiling - Plaster/Drywall	162 on plan	229	SF	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	162 on plan	229	SF	6	10+ years				
	Floor Drain	162 on plan	1	EA	7	10+ years				
	Hand Dryer	162 on plan	1	EA	7	10+ years				
	Lavatory	162 on plan	3	EA	7	10+ years				
	Lighting - Lay-in	162 on plan	3	EA	6	6-10 years				
	Partitions	162 on plan	5	EA	7	10+ years				
	Walls - Masonry	162 on plan	62	SF	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	162 on plan	414	SF	7	10+ years				
	Water Closet	162 on plan	5	EA	6	10+ years				
	Accessories	163 on plan	222	SF	7	10+ years				
	Ceiling - Plaster/Drywall	163 on plan	222	SF	6					
	Floor - Tile Ceramic/ Porcelain	163 on plan	222	SF	6	10+ years 10+ years				
	Floor Drain	163 on plan	1	EA	7	•				
	Hand Dryer	163 on plan	1	EA	7	10+ years 10+ years				
	•	163 on plan	3	EA	6	•				
	Lavatory		3 1	EA	6	10+ years				
	Lighting - Lay-in	163 on plan				6-10 years	Dogo not work			
	Lighting - Lay-in	163 on plan	2	EΑ	5 7	0-1 year	Does not work.			
	Partitions	163 on plan	2	EΑ		10+ years				
	Urinals	163 on plan	3	EA	6	10+ years				
	Walls - Masonry	163 on plan	62	SF	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	163 on plan	306	SF	6	10+ years				
	Water Closet	163 on plan	2	EA	6	10+ years				
	Accessories	246	229	SF	7	10+ years				
	Ceiling - Plaster/Drywall	246	229	SF	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	246	229	SF	6	10+ years				
	Floor Drain	246	1	EA	7	10+ years				
	Hand Dryer	246	1	EA	7	10+ years				

Campus Name: Collins HS Page : 17 of 68 Assessment Date: 06/22/2022





Catego	Category : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	246	3	EA	7	10+ years	
	Lighting - Lay-in	246	3	EΑ	6	6-10 years	
	Partitions	246	5	EΑ	7	10+ years	
	Walls - Masonry	246	62	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	246	414	SF	7	10+ years	
	Water Closet	246	5	EA	7	10+ years	
	Accessories	247	222	SF	7	10+ years	
	Ceiling - Plaster/Drywall	247	222	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	247	222	SF	6	10+ years	
	Floor Drain	247	1	EA	7	10+ years	
	Hand Dryer	247	1	EA	7	10+ years	
	Lavatory	247	3	EA	7	10+ years	
	Lighting - Lay-in	247	3	EA	6	6-10 years	
	Partitions	247	2	EA	7	10+ years	
	Urinals	247	2	EA	7	10+ years	
	Urinals	247	_ 1	EA	5	1-2 years	urinal out of order
	Walls - Masonry	247	62	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	247	306	SF	6	10+ years	
	Water Closet	247	2	EA	7	10+ years	
	Accessories	340	229	SF	7	10+ years	
	Ceiling - Plaster/Drywall	340	229	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	340	229	SF	6	10+ years	
	Floor Drain	340	1	EA	7	10+ years	
	Hand Dryer	340	1	EA	7	10+ years	
	Lavatory	340	3	EA	7	10+ years	
	Lighting - Lay-in	340	3	EA	6	6-10 years	
	Partitions	340	5	EA	7	10+ years	
	Walls - Masonry	340	62	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	340	414	SF	6	10+ years	
	Water Closet	340	5	EA	7	10+ years	
	Accessories	340 341	222	SF	7	10+ years	
	Ceiling - Plaster/Drywall	341	222	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	341	222	SF	6		
	Floor Prain	341	1	SF EA	7	10+ years	
	Hand Dryer	341 341	1	EA EA	7	10+ years	
			3	EA EA	7	10+ years	
	Lavatory	341	3	EA EA	<i>7</i> 6	10+ years	
	Lighting - Lay-in	341				6-10 years	
	Partitions	341	2	EΑ	7	10+ years	
	Urinals	341	2	EΑ	7	10+ years	Not functional
	Urinals	341	1	EA	5	0-1 year	Not functional
	Walls - Masonry	341	62	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	341	306	SF	6	10+ years	
	Water Closet	341	2	EA	7	10+ years	
	Accessories	Unisex 123 (in 124)	55	SF	7	10+ years	

Campus Name: Collins HS Page : 18 of 68 Assessment Date: 06/22/2022





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Unisex 123 (in 124)	55	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Unisex 123 (in 124)	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex 123 (in 124)	55	SF	6	10+ years	
	Floor Drain	Unisex 123 (in 124)	1	EA	7	10+ years	
	Lavatory	Unisex 123 (in 124)	1	EA	7	10+ years	
	Lighting - Lay-in	Unisex 123 (in 124)	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Unisex 123 (in 124)	115	SF	6	10+ years	
	Water Closet	Unisex 123 (in 124)	1	EA	7	10+ years	
	Accessories	Unisex 151	23	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Unisex 151	23	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Unisex 151	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex 151	23	SF	6	10+ years	
	Lavatory	Unisex 151	1	EA	7	10+ years	
	Lighting - Lay-in	Unisex 151	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Unisex 151	46	SF	6	10+ years	
	Water Closet	Unisex 151	1	EA	6	10+ years	
	Accessories	Unisex 160	23	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Unisex 160	22	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Unisex 160	1	SF	5	1-2 years	Water damage.
	Doors - Wood Doors inclu hw	Unisex 160	1	EA	7	10+ years	Ç
	Floor - Tile Ceramic/ Porcelain	Unisex 160	23	SF	6	10+ years	
	Lavatory	Unisex 160	1	EA	7	10+ years	
	Lighting - Lay-in	Unisex 160	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Unisex 160	46	SF	6	10+ years	
	Water Closet	Unisex 160	1	EA	7	10+ years	
	Accessories	Unisex Across from 235 (248 on plan)	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Unisex Across from 235 (248 on plan)	52	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Unisex Across from 235 (248 on plan)	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex Across from 235 (248 on plan)	52	SF	6	10+ years	
	Floor Drain	Unisex Across from 235 (248 on plan)	1	EA	7	10+ years	
	Lavatory	Unisex Across from 235 (248 on plan)	1	EA	7	10+ years	
	Lighting - Lay-in	Unisex Across from 235 (248 on plan)	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Unisex Across from 235 (248 on plan)	108	SF	7	10+ years	
	Water Closet	Unisex Across from 235 (248 on plan)	1	EA	7	10+ years	
	Accessories	Unisex Across from 236 (220 on	22	SF	7	6-10 years	

Campus Name: Collins HS Page : 19 of 68 Assessment Date: 06/22/2022



Catego	ry : Room		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Plaster/Drywall	plan) Unisex Across from 236 (220 on	22	SF	6	10+ years	
	Doors - Wood Doors inclu hw	plan) Unisex Across from 236 (220 on	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	plan) Unisex Across from 236 (220 on plan)	22	SF	6	10+ years	
	Lavatory	Unisex Across from 236 (220 on plan)	1	EA	7	10+ years	
	Lighting - Lay-in	Unisex Across from 236 (220 on plan)	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Unisex Across from 236 (220 on plan)	44	SF	6	10+ years	
	Water Closet	Unisex Across from 236 (220 on plan)	1	EA	7	10+ years	
	Accessories	Unisex Across from 240 (223 on plan)	22	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Unisex Across from 240 (223 on plan)	22	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Unisex Across from 240 (223 on plan)	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex Across from 240 (223 on plan)	22	SF	6	10+ years	
	Lavatory	Unisex Across from 240 (223 on plan)	1	EA	7	10+ years	
	Lighting - Lay-in	Unisex Across from 240 (223 on plan)	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Unisex Across from 240 (223 on plan)	44	SF	6	10+ years	
	Water Closet	Unisex Across from 240 (223 on plan)	1	EA	7	10+ years	
	Accessories	Unisex Across from 315 (346 on plan)	22	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Unisex Across from 315 (346 on plan)	22	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Unisex Across from 315 (346 on plan)	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex Across from 315 (346 on plan)	22	SF	6	10+ years	
	Lavatory	Unisex Across from 315 (346 on plan)	1	EA	7	10+ years	
	Lighting - Lay-in	Unisex Across from 315 (346 on plan)	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Unisex Across from 315 (346 on	44	SF	7	10+ years	

Campus Name: Collins HS Page : 20 of 68 Assessment Date: 06/22/2022



ory : Room Building : Main

Catego	ry : Room		Building : Main						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
	Water Closet	plan) Unisex Across from 315 (346 on	1	EA	7	10+ years			
	Accessories	plan) Unisex Across from 319 (335 on plan)	22	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Unisex Across from 319 (335 on plan)	22	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Unisex Across from 319 (335 on plan)	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Unisex Across from 319 (335 on plan)	22	SF	6	10+ years			
	Lavatory	Unisex Across from 319 (335 on plan)	1	EA	7	10+ years			
	Lighting - Lay-in	Unisex Across from 319 (335 on plan)	1	EA	6	6-10 years			
	Walls - Tile Ceramic/ Porcelain	Unisex Across from 319 (335 on plan)	44	SF	6	10+ years			
	Water Closet	Unisex Across from 319 (335 on plan)	1	EA	7	10+ years			
	Accessories	Unisex Across from 320 (332 on plan)	52	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Unisex Across from 320 (332 on plan)	52	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Unisex Across from 320 (332 on plan)	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Unisex Across from 320 (332 on plan)	52	SF	6	10+ years			
	Floor Drain	Unisex Across from 320 (332 on plan)	1	EA	7	10+ years			
	Lavatory	Unisex Across from 320 (332 on plan)	1	EA	7	10+ years			
	Lighting - Lay-in	Unisex Across from 320 (332 on plan)	1	EA	6	6-10 years			
	Walls - Tile Ceramic/ Porcelain	Unisex Across from 320 (332 on plan)	108	SF	6	10+ years			
	Water Closet	Unisex Across from 320 (332 on plan)	1	EA	7	10+ years			
	Accessories	in 029 Engineer's Office (036 on plan)	116	SF	7	10+ years			
	Ceiling - Plaster/Drywall	in 029 Engineer's Office (036 on plan)	116	SF	6	10+ years			
	Doors - Steel Doors incl hw	in 029 Engineer's Office (036 on plan)	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	in 029 Engineer's Office (036 on	116	SF	6	10+ years			







Catego	ory : Room		В	uilding	: Main		3 S Sacramento DRIVE, Chicago, IL 60623
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		plan)					
	Floor Drain	in 029 Engineer's Office (036 on	1	EA	7	10+ years	
		plan)					
	Lavatory	in 029 Engineer's Office (036 on	1	EA	7	10+ years	
		plan)			_		
	Lighting - Lay-in	in 029 Engineer's Office (036 on	3	EA	6	6-10 years	
	Doutitions	plan)	4	Ε.	7	10	
	Partitions	in 029 Engineer's Office (036 on	1	EA	7	10+ years	
	Showers	plan) in 029 Engineer's Office (036 on	1	EA	7	10+ years	
	Showers	plan)	I	EA	,	10+ years	
	Walls - Tile Ceramic/ Porcelain	in 029 Engineer's Office (036 on	226	SF	6	10+ years	
	Walls The Octamby Forcelant	plan)	220	Oi.	O	101 years	
	Water Closet	in 029 Engineer's Office (036 on	1	EA	7	10+ years	
		plan)	•		•	.o. you.o	
		. ,					
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #106A (Other Instructional Use)						
	Ceiling - Lay-in	1st Floor	1,002	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	18	SF	4	1-2 years	Water damage.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	Repaired
	Floor - Carpet	1st Floor	1,020	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	650	SF	6	10+ years	
	Wireless System	1st Floor	1	EA	7	10+ years	
Classroo	om #BLDG A 112 (Regular Classroom)						
Ciassiul	Ceiling - Lay-in	1st Floor	654	SF	6	10+ years	
	Ceiling - Lay-iii Ceiling - Plaster/Drywall	1st Floor	50	SF	6	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	704	SF	6	10+ years	
		1st Floor	11	EA	6	6-10 years	
	Lighting - Lay-in	13111001		LF	7	6-10 years	
	Lighting - Lay-in Marker Board	1st Floor					
	Marker Board	1st Floor	24 250				
	Marker Board Walls - Masonry	1st Floor	250	SF	7	10+ years	
	Marker Board						
Classroo	Marker Board Walls - Masonry	1st Floor	250	SF	7	10+ years	
Classroo	Marker Board Walls - Masonry Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years	



	Category : Classroom			Building : Main				
			Recommend					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	535	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	10	EA	6	6-10 years		
	Marker Board	1st Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	730	SF	6	10+ years		
Classroc	om #BLDG A 114 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	503	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	32	SF	6	10+ years		
	Doors - Side-lite	1st Floor	13	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years		
	Floor - Tile	1st Floor	535	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	10	EA	6	6-10 years		
	Marker Board	1st Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	730	SF	6	10+ years		
Classroc	om #BLDG A 115 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	622	SF	6	10+ years		
	Ceiling - Lay-in	1st Floor	32	SF	4	0-1 year	Water damage.	
	Ceiling - Plaster/Drywall	1st Floor	50	SF	6	10+ years	Trate: damage:	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years		
	Floor - Tile	1st Floor	704	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	11	EA	6	6-10 years		
	Marker Board	1st Floor	24	LF	7	6-10 years		
	Walls - Masonry	1st Floor	250	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	500	SF	6	10+ years		
Classroc	om #BLDG A 117 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	712	SF	6	10+ years		
	Ceiling - Lay-in	1st Floor	24	SF	4	0-1 year	Water damage.	
	Ceiling - Plaster/Drywall	1st Floor	100	SF	6	10+ years		
	Doors - Side-lite	1st Floor	13	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	836	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	11	EA	6	6-10 years		
	Marker Board	1st Floor	24	LF	7	6-10 years		
	Walls - Masonry	1st Floor	250	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	550	SF	6	10+ years		
lassroc	om #BLDG A 118 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	820	SF	6	10+ years		



Catego	Category : Classroom		В	uilding	: Main				
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	1st Floor	16	SF	4	0-1 year	Water damage.		
	Doors - Side-lite	1st Floor	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	836	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	1	ĒΑ	6	6-10 years			
	Lighting - Lay-in	1st Floor	8	EΑ	6	6-10 years			
	Marker Board	1st Floor	12	LF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	510	SF	6	10+ years			
Classroo	m #BLDG A 119 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	812	SF	6	10+ years			
	Ceiling - Lay-in	1st Floor	48	SF	4	0-1 year	Water damage.		
	Doors - Side-lite	1st Floor		SF		•	water damage.		
			13		6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	860	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	9	EA	6	6-10 years			
	Marker Board	1st Floor	12	LF	7	10+ years			
	Walls - Concrete Block	1st Floor	310	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	592	SF	6	10+ years			
Classroo	m #BLDG A 137 (Store Room)								
	Ceiling - Lay-in	1st Floor	534	SF	6	10+ years			
	Doors - Side-lite	1st Floor	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	488	SF	6	10+ years			
	Floor - Tile	1st Floor	46	SF	4	0-1 year	Damaged tile		
	Lighting - Lay-in	1st Floor	9	EA	6	6-10 years	Damaged tile		
	Marker Board	1st Floor	24	LF	7	,			
	Walls - Plaster/Drywall	1st Floor	732	SF	6	10+ years 10+ years			
	Walls Tastel/Diywall	13(1100)	102	O.	O	101 years			
_Classroo	m #BLDG A 139 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	534	SF	6	10+ years			
	Doors - Side-lite	1st Floor	13	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	534	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	9	EA	6	6-10 years			
	Marker Board	1st Floor	24	LF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	732	SF	6	10+ years			
_Classroo	m #BLDG A 200 (Science Lab Level 1)								
	Casework	1st Floor	74	LF	7	10+ years			
	Ceiling - Lay-in	1st Floor	998	SF	6	10+ years			
	Ceiling - Lay-in Ceiling - Plaster/Drywall	1st Floor	80	SF	6	10+ years			
	Centing - Flaster/Drywan	13111001	00	OI.	U	10+ years			



Catego	Category : Classroom		В	uilding	: Main				
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Side-lite	1st Floor	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years			
	Eye Wash Station	1st Floor	1	EΑ	7	10+ years			
	Floor - Tile	1st Floor	1,078	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	17	EA	6	6-10 years			
	Marker Board	1st Floor	10	LF	7	6-10 years			
	Science Lab Shower	1st Floor	1	EA	7	10+ years			
	Storage/ Closet	1st Floor	100	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	920	SF	6	10+ years			
	Work Sink	1st Floor	4	EA	7	10+ years			
Classroo	om #BLDG A 203 (Science Lab Level 2)							
	Casework	2nd Floor	66	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	965	SF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	180	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Eye Wash Station	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	1,145	SF	6	10+ years			
	Gas Line	2nd Floor	, 14 14	ĒΑ	7	10+ years			
	Lighting - Lay-in	2nd Floor	19	EA	6	6-10 years			
	Marker Board	2nd Floor	10	LF	7	6-10 years			
	Science Lab Shower	2nd Floor	1	EA	7	10+ years			
	Storage/ Closet	2nd Floor	100	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	900	SF	6	10+ years			
	Work Sink	2nd Floor	8	ĒΑ	7	10+ years			
_Classroo	om #BLDG A 205 (Science Lab Level 1)							
	Casework	2nd Floor	78	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	1,068	SF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years			
	Eye Wash Station	2nd Floor	1	ΕA	7	10+ years			
	Floor - Tile	2nd Floor	1,118	SF	6	10+ years			
	Gas Line	2nd Floor	15	EΑ	7	10+ years			
	Lighting - Lay-in	2nd Floor	18	EΑ	6	6-10 years			
	Marker Board	2nd Floor	10	LF	7	6-10 years			
	Science Lab Fume Hood	2nd Floor	10	EA	7	10+ years			
	Science Lab Shower	2nd Floor	1	EA	7	10+ years			
	Storage/ Closet	2nd Floor	100	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	574	SF	6	10+ years			
	Work Sink	2nd Floor	9	EA	7	10+ years			
	WORK OHIK	2110 1 1001	9	LA	,	ioi yeais			



Category : Classroom		В	uilding	: Main				
0	Mana Tama	l costion	0	HOM	Danie.	Recommend	0	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classrooi	m #BLDG A 206 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	615	SF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	10	SF	4	1-2 years	Water damage.	
	Ceiling - Plaster/Drywall	2nd Floor	75	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	700	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	11	EA	6	6-10 years		
	Marker Board	2nd Floor	36	LF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	760	SF	6	10+ years		
Classrooi	m #BLDG A 226 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	685	SF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	735	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	11	EA	6	6-10 years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	700	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	80	SF	5	0-1 year	Damaged wall	
Classroo	m #BLDG A 228 (Regular Classroom)							
Classioo	Ceiling - Lay-in	2nd Floor	643	SF	6	10+ years		
	Ceiling - Lay-iii Ceiling - Plaster/Drywall	2nd Floor	50	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	13	EA	7	10+ years		
	Floor - Tile	2nd Floor	693	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	11	EA	6	6-10 years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	786	SF	6	10+ years		
	Walls Tlastel/Diywall	2110 1 1001	700	O.	O	101 years		
_Classrooi	m #BLDG A 229 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	625	SF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	675	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	11	EA	6	6-10 years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	770	SF	6	10+ years		
_Classrooi	m #BLDG A 230 (Regular Classroom)							

Campus Name: Collins HS Page : 26 of 68 Assessment Date: 06/22/2022



Catego	ry : Classroom		В	uilding	: Main		3 0 Gaeramento Britve, Onicago, le 00023
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	932	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	48	SF	4	1-2 years	Water damage.
	Ceiling - Plaster/Drywall	2nd Floor	40	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,010	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	635	SF	6	10+ years	
_Classroo	om #BLDG A 231 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	472	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	1-2 years	Water damage.
	Ceiling - Plaster/Drywall	2nd Floor	56	SF	6	10+ years	3
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	536	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	7	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	730	SF	6	10+ years	
_Classroc	om #BLDG A 232 (Store Room)						
	Ceiling - Lay-in	2nd Floor	500	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	56	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	556	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	6	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	738	SF	6	10+ years	
Classroo	om #BLDG A 233 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	596	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	74	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	670	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	780	SF	6	10+ years	
Classroo	om #BLDG A 234 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	801	SF	6	10+ years	
	-					-	



ategory : Classroom

Ruilding : Main

Category : Classroom			Building : Main					
_						Recommend	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	2nd Floor	65	SF	4	1-2 years	Water damage.	
	Ceiling - Plaster/Drywall	2nd Floor	9	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years		
	Floor - Tile	2nd Floor	875	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years		
	Marker Board	2nd Floor	24	LF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	558	SF	6	6-10 years		
_Classroo	om #BLDG A 235 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	601	SF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	24	SF	4	0-1 year	Water damage.	
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	675	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	11	EA	6	6-10 years		
	Marker Board	2nd Floor	24	LF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	770	SF	6	10+ years		
	·	2110 1 1001	7.10	O.	Ü	.o. youro		
Classroo	om #BLDG A 236 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	623	SF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	20	SF	4	1-2 years	Water damage.	
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	693	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	11	EA	6	6-10 years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	786	SF	6	10+ years		
Classroo	om #BLDG A 237 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	616	SF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	20	SF	4	0-1 year	Water damage.	
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	6	10+ years	samagoi	
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	13	EA	7	10+ years		
	Floor - Tile	2nd Floor	682	SF	6	10+ years		
	Floor - Tile	2nd Floor	4	SF	4	1-2 years	Damaged tile	
	Lighting - Lay-in	2nd Floor	11	EA	6	6-10 years	Damageu IIIe	
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	780	SF	6			
	vvalis - Flastel/Diywall	2110 [100]	780	SI-	U	10+ years		



Catego	ry : Classroom		В	uilding	: Main		5 6 Gadramento Bittve, Onicago, le 60025
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #BLDG A 238 (Regular Classroom	1)					
	Ceiling - Lay-in	2nd Floor	616	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	20	SF	4	0-1 year	Water damage.
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	6	10+ years	1 9 1
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	686	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	780	SF	6	10+ years	
_Classroc	om #BLDG A 239 (Regular Classroom)					
	Ceiling - Lay-in	2nd Floor	626	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	10	SF	4	0-1 year	Water damage.
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	6	10+ years	13
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	686	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	780	SF	6	10+ years	
Classroo	om #BLDG A 240 (Regular Classroom))					
	Ceiling - Lay-in	2nd Floor	596	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	74	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	670	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	780	SF	6	2-5 years	
	Walls - Plaster/Drywall	2nd Floor	100	SF	5	1-2 years	Damaged wall
_Classroo	om #BLDG A 300 (Computer Lab)						
	Ceiling - Lay-in	3rd Floor	993	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	993	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	670	SF	7	10+ years	
Classroo	om #BLDG A 301 (Regular Classroom)					
	Ceiling - Lay-in	3rd Floor	675	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		3 6 Gadramento Brive, Grieago, le 60025
Guiogo	.,		_	uug	· maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	3rd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	675	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	11	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	770	SF	6	10+ years	
_Classroo	om #BLDG A 302 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	693	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Tile	3rd Floor	693	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	6	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	786	SF	6	10+ years	
_Classroo	om #BLDG A 304 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	697	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	697	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	6	6-10 years	
	Marker Board	3rd Floor	19	LF	7	10+ years	
	Walls - Concrete Block	3rd Floor	290	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	530	SF	6	10+ years	
_Classroo	om #BLDG A 307 (Art Room)						
	Casework	3rd Floor	5	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,170	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	, 1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	1,170	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	15	EA	6	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	188	SF	7	10+ years	
	Storage/ Closet	3rd Floor	173	SF	7	10+ years	
	Storage/ Closet	3rd Floor	90	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	650	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	250	SF	6	10+ years	
	Work Sink	3rd Floor	1	ĒΑ	7	10+ years	
_Classroo	om #BLDG A 310 (Science Lab Level 1)						
	Casework	3rd Floor	65	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	970	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	30	SF	4	1-2 years	Water damage.
	5	-				,	ŭ



Category : Classroom		В	uilding	: Main			
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	3rd Floor	13	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	2	EA	7	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,000	SF	6	10+ years	
	Gas Line	3rd Floor	16	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	7	10+ years	
	Science Lab Shower	3rd Floor	1	EA	7	10+ years	
	Storage/ Closet	3rd Floor	100	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	240	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	450	SF	6	10+ years	
	Work Sink	3rd Floor	7	EΑ	7	10+ years	
	Work Sink	3rd Floor	11	EA	5	0-1 year	Does not work.
						, , , , , ,	
Classroc	om #BLDG A 313 (Science Lab Level 1)						
	Casework	3rd Floor	68	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,146	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	24	SF	4	1-2 years	Water damage.
	Doors - Side-lite	3rd Floor	13	SF	7	10+ years	ŭ
	Doors - Steel Doors incl hw	3rd Floor	1	ĒΑ	7	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,170	SF	6	10+ years	
	Gas Line	3rd Floor	, 15	ĒΑ	7	10+ years	
	Lighting - Lay-in	3rd Floor	19	ΕA	6	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	7	10+ years	
	Science Lab Shower	3rd Floor	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	560	SF	6	10+ years	
	Work Sink	3rd Floor	12	EA	7	10+ years	
					•	, , , , , , , , , , , , , , , , , , , ,	
Classroo	om #BLDG A 314 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	692	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	1-2 years	Water damage.
	Ceiling - Plaster/Drywall	3rd Floor	130	SF	6	10+ years	•
	Doors - Side-lite	3rd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	830	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	11	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	835	SF	6	10+ years	
	*					-	
Classroo	om #BLDG A 315 (Regular Classroom)						



Catego	Category : Classroom		В	uilding	: Main				
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	3rd Floor	465	SF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	70	SF	6	10+ years			
	Doors - Side-lite	3rd Floor	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	535	SF	6	6-10 years			
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years			
	Marker Board	3rd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	535	SF	6	10+ years			
_Classroo	m #BLDG A 316 (Regular Classroom)								
	Ceiling - Lay-in	3rd Floor	636	SF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	50	SF	6	10+ years			
	Doors - Side-lite	3rd Floor	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	686	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	11	EA	6	6-10 years			
	Marker Board	3rd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	780	SF	6	10+ years			
	Walls Flastel/Dlywall	010 1 1001	700	O.	J	101 years			
Classroo	m #BLDG A 317 (Regular Classroom)								
	Ceiling - Lay-in	3rd Floor	50	SF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	636	SF	6	10+ years			
	Doors - Side-lite	3rd Floor	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	686	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	11	EA	6	6-10 years			
	Marker Board	3rd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	780	SF	6	10+ years			
Classroo	om #BLDG A 318 (Regular Classroom)								
	Ceiling - Lay-in	3rd Floor	15	SF	7	10+ years	Repaired		
	Ceiling - Lay-in	3rd Floor	621	SF	6	10+ years	•		
	Ceiling - Plaster/Drywall	3rd Floor	50	SF	6	10+ years			
	Doors - Side-lite	3rd Floor	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years			
	Floor - Tile	3rd Floor	686	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	11	EA	6	6-10 years			
	Marker Board	3rd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	780	SF	6	10+ years			
Closses	om #BLDG A 319 (Regular Classroom)								
Ciassio	, ,	Ord Floor	0.40	C.E.	^	10			
	Ceiling - Lay-in	3rd Floor	643	SF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	50	SF	6	10+ years			



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Doors - Side-lite	3rd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	693	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	786	SF	6	10+ years	
Classroc	om #BLDG A 320 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	625	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	50	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	675	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	6	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	770	SF	6	6-10 years	
Classroc	om #BLDG A 321 (Regular Classroom)						
<u> </u>	Ceiling - Lay-in	3rd Floor	866	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	9	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	10+ years	
	Floor - Tile	3rd Floor	875	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	6	6-10 years	
		3rd Floor		LF	7	6-10 years	
	Marker Board Walls - Plaster/Drywall	3rd Floor	24 558	SF	6	10+ years	
Placeron	om #BLDG A 322 (Regular Classroom)						
JidaaiUU	Ceiling - Lay-in	3rd Floor	596	SF	6	10+ years	
	Ceiling - Lay-iii Ceiling - Plaster/Drywall	3rd Floor	74	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	13	SF	7	10+ years	
	Doors - Side-life Doors - Wood Doors inclu hw	3rd Floor	13	SF EA	7 7	•	
	Floor - Tile	3rd Floor 3rd Floor	670	SF	<i>7</i> 6	10+ years	
						10+ years	
	Lighting - Lay-in	3rd Floor	8	EA	6	6-10 years	
	Marker Board Walls - Plaster/Drywall	3rd Floor 3rd Floor	24 780	LF SF	7 6	10+ years 10+ years	
Classroo	om #BLDG A 323 (Regular Classroom)					•	
عاظمما بال	Ceiling - Lay-in	3rd Floor	500	SF	e	10+ years	
					6		
	Ceiling - Plaster/Drywall	3rd Floor	56	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	556	SF	6	10+ years	





Category : Classroom			В	Building : Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	3rd Floor	7	EΑ	6	6-10 years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	738	SF	6	10+ years		
Classroo	om #BLDG A 324 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	480	SF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	56	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	13	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years		
	Floor - Tile	3rd Floor	536	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	7	EΑ	6	6-10 years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	730	SF	6	10+ years		

Category: Interior Building: Main

Jarogo	y : iiitoiioi			ananig			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group Corridor	item - Type	Location	Quantity	OCIVI	Naiik	Replacement	Comments
Corridor	Coiling Lovin	1et Floor	6.542	QE.	6	10 L VOORO	
	Ceiling - Lay-in	1st Floor	6,543	SF	6	10+ years	Water demaged tile
	Ceiling - Lay-in	1st Floor	10	SF	4	1-2 years	Water damaged tile
	Doors - Steel Doors incl hw	1st Floor	38	EΑ	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EΑ	7	6-10 years	
	Drinking Fountains - Single Water Cooler	1st Floor	1	EA	_	6-10 years	
	Floor - Tile/Sheet	1st Floor	6,553	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	66	EA	6	6-10 years	
	Student Lockers - One Tier	1st Floor	161	EA	7	10+ years	
	Walls - Masonry	1st Floor	5,522	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,202	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor Elevator Lobby	249	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor Elevator Lobby	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor Elevator Lobby	249	SF	7	10+ years	
	Lighting - Lay-in	1st Floor Elevator Lobby	4	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor Elevator Lobby	684	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor Vestibules	485	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Vestibules	95	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor Vestibules	8	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor Vestibules	580	SF	7	10+ years	
	Lighting - Lay-in	1st Floor Vestibules	3	EA	6	6-10 years	
	Walls - Masonry	1st Floor Vestibules	830	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Vestibules	54	SF	6	10+ years	
	•	2nd Floor		SF	6	•	
		2nd Floor	10		4		Water damage.
		2nd Floor	-		6		
	•				7	•	
	Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain	2nd Floor	5,941 10 602 2	SF SF SF EA		10+ years 0-1 year 10+ years 6-10 years	Water damage.

Campus Name: Collins HS Page : 34 of 68 Assessment Date: 06/22/2022



Catego	ry : Interior		В	uilding	: Main		· • • • • • • • • • • • • • • • • • • •
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	6,553	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	67	EA	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	392	EA	7	10+ years	
	Walls - Masonry	2nd Floor	2,844	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6,956	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor Elevator Lobby	253	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor Elevator Lobby	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor Elevator Lobby	253	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor Elevator Lobby	3	EΑ	6	6-10 years	
	Walls - Concrete Block	2nd Floor Elevator Lobby	698	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	6,354	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	180	SF	4	0-1 year	Water damage.
	Doors - Steel Doors incl hw	3rd Floor	8	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	6,534	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	66	EA	6	6-10 years	
	Student Lockers - One Tier	3rd Floor	367	EA	7	10+ years	
	Walls - Masonry	3rd Floor	3,024	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5,720	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor Elevator Lobby	253	SF	6	6-10 years	
	Doors - Wood Doors include hw	3rd Floor Elevator Lobby	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor Elevator Lobby	253	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor Elevator Lobby	4	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor Elevator Lobby	698	SF	7	10+ years	
	Ceiling - Exposed	Basement	2,230	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	25	EA	7	10+ years	
	Drinking Fountains - Single Fountain	Basement	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	2,230	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	8	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement	14	EA	6	6-10 years	
	Walls - Concrete Block	Basement	4,600	SF	7	10+ years	
Safety							
	Camera Viewing Station	Various	3	EA	7	6-10 years	
	Security Cameras	Various	32	EA	7	6-10 years	
	Security Cameras	Various	10	EA	7	6-10 years	
<u>Stairs</u>	Ceiling - Plaster/Drywall	Basement - North	180	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement - North	84	SF	7	10+ years	
	Handrails	Basement - North	56	LF	7	10+ years	
	Lighting - Pendent/Surface	Basement - North	3	EA	6	6-10 years	
	Lighting I endembounde	Dascinent - Notti	3	LA	J	0-10 years	

Campus Name: Collins HS Page : 35 of 68 Assessment Date: 06/22/2022





Category : Interior			В	Building : Main			<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stairs - Concrete	Basement - North	96	LF	7	10+ years	
	Walls - Concrete Block	Basement - North	750	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - South	180	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement - South	84	SF	7	10+ years	
	Handrails	Basement - South	56	LF	7	10+ years	
	Lighting - Pendent/Surface	Basement - South	3	EA	6	6-10 years	
	Stairs - Concrete	Basement - South	96	LF	7	10+ years	
	Walls - Concrete Block	Basement - South	750	SF	7	10+ years	
	Ceiling - Lay-in	North	280	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North	350	SF	6	10+ years	
	Floor - Terrazzo	North	180	SF	7	10+ years	
	Handrails	North	218	LF	7	10+ years	
	Lighting - Lay-in	North	5	EA	6	6-10 years	
	Stairs - Terrazzo	North	432	LF	7	10+ years	
	Walls - Masonry	North	1,350	SF	7	10+ years	
	Walls - Plaster/Drywall	North	100	SF	6	10+ years	
	Ceiling - Lay-in	South	280	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	350	SF	6	10+ years	
	Floor - Terrazzo	South	180	SF	7	10+ years	
	Handrails	South	218	LF	7	10+ years	
	Lighting - Lay-in	South	5	EA	6	6-10 years	
	Stairs - Terrazzo	South	432	LF	7	10+ years	
	Walls - Masonry	South	1,350	SF	7	10+ years	
	Walls - Plaster/Drywall	South	100	SF	6	10+ years	
_Vertical (Conveyance						
	Elevator - Hydraulic Elevator	3rd Floor	1	EA	7	10+ years	
	Elevator - Hydraulic Elevator	3rd Floor	1	EA	4	0-1 year	Does not work.

Campus Name: Collins HS Page : 36 of 68 Assessment Date: 06/22/2022



Category: Exterior Building: Linked Addition-Fine Arts & Tech Building

Catego	ry : Exterior		Building : Linked Addition-Fine Arts & Tech Building						
						Recommend			
≩roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
ntrance									
	Exterior Doors - Side lite	17	4	EA	7	10+ years			
	Exterior Doors - Store Front	17	2	EA	6	10+ years			
	Exterior Doors - Transom Lite	17	1	EA	7	10+ years			
	Exterior Doors - Side lite	18	4	EA	6	10+ years			
	Exterior Doors - Store Front	18	2	EA	6	10+ years			
	Exterior Doors - Transom Lite	18	1	EA	6	10+ years			
	Exterior Doors - Side lite	19	4	EA	7	10+ years			
	Exterior Doors - Store Front	19	1	EA	6	10+ years			
	Exterior Doors - Transom Lite	19	1	EA	7	10+ years			
	Exterior Doors - Exterior FRP Door	2	2	EA	6	10+ years			
	Exterior Doors - Side lite	2	4	EA	6	10+ years			
	Exterior Doors - Transom Lite	2	1	EA	6	10+ years			
	Exterior Doors - Exterior Steel Door	2.5	1	EA	6	10+ years			
	Exterior Stairs - Concrete	2.5	3	LF	6	10+ years			
	Exterior Doors - Store Front	3	1	EA	7	10+ years			
	Exterior Doors - Transom Lite	3	1	EA	7	10+ years			
	Exterior Doors - Exterior FRP Door	4	2	EA	6	10+ years			
	Exterior Doors - Side lite	4	6	EA	7	10+ years			
	Exterior Doors - Transom Lite	4	1	EA	7	10+ years			
	Exterior Stairs - Concrete	4	10	LF	5	1-2 years	Cracked concrete		
	Entrance Control - Audio and Video	5	1	EA	7	10+ years			
	Exterior Doors - Exterior FRP Door	5	6	ĒΑ	6	10+ years			
	Exterior Doors - Side lite	5	23	EA	6	10+ years			
	Exterior Doors - Transom Lite	5	3	EA	6	10+ years			
	Power Door Operator and Controls	5	1	EA	7	10+ years			
						,			
oundati									
	Foundation - Concrete	Entire Building	944	LF	7	10+ years			
	Superstructure - Metal Deck/ Concrete	Entire Building	37,803	SF	7	10+ years			
	Topping								
ighting									
- 3	Exterior Lighting - Lighting	Entire Building	3	EA	5	6-10 years			
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	7	6-10 years			
Roof Sys	etem.								
COI CY	Coping - Metal	G	110	LF	6	10+ years			
	Downspouts - Interior Downspouts	G	30	LF	6	10+ years			
	Parapet - Parapet < 16" Height	G	110	LF	6	10+ years			
	Roof - Modified Bitumen	G	2,124	SF	6	6-10 years			
	Roof Structure - Steel / Metal Deck/	G	2,124	SF	7	10+ years			
	1001 Oli doldie - Oleel / Melai Deon	S	2,124	Oi.	'	TOT years			

Campus Name: Collins HS Page : 37 of 68 Assessment Date: 06/22/2022





Catego	ry : Exterior		В	uilding	: Linked	d Addition-Fine	Arts & Tech Building
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Concrete Topping						
	Coping - Metal	Н	105	LF	6	10+ years	
	Downspouts - Interior Downspouts	Н	30	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Н	105	LF	6	10+ years	
	Roof - Modified Bitumen	Н	1,930	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	Н	1,930	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	I	1	EA	7	10+ years	
	Coping - Metal	I	157	LF	6	10+ years	
	Downspouts - Interior Downspouts		80	LF	6	10+ years	
	Parapet - 16" - 30" Height	İ	64	LF	6	10+ years	
	Parapet - Parapet > 30"	i	63	LF	6	10+ years	
	Parapet - Parapet > 30"	i	30	LF	4	1-2 years	Open joints, cracked bbrick. Section
	rarapot rarapot > 00	•	00		•	1 2 youro	of wall has shifted and is out of
							alignment
	Roof - Modified Bitumen	1	5,952	SF	6	6-10 years	aligninient
	Roof Structure - Steel / Metal Deck/		5,952	SF	7	10+ years	
		ı	5,952	SF	/	10+ years	
	Concrete Topping		4	- ^	7	40	
	Access Ladder - Metal	J	1	EA	7	10+ years	
	Coping - Metal	J	346	LF	6	10+ years	
	Downspouts - Interior Downspouts	J	90	LF	6	10+ years	
	Parapet - 16" - 30" Height	J	76	LF	6	10+ years	
	Parapet - Parapet < 16" Height	J	270	LF	6	10+ years	
	Roof - Modified Bitumen	J	8,277	SF	6	6-10 years	Roof is in good condition
	Roof Structure - Steel / Metal Deck/	J	8,277	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	K	1	EA	7	10+ years	
	Coping - Metal	K	157	LF	6	10+ years	
	Downspouts - Interior Downspouts	K	80	LF	6	10+ years	
	Parapet - 16" - 30" Height	K	64	LF	6	10+ years	
	Parapet - Parapet > 30"	K	93	LF	6	10+ years	
	Parapet - Parapet > 30"	K	10	LF	5	1-2 years	Cracked brick
	Roof - Modified Bitumen	K	16	SF	5	1-2 years	Vegetation growing at drains
	Roof - Modified Bitumen	K	5,936	SF	5	6-10 years	Roof is in good condition
	Roof Structure - Steel / Metal Deck/	K	5,952	SF	7	10+ years	. too. io iii good comailion
	Concrete Topping		0,002	О.	•	.o. you.o	
	Access Ladder - Metal	1	1	EA	7	10+ years	
	Coping - Metal	Ī	250	LF	6	10+ years	
	Downspouts - Interior Downspouts	Ĺ	86	LF	6	10+ years	
	Parapet - 16" - 30" Height	L I	38	LF	6	10+ years	
	Parapet - Parapet < 16" Height	L	212	LF LF	6	10+ years	
		L 1		SF			
	Roof - Modified Bitumen	L I	13,548		6	6-10 years	Distoring ash anota Failed residen
	Roof - Modified Bitumen	L	20	SF	4	1-2 years	Blistering, soft spots, Failed repairs
	Roof Hatch - Metal	L	1	EA	7	10+ years	

Campus Name: Collins HS Page : 38 of 68 Assessment Date: 06/22/2022





Catogo	ry - Exterior	Р	Building : Linked Addition-Fine Arts & Tech Building						
Catego	ategory : Exterior								
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Roof Structure - Steel / Metal Deck/	L	13,568	SF	7	10+ years			
	Concrete Topping					•			
	11 0								
Walls									
	Canopy - Concrete/ Stucco	Entire Building	340	SF	7	10+ years			
	Exterior Walls - Brick	Entire Building	67,103	SF	6	10+ years			
		3	,			,			
Windows	3								
	Guard - Guards perforated	Entire Building	480	SF	6	10+ years			
	Lintels - Steel	Entire Building	83	LF	6	10+ years			
	Lintels - Steel	Entire Building	10	LF	5	0-1 year	Corroded steel		
	Storefront Windows	Entire Building	945	SF	6	10+ years			
	Windows - Casement Aluminum Double-	Entire Building	480	SF	6	10+ years			
	pane			=	•	- ,			
	pane								

Category : Electrical Building : Linked Addition-Fine Arts & Tech Building

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System	Location	Quantity	OOM	Naiik	Replacement	Comments
Lineigei	Emergency A/C Power - Auditoium and	Entire Building	4,368	SF	7	6-10 years	
	Aisle Lighting						
	Emergency A/C Power - Corridors and Stairs	Entire Building	5,368	SF	7	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	684	SF	7	6-10 years	
	Exit Signs - Auditoium	Entire Building	4	EΑ	6	2-5 years	Batteries need to be changed.
	Exit Signs - Corridors and Stairs	Entire Building	8	EA	6	2-5 years	Batteries need to be changed.
	Security System - CCTV	Entire Building	66,155	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	66,155	SF	6	6-10 years	
Main Se	vice						
	PA System	Entire Building	66,155	SF	6	6-10 years	New item added per current observation Served from main building
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	7	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	4	0-1 year	Older panel
	Lighting and Power Panels - Above 100 A	Entire Building	4	EΑ	7	6-10 years	·
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EΑ	6	6-10 years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	6-10 years	
	amp Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	

Campus Name: Collins HS Page : 39 of 68 Assessment Date: 06/22/2022



Catego	ory : Fire Protection		В	Building : Linked Addition-Fine Arts & Tech Building						
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Fire Alaı										
	Fire Alarm Strobe Lights	Entire Building	66,155	SF	6	6-10 years				
	Fire Alarm_System	Entire Building	66,155	SF	6	6-10 years	Served from main building			
Catego	ory : Mechanical		В	uilding	: Linked		Arts & Tech Building			
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Air Cond	ditioning									
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	2-5 years				
Air Hand	dling Systems									
	Fan Coil Unit- Celing Mounted - Electric	1st Floor	1	EA	6	6-10 years	Above ceiling, could not access.			
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-11			
	Gas Heating and DX Cooling w/ Self					•				
	Contained Compressor - 21 - 30 tons									
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	2	0-1 year	RTU-12 Abandoned and replaced			
	Gas Heating and DX Cooling w/ Self						with RTU-21			
	Contained Compressor - 21 - 30 tons	D (_ ^	•	0.40	DTIL 0.0			
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-9 Served classrooms			
	Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons									
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-10			
	Gas Heating and DX Cooling w/ Self	11001	'	L/ \	O	o to years	1010			
	Contained Compressor - 46 - 60 tons									
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	6	10+ years	Replace from RTU-12 Installed new			
	Gas Heating and DX Cooling Coil - 21 - 30					, , , , , ,	RTU-21.			
	tons									
	Zone Dampers	Roof - Zone Dampers	16	EA	6	2-5 years	Integral to the RTU's.			
-leating	Devices									
	Unit Heater - Electric	1st Floor	1	EΑ	6	6-10 years				
	Cabinet Heaters - With Electric Coil	Entire Building	2	EA	6	6-10 years				
Tampar	ature Control									
ramber		Entire Building	66 155	SF	6	6-10 years	Renaired and working per building			
	DDC System	Little Ballaling	00,100	Si	O	0-10 years				
	Thermostats - DDC	Entire Buildina	19	EA	6	6-10 years	5.1g.1001			
		9				5 . 5 , 5 5				
/entilati										
		Roof	1	EA	6	6-10 years				
	CFM									
·	on Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building Entire Building Roof	66,155 19	SF EA EA		6-10 years 6-10 years 6-10 years	Repaired and working per be engineer			





Catego	Category : Mechanical				Building : Linked Addition-Fine Arts & Tech Building					
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	6	EA	6	6-10 years				
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	1	EA	7	6-10 years				
	Roof Mounted Duct Work	Roof	15	LF	6	10+ years				

Category: Plumbing Building: Linked Addition-Fine Arts & Tech Building

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Piping						•	
. •	Domestic Piping-Hot Water Return Lines	Entire Building	37,803	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	37,803	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	37,803	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	37,803	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	37,803	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	37,803	SF	6	10+ years	
	Sanitary Piping	Entire Building	37,803	SF	7	10+ years	
	Storm Piping	Entire Building	37,803	SF	7	10+ years	
	Vent Piping	Entire Building	37,803	SF	7	10+ years	

Category : Room **Building: Linked Addition-Fine Arts & Tech Building**

uiogo	iy . itooiii		Building . Elliked Additional Arts & Teen Building					
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
dminist	trative Suites/Offices							
	Ceiling - Lay-in	130A - Office in Class Room 130	216	SF	6	10+ years	This room was not accessible as there was no key. Components of this room are ranked based on sim rooms.	
	Doors - Steel Doors incl hw	130A - Office in Class Room 130	1	EA	6	10+ years	This room was not accessible as there was no key. Components of this room are ranked based on sim rooms.	
	Floor - Tile	130A - Office in Class Room 130	216	SF	6	10+ years		
	Lighting - Lay-in	130A - Office in Class Room 130	2	EA	6	6-10 years		
	Power Distribution	130A - Office in Class Room 130	6	EA	7	10+ years		
	Walls - Concrete Block	130A - Office in Class Room 130	553	SF	7	10+ years		
	Ceiling - Lay-in	132A - Office in Art Room 132	68	SF	6	10+ years		
	Doors - Side-lite	132A - Office in Art Room 132	25	SF	7	10+ years		
	Doors - Steel Doors incl hw	132A - Office in Art Room 132	1	EΑ	7	10+ years		



Catego	Category : Room			Building : Linked Addition-Fine Arts & Tech Building				
Jaioge	.,		_	uug		Recommend	7 mio di 100m Dumanig	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile	132A - Office in Art Room 132	68	SF	6	10+ years		
	Lighting - Lay-in	132A - Office in Art Room 132	2	ĒΑ	6	6-10 years		
	Power Distribution	132A - Office in Art Room 132	2	EA	7	10+ years		
	Walls - Concrete Block	132A - Office in Art Room 132	155	SF	7	10+ years		
	Ceiling - Lay-in	137 - Office	199	SF	6	10+ years		
	Ceiling - Lay-in	137 - Office	8	SF	4	1-2 years	Missing	
	Doors - Steel Doors incl hw	137 - Office	1	EA	7	10+ years	Wildeling	
	Floor - Tile	137 - Office	207	SF	6	10+ years		
	Lighting - Lay-in	137 - Office	4	EA	6	6-10 years		
	Power Distribution	137 - Office	6	EA	7	10+ years		
	Walls - Concrete Block	137 - Office	508	SF	7			
		140 - Media Center Open Office	1,022	SF	6	10+ years	This room was not assessible as	
	Ceiling - Lay-in	·				10+ years	This room was not accessible as there was no key. Components of this room are ranked based on similar rooms.	
	Doors - Steel Doors incl hw	140 - Media Center Open Office	2	EA	7	10+ years	This room was not accessible as there was no key. Components of this room are ranked based on similar rooms.	
	Floor - Carpet	140 - Media Center Open Office	1,022	SF	6	6-10 years		
	Lighting - Pendent/Surface	140 - Media Center Open Office	20	ĒΑ	6	10+ years		
	Power Distribution	140 - Media Center Open Office	12	EA	7	10+ years		
	Walls - Concrete Block	140 - Media Center Open Office	240	SF	7	10+ years		
	Walls - Plaster/Drywall	140 - Media Center Open Office	1,492	SF	6	10+ years		
	Ceiling - Lay-in	140E	183	SF	6	10+ years		
	Doors - Steel Doors incl hw	140E	1	EΑ	7	10+ years		
	Floor - Tile	140E	183	SF	6	10+ years		
	Lighting - Lay-in	140E	2	EA	6	2-5 years		
	Power Distribution	140E	4	EΑ	7	10+ years		
	Walls - Plaster/Drywall	140E	628	SF	6	10+ years		
	Work Sink	140E	1	EA	7	10+ years		
	Ceiling - Lay-in	144A Office	117	SF	6	10+ years		
	Doors - Side-lite	144A Office	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	144A Office	1	EA	7	10+ years		
	Floor - Tile	144A Office	117	SF	6	10+ years		
	Lighting - Lay-in	144A Office	4	EA	6	6-10 years		
	Power Distribution	144A Office	2	EA	7	10+ years		
	Walls - Concrete Block	144A Office	400	SF	7	•		
	vvalis - Collete Block	144A Office	400	ЗF	,	10+ years		
_Auditoriu	ım & Theater							
	Ceiling - Exposed	1st Floor	4,368	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st Floor	10	EΑ	7	10+ years		
	Floor - Carpet	1st Floor	4,368	SF	6	6-10 years	Vent cover missing	
	Lighting - Pendent/Surface	1st Floor	34	EA	6	6-10 years		
			31	_, ,	Ü	o .o youro		





Catego	ategory : Room			Building : Linked Addition-Fine Arts & Tech Building				
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Main Floor Seating	1st Floor	450	EΑ	7	10+ years		
	Sound System	1st Floor	1	EA	7	6-10 years		
	Stage	1st Floor	1,696	SF	6	10+ years		
	Stage Curtain	1st Floor	10	EA	7	6-10 years		
	Stage Lift	1st Floor	1	EΑ	7	10+ years		
	Stage Lighting System	1st Floor	1	EΑ	7	6-10 years		
	Stairs - Wood	1st Floor	100	LF	6	10+ years		
	Storage/ Closet	1st Floor	135	SF	7	10+ years		
	Walls - Masonry	1st Floor	1,500	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	776	SF	6	10+ years		
	Walls - Sound Panel	1st Floor	770	SF	7	10+ years		
Mechani	cal/ Service Rooms							
	Janitor's Closet	Arts Building Support Spaces	22	SF	7	10+ years		
	Janitor's Closet	Arts Building Support Spaces	22	SF	7	10+ years		
	Mechanical/ Service Rooms	Arts Building Support Spaces	174	SF	7	10+ years		
	Storage Room	Arts Building Support Spaces	200	SF	7	10+ years		
Restroor	n							
	Accessories	149 - Boys' Toilet Room	342	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	149 - Boys' Toilet Room	337	SF	6	10+ years		
	Ceiling - Plaster/Drywall	149 - Boys' Toilet Room	5	SF	5	0-1 year	Cracked ceiling	
	Floor - Tile Ceramic/ Porcelain	149 - Boys' Toilet Room	342	SF	6	10+ years	Gracitod coming	
	Floor Drain	149 - Boys' Toilet Room	1	EA	7	10+ years		
	Hand Dryer	149 - Boys' Toilet Room	1	EΑ	7	6-10 years		
	Lavatory	149 - Boys' Toilet Room	3	EA	7	10+ years		
	Lighting - Lay-in	149 - Boys' Toilet Room	8	EA	6	6-10 years		
	Partitions	149 - Boys' Toilet Room	2	EΑ	7	10+ years		
	Urinals	149 - Boys' Toilet Room	4	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	149 - Boys' Toilet Room	719	SF	6	10+ years		
	Water Closet	149 - Boys' Toilet Room	2	EA	7	10+ years		
	Accessories	150 - Girls' Toilet Room	342	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	150 - Girls' Toilet Room	342	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	150 - Girls' Toilet Room	342	SF	6	10+ years		
	Floor Drain	150 - Girls' Toilet Room	1	EA	7	10+ years		
	Hand Dryer	150 - Girls' Toilet Room	1	EA	7	6-10 years		
	Lavatory	150 - Girls Toilet Room	3	EA	7	10+ years		
	Lighting - Lay-in	150 - Girls Toilet Room	8	EA	6	6-10 years		
	Partitions	150 - Girls Toilet Room	6	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	150 - Girls Toilet Room	719	SF	6	10+ years		
	Water Closet	150 - Girls' Toilet Room	6	EA	6	10+ years		
Catego	ry : Classroom		В	uildina	: Linked	d Addition-Fine	Arts & Tech Building	
	Item - Type	Location	Quantity	UOM	Rank		Comments	





					Replacement
Classroom #130 (Other Instructional Use)					nopiacomon.
Casework	1st Floor	25	LF	7	10+ years
Ceiling - Lay-in	1st Floor	1,879	SF	6	10+ years
Doors - Steel Doors incl hw	1st Floor	4	ĒΑ	6	10+ years
Floor - Tile	1st Floor	1,879	SF	6	10+ years
Lighting - Lay-in	1st Floor	44	ĒΑ	6	6-10 years
Marker Board	1st Floor	16	LF	7	6-10 years
Storage/ Closet	1st Floor	74	SF	7	10+ years
Walls - Concrete Block	1st Floor	1,454	SF	7	10+ years
Classroom #132 (Art Room)					
Casework	1st Floor	37	LF	7	10+ years
Ceiling - Lay-in	1st Floor	1,416	SF	6	10+ years
Doors - Steel Doors incl hw	1st Floor	3	EA	7	10+ years
Floor - Tile	1st Floor	1,416	SF	6	10+ years
Lighting - Lay-in	1st Floor	41	EA	6	6-10 years
Marker Board	1st Floor	16	LF	7	6-10 years
Storage/ Closet	1st Floor	110	SF	7	10+ years
Walls - Concrete Block	1st Floor	1,729	SF	7	10+ years
Work Sink	1st Floor	1,729	EA	7	•
WORK SINK	TSI FIOOI	Z	EA	,	6-10 years
Classroom #133 (Other Instructional Use)					
Ceiling - Lay-in	1st Floor	687	SF	6	10+ years
Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years
Floor - Tile	1st Floor	687	SF	6	10+ years
Lighting - Lay-in	1st Floor	18	EA	6	6-10 years
Marker Board	1st Floor	16	LF	7	6-10 years
Walls - Concrete Block	1st Floor	1,027	SF	6	10+ years
Classroom #134 (Choral Room)					
Ceiling - Lay-in	1st Floor	1,431	SF	6	10+ years
Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years
Floor - Tile/Sheet	1st Floor	1,431	SF	6	6-10 years
Lighting - Pendent/Surface	1st Floor	21	EΑ	6	6-10 years
Marker Board	1st Floor	16	LF	7	6-10 years
Sound Panels	1st Floor	20	EΑ	7	10+ years
Storage/ Closet	1st Floor	144	SF	7	10+ years
Walls - Concrete Block	1st Floor	2,045	SF	7	10+ years
Classroom #136 (Band Room)					
Ceiling - Lay-in	1st Floor	1,743	SF	6	10+ years
Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years
Floor - Carpet	1st Floor	1,743	SF	6	6-10 years
Lighting - Pendent/Surface	1st Floor	1,743	EA	6	6-10 years
Marker Board	1st Floor	16	LF	7	6-10 years
Mainei Duaiu	1301 1001	10	LI	,	0-10 years



Schools						13 S Sacramento DRIVE, Chicago, IL 60623
					Replacement	
Risers	1st Floor	116	LF	7	10+ years	
Sound Panels	1st Floor	23	EA	7	10+ years	
Storage/ Closet	1st Floor	150	SF	7	10+ years	
Walls - Concrete Block	1st Floor	2,427	SF	7	10+ years	
Traile Control 2.00.		_,	О.	•	. o . y ca c	
Classroom #140A (Computer Lab)						
Casework	1st Floor	32	LF	7	10+ years	
Ceiling - Lay-in	1st Floor	1,063	SF	6	10+ years	
Doors - Steel Doors incl hw	1st Floor	3	EA	6	10+ years	
Floor - Carpet	1st Floor	1,063	SF	6	6-10 years	
Lighting - Pendent/Surface	1st Floor	42	EA	6	10+ years	
Walls - Plaster/Drywall	1st Floor	1,698	SF	6	10+ years	
		· ·		7		
Wireless System	1st Floor	1	EA	/	6-10 years	
Classroom #140B (Computer Lab)						
Ceiling - Lay-in	1st Floor	1,022	SF	6	10+ years	
Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
Floor - Tile	1st Floor	1,022	SF	6	6-10 years	
Lighting - Pendent/Surface	1st Floor		EA	6		
Marker Board	1st Floor	12 8	LF	_	6-10 years	
		_		7	6-10 years	
Walls - Plaster/Drywall	1st Floor	1,488	SF	6	10+ years	
Wireless System	1st Floor	1	EA	7	6-10 years	
Classroom #140D (Multi Purpose Room)						
Ceiling - Lay-in	1st Floor	368	SF	6	10+ years	
Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
Floor - Carpet	1st Floor	368	SF	6	6-10 years	
Lighting - Lay-in	1st Floor	6	EA	6	6-10 years	
		-		6		
Walls - Plaster/Drywall	1st Floor	822	SF	О	10+ years	
_Classroom #140F (Store Room)						
Ceiling - Lay-in	1st Floor	246	SF	6	10+ years	
Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	5	0-1 year	Missing door
Floor - Tile	1st Floor	246	SF	6	10+ years	g dee.
Lighting - Lay-in	1st Floor	3	EA	6	6-10 years	
Walls - Plaster/Drywall	1st Floor	732	SF	6	10+ years	
walls - Flastel/Drywall	151 F1001	132	SF	O	10+ years	
Classroom #144 (Regular Classroom)						
Casework	1st Floor	53	LF	7	10+ years	
Ceiling - Lay-in	1st Floor	1,007	SF	6	10+ years	
Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
Floor - Tile	1st Floor	1,007	SF	6	10+ years	
Lighting - Lay-in	1st Floor	25	EA	6	6-10 years	
Marker Board	1st Floor	16	LF	7	6-10 years	
		-			•	
Storage/ Closet	1st Floor	100	SF	7	10+ years	



				Replacement	
Walls - Concrete Block	1st Floor	575 SI		10+ years	
Walls - Plaster/Drywall	1st Floor	575 SI		10+ years	
Work Sink	1st Floor	2 E	A 7	10+ years	
Classroom #146 (Regular Classroom)					
Ceiling - Lay-in	1st Floor	1,062 SI	SF 6	10+ years	
Doors - Steel Doors incl hw	1st Floor	1 E/	:A 7	' 10+ years	
Floor - Tile	1st Floor	1,062 SI	SF 6	10+ years	
Lighting - Lay-in	1st Floor	20 E/	Α 6		
Marker Board	1st Floor	8 LI	.F 7	6-10 years	
Storage/ Closet	1st Floor	123 SI	SF 7	' 10+ years	
Walls - Concrete Block	1st Floor	900 SI		10+ years	
Walls - Plaster/Drywall	1st Floor	300 SI	SF 6	10+ years	
Classroom #148 (Computer Lab)					
Ceiling - Lay-in	1st Floor	1,008 SI	SF 6	10+ years	
Doors - Steel Doors incl hw	1st Floor	, 2 E		' 10+ years	
Floor - Tile	1st Floor	1,008 SI	SF 6	10+ years	
Lighting - Lay-in	1st Floor	13 E/	Α 6	6-10 years	
Marker Board	1st Floor	16 LF	.F 7	6-10 years	
Storage/ Closet	1st Floor	336 SI	SF 7	10+ years	
Walls - Concrete Block	1st Floor	988 SI	SF 7	10+ years	
Walls - Plaster/Drywall	1st Floor	120 SI	SF 6	10+ years	
Wireless System	1st Floor	1 E	EA 7	6-10 years	

Building: Linked Addition-Fine Arts & Tech Building Category: Interior

aicgo	ry . Interior			ananig	. Liiikee		Arts & rech building
3roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
orridor							
	Ceiling - Lay-in	135 - Band & Choir Room Foyer	490	SF	7	10+ years	
	Doors - Steel Doors incl hw	135 - Band & Choir Room Foyer	2	EA	7	10+ years	
	Floor - Tile/Sheet	135 - Band & Choir Room Foyer	490	SF	7	10+ years	
	Lighting - Lay-in	135 - Band & Choir Room Foyer	6	EA	6	6-10 years	
	Walls - Concrete Block	135 - Band & Choir Room Foyer	759	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st FIr - Main Entry Lobby	1,711	SF	6	10+ years	
	Doors - Store Front	1st FIr - Main Entry Lobby	7	EA	7	10+ years	
	Floor - Terrazzo	1st FIr - Main Entry Lobby	1,711	SF	6	10+ years	
	Lighting - Lay-in	1st Flr - Main Entry Lobby	28	EΑ	6	6-10 years	
	Walls - Masonry	1st Flr - Main Entry Lobby	417	SF	7	10+ years	
	Ceiling - Lay-in	1st Flr - North Corridor	995	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Flr - North Corridor	2	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Flr - North Corridor	2	EA	7	10+ years	
	Floor - Terrazzo	1st Flr - North Corridor	995	SF	7	10+ years	
	Lighting - Lay-in	1st Flr - North Corridor	9	EA	6	6-10 years	
	Student Lockers - One Tier	1st Flr - North Corridor	44	EA	7	10+ years	



Catego	ry : Interior		В	uilding	: Linked	l Addition-Fine	Arts & Tech Building
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Flr - North Corridor	1,436	SF	7	10+ years	
	Ceiling - Lay-in	1st Flr - South Corridor	938	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Flr - South Corridor	4	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Flr - South Corridor	2	EA	7	10+ years	
	Floor - Terrazzo	1st Flr - South Corridor	938	SF	6	10+ years	
	Lighting - Lay-in	1st Flr - South Corridor	9	EA	6	6-10 years	
	Student Lockers - One Tier	1st Flr - South Corridor	47	EA	7	10+ years	
	Walls - Concrete Block	1st Flr - South Corridor	1,527	SF	7	10+ years	
	Ceiling - Lay-in	1st Flr - West Corridor	1,725	SF	6	10+ years	
	Doors - Side-lite	1st Flr - West Corridor	44	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Flr - West Corridor	4	EA	7	10+ years	
	Floor - Terrazzo	1st Flr - West Corridor	1,725	SF	6	10+ years	
	Lighting - Lay-in	1st Flr - West Corridor	17	EA	6	6-10 years	
	Walls - Concrete Block	1st Flr - West Corridor	3,219	SF	7	10+ years	
Safety							
· •	Metal Dedector	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	12	EA	7	6-10 years	
	Security Cameras	1st Floor	4	EA	7	6-10 years	

Campus Name: Collins HS Page : 47 of 68 Assessment Date: 06/22/2022



Category: Exterior Building: Linked Addition-Physical Education Building

	y : Exterior			unung	. LIIIKEU		sical Education Building
rous	Itom Type	Location	Quantity	UOM	Rank	Recommend	Comments
oup	Item - Type	Location	Quantity	UUW	Kank	Replacement	Confinents
trance							
	Exterior Doors - Exterior FRP Door	10	2	EA	6	10+ years	
	Exterior Doors - Side lite	10	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	10	1	EA	6	10+ years	
	Exterior Stairs - Concrete	10	50	LF	6	10+ years	
	Exterior Stairs - Concrete	10	10	LF	5	0-1 year	Broken concrete
	Stair Handrail - Steel_Stair Handrail	10	18	LF	5	10+ years	
	Exterior Doors - Exterior FRP Door	11	2	EA	6	10+ years	
	Exterior Doors - Side lite	11	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	11	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	12	2	EA	6	10+ years	
	Exterior Doors - Side lite	12	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	12	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	12.5	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	13	14	EA	6	10+ years	
	Exterior Doors - Transom Lite	13	7	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	14	6	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	14	6	EA	6	10+ years	
	Exterior Doors - Side lite	14	12	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	14	3	EΑ	6	10+ years	
	Exterior Doors - Exterior FRP Door	15	2	EA	6	10+ years	
	Exterior Doors - Side lite	15	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	15	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	9	2	EΑ	6	10+ years	
	Exterior Doors - Side lite	9	4	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	9	1	EA	6	10+ years	
undatio	on Foundation - Concrete	Entire Building	1,018	LF	7	10+ years	
	Foundation - Concrete	Entire Building Entire Building	1,018	LF LF	, 5	0-1 years	Seepage in boiler room
				SF	5 7		Seepage III boller room
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	66,155	ЭF	1	10+ years	
	, opping						
hting							
	Exterior Lighting - Wall Mounted	Entire Building	19	EA	7	6-10 years	New LED fixtures
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	1-2 years	Old, obsolete fixture
of Sys	tem						
	Access Ladder - Metal	A	1	EA	7	10+ years	
	Coping - Metal	A	636	LF	6	10+ years	
	Downspouts - Interior Downspouts	A	90	LF	6	10+ years	
	DOMISDOUIS - IIIGHOLDOWNSOONS						

Campus Name: Collins HS Page : 48 of 68 Assessment Date: 06/22/2022



atego	ry : Exterior		Building : Linked Addition-Physical Education Building						
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Parapet - Parapet > 30"	Α	336	LF	6	10+ years			
	Roof - Modified Bitumen	Α	20,957	SF	6	10+ years			
	Roof - Modified Bitumen	А	50	SF	4	0-1 year	Roof is leaking at equipment curbs. Damage to wood gym floor below. Occurs at large gym and small gym. Open seems that curb		
	Roof - Modified Bitumen	Α	10	SF	4	0-1 year	Blistering. Open seems		
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Α	21,017	SF	7	10+ years			
	Coping - Metal	В	40	LF	6	10+ years			
	Parapet - Parapet < 16" Height	В	40	LF	6	10+ years			
	Roof - Modified Bitumen	B	400	SF	6	10+ years			
	Roof Structure - Steel / Metal Deck/	В	400	SF	7	10+ years			
	Concrete Topping	_	100	٥.	•	,			
	Coping - Metal	С	290	LF	6	10+ years			
	Downspouts - Interior Downspouts	Č	165	LF	6	10+ years			
	Parapet - Parapet < 16" Height	C	125	LF	6	10+ years			
	Parapet - Parapet > 30"	C	150	LF	6	10+ years			
	Parapet - Parapet > 30"	Č	15	LF	5	10+ years	Deteriorated mortar at wall flashing		
	Roof - Modified Bitumen	Č	23,328	SF	6	6-10 years	Repaired		
	Roof - Modified Bitumen	Č	6	SF	5	1-2 years	Blistering		
	Roof Hatch - Metal	Č	1	EA	7	10+ years	Blistering		
	Roof Structure - Steel / Metal Deck/	C	23,334	SF	7	10+ years			
	Concrete Topping	O	20,004	Oi.	'	10+ years			
	Coping - Metal	D	96	LF	6	10+ years			
	Downspouts - Interior Downspouts	D	30	LF	6	10+ years			
	Parapet - Parapet < 16" Height	D	96	LF	6	10+ years			
	Roof - Modified Bitumen	D	768	SF	6	6-10 years	Repaired		
	Roof Structure - Steel / Metal Deck/	D	768 768	SF	7	•	Repaired		
	Concrete Topping					10+ years			
	Access Ladder - Metal	E	1	EA	7	10+ years			
	Chimney - Metal Flue	E	10	LF	6	10+ years			
	Coping - Metal	Ē	422	LF	6	10+ years			
	Downspouts - Interior Downspouts	E	90	LF · –	6	10+ years			
	Parapet - 16" - 30" Height	E	211	LF	6	10+ years			
	Parapet - Parapet < 16" Height	E	211	LF	6	10+ years			
	Roof - Modified Bitumen	E	10,315	SF	6	10+ years	Roof is in good shape		
	Roof - Modified Bitumen	Е	3	SF	4	1-2 years	Open seams, Generally at equipment curbs		
	Roof Structure - Steel / Metal Deck/ Concrete Topping	E	10,318	SF	7	10+ years			
Valls	Canopy - Concrete/ Stucco	Entire Building	480	SF	6	10+ years			



Collins Academy High School 1313 S Sacramento DRIVE, Chicago, IL 60623 Physical Education Building

Catego	ry : Exterior		В	uilding	: Linked	I Addition-Phy	sical Education Building
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Brick	Entire Building	22,458	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	3,000	SF	5	10+ years	Deteriorated mortar
	Exterior Walls - Brick	Entire Building	80	SF	4	0-1 year	Large crack near entry door 12, off of
	Exterior Walls - Brick	Entire Building	10	SF	3	0-1 year	roof C Cracked, displaced brick near stairs to roof E
Windows							
_ vviiidow.	Clerestory - Glass Double-Pane	Entire Building	120	SF	4	0-1 year	Corroded windows
	Guard - Guards perforated	Entire Building	1,120	SF	6	10+ years	
	Lintels - Steel	Entire Building	96	LF	5	0-1 year	Badly corroded.
	Storefront Windows	Entire Building	520	SF	6	10+ years	Dadiy concaca.
Catono	ry : Electrical		B	uildina	·linkor	l Addition-Phy	sical Education Building
Catego	ry . Liectricai			unung	. Liliket	Recommend	Sical Education Building
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	ncy System		,				
morgo	Automatic Transfer Switch	Electrical Room	2	EA	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	2,488	SF	7	10+ years	
	Stairs	Ziiliio Zallallig	2,100	O.	•	.o. youro	
	Emergency A/C Power - Gym	Entire Building	11,943	SF	7	10+ years	
	Emergency A/C Power - Gym	Entire Building	11,943	SF	7	10+ years	
	Emergency A/C Power - Pool	Entire Building	10,063	SF	7	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	452	SF	7	10+ years	
	Exit Signs - Corridors and Stairs	Entire Building	11	EA	6	2-5 years	Bulb needs replacement
	Exit Signs - Gym	Entire Building	4	EΑ	6	2-5 years	Bulb needs replacement
	Exit Signs - Gym	Entire Building	4	EA	6	2-5 years	Bulb needs replacement
	Exit Signs - Gym	Entire Building	1	EA	6	2-5 years	Bulb needs replacement
	Exit Signs - Multipurpose Room	Entire Building	1	EA	6	2-5 years	Bulb needs replacement
	Exit Signs - Pool	Entire Building	5	EΑ	6	2-5 years	Bulb needs replacement
	Emergency Battery Packs - Multipurpose	Entire Building	3	EA	6	2-5 years	Build riceus replacement
	Room	Entire Duilding	27.002	C.E.	7	C 10	
	Security System - CCTV Security System - Intrusion Detection	Entire Building Entire Building	37,803 37,803	SF SF	7 6	6-10 years 6-10 years	
	decurity dysterii - intrusion betection	Little building	37,003	Oi.	O	0-10 years	
Main Se							
	Independent Electrical Service for	Basement	2	EA	6	10+ years	New item added per current observation
							ODGOI VALIOTI
	emergency power Main Electrical Service - 1200 A	Electrical Room	1	EA	4	1-2 years	Rusty, corroded and deteriorated
	emergency power	Electrical Room Entire Building	1 37,803	EA SF	4 6	1-2 years 6-10 years	



Collins Academy High School

can handle extra strobe lights

1313 S Sacramento DRIVE, Chicago, IL 60623

Category : Electrical Building : Linked Addition-Physical Education Building					sical Education Building		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	5	EA	7	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Live. New item added per current observation
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EΑ	7	6-10 years	
	Transformers - 277/480 - 120/208	Entire Building	2	EA	6	6-10 years	

Category : Fire Protection

Building: Linked Addition-Physical Education Building Recommend Item - Type Group Location Quantity UOM Rank Replacement Comments Fire Alarm Fire Alarm_System **Entire Building** 37,803 SF 6-10 years Served from main building System 6

Building: Linked Addition-Physical Education Building Category : Mechanical

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Hand	ling Systems						
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-16 Pool roof
	Gas Heating and DX Cooling w/ Self						
	Contained Compressor - 21 - 30 tons						
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-19
	Gas Heating and DX Cooling w/ Self						
	Contained Compressor - 21 - 30 tons				_		
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-17 Repaired.
	Gas Heating and DX Cooling w/ Self						
	Contained Compressor - 21 - 30 tons	Deat	4	_^	0	0.40	DTH 00 High as of Westings as
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self	Roof	1	EA	6	6-10 years	RTU-20 High roof Working per current observation
	Contained Compressor - 21 - 30 tons						current observation
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-18 High roof
	Gas Heating and DX Cooling w/ Self	Roof		LA	U	0-10 years	10-10 High 1001
	Contained Compressor - 21 - 30 tons						
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	2	0-1 year	RTU-14 Not Working per current
	Gas Heating and DX Cooling Coil - 21 - 30					, , , , ,	observation Lower roof
	tons						
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	2	0-1 year	RTU-15 Lower roof Not working per
	Gas Heating and DX Cooling Coil - 21 - 30						current observation
	tons						
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-13 Working per current
	Gas Heating and DX Cooling Coil - Greater						observation Lower roof
	than 45 tons						

Campus Name: Collins HS Page : 51 of 68 Assessment Date: 06/22/2022



Catego	ry : Mechanical		В	uilding	: Linked		sical Education Building
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	VAV Box	Roof - Zone Dampers	Quantity 4	EA	3	0-1 year	Serves gym and rooms. Not working
			·		-	-	per building engineer
	Zone Dampers	Roof - Zone Dampers	8	EA	6	6-10 years	
Boiler Sy	vetame						
Doller O	Combustion Dampers	Basement	2	EA	6	10+ years	
	·					•	
Heating							
	Cabinet Heaters - With Electric Coil	Entire Building	3	EA	6	6-10 years	
Tempera	ature Control						
	Thermostats - DDC	Entire Building	17	EA	4	1-2 years	Not working with system Manually
		S				,	control Per building engineer
\/a=tilati							
Ventilation	Exhaust Fans- Roof Mounted - 1501 - 8000	Roof	2	EA	6	6-10 years	
	CFM	11001	_	_/\	Ū	o ro youro	
	Exhaust Fans- Roof Mounted - 500 - 1500	Roof	3	EA	6	6-10 years	Quantity change per current
	CFM Exhaust Fans- Roof Mounted - Less than	Roof	1	EA	6	6-10 years	observation New item added per current
	500 CFM	Rooi	'	LA	O	0-10 years	observation
_			_				
Catego	ry : Plumbing		В	uilding	: Linked	I Addition-Phy Recommend	sical Education Building
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat		20041011	Quantity	OO.III	rturik	rtopiacomont	Comments
	Gas Heater - Greater than 600000 BTU/HR	Basement	2	EA	6	6-10 years	
	Hot Water Storage Tank_Gas - 201 - 500	Basement	1	EA	6	10+ years	
	Gallons						
Piping							
тріпд	Domestic Piping-Hot Water Return Lines	Entire Building	66,155	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	66,155	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	66,155	SF	6	10+ years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	66,155	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	66,155	SF	6	10+ years	
	(Risers)	-	,			•	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	66,155	SF	6	10+ years	
	ITTOM RICARS TO FIVEIITAS)						
	(from Risers to Fixtures) Sanitary Piping	Entire Building	66,155	SF	7	10+ years	





Catego	ry : Plumbing	g Building : Linked Addition-Physical Education Building					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storm Piping	Entire Building	66,155	SF	7	10+ years	
	Vent Piping	Entire Building	66,155	SF	7	6-10 years	
Pool Sys	stems						
•	Pool Drain Piping	Basement	100	LF	7	10+ years	
	Pool Filtration System including Pump	Basement	1	EΑ	6	6-10 years	
	Pool Hot Water Heater - Gas Fired	Basement	1	EA	4	0-1 year	Corroded and deteriorated not working per current observation
	Pool Supply and Return Piping	Basement	270	LF	7	10+ years	31
Pumps							
	Pumps - Ejector-Duplex	Basement	1	EΑ	6	2-5 years	
	Pumps - Sump-Duplex	Basement	1	EA	6	2-5 years	

Category: Room **Building: Linked Addition-Physical Education Building**

				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Lay-in	181-Pool office	139	SF	6	10+ years	
	Ceiling - Lay-in	181-Pool office	24	SF	4	0-1 year	Missing tiles
	Doors - Side-lite	181-Pool office	7	SF	6	10+ years	
	Doors - Steel Doors incl hw	181-Pool office	1	EA	6	10+ years	
	Floor - Tile	181-Pool office	163	SF	6	10+ years	
	Lighting - Lay-in	181-Pool office	2	EA	6	6-10 years	
	Walls - Concrete Block	181-Pool office	461	SF	6	10+ years	
	Ceiling - Lay-in	182-Pool office	163	SF	6	10+ years	
	Doors - Side-lite	182-Pool office	7	SF	6	10+ years	
	Doors - Steel Doors incl hw	182-Pool office	1	EA	6	10+ years	
	Floor - Tile	182-Pool office	163	SF	6	10+ years	
	Lighting - Lay-in	182-Pool office	2	EA	6	6-10 years	
	Walls - Concrete Block	182-Pool office	461	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Flr - Office at far north corr.	240	SF	6	10+ years	Ceiling peeling.
		across from weight room					
	Doors - Steel Doors incl hw	1st Flr - Office at far north corr.	1	EA	6	10+ years	
		across from weight room					
	Floor - Carpet	1st Flr - Office at far north corr.	240	SF	6	6-10 years	
		across from weight room					
	Lighting - Pendent/Surface	1st Flr - Office at far north corr.	2	EA	6	6-10 years	
		across from weight room			_		
	Power Distribution	1st Flr - Office at far north corr.	4	EA	7	10+ years	
		across from weight room					
	Walls - Concrete Block	1st FIr - Office at far north corr.	480	SF	6	10+ years	
		across from weight room					

Campus Name: Collins HS Page : 53 of 68 Assessment Date: 06/22/2022



Catego	ry : Room	В	uilding	: Linked	Addition-Phy	sical Education Building	
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Flr Locker Room Staff Office (in boy's locker room)	281	SF	6	10+ years	Unable to access due to private padlock
	Doors - Steel Doors incl hw	1st Flr Locker Room Staff Office (in boy's locker room)	1	EA	6	10+ years	Unable to access due to private padlock
	Floor - Tile	1st Flr Locker Room Staff Office (in boy's locker room)	281	SF	6	10+ years	Unable to access due to private padlock
	Lighting - Pendent/Surface	1st Flr Locker Room Staff Office (in boy's locker room)	8	EA	6	6-10 years	Unable to access due to private padlock
	Power Distribution	1st Flr Locker Room Staff Office (in boy's locker room)	10	EA	6	10+ years	Unable to access due to private padlock
	Walls - Concrete Block	1st Flr Locker Room Staff Office (in boy's locker room)	600	SF	6	10+ years	Unable to access due to private padlock
	Ceiling - Plaster/Drywall	1st flr-gym office-large gymnasium (gym storage on plan)	230	SF	6	10+ years	padiock
	Doors - Steel Doors incl hw	1st flr-gym office-large gymnasium (gym storage on plan)	2	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st flr-gym office-large gymnasium (gym storage on plan)	230	SF	7	10+ years	
	Lighting - Pendent/Surface	1st flr-gym office-large gymnasium (gym storage on plan)	3	EA	6	6-10 years	
	Power Distribution	1st flr-gym office-large gymnasium	2	EA	6	10+ years	
	Walls - Concrete Block	(gym storage on plan) 1st flr-gym office-large gymnasium	564	SF	6	10+ years	
	Ceiling - Lay-in	(gym storage on plan) 64M Office @ Small Gym ('Park	146	SF	6	10+ years	
	Ceiling - Lay-in	District Office' on plan) 64M Office @ Small Gym ('Park	4	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	District Office' on plan) 64M Office @ Small Gym ('Park	1	EA	6	10+ years	
	Floor - Tile	District Office' on plan) 64M Office @ Small Gym ('Park	150	SF	6	10+ years	
	Lighting - Lay-in	District Office' on plan) 64M Office @ Small Gym ('Park District Office' on plan)	4	EA	6	6-10 years	
	Power Distribution	64M Office @ Small Gym ('Park District Office' on plan)	6	EA	6	10+ years	
	Walls - Concrete Block	64M Office @ Small Gym ('Park District Office' on plan)	350	SF	6	10+ years	
	Ceiling - Lay-in	BOE Office @ small gym	150	SF	6	10+ years	
	Doors - Wood Doors inclu hw	BOE Office @ small gym	1	EA	6	10+ years	
	Floor - Tile	BOE Office @ small gym	150	SF	6	10+ years	
	Lighting - Lay-in	BOE Office @ small gym	3	EA	6	6-10 years	
	Lighting - Lay-in	BOE Office @ small gym	1	EA	5	0-10 years 0-1 year	Missing cover
	Power Distribution	BOE Office @ small gym	4	EA	7	10+ years	iviissii ig covei
	I OME! DISHIDUHUH	BOE Office & Striati gym	4	EA	,	10+ years	

Campus Name: Collins HS Page : 54 of 68 Assessment Date: 06/22/2022





Catego	ry : Room	Building : Linked Addition-Physical Education Building					
Jaiogo	.,			- II willing		Recommend	c.ca. Ladoution Banding
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	BOE Office @ small gym	350	SF	7	10+ years	
	Ceiling - Lay-in	Gym Office In Girls Locker	250	SF	6	10+ years	
	Ceiling - Lay-in	Gym Office In Girls Locker	10	SF	4	0-1 year	Cracking and missing tiles
	Doors - Steel Doors incl hw	Gym Office In Girls Locker	1	ĒΑ	6	10+ years	craceing and incoming made
	Floor - Tile	Gym Office In Girls Locker	260	SF	6	10+ years	
	Lighting - Pendent/Surface	Gym Office In Girls Locker	7	EA	7	6-10 years	Updated to match current
	Lighting Tondon Canado	Cym Cinco in Cinc Eddici	,		•	o ro youro	observations
	Power Distribution	Gym Office In Girls Locker	4	EA	7	10+ years	0.000.1400
	Walls - Concrete Block	Gym Office In Girls Locker	594	SF	7	10+ years	
Gvmnas	ia						
	Bleacher Seating	1st Floor Auxiliary Gym (Small)	280	EA	6	10+ years	
	Ceiling - Exposed	1st Floor Auxiliary Gym (Small)	8,265	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor Auxiliary Gym (Small)	2	EA	6	10+ years	
	Floor - Wood	1st Floor Auxiliary Gym (Small)	8,265	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure	1st Floor Auxiliary Gym (Small)	12	EA	6	6-10 years	
	Sodium	13t 1 1001 Adamaty Cyffi (Offidil)	12	L/\	O	o io youis	
	Scoreboards	1st Floor Auxiliary Gym (Small)	1	EA	7	6-10 years	
	Sound System	1st Floor Auxiliary Gym (Small)	1	EΑ	7	6-10 years	
	Storage/ Closet	1st Floor Auxiliary Gym (Small)	150	SF	7	10+ years	
	Storage/ Closet	1st Floor Auxiliary Gym (Small)	150	SF	7	10+ years	
	Walls - Concrete Block	1st Floor Auxiliary Gym (Small)	7,660	SF	6	10+ years	
	Bleacher Seating	1st Flr - Large Gymnasium	1,260	EA	7	10+ years	
	Ceiling - Exposed	1st Flr - Large Gymnasium	12,093	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Fir - Large Gymnasium	12,093	EA	7	10+ years	
	Doors - Steel Doors incl hw		1	EA	6	•	
		1st Flr - Large Gymnasium	=	SF		10+ years	
	Floor - Wood	1st Flr - Large Gymnasium	12,093		6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Flr - Large Gymnasium	16	EΑ	6	6-10 years	
	Scoreboards	1st Flr - Large Gymnasium	1	EΑ	7	6-10 years	
	Sound System	1st Flr - Large Gymnasium	1	EA	7	6-10 years	
	Storage/ Closet	1st Flr - Large Gymnasium	150	SF	7	10+ years	
	Walls - Concrete Block	1st Flr - Large Gymnasium	11,800	SF	6	10+ years	
Locker/S	Shower Room						
	Accessories	1st Floor Women Staff Locker	147	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Women Staff Locker	147	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor Women Staff Locker	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Women Staff Locker	147	SF	6	10+ years	
	Floor Drain	1st Floor Women Staff Locker	3	ĒΑ	7	10+ years	
	Lavatory	1st Floor Women Staff Locker	1	EA	6	10+ years	
	Lighting - Lay-in	1st Floor Women Staff Locker	4	EA	7	6-10 years	Updated to match current
	5 · · · · · · · · · · · · · · · · · · ·		·		•	2 . 2 , 00.0	observations
	Partitions	1st Floor Women Staff Locker	1	EA	7	6-10 years	Updated to match current

Campus Name: Collins HS Page : 55 of 68 Assessment Date: 06/22/2022



wy.	ry : Room	Building : Linked Addition-Physical Education Building						
_				_		Recommend		
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Showers	1st Floor Women Staff Locker	2	EΑ	5	0-1 year	Not in use	
	Student Lockers - One Tier	1st Floor Women Staff Locker	5	EA	6	6-10 years		
	Walls - Concrete Block	1st Floor Women Staff Locker	328	SF	7	10+ years		
	Water Closet	1st Floor Women Staff Locker	1	EA	6	10+ years		
	Accessories	1st Flr Men's Staff Locker Rm - In	147	SF	7	6-10 years	Inside padlocked area, no access	
		Boys' Locker Rm.						
	Ceiling - Plaster/Drywall	1st Flr Men's Staff Locker Rm - In	147	SF	6	10+ years	Inside padlocked area, no access	
		Boys' Locker Rm.						
	Doors - Steel Doors incl hw	1st Flr Men's Staff Locker Rm - In	1	EA	6	10+ years	Inside padlocked area, no access	
		Boys' Locker Rm.						
	Floor - Tile Ceramic/ Porcelain	1st Flr Men's Staff Locker Rm - In	147	SF	6	10+ years	Inside padlocked area, no access	
		Boys' Locker Rm.						
	Floor Drain	1st Flr Men's Staff Locker Rm - In	3	EA	7	10+ years	Inside padlocked area, no access	
		Boys' Locker Rm.						
	Lavatory	1st Flr Men's Staff Locker Rm - In	1	EA	6	10+ years	Inside padlocked area, no access	
		Boys' Locker Rm.						
	Lighting - Lay-in	1st Flr Men's Staff Locker Rm - In	2	EA	6	6-10 years	Inside padlocked area, no access	
		Boys' Locker Rm.						
	Partitions	1st Flr Men's Staff Locker Rm - In	1	EA	7	10+ years	Inside padlocked area, no access	
		Boys' Locker Rm.						
	Showers	1st Flr Men's Staff Locker Rm - In	2	EA	5	10+ years	Inside padlocked area, no access	
		Boys' Locker Rm.						
	Student Lockers - One Tier	1st Flr Men's Staff Locker Rm - In	5	EA	6	10+ years	Inside padlocked area, no access	
		Boys' Locker Rm.						
	Walls - Tile Ceramic/ Porcelain	1st Flr Men's Staff Locker Rm - In	428	SF	6	10+ years	Inside padlocked area, no access	
		Boys' Locker Rm.						
	Water Closet	1st Flr Men's Staff Locker Rm - In	1	EA	6	10+ years	Inside padlocked area, no access	
		Boys' Locker Rm.						
	Accessories	Boys Locker Room	3,528	SF	7	6-10 years		
	Benches, ped mounted	Boys Locker Room	45	LF	6	10+ years		
	Ceiling - Plaster/Drywall	Boys Locker Room	3,528	SF	6	10+ years		
	Doors - Steel Doors incl hw	Boys Locker Room	3	EA	7	10+ years		
	Floor - Epoxy/ Painted	Boys Locker Room	2,627	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Boys Locker Room	901	SF	6	10+ years		
	Floor Drain	Boys Locker Room	10	EA	7	10+ years		
	Hand Dryer	Boys Locker Room	7	EA	7	6-10 years		
	Lavatory	Boys Locker Room	3	EA	6	10+ years		
	Lighting - Lay-in	Boys Locker Room	38	EA	6	6-10 years		
	Partitions	Boys Locker Room	1	EA	7	10+ years		
	Showers	Boys Locker Room	19	EA	7	10+ years		
	Student Lockers - One Tier	Boys Locker Room	43	EΑ	6	10+ years	Updated to match current	
			.0		ū	121 ,00.0	observations	
	Urinals	Boys Locker Room	2	EA	7	10+ years		
		Boys Locker Room	1,640	SF	6	10+ years		

Campus Name: Collins HS Page : 56 of 68 Assessment Date: 06/22/2022



Catego	ry : Room		В	uilding	: Linked	d Addition-Phy	sical Education Building
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Tile Ceramic/ Porcelain	Boys Locker Room	1,430	SF	6	10+ years	
	Water Closet	Boys Locker Room	1	EA	7	10+ years	
	Accessories	Girls Locker Room	3,528	SF	7	6-10 years	
	Benches, ped mounted	Girls Locker Room	65	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Girls Locker Room	3,528	SF	6	10+ years	
	Doors - Steel Doors incl hw	Girls Locker Room	2	EA	6	10+ years	
	Floor - Epoxy/ Painted	Girls Locker Room	2,627	SF	7	2-5 years	
	Floor - Tile Ceramic/ Porcelain	Girls Locker Room	901	SF	6	10+ years	
	Floor Drain	Girls Locker Room	10	EΑ	7	10+ years	
	Hand Dryer	Girls Locker Room	8	EA	7	10+ years	
	Lavatory	Girls Locker Room	2	EA	7	10+ years	
	Lighting - Lay-in	Girls Locker Room	49	EA	6	6-10 years	
	Partitions	Girls Locker Room	3	EA	7	10+ years	
	Showers	Girls Locker Room	18	EA	7	10+ years	
	Student Lockers - One Tier	Girls Locker Room	40	EA	7	10+ years	
	Student Lockers - Two Tier	Girls Locker Room	110	EA	7	10+ years	
	Walls - Concrete Block	Girls Locker Room	3,070	SF	7	10+ years	
	Water Closet	Girls Locker Room	3	EA	7	10+ years	
	Accessories	Visiting Boys Locker Room	663	SF	7	6-10 years	Inside padlocked area, no access
	Ceiling - Lay-in	Visiting Boys Locker Room	330	SF	6	10+ years	Inside padlocked area, no access
	Ceiling - Plaster/Drywall	Visiting Boys Locker Room	333	SF	6	10+ years	Inside padlocked area, no access
	Doors - Steel Doors incl hw	Visiting Boys Locker Room	2	EA	6	6-10 years	Inside padlocked area, no access
	Floor - Epoxy/ Painted	Visiting Boys Locker Room	333	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Visiting Boys Locker Room	330	SF	6	10+ years	Inside padlocked area, no access
	Floor Drain	Visiting Boys Locker Room	5	EA	7	10+ years	
	Lavatory	Visiting Boys Locker Room	1	EA	5	10+ years	
	Lighting - Lay-in	Visiting Boys Locker Room	7	EA	6	6-10 years	
	Lighting - Pendent/Surface	Visiting Boys Locker Room	6	EA	5	2-5 years	
	Partitions	Visiting Boys Locker Room	1	EA	7	6-10 years	
	Showers	Visiting Boys Locker Room	5	EΑ	7	6-10 years	
	Student Lockers - One Tier	Visiting Boys Locker Room	58	EA	6	6-10 years	
	Urinals	Visiting Boys Locker Room	1	EΑ	7	10+ years	
	Walls - Concrete Block	Visiting Boys Locker Room	504	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Visiting Boys Locker Room	504	SF	6	10+ years	
	Water Closet	Visiting Boys Locker Room	1	EA	7	10+ years	
	Accessories	Visiting Girls Locker Room	663	SF	7	6-10 years	
	Ceiling - Lay-in	Visiting Girls Locker Room	331	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Visiting Girls Locker Room	332	SF	6	10+ years	
	Doors - Steel Doors incl hw	Visiting Girls Locker Room	1	EA	6	10+ years	
	Floor - Epoxy/ Painted	Visiting Girls Locker Room	331	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Visiting Girls Locker Room	332	SF	6	10+ years	
	Floor Drain	Visiting Girls Locker Room	4	EA	7	10+ years	
	Lavatory	Visiting Girls Locker Room	1	EA	6	10+ years	
	Lighting - Lay-in	Visiting Girls Locker Room	5	EA	6	6-10 years	
	· · · · · · · · · · · · · · · · · · ·	C				•	

Campus Name: Collins HS Page : 57 of 68 Assessment Date: 06/22/2022



	ry : Room		Ві	uilding	Linked	Addition-Phy	sical Education Building
				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Visiting Girls Locker Room	4	EA	6	6-10 years	
	Partitions	Visiting Girls Locker Room	1	EA	4	0-1 year	Dented, not able to fully close.
	Showers	Visiting Girls Locker Room	5	EA	7	10+ years	
	Student Lockers - One Tier	Visiting Girls Locker Room	61	EA	6	10+ years	
	Urinals	Visiting Girls Locker Room	1	EA	6	10+ years	
	Walls - Concrete Block	Visiting Girls Locker Room	1,008	SF	6	10+ years	
	Water Closet	Visiting Girls Locker Room	['] 1	EA	6	10+ years	
unch &	Multipurpose Room						
	Ceiling - Lay-in	1st Flr - Large Gymnasium- Canteen	125	SF	6	10+ years	
	55g _5,	Room			-	, , , , , , , , , , , , , , , , , , , ,	
	Doors - Steel Doors incl hw	1st Flr - Large Gymnasium- Canteen	2	EA	6	10+ years	
	Boold Gloof Boold Mortin	Room	_	_, `	Ŭ	ioi youro	
	Floor - Tile	1st Flr - Large Gymnasium- Canteen	125	SF	6	10+ years	
	11001 1110	Room	120	Oi.	O	101 years	
	Lighting - Lay-in	1st Flr - Large Gymnasium- Canteen	7	EA	6	6-10 years	
	Lighting - Lay-in	Room	,	LA	U	0-10 years	
	Lighting - Lay-in	1st Flr - Large Gymnasium- Canteen	1	EA	5	0-1 year	Missing cover
	Lighting - Lay-in	Room	Į	LA	3	0-1 year	wissing cover
	Storage / Claset		100	SF	7	10	
	Storage/ Closet	1st Flr - Large Gymnasium- Canteen Room	100	SF	7	10+ years	
	Walla Canarata Black		225	SF	e	10	
	Walls - Concrete Block	1st Flr - Large Gymnasium- Canteen Room	225	SF	6	10+ years	
lechan	ical/ Service Rooms						
ICCHAIL	Janitor's Closet	1st Floor Support Spaces	30	SF	7	10+ years	
			30				
		1ct Floor Support Spaces	30	GE.		10 L VOORC	
	Janitor's Closet	1st Floor Support Spaces	30 35	SF	7	10+ years	Undated to match current
	Janitor's Closet Mechanical/ Service Rooms	1st Floor Support Spaces 1st Floor Support Spaces	30 35	SF SF	7	10+ years 10+ years	Updated to match current
	Mechanical/ Service Rooms	1st Floor Support Spaces	35	SF	7	10+ years	Updated to match current observations
	Mechanical/ Service Rooms Mechanical/ Service Rooms	1st Floor Support Spaces 1st Floor Support Spaces	35 31	SF SF	7 7	10+ years 10+ years	•
	Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms	1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces	35 31 30	SF SF SF	7 7 7	10+ years 10+ years 10+ years	•
	Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms	1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces	35 31 30 175	SF SF SF	7 7 7 7	10+ years 10+ years 10+ years 10+ years	•
	Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room	1st Floor Support Spaces	35 31 30 175 100	SF SF SF SF	7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years	•
	Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room	1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces	35 31 30 175 100 350	SF SF SF SF SF	7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	•
	Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room	1st Floor Support Spaces	35 31 30 175 100	SF SF SF SF	7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years	•
1 & loo	Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Storage Room Storage Room	1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces	35 31 30 175 100 350 200	SF SF SF SF SF	7 7 7 7 7 7	10+ years	•
1 & loo	Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Storage Room Storage Room Atatorium Accessories	1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces	35 31 30 175 100 350	SF SF SF SF SF	7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	•
1 & loo	Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Storage Room Storage Room Storage Room Blatatorium Accessories Bleachers Seating/Plank Seating	1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces	35 31 30 175 100 350 200	SF SF SF SF SF	7 7 7 7 7 7	10+ years	•
1 & loo	Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Storage Room Storage Room Storage Room Storage Room Celsing - Exposed	1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces	35 31 30 175 100 350 200	SF SF SF SF SF	7 7 7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	•
1. <u>& loo</u> 2	Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Storage Room Storage Room Storage Room Blatatorium Accessories Bleachers Seating/Plank Seating	1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces	35 31 30 175 100 350 200	SF SF SF SF SF SF	7 7 7 7 7 7 7	10+ years	•
<u>1 & Ioo</u>	Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Storage Room Storage Room Storage Room Storage Room Celsing - Exposed	1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces 1st Floor Support Spaces	35 31 30 175 100 350 200 10,063 34 10,063	SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7	10+ years	•

Campus Name: Collins HS Page : 58 of 68 Assessment Date: 06/22/2022





atego	ry : Room	В	sical Education Building				
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Pool Basin	1st Floor	2,136	SF	7	10+ years	
	Pool Deck	1st Floor	6,745	SF	7	10+ years	
	Pool Deck Drains	1st Floor	36	EA	7	10+ years	
	Storage/ Closet	1st Floor	250	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	11,765	SF	7	10+ years	
estroor	n						
esilooi		101 pool office	28	SF	7	6.10 vooro	
	Accessories	181-pool office			7	6-10 years	
	Ceiling - Plaster/Drywall	181-pool office	28	SF	6	10+ years	
	Doors - Steel Doors incl hw	181-pool office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	181-pool office	28	SF	6	10+ years	
	Lavatory	181-pool office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	181-pool office	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	181-pool office	56	SF	6	10+ years	
	Water Closet	181-pool office	1	EA	7	10+ years	
	Accessories	182-pool office	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	182-pool office	40	SF	6	10+ years	
	Doors - Steel Doors incl hw	182-pool office	1	EA	7	10+ years	
				SF	6	•	
	Floor - Tile Ceramic/ Porcelain	182-pool office	40			10+ years	
	Floor Drain	182-pool office	1	EA	7	10+ years	
	Lavatory	182-pool office	1	EA	7	10+ years	
	Lighting - Lay-in	182-pool office	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	182-pool office	75	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	182-pool office	5	SF	5	0-1 year	Cracking tiles
	Water Closet	182-pool office	1	EA	7	10+ years	•
	Accessories	1st Flr - West Corr - Female Toilet Room	226	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Flr - West Corr - Female Toilet Room	226	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Flr - West Corr - Female Toilet Room	226	SF	6	10+ years	
	Floor Drain	1st Flr - West Corr - Female Toilet Room	1	EA	7	10+ years	
	Hand Dryer	1st Flr - West Corr - Female Toilet Room	1	EA	7	6-10 years	
	Lavatory	1st Flr - West Corr - Female Toilet Room	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Flr - West Corr - Female Toilet Room	4	EA	6	6-10 years	
	Partitions	1st Flr - West Corr - Female Toilet Room	5	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Flr - West Corr - Female Toilet Room	480	SF	6	10+ years	
	Water Closet	1st Flr - West Corr - Female Toilet	5	EA	7	10+ years	

Campus Name: Collins HS Page : 59 of 68 Assessment Date: 06/22/2022





Catego	ry : Room	В	uilding	: Linked	Addition-Phy	sical Education Building		
0				11011	D- 1	Recommend	0	
Group	item - Type	Location Room	Quantity	UOM	Rank	Replacement	Comments	
	Accessories	1st Flr - West Corridor - Male Toilet Room	226	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Flr - West Corridor - Male Toilet Room	226	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Flr - West Corridor - Male Toilet Room	226	SF	6	10+ years		
	Floor Drain	1st Flr - West Corridor - Male Toilet Room	1	EA	7	10+ years		
	Hand Dryer	1st Flr - West Corridor - Male Toilet Room	1	EA	7	10+ years		
	Lavatory	1st Flr - West Corridor - Male Toilet Room	3	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Flr - West Corridor - Male Toilet Room	4	EA	6	6-10 years		
	Partitions	1st Flr - West Corridor - Male Toilet Room	2	EA	7	10+ years		
	Urinals	1st Flr - West Corridor - Male Toilet Room	3	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st Flr - West Corridor - Male Toilet Room	480	SF	6	10+ years		
	Water Closet	1st Flr - West Corridor - Male Toilet Room	2	EA	7	10+ years		
	Accessories	1st Flr-Large Gymnasium-Canteen Room	16	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Flr-Large Gymnasium-Canteen Room	16	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st FIr-Large Gymnasium-Canteen Room	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Flr-Large Gymnasium-Canteen Room	16	SF	6	10+ years		
	Lavatory	1st Flr-Large Gymnasium-Canteen Room	1	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Flr-Large Gymnasium-Canteen Room	1	EA	6	6-10 years		
	Walls - Tile Ceramic/ Porcelain	1st Flr-Large Gymnasium-Canteen Room	39	SF	6	10+ years		
	Water Closet	1st Flr-Large Gymnasium-Canteen Room	1	EA	7	10+ years		
	Accessories	1st Flr-Large Gymnasium-FSM Room	16	SF	7	6-10 years		
	Ceiling - Lay-in	1st Flr-Large Gymnasium-FSM Room	16	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st Flr-Large Gymnasium-FSM	1	EA	7	10+ years		





Building: Linked Addition-Physical Education Building Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Room 1st Flr-Large Gymnasium-FSM SF Floor - Tile Ceramic/ Porcelain 6 16 10+ years Room Lavatory 1st Flr-Large Gymnasium-FSM EΑ 7 10+ years Room Lighting - Lay-in 1st Flr-Large Gymnasium-FSM EΑ 6 1 6-10 years Walls - Tile Ceramic/ Porcelain 1st Flr-Large Gymnasium-FSM 39 SF 6 10+ years Room Water Closet 1st Flr-Large Gymnasium-FSM FΑ 7 1 10+ years Room Accessories 64M Office toilet @ Small Gym 16 SF 7 6-10 years ('Park District Office' toilet room on plan) SF Ceiling - Plaster/Drywall 64M Office toilet @ Small Gym 16 6 10+ years ('Park District Office' toilet room on plan) Doors - Wood Doors inclu hw 64M Office toilet @ Small Gym 1 EΑ 7 10+ years ('Park District Office' toilet room on plan) Floor - Tile Ceramic/ Porcelain 64M Office toilet @ Small Gym 16 SF 6 10+ years ('Park District Office' toilet room on Lavatory 64M Office toilet @ Small Gym EΑ 7 10+ years ('Park District Office' toilet room on plan) Lighting - Lay-in 64M Office toilet @ Small Gym EΑ 6 6-10 years 1 ('Park District Office' toilet room on plan) Walls - Tile Ceramic/ Porcelain 64M Office toilet @ Small Gym 39 SF 6 10+ years ('Park District Office' toilet room on plan) Water Closet EΑ 7 64M Office toilet @ Small Gym 10+ years ('Park District Office' toilet room on plan) Accessories toilet in BOE Office SF 7 6-10 years 16 SF Ceiling - Plaster/Drywall toilet in BOE Office 16 6 10+ years Doors - Wood Doors inclu hw 7 toilet in BOE Office 1 EΑ 10+ years SF Floor - Tile Ceramic/ Porcelain toilet in BOE Office 16 6 10+ years EΑ 7 toilet in BOE Office 1 10+ years Lavatory Lighting - Pendent/Surface toilet in BOE Office 1 EΑ 5 0-1 year Does not work. Walls - Tile Ceramic/ Porcelain SF 6 toilet in BOE Office 40 10+ years Water Closet toilet in BOE Office EΑ 7 10+ years



Catego	ry : Classroom		В	uilding	: Linked	Addition-Phy	sical Education Building
_				_		Recommend	_
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroo	m #121 FSM Control (Other Instructional Use)						
	Ceiling - Lay-in	1st Floor	423	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	14	SF	4	0-1 year	Water damage.
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	· ·
	Floor - Wood	1st Floor	437	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	8	EΑ	6	6-10 years	
	Lighting - Lay-in	1st Floor	3	EA	5	0-1 year	Does not work.
	Walls - Concrete Block	1st Floor	573	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	191	SF	6	10+ years	
Classroo	m #122 FSM Studio (Other Instructional Use)						
	Ceiling - Lay-in	1st Floor	752	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	752	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	11	ĒΑ	6	6-10 years	
	Walls - Concrete Block	1st Floor	784	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	235	SF	6	10+ years	
Classroo	m #123 FSM Room (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	868	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	39	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	907	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	44	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,099	SF	6	10+ years	
Classroo	m #124 Exercise (Fitness Room)						
	Ceiling - Lay-in	1st Floor	888	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	29	SF	4	0-1 year	Water damage.
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	6	10+ years	· · · · · · · · · · · · · · · · · · ·
	Floor - Weight/ Fitness Room Floor Matting	1st Floor	917	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,077	SF	6	10+ years	
lassroo	m #Weight Rm-East (Fitness Room)						
	Ceiling - Plaster/Drywall	1st Floor	378	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Concrete	1st Floor	378	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	6	6-10 years	





Catego	ry : Interior		В	uilding	: Linked	Addition-Phy	sical Education Building
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Flr - West Corridor	2,353	SF	6	10+ years	
	Ceiling - Lay-in	1st Flr - West Corridor	8	SF	4	0-1 year	Cracking tiles
	Ceiling - Plaster/Drywall	1st Flr - West Corridor	754	SF	6	10+ years	-
	Doors - Side-lite	1st Flr - West Corridor	180	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Flr - West Corridor	6	EA	6	10+ years	
	Doors - Transom Window	1st Flr - West Corridor	54	SF	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Flr - West Corridor	2	EA	7	10+ years	
	Floor - Terrazzo	1st Flr - West Corridor	3,015	SF	6	10+ years	
	Floor - Terrazzo	1st Flr - West Corridor	100	SF	4	0-1 year	Cracking
	Lighting - Lay-in	1st Flr - West Corridor	27	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Flr - West Corridor	6	EA	6	6-10 years	
	Walls - Concrete Block	1st Flr - West Corridor	2,600	SF	7	10+ years	
	Walls - Concrete Block	1st Flr - West Corridor	10	SF	6	0-1 year	Cracking mortar
	Walls - Masonry	1st Flr - West Corridor	758	SF	7	10+ years	
	Ceiling - Lay-in	1st Flr Corr - South	1,624	SF	6	10+ years	
	Ceiling - Lay-in	1st Flr Corr - South	30	SF	4	1-2 years	Missing/water damage.
	Doors - Steel Doors incl hw	1st Flr Corr - South	2	EA	7	10+ years	
	Floor - Terrazzo	1st Flr Corr - South	1,604	SF	6	10+ years	
	Floor - Terrazzo	1st Flr Corr - South	50	SF	5	0-1 year	Cracking
	Lighting - Lay-in	1st Flr Corr - South	19	EA	6	6-10 years	
	Walls - Concrete Block	1st Flr Corr - South	3,529	SF	6	10+ years	
	Ceiling - Lay-in	1st flr - building connection	696	SF	6	10+ years	
	Ceiling - Lay-in	1st flr - building connection	24	SF	4	1-2 years	Water damage
	Doors - Steel Doors incl hw	1st flr - building connection	12	EA	6	10+ years	
	Floor - Terrazzo	1st flr - building connection	720	SF	6	10+ years	
	Lighting - Lay-in	1st flr - building connection	8	EA	6	6-10 years	
	Walls - Masonry	1st flr - building connection	60	SF	7	10+ years	
	Walls - Plaster/Drywall	1st flr - building connection	60	SF	6	10+ years	
Safety							
•	Security Cameras	1st Floor	21	EA	7	6-10 years	
	Security Cameras	1st Floor	6	EA	7	6-10 years	



Category : Site Building : Site

Catego	ry : Site		В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	10	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	6	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	ΕA	4	0-1 year	Site drain is full of debris, with
	3					, , , , ,	potholes and broken asphalt around
							it. previous assessment mentions that
							it may be sinking, but that is not
							readily apparent
	Civil/ Drainage - Site Manhole	Entire Site	12	EA	6	10+ years	, , , , , ,
						, , , , , ,	
encing							
	Fencing - Guard Rail	Entire Site	183	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	759	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	18	LF	4	0-1 year	Damaged gate hardware
	Fencing - New Standard Ornamental	Entire Site	18	LF	4	0-1 year	Bent posts and fence
	Fencing - New Standard Ornamental	Entire Site	24	LF	4	0-1 year	Damage to post and fencing, bent
	Fencing - Old Standard Ornamental	Entire Site	100	LF	6	10+ years	
	Fencing - Old Standard Ornamental	Entire Site	300	LF	4	0-1 year	Corroding fence
	Fencing - Old Standard Ornamental	Entire Site	30	LF	4	0-1 year	Corroding fence. Verified dimension
	Fencing - Old Standard Ornamental	Entire Site	30	LF	4	1-2 years	Smashed, burnt and corroded fence
							and gate
Landsca	na						
Lanusca	Benches	Entire Site	6	EA	7	10+ years	
	Benches	Entire Site	20	EΑ	4	0-1 year	Courtyard benches are rotted.
	Benches	Entire Site	6	EΑ	4	0-1 year	Rotted wood, pieces missing.
	Landscape - Grass	Entire Site	57,873	SF	6	10+ years	Notice wood, pieces missing.
	Landscape - Hardscape- Concrete	Entire Site	34,266	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	682	SF	4	0-1 year	Broken concrete, cracks
	Landscape - Hardscape- Pavers	Entire Site	2,245	SF	6	10+ years	Broken concrete, ordeke
	Landscape - Hardscape- Pavers	Entire Site	9,780	SF	6	10+ years	
	Parkway trees	Entire Site	6	EA	6	10+ years	
	Retaining Wall - Concrete	Entire Site	227	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	200	SF	5	1-2 years	Retaining walls leading to dock have
	Retaining Waii - Concrete	Littile Site	200	OI.	3	1-2 years	several large cracks which seep
	D	F // 0'/		~-	_	2.4	water
	Retaining Wall - Concrete	Entire Site	20	SF	5	0-1 year	Top of retaining wall is spalled, Bent
	Track Pagantagles	Entire Site	4	EA	6	10 Lyong	dangerous metal grate
	Trash Receptacles	Entire Site	4	EA	O	10+ years	
Parking	Lot						
g	Concrete Curbs	SW, W, N	1,005	LF	6	10+ years	
		- , ,	.,000		-	- ,	

Campus Name: Collins HS Page : 64 of 68 Assessment Date: 06/22/2022



commend colacement D-1 year D-1 years D-1 years D-1 year D-1 years D-1 year D-1 year D-1 years D-2 years D-3 years D-3 years D-4 years D-1 years D-1 years D-1 years D-2 years D-3 years D-3 years D-4 years D-1 years
D-1 year D-1 years D-1 years D-1 years D-1 year Broken/cracked. D-1 years G in North Lot, 3 in SW Lot. Potholes, large cracks, alligatored, and crumbling surface. 10 years D-1 years D-2 years
O+ years O+ years O+ years 6 in North Lot, 3 in SW Lot. Potholes, large cracks, alligatored, and crumbling surface. 10 years O+ years O+ years
0+ years 6 in North Lot, 3 in SW Lot. 0-1 year Potholes, large cracks, alligatored, and crumbling surface. 10 years 0+ years
Potholes, large cracks, alligatored, and crumbling surface. 10 years 0+ years
and crumbling surface. 10 years 0+ years
0+ years
)+ years
0+ years
0+ years
O-1 year Broken, shattered walks. Some damage to sidewalks, most damage is to concrete hard scape. Other damage noted under site.
0+ years
0+ years
O+ years
0+ years
0+ years
).).

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").



Classroom Summary

,			D	Floor Plan	A	Glazed	Operable	\A(!	0
Current Usage	Intended Usage	Room Location	Room Number	Room Number	Area (SF)	Window Area	Window Area	Window Stop	Smart- Board
Building : Main	intended Usage	Room Location	Number	Number	(SF)	Alea	Alea	Зюр	Боаги
Art Room	Science Classroom	3rd Floor	BLDG A	BLDG A 300	1,170	278	55	N	N
Art Room	Ocience Glassicom	314 1 1001	307	DLDG A 300	1,170	270	33	11	IN.
Computer Lab	Regular Classroom	3rd Floor	BLDG A	BLDG A 322	993	310	85	N	Y
		1.5	300	100	4 000	450			
Other Instructional Use	Other Instructional Use	1st Floor	106A	106	1,020	450	88	N	N
Regular Classroom	Regular Classroom	1st Floor	BLDG A 112	BLDG A 125	704	164	22	N	Υ
Regular Classroom	Regular Classroom	1st Floor	BLDG A 113	BLDG A 126	535	140	33	N	N
Regular Classroom	Regular Classroom	1st Floor	BLDG A	BLDG A 127	535	140	33	N	N
Regular Glassicom	regular olassioom	13011001	114	DEBOTA 121	555	140	33	1	1
Regular Classroom	Regular Classroom	1st Floor	BLDG A	BLDG A 128	704	164	22	N	N
			115						
Regular Classroom	Regular Classroom	1st Floor	BLDG A 117	N/A	836	210	44	N	N
Regular Classroom	Regular Classroom	1st Floor	BLDG A	N/A	836	420	88	N	N
			118						
Regular Classroom	Regular Classroom	1st Floor	BLDG A 119	N/A	860	210	33	N	N
Regular Classroom	Regular Classroom	1st Floor	BLDG A	ASOCIAL	534	138	33	N	N
			139	SCIENCE					
Regular Classroom	Regular Classroom	2nd Floor	BLDG A 206	212	700	180	44	N	N
Regular Classroom	Regular Classroom	2nd Floor	BLDG A	200	735	172	33	N	N
rtogular Glassiosini	Trogular Glassicom	2110 1 1001	226	200	700	1,72	00	14	.,
Regular Classroom	Regular Classroom	2nd Floor	BLDG A	Lounge	693	180	44	N	N
	-		228						
Regular Classroom	Regular Classroom	2nd Floor	BLDG A 229	Library	675	180	44	N	N
Regular Classroom	Regular Classroom	2nd Floor	BLDG A	Library	1,010	450	88	N	N
3			230		,				
Regular Classroom	Regular Classroom	2nd Floor	BLDG A	Library	536	142	33	N	N
			231	<u> </u>				ļ	<u> </u>
Regular Classroom	Regular Classroom	2nd Floor	BLDG A 233	Library	670	172	33	N	N
Regular Classroom	Regular Classroom	2nd Floor	BLDG A	218	875	422	88	N	N
3	3		234				- -		
Regular Classroom	Regular Classroom	2nd Floor	BLDG A	offices	675	180	44	N	N
			235						

Campus Name: Collins HS Page : 66 of 68 Assessment Date: 06/22/2022



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	2nd Floor	BLDG A 236	Offices	693	180	44	N	N
Regular Classroom	Regular Classroom	2nd Floor	BLDG A 237	215	686	172	33	N	N
Regular Classroom	Regular Classroom	2nd Floor	BLDG A 238	214	686	172	33	N	N
Regular Classroom	Regular Classroom	2nd Floor	BLDG A 239	213	686	172	33	N	N
Regular Classroom	Regular Classroom	2nd Floor	BLDG A 240	212	670	172	33	N	N
Regular Classroom	Regular Classroom	3rd Floor	BLDG A 301	BLDG A 323	675	180	44	N	Y
Regular Classroom	Regular Classroom	3rd Floor	BLDG A 302	BLDG A 324	693	180	44	N	Y
Regular Classroom	Regular Classroom	3rd Floor	BLDG A 304	N/A	697	142	48	N	Y
Regular Classroom	Regular Classroom	3rd Floor	BLDG A 314	BLDG A 311	830	210	44	N	Y
Regular Classroom	Regular Classroom	3rd Floor	BLDG A 315	BLDG A 312	535	140	33	N	N
Regular Classroom	Regular Classroom	3rd Floor	BLDG A 316	BLDG A 313	686	172	33	N	N
Regular Classroom	Regular Classroom	3rd Floor	BLDG A 317	BLDG A 314	686	172	33	N	N
Regular Classroom	Regular Classroom	3rd Floor	BLDG A 318	BLDG A 315	686	172	33	N	N
Regular Classroom	Regular Classroom	3rd Floor	BLDG A 319	BLDG A 316	693	180	44	N	Y
Regular Classroom	Regular Classroom	3rd Floor	BLDG A 320	BLDG A 317	675	180	44	N	N
Regular Classroom	Regular Classroom	3rd Floor	BLDG A 321	BLDG A 318	875	422	88	N	Y
Regular Classroom	Regular Classroom	3rd Floor	BLDG A 322	BLDG A 319	670	172	33	N	Y
Regular Classroom	Regular Classroom	3rd Floor	BLDG A 323	BLDG A 321	556	136	22	N	Y
Regular Classroom	Regular Classroom	3rd Floor	BLDG A 324	BLDG A 321B	536	142	33	N	Y
Science Lab Level 1	Science Classroom	1st Floor	BLDG A 200	201	1,078	284	66	N	N
Science Lab Level 1	Science Lab Level 1	2nd Floor	BLDG A 205	208	1,118	484	99	N	N





Regular Classroom

Office

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Science Lab Level 1	Science Lab Level 1	3rd Floor	BLDG A 310	BLDG A 305	1,000	240	44	N	N
Science Lab Level 1	Science Lab Level 1	3rd Floor	BLDG A 313	BLDG A 310	1,170	484	99	N	N
Science Lab Level 2	Science Lab Level 2	2nd Floor	BLDG A 203	205	1,145	270	44	N	N
Store Room	Regular Classroom	1st Floor	BLDG A 137	A SOCIAL SCIENC	534	138	33	N	N
Store Room	Regular Classroom	2nd Floor	BLDG A 232	Library	556	136	22	N	N
Building : Linked Addition-	Fine Arts & Tech Building								
Art Room	Art Room	1st Floor	132	132	1,416	85	20	Υ	N
Band Room	Band Room	1st Floor	136	136	1,743	0	0	N	N
Choral Room	Choral Room	1st Floor	134	134	1,431	0	0	N	N
Computer Lab	Autoshop	1st Floor	140A	140	1,063	455	280	N	N
Computer Lab	Computer Lab	1st Floor	148	148	1,008	119	21	N	N
Computer Lab	Other Instructional Use	1st Floor	140B	140	1,022	80	0	N	N
Multi Purpose Room	Autoshop	1st Floor	140D	140	368	72	0		
Other Instructional Use	Music Room	1st Floor	133	133	687	0	0	N	N
Other Instructional Use	Other Instructional Use	1st Floor	130	130	1,879	153	16	Y	N
Regular Classroom	Art Room	1st Floor	144	144	1,007	68	16	N	N
Regular Classroom	Art Room	1st Floor	146	144	1,062	68	16	N	N
Store Room	Autoshop	1st Floor	140F		246	0	0		
Building : Linked Addition-	Physical Education Building								
Fitness Room	Office	1st Floor	124 Exercise	176	917	85	15	N	N
Fitness Room	Store Room	1st Floor	Weight Rm- East	n/a	378	0	0	N	N
Other Instructional Use	Office	1st Floor	121 FSM Control	Exercise Room	437	0	0	N	N
Other Instructional Use	Office	1st Floor	122 FSM Studio	Exercise Room	752	30	0	N	N
			100 501	5				.	

123 FSM

Room

Board of

Edu.

907

85

15

Ν

Ν

1st Floor