

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1911	4	67,120
Addition	1993	1	4,548
Campus Total			71,668

Catego	ry : Exterior	В	uilding	: Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Cell Equi	pment						
·	Cell Equipment - Antenna	West Façade	2	EA	7	10+ years	
Entrance							
	Exterior Doors - Exterior Steel Door	#10 -NE Exit	1	EA	7	10+ years	
	Exterior Stairs - Concrete	#10 -NE Exit	5	LF	7	6-10 years	
	Exterior Doors - Side lite	#11- NW Exit	2	EΑ	7	10+ years	
	Exterior Doors - Store Front	#11- NW Exit	4	EΑ	7	10+ years	
	Exterior Doors - Transom Lite	#11- NW Exit	4	EΑ	7	10+ years	
	Exterior Stairs - Concrete	#11- NW Exit	30	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#12- Boiler Room- NW	1	EΑ	6	6-10 years	
	Entrance Control - Audio and Video	#3- Main- SW	1	EΑ	7	10+ years	
	Exterior Doors - Side lite	#3- Main- SW	2	EΑ	7	10+ years	
	Exterior Doors - Store Front	#3- Main- SW	4	EA	7	10+ years	
	Exterior Doors - Transom Lite	#3- Main- SW	4	EΑ	7	10+ years	
	Exterior Stairs - Concrete	#3- Main- SW	24	LF	7	10+ years	
	Ramps - Concrete	#3- Main- SW	15	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#3- Main- SW	30	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#4- SE	1	EA	7	10+ years	
	Exterior Stairs - Concrete	#4- SE	8	LF	7	10+ years	
	Exterior Stairs - Stone	#4- SE	3	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#5- SE	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#6- SE	1	EA	7	10+ years	
	Exterior Stairs - Stone	#6- SE	5	LF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Exterior Doors - Exterior Steel Door	Fire escape doors at W elevation	4	EA	6	6-10 years			
Fire Esc	ane								
<u> </u>	Fire Escape	Façade- NW	70	LF	6	6-10 years			
Foundat	ion								
FOULIDAL	Foundation - Masonry	Entire Building	760	LF	7	10+ years			
	Foundation - Masonry	Entire Building	60	LF	6	10+ years			
	Superstructure - Steel with Clay Tile Arch	Entire Building	67,120	SF	7	10+ years			
	Superstructure - Steel with Glay The Alon	Little Building	07,120	OI.	,	10+ years			
Lighting									
	Exterior Lighting - Wall Mounted	Entire Building	15	EA	6	10+ years			
Roof Sys	stem								
,	Coping - Stone	Link roof	16	LF	6	10+ years			
	Downspouts - Exterior Downspouts	Link roof	16	LF	6	6-10 years			
	Parapet - 16" - 30" Height	Link roof	16	LF	6	10+ years			
	Roof - Modified Bitumen	Link roof	127	SF	5	6-10 years	Ripples/soft spots observed - Detachment from substrate		
	Roof Structure - Steel with Clay Tile Arch	Link roof	127	SF	7	10+ years	Detacriment nom substrate		
	Access Ladder - Metal	Low E roof	1	ĒΑ	7	6-10 years			
	Access Ladder - Metal	Low E roof	1	EA	4	1-2 years			
	Coping - Metal	Low E roof	47	LF	6	6-10 years			
	Coping - Stone	Low E roof	230	LF	6	10+ years			
	Downspouts - Interior Downspouts	Low E roof	78	LF	6	6-10 years			
	Parapet - Parapet > 30"	Low E roof	268	LF	6	10+ years			
	Parapet - Parapet > 30"	Low E roof	20	LF	5	2-5 years	Open mortar Joints		
	Roof - Modified Bitumen	Low E roof	4,560	SF	5	6-10 years	Soft Spots detachment from substra		
	Roof Hatch - Metal	Low E roof	1	EA	7	6-10 years	in spots		
	Roof Structure - Steel with Clay Tile Arch	Low E roof	4,560	SF	7	10+ years			
	Chimney - Brick Chimney- Concrete/ Mortar	Low W roof	16	LF	6	10+ years			
	Liner Chimney - Brick Chimney- Concrete/ Mortar	Low W roof	15	LF	6	10+ years			
	Liner Chimney - Brick Chimney- Concrete/ Mortar	Low W roof	52	LF	6	10+ years			
	Liner	Low W roof	45		7	10			
	Coping Stone	Low W roof	15	LF LF	7	10+ years			
	Coping - Stone	Low W roof	5		7	10+ years			
	Coping - Stone	Low W roof	135	LF	6	10+ years			
	Downspouts - Exterior Downspouts	Low W roof	16	LF	6	6-10 years			
	Downspouts - Interior Downspouts	Low W roof	16	LF	6	6-10 years			
	Parapet - Parapet < 16" Height	Low W roof	155	LF	7	10+ years			



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	Low W roof	2,800	SF	5	6-10 years	Soft spots, detachment from substrate in spots
	Roof Structure - Steel with Clay Tile Arch	Low W roof	2,853	SF	7	10+ years	•
	Access Ladder - Metal	Main Roof	_,;;;	ĒΑ	7	6-10 years	
	Access Ladder - Metal	Main Roof	2	EA	7	10+ years	South
	Coping - Stone	Main Roof	2	LF	6	6-10 years	
	Coping - Stone	Main Roof	575	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Main Roof	272	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Main Roof	80	LF	5	6-10 years	
	Parapet - Parapet < 16" Height	Main Roof	457	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Main Roof	40	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	40	SF	5	6-10 years	Soft spots, detachment from
	1001 - Modified Bitarrieri	Wall Roof	40	Oi	3	0-10 years	substrate in spots
	Roof - Modified Bitumen	Main Roof	14,840	SF	5	6-10 years	Soft spots, cracking ripples/Detachment from substrate in
							spots
	Roof Hatch - Metal	Main Roof	1	EΑ	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	14,880	SF	7	10+ years	
Valls							
	Canopy - Metal	Entire Building	35	SF	7	6-10 years	
	Canopy - Metal	Entire Building	35	SF	7	6-10 years	
	Cornice - Masonry Projecting Limestone	Entire Building	1,150	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	15	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	39,000	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	20	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	50	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	30	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	20	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	5,100	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	5	SF	6	10+ years	
Vindows	3						
	Guard - Guards perforated	Entire Building	3,282	SF	6	6-10 years	
	Lintels - Brick	Entire Building	50	ĹF	6	6-10 years	
	Lintels - Steel	Entire Building	1,173	LF	6	6-10 years	
	Windows - Casement Aluminum	Entire Building	9,180	SF	7	6-10 years	
	Windows - Casement Aluminum Double- pane	Entire Building	10	SF	7	6-10 years	
	Windows - Sash Aluminum	Entire Building	50	SF	7	6-10 years	
	Windows - Sash Aluminum Windows - Sash Aluminum	Entire Building Entire Building	2,100	SF	7	6-10 years	
Catego	ry : Electrical		R	uilding	: Main		
		Location				Recommend	Comments
Group	-	Location	Quantity	UOM	Rank	Recommend	Comments



						Replacement	
eraen	cy System						
3	Automatic Transfer Switch	Electrical Room	1	EA	4	2-5 years	Deteriorated, not reliable, more tha 50 years old, functional, replaceme parts not available
	Emergency A/C Power - Corridors and Stairs	Entire Building	8,857	SF	6	10+ years	parts not available
	Emergency Battery Packs - Corridors and Stairs	Entire Building	11	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	6	6-10 years	Recently installed, with battery pac
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	2	0-1 year	No battery packs
	Exit Signs - Corridors and Stairs	Entire Building	7	EA	2	0-1 year	No battery packs
	Exit Signs - Gym	Entire Building	5	EA	2	0-1 year	No battery packs, Found only 5 ex signs
	Security System - CCTV	Entire Building	67,120	SF	5	6-10 years	g
	Security System - Intrusion Detection	Entire Building	67,120	SF	5	6-10 years	
in Serv							
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	Functional, ATS and second meter serves main and addition buildings older ATS
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	Serves main and addition building. Electrical service is marginal.
	PA System	Entire Building	67,120	SF	5	6-10 years	Serves main and addition buildings
wer Dis	stribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	9	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	Functional panels rated 7
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	Functional panels rated 7
tegor	y : Fire Protection		В	uilding	: Main		
oup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
e Alarn							
	Fire Alarm Panel	Mechanical Room	1	EA	7	10+ years	Recently updated, serves main and addition
	Fire Alarm Strobe Lights	Mechanical Room	67,120	SF	6	10+ years	Recently installed
	Fire Alarm_System	Mechanical Room	67,120	SF	6	6-10 years	Parts of system updated in 2020, connected to addition



Catego	Category : Mechanical				: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Hand	lling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm	Mechanical Room	2	EA	5	6-10 years	Serves classrooms and offices, main building, East and west side, AHU 1, AHU 2
	Air Intake	Mechanical Room	2	EA	5	6-10 years	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	2	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	200	LF	5	6-10 years	Common return
	Zone Dampers	Mechanical Room	20	EA	5	6-10 years	Partial BAS control. Some (~ 1/2) of the total dampers are manually controlled. 20 served by AHU1, 20 served by AHU 2
	Zone Dampers	Mechanical Room	20	EA	4	2-5 years	Disconnected actuators, corroded, manually operated, functional
Boiler Sy	/stems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	5	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	10+ years	1 pump for both boilers
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	, , ,
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	10+ years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	2	EA	5	6-10 years	Serves main and addition building
	Steam- Low Pressure Boiler - 101 - 150 HP					•	Ç
	Piping - Condensate Pipe- Steel	Boiler Room	250	LF	5	6-10 years	Minor leaks occasionally repaired, connect to air handler in mezzanine in addition building
	Piping - Steam Pipe- Steel	Boiler Room	250	LF	5	6-10 years	Minor leaks occasionally repaired, connect to air handler in addition mezzanine
	Steam Traps	Boiler Room	26	EA	5	6-10 years	Occasional repair of leaking steam traps required.
_Heating	Devices						
	Cabinet Heaters - With Steam Coil	1st Floor	2	EA	6	10+ years	
	Cabinet Heaters - With Steam Coil	1st Floor	3	EA	5	6-10 years	Cabinet is showing deterioration, not painted
	Unit Heater - Gas	Boiler Room and Mechanical Room	2	EA	5	6-10 years	•
	Unit Heater - Steam	Boiler Room and Mechanical Room	1	EA	6	6-10 years	
	Fin Tube - Electric	Entire Building	15	LF	4	2-5 years	Worm, deteriorated paint, on offices, functional
	Unit Heater - Electric	Entire Building	2	EA	5	6-10 years	Per engineer, only 2 electric unit

Campus Name: Corkery Page : 5 of 32 Assessment Date: 01/24/2022



Catego	ry : Mechanical	·	В	uilding	: Main	·	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Unit Heater - Steam	Entire Building	2	EA	5	6-10 years	heaters in school buildings Previously not assessed, located
	Onit Fleater - Steam	Littile ballaring	2	LA	3	0-10 years	above ceilings
	Cabinet Heaters - With Electric Coil	Entire Building	2	EA	5	6-10 years	Ceiling mounted, found 2
	Wall Heater - Electric	Entire Building	2	EA	6	10+ years	Serve restrooms
	Wall Heater - Electric	Entire Building	1	EA	5	6-10 years	Serve restrooms, older, not reliable
Tempera	ature Control						
	Electric Thermostat	Entire Building	8	EA	5	6-10 years	Serve unit heaters and exhaust fans
	Hybrid Pneumatic/DDC System	Entire Building	67,120	SF	4	2-5 years	Some dampers manually controlled, Mostly DDC computer controlled, pneumatic compressor and gages. Software not updated during last 8 years
	Thermostats - DDC	Entire Building	30	EA	6	6-10 years	
	Thermostats - Pneumatic	Entire Building	3	EA	5	6-10 years	In air handler rooms, control air handlers
Ventilation	on						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Basement and Roof	2	EA	5	6-10 years	

Category: Plumbing Building: Main

5	. y						
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	4	2-5 years	Serves main building, tankless, per nameplate, built in 2000, not reliable
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Boiler Room	1	EA	5	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	67,120	SF	4	2-5 years	Pressure is low on top floor
	Domestic Piping-Hot Water Return Risers	Entire Building	67,120	SF	4	2-5 years	Minor leaks occasionally repaired
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	67,120	SF	4	2-5 years	Old pipes are partially calcified
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	67,120	SF	4	2-5 years	Installed in 1911
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	67,120	SF	4	2-5 years	Minor leaks frequently repaired
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	67,120	SF	4	2-5 years	More than 100 years old
	Sanitary Piping	Entire Building	67,120	SF	4	2-5 years	Frequent repairs and unclogging

Campus Name: Corkery Page : 6 of 32 Assessment Date: 01/24/2022



Catego	Category : Plumbing			uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	71						needed
	Storm Piping	Entire Building	67,120	SF	5	6-10 years	
	Vent Piping	Entire Building	67,120	SF	5	6-10 years	Recently cleaned
Pumps							
•	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	5	6-10 years	Serves main and addition buildings

Building: Main Category: Room

atego	ry : Room		Б	ullaing	: wain		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						
	Ceiling - Lay-in	Assistant principals office	120	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Assistant principals office	1	EA	7	10+ years	
	Floor - Tile	Assistant principals office	120	SF	7	10+ years	
	Lighting - Lay-in	Assistant principals office	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Assistant principals office	340	SF	7	10+ years	
	AC Unit	Basement south of classroom #007	2	EA	7	6-10 years	
	Ceiling - Lay-in	Basement south of classroom #007	880	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement south of classroom #007	3	EA	6	10+ years	
	Floor - Tile	Basement south of classroom #007	880	SF	6	10+ years	
	Floor - Tile	Basement south of classroom #007	25	SF	5	0-1 year	Damaged and cracked tiles
	Lighting - Lay-in	Basement south of classroom #007	12	EA	7	6-10 years	
	Power Distribution	Basement south of classroom #007	18	EA	6	6-10 years	
	Storage/ Closet	Basement south of classroom #007	60	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement south of classroom #007	1,962	SF	6	10+ years	
	Ceiling - Exposed	Engineer's Office- Basement	163	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Office- Basement	50	SF	6	0-1 year	major failure. cracked and staine
	Doors - Steel Doors incl hw	Engineer's Office- Basement	1	EA	6	10+ years	
	Floor - Concrete	Engineer's Office- Basement	213	SF	7	10+ years	
	Lighting - Pendent/Surface	Engineer's Office- Basement	1	EA	7	6-10 years	
	Power Distribution	Engineer's Office- Basement	6	EA	6	6-10 years	
	Walls - Plaster/Drywall	Engineer's Office- Basement	100	SF	6	1-2 years	
	Walls - Plaster/Drywall	Engineer's Office- Basement	177	SF	6	10+ years	
	Ceiling - Lay-in	Gym Office - Basement	83	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gym Office - Basement	1	EA	6	10+ years	
	Floor - Tile	Gym Office - Basement	83	SF	6	10+ years	
	Lighting - Pendent/Surface	Gym Office - Basement	1	EA	7	6-10 years	
	Power Distribution	Gym Office - Basement	4	EA	6	6-10 years	
	Walls - Masonry	Gym Office - Basement	106	SF	6	10+ years	
	Walls - Plaster/Drywall	Gym Office - Basement	1	SF	6	0-1 year	Hole in wall
	Ceiling - Plaster/Drywall	Janitor's Lounge - Basement	121	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Janitor's Lounge - Basement	1	EA	6	10+ years	
	Floor - Concrete	Janitor's Lounge - Basement	121	SF	7	10+ years	
	Lighting - Pendent/Surface	Janitor's Lounge - Basement	2	EA	7	6-10 years	

Campus Name: Corkery Page : 7 of 32 Assessment Date: 01/24/2022



Catego	ry : Room		В	uilding	: Main		. 5 :
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Janitor's Lounge - Basement	4	EΑ	6	10+ years	
	Walls - Masonry	Janitor's Lounge - Basement	157	SF	6	10+ years	
	AC Unit	Principals office	1	EΑ	7	6-10 years	
	Ceiling - Lay-in	Principals office	312	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Principals office	1	EA	7	10+ years	
	Floor - Tile	Principals office	312	SF	7	6-10 years	
	Lighting - Lay-in	Principals office	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	Principals office	660	SF	7	10+ years	
	AC Unit	Room 006, Adjustment Offices	2	EA	7	6-10 years	
	Ceiling - Lay-in	Room 006, Adjustment Offices	805	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 006, Adjustment Offices	1	EA	6	10+ years	
	Lighting - Lay-in	Room 006, Adjustment Offices	10	EA	7	6-10 years	
	Power Distribution	Room 006, Adjustment Offices	12	EA	6	6-10 years	
	Walls - Metal Panel	Room 006, Adjustment Offices	784	SF	6	10+ years	
	Walls - Plaster/Drywall	Room 006, Adjustment Offices	261	SF	6	10+ years	
	Ceiling - Lay-in	Room 008, Teacher's	804	SF	6	10+ years	
	Ç ,	Lounge/Storeroom in Basement				·	
	Doors - Side-lite	Room 008, Teacher's	14	SF	6	10+ years	
		Lounge/Storeroom in Basement				,	
	Doors - Wood Doors inclu hw	Room 008, Teacher's	1	EA	6	10+ years	
		Lounge/Storeroom in Basement				,	
	Floor - Tile	Room 008, Teacher's	804	SF	6	10+ years	
		Lounge/Storeroom in Basement				,	
	Lighting - Lay-in	Room 008, Teacher's	12	EA	7	6-10 years	
	0 0 ,	Lounge/Storeroom in Basement				•	
	Power Distribution	Room 008, Teacher's	10	EA	6	6-10 years	
		Lounge/Storeroom in Basement				,	
	Walls - Plaster/Drywall	Room 008, Teacher's	804	SF	6	10+ years	
	•	Lounge/Storeroom in Basement				·	
	Work Sink	Room 008, Teacher's	1	EA	7	10+ years	
		Lounge/Storeroom in Basement				,	
		· ·					
Gvmnas	ia						
, –	Ceiling - Lay-in	Basement	3,570	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	4	EA	6	10+ years	
	Floor - Sport Flooring	Basement	3,570	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	12	EA	7	6-10 years	
	Scoreboards	Basement	1	EA	7	10+ years	
	Storage/ Closet	Basement	291	SF	7	10+ years	
	Walls - Masonry	Basement	3,614	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	1,204	SF	6	10+ years	
	_						
_MDF_ID							
	Doors - Steel Doors incl hw	Basement north of room #007	1	EA	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
	,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Finishes	Basement north of room #007	275	SF	7	10+ years	
	Other Cooling Unit	Basement north of room #007	1	EA	7	10+ years	Ductless split system
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	15	SF	5	10+ years	
	Janitor's Closet	1st Floor	15	SF	5	10+ years	
	Janitor's Closet	2nd Floor	15	SF	5	10+ years	
	Janitor's Closet	2nd Floor	15	SF	5	10+ years	
	Janitor's Closet	3rd Floor	15	SF	5	10+ years	
	Janitor's Closet	3rd Floor	15	SF	5	10+ years	
	Boiler Room	Basement	1,155	SF	7	10+ years	
	Coal Room	Basement	400	SF	7	10+ years	
	Janitor's Closet	Basement	35	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	1,201	SF	7	10+ years	Relamp one fixture
	Storage Room	Basement	170	SF	7	10+ years	
	Storage Room	Basement east side	283	SF	7	10+ years	
Restroor	n						
	Accessories	1st Floor	338	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	338	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	338	SF	6	10+ years	
	Floor Drain	1st Floor	2	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	6	10+ years	
	Lighting - Lay-in	1st Floor	6	EA	6	6-10 years	
	Partitions	1st Floor	8	EA	7	10+ years	
	Walls - Masonry	1st Floor	219	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	219	SF	6	10+ years	
	Water Closet	1st Floor	8	EA	6	10+ years	
	Accessories	1st Floor	323	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	323	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	323	SF	6	10+ years	
	Floor Drain	1st Floor	2	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	6	10+ years	
	Lighting - Lay-in	1st Floor	6	EA	6	6-10 years	
	Partitions	1st Floor	3	EA	7	10+ years	
	Urinals	1st Floor	5	EA	6	10+ years	
	Walls - Masonry	1st Floor	209	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	209	SF	6	10+ years	
	Water Closet	1st Floor	3	EA	6	10+ years	
	Accessories	1st Floor Unisex Restroom North	35	SF	7	6-10 years	



Catego	Category : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor Unisex Restroom North	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Unisex Restroom North	1	EA	6	10+ years	
	Floor - Tile Quarry	1st Floor Unisex Restroom North	35	SF	6	10+ years	
	Lavatory	1st Floor Unisex Restroom North	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Unisex Restroom North	1	EA	6	6-10 years	
	Partitions	1st Floor Unisex Restroom North	1	EA	7	10+ years	
	Walls - Masonry	1st Floor Unisex Restroom North	89	SF	6	10+ years	
	Water Closet	1st Floor Unisex Restroom North	1	EA	6	10+ years	
	Accessories	1st Floor Unisex Restroom South	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Unisex Restroom South	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Unisex Restroom South	1	EA	6	10+ years	
	Floor - Tile Quarry	1st Floor Unisex Restroom South	35	SF	6	10+ years	
	Lavatory	1st Floor Unisex Restroom South	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Unisex Restroom South	1	EA	6	6-10 years	
	Partitions	1st Floor Unisex Restroom South	1	EA	7	10+ years	
	Walls - Masonry	1st Floor Unisex Restroom South	89	SF	6	10+ years	
	Water Closet	1st Floor Unisex Restroom South	1	EA	6	10+ years	
	Accessories	2nd Floor	338	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	338	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	338	SF	6	10+ years	
	Floor Drain	2nd Floor	2	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	6	6-10 years	
	Partitions	2nd Floor	8	EA	7	10+ years	
	Walls - Masonry	2nd Floor	219	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	219	SF	6	10+ years	
	Water Closet	2nd Floor	8	ĒΑ	6	10+ years	
	Accessories	2nd Floor	323	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	323	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	4	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	323	SF	6	10+ years	
	Floor Drain	2nd Floor	2	ĒΑ	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	6	6-10 years	
	Partitions	2nd Floor	3	EA	7	10+ years	
	Urinals	2nd Floor	5	EΑ	6	10+ years	
	Walls - Masonry	2nd Floor	209	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	209	SF	6	10+ years	
	Water Closet	2nd Floor	3	EA	6	10+ years	
	Accessories	2nd Floor Unisex North	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Unisex North	35	SF	6	10+ years	
	Coming Flactor/Drywan	ZHOT HOST CHISOX HORIT	55	J1	J	ioi youis	



Catego	Category : Room			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor Unisex North	1	EΑ	6	10+ years	
	Floor - Tile Quarry	2nd Floor Unisex North	35	SF	6	10+ years	
	Lavatory	2nd Floor Unisex North	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Unisex North	1	EA	6	6-10 years	
	Partitions	2nd Floor Unisex North	1	EΑ	7	10+ years	
	Walls - Masonry	2nd Floor Unisex North	89	SF	6	10+ years	
	Water Closet	2nd Floor Unisex North	1	EA	6	10+ years	
	Accessories	2nd Floor Unisex South	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Unisex South	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Unisex South	1	EA	6	10+ years	
	Floor - Tile Quarry	2nd Floor Unisex South	35	SF	6	10+ years	
	Lavatory	2nd Floor Unisex South	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Unisex South	1	EA	6	6-10 years	
	Partitions	2nd Floor Unisex South	1	EA	7	10+ years	
	Walls - Masonry	2nd Floor Unisex South	89	SF	6	10+ years	
	Water Closet	2nd Floor Unisex South	1	EA	6	10+ years	
	Accessories	3rd Floor	338	SF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	338	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	338	SF	6	10+ years	
	Floor Drain	3rd Floor	2	EA	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	6-10 years	
	Lavatory	3rd Floor	3	EA	6	10+ years	
	Lighting - Lay-in	3rd Floor	6	EA	6	6-10 years	
	Partitions	3rd Floor	8	EA	7	10+ years	
	Walls - Masonry	3rd Floor	219	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	219	SF	6	10+ years	
	Water Closet	3rd Floor	8	EA	6	10+ years	
	Accessories	3rd Floor	323	SF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	323	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	323	SF	6	10+ years	
	Floor Drain	3rd Floor	2	EΑ	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	6-10 years	
	Lavatory	3rd Floor	3	EA	6	10+ years	
	Lighting - Lay-in	3rd Floor	6	EA	6	6-10 years	
	Partitions	3rd Floor	3	EA	7	10+ years	
	Urinals	3rd Floor	5	EA	6	10+ years	
	Walls - Masonry	3rd Floor	209	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	209	SF	6	10+ years	
	Water Closet	3rd Floor	3	ĒΑ	6	10+ years	
	Accessories	3rd Floor Unisex South	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor Unisex South	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Unisex South	1	EA	6	10+ years	
		c.acc. c.moon count	'		•	, oaro	

Campus Name: Corkery Page : 11 of 32 Assessment Date: 01/24/2022



Category : Room			В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Quarry	3rd Floor Unisex South	35	SF	6	10+ years	
	Lavatory	3rd Floor Unisex South	1	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor Unisex South	1	EA	6	6-10 years	
	Partitions	3rd Floor Unisex South	1	EA	7	10+ years	
	Walls - Masonry	3rd Floor Unisex South	89	SF	6	10+ years	
	Water Closet	3rd Floor Unisex South	1	EA	6	10+ years	
	Accessories	3rd Floor unisex North	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor unisex North	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor unisex North	1	EA	6	10+ years	
	Floor - Tile Quarry	3rd Floor unisex North	35	SF	6	10+ years	
	Lavatory	3rd Floor unisex North	1	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor unisex North	1	EA	6	6-10 years	
	Partitions	3rd Floor unisex North	1	EA	7	10+ years	
	Walls - Masonry	3rd Floor unisex North	89	SF	6	10+ years	
	Water Closet	3rd Floor unisex North	1	EA	6	10+ years	
	Accessories	Basement	338	SF	7	6-10 years	
	Ceiling - Lay-in	Basement	290	SF	6	10+ years	
	Ceiling - Lay-in	Basement	48	SF	5	0-1 year	Water damaged tiles
	Doors - Wood Doors inclu hw	Basement	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	338	SF	6	10+ years	
	Floor Drain	Basement	2	EA	7	10+ years	
	Hand Dryer	Basement	2	EA	7	6-10 years	
	Lavatory	Basement	3	EA	6	10+ years	
	Lighting - Lay-in	Basement	6	EA	6	6-10 years	
	Partitions	Basement	8	EA	7	10+ years	
	Walls - Masonry	Basement	219	SF	6	10+ years	
	Walls - Structural Glazed Tile	Basement	219	SF	6	10+ years	
	Water Closet	Basement	8	EA	6	10+ years	
	Accessories	Basement	323	SF	7	6-10 years	Bathroom repairs in progress
	Ceiling - Lay-in	Basement	195	SF	6	10+ years	
	Ceiling - Lay-in	Basement	128	SF	5	0-1 year	
	Doors - Wood Doors inclu hw	Basement	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	323	SF	6	10+ years	
	Floor Drain	Basement	2	EA	7	10+ years	
	Hand Dryer	Basement	2	EA	7	6-10 years	
	Lavatory	Basement	3	EA	6	10+ years	
	Lighting - Lay-in	Basement	6	EA	6	6-10 years	
	Partitions	Basement	3	EA	7	10+ years	
	Urinals	Basement	5	EA	6	10+ years	
	Walls - Masonry	Basement	209	SF	6	10+ years	
	Walls - Structural Glazed Tile	Basement	209	SF	6	10+ years	
	Water Closet	Basement	3	EA	6	10+ years	
	Accessories	Basement inside room #Pre-K 001	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement inside room #Pre-K 001	36	SF	6	10+ years	



Category : Room				uilding	: Main					
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Ceiling - Plaster/Drywall	Basement inside room #Pre-K 001	4	SF	6	0-1 year				
	Doors - Wood Doors inclu hw	Basement inside room #Pre-K 001	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Basement inside room #Pre-K 001	40	SF	6	10+ years				
	Lavatory	Basement inside room #Pre-K 001	1	EA	6	10+ years				
	Lighting - Pendent/Surface	Basement inside room #Pre-K 001	1	EA	6	6-10 years				
	Walls - Masonry	Basement inside room #Pre-K 001	233	SF	6	10+ years				
	Water Closet	Basement inside room #Pre-K 001	1	EA	6	10+ years				
	Accessories	North West	25	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	North West	25	SF	6	10+ years				
	Doors - Wood Doors inclu hw	North West	1	EA	6	10+ years				
	Floor - Tile	North West	25	SF	6	10+ years				
	Lavatory	North West	1	EA	6	10+ years				
	Lighting - Pendent/Surface	North West	1	EA	6	6-10 years				
	Walls - Vinyl Coated Gypsum Panel	North West	76	SF	6	6-10 years	Panelling			
	Water Closet	North West	1	EA	6	10+ years	-			

Category : Classroom **Building: Main**

Group	Itam - Tuno	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	Item - Type	Location	Quantity	OCIVI	Naiik	Replacement	Comments
Classroo	om #001 (Pre School)					0.40	_
	AC Units	Basement	1	EA	7	6-10 years	
	Casework	Basement	26	LF	6	10+ years	
	Ceiling - Lay-in	Basement	844	SF	6	10+ years	
	Ceiling - Lay-in	Basement	12	SF	5	0-1 year	Damaged tiles
	Chalk Board	Basement	5	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	6-10 years	
	Floor - Tile	Basement	819	SF	6	10+ years	
	Floor - Tile	Basement	25	SF	5	0-1 year	Broken and cracked tile
	Lighting - Lay-in	Basement	12	EA	7	6-10 years	
	Marker Board	Basement	6	LF	6	6-10 years	
	Storage/ Closet	Basement	80	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	951	SF	6	10+ years	
_Classroo	om #002 (Vacant)						
	Casework	1st Floor	26	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	5	0-1 year	Water damage
	Ceiling - Plaster/Drywall	1st Floor	844	SF	6	10+ years	ŭ
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	844	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Storage/ Closet	1st Floor	80	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	951	SF	6	10+ years	

Campus Name: Corkery Page : 13 of 32 Assessment Date: 01/24/2022



Category : Classroom			В	uilding	: Main		
_			• 414			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #003 (Kindergarten)						
Cidooroc	Casework	Basement	7	LF	6	10+ years	
	Ceiling - Lay-in	Basement	, 756	SF	6	10+ years	
	Chalk Board	Basement	11	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Wood	Basement	756	SF	6	10+ years	
	Lighting - Lay-in	Basement	12	EA	7	6-10 years	
	Marker Board	Basement	14	LF	6	6-10 years	
	Storage/ Closet	Basement	60	SF	7	10+ years	
	Walls - Concrete Block	Basement	892	SF	6	10+ years	
01	#007 (O)						
Liassroc	om #007 (Computer Lab) AC Units	Pagament		EA	7	6 10 4000	
		Basement	2 7			6-10 years	
	Casework	Basement	· · · · · · · · · · · · · · · · · · ·	LF CF	6	10+ years	
	Ceiling - Lay-in	Basement	756	SF	6	10+ years	
	Chalk Board	Basement	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Carpet	Basement	756	SF	6	6-10 years	
	Lighting - Lay-in	Basement	12	EA	7	6-10 years	
	Storage/ Closet	Basement	60	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	892	SF	6	10+ years	
	Wireless System	Basement	1	EA	7	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroc	om #100 (Special Program)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	22	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	780	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	780	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	ĒΑ	7	6-10 years	
	Storage/ Closet	1st Floor	47	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,089	SF	6	10+ years	
Classroo	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	820	SF	6	10+ years	
	Chalk Board	1st Floor	32	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood Boots inclu tiw	1st Floor	820	SF	6	10+ years	
	i iooi - vvoou	13(1100)	320	31	U	TOT years	



Catego	ry : Classroom		R	uilding	· Main	-	2510 5 Kildare AVENDE, Criicago, il 60625
Outogo	19.01000100111			ananig	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
O. Cup	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Storage/ Closet	1st Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	932	SF	6	10+ years	
Classroo	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	820	SF	6	10+ years	
	Chalk Board	1st Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	820	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,172	SF	6	10+ years	
Classro	om #103 (Regular Classroom)						
Ciassion	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	820	SF	6	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	6	10+ years	
	Floor - Wood	1st Floor	820	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	932	SF	6	10+ years	
Classroo	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	820	SF	6	10+ years	
	Chalk Board	1st Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	820	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,172	SF	6	10+ years	
Classroo	om #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	, 10 011110	1001	ı	_/ \	,	o io youis	



Catego	Category : Classroom		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Casework	1st Floor	7	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	820	SF	6	10+ years			
	Chalk Board	1st Floor	18	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood	1st Floor	820	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	12	EΑ	7	6-10 years			
	Marker Board	1st Floor	112	LF	6	6-10 years			
	Storage/ Closet	1st Floor	70	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	932	SF	6	10+ years			
Classroc	om #106 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	7	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	820	SF	6	10+ years			
	Chalk Board	1st Floor	18	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood	1st Floor	820	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years			
	Marker Board	1st Floor	12	LF	6	6-10 years			
	Storage/ Closet	1st Floor	55	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,172	SF	6	10+ years			
	vvalis - i lastei/Diywali	13111001	1,172	OI.	U	10+ years			
Classroo	om #107 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	7	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	820	SF	6	10+ years			
	Chalk Board	1st Floor	18	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood	1st Floor	820	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years			
	Marker Board	1st Floor	8	LF	6	6-10 years			
	Storage/ Closet	1st Floor	70	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	932	SF	6	10+ years			
Classroo	om #108 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	7	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	820	SF	6	10+ years			
	Chalk Board	1st Floor	18	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood	1st Floor	820	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years			
	Marker Board	1st Floor	12	LF	6	6-10 years			



Category : Classroom		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,172	SF	6	10+ years	
Classroo	m #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	820	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	820	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	14	LF	6	6-10 years	
	Storage/ Closet	1st Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	932	SF	6	10+ years	
Classroo	m #200 (Regular Classroom)						
Ciassioo	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor 2nd Floor	820	SF	6	•	
	Chalk Board	2nd Floor 2nd Floor		SF LF	4	10+ years 2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	18 1	EA	6	•	
						10+ years	
	Floor - Wood	2nd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,172	SF	6	10+ years	
Classroo	m #201 (Art Room)						
	Casework	2nd Floor	21	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	932	SF	6	10+ years	
	Work Sink	2nd Floor	1	EΑ	7	10+ years	
Classroo	m #202 (Library)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Chair Board	2110 1 1001	10	LI	7	2 0 years	



Catego	Category : Classroom		В	uilding	: Main				
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years			
	Floor - Wood	2nd Floor	820	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	6	LF	6	6-10 years			
	Storage/ Closet	2nd Floor	55	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,172	SF	6	10+ years			
Classroo	m #203 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	7	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years			
	Chalk Board	2nd Floor	6	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Wood Doors Inclu IIW	2nd Floor	820	SF	6				
						10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	8	LF	6	6-10 years			
	Storage/ Closet	2nd Floor	70	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	932	SF	6	10+ years			
Classroo	m #204 (Library)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	6	10+ years			
	Floor - Carpet	2nd Floor	820	SF	7	6-10 years			
	Lighting - Lay-in	2nd Floor	12	EΑ	6	6-10 years			
	Storage/ Closet	2nd Floor	55	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,172	SF	6	10+ years			
Classroo	m #205 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years			
	Chalk Board	2nd Floor	12	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Wood	2nd Floor	820	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	6	LF	6	6-10 years			
	Storage/ Closet	2nd Floor	70	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	932	SF	6	10+ years 10+ years			
Clasoroo	m #206 (Regular Classroom)								
<u>UIASSI UU</u>		Ond Flagr	4		7	C 40			
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	7	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years			



Category : Classroom		В	Building : Main					
						Recommend		
≩roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Chalk Board	2nd Floor	18	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Wood	2nd Floor	820	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	6	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	55	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,172	SF	6	10+ years		
Classroc	om #207 (Regular Classroom)							
	Casework	2nd Floor	7	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years		
	Chalk Board	2nd Floor	18	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ΕA	6	10+ years		
	Floor - Wood	2nd Floor	820	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	6	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	20	SF		-		
			932		7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	932	SF	6	10+ years		
Classroc	om #208 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	7	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years		
	Chalk Board	2nd Floor	18	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Wood	2nd Floor	820	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	6	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	55	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,172	SF	6	10+ years		
Classroo	om #209 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years		
	Casework	2nd Floor	16	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Carpet	2nd Floor	820	SF	6	6-10 years		
		2nd Floor 2nd Floor		EA	7	-		
	Lighting - Lay-in		12			6-10 years		
	Marker Board	2nd Floor	8	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	20	SF	7	10+ years		
	Walls - Metal Panel	2nd Floor	932	SF	6	10+ years		

Campus Name: Corkery Page: 19 of 32 Assessment Date: 01/24/2022



Category : Classroom			В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	6	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,172	SF	6	10+ years	
	vvalio i lactori bi y vali	014 1 1001	1,172	O.	Ü	101 youro	
lassroc	om #301 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	932	SF	6	10+ years	
				-	-	, , , , , , , , , , , , , , , , , , , ,	
Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,172	SF	6	•	
	walls - Plaster/Drywall	31d F1001	1,172	SF	0	10+ years	
lassroc	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	14	LF	6	6-10 years	
	Marker Doard	314 I 1001	14	LI	U	o- io yeais	



Catego	ory : Classroom		В	uilding	: Main		STO G Middle AVENCE, Gilledgo, IE 60025
o ano go	.,		_	······································		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	932	SF	6	10+ years	
Classro	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	6	6-10 years	
		3rd Floor	55	SF	7		
	Storage/ Closet			SF SF		10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,172	5F	6	10+ years	
_Classroo	om #305 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	932	SF	6	10+ years	
Classro	om #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,172	SF	6	10+ years	
OI-	·					•	
_Classroo	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	



	00110013						510 5 Kildare AVENOE, Chicago, IL 6062
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	932	SF	6	10+ years	
lassroc	om #308 (Regular Classroom)						
Idooroc	AC Units	3rd Floor	1	EA	7	6.10 years	
			-	LF		6-10 years	
	Casework	3rd Floor	7		6	10+ years	
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	6	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	55	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,172	SF	6	10+ years	
lassroc	om #309 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	932	SF	6	10+ years	
atego	ry : Interior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Lay-in	1st Floor	2,091	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	2	ΕA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,091	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	31	EA	6	6-10 years	
	Lighting - Lendent/Sulface	131 1 1001			_	-	
	Walla Blooter/Drawall	1et Floor	4 400	6	C	101110000	
	Walls - Plaster/Drywall Ceiling - Lay-in	1st Floor 2nd Floor	4,420 2,091	SF SF	6 6	10+ years 10+ years	



Catego	ry : Interior		В	uilding	: Main		ore or kindare // Ervot, orneage, it 00020
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	2nd Floor	4	EΑ	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,091	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	31	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	4,420	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	2,091	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	4	EA	6	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,091	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	31	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	4,420	SF	6	10+ years	
	Ceiling - Lay-in	Basement	3,261	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	12	EA	6	10+ years	
	Drinking Fountains - Double Fountain	Basement	3	EA	7	10+ years	
	Floor - Carpet	Basement	662	SF	6	6-10 years	
	Floor - Tile/Sheet	Basement	2,599	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	8	EA	6	6-10 years	
	Lighting - Wall Mounted	Basement	32	EA	6	6-10 years	
	Walls - Masonry	Basement	1,320	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	4,930	SF	6	10+ years	
Safety							
•	Camera Viewing Station	Entire Building	4	EA	7	6-10 years	
	Security Cameras	Entire Building	18	EA	7	6-10 years	
	Security Cameras	Entire Building	6	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North	434	SF	6	10+ years	
	Floor - Asphalt	North	1,242	SF	6	10+ years	
	Handrails	North	192	LF	7	10+ years	
	Lighting - Pendent/Surface	North	21	EA	6	6-10 years	
	Lighting - Wall Mounted	North	4	EA	6	6-10 years	
	Stairs - Asphalt	North	90	LF	6	10+ years	
	Walls - Masonry	North	4,536	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	434	SF	6	10+ years	
	Floor - Asphalt	South	1,242	SF	6	10+ years	
	Handrails	South	192	LF	7	10+ years	
	Lighting - Pendent/Surface	South	21	EA	6	6-10 years	
	Stairs - Asphalt	South	90	LF	6	10+ years	
	Walls - Masonry	South	4,536	SF	6	10+ years	



Category : Exterior Building : Addition

	Ham Tuna	Lagation	Ouantite:	LION	Donle	Recommend	Comments
up	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
trance							
	Exterior Doors - Exterior Steel Door	#7- NE	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#8- NE	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#9- NE	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#9- NE	2	EA	7	10+ years	
oundatio	on						
	Foundation - Concrete	Entire Building	250	LF	7	10+ years	
	Superstructure - Steel	Entire Building	250	SF	7	10+ years	MOVE TO MAIN MICHAEL
ghting_	Exterior Lighting - Wall Mounted	North Façade	1	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Norm Façade	ı	EA	O	6-10 years	
oof Sys							
	Chimney - Metal Flue	Low NE roof	20	LF	7	10+ years	
	Coping - Stone	Low NE roof	110	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low NE roof	30	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Low NE roof	100	LF	6	10+ years	
	Roof - EPDM/ Synthetic Rubber	Low NE roof	1,400	SF	5	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Low NE roof	1,400	SF	7	10+ years	
	Coping - Stone	Low NW roof	58	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low NW roof	32	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Low NW roof	58	LF	6	10+ years	
	Roof - EPDM/ Synthetic Rubber	Low NW roof	634	SF	5	•	
	Roof Structure - Steel / Metal Deck/	Low NW roof	634	SF	5 7	6-10 years	
	Concrete Topping		634	5F	7	10+ years	
	Coping - Stone	Low W roof	12	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Low W roof	16	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Low W roof	8	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Low W roof	4	LF	6	10+ years	
	Roof - EPDM/ Synthetic Rubber	Low W roof	157	SF	5	6-10 years	
	Roof Structure - Steel / Metal Deck/	Low W roof	157	SF	7	10+ years	
	Concrete Topping					•	
	Coping - Stone	Main Roof	195	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	48	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Main Roof	195	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	2,300	SF	5	6-10 years	
	Roof Structure - Steel / Metal Deck/	Main Roof	2,300	SF	7	10+ years	
	Concrete Topping	Wall Roof	2,500	O.	•	101 yours	
	Control Copping						



Catego	ry : Exterior		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Brick	Entire Building	30	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	5,247	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	20	SF	5	6-10 years	
	Exterior Walls - Brick	Entire Building	10	SF	5	6-10 years	
Vindows							
	Clerestory - Glass Double-Pane	Entire Building	144	SF	7	10+ years	
	Curtain wall - Louver	Entire Building	18	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	667	SF	6	10+ years	
	Lintels - Brick	Entire Building	47	LF	7	10+ years	
	Lintels - Steel	Entire Building	96	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	667	SF	7	10+ years	

Category : Electrical **Building: Addition**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
_	Exit Signs - Corridors and Stairs	1st Floor	5	EA	6	6-10 years	With battery and floodlight, recently installed
	Exit Signs - Corridors and Stairs	1st Floor	1	EA	2	0-1 year	No battery backup
	Exit Signs - Lunchroom	1st Floor	2	EA	2	0-1 year	No battery back-up
	Exit Signs - Multipurpose Room	1st Floor	2	EA	2	0-1 year	No battery back-up
	Emergency Battery Packs - Corridors and Stairs	1st Floor	2	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	1st Floor	2	EΑ	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	1st Floor	2	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	401	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	650	SF	6	10+ years	
	Emergency A/C Power - Multipurpose Room	Entire Building	2,648	SF	6	10+ years	1993 installation
	Security System - CCTV	Entire Building	4,548	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	4,548	SF	5	6-10 years	
Main Se	rvice						
	PA System	1st Floor	4,548	SF	5	6-10 years	Connected addition to main building, recently repaired
Power D	istribution						
	Lighting and Power Panels - 100 A	1st Floor	1	EA	7	10+ years	1993 installation
	Lighting and Power Panels - Above 100 A	1st Floor	2	EA	7	10+ years	Found 2
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	10+ years	Served from main building

Campus Name: Corkery Page : 25 of 32 Assessment Date: 01/24/2022



Catego	ry : Electrical		В	uilding	: Additi		STO O Midare AVENOE, Officago, IE 00025
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Fire Protection		В	uilding	: Additi	on	
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m Fire Alarm Strobe Lights	Entire Building	4,548	SF	6	10+ years	Recently inmstalled
	Fire Alarm_System	Entire Building	4,548	SF	6	10+ years	Newer fire alarm panel in main building, connected to main building
Catego	ry : Mechanical		В	uilding	: Additi	on	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Cond	Condensing Unit- Roof Mounted - Less than 5 tons	Lower Roof	1	EA	4	2-5 years	Serves evaporator in main building, occasional repairs needed. not readily accessible on small lower roof. Mini split system
_Air Hand	ling Systems						
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm	Mezzanine near cafeteria	1	EA	4	2-5 years	Recently serviced. Frequent pairs needed, request is in for a replacement, 1993 installation. Serves lunchroom and multi-purpose room. Steam from main building
	Air Intake	Mezzanine near cafeteria	1	EA	5	6-10 years	From roof
	Zone Dampers	Mezzanine near cafeteria	4	EA	5	6-10 years	Serves kitchen/cafeteria and multi- purpose room, controlled by 4 thermostats
	Make Up Air Unit- Roof Mounted- Gas Heating - 6000 - 10,000 cfm	Roof	1	EA	4	2-5 years	Serves kitchen area, 1993 installation, not reliable
Boiler S	vstems						
•	Piping - Condensate Pipe- Steel	Mezzanine	250	LF	6	10+ years	Previously not assessed, connected to main building
	Piping - Steam Pipe- Steel	Mezzanine	200	LF	6	10+ years	Connected to main building, serves air handler in mezzanine
	Steam Traps	Mezzanine	2	EA	5	6-10 years	Previously not assessed, near air handler
Heating	Devices						
	Wall Heater - Electric Unit Heater - Gas	1st Floor Mechanical Room	2	EA EA	6 5	10+ years 6-10 years	Previously not assessed Next to kitchen

Campus Name: Corkery Page : 26 of 32 Assessment Date: 01/24/2022



Catego	ry : Mechanical		В	uilding	: Addition	on	
			0		.	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	ical Plumbing						
	Condensate-Steel or Galvanized	Entire Building	200	LF	5	6-10 years	In mezzanine, serve air handler, steam and condensate pipes
Tempera	ature Control						
·	DDC System	Mechanical Room	4,548	SF	5	6-10 years	Software upgraded in 2013, server located in main building, serves air handler
	Electric Thermostat	Mechanical Room	5	EA	5	6-10 years	Serves make-up unit, unit heaters, exhaust fans
	Thermostats - DDC	Mechanical Room	4	EA	6	10+ years	Serve cafeteria/kitchen, multi purpose room
Ventilation	on						
	Exhaust Fans- Indoor - Less than 500 CFM	1st floor and Roof	1	EA	5	6-10 years	Serves kitchen
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	1st floor and Roof	1	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	1st floor and Roof	1	EA	5	6-10 years	
Catego	ry : Plumbing		В	uilding	: Additio	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate		4-4-51		ΕΛ		0.40	O a mara and distant
	Gas Heater - Less than 150000 BTU/HR Electric Heater - Less than 20 KW	1st Floor 1st Floor	1	EA EA	5 5	6-10 years 6-10 years	Serves addition Serves addition (kitchen), located in a closet, previously not assessed,
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	4,548	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	4,548	SF	6	10+ years	1993 installation
	Sanitary Piping	Entire Building	4,548	SF	6	10+ years	
	Storm Piping	Entire Building	4,548	SF	6	10+ years	
	Vent Piping	Entire Building	4,548	SF	6	10+ years	
	ry : Room		В	uilding	: Addition	on	
Catego	.,					Recommend	
_							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group		Location Kitchen Manager's Office	Quantity 75	UOM SF	Rank		Comments

Campus Name: Corkery Page : 27 of 32 Assessment Date: 01/24/2022



Ceiling - Lay-in	<u> </u>	oro o raidaro reverence, oriioago,		Additio	uilding :	В		y : Room	Catego
Ceiling - Lay-in Kitchen Manager's Office 1					_				
Doors - Steel Doors incl hw Kitchen Manager's Office		Comments		Rank		Quantity			Group
Floor - Tile		Damaged tiles	0-1 year	5	SF	6	Kitchen Manager's Office		
Lighting - Lay-in Kitchen Manager's Office 2			10+ years	6	EA	1	Kitchen Manager's Office	Doors - Steel Doors incl hw	
Power Distribution Kitchen Manager's Office 4			10+ years	6	SF	81	Kitchen Manager's Office	Floor - Tile	
Kitchen Kitchen Manager's Office 109 SF 6 10+ years Kitchen Ceiling - Lay-in 1st Floor 559 SF 6 10+ years Ceiling - Lay-in 1st Floor 6 SF 5 0-1 year Damaged tiles Doors - Steel Doors incl hw 1st Floor 1 EA 6 10+ years Floor - Tile/Sheet 1st Floor 559 SF 7 10+ years Lighting - Lay-in 1st Floor 8 EA 7 6-10 years Storage/ Closet 1st Floor 38 SF 7 10+ years Walls - Concrete Block 1st Floor 726 SF 6 10+ years Lunch & Multipurpose Room 2,648 SF 6 10+ years Poors - Steel Doors incl hw 1st Floor 2,648 SF 6 10+ years Floor - Tile 1st Floor 2,623 SF 6 10+ years Floor - Tile 1st Floor 25 SF 5 0			6-10 years	7	EA	2	Kitchen Manager's Office	Lighting - Lay-in	
Ceiling - Lay-in			6-10 years	6	EA	4	Kitchen Manager's Office	Power Distribution	
Ceiling - Lay-in 1st Floor 559 SF 6 10+ years Ceiling - Lay-in 1st Floor 6 SF 5 0-1 year Damaged tiles Doors - Steel Doors incl hw 1st Floor 1 EA 6 10+ years Floor - Tile/Sheet 1st Floor 559 SF 7 10+ years Lighting - Lay-in 1st Floor 8 EA 7 6-10 years Storage/ Closet 1st Floor 38 SF 7 10+ years Walls - Concrete Block 1st Floor 726 SF 6 10+ years Lunch & Multipurpose Room 2,648 SF 6 10+ years Loors - Steel Doors incl hw 1st Floor 2,648 SF 6 10+ years Floor - Tile 1st Floor 2,623 SF 6 10+ years Floor - Tile 1st Floor 25 SF 5 0-1 year Lighting - Metal Halide/Sodium Vapor 1st Floor 9 EA 6 6-10 years Walls - Concrete Block 1st Floor 2,581 SF 6<				6	SF	109		Walls - Concrete Block	
Ceiling - Lay-in 1st Floor 6 SF 5 0-1 year Damaged tiles Doors - Steel Doors incl hw 1st Floor 1 EA 6 10+ years 10+ years Floor - Tile/Sheet 1st Floor 559 SF 7 10+ years 10+ years Lighting - Lay-in 1st Floor 8 EA 7 6-10 years 550 SF 7 10+ years Storage/ Closet 1st Floor 38 SF 7 10+ years 10+ years Walls - Concrete Block 1st Floor 726 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 2,648 SF 6 10+ years Floor - Tile 1st Floor 2,623 SF 6 10+ years Floor - Tile 1st Floor 2,623 SF 6 10+ years Floor - Tile 1st Floor 25 SF 5 0-1 year Lighting - Metal Halide/Sodium Vapor 1st Floor 9 EA 6 6-10 years Walls - Concrete Block 1st Floor 2,581 SF 6 10+ years									Kitchen
Ceiling - Lay-in 1st Floor 6 SF 5 0-1 year Damaged tiles Doors - Steel Doors incl hw 1st Floor 1 EA 6 10+ years 1			10+ years	6	SF	559	1st Floor	Ceiling - Lay-in	
Doors - Steel Doors incl hw		Damaged tiles		5	SF	6	1st Floor	Ceiling - Lay-in	
Lighting - Lay-in 1st Floor 8 EA 7 6-10 years Storage/ Closet 1st Floor 38 SF 7 10+ years Walls - Concrete Block 1st Floor 726 SF 6 10+ years Lunch & Multipurpose Room Ceiling - Exposed 1st Floor 2,648 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Tile 1st Floor 2,623 SF 6 10+ years Floor - Tile 1st Floor 25 SF 5 0-1 year Lighting - Metal Halide/Sodium Vapor 1st Floor 9 EA 6 6-10 years Walls - Concrete Block 1st Floor 2,581 SF 6 10+ years		•	-	6	EA	1	1st Floor		
Lighting - Lay-in 1st Floor 8 EA 7 6-10 years Storage/ Closet 1st Floor 38 SF 7 10+ years Walls - Concrete Block 1st Floor 726 SF 6 10+ years Lunch & Multipurpose Room Ceiling - Exposed 1st Floor 2,648 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Tile 1st Floor 2,623 SF 6 10+ years Floor - Tile 1st Floor 25 SF 5 0-1 year Lighting - Metal Halide/Sodium Vapor 1st Floor 9 EA 6 6-10 years Walls - Concrete Block 1st Floor 2,581 SF 6 10+ years			10+ years	7	SF	559	1st Floor	Floor - Tile/Sheet	
Storage/ Closet 1st Floor 38 SF 7 10+ years Walls - Concrete Block 1st Floor 726 SF 6 10+ years Lunch & Multipurpose Room 2,648 SF 6 10+ years Ceiling - Exposed 1st Floor 4 EA 6 10+ years Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Tile 1st Floor 2,623 SF 6 10+ years Floor - Tile 1st Floor 25 SF 5 0-1 year Lighting - Metal Halide/Sodium Vapor 1st Floor 9 EA 6 6-10 years Walls - Concrete Block 1st Floor 2,581 SF 6 10+ years				7	EA		1st Floor	Lighting - Lay-in	
Walls - Concrete Block 1st Floor 726 SF 6 10+ years Lunch & Multipurpose Room Ceiling - Exposed 1st Floor 2,648 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Tile 1st Floor 2,623 SF 6 10+ years Floor - Tile 1st Floor 25 SF 5 0-1 year Lighting - Metal Halide/Sodium Vapor 1st Floor 9 EA 6 6-10 years Walls - Concrete Block 1st Floor 2,581 SF 6 10+ years						38			
Ceiling - Exposed 1st Floor 2,648 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Tile 1st Floor 2,623 SF 6 10+ years Floor - Tile 1st Floor 25 SF 5 0-1 year Lighting - Metal Halide/Sodium Vapor 1st Floor 9 EA 6 6-10 years Walls - Concrete Block 1st Floor 2,581 SF 6 10+ years				6	SF	726	1st Floor		
Ceiling - Exposed 1st Floor 2,648 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Tile 1st Floor 2,623 SF 6 10+ years Floor - Tile 1st Floor 25 SF 5 0-1 year Lighting - Metal Halide/Sodium Vapor 1st Floor 9 EA 6 6-10 years Walls - Concrete Block 1st Floor 2,581 SF 6 10+ years								Multipurpose Room	Lunch &
Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Tile 1st Floor 2,623 SF 6 10+ years Floor - Tile 1st Floor 25 SF 5 0-1 year Lighting - Metal Halide/Sodium Vapor 1st Floor 9 EA 6 6-10 years Walls - Concrete Block 1st Floor 2,581 SF 6 10+ years			10+ years	6	SF	2 648	1st Floor	·	
Floor - Tile 1st Floor 2,623 SF 6 10+ years Floor - Tile 1st Floor 25 SF 5 0-1 year Lighting - Metal Halide/Sodium Vapor 1st Floor 9 EA 6 6-10 years Walls - Concrete Block 1st Floor 2,581 SF 6 10+ years									
Floor - Tile 1st Floor 25 SF 5 0-1 year Lighting - Metal Halide/Sodium Vapor 1st Floor 9 EA 6 6-10 years Walls - Concrete Block 1st Floor 2,581 SF 6 10+ years			•			-			
Lighting - Metal Halide/Sodium Vapor 1st Floor 9 EA 6 6-10 years Walls - Concrete Block 1st Floor 2,581 SF 6 10+ years			,	-					
Walls - Concrete Block 1st Floor 2,581 SF 6 10+ years				-					
, , , , , , , , , , , , , , , , , , ,			•	-					
Walls - Masonry 1st Floor 860 SF 6 10+ years			10+ years	6	SF	860	1st Floor	Walls - Masonry	
Ceiling - Exposed Servery 399 SF 6 10+ years			•	-					
Doors - Steel Doors incl hw Servery 4 EA 6 10+ years				-	_				
Floor - Tile Servery 399 SF 6 10+ years			•	-		-			
Lighting - Lay-in Servery 6 EA 6 6-10 years				-					
Serving Line Servery 12 LF 6 10+ years				-			,		
Walls - Concrete Block Servery 498 SF 6 10+ years			•	-			•		
Restroom									Restroon
Accessories In the Kitchen Area 81 SF 7 6-10 years			6-10 years	7	SF	81	In the Kitchen Area		1.0000000
Ceiling - Lay-in In the Kitchen Area 81 SF 6 10+ years			•						
Doors - Steel Doors incl hw In the Kitchen Area 2 EA 6 10+ years				-				Doors - Steel Doors incl hw	
Floor - Tile In the Kitchen Area 81 SF 6 10+ years			,						
Floor Drain In the Kitchen Area 2 EA 7 10+ years				-					
Lavatory In the Kitchen Area 1 EA 6 10+ years			•						
Lighting - Lay-in In the Kitchen Area 2 EA 7 6-10 years				_					
Walls - Concrete Block In the Kitchen Area 2 EA 7 6-10 years Walls - Concrete Block In the Kitchen Area 105 SF 6 10+ years									
,			•	-					
Water Closet In the Kitchen Area 1 EA 6 10+ years			10+ years	U	EA	Į	III IIIE NIIGIIEII AIEd	Water Cluser	

Campus Name: Corkery Page : 28 of 32 Assessment Date: 01/24/2022



Catego	ry : Interior		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	401	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	401	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	5	EΑ	6	6-10 years	
	Walls - Concrete Block	1st Floor	988	SF	6	10+ years	
Safety							
•	Security Cameras	Entire Building	2	EA	7	6-10 years	
	Security Cameras	Entire Building	4	EA	7	6-10 years	

Campus Name: Corkery Page : 29 of 32 Assessment Date: 01/24/2022



Category : Site Building : Site

atego	ry . Site			unung	. Oite		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ivil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	10	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	11	EA	6	10+ years	
encing							
	Fencing - Chain Link	Entire Site	20	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,549	LF	6	10+ years	
	•					•	
andsca	pe						
	Benches	Entire Site	3	EA	7	10+ years	
	Landscape - Grass	Entire Site	16,796	SF	6	10+ years	
	Landscape - Grass	Entire Site	2,208	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	1,690	SF	7	10+ years	Southwest corner of site
	Landscape - Hardscape- Concrete	Entire Site	7,913	SF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	15	ĒΑ	6	6-10 years	2 Broken heads/fixtures
	Parkway trees	Entire Site	31	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	3,030	SF	6	10+ years	
	Play Area - Hardscape- Concrete	Entire Site	10,081	SF	6	10+ years	Item type - "Changed"
	Play Area - Hardscape- Concrete	Entire Site	5,896	SF	6	10+ years	Item Type - "Changed"
	Play Area - Synthetic Turf	Entire Site	10,900	SF	7	10+ years	,,
	Trash Receptacles	Entire Site	,	EA	7	10+ years	
	Walking Path - Hardscape- Asphalt	Entire Site	1,994	SF	6	10+ years	Asset type - "Changed"
arking							
	Concrete Curbs	Parking Lot- North	498	LF	6	6-10 years	
	Lighting - Pole Mounted	Parking Lot- North	3	EA	7	10+ years	0 1 1/5 1
	Surface - Asphalt	Parking Lot- North	1,841	SF	4	1-2 years	Cracked/Broken and aspha
	Cumfana Annhalt	Dayling Lat North	40.770	C.E.	4	0.5.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	deterioration
	Surface - Asphalt	Parking Lot- North	12,772	SF	4	2-5 years	Cracked/Broken
	Trash Compactor	Parking Lot- North	1 400	EA	6	10+ years	
	Trash Enclosure - Chain Links	Parking Lot- North	1,429	SF	6	10+ years	
	Vehicular Screening	Parking Lot- North	188	LF	6	10+ years	
aygrou	ınd						
, 5	Equipment - Pre K 3-5	North	5	EA	7	6-10 years	
	Surface - Poured Surface	North	975	SF	7	10+ years	
	Equipment - Combo 3-12	South	1	ĒΑ	7	10+ years	
	Surface - Poured Surface	South	2,172	SF	7	10+ years	
dewalk	Sidewalks - Internal Walks	Entire Site	83	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	83	LF	6	10+ vears	



Categoi	ry : Site						
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Internal Walks	Entire Site	30	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	12,658	SF	6	10+ years	
Signage							
0 0	Flag Pole - Flag Pole	Southwest, South and East Facade	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Southwest, South and East Facade	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter	Southwest, South and East Facade	1	EA	6	10+ years	
	Sign						
	Monument - Building Mounted Cut Letter Sign	Southwest, South and East Facade	1	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Corkery Page: 31 of 32 Assessment Date: 01/24/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classroom Summary			_	Floor Plan	_	Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Regular Classroom	2nd Floor	201	201	820	180	90	N	N
Computer Lab	Regular Classroom	Basement	007	007	756	270	120	N	N
Kindergarten	Regular Classroom	Basement	003	003	756	270	120	N	N
Library	Regular Classroom	2nd Floor	202	202	820	150	60	N	N
Library	Regular Classroom	2nd Floor	204	204	820	150	60	N	N
Pre School	Regular Classroom	Basement	001	001	844	270	120	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	820	300	150	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	820	150	60	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	820	300	150	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	820	180	90	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	820	300	150	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	820	180	90	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	820	300	150	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	820	180	90	N	N
Regular Classroom	Regular Classroom	1st Floor	109	109	820	300	150	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	820	180	90	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	820	300	150	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	820	180	90	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	820	180	90	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	820	180	90	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	820	180	90	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	820	300	150	N	N
Regular Classroom	Regular Classroom	3rd Floor	300	300	820	150	60	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	301	820	300	150	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	820	120	45	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	820	300	150	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	820	180	90	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	820	300	150	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	820	180	90	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	820	300	150	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	820	180	90	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	820	300	150	N	N
Special Program	Regular Classroom	1st Floor	100	100	780	120	45	N	N
Vacant	Kindergarten	1st Floor	002	002	844	270	120	N	N