

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1996	3	73,350
Campus Total			73,350

Category : Exterior Building : Main

	.y . =xterie.					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance			•			<u>-</u>	
	Exterior Doors - Side lite	#1 E	1	EA	6	6-10 years	
	Exterior Doors - Store Front	#1 E	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 E	3	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#10 W	2	EA	6	6-10 years	Paint.
	Exterior Doors - Exterior Steel Door	#11 S	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#12 S	1	EA	6	6-10 years	
	Entrance Control - Audio and Video	#2 E	1	EA	5	6-10 years	Buzzer works,i¿¼ Electric signal to the door is not working
	Exterior Doors - Side lite	#2 E	1	EA	6	6-10 years	3
	Exterior Doors - Store Front	#2 E	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#2 E	3	EA	6	6-10 years	
	Power Door Operator and Controls	#2 E	2	EA	7	6-10 years	
	Exterior Doors - Side lite	#3 E	1	EA	6	6-10 years	
	Exterior Doors - Store Front	#3 E	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#3 E	3	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#4 N	1	EA	5	0-1 year	Door and frame are rusting.
	Exterior Doors - Exterior Steel Door	#5 W	1	EA	6	6-10 years	-
	Exterior Doors - Exterior Steel Door	#6 Exit W	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#7 Exit W	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#8 W	2	EA	5	0-1 year	Doors and frame are rusting.
	Exterior Doors - Transom Lite	#8 W	1	EA	5	0-1 year	Rusting.
	Exterior Stairs - Concrete	#8 W	10	LF	5	0-1 year	Large cracks in the landing
	Stair Handrail - Steel_Stair Handrail	#8 W	20	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#9 W	2	EA	6	6-10 years	Paint required.



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ramp Handrail - Steel_Ramp Handrail	#9 W	42	LF	6	6-10 years	Paint required.
	Ramps - Concrete	#9 W	11	LF	6	10+ years	
	Ramps - Concrete	#9 W	10	LF	5	0-1 year	Cracks in the ramp
	Exterior Doors - Exterior Steel Door	Lower Roofs	2	EA	6	6-10 years	
Foundati	ion						
	Foundation - Concrete	Entire Building	851	LF	6	10+ years	Hairline cracks in concrete foundation
	Superstructure - Steel	Entire Building	28,055	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	26	EA	6	6-10 years	
Roof Sys							
	Coping - Stone	East Low Roof	117	LF	6	10+ years	
	Downspouts - Interior Downspouts	East Low Roof	120	LF	6	6-10 years	
	Parapet - Parapet > 30"	East Low Roof	117	LF	6	10+ years	
	Roof - Modified Bitumen	East Low Roof	1,276	SF	5	0-1 year	Cracking.
	Roof Structure - Steel / Metal Deck/ Concrete Topping	East Low Roof	1,276	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	Ladder and hatch are in good shape and usable
	Access Ladder - Metal	Main Roof	1	EA	7	6-10 years	and dadbie
	Chimney - Metal Flue	Main Roof	16	LF	6	0-1 year	Very rusted Chimneys
	Coping - Stone	Main Roof	705	LF	6	10+ years	very rusted orinings
	Downspouts - Interior Downspouts	Main Roof	390	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Main Roof	705	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	22,066	SF	5	0-1 year	Bubbling, cracking, and ponding
						•	spots throughout.
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	Ladder and hatch are in good shape and usable
	Roof Hatch - Metal	Main Roof	1	EA	7	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	22,066	SF	7	10+ years	
	Coping - Stone	South Low Roof	206	LF	6	10+ years	
	Downspouts - Interior Downspouts	South Low Roof	120	LF	6	6-10 years	
	Parapet - Parapet > 30"	South Low Roof	206	LF	6	10+ years	
	Roof - Modified Bitumen	South Low Roof	4,854	SF	5	0-1 year	Bubbling and cracking throughout.
	Roof Structure - Steel / Metal Deck/ Concrete Topping	South Low Roof	4,854	SF	7	10+ years	
Malla	-						
Valls	Canopy - Concrete/ Stucco	Entire Building	628	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	25,046	SF	6	10+ years	



Main Service

Richard J Daley Elementary Academy

Quantity changed to match current

ALL M	Schools					50	024 S Wolcott AVENUE, Chicago, IL 606
Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Stone-Cast	Entire Building	5,936	SF	5	10+ years	
Vindows	3						
	Curtain wall - Glazed Double Pane	Entire Building	416	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	65	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	2,499	SF	7	10+ years	
	Lintels - Steel	Entire Building	1,019	LF	7	10+ years	
	Windows - Decorative	Entire Building	360	SF	6	10+ years	
atego	ry : Electrical		В	uilding	: Main		
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Exit Signs - Corridors and Stairs	1st floor, Entire Building	30	EA	4	0-1 year	Lettering worn throughout.
	Exit Signs - Gym	1st floor, Entire Building	3	EA	4	0-1 year	Gym has three egress doors. Exit Sign quantity changed to match current observations. Older signs with cages bent.
	Exit Signs - Lunchroom	1st floor, Entire Building	4	EΑ	6	6-10 years	
	Exit Signs - Multipurpose Room	1st floor, Entire Building	3	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	1st floor, Entire Building	9,721	SF	6	10+ years	
	Emergency A/C Power - Gym	1st floor, Entire Building	3,860	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	1st floor, Entire Building	3,389	SF	6	10+ years	
	Emergency A/C Power - Multipurpose Room	1st floor, Entire Building	2,042	SF	6	10+ years	
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	Serves second feed.
	Security System - CCTV	Entire Building	73,350	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	73,350	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	15	EA	6	6-10 years	

Electrical Room Main Electrical Service - 2000 A 277/480/3PH

Lighting and Power Panels - Above 100 A

Independent Electrical Service for Electrical Room 2 EΑ 6 10+ years Quantity changed to match current emergency power observations 73,350 PA System **Entire Building** SF 5 6-10 years Power Distribution Lighting and Power Panels - 100 A Electrical Room, Entire Building Item Type and location changed to 2 EΑ 7 10+ years match current observations.

1

16

EΑ

EΑ

6

7

10+ years

10+ years

Campus Name: Daley Page: 3 of 32 Assessment Date: 11/03/2021

Electrical Room, Entire Building



Catego	ry : Electrical		R	uilding	· Main		024 S Wolcott AVENUE, Chicago, IL 60609
Calego	ry . Liectricai			ununig	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Croup	Rom Typo	Location	Quantity	OOM	Runn	rtopiacomont	observations
	Main Distribution Panels - 400 - 600 amp	Electrical Room, Entire Building	1	EA	7	10+ years	Five-section motor control center. Located in the 3rd Floor Mechanical Room.
	Main Distribution Panels - Greater than 600 amp	Electrical Room, Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - Less than 400 amp	Electrical Room, Entire Building	1	EA	7	10+ years	Located in the 3rd Floor Mechanical Room
	Main Distribution Panels - Less than 400 amp	Electrical Room, Entire Building	1	EA	7	10+ years	Located in the 1st Floor Mechanical Room
	Transformers - 277/480 - 120/208	Electrical Room, Entire Building	3	EA	7	10+ years	Quantity changed to match current observations
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Electrical Room	1	EA	3	0-1 year	Fire panel went down last week and repairs are forthcoming.
	Fire Alarm Strobe Lights	Electrical Room	73,350	SF	6	10+ years	
	Fire Alarm_System	Electrical Room	73,350	SF	6	10+ years	
	Fire Pump Controller	Electrical Room	1	EA	6	10+ years	
Pump Ro	pom Assembly						
·	Fire Pump - 25-50 hp	Pump Room	1	EA	6	10+ years	Leak-free with evidence of corrosion from past leaks.
	Jockey Pump	Pump Room	1	EA	6	10+ years	•
Sprinklei	System						
•	Sprinkler Heads	Entire Building	73,350	SF	7	10+ years	
	Sprinkler Piping	Entire Building	73,350	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	73,350	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	· ·						
	Chemical Pot Feeder	Roof	1	EA	6	10+ years	
	Chiller-Air Cooled-Screw Type-Roof Mounted - 201 - 300 tons	Roof	1	EA	7	6-10 years	Installed in 2018.
	Pipes - Chilled Water Pipe- Copper	Roof	200	LF	6	10+ years	



Catego	ry : Mechanical		В	uilding	: Main		024 6 Wolcott AVENOE, Officago, IE 00005
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Hand	ling Systems						
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	1st Floor	1	EA	5	6-10 years	Designated ER-2. Serves 1st Floor. Fully operational but running loud; new motor received and awaiting replacement.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	1st Floor	1	EA	5	6-10 years	AHU-2 serves 1st Floor.
	Air Intake	1st Floor	1	EA	6	10+ years	
	VAV Box	1st Floor	25	EA	6	10+ years	
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	3rd Floor	1	EA	6	10+ years	Designated ER-1. Serves 2nd and 3rd Floors.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	3rd Floor	1	EA	5	6-10 years	AHU-1, serve 2nd and 3rd Floors.
	Air Intake	3rd Floor	1	EA	6	10+ years	
	VAV Box	3rd Floor	40	EA	6	10+ years	
	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 11 - 20 tons	Lower Roof	1	EA	5	2-5 years	AHU-3, serves gym. Well maintained and fully operational but approaching the end of its EUL.
Boiler Sy	stems						
	Boiler Auxiliary- Non Condensing Hot Water - 3001 - 4000 MBH	Boiler Room	2	EA	6	6-10 years	No major repairs needed per Building Engineer and no history of major repairs. Rank adjusted based on current observations.
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 3001 - 4000 MBH	Boiler Room	2	EA	6	6-10 years	No major repairs needed per Building Engineer and no history of major repairs. Rank adjusted based on current observations.
	Water Fill System	Boiler Room	1	EA	6	10+ years	
Heating	Devices						
	Cabinet Heaters - With Hot Water Coil	1st Floor	7	EA	6	10+ years	Quantity changed to match current observations. Equipped with integral controls.
	Unit Heater - Hot Water	Entire Building	1	EA	6	10+ years	Controlled by a wall-mounted electric thermostat.
	Unit Heater - Hot Water	Entire Building	6	EA	6	10+ years	Quantity changed to match current observations and per Building Engineer. Provided with bracketmounted electric thermostats.

Campus Name: Daley Page : 5 of 32 Assessment Date: 11/03/2021



Catego	ry : Mechanical		B	uilding	: Main		
	_				_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Wall Heater - Electric	Entire Building	6	EA	6	10+ years	Equipped with integral controls.
	Radiator Panels - Hot Water	Entire Building	13	EA	7	6-10 years	Equipped with integral controls.
Mechani	cal Plumbing						
	Chilled Water Pump - 10 - 20 HP	Boiler Room	2	EA	5	6-10 years	P-1 and P-2.
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	P-10. Located in 1st Floor Mechanical Room for AHU-2.
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	P-9. Located in Boiler Room for AHU-1.
	Hot Water Pump - Less than 10	Boiler Room	2	EA	6	6-10 years	P-3 and P-4.
	Hot Water Pump - Less than 10	Boiler Room	4	EA	5	6-10 years	P-5, P-6, P-7 and P-8. Quantity
			·		-	,	changed as total has been divided/aggregated.
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	10+ years	00 0
Tempera	ature Control						
	DDC System	Entire Building	73,350	SF	4	1-2 years	Original to the building and still functional but nearing the end of its EUL.
	Electric Thermostat	Entire Building	1	EA	6	10+ years	Controls the Electrical Room unit heater (only the seven hot water unit heaters in this school have electric thermostats). Quantity changed to match current observations.
	Electric Thermostat	Entire Building	6	EA	6	10+ years	Attached to hot water unit heater mounting brackets. Used for controlling the six hot water unit heaters that are not provided with a wall-mounted electric thermostat.
	Thermostats - DDC	Entire Building	66	EA	6	10+ years	Temperature sensors and manually- adjustable thermostats are both present throughout the building.
Ventilatio							
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	7	EA	6	10+ years	Quantity changed to match current observations
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	10+ years	
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments



						Replacement	
Hot Wate	er						
	Electric Heater - Less than 20 KW	1st Floor	1	EA	5	6-10 years	Installed in 2016
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EΑ	6	6-10 years	Manufactured in 2004.
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	5	2-5 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	73,350	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	73,350	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	73,350	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	73,350	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	73,350	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	73,350	SF	6	10+ years	
	Sanitary Piping	Entire Building	73,350	SF	6	10+ years	
	Storm Piping	Entire Building	73,350	SF	6	10+ years	
	Vent Piping	Entire Building	73,350	SF	6	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	1st Floor	1	EA	6	10+ years	
	Pumps - Domestic Booster Pump-Simplex	1st Floor	1	EA	6	10+ years	Serves the landscaping irrigation system.
	Pumps - Sump-Simplex	1st Floor	1	EA	6	10+ years	Bottom of elevator pit. Inaccessible at the time of assessment.

Category : Room **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	100A Gym Office	102	SF	6	10+ years	
	Doors - Side-lite	100A Gym Office	10	SF	6	10+ years	
	Doors - Steel Doors incl hw	100A Gym Office	1	EA	6	10+ years	
	Floor - Tile	100A Gym Office	102	SF	6	10+ years	
	Lighting - Lay-in	100A Gym Office	1	EA	6	6-10 years	
	Power Distribution	100A Gym Office	6	EA	7	10+ years	
	Walls - Concrete Block	100A Gym Office	362	SF	6	10+ years	
	Ceiling - Lay-in	102 Faculty Lounge	919	SF	6	10+ years	
	Doors - Side-lite	102 Faculty Lounge	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	102 Faculty Lounge	1	EA	6	10+ years	
	Floor - Carpet	102 Faculty Lounge	679	SF	6	6-10 years	
	Floor - Tile	102 Faculty Lounge	240	SF	6	10+ years	
	Lighting - Lay-in	102 Faculty Lounge	9	EA	6	6-10 years	
	Power Distribution	102 Faculty Lounge	16	EA	7	10+ years	

Campus Name: Daley Page: 7 of 32 Assessment Date: 11/03/2021



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	102 Faculty Lounge	514	SF	6	10+ years	
	Walls - Plaster/Drywall	102 Faculty Lounge	514	SF	6	10+ years	
	Work SInk	102 Faculty Lounge	1	EA	7	10+ years	
	Ceiling - Lay-in	103A Kitchen Manager Office	146	SF	6	10+ years	
	Doors - Side-lite	103A Kitchen Manager Office	16	SF	6	10+ years	
	Doors - Steel Doors incl hw	103A Kitchen Manager Office	1	EA	6	10+ years	
	Floor - Tile	103A Kitchen Manager Office	146	SF	6	10+ years	
	Lighting - Lay-in	103A Kitchen Manager Office	1	EA	6	6-10 years	
	Power Distribution	103A Kitchen Manager Office	6	EA	7	10+ years	
	Walls - Concrete Block	103A Kitchen Manager Office	431	SF	6	10+ years	
	Ceiling - Lay-in	104 Administration	586	SF	6	10+ years	
	Doors - Wood Doors inclu hw	104 Administration	1	EA	6	10+ years	
	Floor - Carpet	104 Administration	384	SF	6	6-10 years	
	Floor - Tile	104 Administration	202	SF	6	10+ years	
	Lighting - Lay-in	104 Administration	6	EA	6	6-10 years	
	Power Distribution	104 Administration	14	EA	7	10+ years	
	Walls - Concrete Block	104 Administration	199	SF	6	10+ years	
	Walls - Metal Panel	104 Administration	317	SF	6	10+ years	
	Walls - Plaster/Drywall	104 Administration	313	SF	6	10+ years	
	Ceiling - Lay-in	104A Counselor's Office	164	SF	6	10+ years	
	Doors - Wood Doors inclu hw	104A Counselor's Office	1	EA	6	10+ years	
	Floor - Carpet	104A Counselor's Office	164	SF	6	6-10 years	
	Lighting - Lay-in	104A Counselor's Office	2	EΑ	6	6-10 years	
	Power Distribution	104A Counselor's Office	8	EA	7	10+ years	
	Walls - Concrete Block	104A Counselor's Office	221	SF	6	10+ years	
	Walls - Plaster/Drywall	104A Counselor's Office	237	SF	6	10+ years	
	Ceiling - Lay-in	104B Student Services (Use as	161	SF	6	10+ years	
	3	Copy Room)				,	
	Doors - Side-lite	104B Student Services (Use as	10	SF	6	10+ years	
		Copy Room)				, , , , ,	
	Doors - Wood Doors inclu hw	104B Student Services (Use as	1	EA	6	10+ years	
		Copy Room)				, , , , ,	
	Floor - Carpet	104B Student Services (Use as	161	SF	6	6-10 years	
		Copy Room)			•	- · · · · · · · · · · · · · · · · · · ·	
	Lighting - Lay-in	104B Student Services (Use as	2	EA	6	6-10 years	
	gg,	Copy Room)	_		•	- · · · · · · · · · · · · · · · · · · ·	
	Power Distribution	104B Student Services (Use as	8	EA	7	10+ years	
		Copy Room)	· ·		•	,	
	Walls - Concrete Block	104B Student Services (Use as	208	SF	6	10+ years	
		Copy Room)	_30	٥.	ū	,	
	Walls - Plaster/Drywall	104B Student Services (Use as	243	SF	6	10+ years	
		Copy Room)	2 10	٥.	Ū	,	
	Work SInk	104B Student Services (Use as	1	EA	7	10+ years	
		Copy Room)	·	_, .	•	,	
		- ap,					



Category : Room			Building : Main							
_				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Ceiling - Lay-in	104C Conference Room	198	SF	6	10+ years				
	Doors - Wood Doors inclu hw	104C Conference Room	1	EA	6	10+ years				
	Floor - Carpet	104C Conference Room	198	SF	6	6-10 years				
	Lighting - Lay-in	104C Conference Room	3	EA	6	6-10 years				
	Power Distribution	104C Conference Room	6	EA	7	10+ years				
	Walls - Concrete Block	104C Conference Room	101	SF	6	10+ years				
	Walls - Plaster/Drywall	104C Conference Room	352	SF	6	10+ years				
	Ceiling - Lay-in	104D Principal's Office	284	SF	6	10+ years				
	Doors - Wood Doors inclu hw	104D Principal's Office	1	EA	6	10+ years				
	Floor - Carpet	104D Principal's Office	284	SF	6	6-10 years				
	Lighting - Lay-in	104D Principal's Office	4	EA	6	6-10 years				
	Power Distribution	104D Principal's Office	6	EA	7	10+ years				
	Walls - Concrete Block	104D Principal's Office	280	SF	6	10+ years				
	Walls - Plaster/Drywall	104D Principal's Office	280	SF	6	10+ years				
	Ceiling - Lay-in	104E Assistant Principal's Office	159	SF	6	10+ years				
	Doors - Wood Doors inclu hw	104E Assistant Principal's Office	1	EA	6	10+ years				
	Floor - Carpet	104E Assistant Principal's Office	159	SF	6	6-10 years				
	Lighting - Lay-in	104E Assistant Principal's Office	2	EA	6	6-10 years				
	Power Distribution	104E Assistant Principal's Office	6	EA	7	10+ years				
	Walls - Concrete Block	104E Assistant Principal's Office	219	SF	6	10+ years				
	Walls - Plaster/Drywall	104E Assistant Principal's Office	219	SF	6	10+ years				
	Ceiling - Lay-in	107B Office in Multipurpose Room	108	SF	6	10+ years				
	Doors - Wood Doors inclu hw	107B Office in Multipurpose Room	1	EA	6	10+ years				
	Floor - Tile	107B Office in Multipurpose Room	108	SF	6	10+ years				
	Lighting - Lay-in	107B Office in Multipurpose Room	1	EA	6	6-10 years				
	Power Distribution	107B Office in Multipurpose Room	8	EA	7	10+ years				
	Walls - Plaster/Drywall	107B Office in Multipurpose Room	381	SF	6	10+ years				
	Ceiling - Lay-in	107C Office in Multipurpose Room	108	SF	6	10+ years				
	Doors - Side-lite	107C Office in Multipurpose Room	10	SF	6	10+ years				
	Doors - Wood Doors inclu hw	107C Office in Multipurpose Room	1	EA	6	10+ years				
	Floor - Tile	107C Office in Multipurpose Room	108	SF	6	10+ years				
	Lighting - Lay-in	107C Office in Multipurpose Room	1	EΑ	6	6-10 years				
	Power Distribution	107C Office in Multipurpose Room	8	EA	7	10+ years				
	Walls - Plaster/Drywall	107C Office in Multipurpose Room	381	SF SF	6	10+ years				
	Ceiling - Lay-in	107D Office in Multipurpose Room	108		6	10+ years				
	Doors - Wood Doors inclu hw	107D Office in Multipurpose Room	1	EA SF	6	10+ years				
	Floor - Tile	107D Office in Multipurpose Room	108		6	10+ years				
	Lighting - Lay-in	107D Office in Multipurpose Room	1	EΑ	6	6-10 years				
	Power Distribution	107D Office in Multipurpose Room	8	EA SF	7	10+ years				
	Walls - Concrete Block	107D Office in Multipurpose Room	102		6	10+ years				
	Walls - Plaster/Drywall	107D Office in Multipurpose Room	298	SF	6	10+ years				
	Ceiling - Lay-in Doors - Wood Doors inclu hw	308A Workroom	150	SF	6	10+ years				
		308A Workroom	1	EA SF	6 6	10+ years				
	Floor - Tile	308A Workroom	150	3 F	ъ	10+ years				



Catego	ry : Room		В	uilding	: Main		. 5 :
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	308A Workroom	2	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	308A Workroom	460	SF	6	10+ years	
	Ceiling - Exposed	Counselor	90	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Counselor	1	EΑ	7	10+ years	
	Floor - Tile	Counselor	90	SF	6	6-10 years	
	Lighting - Lay-in	Counselor	2	EA	7	10+ years	
	Power Distribution	Counselor	1	EA	7	10+ years	
	Walls - Concrete Block	Counselor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	Counselor	260	SF	7	10+ years	
	Ceiling - Lay-in	Engineer's Office 1st Flr in	92	SF	6	10+ years	
		Receiving area			-	, , , , , , , , , , , , , , , , , , , ,	
	Doors - Side-lite	Engineer's Office 1st Flr in	10	SF	6	10+ years	
		Receiving area		-	-	, , , , , , , , , , , , , , , , , , , ,	
	Doors - Steel Doors incl hw	Engineer's Office 1st Flr in	1	EA	6	10+ years	
	Boold Gloci Boold Mornin	Receiving area	•	_, 、	Ū	ioi youro	
	Floor - Tile	Engineer's Office 1st Flr in	92	SF	6	10+ years	
	11001 1110	Receiving area	02	O.	Ū	101 youro	
	Lighting - Lay-in	Engineer's Office 1st Flr in	2	EA	6	6-10 years	
	Lighting - Lay-in	Receiving area	2	LA	U	0-10 years	
	Power Distribution	Engineer's Office 1st Flr in	6	EA	7	10+ years	
	1 Ower Distribution	Receiving area	U	LA	'	10+ years	
	Walls - Concrete Block	Engineer's Office 1st Flr in	344	SF	6	10+ years	
	Walls - Coliciete block	Receiving area	J -1-1	01	U	10+ years	
	Ceiling - Exposed	Lead Coach	90	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Lead Coach	1	EA	7	10+ years	
	Floor - Tile	Lead Coach	90	SF	6	6-10 years	
	Lighting - Pendent/Surface	Lead Coach	2	EA	7	6-10 years	
	Power Distribution	Lead Coach	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Lead Coach	380	SF	7	10+ years	
	Ceiling - Lay-in	Library Workroom 208A	169	SF	6	10+ years	
	Doors - Side-lite	Library Workroom 208A	109	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Library Workroom 208A	10	EA	6	•	
		Library Workroom 208A	169	SF	6	10+ years	
	Floor - Tile	Library Workroom 208A		EA	7	10+ years	
	Lighting - Lay-in Power Distribution	Library Workroom 208A	2 6	EA	7	6-10 years	
		Library Workroom 208A		SF	6	10+ years	
	Walls - Concrete Block		147 326	SF SF	6	10+ years	
	Walls - Plaster/Drywall	Library Workroom 208A		SF SF		10+ years	
	Ceiling - Exposed Doors - Wood Doors inclu hw	Nurse Nurse	90	SF EA	7 7	10+ years	
				SF		10+ years	
	Floor - Tile	Nurse	90		6	6-10 years	
	Lighting - Pendent/Surface	Nurse	2	EA	7	10+ years	
	Power Distribution	Nurse	1	EA	7	10+ years	
	Walls - Concrete Block	Nurse	120	SF	7	10+ years	
	Walls - Plaster/Drywall	Nurse	260	SF	7	10+ years	

Campus Name: Daley Page : 10 of 32 Assessment Date: 11/03/2021



Catego	ry : Room		Building : Main							
				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Ceiling - Exposed	Occupational Therapist	90	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Occupational Therapist	1	EA	7	10+ years				
	Floor - Tile	Occupational Therapist	90	SF	6	6-10 years				
	Lighting - Pendent/Surface	Occupational Therapist	2	EA	7	10+ years				
	Power Distribution	Occupational Therapist	1	EA	7	10+ years				
	Walls - Plaster/Drywall	Occupational Therapist	380	SF	7	10+ years				
	Ceiling - Exposed	Psychologist	90	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Psychologist	1	EA	7	6-10 years				
	Floor - Tile	Psychologist	90	SF	6	6-10 years				
	Lighting - Lay-in	Psychologist	1	EA	6	6-10 years				
	Power Distribution	Psychologist	1	EA	7	10+ years				
	Walls - Concrete Block	Psychologist	120	SF	7	10+ years				
	Walls - Plaster/Drywall	Psychologist	260	SF	7	10+ years				
	Ceiling - Exposed	Social Work intern	90	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Social Work intern	1	EA	7	10+ years				
	Floor - Tile	Social Work intern	90	SF	6	6-10 years				
	Lighting - Pendent/Surface	Social Work intern	2	EA	7	10+ years				
	Power Distribution	Social Work intern	1	EA	7	10+ years				
	Walls - Plaster/Drywall	Social Work intern	380	SF	7	10+ years				
	Ceiling - Exposed	Social Worker	90	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Social Worker	1	EA	7	10+ years				
	Floor - Tile	Social Worker	90	SF	6	6-10 years				
	Lighting - Pendent/Surface	Social Worker	2	EA	7	10+ years				
	Power Distribution	Social Worker	1	EA	7	10+ years				
	Walls - Concrete Block	Social Worker	120	SF	7	10+ years				
	Walls - Plaster/Drywall	Social Worker	260	SF	7	10+ years				
	Ceiling - Lay-in	Speech Office (Student Services 1st	161	SF	6	10+ years				
		Floor in General Office)								
	Doors - Side-lite	Speech Office (Student Services 1st	10	SF	6	10+ years				
		Floor in General Office)								
	Doors - Wood Doors inclu hw	Speech Office (Student Services 1st	1	EA	6	10+ years				
		Floor in General Office)								
	Floor - Carpet	Speech Office (Student Services 1st	161	SF	6	6-10 years				
		Floor in General Office)								
	Lighting - Lay-in	Speech Office (Student Services 1st	2	EA	6	6-10 years				
		Floor in General Office)								
	Power Distribution	Speech Office (Student Services 1st	8	EA	7	10+ years				
		Floor in General Office)				•				
	Walls - Concrete Block	Speech Office (Student Services 1st	208	SF	6	10+ years				
		Floor in General Office)								
	Walls - Plaster/Drywall	Speech Office (Student Services 1st	243	SF	6	10+ years				
		Floor in General Office)				•				
	Ceiling - Exposed	Teacher Office	90	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Teacher Office	1	EA	7	10+ years				
						•				

Campus Name: Daley Page : 11 of 32 Assessment Date: 11/03/2021



Category : Room		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Teacher Office	90	SF	6	6-10 years	
	Lighting - Pendent/Surface	Teacher Office	2	EΑ	7	10+ years	
	Power Distribution	Teacher Office	1	EA	7	10+ years	
	Walls - Concrete Block	Teacher Office	120	SF	7	10+ years	
	Walls - Plaster/Drywall	Teacher Office	260	SF	7	10+ years	
Gymnasi	a						
,	Bleacher Seating	100 Gymnasium	50	EA	6	10+ years	
	Ceiling - Exposed	100 Gymnasium	3,860	SF	6	10+ years	
	Doors - Steel Doors incl hw	100 Gymnasium	1	EA	6	10+ years	
	Floor - Sport Flooring	100 Gymnasium	3,860	SF	7	10+ years	
	Lighting - Pendent/Surface	100 Gymnasium	10	EA	6	6-10 years	
						•	
	Scoreboards	100 Gymnasium	1	EA SF	7	6-10 years	
	Storage/ Closet	100 Gymnasium	196		7	10+ years	
	Walls - Concrete Block	100 Gymnasium	7,090	SF	6	10+ years	
	Walls - Plaster/Drywall	100 Gymnasium	45	SF	6	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	1,284	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	1,284	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Serving Line	1st Floor	12	LF	6	10+ years	
	Storage/ Closet	1st Floor	84	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,375	SF	6	10+ years	
Library							
	Casework	2nd floor Room 208	143	LF	6	10+ years	
	Ceiling - Lay-in	2nd floor Room 208	1,284	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd floor Room 208	856	SF	6	10+ years	
	Doors - Side-lite	2nd floor Room 208	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor Room 208	2	EA	6	10+ years	
	Floor - Carpet	2nd floor Room 208	2,140	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd floor Room 208	20	EA	7	6-10 years	
	Walls - Concrete Block	2nd floor Room 208	1,415	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd floor Room 208	548	SF	6	10+ years	
Lunch 9	Multipurpose Room						
LUIICII X		105 Student Dining	2 200	SF	6	101.1/22/2	
	Ceiling - Lay-in	105 Student Dining	3,389		6	10+ years	
	Doors - Side-lite	105 Student Dining	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	105 Student Dining	3	EA	6	10+ years	
	llaan lila	105 Student Dining	2 200	C E	6	10 L VOORO	
	Floor - Tile Lighting - Lay-in	105 Student Dining 105 Student Dining	3,389 49	SF EA	6	10+ years 6-10 years	

Campus Name: Daley Page: 12 of 32 Assessment Date: 11/03/2021



Catego	ry : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Concrete Block	105 Student Dining	1,998	SF	6	10+ years			
	Walls - Plaster/Drywall	105 Student Dining	396	SF	6	10+ years			
	Ceiling - Lay-in	107 Multi-Purpose Room	2,042	SF	6	10+ years			
	Doors - Side-lite	107 Multi-Purpose Room	20	SF	6	10+ years			
	Doors - Wood Doors inclu hw	107 Multi-Purpose Room	2	EA	6	10+ years			
	Floor - Tile	107 Multi-Purpose Room	2,042	SF	6	10+ years			
	Lighting - Lay-in	107 Multi-Purpose Room	27	EA	6	6-10 years			
	Walls - Concrete Block	107 Multi-Purpose Room	1,527	SF	6	10+ years			
	Walls - Plaster/Drywall	107 Multi-Purpose Room	396	SF	6	10+ years			
MDF_ID	F								
	Doors - Wood Doors inclu hw	MDF	1	EA	7	10+ years			
	Finishes	MDF	256	SF	5	10+ years	Water damaged/missing ceiling tile.		
	Other Cooling Unit	MDF	1	EA	7	6-10 years			
Mechani	ical/ Service Rooms								
	Janitor's Closet	1st Floor	10	SF	5	10+ years	Flooring cracked/missing.		
	Loading Docks	1st Floor	488	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	105	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	260	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	769	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	44	SF	7	10+ years			
	Storage Room	1st Floor	89	SF	7	10+ years			
	Storage Room	1st Floor	158	SF	7	10+ years			
	Vaults	1st Floor	157	SF	7	10+ years			
	Janitor's Closet	2nd Floor	22	SF	5	10+ years	Flooring missing.		
	Mechanical/ Service Rooms	2nd Floor	44	SF	7	10+ years	3 3		
	Storage Room	2nd Floor	1,985	SF	7	10+ years			
	Boiler Room	3rd Floor	1,030	SF	7	10+ years			
	Janitor's Closet	3rd Floor	22	SF	7	10+ years			
	Mechanical/ Service Rooms	3rd Floor	1,050	SF	7	10+ years			
	Storage Room	3rd Floor	1,100	SF	7	10+ years			
Restroor	m								
	Accessories	1st Floor Boys Restroom - (Boys next to 100 Gym)	130	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor Boys Restroom - (Boys next to 100 Gym)	130	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor Boys Restroom - (Boys next to 100 Gym)	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys Restroom - (Boys next to 100 Gym)	130	SF	6	10+ years			
	Floor Drain	1st Floor Boys Restroom - (Boys	1	EA	7	10+ years			

Campus Name: Daley Page: 13 of 32 Assessment Date: 11/03/2021



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		next to 100 Gym)					
	Lavatory	1st Floor Boys Restroom - (Boys	2	EA	6	10+ years	
	Litalistic of Landin	next to 100 Gym)	0	_^	7	0.40	
	Lighting - Lay-in	1st Floor Boys Restroom - (Boys	2	EA	7	6-10 years	
	Partitions	next to 100 Gym) 1st Floor Boys Restroom - (Boys	1	EA	7	10+ years	
	Faititions	next to 100 Gym)	ı	EA	7	10+ years	
	Urinals	1st Floor Boys Restroom - (Boys	1	EA	6	10+ years	
	Officials	next to 100 Gym)		L/\	O	101 years	
	Walls - Concrete Block	1st Floor Boys Restroom - (Boys	280	SF	6	10+ years	
		next to 100 Gym)		٠.	•	. o . y ca. c	
	Walls - Tile Ceramic/ Porcelain	1st Floor Boys Restroom - (Boys	140	SF	6	10+ years	
		next to 100 Gym)				,	
	Water Closet	1st Floor Boys Restroom - (Boys	1	EA	6	10+ years	
		next to 100 Gym)				•	
	Accessories	1st Floor Girls Restroom (Girls	115	SF	7	6-10 years	
		across from 105)					
	Ceiling - Plaster/Drywall	1st Floor Girls Restroom (Girls	115	SF	6	10+ years	
		across from 105)					
	Doors - Wood Doors inclu hw	1st Floor Girls Restroom (Girls	1	EA	6	10+ years	
	EL T'' O ' / D L '	across from 105)	445	0.5	•	40	
	Floor - Tile Ceramic/ Porcelain	1st Floor Girls Restroom (Girls	115	SF	6	10+ years	
	Floor Drain	across from 105) 1st Floor Girls Restroom (Girls	1	EA	7	10	
	FIOOI DIAIN	across from 105)	1	EA	7	10+ years	
	Lavatory	1st Floor Girls Restroom (Girls	2	EA	6	10+ years	
	Lavatory	across from 105)	2	LA	U	10+ years	
	Lighting - Lay-in	1st Floor Girls Restroom (Girls	2	EA	6	6-10 years	
	Lighting Lay in	across from 105)	_	_, 、	Ü	o io youio	
	Partitions	1st Floor Girls Restroom (Girls	2	EA	7	10+ years	
		across from 105)				,	
	Walls - Concrete Block	1st Floor Girls Restroom (Girls	280	SF	6	10+ years	
		across from 105)					
	Walls - Tile Ceramic/ Porcelain	1st Floor Girls Restroom (Girls	140	SF	6	10+ years	
		across from 105)					
	Water Closet	1st Floor Girls Restroom (Girls	2	EA	6	10+ years	
		across from 105)					
	Accessories	1st Floor Men's Staff Locker Room	115	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Men's Staff Locker Room	115	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor Men's Staff Locker Room	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Men's Staff Locker Room	115	SF	6	10+ years	
	Floor Drain	1st Floor Men's Staff Locker Room 1st Floor Men's Staff Locker Room	2	EA EA	7	10+ years	
	Lavatory Lighting - Lay-in	1st Floor Men's Starr Locker Room 1st Floor Men's Staff Locker Room	1 3	EA EA	6 6	10+ years 6-10 years	
	Lighting - Lay-in	151 FIOOI WEITS STAIL LOCKEL KOOM	3	EA	Ö	o- to years	

Campus Name: Daley Page : 14 of 32 Assessment Date: 11/03/2021



Catego	Category : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	1st Floor Men's Staff Locker Room	1	EA	7	10+ years	
	Showers	1st Floor Men's Staff Locker Room	1	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor Men's Staff Locker Room	5	EA	6	10+ years	
	Walls - Concrete Block	1st Floor Men's Staff Locker Room	409	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Men's Staff Locker Room	142	SF	6	10+ years	
	Water Closet	1st Floor Men's Staff Locker Room	1	ĒA	6	10+ years	
	Accessories	1st Floor Women's Staff Locker	115	SF	7	6-10 years	
		Room					
	Benches	1st Floor Women's Staff Locker Room	3	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Women's Staff Locker	115	SF	6	10+ years	
		Room					
	Doors - Steel Doors incl hw	1st Floor Women's Staff Locker Room	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Women's Staff Locker Room	115	SF	6	10+ years	
	Floor Drain	1st Floor Women's Staff Locker Room	2	EA	7	10+ years	
	Lavatory	1st Floor Women's Staff Locker Room	1	EA	6	10+ years	
	Lighting - Lay-in	1st Floor Women's Staff Locker Room	3	EA	6	6-10 years	
	Partitions	1st Floor Women's Staff Locker Room	1	EA	7	10+ years	
	Showers	1st Floor Women's Staff Locker Room	1	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor Women's Staff Locker Room	5	EA	6	10+ years	
	Walls - Concrete Block	1st Floor Women's Staff Locker Room	409	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Women's Staff Locker Room	142	SF	6	10+ years	
	Water Closet	1st Floor Women's Staff Locker Room	1	EA	6	10+ years	
	Accessories	2nd fl Boys	531	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd fl Boys	531	SF	6	10+ years	Paint cracking.
	Floor - Tile Ceramic/ Porcelain					•	Paint Cracking.
		2nd fl Boys	531	SF	6	10+ years	
	Floor Drain	2nd fl Boys	3	EA	7	10+ years	
	Lavatory	2nd fl Boys	1	EA	6	10+ years	
	Lighting - Lay-in	2nd fl Boys	9	EA	7	6-10 years	
	Lighting - Lay-in	2nd fl Boys	8	EA	7	6-10 years	
	Partitions	2nd fl Boys	2	EA	7	10+ years	
	Urinals	2nd fl Boys	15	EA	6	10+ years	
	Walls - Concrete Block	2nd fl Boys	960	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Tile Ceramic/ Porcelain	2nd fl Boys	460	SF	6	10+ years	
	Water Closet	2nd fl Boys	2	EA	6	10+ years	
	Accessories	2nd fl Girls	531	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd fl Girls	531	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd fl Girls	531	SF	6	10+ years	
	Floor Drain	2nd fl Girls	3	EA	7	10+ years	
	Lavatory	2nd fl Girls	1	EA	6	10+ years	
	Lighting - Lay-in	2nd fl Girls	9	EA	7	6-10 years	
	Lighting - Lay-in	2nd fl Girls	8	EA	7	6-10 years	
	Partitions	2nd fl Girls	15	EA	7	10+ years	
	Walls - Concrete Block	2nd fl Girls	960	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd fl Girls	460	SF	6	10+ years	
	Water Closet	2nd fl Girls	15	EA	6	10+ years	
	Accessories	2nd fl Men	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd fl Men	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd fl Men	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd fl Men	60	SF	6	10+ years	
	Floor Drain	2nd fl Men	1	EA	7	10+ years	
	Lavatory	2nd fl Men	1	EA	6	10+ years	
	Lighting - Lay-in	2nd fl Men	2	EA	7	6-10 years	
	Walls - Concrete Block	2nd fl Men	220	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd fl Men	80	SF	6	10+ years	
	Water Closet	2nd fl Men	1	EA	6	10+ years	
	Accessories	2nd fl Women	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd fl Women	60	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	2nd fl Women	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd fl Women	60	SF	6	10+ years	
	Floor Drain	2nd fl Women	1	EA	7	10+ years	
	Lavatory	2nd fl Women	1	EA	6	10+ years	
	Lighting - Lay-in	2nd fl Women	2	EA	7	6-10 years	
	Walls - Concrete Block	2nd fl Women	220	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd fl Women	80	SF	6	10+ years	
	Water Closet	2nd fl Women	1	EA	6	10+ years	
	Accessories	3rd fl Boys	531	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd fl Boys	531	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd fl Boys	531	SF	6	10+ years	
	Floor Drain	3rd fl Boys	3	EΑ	7	10+ years	
	Lavatory	3rd fl Boys	1	EΑ	6	10+ years	
	Lighting - Lay-in	3rd fl Boys	9	EΑ	7	6-10 years	
	Lighting - Lay-in	3rd fl Boys	8	EΑ	7	6-10 years	
	Partitions	3rd fl Boys	2	EΑ	7	10+ years	
	Urinals	3rd fl Boys	15	EA	6	10+ years	
	Walls - Concrete Block	3rd fl Boys	960	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd fl Boys	460	SF	6	10+ years	

Campus Name: Daley Page : 16 of 32 Assessment Date: 11/03/2021



Catego	Category : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	3rd fl Boys	2	EA	6	10+ years	
	Accessories	3rd fl Girls	531	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd fl Girls	531	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd fl Girls	531	SF	6	10+ years	
	Floor Drain	3rd fl Girls	3	EA	7	10+ years	
	Lavatory	3rd fl Girls	1	EA	6	10+ years	
	Lighting - Lay-in	3rd fl Girls	9	EA	7	6-10 years	
	Lighting - Lay-in	3rd fl Girls	8	EA	7	6-10 years	
	Partitions	3rd fl Girls	15	EA	7	10+ years	
	Walls - Concrete Block	3rd fl Girls	960	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd fl Girls	460	SF	6	10+ years	
	Water Closet	3rd fl Girls	15	ĒΑ	6	10+ years	
	Accessories	3rd fl Men	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd fl Men	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd fl Men	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd fl Men	60	SF	6	10+ years	
	Floor Drain	3rd fl Men	1	ĒΑ	7	10+ years	
	Lavatory	3rd fl Men	1	EA	6	10+ years	
	Lighting - Lay-in	3rd fl Men	2	EA	7	6-10 years	
	Walls - Concrete Block	3rd fl Men	220	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd fl Men	80	SF	6	10+ years	
	Water Closet	3rd fl Men	1	ĒΑ	6	10+ years	
	Accessories	3rd fl Women	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd fl Women	60	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd fl Women	60	SF	6	10+ years	
	Floor Drain	3rd fl Women	1	EΑ	7	10+ years	
	Lavatory	3rd fl Women	1	EΑ	6	10+ years	
	Lighting - Lay-in	3rd fl Women	2	EA	7	6-10 years	
	Walls - Concrete Block	3rd fl Women	220	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd fl Women	80	SF	6	10+ years	
	Water Closet	3rd fl Women	1	ĒΑ	6	10+ years	
	Accessories	Restroom in 106	51	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Restroom in 106	51	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom in 106	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Restroom in 106	51	SF	6	10+ years	
	Floor Drain	Restroom in 106	1	EA	7	10+ years	
	Lavatory	Restroom in 106	1	EΑ	6	10+ years	
	Lighting - Lay-in	Restroom in 106	1	EΑ	6	6-10 years	
	Walls - Concrete Block	Restroom in 106	267	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Restroom in 106	64	SF	6	10+ years	
	Water Closet	Restroom in 106	1	EA	6	10+ years	
	Accessories	Toilet between 109 and 110	48	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Toilet between 109 and 110	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Toilet between 109 and 110	1	EA	6	10+ years	
	200.0 Wood 20010 IIIold IIW	Tonot bottoon 100 and 110		_/ \	J	ioi youis	

Campus Name: Daley Page : 17 of 32 Assessment Date: 11/03/2021



Catego	ry : Room		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	Toilet between 109 and 110	48	SF	6	10+ years	
	Floor Drain	Toilet between 109 and 110	1	EA	7	10+ years	
	Lavatory	Toilet between 109 and 110	1	EA	6	10+ years	
	Lighting - Lay-in	Toilet between 109 and 110	1	EA	6	6-10 years	
	Walls - Concrete Block	Toilet between 109 and 110	198	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Toilet between 109 and 110	60	SF	6	10+ years	
	Water Closet	Toilet between 109 and 110	1	EA	6	10+ years	
	Accessories	Toilet in General Office	53	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Toilet in General Office	53	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Toilet in General Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Toilet in General Office	53	SF	6	10+ years	
	Floor Drain	Toilet in General Office	1	EA	7	10+ years	
	Lavatory	Toilet in General Office	1	EA	6	10+ years	
	Lighting - Lay-in	Toilet in General Office	1	EA	6	6-10 years	
	Walls - Concrete Block	Toilet in General Office	198	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Toilet in General Office	56	SF	6	10+ years	
	Water Closet	Toilet in General Office	1	EA	6	10+ years	

Category : Classroom **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroc	m #106 (Pre School)						
	Casework	1st Floor	33	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,032	SF	6	10+ years	
	Doors - Side-lite	1st Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,032	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	838	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	452	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	m #108 (Vacant)						
	Casework	1st Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	2	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	808	SF	6	10+ years	
	Doors - Side-lite	1st Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	810	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	6	6-10 years	
	Storage/ Closet	1st Floor	58	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	700	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	342	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
						·	

Campus Name: Daley Page : 18 of 32 Assessment Date: 11/03/2021



Catego	ry : Classroom		Building : Main		: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #109 (Kindergarten)						
	Casework	1st Floor	63	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,005	SF	6	10+ years	
	Doors - Side-lite	1st Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,005	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	466	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	538	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
						,	
Classroo	om #110 (Kindergarten)						
	Casework	1st Floor	63	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,167	SF	6	10+ years	
	Doors - Side-lite	1st Floor	[′] 10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	1,167	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	5	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,119	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	138	SF	6	10+ years	
	Work Sink	1st Floor	2	EΑ	7	10+ years	
_Classroc	om #201 (Regular Classroom)						
	Casework	2nd Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	930	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	930	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	468	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	744	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
	Casework	2nd Floor	57	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	930	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	930	SF	7	10+ years	

Campus Name: Daley Page: 19 of 32 Assessment Date: 11/03/2021



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	168	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,124	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #204 (Regular Classroom)						
	Casework	2nd Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	930	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	930	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	766	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	260	SF	6	10+ years	
Classro	om #205 (Regular Classroom)						
Classion	Casework	2nd Floor	57	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	930	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	10+ years	
	Floor - Tile	2nd Floor	930	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	930	EA	7	•	
	Marker Board	2nd Floor	12	LF	6	6-10 years 6-10 years	
	Walls - Concrete Block	2nd Floor	168	SF	6	10+ years	
		2nd Floor		SF	_		
	Walls - Plaster/Drywall Work Sink	2nd Floor	1,124	EA	6 7	10+ years	
	WORK SILIK	2110 F1001	1	EA	,	10+ years	
Classroo	om #206 (Regular Classroom)						
	Casework	2nd Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	930	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	930	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	146	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	840	SF	6	10+ years	

Campus Name: Daley Page : 20 of 32 Assessment Date: 11/03/2021



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #207 (Regular Classroom)						
	Casework	2nd Floor	57	LF	6	2-5 years	
	Ceiling - Lay-in	2nd Floor	930	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	930	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	168	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,124	SF	6	10+ years	Paint required, patching throughout.
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #209 (Regular Classroom)						
	Casework	2nd Floor	57	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	930	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	930	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	80	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	168	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,124	SF	6	10+ years	
	Work Sink	2nd Floor	1,124	EA	7	10+ years	
Classro	om #211 (Regular Classroom)						
Oldoorok	Casework	2nd Floor	57	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	930	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	10+ years	
	Floor - Tile	2nd Floor	930	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	930	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	168	SF	6	10+ years	
	Walls - Concrete Block Walls - Plaster/Drywall	2nd Floor	1,124	SF SF	6	•	
	Work Sink	2nd Floor	1,124	EA	7	10+ years 10+ years	
Classro	om #212 (Regular Classroom)						
Classiul	Casework	2nd Floor	18	LF	6	10+ years	
				SF		•	
	Ceiling - Lay-in	2nd Floor	1,342	3 F	6	10+ years	



Catego	ry : Classroom		В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Water damage.
	Doors - Side-lite	2nd Floor	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,350	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	7	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	723	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	599	SF	6	10+ years	
Classroo	om #213 (Regular Classroom)						
	Casework	2nd Floor	57	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	930	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	10+ years	
	Floor - Tile	2nd Floor	930	SF	6	•	
		2nd Floor		EA	7	6-10 years	
	Lighting - Lay-in Marker Board	2nd Floor 2nd Floor	9 12	LF		6-10 years	
				SF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	168		6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,124	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #214 (Regular Classroom)						
	Casework	2nd Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	926	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	4	SF	4	0-1 year	Water damage.
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	3
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	930	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	9	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	446	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	540	SF	6	10+ years	
Classroo	om #215 (Regular Classroom)						
	Casework	2nd Floor	57	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	930	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	10	EA	6	10+ years	
	Floor - Tile	2nd Floor 2nd Floor		SF	7		
		2nd Floor 2nd Floor	930			10+ years	
	Lighting - Lay-in		9	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF SF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	168	SE	6	10+ years	

Campus Name: Daley Page : 22 of 32 Assessment Date: 11/03/2021



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	1,124	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #216 (Special Education)						
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	443	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	443	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	355	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	440	SF	6	10+ years	
Classroo	om #217 (Regular Classroom)						
	Casework	2nd Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	930	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	930	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	468	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	744	SF	6	10+ years	
Classroo	om #218 (Regular Classroom)						
	Casework	2nd Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	926	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	4	SF	4	0-1 year	Water damage.
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	Water damage.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	930	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	746	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	240	SF	6	10+ years	
Classroo	om #301 (Science)						
	Casework	3rd Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	930	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Side-like	314 (100)	10	SI-	U	10+ years	

Campus Name: Daley Page : 23 of 32 Assessment Date: 11/03/2021



Catego	ry : Classroom		В	uilding	: Main		· • • • • • • • • • • • • • • • • • • •
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years	
	Floor - Tile	3rd Floor	930	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	468	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	744	SF	6	10+ years	
Classroo	om #303 (Regular Classroom)						
	Casework	3rd Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	930	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	930	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	9	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	168	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,044	SF	6	10+ years	
Classroo	om #304 (Regular Classroom)						
	Casework	3rd Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	930	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	6	10+ years	
	Floor - Tile	3rd Floor	930	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	766	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	260	SF	6	10+ years	
Classroo	om #305 (Regular Classroom)						
<u> </u>	Casework	3rd Floor	52	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	930	SF	6	10+ years 10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Floor - Tile	3rd Floor	930	SF SF	6	10+ years 10+ years	
		3rd Floor		SF EA	7		
	Lighting - Lay-in Marker Board	3rd Floor 3rd Floor	9 12	LF	6	6-10 years 6-10 years	
	Walls - Concrete Block	3rd Floor	528	SF	6	•	
	Walls - Plaster/Drywall	3rd Floor	684	SF	6	10+ years 10+ years	
Classro	om #306 (Regular Classroom)						
	,	3rd Floor	-	LF	6	101.1/2272	
	Casework		52	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	930	21	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		524 6 Wolcott AVENGE, Officago, IE 00005
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	930	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	146	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	840	SF	6	10+ years	
Classroo	om #308 (Regular Classroom)						
	Casework	3rd Floor	29	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	550	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	550	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	297	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	560	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #310 (Faculty Lounge)						
	Casework	3rd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	332	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	332	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	6	EΑ	7	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	192	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	447	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #311 (Regular Classroom)						
	Casework	3rd Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	930	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	930	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	930	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	468	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	744	SF	6	10+ years	
Classroo	om #312 (Computer Lab)						
	Casework	3rd Floor	28	LF	6	10+ years	
	Guodin	014 1 1001	20	Li	Ü	ioi youis	

Campus Name: Daley Page : 25 of 32 Assessment Date: 11/03/2021



Calego	ory : Classroom		В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	3rd Floor	930	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	930	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	506	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	480	SF	6	10+ years	
Classro	om #313 (Regular Classroom)						
	Casework	3rd Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	930	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	930	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	9	EΑ	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	168	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,042	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2	SF	5	0-1 year	Chipped plaster
Classes	are #244 (Barular Classes)						
Classro	om #314 (Regular Classroom)					10	
	Casework	3rd Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	930	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	930	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years	
	Lighting - Lay-in Marker Board	3rd Floor 3rd Floor	9 12	EA LF	7 6	6-10 years 6-10 years	
	Lighting - Lay-in Marker Board Walls - Concrete Block	3rd Floor 3rd Floor 3rd Floor	9 12 446	EA LF SF	7 6 6	6-10 years 6-10 years 10+ years	
	Lighting - Lay-in Marker Board	3rd Floor 3rd Floor	9 12	EA LF	7 6	6-10 years 6-10 years	
Classroo	Lighting - Lay-in Marker Board Walls - Concrete Block	3rd Floor 3rd Floor 3rd Floor	9 12 446	EA LF SF	7 6 6	6-10 years 6-10 years 10+ years	
Classroo	Lighting - Lay-in Marker Board Walls - Concrete Block Walls - Plaster/Drywall	3rd Floor 3rd Floor 3rd Floor	9 12 446	EA LF SF	7 6 6	6-10 years 6-10 years 10+ years	
Classroo	Lighting - Lay-in Marker Board Walls - Concrete Block Walls - Plaster/Drywall om #315 (Regular Classroom) Casework Ceiling - Lay-in	3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 12 446 540	EA LF SF SF	7 6 6 6	6-10 years 6-10 years 10+ years 10+ years	
Classroo	Lighting - Lay-in Marker Board Walls - Concrete Block Walls - Plaster/Drywall om #315 (Regular Classroom) Casework	3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 12 446 540	EA LF SF SF	7 6 6 6	6-10 years 6-10 years 10+ years 10+ years	
Classroo	Lighting - Lay-in Marker Board Walls - Concrete Block Walls - Plaster/Drywall om #315 (Regular Classroom) Casework Ceiling - Lay-in	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 12 446 540 52 930	EA LF SF SF LF SF SF EA	7 6 6 6 6	6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years	
Classroo	Lighting - Lay-in Marker Board Walls - Concrete Block Walls - Plaster/Drywall om #315 (Regular Classroom) Casework Ceiling - Lay-in Doors - Side-lite	3rd Floor	9 12 446 540 52 930 10	EA LF SF SF	7 6 6 6 6 6 6	6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
Classroo	Lighting - Lay-in Marker Board Walls - Concrete Block Walls - Plaster/Drywall om #315 (Regular Classroom) Casework Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 12 446 540 52 930 10 1	EA LF SF SF LF SF SF EA	7 6 6 6 6 6 6	6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	
Classroo	Lighting - Lay-in Marker Board Walls - Concrete Block Walls - Plaster/Drywall om #315 (Regular Classroom) Casework Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 12 446 540 52 930 10 1 1 930	EA LF SF SF LF SF EA SF	7 6 6 6 6 6 6 6	6-10 years 6-10 years 10+ years 6-10 years	
Classroo	Lighting - Lay-in Marker Board Walls - Concrete Block Walls - Plaster/Drywall Dom.#315 (Regular Classroom) Casework Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	3rd Floor	9 12 446 540 52 930 10 1 930 9	EA LF SF SF SF EA SF EA	7 6 6 6 6 6 6 6 7	6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	

Campus Name: Daley Page : 26 of 32 Assessment Date: 11/03/2021



Catego	ry : Classroom		Building : Main				
				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	om #316 (Special Education)						
	Casework	3rd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	346	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	346	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	265	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	440	SF	6	10+ years	
lassroc	om #317 (Regular Classroom)						
	Casework	3rd Floor	59	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,002	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,002	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	496	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	698	SF	6	10+ years	
lassroc	om #318 (Science Classroom)						
	Casework	3rd Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	930	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	930	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	746	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	240	SF	6	10+ years	
atego	ry : Interior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Lay-in	1st Floor	2,832	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	6	10+ years	
	Drinking Fountains - Double Water Cooler	1st Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,615	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	46	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	8	SF	6	10+ years	



	Catego	ry : Interior		В	Building : Main			
Walls - Concrete Block 1st Floor 280 SF 6 10+ years Celling - Lay-in 2nd Floor 2.616 SF 6 10+ years Celling - Lay-in 2nd Floor 2.616 SF 6 10+ years Celling - Lay-in 2nd Floor 2.616 SF 6 10+ years Celling - Lay-in 2nd Floor 2.616 SF 6 10+ years Celling - Lay-in 2nd Floor 1 EA 7 10+ years Repaired Celling - Lay-in 2nd Floor 1 EA 7 10+ years Repaired Celling - Lay-in 2nd Floor 2.624 SF 7 10+ years Celling - Lay-in 2nd Floor 2.624 SF 7 10+ years Celling - Lay-in 2nd Floor 2.624 SF 7 10+ years Celling - Lay-in 2nd Floor 2.623 SF 6 10+ years Celling - Lay-in 2nd Floor 2.623 SF 6 10+ years Celling - Lay-in 3rd Floor 2.623 SF 7 10+ years Celling - Lay-in 3rd Floor 2.623 SF 7 10+ years Celling - Lay-in 3rd Floor 2.623 SF 7 10+ years Celling - Lay-in 3rd Floor 2.623 SF 7 10+ years Celling - Lay-in 3rd Floor 2.623 SF 7 10+ years Celling - Lay-in 3rd Floor 2.623 SF 7 10+ years Celling - Lay-in 3rd Floor 2.623 SF 7 10+ years Celling - Lay-in 3rd Floor 2.623 SF 7 10+ years Celling - Lay-in 3rd Floor 2.623 SF 7 10+ years Celling - Lay-in 3rd Floor 2.623 SF 7 10+ years Celling - Lay-in 3rd Floor 2.623 SF 7 10+ years Celling - Lay-in 3rd Floor 2.623 SF 7 10+ years Celling - Lay-in 3rd Floor 2.623 SF 7 10+ years Celling - Lay-in 3rd Floor 2.623 SF 7 2.623 SF 7 2.623 SF 8								
Walls - Plaster/Dywall	Group							Comments
Ceiling - Lay-in								
Celling - Lay-in						6		
Drinkling Fountains - Double Water Cooler				•		_		
Drinking Fountains - Double Water Cooler Znd Floor 2,62 kF 7 10+ years				8				Water damage.
Floor - Tile/Sheet 2nd Floor 2,624 SF 7 10+ years				1				Repaired
Lighting - Lay-in 2nd Floor 4,641 SF 6 6-10 years				1				
Walls - Concrete Block 2nd Floor 4,641 SF 6 10+ years Ceiling - Lay-in 3rd Floor 2,623 SF 6 10+ years Drinking Fountains - Double Water Cooler 3rd Floor 2 EA 7 10+ years Floor - Tile/Sheet 3rd Floor 20 EA 6 6-10 years Walls - Concrete Block 3rd Floor 2 EA 7 10+ years Walls - Concrete Block 3rd Floor 2 EA 7 6-10 years Safety Camera Viewing Station 1st Floor 1 EA 7 6-10 years Metal Dedector 1st Floor 1 EA 7 6-10 years Security Cameras 1st Floor 15 EA 7 6-10 years Security Cameras 1st Floor 15 EA 7 6-10 years Security Cameras 1st Floor 15 EA 7 10+ years Statirs				•	_			
Ceiling - Lay-in 3rd Floor 2,623 SF 6 10+ ýears								
Drinking Fountains - Double Water Cooler 3rd Floor 2,623 SF 7 10+ years 10+						_	10+ years	
Floor - Tile/Sheet 3rd Floor 2,623 SF 7 10+ years 10				2,623	SF			
Lighting - Lay-in 3rd Floor 20 EA 6 6-10 years			3rd Floor				10+ years	
Safety				2,623				
Camera Viewing Station			3rd Floor	20	EA	6		
Camera Viewing Station		Walls - Concrete Block	3rd Floor	4,641	SF	6	10+ years	
Camera Viewing Station	Safety							
Metal Dedector 1st Floor 1 EA 7 6-10 years Security Cameras 1st Floor 15 EA 7 6-10 years Security Cameras 1st Floor 1 EA 7 6-10 years Security Cameras 1st Floor 1 EA 7 6-10 years Security Cameras 1st Floor 1 EA 7 6-10 years Security Cameras Secu	-	Camera Viewing Station	1st Floor	2	EA	7	6-10 years	
Security Cameras			1st Floor		EA	7	6-10 years	
Ceiling - Plaster/Drywall Main Stair 2 286 SF 6 10+ years		Security Cameras	1st Floor	15	EA	7	6-10 years	
Ceiling - Plaster/Drywall Main Stair 2 286 SF 6 10+ years Floor - Concrete Main Stair 2 286 SF 7 10+ years Handrails Main Stair 2 123 LF 7 10+ years Lighting - Pendent/Surface Main Stair 2 10 EA 7 6-10 years Stairs - Concrete Main Stair 2 52 LF 6 10+ years Walls - Concrete Block Main Stair 2 1,040 SF 6 10+ years Ceiling - Plaster/Drywall North Stair 3 286 SF 6 10+ years Floor - Concrete North Stair 3 286 SF 7 10+ years Lighting - Pendent/Surface North Stair 3 123 LF 7 10+ years Stairs - Concrete Block North Stair 3 52 LF 6 10+ years Walls - Concrete Block North Stair 1 286 SF 7 10+ years Floor - Concrete South Stair 1 286 SF		Security Cameras	1st Floor	1	EA	7	6-10 years	
Floor - Concrete	Stairs							
Floor - Concrete		Ceiling - Plaster/Drywall	Main Stair 2	286	SF	6	10+ years	
Handrails			Main Stair 2	286	SF	7		
Lighting - Pendent/Surface Main Stair 2 10 EA 7 6-10 years Stairs - Concrete Main Stair 2 52 LF 6 10+ years Walls - Concrete Block Main Stair 2 1,040 SF 6 10+ years Ceiling - Plaster/Drywall North Stair 3 286 SF 6 10+ years Floor - Concrete North Stair 3 286 SF 7 10+ years Handrails North Stair 3 123 LF 7 10+ years Lighting - Pendent/Surface North Stair 3 10 EA 7 6-10 years Stairs - Concrete North Stair 3 52 LF 6 10+ years Walls - Concrete Block North Stair 3 3,040 SF 6 10+ years Ceiling - Plaster/Drywall South Stair 1 286 SF 7 10+ years Floor - Concrete South Stair 1 123 LF 7 10+ years Handrails South Stair 1 10 EA		Handrails	Main Stair 2	123	LF	7		
Stairs - Concrete Main Stair 2 52 LF 6 10+ years Walls - Concrete Block Main Stair 2 1,040 SF 6 10+ years Ceiling - Plaster/Drywall North Stair 3 286 SF 6 10+ years Floor - Concrete North Stair 3 286 SF 7 10+ years Handrails North Stair 3 123 LF 7 10+ years Lighting - Pendent/Surface North Stair 3 10 EA 7 6-10 years Stairs - Concrete North Stair 3 3,040 SF 6 10+ years Walls - Concrete Block North Stair 1 286 SF 6 10+ years Ceiling - Plaster/Drywall South Stair 1 286 SF 6 10+ years Floor - Concrete South Stair 1 286 SF 7 10+ years Handrails South Stair 1 123 LF 7 10+ years Lighting - Pendent/Surface South Stair 1 10+ years 10+ years </td <td></td> <td>Lighting - Pendent/Surface</td> <td></td> <td></td> <td></td> <td></td> <td>•</td> <td></td>		Lighting - Pendent/Surface					•	
Ceiling - Plaster/Drywall North Stair 3 286 SF 6 10+ years Floor - Concrete North Stair 3 286 SF 7 10+ years Handrails North Stair 3 123 LF 7 10+ years Lighting - Pendent/Surface North Stair 3 10 EA 7 6-10 years Stairs - Concrete North Stair 3 52 LF 6 10+ years Walls - Concrete Block North Stair 3 3,040 SF 6 10+ years Ceiling - Plaster/Drywall South Stair 1 286 SF 6 10+ years Floor - Concrete South Stair 1 286 SF 7 10+ years Handrails South Stair 1 123 LF 7 10+ years Lighting - Pendent/Surface South Stair 1 10 EA 7 6-10 years Lighting - Pendent/Surface South Stair 1 52 LF 6 10+ years Walls - Concrete South Stair 1 52 LF			Main Stair 2	52	LF	6	10+ years	
Ceiling - Plaster/Drywall North Stair 3 286 SF 6 10+ years Floor - Concrete North Stair 3 286 SF 7 10+ years Handrails North Stair 3 123 LF 7 10+ years Lighting - Pendent/Surface North Stair 3 10 EA 7 6-10 years Stairs - Concrete North Stair 3 52 LF 6 10+ years Walls - Concrete Block North Stair 3 3,040 SF 6 10+ years Ceiling - Plaster/Drywall South Stair 1 286 SF 6 10+ years Floor - Concrete South Stair 1 286 SF 7 10+ years Handrails South Stair 1 123 LF 7 10+ years Lighting - Pendent/Surface South Stair 1 10 EA 7 6-10 years Stairs - Concrete South Stair 1 52 LF 6 10+ years Walls - Concrete Block South Stair 1 1,040 SF		Walls - Concrete Block	Main Stair 2	1,040	SF	6		
Floor - Concrete Handrails North Stair 3 Handrails North Stair 3 Lighting - Pendent/Surface North Stair 3 North Stair 3 North Stair 3 Lighting - Pendent/Surface North Stair 3 North Sta		Ceiling - Plaster/Drywall	North Stair 3	286	SF	6		
Handrails Lighting - Pendent/Surface North Stair 3 Stairs - Concrete North Stair 3 Nor			North Stair 3		SF	7	•	
Stairs - Concrete Walls - Concrete Block North Stair 3 North Stair 1 286 SF 6 10+ years Floor - Concrete South Stair 1 286 SF 7 10+ years Handrails Lighting - Pendent/Surface South Stair 1 10 EA 7 6-10 years Stairs - Concrete South Stair 1 10 FA 7 6-10 years Stairs - Concrete South Stair 1 North Stair 1 North Stair 3 North			North Stair 3	123	LF	7	10+ years	
Stairs - Concrete Walls - Concrete Block North Stair 3 North Stair 1 286 SF 6 10+ years Floor - Concrete South Stair 1 286 SF 7 10+ years Handrails Lighting - Pendent/Surface South Stair 1 10 EA 7 6-10 years Stairs - Concrete South Stair 1 10 FA 7 6-10 years Stairs - Concrete South Stair 1 North Stair 1 North Stair 3 North		Lighting - Pendent/Surface	North Stair 3	10	EA	7	•	
Walls - Concrete Block Ceiling - Plaster/Drywall South Stair 1 286 SF 6 10+ years Floor - Concrete South Stair 1 286 SF 7 10+ years Handrails South Stair 1 123 LF 7 10+ years Lighting - Pendent/Surface South Stair 1 10 EA 7 6-10 years Stairs - Concrete South Stair 1 52 LF 6 10+ years Walls - Concrete Block South Stair 1 1,040 SF 6 10+ years Vertical Conveyance			North Stair 3	52	LF	6	10+ years	
Ceiling - Plaster/Drywall South Stair 1 286 SF 6 10+ years Floor - Concrete South Stair 1 286 SF 7 10+ years Handrails South Stair 1 123 LF 7 10+ years Lighting - Pendent/Surface South Stair 1 10 EA 7 6-10 years Stairs - Concrete South Stair 1 52 LF 6 10+ years Walls - Concrete Block South Stair 1 1,040 SF 6 10+ years		Walls - Concrete Block	North Stair 3		SF	6		
Floor - Concrete Handrails Lighting - Pendent/Surface South Stair 1 Stairs - Concrete Walls - Concrete Block South Stair 1 South Stair		Ceiling - Plaster/Drywall	South Stair 1		SF	6		
Handrails South Stair 1 123 LF 7 10+ years Lighting - Pendent/Surface South Stair 1 10 EA 7 6-10 years Stairs - Concrete South Stair 1 52 LF 6 10+ years Walls - Concrete Block South Stair 1 1,040 SF 6 10+ years Vertical Conveyance			South Stair 1	286	SF	7		
Lighting - Pendent/Surface South Stair 1 10 EA 7 6-10 years Stairs - Concrete South Stair 1 52 LF 6 10+ years Walls - Concrete Block South Stair 1 1,040 SF 6 10+ years Vertical Conveyance		Handrails	South Stair 1		LF	7	•	
Stairs - Concrete South Stair 1 52 LF 6 10+ years Walls - Concrete Block South Stair 1 1,040 SF 6 10+ years Vertical Conveyance			South Stair 1	10		7	6-10 years	
Walls - Concrete Block South Stair 1 1,040 SF 6 10+ years			South Stair 1	52		6		
·		Walls - Concrete Block	South Stair 1		SF	6		
·	_Vertical	Conveyance						
			Main entrance	1	EA	6	10+ years	

Campus Name: Daley Page : 28 of 32 Assessment Date: 11/03/2021



Building: Main Category: Interior

Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments

Campus Name: Daley Page : 29 of 32 Assessment Date: 11/03/2021



vil/Drain		Location	Quantitu			Recommend	
vil/Drain	age	Location		Quantity UOM Rank			Comments
		2004.1011	Quantity	UOIVI	Kalik	Replacement	Comments
	Civil/ Drainage - Catch Basin	Entire Site	12	EA	6	6-10 years	
	Civil/ Drainage - Catch Basin Civil/ Drainage - Site Manhole	Entire Site	11	EA	6	6-10 years	
	Civil/ Dialitage - Site Marificle	Little Site	11	LA	U	0-10 years	
encing							
	Fencing - Chain Link	Entire Site	32	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	1,727	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	50	LF	4	0-1 year	Damages to fencing including displacement of posts, broken o missing hardware
ndscape	e						
	Benches	Entire Site	8	EA	6	6-10 years	
	Irrigation	Entire Site	1,552	SF	6	6-10 years	
	Landscape - Grass	Entire Site	10,160	SF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	1	EA	6	6-10 years	
	Parkway trees	Entire Site	9	EA	6	10+ years	
	Parkway trees	Entire Site	3	EA	4	0-1 year	Missing trees
	Planting Beds/ Area	Entire Site	1,268	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	773	SF	6	6-10 years	
	Retaining Wall - Concrete	Entire Site	240	SF EA	6 6	10+ years	
	Trash Receptacles	Entire Site	6	EA	6	6-10 years	
arking Lo							
	Concrete Curbs	South Courtyard	864	LF	6	10+ years	
	Interior Plantings	South Courtyard	120	LF	6	10+ years	
	Lighting - Lighting	South Courtyard	2	EA	6	6-10 years	
	Surface - Asphalt	South Courtyard	10,264	SF	6	6-10 years	
	Surface - Asphalt	South Courtyard	11,264	SF	6	6-10 years	
	Surface - Asphalt	South Courtyard	1,000	SF	4	0-1 year	Potholes and large cracks
	Surface - Concrete	South Courtyard	526	SF	6	10+ years	
	Trash Compactor	South Courtyard	1	EA	6	6-10 years	
	Trash Enclosure - Chain Links	South Courtyard	216	SF	6	6-10 years	
	Vehicular Screening	South Courtyard	244	LF	6	10+ years	
aygroun	d						
	Equipment - School Age 5-12	North Courtyard	1	EA	6	6-10 years	
	Surface - Square Rubber Mats	North Courtyard	1,150	SF	4	0-1 year	Separating, curling, vegetation growth.

Campus Name: Daley Page : 30 of 32 Assessment Date: 11/03/2021



Catego	ry : Site		В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Internal Walks	Entire Site	496	LF	6	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	1,500	SF	6	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	48	SF	4	0-1 year	Cracking.
Signage							
	Flag Pole - Flag Pole	East Courtyard, North East, East	1	EA	7	10+ years	
		Facade					
	Marquee - Free Standing Back Lighted	East Courtyard, North East, East	2	EA	6	6-10 years	
		Facade					
	Monument - Building Mounted Cut Letter	East Courtyard, North East, East	3	EA	7	10+ years	
	Sign	Facade					

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Daley Page: 31 of 32 Assessment Date: 11/03/2021

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classiconi Summary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	<u> </u>	•	1	•		•		•	•
Computer Lab	Computer Lab	3rd Floor	312	312	930	96	24	N	N
Faculty Lounge	Science	3rd Floor	310	310	332	64	16	N	N
Kindergarten	Regular Classroom	1st Floor	109	122	1,005	96	45	N	N
Kindergarten	Regular Classroom	1st Floor	110	125	1,167	96	45	N	N
Pre School	Regular Classroom	1st Floor	106	106	1,032	96	45	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	930	96	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	930	96	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	930	96	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	930	96	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	930	96	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	930	96	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	930	96	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	930	96	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	1,350	176	60	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	213	213	930	96	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	930	96	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	930	96	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	930	96	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	218	218	930	96	24	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	930	96	24	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	930	96	24	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	930	96	24	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	930	96	24	N	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	930	96	24	N	N
Regular Classroom	Regular Classroom	3rd Floor	313	313	930	96	24	N	N
Regular Classroom	Regular Classroom	3rd Floor	314	314	930	96	24	N	N
Regular Classroom	Regular Classroom	3rd Floor	315	315	930	96	24	N	N
Regular Classroom	Regular Classroom	3rd Floor	317	317	1,002	96	24	N	N
Regular Classroom	Science	3rd Floor	308	308	550	64	16	N	N
Science	Regular Classroom	3rd Floor	301	301	930	96	24	N	N
Science Classroom	Regular Classroom	3rd Floor	318	318	930	96	24	N	N
Special Education	Special Education	2nd Floor	216	216	443	32	8	N	Υ
Special Education	Special Education	3rd Floor	316	316	346	32	8	N	N
Vacant	Pre School	1st Floor	108	108	810	96	45	N	N