

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1929	3	101,627
Campus Total			101,627

Jatego	ry : Exterior		Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	pment						
	Cell Equipment - Antenna	Entire Building	9	EA	7	10+ years	
	Cell Equipment - Cabinets	Entire Building	4	EA	7	10+ years	
Entrance							
	Entrance Control - Audio and Video	#1 E	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#1 E	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 E	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#1 E	30	LF	6	10+ years	
	Power Door Operator and Controls	#1 E	2	EA	7	10+ years	
	Ramps - Concrete	#1 E	60	LF	7	10+ years	Missed in prior assessment
	Stair Handrail - Steel_Stair Handrail	#1 E	30	LF	6	10+ years	•
	Entrance Control - Audio and Video	#10 Exit S	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#10 Exit S	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#10 Exit S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#10 Exit S	80	LF	6	10+ years	
	Power Door Operator and Controls	#10 Exit S	2	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#10 Exit S	186	LF	6	10+ years	
	Ramps - Concrete	#10 Exit S	93	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#10 Exit S	60	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#2 E	1	EA	6	10+ years	
	Exterior Doors - Side lite	#2 E	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#2 E	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#3 Exit E	2	EA	6	10+ years	

Campus Name: Dixon Page : 1 of 29 Assessment Date: 02/07/2022





Catego	ry : Exterior		В	uilding	: Main	000000	ant Lawrence Avenue, Omeago, ie 00010
Cuiogo	.yx.ce.		_	ug		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Exterior Doors - Transom Lite	#3 Exit E	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	#3 Exit E	80	LF	4	0-1 year	Cracking and open joints, spalling throughout
	Exterior Doors - Exterior Steel Door	#4 Exit W	2	EA	6	10+ years	3
	Exterior Doors - Transom Lite	#4 Exit W	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#4 Exit W	108	LF	6	10+ years	
	Power Door Operator and Controls	#4 Exit W	1	EA	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#4 Exit W	64	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5 N	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5 N	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#5 N	80	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#6 Exit W	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6 Exit W	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 Exit W	63	LF	5	10+ years	
	Exterior Doors - Exterior Steel Door	#6.1 Exit E	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6.1 Exit E	1	ĒΑ	6	10+ years	
	Exterior Stairs - Concrete	#6.1 Exit E	3	LF	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage	#6.2 OHD	1	EA	6	10+ years	
	Door						
	Exterior Doors - Exterior Steel Door	#7 W	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#7 W	3	LF	5	6-10 years	
	Exterior Doors - Exterior Steel Door	#7.1 W	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#8 Exit W	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8 Exit W	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#8 Exit W	60	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#9 S	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#9 S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#9 S	64	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	7.2 W	1	EA	6	10+ years	
Foundat	ion						
	Foundation - Concrete	Entire Building	1,343	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	101,627	SF	7	10+ years	
		g	,	-		, , , , , , , , , , , , , , , , , , , ,	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	10	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	18	EA	6	10+ years	
Roof Sys	stem						
	Access Ladder - Metal	Boiler Room Roof	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Boiler Room Roof	39	LF	5	6-10 years	
	Liner	Doller Mooth Moot	39	LI	J	o- io yeais	
	Chimney - Metal Flue	Boiler Room Roof	12	LF	6	10+ years	
	-7				-	- ,	

Campus Name: Dixon Page : 2 of 29 Assessment Date: 02/07/2022





Secommend   Copy   Item - Type
Coping - Stone
Coping - Stone
Downspouts - Exterior Downspouts   Boiler Room Roof   36   LF   6   10+ years   Roof - Parapet < 16" Height   Boiler Room Roof   3,064   SF   6   10+ years   Roof - Modified Bitumen   Boiler Room Roof   3,064   SF   6   10+ years   Roof Structure - Steel with Clay Tile Arch   Boiler Room Roof   3,064   SF   7   10+ years   Roof Structure - Steel with Clay Tile Arch   Boiler Room Roof   5   EA   7   10+ years   Roof - Modified Pitumen   Main Roof   5   EA   7   10+ years   Roof - Modified Downspouts   Main Roof   882   LF   6   10+ years   Roof - Modified Bitumen   Main Roof   112   LF   6   10+ years   Roof - Modified Bitumen   Main Roof   112   LF   6   10+ years   Roof - Modified Bitumen   Main Roof   19,113   SF   6   10+ years   Roof - Modified Pitumen   Main Roof   19,113   SF   6   10+ years   Roof Structure - Concrete   Main Roof   19,113   SF   7   10+ years   Roof Structure - Concrete   Main Roof   19,113   SF   7   10+ years   Roof Structure - Concrete   Mest Roof   2   EA   7   10+ years   Roof Structure - Concrete   Mest Roof   597   LF   6   10+ years   Roof Structure - Concrete   West Roof   597   LF   6   10+ years   Roof Structure - Concrete   West Roof   9,214   SF   6   10+ years   Roof Structure - Concrete   West Roof   9,214   SF   6   10+ years   Roof Structure - Concrete   West Roof   9,214   SF   6   10+ years   Roof Structure - Concrete   Roof Structure
Parapet - Parapet < 16" Height   Boiler Room Roof   3,064   SF   6   10+ years   Roof - Modified Bitumen   Boiler Room Roof   3,064   SF   6   10+ years   Roof Structure - Steel with Clay Tile Arch   Boiler Room Roof   3,064   SF   7   10+ years   Roof Structure - Steel with Clay Tile Arch   Boiler Room Roof   3,064   SF   7   10+ years   Roof Structure - Steel with Clay Tile Arch   Boiler Room Roof   3,064   SF   7   10+ years   Roof Structure - Steel with Clay Tile Arch   Boiler Room Roof   3,064   SF   7   10+ years   Roof Structure - Concrete   Main Roof
Roof - Modified Bitumen   Boiler Room Roof   3,064   SF   6   10+ years
Roof Structure - Steel with Clay Tile Arch   Access Ladder - Metal   Main Roof   5 EA 7   10+ years
Access Ladder - Metal
Coping - Stone
Downspouts - Interior Downspouts
Parapet - Parapet < 16" Height   Main Roof   112
Parapet - Parapet > 30"
Roof - Modified Bitumen Roof Hatch - Metal Roof Hatch - Metal Roof Hatch - Metal Roof Main Roof Roof Structure - Concrete Roof Structure - Concrete Access Ladder - Metal West Roof Coping - Stone Downspouts - Exterior Downspouts Parapet - 16" - 30" Height Roof - Modified Bitumen Roof - Modified Bitumen Roof Structure - Concrete West Roof Roof Structure - Concrete Roof Structure - Concrete Entire Building Exterior Walls - Brick Exterior Walls - Terra Cotta Entire Building 1,754 SF 6 10+ years
Roof Hatch - Metal Main Roof 2 EA 7 10+ years Roof Structure - Concrete Main Roof 19,113 SF 7 10+ years Access Ladder - Metal West Roof 2 EA 7 10+ years Coping - Stone West Roof 597 LF 6 10+ years Downspouts - Exterior Downspouts West Roof 166 LF 6 10+ years Parapet - 16" - 30" Height West Roof 597 LF 6 10+ years Roof - Modified Bitumen West Roof 9,214 SF 6 10+ years Roof Structure - Concrete West Roof 9,214 SF 7 10+ years Roof Structure - Concrete Entire Building 336 SF 5 6-10 years Exterior Walls - Brick Entire Building 786 SF 6 10+ years Exterior Walls - Stone-Cast Entire Building 1,754 SF 6 10+ years Exterior Walls - Terra Cotta Entire Building 1,754 SF 6 10+ years Exterior Walls - Terra Cotta Entire Building 1,754 SF 6 10+ years
Roof Structure - Concrete
Access Ladder - Metal West Roof 2 EA 7 10+ years Coping - Stone West Roof 597 LF 6 10+ years Downspouts - Exterior Downspouts West Roof 166 LF 6 10+ years Parapet - 16" - 30" Height West Roof 597 LF 6 10+ years Roof - Modified Bitumen West Roof 9,214 SF 6 10+ years Roof Structure - Concrete West Roof 9,214 SF 7 10+ years  Walls  Cheek-Wall - Concrete Entire Building 336 SF 5 6-10 years Exterior Walls - Brick Entire Building 45,692 SF 6 10+ years Exterior Walls - Stone-Cast Entire Building 786 SF 6 10+ years Exterior Walls - Terra Cotta Entire Building 1,754 SF 6 10+ years
Coping - Stone West Roof 597 LF 6 10+ years Downspouts - Exterior Downspouts West Roof 166 LF 6 10+ years Parapet - 16" - 30" Height West Roof 597 LF 6 10+ years Roof - Modified Bitumen West Roof 9,214 SF 6 10+ years Roof Structure - Concrete West Roof 9,214 SF 7 10+ years  Cheek-Wall - Concrete Entire Building 336 SF 5 6-10 years Large cracks Exterior Walls - Brick Entire Building 45,692 SF 6 10+ years Exterior Walls - Stone-Cast Entire Building 786 SF 6 10+ years Exterior Walls - Terra Cotta Entire Building 1,754 SF 6 10+ years
Downspouts - Exterior Downspouts Parapet - 16" - 30" Height West Roof Roof - Modified Bitumen West Roof West Roof Roof Structure - Concrete West Roof  Cheek-Wall - Concrete Entire Building Exterior Walls - Brick Exterior Walls - Stone-Cast Exterior Walls - Terra Cotta Entire Building Exterior Walls - Terra Cotta  West Roof  166 LF 6 10+ years 1
Parapet - 16" - 30" Height West Roof 597 LF 6 10+ years Roof - Modified Bitumen West Roof 9,214 SF 6 10+ years Roof Structure - Concrete West Roof 9,214 SF 7 10+ years  Walls  Cheek-Wall - Concrete Entire Building 336 SF 5 6-10 years Large cracks Exterior Walls - Brick Entire Building 45,692 SF 6 10+ years Exterior Walls - Stone-Cast Entire Building 786 SF 6 10+ years Exterior Walls - Terra Cotta Entire Building 1,754 SF 6 10+ years
Roof - Modified Bitumen West Roof 9,214 SF 6 10+ years Roof Structure - Concrete West Roof 9,214 SF 7 10+ years  Walls  Cheek-Wall - Concrete Entire Building 336 SF 5 6-10 years Large cracks  Exterior Walls - Brick Entire Building 45,692 SF 6 10+ years  Exterior Walls - Stone-Cast Entire Building 786 SF 6 10+ years  Exterior Walls - Terra Cotta Entire Building 1,754 SF 6 10+ years
Roof Structure - Concrete  West Roof  9,214 SF 7 10+ years  Walls  Cheek-Wall - Concrete Entire Building Structure - Concrete Entire Building Structure - Concrete Entire Building Structure - Concrete Structure - Concret
Cheek-Wall - Concrete Entire Building 336 SF 5 6-10 years Large cracks Exterior Walls - Brick Entire Building 45,692 SF 6 10+ years Exterior Walls - Stone-Cast Entire Building 786 SF 6 10+ years Exterior Walls - Terra Cotta Entire Building 1,754 SF 6 10+ years
Cheek-Wall - ConcreteEntire Building336SF56-10 yearsLarge cracksExterior Walls - BrickEntire Building45,692SF610+ yearsExterior Walls - Stone-CastEntire Building786SF610+ yearsExterior Walls - Terra CottaEntire Building1,754SF610+ years
Cheek-Wall - ConcreteEntire Building336SF56-10 yearsLarge cracksExterior Walls - BrickEntire Building45,692SF610+ yearsExterior Walls - Stone-CastEntire Building786SF610+ yearsExterior Walls - Terra CottaEntire Building1,754SF610+ years
Exterior Walls - Brick Entire Building 45,692 SF 6 10+ years  Exterior Walls - Stone-Cast Entire Building 786 SF 6 10+ years  Exterior Walls - Terra Cotta Entire Building 1,754 SF 6 10+ years
Exterior Walls - Stone-Cast Entire Building 786 SF 6 10+ years  Exterior Walls - Terra Cotta Entire Building 1,754 SF 6 10+ years
Exterior Walls - Terra Cotta Entire Building 1,754 SF 6 10+ years
Windows
Guard - Guards perforated Entire Building 3,599 SF 6 10+ years
Guard - Guards wire guard Entire Building 126 SF 6 10+ years
Lintels - Steel Entire Building 1,202 LF 6 10+ years
Skylite - Glass Double-Pane Entire Building 50 SF 6 10+ years
Windows - Sash Aluminum Double-pane Entire Building 11,309 SF 6 10+ years
Category : Electrical Building : Main
Recommend
Group Item - Type Location Quantity UOM Rank Replacement Comments
Emergency System
Emergency Generator- Outdoor- Natural Courtyard 1 EA 6 10+ years
Gas - 60 - 100 KW
Automatic Transfer Switch Electrical Room 3 EA 6 10+ years
Exit Signs - Auditoium Electrical Room 14 EA 6 6-10 years Quantity changed to match current
observations
Exit Signs - Corridors and Stairs Electrical Room 40 EA 6 6-10 years

Campus Name: Dixon Page : 3 of 29 Assessment Date: 02/07/2022



Catego	ry : Electrical		R	uilding	· Main		aint Lawrence AVENUE, Chicago, IL 60619
Calego	ry . Liectricai		<u> </u>	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Огоар	Exit Signs - Gym	Electrical Room	3	EA	6	2-5 years	Location changed to match current observations. Quantity changed as total has been divided/aggregated.
	Exit Signs - Gym	Electrical Room	1	EA	4	1-2 years	Unit is operational but shows signs o damage
	Security System - CCTV	Entire Building	101,627	SF	6	6-10 years	System upgraded in 2021.
	Security System - Intrusion Detection	Entire Building	101,627	SF	6	6-10 years	1,3
	Emergency Battery Packs - Corridors and Stairs	Entire Building	1	EA	6	2-5 years	
/lain Sei	vice						
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	101,627	SF	6	6-10 years	
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	2-5 years	Quantity changed to match current observations
	Lighting and Power Panels - 100 A	Entire Building	5	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	4	1-2 years	Missing breakers expose live conductors
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	10+ years	In the MDF Room inside Room 300
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	10+ years	Quantity changed to match current observations
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	2	EA	6	10+ years	Quantity changed per Building Engineer and based on current observations.
	Transformers - 120/240 - 120/208	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Entire Building	104.007	EA	7	10+ years	
	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	101,627 101,627	SF SF	7 7	6-10 years 6-10 years	

Campus Name: Dixon Page : 4 of 29 Assessment Date: 02/07/2022



Catego	Category : Mechanical		В				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Cond							
	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons	Courtyard	1	EA	6	10+ years	
	Pipes - Chilled Water Pipe- Copper	Courtyard	100	LF	6	10+ years	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years	
Air Hand	ling Systems						
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Hot Water and Chilled Water Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	6	10+ years	AHU-1 serves south part of building
	Air Intake	Mechanical Room	2	EA	6	10+ years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Reheat Boxes - Reheat Boxes with Hot Water Coil	Mechanical Room	5	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	200	LF	7	10+ years	
	Zone Dampers	Mechanical Room	18	EA	6	6-10 years	Quantity changed per Building Engineer and to match current observations.
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Hot Water and Chilled Water Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	6	10+ years	AHU-2 serves north part of building
	Air Intake	Mechanical Room	2	EA	6	10+ years	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Reheat Boxes - Reheat Boxes with Hot Water Coil	Mechanical Room	6	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	200	LF	7	6-10 years	
	Zone Dampers	Mechanical Room	19	EA	6	6-10 years	Quantity changed per Building Engineer and to match current observations.
	Air Handling Unit- Built Up- Multi Zone- Hot Water and Chilled Water Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	6	10+ years	AHU-3 serves auditorium and gym
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	200	LF	7	10+ years	
	Zone Dampers	Mechanical Room	8	EA	6	10+ years	
	Outdoor Return Fans- inline Centrifugal - Greater than 20000 CFM	Roof	2	EA	6	10+ years	
	Air Handling Unit- Package Single Zone- Outdoor Ground Mounted- Electric and DX	Site - East	1	EA	2	0-1 year	Serves greenhouse. Nonfunctional and out of service.

Campus Name: Dixon Page : 5 of 29 Assessment Date: 02/07/2022



Catego	ry : Mechanical		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Cooling Coil - 8001-12000 cfm Air Intake	Site - East	1	EA	3	0-1 year	Air Handler is nonfunctional and out of service
Boiler S							
	Boiler Auxiliary- Condensing Hot Water - 2001 - 3000 HP	Boiler Room	2	EA	6	10+ years	Rank changed to match current observations
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	Rank changed to match current observations
	Condensing- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	6	10+ years	Rank changed to match current observations
	Glycol Feed System	Boiler Room	1	EA	6	6-10 years	Rank changed to match current observations
Heating	Devices						
	Unit Heater - Gas	Boiler Room	1	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	15	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	1	EA	5	6-10 years	Quantity adjusted to match current observations and per Building Engineer
	Fin Tube - Hot Water	Entire Building	200	LF	6	10+ years	3
	Radiators - Hot Water	Entire Building	6	EA	5	6-10 years	Per Building Engineer, radiators are physically operational as intended in service, however they are not currently in use and have been isolated as they are located in spaces where it has been determined that they are not needed for heating.
Mechan	cal Plumbing						
	Dual Temperature Pump - 10 - 20 HP	Boiler Room	2	EA	6	6-10 years	
	Dual Temperature Pump - Less than 10	Boiler Room	3	EA	6	10+ years	
	Hydronic Supply and Return - Copper	Entire Building	500	LF . –	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	300	LF	6	10+ years	
Tempera	ature Control						
	DDC System	Entire Building	101,627	SF	7	6-10 years	
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Controls unit heater
	Thermostats - DDC	Entire Building	65	EA	6	6-10 years	
Ventilati	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	

Campus Name: Dixon Page : 6 of 29 Assessment Date: 02/07/2022



							aint Lawrence Avenue, Chicago, iL 606
ategor	ry : Mechanical		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	Quantity changed per Building Engineer and to match current observations.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	Quantity changed per Building Engineer and to match current observations.
	Roof Mounted Duct Work Type II Exhaust Hood- Warming Kitchen	Entire Building Entire Building	50 1	LF EA	6 6	6-10 years 6-10 years	
ategoi	ry : Plumbing		В	uilding	: Main		
	•			J		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	6	6-10 years	Item Type and Rank changed to match current observations.
ping							
	Domestic Piping-Hot Water Return Lines	Entire Building	101,627	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	101,627	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	101,627	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	101,627	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	101,627	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	101,627	SF	6	6-10 years	
	Sanitary Piping	Entire Building	101,627	SF	6	10+ years	
	Storm Piping	Entire Building	101,627	SF	6	10+ years	
	Vent Piping	Entire Building	101,627	SF	6	10+ years	
mps	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	5	1-2 years	Pump has been nonfunctional for
	Tamps - Domestic Dooster Fump-Duplex	Medianical NOOM	ı	LA	3	1-2 years	number of years but not repaired because it is not needed.
	Pumps - Sump-Duplex	Mechanical Room	1	EA	6	6-10 years	
tegor	ry : Room		В	uilding	: Main		
	_					Recommend	_
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ministr	rative Suites/Offices						
	Ceiling - Lay-in	1st Floor - 100	588	SF	7	10+ years	
				SF			

Assessment Date: 02/07/2022 Page : 7 of 29 Campus Name: Dixon





Category : Room		Building : Main							
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	1st Floor - 100	1	EA	7	10+ years			
	Floor - Tile	1st Floor - 100	588	SF	6	10+ years			
	Lighting - Lay-in	1st Floor - 100	7	EA	7	10+ years			
	Power Distribution	1st Floor - 100	10	EA	7	10+ years			
	Walls - Plaster/Drywall	1st Floor - 100	1,156	SF	7	10+ years			
	AC Unit	1st Floor - 101	1	EA	7	6-10 years			
	Ceiling - Lay-in	1st Floor - 101	325	SF	7	10+ years			
	Doors - Transom Window	1st Floor - 101	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor - 101	3	EA	7	10+ years			
	Floor - Carpet	1st Floor - 101	321	SF	7	6-10 years			
	Floor - Carpet	1st Floor - 101	4	SF	5	1-2 years	Torn		
	Lighting - Lay-in	1st Floor - 101	5	EA	7	10+ years			
	Power Distribution	1st Floor - 101	10	EA	7	10+ years			
	Storage/ Closet	1st Floor - 101	18	SF	7	10+ years			
	Storage/ Closet	1st Floor - 101	18	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor - 101	492	SF	7	10+ years			
	Ceiling - Lay-in	1st Floor - Assistant Principal's	64	SF	7	10+ years			
	Doors - Transom Window	Office 1st Floor - Assistant Principal's Office	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor - Assistant Principal's Office	2	EA	7	10+ years			
	Floor - Carpet	1st Floor - Assistant Principal's Office	64	SF	7	6-10 years			
	Lighting - Lay-in	1st Floor - Assistant Principal's Office	4	EA	7	10+ years			
	Power Distribution	1st Floor - Assistant Principal's Office	6	EA	7	10+ years			
	Walls - Plaster/Drywall	1st Floor - Assistant Principal's Office	112	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor - Auditorium Office	83	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor - Auditorium Office	15	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor - Auditorium Office	2	EA	7	10+ years			
	Floor - Terrazzo	1st Floor - Auditorium Office	98	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor - Auditorium Office	1	EA	7	10+ years			
	Power Distribution	1st Floor - Auditorium Office	6	EA	7	10+ years			
	Walls - Plaster/Drywall	1st Floor - Auditorium Office	202	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor - Auditorium Office	10	SF	6	10+ years			
	Ceiling - Lay-in	1st Floor - Health Room	600	SF	7	10+ years			
	Doors - Transom Window	1st Floor - Health Room	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor - Health Room	1	EA	7	10+ years			
	Floor - Carpet	1st Floor - Health Room	590	SF	7	6-10 years			
	Floor - Carpet	1st Floor - Health Room	10	SF	5	1-2 years	Torn		
	Lighting - Lay-in	1st Floor - Health Room	5	EA	7	10+ years			

Campus Name: Dixon Page: 8 of 29 Assessment Date: 02/07/2022





Category : Room			Building : Main							
_				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Power Distribution	1st Floor - Health Room	18	EA	7	10+ years				
	Storage/ Closet	1st Floor - Health Room	25	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor - Health Room	1,154	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor - Health Room Office 1	52	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor - Health Room Office 1	1	EA	7	10+ years				
	Floor - Carpet	1st Floor - Health Room Office 1	52	SF	7	6-10 years				
	Lighting - Lay-in	1st Floor - Health Room Office 1	1	EA	7	10+ years				
	Power Distribution	1st Floor - Health Room Office 1	4	EA	7	10+ years				
	Walls - Metal Panel	1st Floor - Health Room Office 1	48	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor - Health Room Office 1	65	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor - Health Room Office 2	112	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor - Health Room Office 2		EA	7	10+ years				
	Floor - Carpet	1st Floor - Health Room Office 2	112	SF	7	6-10 years				
	Lighting - Lay-in	1st Floor - Health Room Office 2	4	EA	7	10+ years				
	Power Distribution	1st Floor - Health Room Office 2	6	EA	7	10+ years				
	Walls - Metal Panel	1st Floor - Health Room Office 2	102	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor - Health Room Office 2	102	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor - Kitchen Office	48	SF	7	10+ years				
	Floor - Tile	1st Floor - Kitchen Office	48	SF	7	10+ years				
	Lighting - Lay-in	1st Floor - Kitchen Office	1	EA	7	10+ years				
	Power Distribution	1st Floor - Kitchen Office	4	EA	7	10+ years				
	Walls - Plaster/Drywall	1st Floor - Kitchen Office	120	SF	7	10+ years				
	AC Unit	1st Floor - Main Office	1	EA	7	6-10 years				
	Ceiling - Lay-in	1st Floor - Main Office	406	SF	7	10+ years				
	Doors - Transom Window	1st Floor - Main Office	9	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor - Main Office	2	EA	7	10+ years				
	Floor - Tile	1st Floor - Main Office	400	SF	7	10+ years	01: 1/ 1			
	Floor - Tile	1st Floor - Main Office	6	SF	4	0-1 year	Chipped/cracked			
	Lighting - Lay-in	1st Floor - Main Office	5	EΑ	7	10+ years				
	Power Distribution	1st Floor - Main Office	10	EA	7	10+ years				
	Walls - Plaster/Drywall	1st Floor - Main Office	874	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor- Principal's Office	64	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor- Principal's Office	1	EA	7	10+ years	Town with the			
	Floor - Carpet	1st Floor- Principal's Office	64	SF	4	1-2 years	Torn, missing			
	Lighting - Lay-in	1st Floor- Principal's Office	4	EΑ	7	10+ years				
	Power Distribution	1st Floor- Principal's Office	6	EA SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor- Principal's Office	112		7	10+ years				
	AC Unit	1st Floor-Attendance Room	1 325	EA SF	7	6-10 years				
	Ceiling - Lay-in Doors - Wood Doors inclu hw	1st Floor-Attendance Room		SF EA	7	10+ years				
		1st Floor-Attendance Room	1	SF	7 7	10+ years				
	Floor - Tile	1st Floor-Attendance Room	325	SF EA		6-10 years				
	Lighting - Lay-in Power Distribution	1st Floor-Attendance Room	3 10	EA EA	7	10+ years				
		1st Floor-Attendance Room 1st Floor-Attendance Room	10	SF	7 7	10+ years				
	Storage/ Closet	15t Floor-Attendance Rooff	10	SF	,	10+ years				





Catego	ry : Room		В	uilding	: Main		Ţ
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor-Attendance Room	18	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Attendance Room	492	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor North - Former store room	115	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor North - Former store room	15	SF	4	1-2 years	Damaged and missing tile
	Doors - Transom Window	2nd Floor North - Former store room	9	SF	7	10+ years	-
	Doors - Wood Doors inclu hw	2nd Floor North - Former store room	1	EA	7	10+ years	
	Floor - Tile	2nd Floor North - Former store room	125	SF	7	10+ years	
	Floor - Tile	2nd Floor North - Former store room	5	SF	4	1-2 years	Chipped tile
	Lighting - Lay-in	2nd Floor North - Former store room	3	EA	7	10+ years	
	Power Distribution	2nd Floor North - Former store room	8	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor North - Former store room	540	SF	7	10+ years	
	AC Unit	Engineer's Office in Bsmt	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's Office in Bsmt	87	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office in Bsmt	1	EA	7	10+ years	
	Floor - Carpet	Engineer's Office in Bsmt	87	SF	7	6-10 years	
	Lighting - Pendent/Surface	Engineer's Office in Bsmt	2	EA	7	10+ years	
	Power Distribution	Engineer's Office in Bsmt	10	EA	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Office in Bsmt	313	SF	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Office in Bsmt	10	SF	5	1-2 years	Damaged
	Ceiling - Plaster/Drywall	Office#1 next to Engineer's Office in	64	SF	7	10+ years	
		Bsmt					
	Doors - Wood Doors inclu hw	Office#1 next to Engineer's Office in	1	EA	7	10+ years	
		Bsmt				-	
	Floor - Carpet	Office#1 next to Engineer's Office in	64	SF	7	6-10 years	
		Bsmt					
	Lighting - Pendent/Surface	Office#1 next to Engineer's Office in	1	EA	7	10+ years	
		Bsmt					
	Power Distribution	Office#1 next to Engineer's Office in	4	EA	7	10+ years	
		Bsmt					
	Walls - Plaster/Drywall	Office#1 next to Engineer's Office in	293	SF	7	10+ years	
		Bsmt					
	Ceiling - Plaster/Drywall	Office#2 next to Engineer's Office in	124	SF	7	10+ years	
		Bsmt					
	Doors - Wood Doors inclu hw	Office#2 next to Engineer's Office in	1	EA	7	10+ years	
		Bsmt					
	Floor - Carpet	Office#2 next to Engineer's Office in	124	SF	7	6-10 years	
		Bsmt					
	Lighting - Pendent/Surface	Office#2 next to Engineer's Office in	2	EA	7	10+ years	
		Bsmt					
	Power Distribution	Office#2 next to Engineer's Office in	4	EA	7	10+ years	
		Bsmt					
	Walls - Plaster/Drywall	Office#2 next to Engineer's Office in	384	SF	6	10+ years	
		Bsmt					

Campus Name: Dixon Page : 10 of 29 Assessment Date: 02/07/2022





Catego	ry : Room		В	uilding	: Main	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-		Location	Qualitity	OOW	Naiik	Replacement	Comments
Auditoriu	m & Theater	1st Floor	120	ГΛ	7	10	
	Balcony Seating	1st Floor 1st Floor	120 3,784	EA SF	7 7	10+ years	
	Ceiling - Plaster/Drywall					10+ years	
	Doors - Steel Doors incl hw	1st Floor	12	EA SF	7	10+ years	
	Floor - Tile	1st Floor	3,784		7	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor	5	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EΑ	7	10+ years	
	Lighting - Wall Mounted	1st Floor	10	EΑ	7	10+ years	
	Main Floor Seating	1st Floor	480	EΑ	7	10+ years	
	Sound System	1st Floor	1	EA	7	10+ years	
	Stage	1st Floor	1,351	SF	7	10+ years	
	Stage Curtain	1st Floor	5	EA	7	10+ years	
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Wood	1st Floor	14	LF	7	10+ years	
	Stairs - Terrazzo	1st Floor	33	LF	7	10+ years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	6,288	SF	7	10+ years	
Green Ho	ouse						
	Finishes	South East corner of Main Building	2,000	SF	7	2-5 years	Corrected quantities
	Glazing	South East corner of Main Building	2,000	SF	6	2-5 years	Corrected quantities. Framing is deteriorating according to engineer
	Mechanical	South East corner of Main Building	2,000	SF	5	2-5 years	Corrected quantities. Rating based or observations
	Plumbing	South East corner of Main Building	702	SF	5	2-5 years	Corrected quantities. Rating based o observations
Gymnasi	a						
•	Ceiling - Lay-in	1st Floor	2,891	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years	
	Floor - Wood	1st Floor	2,891	SF	5	6-10 years	Popping nails according to engineer
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	11 3
	Scoreboards	1st Floor	1	EA	7	10+ years	
	Storage/ Closet	1st Floor	200	SF	5	10+ years	
	Walls - Masonry	1st Floor	1,600	SF	7	10+ years	
	Walls - Masonry	1st Floor	2	SF	4	0-1 year	Hole
	Walls - Plaster/Drywall	1st Floor	3,668	SF	7	10+ years	110.0
	Walls - Plaster/Drywall	1st Floor	30	SF	4	0-1 year	Cracked
Kitchen							
	Ceiling - Lay-in	1st Floor	265	SF	7	10+ years	
	yy	1st Floor	18	SF	7	10+ years	





Catogo	ry : Room		D	uilding	· Main	0300 0 0	allit Lawrence Avenue, Chicago, ic 606 19
Calego	iy. Koon		В	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Floor - Tile	1st Floor	265	SF	7	10+ years	Comments
	Lighting - Lay-in	1st Floor	4	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	784	SF	7	10+ years	
	walls - Plaster/Drywall	ISI FIOOI	704	SF	,	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor - 106	1,536	SF	7	10+ years	
	Doors - Transom Window	1st Floor - 106	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - 106	2	EA	7	10+ years	
	Floor - Tile	1st Floor - 106	1,536	SF	5	2-5 years	
	Lighting - Lay-in	1st Floor - 106	20	EA	7	10+ years	
	Serving Line	1st Floor - 106	8	LF	7	10+ years	
	Storage/ Closet	1st Floor - 106	60	SF	7	10+ years	
				SF	7	•	
	Walls - Plaster/Drywall	1st Floor - 106	1,640	5F	/	10+ years	
MDF_ID	F						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	72	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor - In 300	1	EA	7	10+ years	
	Finishes	3rd Floor - In 300	178	SF	7	10+ years	
	Finishes	3rd Floor - In 300	4	SF	5	1-2 years	Cracked/deteriorated
	Other Cooling Unit	3rd Floor - In 300	1	ĒΑ	7	6-10 years	Ductless split system
	Window AC Unit	3rd Floor - In 300	1	EA	7	6-10 years	- nonce chin shere
Machani	ical/ Service Rooms						
IVIECHALII	Janitor's Closet	1st Floor	36	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	76	SF	7	10+ years	
		1st Floor	108	SF	7		
	Vaults Janitor's Closet	2nd Floor	18	SF SF		10+ years	
		2nd Floor		SF SF	7 7	10+ years	
	Storage Room		98	SF SF		10+ years	
	Janitor's Closet	3rd Floor	32		7	10+ years	
	Storage Room	3rd Floor	123	SF	7	10+ years	
	Storage Room	3rd Floor	15	SF	5	2-5 years	
	Air Intake Plenums	Basement	762	SF	7	10+ years	
	Air Tunnel	Basement	2,236	SF	7	10+ years	
	Auditorium Plenums	Basement	4,900	SF	7	10+ years	
	Boiler Room	Basement	2,406	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	8,880	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	6,852	SF	7	10+ years	
	Storage Room	Basement	522	SF	7	10+ years	
Restroor	m						
	Accessories	1st Floor	236	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	236	SF	7	10+ years	
	Coming Tractor/Drywan	1301 1001	250	01	,	101 years	

Campus Name: Dixon Page : 12 of 29 Assessment Date: 02/07/2022





Catego	ry : Room		В	uilding	: Main		. 5
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	1st Floor	236	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	10+ years	
	Partitions	1st Floor	4	EA	7	10+ years	
	Partitions	1st Floor	1	EA	4	0-1 year	Missing door
	Walls - Concrete Block	1st Floor	162	SF	7	10+ years	•
	Walls - Plaster/Drywall	1st Floor	62	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	466	SF	7	10+ years	
	Water Closet	1st Floor	5	EA	7	10+ years	
	Accessories	1st Floor	227	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	227	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	227	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	10+ years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	3	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	142	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	57	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	438	SF	7	10+ years	
	Water Closet	1st Floor	2	ĒΑ	7	10+ years	
	Accessories	1st Floor - In 101	37	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - In 101	37	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - In 101	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor - In 101	37	SF	7	10+ years	
	Lavatory	1st Floor - In 101	1	ĒΑ	7	10+ years	
	Lighting - Lay-in	1st Floor - In 101	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - In 101	218	SF	7	10+ years	
	Water Closet	1st Floor - In 101	1	EΑ	7	10+ years	
	Accessories	1st Floor - Principal's Office	37	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Principal's Office	37	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Principal's Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Principal's Office	37	SF	7	10+ years	
	Lavatory	1st Floor - Principal's Office	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor - Principal's Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Principal's Office	218	SF	7	10+ years	
	Water Closet	1st Floor - Principal's Office	1	EA	7	10+ years	
	Accessories	1st Floor - Women's Next to elevator	82	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor - Women's Next to elevator	82	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Women's Next to elevator	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Women's Next to elevator	82	SF	7	10+ years	
	I IOOF - THE	13t 1 1001 - WOITIGH 3 INEXT TO GIEVATOR	02	Ji	,	TOT years	

Campus Name: Dixon Page: 13 of 29 Assessment Date: 02/07/2022





Catego	ry : Room		Building : Main					
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lavatory	1st Floor - Women's Next to elevator	1	EA	7	10+ years		
	Lighting - Lay-in	1st Floor - Women's Next to elevator	1	EA	7	10+ years		
	Partitions	1st Floor - Women's Next to elevator	1	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor - Women's Next to elevator	492	SF	7	10+ years		
	Water Closet	1st Floor - Women's Next to elevator	1	EA	7	10+ years		
	Accessories	1st floor - Men's	85	SF	7	6-10 years		
	Ceiling - Lay-in	1st floor - Men's	85	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st floor - Men's	1	EA	7	10+ years		
	Floor - Tile	1st floor - Men's	85	SF	7	10+ years		
	Lavatory	1st floor - Men's	1	EA	7	10+ years		
	Lighting - Lay-in	1st floor - Men's	1	EA	7	10+ years		
	Partitions	1st floor - Men's	1	EA	7	10+ years		
	Urinals	1st floor - Men's	1	EA	7	10+ years		
	Walls - Plaster/Drywall	1st floor - Men's	420	SF	7	10+ years		
	Walls - Tile	1st floor - Men's	74	SF	7	10+ years		
	Water Closet	1st floor - Men's	1	ĒA	7	10+ years		
	Accessories	2nd Floor	261	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	261	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	261	SF	7	10+ years		
	Floor Drain	2nd Floor	1	ĒΑ	7	10+ years		
	Hand Dryer	2nd Floor	2	EA	7	6-10 years		
	Lavatory	2nd Floor	2	EA	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	10+ years		
	Partitions	2nd Floor	6	ĒΑ	7	10+ years		
	Walls - Concrete Block	2nd Floor	460	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	130	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	2nd Floor	500	SF	7	10+ years		
	Water Closet	2nd Floor	6	EA	7	10+ years		
	Accessories	2nd Floor	261	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	252	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	252	SF	7	10+ years		
	Floor Drain	2nd Floor	1	EA	7	10+ years		
	Hand Dryer	2nd Floor	2	EA	7	6-10 years		
	Lavatory	2nd Floor	2	EA	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	10+ years		
	Partitions	2nd Floor	5	EA	7	10+ years		
	Urinals	2nd Floor	4	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor	460	SF	7	•		
	Walls - Plaster/Drywall	2nd Floor	130	SF	7	10+ years 10+ years		
	Walls - Tile Ceramic/ Porcelain	2nd Floor	500	SF	7	10+ years		
	Water Closet	2nd Floor 2nd Floor	2	SF EA	7 7	10+ years 10+ years		
				SF	7	•		
	Accessories	2nd Floor - Unisex ADA next to	147	3F	1	6-10 years		
	Coiling Plastor/Drywall	elevator 2nd Floor - Unisex ADA next to	147	SF	7	10 Lyons		
	Ceiling - Plaster/Drywall	ZIIU FIOOI - OHISEX ADA HEXT TO	147	SF	,	10+ years		

Campus Name: Dixon Page : 14 of 29 Assessment Date: 02/07/2022





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		elevator					
	Doors - Wood Doors inclu hw	2nd Floor - Unisex ADA next to	1	EA	7	10+ years	
		elevator			_		
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Unisex ADA next to	147	SF	7	10+ years	
	Elean Desir	elevator	4	_^	7	40	
	Floor Drain	2nd Floor - Unisex ADA next to	1	EA	7	10+ years	
	Lavatory	elevator 2nd Floor - Unisex ADA next to	1	EA	7	10+ years	
	Lavalory	elevator	'	LA	,	10+ years	
	Lighting - Lay-in	2nd Floor - Unisex ADA next to	2	EA	7	10+ years	
	Lighting Lay in	elevator	_	_, 、	•	ioi youlo	
	Walls - Concrete Block	2nd Floor - Unisex ADA next to	43	SF	7	10+ years	
		elevator				,	
	Walls - Plaster/Drywall	2nd Floor - Unisex ADA next to	103	SF	7	10+ years	
		elevator					
	Walls - Tile Ceramic/ Porcelain	2nd Floor - Unisex ADA next to	315	SF	7	10+ years	
		elevator					
	Water Closet	2nd Floor - Unisex ADA next to	1	EA	7	10+ years	
		elevator	0.5	05	-	0.40	
	Accessories	2nd Floor North - Men's (used as	85	SF	7	6-10 years	
	Coiling Lov in	storage) 2nd Floor North - Men's (used as	85	SF	7	10 L VOOR9	
	Ceiling - Lay-in	storage)	65	SF	1	10+ years	
	Doors - Transom Window	2nd Floor North - Men's (used as	9	SF	7	10+ years	
	Doors Transom Window	storage)	9	O.	,	101 years	
	Doors - Wood Doors inclu hw	2nd Floor North - Men's (used as	1	EA	7	10+ years	
		storage)	•		•	, , , , , , , , , , , , , , , , , , , ,	
	Floor - Tile Ceramic/ Porcelain	2nd Floor North - Men's (used as	85	SF	6	10+ years	
		storage)				-	
	Lavatory	2nd Floor North - Men's (used as	1	EA	6	10+ years	
		storage)					
	Lighting - Lay-in	2nd Floor North - Men's (used as	1	EA	7	10+ years	
	<b>D</b>	storage)			_	4.0	
	Partitions	2nd Floor North - Men's (used as	1	EA	7	10+ years	
	Urinals	storage) 2nd Floor North - Men's (used as	1	EA	6	10	
	Utiliais	storage)	ı	EA	O	10+ years	
	Walls - Plaster/Drywall	2nd Floor North - Men's (used as	900	SF	6	10+ years	
	vvalis - 1 laster/Drywali	storage)	300	Oi	O	10+ years	
	Water Closet	2nd Floor North - Men's (used as	1	EA	6	10+ years	
		storage)	•		-	,	
	Accessories	3rd Floor	261	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	261	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	261	SF	7	10+ years	

Campus Name: Dixon Page : 15 of 29 Assessment Date: 02/07/2022





Catego	Category : Room		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor Drain	3rd Floor	1	EA	7	10+ years		
	Hand Dryer	3rd Floor	2	EA	7	6-10 years		
	Lavatory	3rd Floor	2	EA	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	3	EΑ	7	10+ years		
	Partitions	3rd Floor	6	EA	7	10+ years		
	Walls - Concrete Block	3rd Floor	460	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	130	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	3rd Floor	500	SF	7	10+ years		
	Water Closet	3rd Floor	6	EA	7	10+ years		
	Accessories	3rd Floor	261	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	252	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor	252	SF	7	10+ years		
	Floor Drain	3rd Floor	1	ĒΑ	7	10+ years		
	Hand Dryer	3rd Floor	2	EΑ	7	6-10 years		
	Lavatory	3rd Floor	2	EΑ	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	3	EΑ	7	10+ years		
	Partitions	3rd Floor	5	EΑ	7	10+ years		
	Urinals	3rd Floor	4	EA	7	10+ years		
	Walls - Concrete Block	3rd Floor	460	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	130	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	3rd Floor	500	SF	7	10+ years		
	Water Closet	3rd Floor	2	EA	7	10+ years		
	Accessories		22	SF	7			
	Ceiling - Plaster/Drywall	In Engineer's Office In Engineer's Office	22	SF SF	7	6-10 years		
	Doors - Wood Doors inclu hw		1	EA		10+ years		
		In Engineer's Office			7	10+ years		
	Floor - Tile	In Engineer's Office	20	SF SF	7	10+ years	Chinned and missing tile	
	Floor - Tile	In Engineer's Office	2		4	0-1 year	Chipped and missing tile	
	Lavatory	In Engineer's Office	1	EΑ	7	10+ years		
	Lighting - Pendent/Surface	In Engineer's Office	1	EA	7	10+ years		
	Walls - Plaster/Drywall	In Engineer's Office	163	SF	6	10+ years		
	Water Closet	In Engineer's Office	1	EA	7	10+ years		
	Accessories	In Office #1 next to Engineer's Office	22	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	In Office #1 next to Engineer's Office	22	SF	6	10+ years		
	Doors - Wood Doors inclu hw	In Office #1 next to Engineer's Office	1	EA	7	10+ years		
	Floor - Tile	In Office #1 next to Engineer's Office	16	SF	6	10+ years	0.1	
	Floor - Tile	In Office #1 next to Engineer's Office	6	SF	4	0-1 year	Chipped tiles	
	Lavatory	In Office #1 next to Engineer's Office	1	EA	6	10+ years		
	Lighting - Pendent/Surface	In Office #1 next to Engineer's Office	1	EA	7	10+ years		
	Walls - Plaster/Drywall	In Office #1 next to Engineer's Office	163	SF	6	10+ years		
	Water Closet	In Office #1 next to Engineer's Office	1	EA	6	10+ years		
	Accessories	In Office #2 next to Engineer's Office	22	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	In Office #2 next to Engineer's Office	22	SF	7	10+ years		
	Doors - Wood Doors inclu hw	In Office #2 next to Engineer's Office	1	EA	6	10+ years		
	Floor - Carpet	In Office #2 next to Engineer's Office	20	SF	7	10+ years		

Campus Name: Dixon Page : 16 of 29 Assessment Date: 02/07/2022



Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Carpet	In Office #2 next to Engineer's Office	2	SF	4	0-1 year	Torn
	Lavatory	In Office #2 next to Engineer's Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	In Office #2 next to Engineer's Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	In Office #2 next to Engineer's Office	163	SF	6	10+ years	
	Water Closet	In Office #2 next to Engineer's Office	1	EA	6	10+ years	
Catego	ry : Classroom		Building : Main				
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #103 (Art Room)						
	Ceiling - Lay-in	1st Floor	630	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	Corrected quantity
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	630	SF	7	6-10 years	
	Kiln	1st Floor	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	7	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	974	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	720	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	720	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	930	SF	7	10+ years	
01	·					,	
Classroo	m #110 (Regular Classroom)  Casework	1st Floor	8	LF	7	101 2000	
	Casework Ceiling - Lay-in	1st Floor 1st Floor	727	SF	7	10+ years	
	Doors - Transom Window			SF SF	7	10+ years	
		1st Floor	16		7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	727	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board Walls - Plaster/Drywall	1st Floor 1st Floor	14 942	LF SF	7 7	6-10 years 10+ years	
	vvalio - i lastel/Diywali	13(1100)	342	Oi	,	10+ years	
Classroo	m #111 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	7	10+ years	

Campus Name: Dixon Page : 17 of 29 Assessment Date: 02/07/2022





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	722	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	722	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EΑ	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	930	SF	7	10+ years	
Classroo	om #112 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	716	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	16	SF	4	1-2 years	Water damage
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	Corrected quantity
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	Corrected quartity
	Floor - Wood	1st Floor	722	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	930	SF	7	10+ years	
	vvalis - Flastel/Drywali	150 11001	930	SI	,	10+ years	
Classroo	om #113 (Regular Classroom)						
	Casework	1st Floor	22	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	722	SF	7	6-10 years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	722	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EΑ	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	930	SF	7	10+ years	
_Classroo	om #200 (Regular Classroom)						
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	722	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Doors Inclu IIW	2nd Floor	722	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor 2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor 2nd Floor		LF	7		
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	30 980	SF	7	6-10 years 10+ years	
	vvalis - Flasiel/Di ywall	ΖΠα ΓΙΟΟΙ	900	SF	1	TOT YEARS	
Classroo	om #201 (Regular Classroom)						
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	722	SF	7	10+ years	

Campus Name: Dixon Page: 18 of 29 Assessment Date: 02/07/2022





Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	Corrected quantity
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	722	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	980	SF	7	6-10 years	
Classroo	om #202 (Regular Classroom)						
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	722	SF	7	6-10 years	
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	722	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	0 0 .	2nd Floor 2nd Floor	30	LF	7	,	
	Marker Board			SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	980	SF	,	10+ years	
Classroo	om #203 (Regular Classroom)						
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	722	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	980	SF	7	10+ years	
Classroo	om #204 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	722	SF	7	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	980	SF	6	6-10 years	
				О.	· ·	0 .0 ,00.0	
Classroo	om #206 (Regular Classroom)	0-15-	10			40	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	722	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	16	SF	6	6-10 years	

Campus Name: Dixon Page: 19 of 29 Assessment Date: 02/07/2022



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Wood	2nd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	975	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	4	1-2 years	Crack in wall by the door jam
Classroc	om #208 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	722	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Wood Books inclu fiw	2nd Floor	722	SF	6	6-10 years	
		2nd Floor	12	EA	7	,	
	Lighting - Lay-in				-	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	975	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Crack in wall by the door jam
Classroc	om #210 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	722	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	16	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Wood	2nd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	6	,	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	980	SF	6	6-10 years 10+ years	
	·					,	
Classroc	om #212 (Library)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	75	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,056	SF	7	6-10 years	
	Chalk Board	2nd Floor	5	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	16	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	6-10 years	
	Floor - Carpet	2nd Floor	1,030	SF	5	2-5 years	
	Floor - Carpet	2nd Floor	26	SF	4	1-2 years	Few torn spots
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	. c tom opoto
	Walls - Plaster/Drywall	2nd Floor	1,180	SF	6	10+ years	
Closses	om #213 (Faculty Lounge)						
Ciassion	om #213 (Faculty Lounge)  Ceiling - Lay-in	2nd Floor	1,056	SF	7	10+ years	
	Coming - Lay-iii	2110 1 1001	1,030	OI.	,	10+ years	

Campus Name: Dixon Page : 20 of 29 Assessment Date: 02/07/2022





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,056	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	18	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	10	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,180	SF	7	10+ years	
Classroo	om #300 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	572	SF	7	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	0	Sr EA	6	10+ years 10+ years	
		3rd Floor	572	SF	6	-	
	Floor - Wood				-	6-10 years	
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,070	SF	7	10+ years	
Classroo	om #301 (Regular Classroom)						
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	722	SF	7	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	10+ years	
Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	722	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EΑ	6	10+ years	
	Floor - Wood	3rd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	50	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	10+ years	
Classro	om #303 (Regular Classroom)						
	Casework	3rd Floor	10	LF	7	10+ years	
	Casework	314 1 1001	10	LI	,	10+ years	

Campus Name: Dixon Page : 21 of 29 Assessment Date: 02/07/2022





Catego	ry : Classroom		В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	3rd Floor	722	SF	7	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	25	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	960	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	20	SF	5	1-2 years	water damage
Classroc	m #304 (Computer Lab)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	722	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	25	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	7	10+ years	
	Wireless System	3rd Floor	1	EA	7	10+ years	
	Wileless Cystem	314 1 1001	·	LA	,	10+ years	
Classroo	m #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EΑ	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	722	SF	7	10+ years	
	Chalk Board	3rd Floor	25	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	722	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	7	10+ years	
Classras	m #306 (Regular Classroom)						
_Classio0	` •	01 []			7	0.40	
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	722	SF	7	10+ years	
	Chalk Board	3rd Floor	25	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
						-	

Campus Name: Dixon Page : 22 of 29 Assessment Date: 02/07/2022





Catego	ry : Classroom		В	uilding	: Main		ant Lawrence Avenue, onleage, in 60013
Outogo	, , , , , , , , , , , , , , , , , , ,			anamg	· Wan	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	25	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	7	10+ years	
Classroo	om #307 (Regular Classroom)						
Cidoorot	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	722	SF	7	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	25	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	7	10+ years	
	vvalis - Flaster/Drywan	314 1 1001	300	Oi	,	10+ years	
_Classroo	om #308 (Regular Classroom)	0.15					
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	722	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	50	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	10+ years	
Classroo	om #309 (Regular Classroom)						
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	722	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EΑ	6	6-10 years	
	Marker Board	3rd Floor	35	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	7	10+ years	
_Classroo	om #310 (Regular Classroom)						
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	722	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EΑ	7	6-10 years	
	Marker Board	3rd Floor	50	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	7	10+ years	
	,	-				<b>,</b>	

Campus Name: Dixon Page : 23 of 29 Assessment Date: 02/07/2022





Category : Classroom			Building : Main			ant Lawrence Avenoe, onleage, in 60015	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #311 (Regular Classroom)						
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	717	SF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	5	SF	4	1-2 years	Missing tiles
	Chalk Board	3rd Floor	25	LF	4	2-5 years	Wildeling thee
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
			25	LF	6	6-10 years	
	Marker Board	3rd Floor		SF		•	
	Walls - Plaster/Drywall	3rd Floor	972		7	10+ years	Dan Kara
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	10+ years	Peeling
_Classro	om #312 (Regular Classroom)						
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	722	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	722	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	50	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	7	10+ years	
	walls Tlastel/Dlywall	314 1 1001	300	Oi.	,	101 years	
Classro	om #313 (Regular Classroom)						
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	722	SF	7	10+ years	
	Chalk Board	3rd Floor	25	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	722	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EΑ	7	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	972	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	10+ years	Peeling/bubbling
Catono	ory : Interior		B	uildina	· Main		
Jaiego	y . Interior		Building : Main		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	4,786	SF	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	2	EΑ	7	6-10 years	
	Drinking Fountains - Triple Fountain	1st Floor	1	EA	7	10+ years	
	-					-	

Campus Name: Dixon Page : 24 of 29 Assessment Date: 02/07/2022





Catago	mr. Intorior		В	المانات م	. Main	00000	ant Lawrence Avertoe, officago, ie 00013
Catego	ry : Interior		В	uilding	. wam	Decemmend	
Craun	Ham Tune	Location	Quantity	UOM	Donk	Recommend	Comments
Group	Item - Type			SF	Rank	Replacement	Comments
	Floor - Terrazzo	1st Floor	1,668	SF SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	3,107		7	6-10 years	Object and tile a
	Floor - Tile/Sheet	1st Floor	10	SF	4	2-5 years	Chipped tiles
	Lighting - Lay-in	1st Floor	47	EΑ	7	6-10 years	
	Student Lockers - One Tier	1st Floor	205	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	4,005	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	5,398	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,927	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	6-10 years	
	Floor - Terrazzo	2nd Floor	661	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,266	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	40	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	183	EΑ	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,020	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	2,424	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,927	SF	6	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor	2	EΑ	7	10+ years	
	Floor - Terrazzo	3rd Floor	661	SF	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,266	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	40	EA	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	183	EΑ	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,020	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	2,424	SF	6	10+ years	
Safety							
	Security Cameras	Entire Buiding	4	EA	7	6-10 years	
Ctoiro							
_Stairs	Cailing Diagtor/Dravall	Cumpasium Stair North	400	SF	7	10	
	Ceiling - Plaster/Drywall	Gymnasium Stair North	400		7	10+ years	
	Floor - Terrazzo	Gymnasium Stair North	400	SF	7	10+ years	
	Handrails	Gymnasium Stair North	264	LF.	7	10+ years	
	Lighting - Pendent/Surface	Gymnasium Stair North	6	EA	7	10+ years	
	Stairs - Terrazzo	Gymnasium Stair North	62	LF	7	10+ years	
	Walls - Masonry	Gymnasium Stair North	905	SF	6	10+ years	
	Walls - Masonry	Gymnasium Stair North	25	SF	5	1-2 years	Cracked
	Ceiling - Plaster/Drywall	Gymnasium Stair South	400	SF	7	10+ years	
	Floor - Terrazzo	Gymnasium Stair South	400	SF	7	10+ years	
	Handrails	Gymnasium Stair South	264	LF	7	10+ years	
	Lighting - Pendent/Surface	Gymnasium Stair South	8	EA	7	10+ years	
	Stairs - Terrazzo	Gymnasium Stair South	62	LF	7	10+ years	
	Walls - Masonry	Gymnasium Stair South	910	SF	6	10+ years	
	Walls - Masonry	Gymnasium Stair South	20	SF	4	0-1 year	Cracked
	Ceiling - Plaster/Drywall	Northeast stair	520	SF	6	10+ years	
	Floor - Terrazzo	Northeast stair	520	SF	6	10+ years	

Campus Name: Dixon Page : 25 of 29 Assessment Date: 02/07/2022



Category : Interior		В	uilding	: Main		·	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Handrails	Northeast stair	264	LF	7	10+ years	
	Lighting - Pendent/Surface	Northeast stair	8	EA	7	10+ years	
	Stairs - Terrazzo	Northeast stair	62	LF	6	10+ years	
	Walls - Plaster/Drywall	Northeast stair	1,090	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Northwest stairs	510	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Northwest stairs	10	SF	4	0-1 year	Cracked
	Floor - Terrazzo	Northwest stairs	520	SF	6	10+ years	
	Handrails	Northwest stairs	264	LF	7	10+ years	
	Lighting - Pendent/Surface	Northwest stairs	8	EA	7	6-10 years	
	Stairs - Terrazzo	Northwest stairs	62	LF	6	10+ years	
	Walls - Plaster/Drywall	Northwest stairs	1,090	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Southeast stair	520	SF	6	10+ years	
	Floor - Terrazzo	Southeast stair	520	SF	6	10+ years	
	Handrails	Southeast stair	264	LF	7	10+ years	
	Lighting - Pendent/Surface	Southeast stair	8	EΑ	7	10+ years	
	Stairs - Terrazzo	Southeast stair	62	LF	6	10+ years	
	Walls - Plaster/Drywall	Southeast stair	1,090	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Southwest stair	520	SF	6	10+ years	
	Floor - Terrazzo	Southwest stair	520	SF	6	10+ years	
	Handrails	Southwest stair	264	LF	7	10+ years	
	Lighting - Pendent/Surface	Southwest stair	8	EA	7	10+ years	
	Stairs - Terrazzo	Southwest stair	62	LF	6	10+ years	
	Walls - Plaster/Drywall	Southwest stair	1,090	SF	6	10+ years	
_Vertical	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years	

Campus Name: Dixon Page : 26 of 29 Assessment Date: 02/07/2022



Category : Site Building : Site

	y . Site		_	unung		D	
	Itam Tuna	Location	Quantity	UOM	Donk	Recommend	Comments
Froup	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
Civil/Drai		F :: 0::					
	Civil/ Drainage - Catch Basin	Entire Site	8	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	6	10+ years	
encing	Fencing - Chain Link	Entire Site	869	LF	6	10+ years	
	Fencing - Chain Link Fencing - New Standard Ornamental	Entire Site	1,038	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,036	LF	4	0-1 year	Bent
				LF LF	-		
	Fencing - Old Standard Ornamental	Entire Site	500	LF LF	4	0-1 year	Rusted throughout
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	167	LF	6	10+ years	
andscar	oe						
	Benches	Entire Site	2	EA	6	10+ years	
	Landscape - Grass	Entire Site	26,519	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	5,478	SF	6	10+ years	
	Parkway trees	Entire Site	30	EA	6	10+ years	
	Parkway trees	Entire Site	1	EA	4	0-1 year	Missing.
	Planting Beds/ Area	Entire Site	3,326	SF	6	10+ years	3
	Play Area - Hardscape- Asphalt	Entire Site	19,209	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	10,888	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	1,050	SF	4	0-1 year	Cracking/damaged.
	Retaining Wall - Masonry	Entire Site	200	SF	6	10+ years	Chiller wall enclosure
	Trash Receptacles	Entire Site	3	EA	6	10+ years	Crimor wan criciccare
			· ·	_, .	· ·	. o . y ca. c	
Parking L							
	Surface - Asphalt	South Courtyard	14,002	SF	4	0-1 year	Striping needed, cracking and potholes.
	Surface - Asphalt	South Courtyard	500	SF	4	0-1 year	Crumbling, severe cracking
	Surface - Concrete	South Courtyard	1,015	SF	6	10+ years	c. csiii ig, covoro crackii ig
	Trash Enclosure - Chain Links	South Courtyard	2,980	SF	6	10+ years	
	Surface - Concrete	West Courtyard	3,623	SF	6	10+ years	
	Surface Soficiete	vvest courtyara	0,020	O1	Ū	101 years	
Playgrou							
	Equipment - Combo 3-12	NW Courtyard	1	EA	6	10+ years	
	Equipment - School Age 5-12	NW Courtyard	1	EA	6	10+ years	
	Surface - Poured Surface	NW Courtyard	4,620	SF	6	10+ years	
Sidewalk	s						
	Sidewalks - Internal Walks	Entire Site	828	LF	6	10+ years	
		Entire Site	10	LF	4	0-1 year	cracking
	Sidewalks - Internal Walks	Entire Site	10	LI	4	U- i yeai	Clacking

Campus Name: Dixon Page : 27 of 29 Assessment Date: 02/07/2022



Category : Site			В	Building : Site					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Sidewalks - Perimeter Sidewalks	Entire Site	14,253	SF	6	10+ years			
	Sidewalks - Perimeter Sidewalks	Entire Site	30	SF	5	2-5 years			
Signage									
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years			
	Monument - Building Mounted Cut Letter Sian	Entire Site	1	EA	6	10+ years			

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Dixon Page : 28 of 29 Assessment Date: 02/07/2022

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



**Classroom Summary** 

Classroom Summary			_	Floor Plan	_	Glazed	Operable		_
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main			•						
Art Room	Regular Classroom	1st Floor	103	103	630	227	110	Υ	Υ
Computer Lab	Regular Classroom	3rd Floor	304	304	722	168	12	Υ	N
Faculty Lounge	Science Lab Level 3	2nd Floor	213	213	1,056	252	18	Υ	N
Library	Art Room	2nd Floor	212	212	1,056	252	18	Υ	N
Regular Classroom	Regular Classroom	1st Floor	104	104	720	126	20	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	110	110	727	126	20	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	111	111	722	126	20	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	112	112	722	126	20	Υ	Ν
Regular Classroom	Regular Classroom	1st Floor	113	113	722	126	30	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	200	200	722	168	12	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	722	168	12	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	722	168	12	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	722	168	12	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	722	168	12	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	722	168	12	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	208	722	168	12	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	210	722	168	12	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	300	300	572	84	6	Y	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	722	168	12	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	722	168	12	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	303	303	722	168	12	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	305	305	722	168	12	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	306	306	722	168	12	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	307	307	722	168	12	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	308	308	722	168	12	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	309	309	722	168	12	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	310	310	722	168	12	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	311	311	722	168	12	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	312	312	722	168	12	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	313	313	722	168	12	Y	Υ