

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1962	3	74,410
Campus Total			74,410

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior FRP Door	#1 - SE	3	EA	6	10+ years	
	Exterior Doors - Side lite	#1 - SE	4	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#2 Exit - SE	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#3 Exit - SW	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 Exit - SW	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#4 Exit - SW	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#5 Exit - W	3	EA	6	10+ years	
	Exterior Doors - Side lite	#5 Exit - W	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5 Exit - W	3	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#6 Exit - NW	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#7 Exit - NW	1	EA	6	10+ years	
	Exterior Doors - Side lite	#7 Exit - NW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7 Exit - NW	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#7.2 - N - Boiler Room	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#7.2 - N - Boiler Room	30	LF	5	2-5 years	
	Stair Handrail - Steel_Stair Handrail	#7.2 - N - Boiler Room	32	LF	5	10+ years	
	Exterior Doors - Exterior Steel Door	#7.5 - N	1	EA	6	10+ years	Hardware missing
	Exterior Stairs - Concrete	#7.5 - N	3	LF	6	10+ years	-
	Exterior Doors - Exterior FRP Door	#8 - N	2	EA	6	10+ years	
	Ramps - Steel or Aluminum	#8 - N	1	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	#8.5 - N - Yard storage	2	EA	6	10+ years	
	Entrance Control - Audio	#9 - NE	1	EA	5	2-5 years	
	Exterior Doors - Exterior FRP Door	#9 - NE	2	EA	6	10+ years	
	Power Door Operator and Controls	#9 - NE	1	EA	7	6-10 years	



GroupItem - TypeLocationQuantityUOMRankRecommend ReplacementCommentFoundationFoundation - Concrete Superstructure - ConcreteEntire Building1,210LF710+ yearsSuperstructure - ConcreteEntire Building74,410SF710+ yearsLightingExterior Lighting - Wall MountedEntire Building37EA610+ yearsRoof SystemChimney - Brick Chimney- Concrete/ Mortar LinerMain Roof40LF610+ yearsRoof SystemSeptem - ConcreteMain Roof899LF710+ yearsRoof SystemMain Roof260LF710+ yearsRoof SystemMain Roof260LF710+ yearsCoping - Metal Downspouts - Interior Downspouts Roof - Modified BitumenMain Roof27,599SF710+ yearsRoof - Modified Bitumen Downspouts - Interior Downspouts Roof - Modified BitumenNorth Low Roof135LF710+ yearsDownspouts - Interior Downspouts Roof - Modified BitumenNorth Low Roof135LF710+ yearsRoof Structure - Concrete Roof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof Structure - Concrete Roof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof - Modified Bitumen Roof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof - Modified Bitumen Roof -	
Foundation Foundation - Concrete Entire Building 1,210 LF 7 10+ years Superstructure - Concrete Entire Building 74,410 SF 7 10+ years Lighting	
Foundation - Concrete Superstructure - ConcreteEntire Building1,210 Entire BuildingLF 7710+ years 10+ yearsLightingExterior Lighting - Wall MountedEntire Building37EA610+ yearsRoof SystemChinney - Brick Chimney- Concrete/ Mortar LinerMain Roof40LF610+ yearsCoping - Metal Downspouts - Interior DownspoutsMain Roof200LF710+ yearsRoof Structure - ConcreteMain Roof27,599SF710+ yearsRoof - Modified Bitumen Coping - MetalMain Roof27,599SF710+ yearsRoof Structure - ConcreteMain Roof135LF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+	S
Foundation - Concrete Superstructure - ConcreteEntire Building1,210 T,4,410LF SF710+ years 10+ yearsLightingExterior Lighting - Wall MountedEntire Building37EA610+ yearsRoof SystemChinney - Brick Chimney- Concrete/ Mortar LinerMain Roof40LF610+ yearsCoping - Metal Downspouts - Interior DownspoutsMain Roof260LF710+ yearsRoof Structure - ConcreteMain Roof27,599SF710+ yearsRoof Structure - ConcreteMain Roof135LF710+ yearsDownspouts - Interior DownspoutsNorth Low Roof135LF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ years	
Superstructure - ConcreteEntire Building74,410SF710+ yearsLightingExterior Lighting - Wall MountedEntire Building37EA610+ yearsRoof SystemChimney - Brick Chimney- Concrete/ Mortar LinerMain Roof40LF610+ yearsCoping - Metal Downspouts - Interior DownspoutsMain Roof260LF710+ yearsRoof Structure - ConcreteMain Roof27,599SF710+ yearsRoof Structure - ConcreteMain Roof27,599SF710+ yearsRoof Structure - ConcreteMain Roof135LF710+ yearsRoof Structure - ConcreteMain Roof135LF710+ yearsRoof Structure - ConcreteMoin Roof135LF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsRoof Structure - OncreteNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,75	
Lighting Exterior Lighting - Wall Mounted Entire Building 37 EA 6 10+ years Roof System	
Exterior Lighting - Wall MountedEntire Building37EA610+ yearsRoof SystemChimney - Brick Chimney- Concrete/ Mortar LinerMain Roof40LF610+ yearsCoping - MetalMain Roof899LF710+ yearsDownspouts - Interior DownspoutsMain Roof260LF710+ yearsRoof - Modified BitumenMain Roof27,599SF710+ yearsRoof Structure - ConcreteMain Roof27,599SF710+ yearsDownspouts - Interior DownspoutsNorth Low Roof135LF710+ yearsRoof - Modified BitumenNorth Low Roof135LF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ years<	
Roof SystemChimney - Brick Chimney- Concrete/ Mortar LinerMain Roof40LF610+ yearsCoping - MetalMain Roof899LF710+ yearsDownspouts - Interior DownspoutsMain Roof260LF710+ yearsRoof - Modified BitumenMain Roof27,599SF710+ yearsRoof Structure - ConcreteMain Roof27,599SF710+ yearsCoping - MetalNorth Low Roof135LF710+ yearsDownspouts - Interior DownspoutsNorth Low Roof28LF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsDownspouts - Interior DownspoutsNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsAccess Ladder - MetalWest High Roof1EA710+ yearsCoping - MetalWest High Roof673LF710+ yearsDownspouts - Interior DownspoutsWest High Roof205LF710+ years	
Chimney - Brick Chimney- Concrete/ Mortar LinerMain Roof40LF610+ yearsCoping - MetalMain Roof899LF710+ yearsDownspouts - Interior DownspoutsMain Roof260LF710+ yearsRoof - Modified BitumenMain Roof27,599SF710+ yearsRoof Structure - ConcreteMain Roof27,599SF710+ yearsCoping - MetalNorth Low Roof135LF710+ yearsDownspouts - Interior DownspoutsNorth Low Roof28LF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsDownspouts - Interior DownspoutsNorth Low Roof1,755SF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsAccess Ladder - MetalWest High Roof1EA710+ yearsCoping - MetalWest High Roof673LF710+ yearsDownspouts - Interior DownspoutsWest High Roof205LF710+ years	
Chimney - Brick Chimney- Concrete/ Mortar LinerMain Roof40LF610+ yearsCoping - MetalMain Roof899LF710+ yearsDownspouts - Interior DownspoutsMain Roof260LF710+ yearsRoof - Modified BitumenMain Roof27,599SF710+ yearsRoof Structure - ConcreteMain Roof27,599SF710+ yearsCoping - MetalNorth Low Roof135LF710+ yearsDownspouts - Interior DownspoutsNorth Low Roof28LF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsDownspouts - Interior DownspoutsNorth Low Roof1,755SF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsAccess Ladder - MetalWest High Roof1EA710+ yearsCoping - MetalWest High Roof673LF710+ yearsDownspouts - Interior DownspoutsWest High Roof205LF710+ years	
LinerMain Roof899LF710+ yearsDownspouts - Interior DownspoutsMain Roof260LF710+ yearsRoof - Modified BitumenMain Roof27,599SF710+ yearsRoof Structure - ConcreteMain Roof27,599SF710+ yearsCoping - MetalNorth Low Roof135LF710+ yearsDownspouts - Interior DownspoutsNorth Low Roof28LF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsAccess Ladder - MetalWest High Roof1EA710+ yearsCoping - MetalWest High Roof673LF710+ yearsDownspouts - Interior DownspoutsWest High Roof205LF710+ years	
Coping - MetalMain Roof899LF710+ yearsDownspouts - Interior DownspoutsMain Roof260LF710+ yearsRoof - Modified BitumenMain Roof27,599SF710+ yearsRoof Structure - ConcreteMain Roof27,599SF710+ yearsCoping - MetalNorth Low Roof135LF710+ yearsDownspouts - Interior DownspoutsNorth Low Roof28LF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsAccess Ladder - MetalWest High Roof1EA710+ yearsCoping - MetalWest High Roof673LF710+ yearsDownspouts - Interior DownspoutsWest High Roof205LF710+ years	
DownspoutsInterior DownspoutsMain Roof260LF710+ yearsRoofModified BitumenMain Roof27,599SF710+ yearsRoof StructureConcreteMain Roof27,599SF710+ yearsCopingMetalNorth Low Roof135LF710+ yearsDownspoutsInterior DownspoutsNorth Low Roof28LF710+ yearsRoofModified BitumenNorth Low Roof1,755SF710+ yearsRoof StructureConcreteNorth Low Roof1,755SF710+ yearsRoof StructureConcreteNorth Low Roof1,755SF710+ yearsAccess LadderWest High Roof1EA710+ yearsCopingMetalWest High Roof673LF710+ yearsDownspoutsInterior DownspoutsWest High Roof205LF710+ years	
Roof - Modified BitumenMain Roof27,599SF710+ yearsRoof Structure - ConcreteMain Roof27,599SF710+ yearsCoping - MetalNorth Low Roof135LF710+ yearsDownspouts - Interior DownspoutsNorth Low Roof28LF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsAccess Ladder - MetalWest High Roof1EA710+ yearsCoping - MetalWest High Roof673LF710+ yearsDownspouts - Interior DownspoutsWest High Roof205LF710+ years	
Roof Structure - ConcreteMain Roof27,599SF710+ yearsCoping - MetalNorth Low Roof135LF710+ yearsDownspouts - Interior DownspoutsNorth Low Roof28LF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsAccess Ladder - MetalWest High Roof1EA710+ yearsCoping - MetalWest High Roof673LF710+ yearsDownspouts - Interior DownspoutsWest High Roof205LF710+ years	
Coping - MetalNorth Low Roof135LF710+ yearsDownspouts - Interior DownspoutsNorth Low Roof28LF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsAccess Ladder - MetalWest High Roof1EA710+ yearsCoping - MetalWest High Roof673LF710+ yearsDownspouts - Interior DownspoutsWest High Roof205LF710+ years	
Downspouts - Interior DownspoutsNorth Low Roof28LF710+ yearsRoof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsAccess Ladder - MetalWest High Roof1EA710+ yearsCoping - MetalWest High Roof673LF710+ yearsDownspouts - Interior DownspoutsWest High Roof205LF710+ years	
Roof - Modified BitumenNorth Low Roof1,755SF710+ yearsRoof Structure - ConcreteNorth Low Roof1,755SF710+ yearsAccess Ladder - MetalWest High Roof1EA710+ yearsCoping - MetalWest High Roof673LF710+ yearsDownspouts - Interior DownspoutsWest High Roof205LF710+ years	
Access Ladder - MetalWest High Roof1EA710+ yearsCoping - MetalWest High Roof673LF710+ yearsDownspouts - Interior DownspoutsWest High Roof205LF710+ years	
Access Ladder - MetalWest High Roof1EA710+ yearsCoping - MetalWest High Roof673LF710+ yearsDownspouts - Interior DownspoutsWest High Roof205LF710+ years	
Downspouts - Interior Downspouts West High Roof 205 LF 7 10+ years	
Roof - Modified Bitumen West High Roof 13,840 SF 7 10+ years	
Roof Hatch - Metal West High Roof 1 EA 7 10+ years	
Roof Structure - Steel / Metal Deck/ West High Roof 13,840 SF 7 10+ years	
Concrete Topping	
Walls	
Canopy - Metal Entire Building 255 SF 6 10+ years	
Canopy - Metal Entire Building 355 SF 6 10+ years	
Exterior Walls - Brick Entire Building 20,560 SF 6 10+ years	
Exterior Walls - Prefabricated Metal Panel Entire Building 3,155 SF 6 10+ years	
Wall	
Windows	
Guard - Guards perforated Entire Building 3,480 SF 6 10+ years	
Lintels - Steel Entire Building 697 LF 6 10+ years	
Storefront Windows Entire Building 362 SF 6 10+ years	
Windows - Casement Aluminum Double- Entire Building 7,024 SF 6 10+ years	
pane	
Category : Electrical Building : Main	
Group Item - Type Location Quantity UOM Rank Recommend Comments	S

Chicago Public Schools				Leif E	ricson Elem	entary Scholastic Academy 3600 W 5th AVENUE, Chicago, IL 60624
					Replacement	•
Emergency System						
Emergency A/C Power - Auditoium and Aisle Lighting	1st Floor & Entire Building	4,900	SF	6	10+ years	Building has EM panel, previously not assessed
Emergency A/C Power - Corridors and Stairs	1st Floor & Entire Building	14,000	SF	6	10+ years	Building has EM panel, previously not assessed
Emergency A/C Power - Gym	1st Floor & Entire Building	5,200	SF	6	10+ years	None uilding has EM panel
Emergency A/C Power - Lunchrooms	1st Floor & Entire Building	3,200	SF	6	10+ years	Building has EM panel
Emergency Battery Packs - Auditoium and Aisle Lighting	1st Floor & Entire Building	2	EA	6	6-10 years	Recently installed
Emergency Battery Packs - Corridors and Stairs	1st Floor & Entire Building	10	EA	6	6-10 years	Recently installed
Exit Signs - Auditoium	1st floor & Entire Building	11	EA	6	6-10 years	Recently replaced, which includes now battery packs
Exit Signs - Corridors and Stairs	1st floor & Entire Building	14	EA	6	6-10 years	
Exit Signs - Gym	1st floor & Entire Building	4	EA	6	6-10 years	
Exit Signs - Lunchroom	1st floor & Entire Building	6	EA	6	6-10 years	
UPS - Less than 30 KW	Basement	1	EA	5	6-10 years	2008 installation, serve emergency building systems only. Recently upgraded. Previously not assessed. In basement
Automatic Transfer Switch	Electrical Room	2	EA	6	10+ years	Found 2, 1 newer ATS serves UPS, other older ATS serves independent service
Security System - CCTV	Entire Building	74,410	SF	5	6-10 years	
Security System - Intrusion Detection	Entire Building	74,410	SF	5	6-10 years	
Main Service						
Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Now locked cabinet, secured, safe, not live
Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	Older ATS, with a meter, functional
PA System	Entire Building	74,410	SF	6	6-10 years	
Power Distribution						
Lighting and Power Panels - 100 A	Entire Building	4	EA	7	10+ years	
Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	Functional panels are rated 7, and with a 10+ remaining life
Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	č
Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	EM panel with fuses
Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	Previously not assessed
Main Distribution Panels - Greater than 600	Entire Building	2	EA	7	10+ years	Functional panels rated 7



Replacement

amp

	Category	2	Fire	Protection
--	----------	---	------	------------

Category : Fire Protection			В	uilding	: Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Fire Alar		2004.011	Quantity			Rophacoment		
	Fire Alarm Panel	Boiler Room & Entire Building	1	EA	3	2-5 years	Older, 30+ years old, not reliable	
	Fire Alarm Strobe Lights	Boiler Room & Entire Building	74,300	SF	6	6-10 years	····,···,···,····	
	Fire Alarm_System	Boiler Room & Entire Building	74,300	SF	5	6-10 years	Using older fire alarm panel	
Catego	ry : Mechanical		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Air Cond								
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years	Serves MDF room evaporating unit. Mating half in MDF room not assessed	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	2	EA	6	6-10 years	Serves office and classroom evaporating units. Mini split system.	
Air Hand	lling Systems							
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	2	EA	5	6-10 years	Evaporating units. Mini split system. Previously not assessed, A third unit in MDF room is not assessed	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 20001-30000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 1, serves auditorium	
	Air Intake	Mechanical Room	1	EA	5	6-10 years	Not painted	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - 8001-12000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 2, serves corridors, both floors. Serves multiple (12) dampers	
	Air Intake	Mechanical Room	1	EA	5	6-10 years	Not painted	
	Zone Dampers	Mechanical Room	12	EA	5	6-10 years	Built into (on top of) air handler, Belimo actuators	
	Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM	Mechanical Room	1	EA	5	6-10 years	Serves auditorium, a return fan, RF 1 serves auditorium AHU 1.	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - 4000-8000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 3, serves gym, difficult to access because of stored items next to AHU in mechanical room	
	Air Intake	Mechanical Room	1	EA	6	6-10 years		
Boiler Sy	vstems							
,	Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	6	6-10 years		
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years		
	Combustion Dampers	Boiler Room	2	EA	6	10+ years		



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Non Condensing- Scotch Marine- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	6	10+ years	Serve main building
	Water Fill System	Boiler Room	1	EA	6	6-10 years	Tank and pump
Gas Boo	oster						
	Gas Booster	Boiler Room	2	EA	5	6-10 years	
Heating	Devices						
•	Wall Heater - Electric	1st Floor	5	EA	6	10+ years	
	Unit Heater - Hot Water	Boiler Room	1	EA	6	10+ years	
	Fin Tube - Hot Water	Entire Building	700	LF	5	10+ years	Occasional leaks repaired
	Cabinet Heaters - With Hot Water Coil	Entire Building	11	EA	5	6-10 years	Previously not assessed
	Unit Heater - Hot Water	Mechanical Room	1	EA	6	6-10 years	Second floor, ceiling mounted
Mechani	ical Plumbing						
	Hot Water Pump - 10 - 20 HP	Boiler Room	2	EA	6	6-10 years	Serve 2 boilers
	Hot Water Pump - Less than 10	Boiler Room	8	EA	6	6-10 years	Serve air handlers and cabinet heaters
	Hydronic Supply and Return - Copper	Entire Building	100	LF	6	10+ years	Previously not assessed
	Hydronic Supply and Return - Steel	Entire Building	800	LF	6	6-10 years	1962 installation
Tempera	ature Control						
	DDC System	Entire Building	74,410	SF	4	2-5 years	Does not work well. Operates in default mode, manually operated
	Electric Thermostat	Entire Building	10	EA	5	6-10 years	Serves cabinet heaters, unit heater mini split systems. Previously not assessed
	Thermostats - DDC	Entire Building	2	EA	4	1-2 years	BAS does not communicate with thermostats. Dampers are manual operated
	Thermostats - DDC	Entire Building	3	EA	4	1-2 years	BAS does not communicate with thermostats. Dampers are manually operated
	Thermostats - DDC	Entire Building	32	EA	4	2-5 years	Needs to be calibrated or repaired.
Unit Ver							
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	30	EA	6	10+ years	
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	7	EA	5	6-10 years	Occasional repair needed

Ventilation



Catego	ry : Mechanical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exhaust Fans- Indoor - 1501 - 8000 CFM	1st Floor and Roof	1	EA	5	6-10 years	Serves restrooms. No return fans fo restrooms, previously assessed as a return fan. Restrooms have exhaust fans, not return fans, for hygiene reasons. Located in mechanical room. Previously assessed incorrectly.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	1st Floor and Roof	10	EA	6	10+ years	,
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	1st Floor and Roof	2	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	1st Floor and Roof	33	EA	6	10+ years	
	Type I Exhaust Hood- Kitchen	1st Floor and Roof	1	EA	2	0-1 year	No fire suppression
Catego	ry : Plumbing		В	uilding	: Main		
_						Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate				= .	_		O
	Electric Heater - Less than 20 KW	1st Floor	1	EA	5	6-10 years	Serves dishwasher, booster heater, previously not assessed
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Recently replaced, tankless
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	Tankless, serves main building
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Boiler Room	1	EA	5	6-10 years	Serves both water heaters
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	74,410	SF	6	6-10 years	1962 installation
	Domestic Piping-Hot Water Return Risers	Entire Building	74,410	SF	6	6-10 years	Functional
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	74,410	SF	6	6-10 years	There are a few pipe clamps
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	74,410	SF	6	6-10 years	There are a few pipe clamps
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	74,410	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	74,410	SF	6	6-10 years	Functional, minor leaks occasionally repaired
	Sanitary Piping	Entire Building	74,410	SF	5	6-10 years	
	Storm Piping	Entire Building	74,410	SF	5	6-10 years	
	Vent Piping	Entire Building	74,410	SF	5	6-10 years	
Pumps							



Category : Plumbing					: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
							pressure is acceptable withou a booster pump
	Pumps - Ejector-Duplex	1st floor & Boiler Room	1	EA	5	6-10 years	
	Pumps - Sump-Simplex	1st floor & Boiler Room	1	EA	6	6-10 years	previously not assessed, under elevator

Catego	ry : Room	Building : Main					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	1st Floor - Main Office & Principal?s Office	3	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor - Main Office & Principal?s Office	622	SF	7	10+ years	
	Doors - Side-lite	1st Floor - Main Office & Principal?s Office	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Main Office & Principal?s Office	3	EA	7	10+ years	
	Floor - Tile	1st Floor - Main Office & Principal?s Office	581	SF	7	10+ years	
	Floor - Tile	1st Floor - Main Office & Principal?s Office	44	SF	6	10+ years	
	Floor - Tile	1st Floor - Main Office & Principal?s Office	5	SF	5	1-2 years	Cracking
	Lighting - Pendent/Surface	1st Floor - Main Office & Principal?s Office	26	EA	7	10+ years	
	Power Distribution	1st Floor - Main Office & Principal?s Office	14	EA	7	10+ years	
	Storage/ Closet	1st Floor - Main Office & Principal?s Office	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor - Main Office & Principal?s Office	742	SF	7	10+ years	
	Work SInk	1st Floor - Main Office & Principal?s Office	1	EA	7	10+ years	
	AC Unit	1st Floor - Nurse?s Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor - Nurse?s Office	186	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - Nurse?s Office	2	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Nurse?s Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Nurse?s Office	186	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Nurse?s Office	6	EA	7	10+ years	
	Power Distribution	1st Floor - Nurse?s Office	8	EA	7	10+ years	
	Walls - Concrete Block	1st Floor - Nurse?s Office	345	SF	7	10+ years	
	Work SInk	1st Floor - Nurse?s Office	1	EA	7	10+ years	
	Ceiling - Lay-in	1st Floor - Room 112	90	SF	7	10+ years	



Catego	ry : Room		R	uilding	: Main		3600 W 5th AVENUE, Chicago, IL 60624
Calego	.,		_	anang		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor - Room 112	8	SF	5	0-1 year	Water damaged and broken tiles
	Doors - Side-lite	1st Floor - Room 112	36	SF	7	10+ years	C C
	Doors - Wood Doors inclu hw	1st Floor - Room 112	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Room 112	98	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Room 112	2	EA	7	10+ years	
	Power Distribution	1st Floor - Room 112	2	EA	7	10+ years	
	Storage/ Closet	1st Floor - Room 112	60	SF	7	10+ years	
	Walls - Concrete Block	1st Floor - Room 112	246	SF	7	10+ years	
	Ceiling - Lay-in	Counseler's Office (Inside Room 101)	146	SF	7	10+ years	
	Ceiling - Lay-in	Counseler's Office (Inside Room 101)	2	SF	5	1-2 years	Missing tile
	Doors - Side-lite	Counseler's Office (Inside Room 101)	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Counseler's Office (Inside Room 101)	1	EA	7	10+ years	
	Floor - Tile	Counseler's Office (Inside Room 101)	150	SF	7	10+ years	
	Lighting - Pendent/Surface	Counseler's Office (Inside Room 101)	1	EA	7	10+ years	
	Power Distribution	Counseler's Office (Inside Room 101)	2	EA	7	10+ years	
	Walls - Concrete Block	Counseler's Office (Inside Room 101)	189	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Office	88	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office	88	SF	6	6-10 years	
	Lighting - Pendent/Surface	Engineer's Office	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	Engineer's Office	112	SF	6	10+ years	
	Ceiling - Lay-in	Gym Teacher's Office	112	SF	6	10+ years	
	Doors - Side-lite	Gym Teacher's Office	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gym Teacher's Office	1	EA	7	10+ years	
	Floor - Tile	Gym Teacher's Office	112	SF	7	10+ years	
	Lighting - Pendent/Surface	Gym Teacher's Office	4	EA	7	10+ years	
	Power Distribution	Gym Teacher's Office	4	EA	7	10+ years	
	Walls - Concrete Block	Gym Teacher's Office	321	SF	7	10+ years	
	Ceiling - Lay-in	Men's Teacher's Lounge, 2nd Floor	340	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Men's Teacher's Lounge, 2nd Floor	1	EA	7	10+ years	
	Floor - Tile	Men's Teacher's Lounge, 2nd Floor	340	SF	7	6-10 years	
	Lighting - Pendent/Surface	Men's Teacher's Lounge, 2nd Floor	7	EA	7	6-10 years	
	Power Distribution	Men's Teacher's Lounge, 2nd Floor	4	EA	7	10+ years	
	Walls - Concrete Block	Men's Teacher's Lounge, 2nd Floor	442	SF	7	10+ years	
	AC Unit	Room 224, Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Room 224, Office	130	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		Sood W Still AVEINDE, Chicago, IE 00024
calogo	· · · · · · · · · · · · · · · · · · ·					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
P.	Doors - Wood Doors inclu hw	Room 224, Office	1	EA	6	10+ years	
	Floor - Tile	Room 224, Office	130	SF	6	6-10 years	
	Lighting - Pendent/Surface	Room 224, Office	4	EA	7	6-10 years	
	Power Distribution	Room 224, Office	4	EA	6	10+ years	
	Walls - Concrete Block	Room 224, Office	169	SF	6	10+ years	
	Ceiling - Lay-in	Women Teacher's Lounge, Room 225	340	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Women Teacher's Lounge, Room 225	1	EA	7	10+ years	
	Floor - Tile	Women Teacher's Lounge, Room 225	340	SF	6	6-10 years	
	Lighting - Pendent/Surface	Women Teacher's Lounge, Room 225	7	EA	7	6-10 years	
	Power Distribution	Women Teacher's Lounge, Room 225	4	EA	6	10+ years	
	Walls - Concrete Block	Women Teacher's Lounge, Room 225	442	SF	6	10+ years	
_Auditoriu	um & Theater						
	Ceiling - Plaster/Drywall	1st Floor	3,572	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	10	EA	7	10+ years	
	Floor - Tile	1st Floor	3,562	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	30	EA	7	10+ years	
	Main Floor Seating	1st Floor	308	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	10+ years	
	Stage	1st Floor	946	SF	7	10+ years	
	Stage Curtain	1st Floor	8	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Tile	1st Floor	10	LF	7	10+ years	
	Storage/ Closet	1st Floor	294	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	5,482	SF	7	10+ years	
_Gymnas			2 5 0 4	05	7	10	
	Ceiling - Exposed	1st Floor	3,524	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	3,524	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Scoreboards	1st Floor	1	EA	7	10+ years	
	Storage/ Closet	1st Floor	356	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	3,523	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,177	SF	7	10+ years	



	Category : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Kitchen							
	Ceiling - Lay-in	1st Floor	895	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	883	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Serving Line	1st Floor	16	LF	7	10+ years	
	Storage/ Closet	1st Floor	167	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,074	SF	7	10+ years	
Library							
-	AC Unit	Room 200	2	EA	7	6-10 years	
	Ceiling - Splined	Room 200	1,251	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 200	2	EA	7	10+ years	
	Floor - Tile	Room 200	1,251	SF	7	6-10 years	
	Lighting - Pendent/Surface	Room 200	31	EA	7	6-10 years	
	Walls - Concrete Block	Room 200	1,501	SF	7	10+ years	
Lunch &	Multipurpose Room						
	AC Unit	1st Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,747	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,717	SF	7	10+ years	
	Floor - Tile	1st Floor	15	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	46	EA	7	10+ years	5
	Storage/ Closet	1st Floor	107	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,096	SF	7	10+ years	
	Ceiling - Lay-in	Faculty Lunchroom	697	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Faculty Lunchroom	2	EA	7	10+ years	
	Floor - Tile	Faculty Lunchroom	713	SF	7	10+ years	
	Lighting - Pendent/Surface	Faculty Lunchroom	20	EA	7	10+ years	
	Walls - Concrete Block	Faculty Lunchroom	869	SF	7	10+ years	
MDF_IDF	F						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	208	SF	7	10+ years	
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years	Split system
Mechanic	cal/ Service Rooms						
	Janitor's Closet	1st Floor	188	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	126	SF	7	10+ years	
	Storage Room	1st Floor	1,159	SF	7	10+ years	
	Storage Room	1st Floor	80	SF	7	10+ years	
	Storage Room	1st Floor	32	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
U				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Janitor's Closet	2nd Floor	40	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	1,888	SF	7	10+ years	
	Storage Room	2nd Floor	289	SF	7	10+ years	
	Storage Room	2nd Floor	20	SF	5	10+ years	
	Boiler Room	Basement	640	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	88	SF	7	10+ years	
	Storage Room	Basement	64	SF	7	10+ years	
	Vaults	Basement	101	SF	7	10+ years	
	Vaults	Basement	138	SF	7	10+ years	
Destroor	_						
Restroor	Accessories	1st Floor - Men	50	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor - Men	50	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Men	2	EA	7	10+ years	
	Floor - Tile	1st Floor - Men	25	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Men	25	SF	7	10+ years	
	Lavatory	1st Floor - Men	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Men	1	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor - Men	1	EA	7	10+ years	
	Walls - Concrete Block	1st Floor - Men	89	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor - Men	89	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor - Men	2	SF	5	1-2 years	Hole in wall where fixture was removed
	Water Closet	1st Floor - Men	1	EA	7	10+ years	Temoved
	Accessories	1st Floor - Women	50	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor - Women	50	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Women	2	EA	7	10+ years	
	Floor - Tile	1st Floor - Women	25	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Women	25	SF	7	10+ years	
	Lavatory	1st Floor - Women	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Women	1	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor - Women	1	EA	7	10+ years	
	Walls - Concrete Block	1st Floor - Women	89	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor - Women	89	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor - Women	2	SF	5	1-2 years	Hole in wall where fixture was
		Ist Floor - Women	2	36	5	1-2 years	removed
	Water Closet	1st Floor - Women	1	EA	7	10+ years	
	Accessories	1st Floor North	201	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor North	201	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor North	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor North	201	SF	7	10+ years	
	Floor Drain	1st Floor North	1	EA	7	10+ years	
	Lavatory	1st Floor North	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor North	4	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		0000 W 0417/VEI/0E, 01100g0, 12 00024
j-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	1st Floor North	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor North	241	SF	7	10+ years	
	Water Closet	1st Floor North	4	EA	7	10+ years	
	Accessories	1st Floor North	194	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor North	194	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor North	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor North	194	SF	7	10+ years	
	Floor Drain	1st Floor North	1	EA	7	10+ years	
	Lavatory	1st Floor North	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor North	3	EA EA	7	10+ years	
	Partitions Urinals	1st Floor North 1st Floor North	3	EA	7 7	10+ years 10+ years	
	Walls - Structural Glazed Tile	1st Floor North	236	SF	7	•	
	Water Closet	1st Floor North	230	EA	7	10+ years 10+ years	
	Accessories	1st Floor Southwest	201	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor Southwest	201	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Southwest	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Southwest	201	SF	7	10+ years	
	Floor Drain	1st Floor Southwest	1	EA	7	10+ years	
	Lavatory	1st Floor Southwest	4	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Southwest	3	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor Southwest	2	EA	7	10+ years	
	Partitions	1st Floor Southwest	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor Southwest	241	SF	7	10+ years	
	Water Closet	1st Floor Southwest	4	EA	7	10+ years	
	Accessories	1st Floor Southwest	194	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor Southwest	194	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Southwest	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Southwest	194	SF	7	10+ years	
	Floor Drain	1st Floor Southwest	1	EA	7	10+ years	
	Lavatory	1st Floor Southwest	4	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Southwest	3	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor Southwest	2	EA	7	10+ years	
	Partitions	1st Floor Southwest	2	EA	7	10+ years	
	Urinals	1st Floor Southwest	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor Southwest	236	SF	7	10+ years	
	Water Closet	1st Floor Southwest	2	EA	7	10+ years	
	Accessories	2nd Floor	853	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	853	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	853	SF	6	6-10 years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	7	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	6-10 years	



Categor	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Wall Mounted	2nd Floor	4	EA	7	6-10 years	
	Partitions	2nd Floor	15	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,108	SF	6	10+ years	
	Water Closet	2nd Floor	15	EA	6	10+ years	
	Accessories	2nd Floor	817	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	807	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	10	SF	5	0-1 year	Damaged
	Floor - Tile Ceramic/ Porcelain	2nd Floor	817	SF	6	6-10 years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	7	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	6-10 years	
	Lighting - Wall Mounted	2nd Floor	4	EA	7	6-10 years	
	Partitions	2nd Floor	6	EA	7	10+ years	
	Urinals	2nd Floor	8	EA	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,021	SF	6	10+ years	
	Water Closet	2nd Floor	6	EA	6	10+ years	
	Accessories	Auditorium	52	SF	7	6-10 years	
	Ceiling - Lay-in	Auditorium	52	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Auditorium	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Auditorium	52	SF	7	10+ years	
	Lavatory	Auditorium	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Auditorium	1	EA	7	10+ years	
	Lighting - Wall Mounted	Auditorium	1	EA	6	10+ years	
	Partitions	Auditorium	1	EA	5	10+ years	
	Walls - Structural Glazed Tile	Auditorium	225	SF	7	10+ years	
	Water Closet	Auditorium	1	EA	7	10+ years	Needs cleaning
	Accessories	In Principal?s Office	50	SF	7	6-10 years	
	Ceiling - Lay-in	In Principal?s Office	50	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Principal?s Office	2	EA	7	10+ years	
	Floor - Tile	In Principal?s Office	18	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Principal?s Office	32	SF	7	10+ years	
	Lavatory	In Principal?s Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Principal?s Office	2	EA	7	10+ years	
	Lighting - Wall Mounted	In Principal?s Office	1	EA	7	10+ years	
	Walls - Concrete Block	In Principal?s Office	94	SF	7	10+ years	
	Walls - Structural Glazed Tile	In Principal?s Office	155	SF	7	10+ years	
	Water Closet	In Principal?s Office	1	EA	7	10+ years	
	Accessories	In Room 109	45	SF	7	6-10 years	
	Ceiling - Lay-in	In Room 109	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Room 109	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Room 109	45	SF	6	6-10 years	
	Lavatory	In Room 109	1	EA	6	10+ years	
	Lighting - Pendent/Surface	In Room 109	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	In Room 109	76	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
e alege	· • · · · · · · · · · · · · · · · · · ·		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	In Room 109	1	EA	6	10+ years	
	Accessories	In Room 111	45	SF	7	6-10 years	
	Ceiling - Lay-in	In Room 111	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Room 111	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Room 111	45	SF	6	6-10 years	
	Lavatory	In Room 111	1	EA	6	10+ years	
	Lighting - Pendent/Surface	In Room 111	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	In Room 111	76	SF	6	10+ years	
	Water Closet	In Room 111	1	EA	6	10+ years	
	Accessories	In room 115	10	SF	7	10+ years	
	Ceiling - Lay-in	In room 115	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In room 115	1	EA	7	10+ years	
	Floor - Tile	In room 115	45	SF	7	6-10 years	
	Lavatory	In room 115	1	EA	7	10+ years	
	Lighting - Chandelier, Incandescent	In room 115	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	In room 115	120	SF	7	10+ years	
	Water Closet	In room 115	1	ĒΑ	7	10+ years	
	Accessories	In the Kitchen Area	52	SF	7	6-10 years	
	Ceiling - Lay-in	In the Kitchen Area	52	SF	7	10+ years	
	Ceiling - Lay-in	In the Kitchen Area	2	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	In the Kitchen Area	2	ĒA	7	10+ years	
	Floor - Tile	In the Kitchen Area	27	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In the Kitchen Area	25	SF	7	10+ years	
	Lavatory	In the Kitchen Area	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In the Kitchen Area	1	EA	7	10+ years	
	Partitions	In the Kitchen Area	1	EA	7	10+ years	
	Student Lockers - One Tier	In the Kitchen Area	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	In the Kitchen Area	70	SF	7	10+ years	
	Water Closet	In the Kitchen Area	1	EA	7	10+ years	
	Accessories	In the Men's Lounge, 2nd Floor	35	SF	5	6-10 years	Sink out of order
	Ceiling - Lay-in	In the Men's Lounge, 2nd Floor	35	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In the Men's Lounge, 2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In the Men's Lounge, 2nd Floor	35	SF	7	10+ years	
	Lavatory	In the Men's Lounge, 2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In the Men's Lounge, 2nd Floor	1	EA	7	10+ years	
	Lighting - Wall Mounted	In the Men's Lounge, 2nd Floor	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	In the Men's Lounge, 2nd Floor	89	SF	7	10+ years	
	Water Closet	In the Men's Lounge, 2nd Floor	1	EA	7	10+ years	
	Accessories	Near Door 5	52	SF	7	6-10 years	
	Ceiling - Lay-in	Near Door 5	50	SF	7	10+ years	
	Ceiling - Lay-in	Near Door 5	2	SF	5	0-1 year	Remodeling in progress
	Doors - Wood Doors inclu hw	Near Door 5	2	EA	7	10+ years	Kemodeling in progress
	Floor - Tile Ceramic/ Porcelain	Near Door 5	52	SF	7	10+ years	
		Near Door 5	52	EA	7	10+ years	
	Lavatory	NGAL DUUL J	1	LA	1	IUT years	



Building : Main Category : Room Recommend Item - Type Quantity UOM Location Group Rank **Replacement** Comments Lighting - Pendent/Surface 10+ years Near Door 5 ΕA 1 7 Lighting - Wall Mounted Near Door 5 1 ΕA 7 10+ years Near Door 5 2 10+ years Partitions ΕA 7 Walls - Structural Glazed Tile Near Door 5 SF 10+ years 221 7 Walls - Structural Glazed Tile SF 0-1 year Remodeling in progress Near Door 5 4 4 Water Closet Near Door 5 ΕA 7 10+ years 1

Category : Classroom			Building : Main					
-			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	m #101 (Counseling Room)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Ceiling - Lay-in	1st Floor	240	SF	6	10+ years		
	Chalk Board	1st Floor	14	LF	4	2-5 years		
	Doors - Side-lite	1st Floor	14	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	240	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years		
	Storage/ Closet	1st Floor	14	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	306	SF	6	10+ years		
Classroo	m #102 (Pre School)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	14	LF	6	10+ years		
	Ceiling - Lay-in	1st Floor	820	SF	6	6-10 years		
	Chalk Board	1st Floor	12	LF	4	2-5 years		
	Doors - Side-lite	1st Floor	14	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	840	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years		
	Marker Board	1st Floor	12	LF	6	6-10 years		
	Storage/ Closet	1st Floor	14	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	905	SF	6	10+ years		
Classroo	m #103 (Regular Classroom)							
	AC Units	1st Floor	2	EA	7	6-10 years		
	Ceiling - Lay-in	1st Floor	810	SF	6	10+ years		
	Ceiling - Lay-in	1st Floor	0	SF	4	2-5 years	Tiles replaced	
	Doors - Side-lite	1st Floor	14	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	840	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years		
	Marker Board	1st Floor	12	LF	6	6-10 years		



Category : Classroom		B	uilding	3600 W Sth AVENUE, Chicago, IL 6062			
Juicgo				unung	· man	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
, o ap	Storage/ Closet	1st Floor	14	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	756	SF	6	10+ years	
				•	Ū	let jeare	
lassroo	m #104 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	840	SF	6	10+ years	
	Doors - Side-lite	1st Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	840	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	14	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	905	SF	6	10+ years	
						2	
lassroo	m #105 (Regular Classroom)						
	AC Units	1st Floor	3	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	820	SF	6	10+ years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	840	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Storage/ Closet	1st Floor	14	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	905	SF	6	10+ years	
lassroo	m #106 (Special Education)						
1000100	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	816	SF	6	10+ years	
	Doors - Side-lite	1st Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	840	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	24	LA	6	-	
	Storage/ Closet	1st Floor	14	SF	7	6-10 years 10+ years	
	Walls - Concrete Block	1st Floor	905	SF	6	•	
	Walls - Concrete Block		905	55	0	10+ years	
lassroo	m #107 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	810	SF	6	10+ years	
	Doors - Side-lite	1st Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
				SF			



Category : Classroom		В	uilding				
Ŭ				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	14	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	905	SF	6	10+ years	
lassroc	om #108 (Office)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	840	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	835	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	14	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	905	SF	6	10+ years	
lassroo	om #109 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	44	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,230	SF	6	10+ years	
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	6	10+ years	
	Floor - Tile	1st Floor	1,250	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	5	LF	6	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,308	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #110 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	798	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	2	SF	5	1-2 years	Missing tile
	Ceiling - Plaster/Drywall	1st Floor	1	SF	6	0-1 year	Hole in gypsum ceiling
	Doors - Side-lite	1st Floor	14	SF	6	10+ years	5,1
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	840	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	14	SF	7	10+ years	
				0			



Categor	ry : Classroom		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-						-	
Classroo	m #111 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	_ 44	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,250	SF	6	10+ years	
	Doors - Side-lite	1st Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,250	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	5	LF	6	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,308	SF	6	10+ years	
	Work Sink	1st Floor	1,000	EA	7	10+ years	
	WORK SINK	13(1100)	I I	LA	'	TOF years	
Classroo	m #115 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	44	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,325	SF	6	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,325	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	27	ĒA	7	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,590	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
						,	
Classroo	m #201 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	840	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	840	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	905	SF	6	10+ years	
Classroo	m #202 (Regular Classroom)						
01035100	AC Units	1st Floor	2	EA	7	6-10 years	
				SF	6	10+ years	
	Coiling Low in						
	Ceiling - Lay-in	1st Floor	840			•	
	Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw	1st Floor 1st Floor 1st Floor	840 14 1	SF SF EA	6 6	10+ years 10+ years 10+ years	



Catego	ategory : Classroom		B	uilding	: Main		
	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Tile	1st Floor	840	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Storage/ Closet	1st Floor	14	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	905	SF	6	10+ years	
						,	
Classroc	m #203 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	840	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	840	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	10+ years	
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	905	SF	6	10+ years	
						,	
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	840	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	840	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	905	SF	6	10+ years	
0							
Classroo	om #205 (Faculty Lounge) AC Units	2nd Floor			7	6.10 years	
			2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	840	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	840	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	905	SF	6	10+ years	
Classroo	om #206 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	745	SF	6	10+ years	



Catego	ry : Classroom		R	uilding	• Main		3600 W 5th AVENUE, Chicago, IL 606
Jareyo	y . 0/25510011		D	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
noup	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	756	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	ĒA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	756	SF	6	10+ years	
	Wireless System	2nd Floor	1	ËA	7	6-10 years	
lassroo	m #207 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,054	SF	6	10+ years	
lassroo	m #208 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	840	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	840	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	ĒA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	905	SF	6	10+ years	
lassroo	m #209 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	820	SF	6	6-10 years	
	Lighting - Metal Halide/Sodium Vapor	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,054	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	840	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	840	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	
	Walls - Tile	2nd Floor	905	SF	6	10+ years	
.							
Jassroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,054	SF	6	10+ years	
Classro	om #212 (Regular Classroom)						
01222100	AC Units	2nd Floor	2	EA	7	6-10 years	
		2nd Floor		SF			
	Ceiling - Lay-in		840		6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	840	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	905	SF	6	10+ years	
Classroo	om #213 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lav-in	2nd Floor	820	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	14	EA	6	10+ years	
	Floor - Tile	2nd Floor	820	SF	6	6-10 years	
			620	Эг	U	0-10 years	



Category : Classroom			В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,054	SF	6	10+ years	
lassroc	m #214 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	840	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	840	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	905	SF	6	10+ years	
lassroc	m #215 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	820	SF	6	6-10 years	
	Lighting - Metal Halide/Sodium Vapor	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,054	SF	6	10+ years	
		210 1001	1,054	36	0	10+ years	
lassroo	m #216 (Regular Classroom)				7	C 10 vicence	
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,054	SF	6	10+ years	
lassroc	m #217 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	



					. Malu		3600 W 5th AVENUE, Chicago, IL 6062
Category : Classroom		В	uilding				
•••• ••	Ham Truce	Leastion	Quentitu		Dauk	Recommend	Commente
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,054	SF	6	10+ years	
lassroo	om #218 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,054	SF	6	10+ years	
laeeroo	om #219 (Regular Classroom)						
71000100	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	14	EA	7	10+ years	
	Floor - Tile	2nd Floor	820	SF	6	6-10 years	
		2nd Floor	20	EA			
	Lighting - Lay-in Marker Board	2nd Floor 2nd Floor	20 16		7 6	6-10 years	
	Storage/ Closet	2nd Floor 2nd Floor	10	SF	6 7	6-10 years	
				SF	6	10+ years	
	Walls - Concrete Block	2nd Floor	1,054	55	6	10+ years	
lassroc	om #220 (Science Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	808	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	808	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	C	0.10	
			16	SF	6	6-10 years	



Walls - Concrete Block

Walls - Structural Glazed Tile

Category : Classroom			В	Ŧ			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	1,025	SF	6	10+ years	
Classroo	om #222 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,054	SF	6	10+ years	
Catego	ory : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	3,796	SF	6	10+ years	
	Doors - Store Front	1st Floor	1	EA	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	2	EA	5	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	5	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	540	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	3,776	SF	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	40	SF	4	1-2 years	Cracked or missing
	Lighting - Pendent/Surface	1st Floor	13	EA	6	6-10 years	Ũ
	Stairs - Concrete Stairs	1st Floor	129	LF	6	10+ years	
	Stairs - Terrazzo	1st Floor	101	LF	6	10+ years	
	Walls - Concrete Block	1st Floor	3,842	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	720	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	3,816	SF	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	3,806	SF	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	10	SF	5	1-2 years	Damaged
	Lighting - Pendent/Surface	2nd Floor	13	EA	7	6-10 years	2
	Stairs - Concrete Stairs	2nd Floor	129	LF	6	10+ years	
	Stairs - Terrazzo	2nd Floor	101	LF	6	10+ years	
			0.040	0-	~	10	

SF

SF

6

6

3,842

540

10+ years

10+ years

atetv	/
,	

v							
<u>у</u>	Camera Viewing Station Security Cameras Security Cameras	Entire Building Entire Building Entire Building	1 10 4	EA EA EA	7 7 4	6-10 years 6-10 years 0-1 year	Not working
	Occurry Cameras		4	LA	-	0-i yeai	

2nd Floor

2nd Floor



Category : Interior			В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Stairs							
	Ceiling - Splined	Main Lobby (Only)	6,960	SF	6	10+ years	
	Floor - Terrazzo	Main Lobby (Only)	6,960	SF	6	10+ years	
	Handrails	Main Lobby (Only)	30	LF	7	10+ years	
	Lighting - Chandelier, Incandescent	Main Lobby (Only)	8	EA	7	6-10 years	
	Lighting - Pendent/Surface	Main Lobby (Only)	8	EA	7	6-10 years	
	Stairs - Terrazzo	Main Lobby (Only)	89	LF	6	10+ years	
	Walls - Structural Glazed Tile	Main Lobby (Only)	7,129	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Main Staircase (All Floors)	352	SF	6	10+ years	
	Floor - Terrazzo	Main Staircase (All Floors)	352	SF	6	10+ years	
	Handrails	Main Staircase (All Floors)	120	LF	7	10+ years	
	Lighting - Pendent/Surface	Main Staircase (All Floors)	4	EA	7	6-10 years	
	Lighting - Wall Mounted	Main Staircase (All Floors)	4	EA	7	6-10 years	
	Stairs - Terrazzo	Main Staircase (All Floors)	446	LF	6	10+ years	
	Walls - Structural Glazed Tile	Main Staircase (All Floors)	400	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Northwest	176	SF	6	10+ years	
	Floor - Tile	Northwest	176	SF	6	6-10 years	
	Handrails	Northwest	60	LF	7	10+ years	
	Lighting - Pendent/Surface	Northwest	1	EA	7	6-10 years	
	Lighting - Wall Mounted	Northwest	2	EA	7	6-10 years	
	Stairs - Tile	Northwest	223	LF	6	10+ years	
	Walls - Structural Glazed Tile	Northwest	200	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Southwest	176	SF	6	10+ years	
	Floor - Tile	Southwest	176	SF	6	6-10 years	
	Handrails	Southwest	60	LF	7	10+ years	
	Lighting - Pendent/Surface	Southwest	1	EA	7	6-10 years	
	Lighting - Wall Mounted	Southwest	2	EA	7	6-10 years	
	Stairs - Tile	Southwest	223	LF	6	10+ years	
	Walls - Structural Glazed Tile	Southwest	200	SF	6	10+ years	
/ertical (
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years	



Category : Site			В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	3	1-2 years	Per Site Engineer this catch basin is damaged
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	8	EA	6	10+ years	
Fencing							
	Fencing - Chain Link	Entire Site	106	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	994	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	30	LF	5	2-5 years	
Landsca	ре						
	Benches	Entire Site	2	EA	4	1-2 years	Missing pieces
	Landscape - Grass	Entire Site	11,560	SF	6	10+ years	
	Parkway trees	Entire Site	12	EA	6	10+ years	Tree/Tree Roots causing
							heave/damage at perimeter
							sidewalks at several trees
	Planting Beds/ Area	Entire Site	2,050	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	45,600	SF	4	1-2 years	Excessive deterioration, cracks throughout
	Play Area - Hardscape- Asphalt	Entire Site	3,450	SF	4	2-5 years	Excessive deterioration, cracks throughout
	Play Area - Hardscape- Asphalt	Entire Site	3,200	SF	4	0-1 year	Excessive deterioration, cracks throughout
	Retaining Wall - Concrete	Entire Site	220	SF	6	10+ years	
	Trash Receptacles	Entire Site	3	ĒA	6	2-5 years	
Parking I	Lot						
0	Concrete Curbs	Parking Lot- North	346	LF	6	10+ years	
	Concrete Curbs	Parking Lot- North	55	LF	4	1-2 years	Broken/Cracked/Damaged
	Surface - Asphalt	Parking Lot- North	7,680	SF	4	1-2 years	Broken and major cracking with separating of asphalt/Spider webbin material deterioration.
Playgrou	Ind						
	Equipment - Pre K 3-5	South Courtyard	1	EA	6	2-5 years	
	Surface - Poured Surface	South Courtyard	1,376	SF	5	2-5 years	
	Equipment - School Age 5-12	West Courtyard	1	EA	6	2-5 years	
	Surface - Poured Surface	West Courtyard	2,545	SF	5	2-5 years	



Category : Site			В	uilding	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Sidewalk					-		
	Sidewalks - Internal Walks	Entire Site	358	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	30	LF	4	1-2 years	Badly Broken/Cracked - significant damage
	Sidewalks - Perimeter Sidewalks	Entire Site	11,550	SF	5	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	150	SF	4	1-2 years	Broken/cracked/Missing pieces of concrete. Heaving/settling and badly pitched - leaning/tilted toward parkway.
Signage							
	Flag Pole - Flag Pole	Southeast	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Southeast	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Southeast	2	EA	6	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

• Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated

Unit means the generally accepted standard unit of measure for each items. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like ٠ chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main					1	I			
Computer Lab	Regular Classroom	2nd Floor	206	206	745	101	16	N	N
Counseling Room	Regular Classroom	1st Floor	101	101	240	12	12	N	N
Faculty Lounge	Regular Classroom	2nd Floor	205	205	840	108	16	N	N
Kindergarten	Kindergarten	1st Floor	109	109	1,250	155	24	N	N
Kindergarten	Kindergarten	1st Floor	111	111	1,250	162	24	N	N
Kindergarten	Kindergarten	1st Floor	115	115	1,325	162	24	N	Y
Office	Regular Classroom	1st Floor	108	108	840	108	16	N	N
Pre School	Regular Classroom	1st Floor	102	102	840	108	16	N	N
Pre School	Regular Classroom	1st Floor	104	104	840	108	16	N	Ν
Regular Classroom	Regular Classroom	1st Floor	103	103	840	108	16	N	Ν
Regular Classroom	Regular Classroom	1st Floor	105	105	840	104	16	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	840	108	16	N	Ν
Regular Classroom	Regular Classroom	1st Floor	110	110	840	108	16	N	Ν
Regular Classroom	Regular Classroom	1st Floor	202	202	840	108	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	201	201	840	108	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	203	203	840	108	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	204	204	840	108	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	207	207	820	108	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	208	208	840	108	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	209	209	820	108	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	210	210	840	108	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	211	211	820	108	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	212	212	840	108	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	213	213	820	108	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	214	214	840	108	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	215	215	820	90	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	216	216	820	90	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	217	217	820	90	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	218	218	820	90	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	219	219	820	90	16	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	222	222	820	90	16	N	Ν
Science Classroom	Regular Classroom	2nd Floor	220	220	808	90	16	N	Ν
Special Education	Regular Classroom	1st Floor	106	106	840	108	16	N	Ν