

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1925	2	76,762
Modular 1 (4-Classroom)	2003	1	4,950
Campus Total			81,712

Category : Exterior Building : Main

Calcyc	Ty . Exterior			unung	. IVICIII		
0	N T	Laadlan	0	HOM	D	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance	9						
	Entrance Control - Audio and Video	#1- Main- SE	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#1- Main- SE	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1- Main- SE	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#1- Main- SE	11	LF	6	10+ years	
	Exterior Stairs - Stone	#1- Main- SE	66	LF	4	0-1 year	Settlement at steps. Large gaps are a trip hazard
	Ramps - Concrete	#1- Main- SE	100	LF	6	10+ years	·
	Stair Handrail - Steel_Stair Handrail	#1- Main- SE	24	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#10 - E	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#10 - E	1	EA	6	6-10 years	
	Exterior Stairs - Stone	#10 - E	90	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#11 - E	1	EΑ	4	0-1 year	Door slab rusted at bottom
	Exterior Doors - Transom Lite	#11 - E	2	EA	6	6-10 years	
	Ramps - Concrete	#11 - E	35	LF	6	10+ years	
	Entrance Control - Audio and Video	#1B - Boiler House - W	1	EΑ	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#1B - Boiler House - W	2	EΑ	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#2 - S	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#2 - S	1	EA	6	6-10 years	
	Exterior Stairs - Stone	#2 - S	72	LF	5	10+ years	
	Exterior Doors - Exterior Steel Door	#2B - Boiler House - N	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#2B - Boiler House - N	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#3 - S	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#3 - S	1	EA	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Main		5414 W LINGEL AVENUE, Officago, IE 00050
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Stairs - Stone	#3 - S	70	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#3 - S	5	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#3B - Chiller - NW	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#4 - SW	1	EA	6	6-10 years	
	Exterior Stairs - Steel or Aluminum	#4 - SW	5	LF	4	0-1 year	Bent and rusted
	Stair Handrail - Steel_Stair Handrail	#4 - SW	12	LF	4	0-1 year	Bent and rusted
	Exterior Doors - Exterior Steel Door	#4B - Chiller - NE	1	EA	6	6-10 years	
	Entrance Control - Audio and Video	#5 - SW	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#5 - SW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#5 - SW	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#5B - Boiler House - E	1	EA	4	0-1 year	Deteriorating door & frame.
	Exterior Doors - Transom Lite	#5B - Boiler House - E	1	EA	7	6-10 years	-
	Exterior Doors - Exterior Steel Door	#6 - W	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#6 - W	1	EA	6	6-10 years	
	Exterior Stairs - Stone	#6 - W	6	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#6.5 - Elevator - NW	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#7 - NW	1	EA	6	6-10 years	
	Exterior Stairs - Steel or Aluminum	#7 - NW	20	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#7 - NW	12	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#8 - N	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#8 - N	16	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#8 - N	120	LF	6	6-10 years	
	Ramps - Concrete	#8 - N	60	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#8 - N	18	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#9 - NE	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#9 - NE	1	EA	6	6-10 years	
	Exterior Stairs - Stone	#9 - NE	54	LF	6	10+ years	
Fire Esca	ape						
	Fire Escape	NW/SW	35	LF	5	2-5 years	
	Fire Escape	NW/SW	35	LF	5	2-5 years	
Foundati	on						
	Foundation - Concrete	Entire Building	960	LF	7	10+ years	
	Foundation - Concrete	Entire Building	19	LF	6	10+ years	
	Superstructure - Concrete	Entire Building	76,762	SF	7	10+ years	
	2.5, 2.5, 35, 35, 37, 37, 37, 37, 37, 37, 37, 37, 37, 37	9	. 5,. 52	٠.	·	.c. youro	
Lighting	Estadou Linktina Douglet as Doubline	Entire Duilding				0.40	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	20	EΑ	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	7	EA	6	6-10 years	
Roof Sys	stem						
	Chimney - Brick Chimney- Concrete/ Mortar	Boiler House Roof	70	LF	6	10+ years	
	z		70	_,	ŭ	.o. youro	



tego	ry : Exterior		В	uilding	: Main		
up	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
чР	Liner	Location	Quantity	COIII	Raine	Ropidoomont	Comments
	Chimney - Brick Chimney- Concrete/ Mortar	Boiler House Roof	20	LF	5	10+ years	
	Liner				-	, , , , , , , , , , , , , , , , , , , ,	
	Coping - Stone	Boiler House Roof	210	LF	6	10+ years	
	Downspouts - Interior Downspouts	Boiler House Roof	20	LF	6	6-10 years	
	Parapet - Parapet > 30"	Boiler House Roof	210	LF	6	10+ years	
	Roof - Modified Bitumen	Boiler House Roof	2,755	SF	6	6-10 years	
	Roof Structure - Concrete	Boiler House Roof	2,755	SF	7	10+ years	
	Coping - Stone	Elevator NW Roof	33	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Elevator NW Roof	35	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Elevator NW Roof	23	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Elevator NW Roof	10	LF	6	10+ years	
	Roof - Modified Bitumen	Elevator NW Roof	140	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/	Elevator NW Roof	140	SF	6	10+ years	
	Concrete Topping	Lievator 1444 Roof	140	Oi.	U	101 years	
	Coping - Stone	Low E Roof	54	LF	6	10+ years	
	Parapet - Parapet > 30"	Low E Roof	54	LF	6	10+ years	
	Roof - Metal	Low E Roof	86	SF	4	0-1 year	Leaking into room 103
	Roof Structure - Concrete	Low E Roof	86	SF	6	10+ years	Leaking into room 105
	Access Ladder - Metal	Main Roof	4	EA	5	2-5 years	
	Coping - Metal	Main Roof	28	LF	6	6-10 years	
	Coping - Stone	Main Roof	951	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	10	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Main Roof	444	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Main Roof	40	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Main Roof	28	LF	6	10+ years	
	Parapet - Parapet < 10 Height	Main Roof	911	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	28,468	SF	5	2-5 years	
	Roof - Modified Bitumen	Main Roof	20,400 50	SF	3	0-1 year	Cracks and bubbling
	Roof Hatch - Metal	Main Roof	4	EA	3 7	•	Cracks and bubbling
	Roof Structure - Concrete	Main Roof	28,518	SF	7	10+ years 10+ years	
	Roof Structure - Concrete	Main Rooi	20,310	SF	,	10+ years	
alls							
	Cheek-Wall - Concrete	Entire Building	18	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	45	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	76	SF	6	10+ years	
	Cornice - Cast Stone	Entire Building	979	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	33,895	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	4,118	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	130	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	2,258	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	1,000	SF	4	0-1 year	Cracked stone at entry

Campus Name: Farnsworth Page: 3 of 30 Assessment Date: 11/09/2021



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	_
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Curtain wall - Louver	Entire Building	7	SF	5	2-5 years	
	Guard - Guards perforated	Entire Building	351	SF	6	6-10 years	
	Lintels - Steel	Entire Building	601	LF	6	10+ years	
	Lintels - Steel	Entire Building	20	LF	5	6-10 years	
	Lintels - Stone	Entire Building	450	LF	6	10+ years	
	Skylite - Glass Double-Pane	Entire Building	24	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,796	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	378	SF	6	6-10 years	
	Windows - Wood- Single-pane	Entire Building	136	SF	5	2-5 years	
atego	ry : Electrical		В	uilding	: Main		
			0		D	Recommend	•
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
nerger	ncy System Automatic Transfer Switch	Electrical Room	2	EA	6	10+ years	
				SF			
	Security System - CCTV	Entire Building	76,762		5	6-10 years	
	Security System - Intrusion Detection	Entire Building	76,762	SF	5	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	4	EA	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,817	SF	6	10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	10,120	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	2,746	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	1,815	SF	6	10+ years	
		<u> </u>			_		III a sibla
	Exit Signs - Auditoium	Entire Building	2	EΑ	4	0-1 year	Illegible
	Exit Signs - Auditoium	Entire Building	3	EA	4	2-5 years	
	Exit Signs - Corridors and Stairs	Entire Building	5	EA	4	2-5 years	According to the building engineer replaced
	Exit Signs - Corridors and Stairs	Entire Building	16	EA	4	2-5 years	
	Exit Signs - Gym	Entire Building	4	EA	4	2-5 years	
ain Sei	rvice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	76,762	SF	5	2-5 years	Every room is now throughout - phone PA system doesn't work properly



Calego	ry : Electrical		В	uilding	: Main		
_				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	ΕA	4	2-5 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	4	2-5 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	2-5 years	
Catego	ry : Fire Protection		R	uilding	· Main		
Outogo				unung	· wan	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar		_					•
	Fire Alarm Panel	Basement	1	EA	6	10+ years	
	Fire Alarm Strobe Lights	Basement	76,762	SF	6	6-10 years	
	Fire Alarm_System	Basement	76,762	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
_ · · · · · · · · · · · · · · · · · · ·			A				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group Air Cond	litioning		•			<u> </u>	Comments
•		Roof	Quantity 1	EA	Rank 7	6-10 years	Comments
•	itioning Condensing Unit- Roof Mounted - Less		•			<u> </u>	Comments
•	itioning Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder	Roof	1	EA	7	6-10 years	Comments
•	itioning Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground	Roof Site West	1	EA EA	7	6-10 years 10+ years	Comments
•	Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 151 - 200 tons	Roof Site West Site West	1	EA EA	7	6-10 years 10+ years 6-10 years	Comments
•	Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 151 - 200 tons Glycol Feed	Roof Site West	1 1 1	EA EA EA	7 6 5	6-10 years 10+ years 6-10 years 10+ years	Comments
•	Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 151 - 200 tons	Roof Site West Site West Site West	1 1 1	EA EA EA	7 6 5	6-10 years 10+ years 6-10 years	Comments
_Air Cond	Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 151 - 200 tons Glycol Feed Pipes - Chilled Water Pipe- Copper Pressure Fill System	Roof Site West Site West Site West Site West	1 1 1 1 400	EA EA EA LF	7 6 5 6 6	6-10 years 10+ years 6-10 years 10+ years 10+ years	Comments
_Air Cond	Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 151 - 200 tons Glycol Feed Pipes - Chilled Water Pipe- Copper Pressure Fill System	Roof Site West Site West Site West Site West Site West	1 1 1 1 400	EA EA EA LF EA	7 6 5 6 6 6 5	6-10 years 10+ years 6-10 years 10+ years 10+ years 6-10 years	
_Air Cond	Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 151 - 200 tons Glycol Feed Pipes - Chilled Water Pipe- Copper Pressure Fill System ling Systems Air Handling Unit- Built Up- Multi Zone- Dual	Roof Site West Site West Site West Site West	1 1 1 400 1	EA EA EA LF	7 6 5 6 6	6-10 years 10+ years 6-10 years 10+ years 10+ years	AHU- 2 served south side
_Air Cond	Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 151 - 200 tons Glycol Feed Pipes - Chilled Water Pipe- Copper Pressure Fill System	Roof Site West	1 1 1 400 1	EA EA EA LF EA	7 6 5 6 6 5	6-10 years 10+ years 6-10 years 10+ years 10+ years 6-10 years	
_Air Cond	Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 151 - 200 tons Glycol Feed Pipes - Chilled Water Pipe- Copper Pressure Fill System ling Systems Air Handling Unit- Built Up- Multi Zone- Dual Temperature Coils - 15001 - 25000 cfm Air Intake	Roof Site West Site West Site West Site West Site West Site West Basement Basement	1 1 1 400 1	EA EA EA LF EA	7 6 5 6 6 5	6-10 years 10+ years 6-10 years 10+ years 10+ years 6-10 years 6-10 years	
_Air Cond	Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 151 - 200 tons Glycol Feed Pipes - Chilled Water Pipe- Copper Pressure Fill System ling Systems Air Handling Unit- Built Up- Multi Zone- Dual Temperature Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm	Roof Site West Site West Site West Site West Site West Site West Basement Basement Basement	1 1 1 400 1	EA EA EA LF EA	7 6 5 6 6 5	6-10 years 10+ years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 10+ years	
_Air Cond	Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 151 - 200 tons Glycol Feed Pipes - Chilled Water Pipe- Copper Pressure Fill System ling Systems Air Handling Unit- Built Up- Multi Zone- Dual Temperature Coils - 15001 - 25000 cfm Air Intake	Roof Site West Site West Site West Site West Site West Site West Basement Basement	1 1 1 400 1	EA EA EA LF EA	7 6 5 6 6 5	6-10 years 10+ years 6-10 years 10+ years 10+ years 6-10 years 6-10 years	
_Air Cond	Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 151 - 200 tons Glycol Feed Pipes - Chilled Water Pipe- Copper Pressure Fill System ling Systems Air Handling Unit- Built Up- Multi Zone- Dual Temperature Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Reheat Boxes - Reheat Boxes with Hot Water Coil Return Duct Work - Indoor- Vertical Shaft	Roof Site West Site West Site West Site West Site West Site West Basement Basement Basement	1 1 1 400 1	EA EA EA LF EA	7 6 5 6 6 5	6-10 years 10+ years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 10+ years	
_Air Cond	Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 151 - 200 tons Glycol Feed Pipes - Chilled Water Pipe- Copper Pressure Fill System ling Systems Air Handling Unit- Built Up- Multi Zone- Dual Temperature Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Reheat Boxes - Reheat Boxes with Hot Water Coil Return Duct Work - Indoor- Vertical Shaft and Ducts	Roof Site West Site West Site West Site West Site West Basement Basement Basement Basement Basement Basement	1 1 1 400 1 1 1 1 7 200	EA EA LF EA EA EA EA EA	7 6 5 6 6 5 6 7	6-10 years 10+ years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 10+ years	
_Air Cond	Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 151 - 200 tons Glycol Feed Pipes - Chilled Water Pipe- Copper Pressure Fill System ling Systems Air Handling Unit- Built Up- Multi Zone- Dual Temperature Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Reheat Boxes - Reheat Boxes with Hot Water Coil Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers	Roof Site West Site West Site West Site West Site West Site West Basement Basement Basement Basement Basement Basement Basement Basement	1 1 1 400 1 1 1 1 7 200	EA EA LF EA EA EA EA EA	7 6 5 6 6 5 6 7 6	6-10 years 10+ years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	AHU- 2 served south side
_Air Cond	Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 151 - 200 tons Glycol Feed Pipes - Chilled Water Pipe- Copper Pressure Fill System ling Systems Air Handling Unit- Built Up- Multi Zone- Dual Temperature Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Reheat Boxes - Reheat Boxes with Hot Water Coil Return Duct Work - Indoor- Vertical Shaft and Ducts	Roof Site West Site West Site West Site West Site West Basement Basement Basement Basement Basement Basement	1 1 1 400 1 1 1 1 7 200	EA EA LF EA EA EA EA EA	7 6 5 6 6 5 6 7	6-10 years 10+ years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 10+ years	



Catego	ry : Mechanical		Building : Main				· · · · · · · · · · · · · · · · · · ·		
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Air Tunnel- Dual Temperature Coils - 15001 - 25000 cfm								
	- 25000 crm Air Intake	Basement	1	EA	6	10+ years			
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	5	6-10 years			
	Reheat Boxes - Reheat Boxes with Hot	Basement	6	EA	6	10+ years			
	Water Coil	Basement	O	L/\	O	101 years			
	Return Duct Work - Indoor- Vertical Shaft	Basement	200	LF	7	10+ years			
	and Ducts	2000			•	.o. you.o			
	Zone Dampers	Basement	14	EA	5	6-10 years			
	Air Handling Unit- Built Up- Single Zone w/	Basement	1	EA	6	6-10 years	AHU- 1 served Auditorium		
	Air Tunnel- Dual Temperature Coils - Less								
	than 8000 cfm								
	Air Intake	Basement	1	EA	6	6-10 years			
	Auxiliaries - Less than 8000 cfm	Basement	1	EA	6	6-10 years			
	Return Duct Work - Indoor- Vertical Shaft	Basement	200	LF	7	6-10 years			
	and Ducts	Decement	4	_^	0	0.40	ALIII A O		
	Air Handling Unit- Built Up- Multi Zone- Dual	Basement	1	EA	6	6-10 years	AHU-4 served Gym		
	Temperature Coils - Less than 8000 cfm Air Intake	Basement	1	EA	6	6-10 years			
	Auxiliaries - Less than 8000 cfm	Basement	1 1	EA	6	6-10 years			
	Return Duct Work - Indoor- Vertical Shaft	Basement	200	LF	7	6-10 years			
	and Ducts	Dasement	200	LI	,	0-10 years			
	Indoor Return Fans- Centrifugal Inline -	Basement	1	EA	7	10+ years	North tunnel-AHU-4 served		
	5000 - 10000 CFM	2400	·	`	•	.o. you.o			
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	24	EA	5	6-10 years	2014 typical of all		
	and Chilled Water	· ·				·			
	Outdoor Return Fans- Air Handling Unit	Roof	2	EA	6	6-10 years			
	Type - 10001 - 20000 CFM								
	Outdoor Return Fans- Air Handling Unit	Roof	2	EA	6	6-10 years			
	Type - 5000 - 10000 CFM								
D 11 0									
Boiler Sy		Boiler Room	2	EA		C 10	Company and proving havilations		
	Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP	Boller Room	2	EA	6	6-10 years	Served main building		
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years			
	Combustion Dampers	Boiler Room	3	EA	6	10+ years			
	Condensing- Hot Water Boiler - 1001 - 2000	Boiler Room	2	EA	6	6-10 years			
	MBH	25/10/11/00/11	4	_, .	J	o lo youlo			
	Dual Temperature Pump	Boiler Room	2	EA	6	10+ years			
	Glycol Feed System	Boiler Room	1	EA	5	6-10 years			
	•					•			
_Heating	Devices								
	Fin Tube - Hot Water	1st Floor	8	LF	5	2-5 years	Room 103 - not working per building		
							engineer		



Catego	ry : Mechanical		Building : Main				
				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Unit Heater - Gas	Boiler Room	1	EA	5	6-10 years	
	Fin Tube - Hot Water	Entire Building	48	LF	5	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	14	EA	6	10+ years	Typical
	Wall Heater - Electric	Entire Building	6	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	3	EA	4	2-5 years	
Mechani	cal Plumbing						
	Chilled Water Pump - 10 - 20 HP	Basement	4	EA	5	6-10 years	
	Hot Water Pump - 10 - 20 HP	Boiler Room	4	EA	6	6-10 years	
	Hydronic Supply and Return - Copper	Entire Building	500	LF	5	10+ years	
Tempera	ature Control						
•	DDC System	Entire Building	76,762	SF	6	10+ years	
	Electric Thermostat	Entire Building	10	EA	5	6-10 years	
	Thermostats - DDC	Entire Building	52	EA	6	10+ years	
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	2nd Floor	1	EA	5	6-10 years	
Ventilatio	on.						
ventuatio	Exhaust Fans- Indoor - Less than 500 CFM	Roof and 1st Floor Warming Kitchen	0	EA	7	6-10 years	MDF room
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof and 1st Floor Warming Kitchen	1	EA	5	6-10 years	MDI 100III
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof and 1st Floor Warming Kitchen	3	EA	6	10+ years	
	Roof Mounted Duct Work	Roof and 1st Floor Warming Kitchen	400	LF	6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Roof and 1st Floor Warming Kitchen	1	EA	6	10+ years	
Catego	ry : Plumbing		В	uilding	: Main		
0	Name Toma	Lagathan	0	HOM	Danila	Recommend	0
Group Hot Wate	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
HOL Walk	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	5	6-10 years	
Piping							
. ipiiiy	Domestic Piping-Hot Water Return Lines	Entire Building	76,762	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	76,762	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	76,762	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	76,762	SF	6	10+ years	



Catego	ry : Plumbing		Building : Main				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	76,762	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	76,762	SF	6	10+ years	
	Sanitary Piping	Entire Building	76,762	SF	6	10+ years	
	Storm Piping	Entire Building	76,762	SF	6	10+ years	
	Vent Piping	Entire Building	76,762	SF	6	10+ years	
Pumps							
•	Pumps - Domestic Booster Pump-Duplex	Basement and Boiler Room	1	EA	6	10+ years	
	Pumps - Ejector-Simplex	Basement and Boiler Room	1	EA	6	2-5 years	
	Pumps - Sump-Duplex	Basement and Boiler Room	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Basement and Boiler Room	1	EA	6	6-10 years	

Category: Room **Building: Main**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	rative Suites/Offices	Location	Quantity	OOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1.5 floor- Office in room 109	100	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1.5 floor- Office in room 109	1	EΑ	6	10+ years	
	Floor - Tile	1.5 floor- Office in room 109	100	SF	6	6-10 years	
	Lighting - Pendent/Surface	1.5 floor- Office in room 109	1	EA	7	6-10 years	
	Power Distribution	1.5 floor- Office in room 109	2	EA	6	10+ years	
	Walls - Plaster/Drywall	1.5 floor- Office in room 109	302	SF	6	10+ years	
	Ceiling - Lay-in	1st floor- Asst Principal Office/Storage	171	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor- Asst Principal Office/Storage	1	EA	6	10+ years	
	Floor - Tile	1st floor- Asst Principal Office/Storage	171	SF	6	10+ years	
	Lighting - Pendent/Surface	1st floor- Asst Principal Office/Storage	4	EA	7	6-10 years	
	Power Distribution	1st floor- Asst Principal Office/Storage	10	EA	6	10+ years	
	Walls - Plaster/Drywall	1st floor- Asst Principal Office/Storage	682	SF	6	10+ years	
	AC Unit	1st floor- Main Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st floor- Main Office	282	SF	6	10+ years	
	Doors - Transom Window	1st floor- Main Office	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor- Main Office	1	EA	6	10+ years	
	Floor - Carpet	1st floor- Main Office	85	SF	6	6-10 years	
	Floor - Tile	1st floor- Main Office	197	SF	6	6-10 years	
	Lighting - Lay-in	1st floor- Main Office	6	EA	7	6-10 years	
	Power Distribution	1st floor- Main Office	14	EA	6	10+ years	



Stroup Item - Type	
Walls - Plaster/Drywall	
AC Unit	
Ceiling - Lay-in	
Doors - Wood Doors inclu hw	
Floor - Carpet	
Lighting - Lay-in	
Power Distribution	
Walls - Plaster/Drywall 1st floor - Principal 506 SF 6 10+ years Ceiling - Lay-in 2nd flr - Teacher's Lounge 421 SF 6 10+ years Doors - Wood Doors inclu hw 2nd flr - Teacher's Lounge 1 EA 6 10+ years Floor - Tile 2nd flr - Teacher's Lounge 411 SF 6 10+ years Floor - Tile 2nd flr - Teacher's Lounge 10 SF 4 1-2 years Chipped Lighting - Pendent/Surface 2nd flr - Teacher's Lounge 5 EA 7 6-10 years Chipped Power Distribution 2nd flr - Teacher's Lounge 4 EA 6 10+ years Chipped Walls - Plaster/Drywall 2nd flr - Teacher's Lounge 718 SF 6 10+ years AC Unit Engineer office in boiler house 1 EA 7 6-10 years AC Unit Engineer office in boiler house 80 SF 7 10+ years Ceiling - Plaster/Drywall Engineer office in boiler house 1	
Ceiling - Lay-in	
Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Floor - Tile And fir - Teacher's Lounge Floor - Tile And fir - Teacher's Lounge At 1 SF 6 10+ years Floor - Tile And fir - Teacher's Lounge At 1 SF 6 10+ years Floor - Tile Lighting - Pendent/Surface And fir - Teacher's Lounge And Fir -	
Floor - Tile	
Floor - Tile	
Floor - Tile 2nd flr- Teacher's Lounge 5 EA 7 6-10 years Power Distribution 2nd flr- Teacher's Lounge 5 EA 7 6-10 years Walls - Plaster/Drywall 2nd flr- Teacher's Lounge 718 SF 6 10+ years AC Unit Engineer office in boiler house 1 EA 7 6-10 years Ceiling - Plaster/Drywall Engineer office in boiler house 80 SF 7 10+ years Doors - Wood Doors inclu hw Engineer office in boiler house 80 SF 7 6-10 years Floor - Tile Engineer office in boiler house 80 SF 7 6-10 years Lighting - Lay-in Engineer office in boiler house 2 EA 7 6-10 years Power Distribution Engineer office in boiler house 2 EA 7 6-10 years Storage/ Closet Engineer office in boiler house 30 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 30 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 30 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 30 SF 7 10+ years Floor - Carpet 1st Floor 4,067 SF 6 10+ years Ploor - Carpet 1st Floor 4 EA 6 10+ years Floor - Carpet 1st Floor 80 SF 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 2,259 SF 7 10+ years Floor - Concrete Epoxy/ Painted	
Lighting - Pendent/Surface 2nd flr- Teacher's Lounge 5 EA 7 6-10 years Power Distribution 2nd flr- Teacher's Lounge 4 EA 6 10+ years Walls - Plaster/Drywall 2nd flr- Teacher's Lounge 718 SF 6 10+ years AC Unit Engineer office in boiler house 1 EA 7 6-10 years Ceiling - Plaster/Drywall Engineer office in boiler house 80 SF 7 10+ years Doors - Wood Doors inclu hw Engineer office in boiler house 1 EA 7 10+ years Floor - Tile Engineer office in boiler house 80 SF 7 6-10 years Lighting - Lay-in Engineer office in boiler house 2 EA 7 6-10 years Power Distribution Engineer office in boiler house 10 EA 7 6-10 years Storage/ Closet Engineer office in boiler house 30 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 30 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 330 SF 7 10+ years Unitorium & Theater Balcony Seating 1st Floor 81 EA 7 10+ years Ceiling - Plaster/Drywall 1st Floor 4,067 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4,067 SF 6 10+ years Floor - Carpet 1st Floor 1,006 SF 6 6-10 years Floor - Concrete 1st Floor 802 SF 7 10+ years Floor - Concrete Floor - Concrete Epoxy/ Painted 1st Floor 2,259 SF 7 10+ years	
Power Distribution 2nd flr- Teacher's Lounge 4 EA 6 10+ years Walls - Plaster/Drywall 2nd flr- Teacher's Lounge 718 SF 6 10+ years AC Unit Engineer office in boiler house 1 EA 7 6-10 years Ceiling - Plaster/Drywall Engineer office in boiler house 80 SF 7 10+ years Doors - Wood Doors inclu hw Engineer office in boiler house 1 EA 7 10+ years Floor - Tile Engineer office in boiler house 80 SF 7 6-10 years Lighting - Lay-in Engineer office in boiler house 2 EA 7 6-10 years Power Distribution Engineer office in boiler house 10 EA 7 6-10 years Storage/ Closet Engineer office in boiler house 30 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 30 SF 7 10+ years Unditorium & Theater Balcony Seating 1st Floor 81 EA 7 10+ years Ceiling - Plaster/Drywall 1st Floor 4,067 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4,067 SF 6 10+ years Floor - Carpet 1st Floor 1,006 SF 6 6-10 years Floor - Concrete 1st Floor 802 SF 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 2,259 SF 7 10+ years Floor - Concrete Epoxy/ Painted	
Walls - Plaster/Drywall 2nd flr- Teacher's Lounge 718 SF 6 10+ years AC Unit Engineer office in boiler house 1 EA 7 6-10 years Ceiling - Plaster/Drywall Engineer office in boiler house 80 SF 7 10+ years Doors - Wood Doors inclu hw Engineer office in boiler house 1 EA 7 10+ years Floor - Tile Engineer office in boiler house 80 SF 7 6-10 years Lighting - Lay-in Engineer office in boiler house 2 EA 7 6-10 years Power Distribution Engineer office in boiler house 10 EA 7 6-10 years Storage/ Closet Engineer office in boiler house 30 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 30 SF 7 10+ years will be seen the proof of the power of the pow	
AC Unit Engineer office in boiler house 1 EA 7 6-10 years Ceiling - Plaster/Drywall Engineer office in boiler house 80 SF 7 10+ years Doors - Wood Doors inclu hw Engineer office in boiler house 1 EA 7 10+ years Floor - Tile Engineer office in boiler house 80 SF 7 6-10 years Lighting - Lay-in Engineer office in boiler house 2 EA 7 6-10 years Power Distribution Engineer office in boiler house 10 EA 7 6-10 years Storage/ Closet Engineer office in boiler house 30 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 30 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 330 SF 7 10+ years Ceiling - Plaster/Drywall 1st Floor 81 EA 7 10+ years Ceiling - Plaster/Drywall 1st Floor 4,067 SF 6 10+ years Floor - Steel Doors incl hw 1st Floor 4,067 SF 6 10+ years Floor - Carpet 1st Floor 1,006 SF 6 6-10 years Floor - Concrete Epoxy/ Painted 1st Floor 2,259 SF 7 10+ years	
Ceiling - Plaster/Drywall Engineer office in boiler house B0 SF 7 10+ years Doors - Wood Doors inclu hw Engineer office in boiler house 1 EA 7 10+ years Floor - Tile Engineer office in boiler house 80 SF 7 6-10 years Lighting - Lay-in Engineer office in boiler house 2 EA 7 6-10 years Power Distribution Engineer office in boiler house 10 EA 7 6-10 years Storage/ Closet Engineer office in boiler house 30 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 330 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 330 SF 7 10+ years Ceiling - Plaster/Drywall 1st Floor 81 EA 7 10+ years Ceiling - Plaster/Drywall 1st Floor 4,067 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Carpet 1st Floor 1,006 SF 6 6-10 years Floor - Concrete Floor - Concrete Epoxy/ Painted 1st Floor 2,259 SF 7 10+ years	
Doors - Wood Doors inclu hw Engineer office in boiler house Floor - Tile Engineer office in boiler house Lighting - Lay-in Engineer office in boiler house Engineer office in boiler house Lighting - Lay-in Engineer office in boiler house To engineer office in boiler house Engineer office in boiler house Engineer office in boiler house To engineer office in boiler house Engineer of	
Floor - Tile Engineer office in boiler house 80 SF 7 6-10 years Lighting - Lay-in Engineer office in boiler house 2 EA 7 6-10 years Power Distribution Engineer office in boiler house 10 EA 7 6-10 years Storage/ Closet Engineer office in boiler house 30 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 330 SF 7 10+ years Unditorium & Theater Balcony Seating 1st Floor 81 EA 7 10+ years Ceiling - Plaster/Drywall 1st Floor 4,067 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Carpet 1st Floor 1,006 SF 6 6-10 years Floor - Concrete 1st Floor 802 SF 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 2,259 SF 7 10+ years	
Lighting - Lay-in Engineer office in boiler house 2 EA 7 6-10 years Power Distribution Engineer office in boiler house 10 EA 7 6-10 years Storage/ Closet Engineer office in boiler house 30 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 330 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 330 SF 7 10+ years Ceiling - Plaster/Drywall 1st Floor 81 EA 7 10+ years Ceiling - Plaster/Drywall 1st Floor 4,067 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Carpet 1st Floor 1,006 SF 6 6-10 years Floor - Concrete 1st Floor 802 SF 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 2,259 SF 7 10+ years	
Power Distribution Engineer office in boiler house 30 SF 7 10+ years Storage/ Closet Engineer office in boiler house 30 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 330 SF 7 10+ years Balcony Seating	
Storage/ Closet Engineer office in boiler house 30 SF 7 10+ years Walls - Plaster/Drywall Engineer office in boiler house 330 SF 7 10+ years ditorium & Theater Balcony Seating 1st Floor 81 EA 7 10+ years Ceiling - Plaster/Drywall 1st Floor 4,067 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Carpet 1st Floor 1,006 SF 6 6-10 years Floor - Concrete 1st Floor 802 SF 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 2,259 SF 7 10+ years	
Walls - Plaster/Drywall Engineer office in boiler house 330 SF 7 10+ years Iditorium & Theater Balcony Seating Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor Floor - Carpet Floor - Concrete Floor - Concrete Floor - Concrete Epoxy/ Painted Engineer office in boiler house 330 SF 7 10+ years 81 EA 7 10+ years 4,067 SF 6 10+ years 4 EA 6 10+ years 1st Floor 1,006 SF 6 6-10 years 802 SF 7 10+ years 7 10+ years 802 SF 7 10+ years 802 SF 7 10+ years	
Balcony Seating	
Balcony Seating 1st Floor 81 EA 7 10+ years Ceiling - Plaster/Drywall 1st Floor 4,067 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Carpet 1st Floor 1,006 SF 6 6-10 years Floor - Concrete 1st Floor 802 SF 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 2,259 SF 7 10+ years	
Ceiling - Plaster/Drywall 1st Floor 4,067 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Carpet 1st Floor 1,006 SF 6 6-10 years Floor - Concrete 1st Floor 802 SF 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 2,259 SF 7 10+ years	
Ceiling - Plaster/Drywall 1st Floor 4,067 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Carpet 1st Floor 1,006 SF 6 6-10 years Floor - Concrete 1st Floor 802 SF 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 2,259 SF 7 10+ years	
Doors - Steel Doors incl hw1st Floor4EA610+ yearsFloor - Carpet1st Floor1,006SF66-10 yearsFloor - Concrete1st Floor802SF710+ yearsFloor - Concrete Epoxy/ Painted1st Floor2,259SF710+ years	
Floor - Carpet 1st Floor 1,006 SF 6 6-10 years Floor - Concrete 1st Floor 802 SF 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 2,259 SF 7 10+ years	
Floor - Concrete 1st Floor 802 SF 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 2,259 SF 7 10+ years	
Floor - Concrete Epoxy/ Painted 1st Floor 2,259 SF 7 10+ years	
= ignining i disadisada (01 100)	
Lighting - Wall Mounted 1st Floor 12 EA 6 6-10 years	
Main Floor Seating 1st Floor 279 EA 7 10+ years	
Stage 1st Floor 395 SF 6 10+ years	
Stage Curtain 1st Floor 8 EA 7 10+ years	
Stage Lift 1st Floor 1 EA 7 10+ years	
Stage Lighting System 1st Floor 1 EA 7 10+ years	
Stage-Stairs - Wood 1st Floor 7 LF 6 10+ years	
Walls - Plaster/Drywall 1st Floor 7,090 SF 6 10+ years	
Walls - Structural Glazed Tile 1st Floor 180 SF 6 10+ years	
inic	



Catego	ry : Room		В	uilding	: Main		5414 W Ellidel AVENUE, Officago, IE 00000
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	171	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	171	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	4	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	806	SF	6	10+ years	
_Gymnas	ia						
•	Ceiling - Plaster/Drywall	1st Floor	2,746	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	2,746	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure	1st Floor	12	EA	7	6-10 years	
	Sodium	1001		_, 、	•	o to youro	
	Walls - Masonry	1st Floor	3,806	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,806	SF	6	10+ years	
	walls - I laster/brywall	13111001	3,000	Oi	O	10+ years	
Kitchen	Calling Plantay/Drawall	1st Floor	500	SF		10:	
	Ceiling - Plaster/Drywall		502		6	10+ years	
	Floor - Epoxy/ Painted	1st Floor	502	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Walls - Masonry	1st Floor	203	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	68	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	405	SF	6	10+ years	
Library							
	Casework	2nd Floor	60	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,465	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Water damage
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Carpet	2nd Floor	1,473	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,895	SF	6	10+ years	
_MDF_ID	F						
_	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Finishes	1st Floor	130	SF	7	10+ years	
	Other Cooling Unit	1st Floor	1	ĒΑ	7	10+ years	Split system
	Window AC Unit	1st Floor	1	EA	7	10+ years	-17
_Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	23	SF	7	6-10 years	
	Janitor's Closet	1st Floor	23	SF	7	6-10 years	
	232. 2 3.333		20	σ.	•	3 .0 ,00.0	



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage Room	1st Floor	79	SF	7	10+ years	
	Janitor's Closet	2nd Floor	23	SF	7	10+ years	
	Janitor's Closet	2nd Floor	9	SF	7	10+ years	Quantity changed to match current observations
	Air Intake Plenums	Basement	349	SF	7	10+ years	
	Air Tunnel	Basement	206	SF	7	10+ years	
	Auditorium Plenums	Basement	2,500	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	3,145	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	10,124	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	164	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	324	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	541	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	848	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	1,782	SF	5	10+ years	
	Air Tunnel	Boiler House	240	SF	7	10+ years	
	Boiler Room	Boiler House	2,113	SF	7	10+ years	
	Coal Room	Boiler House	1,426	SF	7	10+ years	
	Mechanical/ Service Rooms	Boiler House	74	SF	7	10+ years	
	Mechanical/ Service Rooms	Boiler House	124	SF	7	-	
	Storage Room	Boiler House	290	SF	7	10+ years 10+ years	
	Vaults	Boiler House	146	SF	7	10+ years	
	radio	201101 1 10400	110	٥.	•	ioi youio	
Restroor							
	Accessories	1st Floor	95	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	95	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	95	SF	6	6-10 years	
	Floor Drain	1st Floor	1	EΑ	7	10+ years	
	Lavatory	1st Floor	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	1	EΑ	7	10+ years	
	Walls - Masonry	1st Floor	173	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	347	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	58	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	6	10+ years	
	Accessories	1st Floor	386	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	386	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	386	SF	6	6-10 years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	3	ΕA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	ΕA	7	6-10 years	
	Partitions	1st Floor	7	ΕA	7	10+ years	
			•		•	,	



Group Item - Type Location Quantity UOM Rank Replacement Comments Walls - Masonry 1st Floor 360 SF 6 10+ years Walls - Plaster/Drywall 1st Floor 360 SF 6 10+ years Water Closet 1st Floor 7 EA 6 10+ years Accessories 1st floor- BOYS- NW 285 SF 7 6-10 years Ceiling - Plaster/Drywall 1st floor- BOYS- NW 285 SF 7 10+ years	
Walls - Masonry 1st Floor 360 SF 6 10+ years Walls - Plaster/Drywall 1st Floor 360 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 360 SF 6 10+ years Water Closet 1st Floor 7 EA 6 10+ years Accessories 1st floor- BOYS- NW 285 SF 7 6-10 years	
Walls - Plaster/Drywall1st Floor360SF610+ yearsWalls - Structural Glazed Tile1st Floor360SF610+ yearsWater Closet1st Floor7EA610+ yearsAccessories1st floor- BOYS- NW285SF76-10 years	
Walls - Structural Glazed Tile1st Floor360SF610+ yearsWater Closet1st Floor7EA610+ yearsAccessories1st floor- BOYS- NW285SF76-10 years	
Water Closet1st Floor7 EA6 10+ yearsAccessories1st floor- BOYS- NW285 SF7 6-10 years	
Accessories 1st floor- BOYS- NW 285 SF 7 6-10 years	
Ceiling - Plaster/Drywall 1st floor- BOYS- NW 285 SF 7 10+ vears	
Doors - Wood Doors inclu hw 1st floor- BOYS- NW 1 EA 6 10+ years	
Floor - Tile Ceramic/ Porcelain 1st floor- BOYS- NW 285 SF 6 10+ years	
Floor Drain 1st floor- BOYS- NW 1 EA 7 10+ years	
Hand Dryer 1st floor- BOYS- NW 2 EA 7 6-10 years	
Lavatory 1st floor- BOYS- NW 3 EA 6 10+ years	
Lighting - Pendent/Surface 1st floor- BOYS- NW 5 EA 7 6-10 years	
Partitions 1st floor- BOYS- NW 1 EA 7 10+ years	
Urinals 1st floor- BOYS- NW 5 EA 6 10+ years	
Walls - Masonry 1st floor- BOYS- NW 312 SF 6 10+ years	
Walls - Plaster/Drywall 1st floor- BOYS- NW 312 SF 6 10+ years	
Walls - Structural Glazed Tile 1st floor- BOYS- NW 312 SF 6 10+ years	
Water Closet 1st floor- BOYS- NW 1 EA 6 10+ years	
Accessories 1st floor- Principal 25 SF 7 6-10 years	
Ceiling - Plaster/Drywall 1st floor- Principal 25 SF 6 10+ years	
Doors - Wood Doors inclu hw 1st floor- Principal 1 EA 6 10+ years	
Floor - Tile 1st floor - Principal 25 SF 6 6-10 years	
·	
Lavatory 1st floor- Principal 1 EA 6 10+ years Lighting - Pendent/Surface 1st floor- Principal 1 EA 7 6-10 years	
·	
Water Closet 1st floor- Principal 1 EA 6 10+ years Accessories 1st- SW 182 SF 7 6-10 years	
Ceiling - Plaster/Drywall 1st- SW 182 SF 7 10+ years	
•	
$oldsymbol{\iota}$	
· ·	
Hand Dryer 1st- SW 2 EA 7 6-10 years	
Lavatory 1st- SW 2 EA 6 10+ years	
Lighting - Pendent/Surface 1st- SW 3 EA 7 6-10 years	
Partitions 1st- SW 1 EA 7 10+ years	
Urinals 1st- SW 2 EA 6 10+ years	
Walls - Masonry 1st- SW 218 SF 6 10+ years	
Walls - Plaster/Drywall 1st- SW 431 SF 6 10+ years	
Walls - Structural Glazed Tile 1st- SW 79 SF 6 10+ years	
Water Closet 1st- SW 1 EA 6 10+ years	
Accessories 2nd Floor 386 SF 7 6-10 years	
Ceiling - Plaster/Drywall 2nd Floor 366 SF 6 10+ years	
Ceiling - Plaster/Drywall 2nd Floor 20 SF 4 0-1 year Water damage	9



Catego	Category : Room		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	386	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EΑ	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	5	EA	6	10+ years	
	Walls - Masonry	2nd Floor	240	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	240	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	240	SF	6	10+ years	
	Water Closet	2nd Floor	2	EA	6	10+ years	
	Accessories	2nd floor across classroom 214	140	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor across classroom 214	140	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor across classroom 214	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor across classroom 214	140	SF	6	10+ years	
	Floor Drain	2nd floor across classroom 214	1	EA	7	10+ years	
	Lavatory	2nd floor across classroom 214	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd floor across classroom 214	2	EΑ	7	6-10 years	
	Partitions	2nd floor across classroom 214	1	ΕA	7	10+ years	
	Walls - Masonry	2nd floor across classroom 214	146	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd floor across classroom 214	146	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd floor across classroom 214	32	SF	6	10+ years	
	Water Closet	2nd floor across classroom 214	1	EΑ	6	10+ years	Quantity changed to match current
			·	`	Ū	.o. youro	observations
	Accessories	2nd floor inside teachers lounge	74	SF	7	6-10 years	oboot valions
	Ceiling - Plaster/Drywall	2nd floor inside teachers lounge	74	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor inside teachers lounge	1	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor inside teachers lounge	74	SF	6	10+ years	
	Hand Dryer	2nd floor inside teachers lounge	1	EA	7	6-10 years	
	Lavatory	2nd floor inside teachers lounge	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd floor inside teachers lounge	1	EA	7	6-10 years	
	Lighting - Wall Mounted	2nd floor inside teachers lounge	1	EA	6	6-10 years	
	Partitions	2nd floor inside teachers lounge	2	EA	7	10+ years	Quantity changed to match current
	1 diddono	Zha noor molae toachere leange	_		•	101 youro	observations
	Walls - Masonry	2nd floor inside teachers lounge	185	SF	6	10+ years	2237,440,10
	Walls - Plaster/Drywall	2nd floor inside teachers lounge	185	SF	6	10+ years	
	Water Closet	2nd floor inside teachers lounge	2	EA	6	10+ years	
	Accessories	2nd fir- NW	281	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd fir NW	281	SF	6	10+ years	
	Doors - Transom Window	2nd fir- NW	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd fir- NW	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd fir- NW	281	SF	6	10+ years	
	1 100. The Column, 1 crociall	2.10 III 1444	201	٥.	J	ioi youio	

Campus Name: Farnsworth Page: 13 of 30 Assessment Date: 11/09/2021



atego	ry : Room		В	uilding	: Main		
_				_		Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	2nd flr- NW	1	EA	7	10+ years	
	Hand Dryer	2nd flr- NW	2	EA	7	6-10 years	
	Lavatory	2nd flr- NW	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd flr- NW	5	EA	7	6-10 years	
	Partitions	2nd flr- NW	7	EA	7	10+ years	
	Walls - Masonry	2nd flr- NW	240	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd flr- NW	240	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd flr- NW	240	SF	7	10+ years	
	Water Closet	2nd flr- NW	7	EA	6	10+ years	
	Accessories	2nd flr- SW	182	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd flr- SW	182	SF	6	10+ years	
	Doors - Transom Window	2nd flr- SW	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd flr- SW	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd flr- SW	182	SF	6	10+ years	
	Floor Drain	2nd flr- SW	1	EA	7	10+ years	
	Hand Dryer	2nd flr- SW	2	EA	7	6-10 years	
	Lavatory	2nd flr- SW	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd flr- SW	3	EA	7	6-10 years	
	Partitions	2nd flr- SW	4	EA	7	10+ years	Quantity changed to match curre observations
	Walls - Masonry	2nd flr- SW	175	SF	6	10+ years	obool valions
	Walls - Plaster/Drywall	2nd flr- SW	250	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd flr- SW	75	SF	7	10+ years	
	Water Closet	2nd flr- SW	4	ĒΑ	6	10+ years	Quantity changed to match curre observations
	Accessories	Room 103	113	SF	7	6-10 years	Observations
	Ceiling - Plaster/Drywall	Room 103	151	SF	6	10+ years	
				SF			
	Doors - Transom Window Doors - Wood Doors inclu hw	Room 103 Room 103	102 2	SF EA	6 6	10+ years	
					_	10+ years	
	Floor - Tile Coromie/ Perceloin	Room 103	103	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 103 Room 103	48	SF EA	6	10+ years	
	Lavatory	Room 103 Room 103	2		6 7	10+ years	
	Lighting - Pendent/Surface		2	EA SF		6-10 years	
	Walls - Plaster/Drywall	Room 103	179	SF EA	6	10+ years	
	Water Closet	Room 103	1		6	10+ years	
∍go	ry : Classroom		В	uilding	: Main	Recommend	
цр	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
sroc	om #100 (Regular Classroom)						
	Casework	1st Floor	11	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years	
	Chalk Board	1st Floor	32	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	720	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,053	SF	6	10+ years	
Classroo	om #101 (Regular Classroom)						
	Casework	1st Floor	73	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	720	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,027	SF	6	10+ years	
01	#400 (D I. Ol)						
Classroc	om #102 (Regular Classroom)						
	Casework	1st Floor	11	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years	
	Chalk Board	1st Floor	18	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Carpet	1st Floor	720	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EΑ	6	6-10 years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,028	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	25	SF	6	10+ years	
Classroo	om #103 (Special Program)						
	Casework	1st Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,920	SF	6	10+ years	
	Doors - Transom Window	1st Floor	27	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years	
	Floor - Carpet	1st Floor	802	SF	6	6-10 years	
	Floor - Tile	1st Floor	1,118	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	18	ĒΑ	6	6-10 years	
	Storage/ Closet	1st Floor	128	SF	7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,938	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #105 (Regular Classroom)						
Classiuu	Casework	1st Floor	14	LF	6	101.1/2072	
	Casework	181 11001	14	LF	Ö	10+ years	



Catego	ry : Classroom		В	uilding	: Main		5414 W Ellider AVENUE, Gilleago, IE 60050
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	28	LF	7	6-10 years	
	Storage/ Closet	1st Floor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,167	SF	6	10+ years	
Classroo	om #106 (Regular Classroom)						
	Casework	1st Floor	40	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	10+ years	
	Floor - Wood	1st Floor	720	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,534	SF	6	10+ years	
	Work Sink	1st Floor	1,554	EA	7		
	Work Silik	151 11001	1	EA	,	10+ years	
_Classroo	om #107 (Regular Classroom)						
	Casework	1st Floor	14	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	38	LF	7	6-10 years	
	Storage/ Closet	1st Floor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,218	SF	6	10+ years	
Classroo	om #108 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
						-	
	vvalis - Metal Fallel	121 11001	1,227	SF	O	10+ years	
	Walls - Metal Panel	1st Floor	1,227	SF	6	10+ years	



Catego	ory : Classroom		В	uilding	: Main		5414 N Elilide: AVENOE, Officago, IE 00050
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	306	SF	6	10+ years	
Classroo	om #109 (Store Room)						
	Ceiling - Plaster/Drywall	Mezzanine	396	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Mezzanine	2	EA	6	10+ years	
	Floor - Tile	Mezzanine	396	SF	6	6-10 years	
	Lighting - Pendent/Surface	Mezzanine	3	EΑ	7	6-10 years	
	Marker Board	Mezzanine	6	LF	6	6-10 years	
	Walls - Masonry	Mezzanine	383	SF	6	10+ years	
	Walls - Plaster/Drywall	Mezzanine	382	SF	6	10+ years	
	Work Sink	Mezzanine	1	EA	7	10+ years	
Classro	om #110 (Special Program)						
_OIGSSIU(Ceiling - Plaster/Drywall	1st Floor	315	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	Sr EA	6	10+ years 10+ years	
	Doors - Transom Window	1st Floor	20	SF	6	6-10 years	
			20				
	Doors - Wood Doors inclu hw Floor - Tile	1st Floor 1st Floor		EA SF	6 6	10+ years	
	Lighting - Pendent/Surface	1st Floor	315			6-10 years 6-10 years	
	Walls - Plaster/Drywall	1st Floor	8 865	EA SF	6 6	10+ years	
	walls - Flaster/Drywall	13111001	003	OI .	O	10+ years	
_Classroo	om #112 (Special Program)						
	Casework	1st Floor	39	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	785	SF	6	10+ years	
	Chalk Board	1st Floor	4	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Carpet	1st Floor	196	SF	7	6-10 years	
	Floor - Tile	1st Floor	584	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	97	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,053	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroo	om #114 (Regular Classroom)						
	Casework	1st Floor	14	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
			20		•	5 .5 Jours	
						,	



Catego	ry : Classroom		В	uilding	: Main		-
3						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,218	SF	6	10+ years	
Classroo	om #200 (Regular Classroom)						
	Casework	2nd Floor	11	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	714	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	32	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	10	ĹF	4	2-5 years	3.
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	746	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,391	SF	6	10+ years	
	vvalis - Flaster/Drywali	2110 F1001	1,391	SF	O	10+ years	
Classroo	om #201 (Regular Classroom)						
	Casework	2nd Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	688	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	32	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,347	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	671	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	32	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	19	LF	4	2-5 years	water damage
	Doors - Transom Window	2nd Floor	9	SF	6	•	Quantity changed to match current
	Doors - Hansom Window	2110 F1001	9	SF	О	10+ years	observations
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	703	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,391	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
	Casework	2nd Floor	14	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	688	SF	6	10+ years	
		2nd Floor		SF SF			Water demage
	Ceiling - Lay-in	2110 F1001	32	SF	4	0-1 year	Water damage



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,167	SF	6	10+ years	
Classroo	om #204 (Regular Classroom)						
Oldooroc	Casework	2nd Floor	14	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor 2nd Floor		LF	_		
			6		4	2-5 years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,167	SF	7	10+ years	
Classroo	om #206 (Regular Classroom)						
	Casework	2nd Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,167	SF	7	10+ years	
Classroo	om #207 (Other Instructional Use)						
	Casework	2nd Floor	40	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	1,060	SF	6	10+ years	
	Chalk Board	2nd Floor		SF LF	4		
			11	SF		2-5 years	
	Doors - Transom Window	2nd Floor	18		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,045	SF	6	6-10 years	01:
	Floor - Tile	2nd Floor	15	SF	4	0-1 year	Chipped
	Lighting - Pendent/Surface	2nd Floor	18	EΑ	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,482	SF	6	10+ years	
	Work Sink	2nd Floor	4	EA	5	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
_			• 414			Recommend	
3roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #208 (Regular Classroom)						
21000100	Casework	2nd Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Transom Window		9	SF	6		
		2nd Floor			-	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,167	SF	7	10+ years	Changed to match current
	·					•	observations
lassroo	m #209 (Special Education)						
	Ceiling - Plaster/Drywall	Mezzanine	506	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Mezzanine	20	SF	3	0-1 year	Water damage/quantity changed to
	Celling - I laster/Drywaii	Mezzailile	20	OI.	3	0-1 year	match current observations
	Doors Wood Doors include	Mazzanina	2	EA	e	10	
	Doors - Wood Doors inclu hw	Mezzanine	2	EA	6	10+ years	Quantity changed to match curren
					_		observations
	Floor - Terrazzo	Mezzanine	526	SF	6	10+ years	Changed to match current
							observations
	Lighting - Pendent/Surface	Mezzanine	9	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	Mezzanine	694	SF	6	10+ years	
	Work Sink	Mezzanine	1	EA	7	6-10 years	
lassroo	m #210 (Regular Classroom)						
	Casework	2nd Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	688	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	32	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	4	LF	4	2-5 years	water damage
	Doors - Transom Window			SF		•	
		2nd Floor	18		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,167	SF	6	10+ years	
lassroo	m #212 (Regular Classroom)						
	Casework	2nd Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Chair Doald	Z110 1 1001	O	니	-	∠-o years	



July	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	38	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,167	SF	6	10+ years	
Classroo	om #214 (Regular Classroom)						
	Casework	2nd Floor	11	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	746	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	746	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	32	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,020	SF	6	10+ years	
ateno	ry : Interior		R	uilding	· Main		
oulogo				anamg	· Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	5,080	SF	6	10+ years	
	Doors - Transom Window	1st Floor	360	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	14	EA	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	5,080	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	30	ĒΑ	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	10	EΑ	7	6-10 years	
	Stairs - Terrazzo	1st Floor	8	LF	6	10+ years	
	Student Lockers - One Tier	1st Floor	294	EΑ	6	10+ years	
	Walls - Masonry	1st Floor	3,531	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	70,590	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	30	SF	5	2-5 years	Cracking in walls
	Ceiling - Lay-in	2nd Floor	5,040	SF	6	10+ years	- · · · · · · · · · · · · · · · · · · ·
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	2nd Floor	2	EA	7	6-10 years	
			5,040	SF	7	10+ years	
		2nd Floor	5.040			10. 70010	
	Floor - Tile/Sheet	2nd Floor 2nd Floor			6		
		2nd Floor 2nd Floor 2nd Floor	5,040 61 306	EA EA	6 6	6-10 years 10+ years	



Catego	ry : Interior	Building : Main						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years		
	Security Cameras	Entire Building	5	EA	7	6-10 years	Outside	
	Security Cameras	Entire Building	5	EA	7	6-10 years	Inside/quantity changed to match	
	0 " 0	E (4	^	-	0.4	current observations	
	Security Cameras	Entire Building	1	EA	5	0-1 year	Reported as not functional	
Stairs								
	Ceiling - Plaster/Drywall	North	252	SF	6	10+ years		
	Floor - Terrazzo	North	126	SF	7	10+ years	Changed to match current	
					•	·	observations	
	Handrails	North	72	LF	7	10+ years		
	Lighting - Lay-in	North	2	EA	6	6-10 years		
	Stairs - Terrazzo	North	162	LF	6	10+ years	Quantity changed to match current observations	
	Walls - Plaster/Drywall	North	1,300	SF	6	10+ years		
	Ceiling - Plaster/Drywall	North West	252	SF	6	10+ years		
	Floor - Terrazzo	North West	126	SF	7	10+ years	Changed to match current	
					•	-	observations	
	Handrails	North West	72	LF	7	10+ years		
	Lighting - Lay-in	North West	2	EA	6	6-10 years		
	Stairs - Terrazzo	North West	162	LF	6	10+ years	Quantity changed to match current observations	
	Walls - Plaster/Drywall	North West	1,300	SF	6	10+ years		
	Ceiling - Lay-in	South	8	SF	4	0-1 year	Water damage	
	Ceiling - Plaster/Drywall	South	236	SF	6	10+ years	Trator damage	
	Floor - Terrazzo	South	126	SF	7	10+ years	Changed to match current	
	1 1001 - 1 611 4220	Journ	120	Oi.	,	10+ years	observations	
	Handrails	South	72	LF	7	10+ years		
	Lighting - Lay-in	South	2	EA	6	6-10 years		
	Stairs - Terrazzo	South	162	LF	6	10+ years	Quantity changed to match current observations	
	Walls - Plaster/Drywall	South	1,290	SF	6	10+ years	SSSS Validillo	
	Ceiling - Plaster/Drywall	South West	252	SF	6	10+ years		
	Floor - Terrazzo	South West	126	SF	7		Changed to match current	
					•	10+ years	observations	
	Handrails	South West	72	LF	7	10+ years		
	Lighting - Lay-in	South West	2	EA	6	6-10 years		
	Stairs - Terrazzo	South West	162	LF	6	10+ years	Quantity changed to match current observations	
	Walls - Plaster/Drywall	South West	1,300	SF	6	10+ years		
Vertical	Conveyance							
VOLUCAL	Elevator - Elevator- Machine Roomless	North	2	EA	6	10+ years	Missing ceiling grid	
	Fierator - Fierator- Machine 17001111622	INOILII	2	LA	U	10+ years	wissing celling grid	



atego	ry : Exterior		В	uilding	: Modul	ar 1 (4-Classro	om)
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
tranc		Location	Quantity	OOM	Italik	Replacement	Comments
1110	Entrance Control - Audio and Video	#1M - E	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#1M - E	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#2M - W	2	EA	6	6-10 years	
nda	ion — — — — — — — — — — — — — — — — — — —	Factor Building	000			40	
	Foundation - Masonry	Entire Building	282	LF	7	10+ years	
	Superstructure - Steel	Entire Building	4,950	SF	7	10+ years	
ting							
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	5	2-5 years	
of Sv	stem						
ог Оу	Coping - Metal	Entire Building	282	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	Entire Building	52	LF	6	6-10 years	
	Roof - EPDM/ Synthetic Rubber	Entire Building	4,138	SF	5	2-5 years	
	Roof - EPDM/ Synthetic Rubber	Entire Building	812	SF	4	0-1 year	Leaks
	Roof Structure - Steel / Metal Deck/	Entire Building	4,950	SF	7	10+ years	
	Concrete Topping	9	,,,,,			, , , , , , , , , , , , , , , , , , ,	
ılls							
	Exterior Walls - Wood Siding	Entire Building	3,666	SF	6	6-10 years	
	Exterior Walls - Wood Siding	Entire Building	20	SF	4	0-1 year	Hole in wall
dow	s c						
	Guard - Guards perforated	Entire Building	256	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	288	SF	6	6-10 years	
eac	ry : Electrical		В	uildina	: Modul	ar 1 (4-Classro	om)
3			_			Recommend	· ·
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
erge	ncy System						
	Exit Signs - Corridors and Stairs	Entire Building	6	EA	5	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	
	Stairs Security System - Intrusion Detection	Entire Building	5	SF	7	6-10 years	
	Cooling System Initiation Dottomon	o Dananiy	3	٥.	•	o .o youro	
ı Se	rvice						
	PA System	Boiler Room	4,950	SF	5	6-10 years	

Campus Name: Farnsworth Page : 23 of 30 Assessment Date: 11/09/2021



Catego	ry : Electrical		В	uilding	: Modul	ar 1 (4-Classro	oom)	
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Power D	istribution	E 0 B 11						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years		
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years		
Catego	ry : Fire Protection		В	uildina	: Modul	ar 1 (4-Classro	oom)	
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Fire Alar								
	Fire Alarm Strobe Lights	Entire Building	4,950	SF	6	6-10 years	No strobe light	
	Fire Alarm_System	Entire Building	4,950	SF	6	6-10 years		
Con minals la m	Custom							
Sprinkler	System Sprinkler Heads	Entire Building	4.050	SF	7	10 L VOORS		
	•	•	4,950	SF SF	7	10+ years		
	Sprinkler Piping	Entire Building	4,950		6	10+ years		
	Wet Sprinkler System	Entire Building	4,950	SF	6	10+ years		
Catego	ry : Mechanical		Building : Modular 1 (4-Classroom)					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Tempera	ture Control							
	DDC System	1st Floor	4,950	SF	6	6-10 years		
	Electric Thermostat	1st Floor	4	EA	5	6-10 years		
Unit Ven								
	Unit Ventilators- Floor Mounted- Electric	Exterior wall mounted	4	EA	5	2-5 years		
	Heating & DX Cooling Coil W/ Self							
	Contained Compressor							
Ventilatio						0.10		
	Exhaust Fans- Roof Mounted - 500 - 1500	Roof	5	EA	5	6-10 years		
	CFM							
Catego	ry : Plumbing		В	uildina	: Modul	ar 1 (4-Classro	oom)	
			_			Recommend	,	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Hot Wate	• •							
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	6-10 years		
			·		-	,		
Piping								
- 	Domestic Piping-Hot Water Return Lines	Entire Building	4,950	SF	6	10+ years		
	, 3	3	,,,,,	-	-	, ,		

Campus Name: Farnsworth Page : 24 of 30 Assessment Date: 11/09/2021



Category : Plumbing Building : Modular 1 (4-Cla				ar 1 (4-Classro	oom)		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	4,950	SF	6	10+ years	
	Sanitary Piping	Entire Building	4,950	SF	6	10+ years	
	Storm Piping	Entire Building	4,950	SF	6	10+ years	
	Vent Piping	Entire Building	4,950	SF	6	10+ years	
Catego	ry : Classroom		P	uildina	· Modul	ar 1 (4-Classro	nom)
Culogo			_	ananig		Recommend	, ,
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #115 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	812	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	812	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Storage/ Closet	1st Floor	92	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	836	SF	6	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	10+ years	
Classroo	m #116 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	812	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	812	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	16	ĒΑ	7	6-10 years	
	Storage/ Closet	1st Floor	92	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	836	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #117 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	806	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	6	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	812	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Storage/ Closet	1st Floor	92	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	836	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #118 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	812	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
					•	,	

Campus Name: Farnsworth Page : 25 of 30 Assessment Date: 11/09/2021



Catego	ry : Classroom		Building : Modular 1 (4-Classroom)					
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	812	SF	6	6-10 years		
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years		
	Storage/ Closet	1st Floor	92	SF	7	10+ years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	836	SF	6	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years		
atego	ry : Room		В	uilding	: Modul	ar 1 (4-Classro	oom)	
_						Recommend	· ·	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
/lechani	cal/ Service Rooms		•			•		
<u>ICOHOLII</u>	Mechanical/ Service Rooms	Room 115/117 Mechanical Closet	50	SF	7	10+ years	Quantity changed to match curren observations	
Restroor	n							
	Accessories	1st Floor	162	SF	7	6-10 years		
	Ceiling - Lay-in	1st Floor	162	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile/Sheet	1st Floor	162	SF	7	10+ years		
	Floor Drain	1st Floor	1	EA	7	10+ years		
	Hand Dryer	1st Floor	1	EA	7	6-10 years		
	Lavatory	1st Floor	2	EA	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years		
	Partitions	1st Floor	2	EA	7	10+ years		
	Urinals	1st Floor	2	EA	6	10+ years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	300	SF	6	10+ years		
	Water Closet	1st Floor	2	EA	6	10+ years		
	Accessories	1st Floor	162	SF	7	6-10 years		
	Ceiling - Lay-in	1st Floor	162	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years		
	Floor - Tile/Sheet	1st Floor	162	SF	7	10+ years		
	Floor Drain	1st Floor	1	ĒΑ	7	10+ years		
	Hand Dryer	1st Floor	1	EA	7	6-10 years		
	Lavatory	1st Floor	2	EA	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years		
	Partitions	1st Floor	4	EA	7	10+ years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	300	SF	6	10+ years		
	Water Closet	1st Floor	4	EA	6	10+ years		
atego	ry : Interior		В	uilding	: Modul	ar 1 (4-Classro	oom)	
2roun	Itom - Typo	Logation	Quantity	UOM	Donk	Recommend	Commonts	
Group	Item - Type	Location	Quantity	UUW	Rank	Replacement	Comments	



Catego	ry : Interior		Building : Modular 1 (4-Classroom)							
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Ceiling - Lay-in	1st Floor	432	SF	6	10+ years				
	Doors - Wood Doors include hw	1st Floor	4	EA	6	10+ years				
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years				
	Floor - Tile/Sheet	1st Floor	432	SF	7	10+ years				
	Floor - Tile/Sheet	1st Floor	64	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	7	EA	7	6-10 years				
	Walls - Plaster/Drywall	1st Floor	992	SF	6	10+ years				
_Safetv										
	Security Cameras	1st Floor	1	EA	7	6-10 years				

Campus Name: Farnsworth Page : 27 of 30 Assessment Date: 11/09/2021





Category : Site **Building: Site**

						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
nletic	Surface - Synthetic	West	9,920	SF	7	10+ years	
	Surface - Synthetic Surface - Asphalt	West	1,020	SF	7	10+ years	
	Surface - Aspirali	West	1,020	SI	,	10+ years	
ivil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	10	EA	7	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	4	0-1 year	Sinking and hole
	Civil/ Drainage - Site Drain	Entire Site	2	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	7	10+ years	
encina							
ending.	Fencing - Chain Link	Entire Site	165	LF	6	6-10 years	
	Fencing - Guard Rail	Entire Site	50	LF	6	6-10 years	Missed in prior assessment
	Fencing - New Standard Ornamental	Entire Site	1,384	LF	6	6-10 years	
andsca	pe Benches	Entire Site	11	EA	7	10+ years	
	Landscape - Grass	Entire Site	38,418	SF	6	10+ years	
	Landscape - Grass Landscape - Hardscape- Asphalt	Entire Site	160	SF	6	6-10 years	
	Landscape - Hardscape- Asphalt	Entire Site	500	SF	4	0-10 years 0-1 year	Hole/ cracks
	Landscape - Hardscape- Aspirali Landscape - Hardscape- Pavers	Entire Site	1,200	SF	6	10+ years	TIOIE/ CIACKS
	Parkway trees	Entire Site	64	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	420	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	1,863	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	20,031	SF	6	6-10 years	
	Retaining Wall - Concrete	Entire Site	400	SF	6	10+ years	
	Trash Receptacles	Entire Site	3	EA	6	6-10 years	
	Walking Path - Crushed Stone	Entire Site	620	SF	7	10+ years	
	-	Emilio ono	020	O.	,	101 yours	
Parking I							
	Concrete Curbs	SW parking lot	212	LF . –	6	10+ years	
	Interior Plantings	SW parking lot	462	LF	6	10+ years	
	Surface - Asphalt	SW parking lot	10,576	SF	6	6-10 years	
	Surface - Asphalt	SW parking lot	200	SF	4	0-1 year	Cracking and large potholes
	Trash Enclosure - Chain Links	SW parking lot	723	SF	6	6-10 years	
	Vehicular Screening	SW parking lot	14	LF	6	10+ years	
	Concrete Curbs	W Lot	316	LF	6	10+ years	
	Surface - Asphalt	W Lot	11,452	SF	6	6-10 years	
	Surface - Asphalt	W Lot	100	SF	4	0-1 year	Cracks and potholes



James B Farnsworth Elementary School

5414 N Linder AVENUE, Chicago, IL 60630

Catego	ry : Site		Building : Site							
_						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Equipment - Combo 3-12	NE Lot	1	EA	7	10+ years				
	Equipment - Swingset	NE Lot	1	EA	7	10+ years				
	Surface - Poured Surface	NE Lot	6,700	SF	7	10+ years				
Sidewall	KS									
	Sidewalks - Internal Walks	Entire Site	289	LF	7	10+ years				
	Sidewalks - Internal Walks	Entire Site	265	LF	6	10+ years				
	Sidewalks - Perimeter Sidewalks	Entire Site	1,750	SF	6	10+ years				
Signage										
	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	6	6-10 years				
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years				
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years				

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Farnsworth Page: 29 of 30 Assessment Date: 11/09/2021

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	interface esage	Noom Location	Trainbo.	Trainbo.	(0.)	Alou	Alou	Otop	Boara
Other Instructional Use	Science	2nd Floor	207	205	1,060	197	85	N	N
Regular Classroom	Library	1st Floor	101	Library	720	128	78	N	N
Regular Classroom	Regular Classroom	1st Floor	100	106	720	180	78	N	N
Regular Classroom	Regular Classroom	1st Floor	102	107	720	128	78	N	N
Regular Classroom	Regular Classroom	1st Floor	105	104	720	185	85	N	N
Regular Classroom	Regular Classroom	1st Floor	106	116	720	128	78	N	N
Regular Classroom	Regular Classroom	1st Floor	107	105	720	185	85	N	N
Regular Classroom	Regular Classroom	1st Floor	108	115	720	128	78	N	N
Regular Classroom	Regular Classroom	1st Floor	114	114	720	185	85	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	206	746	137	68	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	720	185	85	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	207	703	137	68	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	202	720	185	85	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	208	720	185	85	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	209	720	185	85	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	210	720	185	85	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	211	720	185	85	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	212	212	720	185	85	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	214	214	746	217	217	N	Υ
Special Education	Lunch Room	Mezzanine	209	NA	526	41	41	N	N
Special Program	Kindergarten	1st Floor	103	103	1,920	237	107	N	N
Special Program	Kindergarten	1st Floor	112	120	785	179	109	N	N
Special Program	Special Program	1st Floor	110		315	65	35	N	N
Store Room	Regular Classroom	Mezzanine	109		396	36	18	N	N
			•		•		•	· ·	· -
Building : Modular 1 (4-Cla									
									

Building : Modular 1 (4-Classroom)										
Regular Classroom	Regular Classroom	1st Floor	115	n/a	812	64	28	N	N	
Regular Classroom	Regular Classroom	1st Floor	116	n/a	812	64	28	N	N	
Regular Classroom	Regular Classroom	1st Floor	117	n/a	812	64	28	N	N	
Regular Classroom	Regular Classroom	1st Floor	118	n/a	812	64	28	N	N	

Campus Name: Farnsworth Page : 30 of 30 Assessment Date: 11/09/2021